



**Brougham Village Blocks A to E  
Detailed Engineering Evaluation  
Quantitative Report**

Christchurch City Council



*Christchurch City Council*

# **Brougham Village Blocks A to E**

## **Detailed Engineering Evaluation Quantitative Report**

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: 3 October 2012  
Reference: 6-QUCCC.92

Status: Final Version 4

Brougham Village Blocks A to E  
BU 1072-002 EQ2 to BU 1072-006 EQ2

Detailed Engineering Evaluation  
Quantitative Report - SUMMARY  
Version 4 - Final

356 to 400 Brougham Street, Sydenham, Christchurch

## **Background**

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Brougham Village Blocks A to E, located at 356 to 400 Brougham Street, Sydenham, following the M6.3 Christchurch earthquake on 22 February 2011. The key outcome of this assessment was to ascertain the anticipated seismic performance of the structures and to compare their performance with current design standards. In addition, Opus was tasked with providing conceptual strengthening options to improve the building's seismic performance, with a target of meeting at least 67% of the new building standard (%NBS).

The structures under assessment have been grouped into three primary categories, namely:

- Single Storey Unit;
- 2-Storey Unit – Garage and Residential Units;
- 3-Storey Unit – Residential Units over external stairs

## **Key Damage Observed**

Significant land damage has been observed on site including settlement of up to 100mm, lateral spread of 50mm+ and liquefaction sand boils. The land damage which has occurred on site has caused differential settlement of slab foundations, settlement of walls, and separation of wall joints between units. Significant cracking of reinforced concrete beams and slabs has occurred in the 3 storey sections of the complex.

## **Critical Structural Weaknesses**

The following critical structural weaknesses have been identified:

- Diaphragm collector to lateral resistance system for the 3-storey units
- Land instability

A number of potential collapse hazards have also been highlighted within the document.

## **Indicative Building Strength**

The findings of the assessment are:

### ***Undamaged state***

The seismic performance of the single storey unit has expected strength of 40%NBS and is not Earthquake Prone as defined by legislation. It is considered to be a Grade C - moderate risk structure in accordance with NZSEE guidelines.

The seismic performance of the 2-storey unit has an expected strength of 48%NBS and is not Earthquake Prone as defined by legislation. It is considered to be a Grade C - moderate risk structure in accordance with NZSEE guidelines.

The seismic performance of the 3-storey unit has an expected strength of 22%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

### ***Damaged state***

The ratings provided in this report are based on the undamaged state of the structures. However, there has been significant ground movement in the area of Blocks A to E resulting in considerable differential settlement between units. The differential settlement has caused excessive cracking to occur between wall elements, has caused rotation at the base of a number of walls, has resulted in the failure of some connections between orthogonal walls and will have introduced additional forces into structural elements for which they have not been designed.

The seismic performance of a damaged single storey unit has expected strength of 25%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

The seismic performance of a damaged 2-storey unit has an expected strength of 30%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

The seismic performance of a damaged 3-storey unit has an expected strength of 14%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade E - high risk structure in accordance with NZSEE guidelines.

Where damage was considered severe enough to comprise the integrity of the affected structural elements it is our understanding that the relevant units have been closed – refer to Appendix E for identification of affected units.

The site, in general, is susceptible to future liquefaction and lateral spreading. Future liquefaction of foundations would cause further structural and non-structural damage. Due to the unpredictable effects of liquefaction, the reported building strength does not include a reduction factor for differential settlement induced forces.

### **Recommendations**

The recommendations for the development include:

- A strengthening works concept scheme be developed to increase the seismic capacity of the single storey and 2-storey to at least 67% NBS; this will need to consider compliance with accessibility and fire requirements;
- The 3-storey units pose a potential collapse hazard. Currently, the lateral restraint to the upper two levels of the units is provided by the out-of-plane capacity of the upper storey and a single in-plane wall on the first floor. Failure of the lateral resisting system will result in a high risk of collapse of the upper storeys onto the surrounding properties. The potential hazard zone includes the residential units on either side of the 3-storey unit. Measures to mitigate against the potential hazard will have to be undertaken;
- A full level survey of the site be undertaken to aid any repair work that may be implemented;
- Several geotechnical investigations be undertaken to quantify the liquefaction potential of the site and determine the soil shallow bearing strength of the existing foundations.



## Contents

1	Introduction.....	1
2	Compliance .....	1
3	Earthquake Resistance Standards .....	4
4	Building Description.....	6
5	Survey.....	8
6	Structural Damage.....	8
7	General Observations.....	8
8	Detailed Seismic Assessment.....	9
9	Geotechnical Assessment .....	16
10	Remedial Options .....	19
11	Conclusions .....	20
12	Recommendations.....	20
13	Limitations.....	21
14	References .....	21

**Appendix A – Photographs**

**Appendix B – Floor Plan**

**Appendix C – DEE Spreadsheet**

**Appendix D – Geotechnical Desk Study**

**Appendix E – Site Location and Damage Plan**

## **1 Introduction**

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Brougham Village Blocks A to E, located at 356 to 400 Brougham Street, Sydenham, following the M6.3 Christchurch earthquake on 22 February 2011.

The purpose of the assessment is to determine if the buildings are classed as being Earthquake Prone as defined by legislation

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011.

## **2 Compliance**

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### **2.1 Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Any building with a capacity of less than 34% of new building standard (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% as required by the CCC Earthquake Prone Building Policy.

## **2.2 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 - Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration.

This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) is satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'.

This is typically interpreted by CCC as being 67% of the strength of an equivalent new building. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### **Section 121 – Dangerous Buildings**

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- 36% increase in the basic seismic design load for Christchurch (Z factor increased from 0.22 to 0.3);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

**Figure 3.1: NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

**Table 1: %NBS compared to relative risk of failure**

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

#### 3.1.1 Occupancy

- The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

they are made aware of our assessment. Based on information received from CERA to date, this notice is likely to prohibit occupancy of the building (or parts thereof) until its seismic capacity is improved to the point that it is no longer considered an EPB.

### **3.1.2 Cordoning**

- Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/Christchurch City Council guidelines.

### **3.1.3 Strengthening**

- Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.
- It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### **3.1.4 Our Ethical Obligation**

- In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

## **4 Building Description**

### **4.1 General**

The Brougham Village Blocks A to E refers to the buildings located from 356 to 400 Brougham Street (Fig. 4.1). Blocks A to E refer to nine distinct sub-blocks which are structurally independent. The buildings, which were designed in 1977, are located along the north boundary of the Brougham Village complex. The buildings are a mix of tiered single storey units to the north, and 2 to 3 storey units to the south. Refer to Appendix E for location plans identifying the aforementioned blocks and the varying storey heights.

For the purposes of this report the structures have been separated into three primary building types, namely:

- Single storey unit;
- Garage with residential units above (2-storey);
- 3-storey residential unit.

The buildings are typically reinforced masonry construction with timber framed roofs. The roofs comprise pitched and flat roof areas. The two and three storey buildings have reinforced concrete intermediate floors. The ground level of the multi-level units house the garage and utility areas for the residents of the local sub-block. Local access points are provided in between the sub-blocks in the form of external concrete stairs founded at grade.

Each sub block is approximately 24m long in the north-south direction and 22m wide in the east-west direction.

The formation levels of the buildings have been constructed using cut and fill methods to form tiered levels up to 2m above existing ground level with engineered hardfill.



**Figure 4.1: Brougham Village Blocks A-E**

#### **4.2 Gravity Load Resisting System**

The pitched roof is clad in heavy clay tile, on Woodtex proprietary panels on exposed timber truss rafters. The flat roof areas are constructed using proprietary Woodtex panels on timber roof joists. The timber frame members are fixed to the reinforced masonry walls via bolted steel cleats. The two and three storey buildings have intermediate reinforced concrete floors which are tied into the reinforced masonry walls with specific reinforcement detailing.

The walls are reinforced concrete masonry with an approximate height of 2.25 - 2.4m throughout.

The walls are founded on narrow ground beam footings. The floor consists of an unreinforced concrete ground slab with local thickenings to cater for the masonry pier elements.

#### **4.3 Seismic Force Resisting System**

Seismic forces in both principal directions are resisted by the in-plane and out-of-plane capacity of the reinforced masonry walls. The single storey units lack a sufficient diaphragm and therefore lateral forces have been apportioned on a tributary area basis, assuming that timber roof joists act as collectors to a moderate extent.

The suspended slab floors are mesh reinforced concrete and are assumed to provide a rigid diaphragm which can distribute lateral forces to the wall bracing elements.



## **5 Survey**

Copies of the following drawings were referred to as part of the assessment:

- A set of architectural and structural drawings by D A Cowey Associates. Registered Architects, titled “Brougham Street Urban Renewal 1. Stage 1”.

No copies of the design calculations have been obtained for this building.

The drawings have been used to confirm the structural systems, investigate potential critical structural weaknesses (CSW) wherever possible and identify details which required particular attention.

## **6 Structural Damage**

Typical damage to the buildings includes:

- Differential settlement of the slab foundations (Photo 5).
- Separation of the slab foundations at the interface with adjacent units (Photo 5).
- Settlement of walls and separation of walls at the interface with adjacent units (Photos 4 and 5).
- Cracking and displacement of concrete beams and suspended slab floors in the 2 to 3 storey sections (Photo 6).
- Separation of bond beams from top of reinforced masonry walls (Photo 4).
- Failure of wall due to excessive loading (Photo 10).
- Rotation of reinforced masonry piers to front of garage due to soil movement (Photos 8 and 9).

Surrounding Area Damage:

- Heaving due to ground movement – pavement cracking etc
- Lateral spread and settlement of built-up ground

## **7 General Observations**

Blocks A through E have suffered significant damage primarily due to lateral spread, liquefaction and differential settlement of the land. The extent of damage varies along the site with slight land damage at the extreme west end of the site which increases through the centre and east of the site. Refer to Appendix E – Site Damage Plan for general overview of damaged and evacuated structures.

The sub-blocks to the east of the area under consideration have suffered significant structural damage, in particular the 2 and 3-storey units. Damage to the 2 and 3 storey sections includes the simply supported floor slabs moving off their supporting walls due to wall rotation, the reinforced masonry walls failing due to excess loading, and the masonry piers rotating due to settlement and ground movement.

The sub-blocks to the west of the area under consideration have suffered less significant structural damage, but it is expected that were they subject to the same settlement issues as the eastern end a similar pattern of damage would be observed.

## **8 Detailed Seismic Assessment**

### **8.1 Critical Structural Weaknesses**

As outlined in the Critical Structural Weakness and Collapse Hazards draft briefing document, issued by the Structural Engineering Society (SESOC) on 7 May 2011, the term 'Critical Structural Weakness' (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of the building.

We have identified the following Critical Structural Weaknesses in Blocks A to E:

- Diaphragm collector to lateral resistance system for the 3-storey units – The lateral resistance in the east-west direction of the 3-storey units is limited by the capacity of the collector element to transfer the load to the shear wall. The collector element consists of 2 no. 12mm dia bars from the shear wall bond beam which extend into the concrete floor diaphragm. The failure of the collector element in tension may cause premature failure of the upper storey walls due to out-of-plane motion.
- Land instability – It has been noted that the built-up areas of the site have suffered from lateral spreading, which has resulted in amplified settlements occurring to particular areas, most notably the east end of Blocks A to E.

### **8.2 Potential Structural Hazards**

The following are potential structural hazards which have been identified in the structure. The nature of a structural hazard is to cause localised failure and damage but not influence the structure beyond the immediate area.

- Inadequate precast slab bearing lengths – From the movement observed on site it appears that the simply supported precast slab elements, which span over the external staircases to form the first floor of the 3-storey units, have insufficient bearing length. A number of post-completion installed angles were observed on site which is sufficient in resolving the issue. Where the angles have not been installed and the slabs have pulled away from the supporting wall there is a high risk of collapse. It was noted on site that a number of these occurrences were addressed with temporary propping.
- Inadequate foundations – The foundations to the walls of the single storey and 2-storey units are narrow strip footings typically 160-190mm wide. The effect of such

narrow foundations is to dramatically increase the possibility of shear failure of the soils local to the foundations, resulting in excessive settlements and the introduction of forces to the frame for which it was not designed.

- Brittle construction - Site observed inadequate filling of masonry wall cells may result in the premature failure of affected reinforced masonry shear walls due to brittle behaviour of non-grouted masonry blocks.
- First floor slab cantilever – There are a number of locations where the first floor slab cantilevers beyond the final pier of a unit, it proceeds to step back and forms a re-entrant corner before bearing onto the next pier support. Whilst additional reinforcement has been provided in this area, site observation indicates that the slabs have insufficient capacity to cater for the loads applied during a seismic event.

### **8.3 Seismic Coefficient Parameters**

The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class D, clause 3.1.3 NZS 1170.5:2004;
- Site hazard factor,  $Z = 0.3$ , B1/VM1 clause 2.2.14B;
- Return period factor  $R_u = 1.0$  from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life;
- $\mu_{\max} = 2.0$  for reinforced masonry walls to 2-storey and 3-storey units – due to detailing and construction practices;
- $\mu = 1.25$  for reinforced masonry walls to single storey units;
- All units have been assessed using the equivalent static method as outlined in NZS 1170.5 – 2004.

### **8.4 Detailed Seismic Assessment Results**

Blocks A to E consist of 9 sub-blocks each typically comprising four single storey units and a garage structure with two residential units above. Located in the area between the sub-block units and over the external stairwell is the 3-storey unit (the stairwell is considered as one floor).

There are 3 primary building types assessed in this report. These are:

- Single storey unit;
- Garage with residential units above;
- 3-storey residential unit.

A summary of the structural performance of the buildings are shown in the following tables. Note that the values given represent the worst performing elements in the building, as these

effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing element.

Figure 8.1 provides a reference plan at ground floor level for a typical sub-block. The structural performance tables reference the wall numbers for the single storey structure and the wall line numbers for the garage unit.




Figure 8.1: Sub-Block Ground Floor Reference Plan

#### 8.4.1 Single Storey Unit Assessment Methodology

With the lack of a flexible or rigid roof diaphragm the single storey unit has been assessed on the basis of tributary area loading. The walls have been assessed in the two primary

orthogonal directions. The timber joists have been utilised as collector elements where the connection details and capacity of the sections allow.

**Table 2: Summary of Seismic Performance – Single Storey Unit**

<b>Structural Element/System</b>	<b>Failure mode and description of limiting criteria</b>	<b>% NBS based on calculated capacity</b>
Reinforced masonry Wall W1	In-plane Bending Capacity of wall	47%
Reinforced masonry Wall W2	Out-of-plane Bending Capacity of wall	40%
Reinforced masonry Walls W3 & W4	Out-of-plane Bending Capacity of wall	86%
Reinforced masonry Wall W6	In-plane Bending Capacity of wall	52%
Reinforced masonry Wall W7	Out-of-plane Bending Capacity of wall	87%
Reinforced masonry Pier C2	In-plane Bending Capacity of pier	78%

#### 8.4.2 Two Storey Unit Assessment Methodology

The 2-storey unit has been assessed in the two primary orthogonal directions. The following is a brief description of the methodology adopted for each direction.

##### **North-South:**

Due to the lack of a flexible or rigid roof diaphragm the first floor structure loads are assigned at the first floor level and are distributed with the lower level loads through the first floor slab diaphragm to the walls on a relative stiffness basis. The torsional effects resulting from the application of the 10% eccentricity of load and the 30% of seismic load applied in the orthogonal direction, in accordance with NZS1170.5, have been allowed for.

##### **East-West:**

Due to the lack of a flexible or rigid roof diaphragm the first floor structure loads are assigned at the first floor level and are distributed with the lower level loads through the first floor slab diaphragm to the walls on a relative stiffness basis. The torsional effects resulting from the application of the 10% eccentricity of load and the 30% of seismic load applied in the orthogonal direction, in accordance with NZS1170.5, have been allowed for. This results in large in-plane loads to the walls spanning in the north-south direction. The walls are assessed based the resultant loadings.

**Table 3: Summary of Seismic Performance – 2-Storey Unit**

Structural Element/System	Failure mode and description of limiting criteria	% NBS based on calculated capacity
<b>NORTH - SOUTH DIRECTION</b>		
Reinforced masonry Wall	In-plane Bending Capacity of primary shear wall	85%
<b>EAST - WEST DIRECTION</b>		
Reinforced masonry Wall Line W10	In-plane Shear Capacity of wall	<100%
<b>FIRST FLOOR DIAPHRAGM</b>		
Reinforced Concrete Diaphragm	Diaphragm – Deep Beam Check	96%
Reinforced Concrete Diaphragm	Shear Capacity of wall and slab interface in transfer of horizontal loadings – North-South direction	48%
Reinforced Concrete Diaphragm	Shear Capacity of wall and slab interface in transfer of horizontal loadings – East-West direction	83%

### 8.4.3 Three Storey Unit Assessment Methodology

The 3-storey unit has been assessed in the two primary orthogonal directions. The following is a brief description of the methodology adopted for each direction.

#### North-South:

Due to symmetrical layout in the north-south direction the equivalent static loads are assigned evenly between the two shear wall elements.

#### East-West:

There is a lack of shear walls on the upper floor in the east-west direction; therefore the orthogonal walls are assessed for out-of-plane loading. The sole shear wall on the first floor is hence heavily loaded and an assessment of the wall capacity has been undertaken.

**Table 4: Summary of Seismic Performance – 3-Storey Unit**

Structural Element/System	Failure mode and description of limiting criteria	% NBS based on calculated capacity
<b>NORTH - SOUTH DIRECTION</b>		
Reinforced masonry Wall – Full height	In-plane Bending and Shear Capacity of wall	>100%
<b>EAST - WEST DIRECTION</b>		
Reinforced masonry Wall – 2nd Floor	Out-of-plane Bending Capacity of 2nd floor wall	22%

Reinforced masonry Wall – 1st Floor	Capacity of connection of wall to floor diaphragm	49%
--	---	-----

## 8.5 Discussion of Results

As per the approach in Section 8.4 the discussion of the results is addressed in three sections. The results outlined in the previous section are an assessment of the structure in an undamaged state.

### A) Single Storey Units

The assessment has assumed the timber joists have the capacity to transfer lateral loads and that the wall footings possess some base capacity against out-of-plane rotation. The calculated seismic capacity of the structure is 40% NBS, which is limited by the lowest capacity of a laterally loaded wall. The lack of a roof diaphragm and hence the isolated nature of the walls results in the calculated %NBS values being specific to each wall as detailed in Table 2.

In addition to the calculated capacities, the site has sustained extensive damage due to the underlying soil issues. A number of walls have separated from orthogonal walls, noticeable differential settlement has occurred between units and bond beams have suffered localised damage around connection points. This may result in a reduction of the calculated capacity of the affected walls.

The seismic performance of a damaged single storey unit has expected strength of 25%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D – high risk structure in accordance with NZSEE guidelines.

### B) 2-Storey Units

The assessment of the structure in its undamaged state provides calculated capacity of 48% NBS. This capacity is limited by the out-of-plane bending capacity of the upper storey shear walls.

The settlement which has occurred around Blocks A to E has exacerbated the calculated weaknesses and introduced further issues arising from localised heave and/or settlement of the ground resulting in the rotation of a number of masonry piers, the loss of bearing to the edge of the precast floors over the external stairwells and the addition of loading to various structural elements.

The seismic performance of a damaged 2-storey unit has an expected strength of 30%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

### **C) 3-Storey Units**

The 3-storey units pose a potential collapse hazard. Currently, the lateral restraint to the upper two levels of the units is provided by the out-of-plane capacity of the upper storey and a single in-plane wall on the first floor. Failure of the lateral resisting system will result in a high risk of collapse of the upper storeys onto the surrounding properties. The potential hazard zone includes the residential units on either side of the 3-storey unit

The settlement which has occurred around Blocks A to E has exacerbated the calculated weaknesses and introduced further issues arising from localised heave and/or settlement of the ground resulting in additional loading to the various structural elements.

The seismic performance of a damaged 3-storey unit has an expected strength of 14%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade E - high risk structure in accordance with NZSEE guidelines.

### **8.6 Limitations and Assumptions in Results**

Our analysis is based on a quantitative assessment of the building in its undamaged state. The damage observed on-site to structural elements has been considered qualitatively in this report as it difficult to accurately quantify, as a %NBS, the detrimental effect of this damage. Where damage was considered severe enough to comprise the integrity of the affected structural elements it is our understanding that the relevant units have already been closed. There may have been additional damage to the buildings that was unable to be observed during assessments that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity;
- Assessments of material strengths based on limited drawings, specifications and site inspections;
- The normal variation in material properties which change from batch to batch;
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.



## **9 Geotechnical Assessment**

### **9.1 Introduction**

This section summarises the findings of a Geotechnical Desk Study and Site Walkovers completed on 10 May 2011 and 26 July 2012. The purpose of this desk study is to provide an initial appraisal of the suitability of the land and the future bearing capacity, in accordance with CCC email request of 18 April 2011.

### **9.2 Ground Conditions**

A desk study of geotechnical investigations in the area from Environment Canterbury and EQC identified four logs and five CPT tests within 200m of the site, refer to Location Plan Appendix A. Drill Hole M36/0964, drilled in 1899, was performed adjacent to Unit 402 Brougham Street.

A geological cross-section completed by EQC has been identified adjacent to the site along Brougham Street.

The borehole records, CPT test results and the geological cross-section are included in Appendix A.

The geological cross-section summarises the ground conditions in the area, which are Silty SAND from surface to a depth of 5m below ground level (bgl); SAND and GRAVEL to 7.5m bgl; Sandy GRAVEL to a depth of 11m bgl; Sandy SILT to a depth of 12m bgl; Gravelly SAND to a depth of 23.5m bgl and Sandy GRAVEL to a depth of 27.5m bgl.

The sloping ground, as indicated by the as built drawings is man-made. A specification for the hardfill material that comprises the sloping ground indicates that well graded, face-cut pitrun with a maximum grain size of 75mm has been used in conjunction with a crushed, “no fines” fill with a size range of 25mm and 40mm.

### **9.3 Ground Damage and Ground Induced Building Damage**

As-built drawings have been provided and indicate that the foundation system for the Brougham Village is strip footings to varying depths between 250mm and 700mm bgl. The floor slab is unreinforced concrete, varying in thickness between 100mm and 250mm.

An inspection of an open excavation adjacent to Unit 396 identified that the hardfill is not face-cut, and is sub-rounded to rounded in nature with a maximum size of 100mm, refer to photographs.

No signs of foundation subsidence were observed. A maximum of 50mm to 100mm of horizontal and vertical displacement was observed in the tiled areas around units 356 to 400 Brougham Street, refer to photographs in Appendix D. The land movement has generally been downslope towards Brougham Street.

A number of units located at 356 – 400 Brougham Street have suffered significant structural damage, particularly the section of structure supporting the third storey. In contrast, there

appears to be no structural damage to units 95 and 97 Hastings Street East. There has been significant damage to the buried services throughout the site.

There is evidence of moderate liquefaction throughout the site. Surface disruption and ground heave up to 100mm vertically was recorded at two locations on the asphalt driveway and also a service trench to the north of Unit 402.

It was recommended in May 2011 that the ground floor slabs within all the garages are checked for subsidence and liquefaction. Also the foundations for the 4 units at 131 Hastings Street East should be inspected as unit 2 was yellow stickered due to severe liquefaction. These proposed ground investigations have not yet been undertaken.

#### **9.4 Liquefaction Hazard**

The 2003 ECAN Liquefaction study<sup>2</sup> indicates Brougham Village as having a moderate to high liquefaction potential under high groundwater conditions. Based on a low groundwater table, ground damage is expected to be moderate, subsidence likely to be between 100mm and 300mm.

No liquefaction was reported following the Darfield Earthquake of 4 September 2010.

Liquefaction was identified on site following both the 22 February 2011 and 13 June 2011 earthquake events, by both road observations and interpretation of aerial photos by Tonkin & Taylor<sup>3</sup>. The liquefaction identified was stated as moderate to severe.

Brougham Village is bounded by residential properties to the east, south and west that are located in the CERA “green” zone. The “green” zone has been further categorised into technical categories by the Department of Building and Housing (DBH). This site is bounded by both “Technical Category 2” (TC2) and “Technical Category 3” (TC3) sites. The DBH technical categories are guidelines for residential foundations, however are likely to be used as a guideline by the Christchurch City Council for building consent. TC2 identifies the area may be subject to minor to moderate land damage from liquefaction in future large earthquakes, whilst TC3 identifies the area may be subject to moderate to significant land damage from liquefaction in future large earthquakes.

#### **9.5 Appraisal**

In summary, minimal damage to building foundations has occurred as a result of liquefaction following the 22 February 2011 earthquake. The slab on grade and shallow foundations appear to have performed adequately with only minor damage being reported.

The site is comprised of imported fill material that slopes gently towards Brougham Street. The sloped ground profile has caused lateral spreading of the fill material on top of a liquefied soil layer. This is evident from cracks in the ground between buildings at the north-eastern corner of the site and indicates approximately 50mm of lateral movement. There

---

<sup>2</sup> ECan, The Solid Facts on Christchurch Liquefaction

<sup>3</sup> Project Orbit, 2011, Interagency/Organisation Collaboration Portal for Christchurch Recovery Effort, <http://canterburyrecovery.projectorbit.com/sitepages/home.aspx>

are no streams or open watercourses within close proximity of the site that enhance the risk of lateral spreading.

GNS Science<sup>4</sup> indicates an elevated risk of seismic activity is expected in the Canterbury region as a result of the earthquake sequence following the 4 September 2010 earthquake. Recent advice (Geonet) indicates there is a 14% probability of another Magnitude 6 or greater earthquake occurring in the next 12 months in the Canterbury region. It is expected that the probability of occurrence is likely to decrease with time, following periods of reduced seismic activity. However, similar ground damage to that experienced in February 2011 could re-occur if a future earthquake generated similar or greater intensity ground shaking at this site.

This report has identified a significant risk that liquefaction will occur again in the life of the buildings. This risk could be quantified with additional analysis to provide a risk based assessment of the expected future performance of the land.

## **9.6 Proposed Geotechnical Investigations**

It is recommended that as a minimum, the following geotechnical inspections are undertaken for the repair of the buildings.

- Inspect the ground floor slabs within all the Garages for units 356 to 400, to check for subsidence and liquefaction damage;
- Excavate and inspect foundations in key areas to confirm there has been no damage or ground disruption;
- Undertake a Level Survey of the buildings.

To determine the liquefaction potential of the site in future earthquakes and to identify the Technical Category of the site, the following site investigations (across the entire Brougham Village site) are recommended:

- 12 static Cone Penetration Tests (CPT) to confirm liquefaction potential.
- 2 boreholes to a depth of about 25m, with Standard Penetration Tests at 1.5m depth intervals, and install piezometer to monitor groundwater level.
- Assessment and reporting.

---

<sup>4</sup> GNS Science reporting on Geonet Website: <http://www.geonet.org.nz/canterbury-quakes/aftershocks/> updated on 9 July 2012.

## 10 Remedial Options

The buildings require strengthening, with a target of increasing the seismic performance to as near as practicable to 100%NBS, and to at least 67%NBS. Our concept strengthening scheme to achieve this would include:

- Addressing the issues with single storey units:
  - Repair all minor cracks using appropriate methods – epoxy grout injection techniques etc.;
  - Where walls have experienced major cracking and have evidently lost their structural integrity as indicated on a damage plan (to be provided by the Engineer), break out affected areas and replace to the Engineers specification;
  - Where indicated on the damage plan (to be provided by the Engineer), install adequate fixing between the north-south spanning walls which intersect the primary east-west spanning north elevation wall of the 2-storey unit to eliminate the out-of-plane issues with the walls;
  - Where differential or excessive settlement has occurred between adjacent walls, remove wall sections, break out foundations and replace with newly built footings on suitable bearing strata;
  - To increase the bracing capacity of the units install a diaphragm in the roof structure to eliminate the effect of out-of-plane bending on the walls.
- Addressing the issues with the 2-storey units:
  - Repair all minor cracks using appropriate methods – epoxy grout injection techniques etc.;
  - Where walls have experienced major cracking and yielding of reinforcement, break out affected areas and replace to the Engineers specification;
  - Where differential or excessive settlement has occurred between adjacent walls, remove wall sections, break out foundations and replace with newly built footings on suitable bearing strata;
  - To increase the bracing capacity of the units install a diaphragm in the roof structure to eliminate the effect of out-of-plane bending on the walls.
  - Install a permanent corner support to the cantilevering slab area;
- Addressing the issues with the 3-storey units:
  - There is a potential hazard posed by the 3-storey units. To mitigate the hazard a strengthening scheme will have to be developed to increase the capacity of the east-west lateral restraint system. Additional shear walls and load paths to the foundations maybe required to facilitate this requirement. Following an appraisal by a Quantity Surveyor it may be the case that it is more economically viable to remove the units
- Addressing the issues with the foundations:

- Locally, excessive settlement may occur as a result of the narrow existing footings when subject to the full seismic induced lateral loads. Where excessive settlement has occurred under affected shear walls it may be pertinent to upgrade the footings by widening the footing base to the Engineers specification.

Globally, the lateral spread has resulted in an amplification of the expected damage to the structures. It is expected that ground improvement measures and building re-levelling will be required to rectify the settlement issues encountered.

- A full geotechnical investigation of the site should be undertaken to determine the full extent of the lateral spread and differential settlement and to provide sufficient information to enable any strengthening works that will be required.

## **11 Conclusions**

The seismic performance of an undamaged single storey unit has an expected strength of 40%NBS. The seismic performance of a damaged single storey unit has an expected strength of 25%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

The seismic performance of the 2-storey unit has an expected strength of 48%NBS. The seismic performance of a damaged 2-storey unit has an expected strength of 30%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines.

The seismic performance of the 3-storey unit has an expected strength of 22%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade D - high risk structure in accordance with NZSEE guidelines. The seismic performance of a damaged 3-storey unit has an expected strength of 14%NBS and is Earthquake Prone as defined by legislation. It is considered to be a Grade E - high risk structure in accordance with NZSEE guidelines.

There has been significant ground movement in the area of Blocks A to E. The foundations to the structure are typically narrow strip footings which have not performed satisfactorily and the resulting differential settlement between units has significantly increased the expected level of damage.

There is a significant risk that liquefaction will occur again in the life of the buildings.

## **12 Recommendations**

All the recommendations are subject to the assumptions made during the quantitative assessment being qualified. The following recommendations are provided:

- a) Occupancy of the buildings should be reviewed based on the increased risk of failure of the buildings as outlined in the conclusions;
- b) The strengthening works concept scheme be further developed to increase the seismic capacity of the single storey and 2-storey to at least 67% NBS; this will need to consider compliance with accessibility and fire requirements;

- c) There is a potential hazard posed by the 3-storey units. To mitigate the hazard a strengthening scheme will have to be developed to increase the capacity of the east-west lateral restraint system. Following an appraisal by a Quantity Surveyor it may be the case that it is more economically viable to remove the units;
- d) Several geotechnical investigations be undertaken to quantify the liquefaction potential of the site and determine the soil shallow bearing strength of the existing foundations.

### **13 Limitations**

- a) This report is based on an inspection of the structure with a focus on the damage sustained from the 22 February 2011 Canterbury Earthquake and aftershocks only. Some non-structural damage is mentioned but this is not intended to be a comprehensive list of non-structural items.
- b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- c) This report is prepared for the CCC to assist with assessing remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

### **14 References**

- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC, *Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes*, Structural Engineering Society of New Zealand, 21 December 2011.

## **Appendix A – Photographs**



*Photo 1: West elevation of block A*



*Photo 2: South elevation of block A*





*Photo 3: View of a typical 3 storey section of building*



*Photo 4: 50mm settlement of a masonry wall 4 at the interface with adjacent unit*



*Photo 5: 60mm settlement with 40mm lateral displacement of slab and wall at the interface with adjacent unit*



*Photo 6: Cracking of suspended slab*



Photo 7: Unfilled concrete masonry void




Photo 8 and 9: Masonry piers out of plumb due to differential settlement and lateral spread



*Photo 10: Failure of wall cover concrete due to excess loading*

## **Appendix B – Floor Plan**





D A COWEY ASSOCIATES  
REGISTERED ARCHITECTS  
CHRISTCHURCH

HOLMES WOOD POOLE  
& JOHNSTONE  
CONSULTING ENGINEERS  
CHRISTCHURCH


BROUGHAM STREET — URBAN RENEWAL 1 — STAGE 1

DESIGN	SCALES	DATE
DRN: M.C.J. TRD: M.C.J. CHD: L.P.	1:200	July 75

SITE PREPARATION (1)  
CONTRACTOR SHALL VERIFY ALL DIMENSIONS BEFORE STARTING WORK

FILE	DRAWING
629	SP1





D A COWEY ASSOCIATES  
REGISTERED ARCHITECTS  
CHRISTCHURCH

HOLMES WOOD POOLE  
& JOHNSTONE  
CONSULTING ENGINEERS  
CHRISTCHURCH

BROUGHAM STREET — URBAN RENEWAL 1 — STAGE 1


DESIGN	SCALES	DATE
DRN: M.C.F. TRD: M.C.F. CHD: M.C.F. APD: M.C.F.	1 : 200	July '95

SITE PREPARATION (2)

FILE	DRAWING
629	SP2

CONTRACTOR SHALL VERIFY ALL DIMENSIONS BEFORE STARTING WORK







**LEGEND**

	HARDFILL
	TOPSOIL TO BE REMOVED AND REPLACED BY HARDFILL
	SUBSOIL TO BE REMOVED AND REPLACED BY HARDFILL
	TOP SOIL TO REMAIN
	TOP COURSE
	EXTENT OF EXCAVATION

D A COWEY ASSOCIATES REGISTERED ARCHITECTS CHRISTCHURCH	HOLMES WOOD POOLE & JOHNSTONE CONSULTING ENGINEERS CHRISTCHURCH	BROUGHAM STREET — URBAN RENEWAL 1 — STAGE 1	DESIGN	SCALES	DATE	SITE PREPARATION - SECTIONS	FILE	DRAWING
			DRN: MCJ TRD: MCJ CHK: PFB APD: R.A.T.	HORIZONTAL 1:100 VERTICAL 1:50	JULY 1981		629	SP 3


CONTRACTOR SHALL VERIFY ALL DIMENSIONS BEFORE STARTING WORK







key plan.

- standard 190 block construction.
  - special 190 insulated block construction.
  - shrinkage control joint.
  - 11A** wall number.
  - n.15900** floor level
  - 2** unit number
- note: foundation level refers to top of concrete foundation or underside of blockwork.



standard details for all level 1 plans.



typical groove details.

**D A Cowey Associates**  
Registered Architects  
Christchurch

**Holmes Wood Poole & Johnstone**  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 — STAGE 1

FLOOR PLAN,  
LEVEL 1, A-B.



Scale  
1:50  
Drawn  
S.J.K.  
Traced  
S.E.P.  
Approved  
[Signature]

D  
C  
B  
A 2:2:76 footing wall 19  
2.3.75 Contract


**629/S1A**

The Contractor shall verify all dimensions prior to commencing work.






- key plan**
- standard 190 block construction
  - special 190 insulated block construction
  - shrinkage control joints
  - 64 A** wall number
  - r.l. 15500** floor level
  - 7** unit number
- note: foundation level refers to top of concrete foundation or underside of blockwork



<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p><b>BROUGHAM STREET</b></p> <p>URBAN RENEWAL 1 - STAGE 1</p>	<p>FLOOR PLAN LEVEL 1, B - C</p>	<p>Scale 1 : 50 1 : 20</p> <p>Drawn S.J.K. Traced D.K.R. Approved <i>[Signature]</i></p>	<p>D C B A 2:2.76 footing - walls 19, 30 &amp; 48 2.9.75 Contract</p>	<p>629/S2A</p>
---	---	--	--------------------------------------	--	---	----------------






key plan.

- standard no block construction.
- special no insulated block construction.
- shrinkage control joints.
- 64 A** wall number.
- 13** unit number.
- 64** floor level.

note: foundation level refers to top of concrete foundation or underside of blockwork.



**D A Cowey Associates**  
Registered Architects  
Christchurch

**Holmes Wood Poole & Johnstone**  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

**BROUGHAM STREET**  
URBAN RENEWAL 1 - STAGE 1

**FLOOR PLAN**  
LEVEL 1, C-D.


Scale: 1:50  
Drawn: S.J.K.  
Traced: S.E.P.  
Approved: [Signature]

D  
C  
B  
A 2:2:76 Footing walls: 48, 49 & 50  
2.9.76 Contract




**629/S3A**



D



key plan



D A Cowey Associates  
Registered Architects  
Christchurch

Holmes Wood Poole & Johnstone  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 - STAGE 1

FLOOR PLAN  
LEVEL 1, D - E



Scale 1 : 50  
1 : 20  
Drawn S.J.K.  
Traced D.K.R.  
Approved [Signature]

D  
C  
B  
A 2.2.7b footing walls 50 & 57  
2.2.7c Contract



629/S4A

The Contractor shall verify all dimensions prior to commencing work.







- key plan
- standard 150 block construction
  - special 150 insulated block construction
  - shrinkage control joints
  - wall number
  - floor level
- note: foundation level refers to top of concrete foundation or underside of blockwork



<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p><b>BROUGHAM STREET</b></p> <p>URBAN RENEWAL 1 — STAGE 1</p>	<p><b>FLOOR PLAN</b> LEVEL 1, E-F CENTRAL SERVICE AREA</p>	<p>Scale 1 : 50 1 : 20</p> <p>Drawn S.J.K. Traced D.K.R. Approved </p>	<p>D C B A 2:2:76 footing wall 87 2.9.75 Contract</p>	<p><b>629/5A</b></p> <p><small>The Contractor shall verify all dimensions prior to commencing work.</small></p>
---	---	--	--	--	---	---





key plan.

- standard 190 block construction.
  - special 190 insulated block construction.
  - shrinkage control joints.
  - wall number.
  - floor level.
  - 23** unit number.
- note: foundation level refers to top of concrete foundation or underside of blockwork.

see dwg 629/S6 for central service area.

**D A Cowey Associates**  
Registered Architects  
Christchurch

**Holmes Wood Poole & Johnstone**  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 — STAGE 1

FLOOR PLAN  
LEVEL 1, E-F  
UNITS 23, 24, 25, 26.




Scale 1:50  
Drawn S.J.K.  
Traced S.E.P.  
Approved

D	_____
C	_____
B	_____
A	_____
23-75	Contract

**629/S6**

The Contractor shall verify all dimensions prior to commencing work.






<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p><b>BROUGHAM STREET</b></p> <p>URBAN RENEWAL 1 — STAGE 1</p>	<p><b>FLOOR PLAN</b></p> <p>LEVEL 1, F-G.</p>	<p>Scale 1 : 50</p> <p>Drawn S.J.K.</p> <p>Traced S.E.P.</p> <p>Approved <i>[Signature]</i></p>	<p>D</p> <p>C</p> <p>B</p> <p>A 2:2.7% footing-walls 87, 88, 97</p> <p>2-9-75 Contract</p>	<p>629/S7A</p>
---	---	--	---	---	--	----------------

The Contractor shall verify all dimensions prior to commencing work.




6

H



key plan

- standard 180 block construction
  - special 180 insulated block construction
  - shrinkage control joints
  - wall number
  - floor level
  - unit number
- note: foundation level refers to top of concrete and underside of blockwork



D A Cowey Associates  
Registered Architects  
Christchurch

Holmes Wood Poole & Johnstone  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 - STAGE 1

FLOOR PLANS  
LEVEL 1, G-H

Scale 1 : 50  
Drawn S.J.K.  
Traced D.K.R.  
Approved [Signature]



D  
C  
B  
A 2:2.7b footing - walls 97, 98 & 105  
2-9-75 Contract

629/S8A



H

J



**key plan**

- standard 190 block construction
- special 190 insulated block construction
- shrinkage control joints.
- wall number.
- floor level.
- unit number.


note: foundation level refers to top of concrete and underside of blockwork.

<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p><b>BROUGHAM STREET</b></p> <p>URBAN RENEWAL 1 — STAGE 1</p>	<p>FLOOR PLAN</p> <p>LEVEL 1, H-J</p>	<p>Scale 1:50</p> <p>Drawn S.J.K</p> <p>Traced K.A.L.</p> <p>Approved </p>	<p>D _____</p> <p>C _____</p> <p>B _____</p> <p>A 2:2:76 footing - walls 105, 106 &amp; 116</p> <p>2:9:75 Contract</p>
					<p><b>629/S9A</b></p> <p><small>The Contractor shall verify all dimensions prior to commencing work.</small></p>



J



K



**key plan**


- standard 150 block construction
- special 150 insulated block construction
- shrinkage control joints
- 4A** wall number
- fl 16500** floor level
- 45** unit number

note: foundation level refers to top of concrete and underside of blockwork.




<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p><b>BROUGHAM STREET</b></p> <p>URBAN RENEWAL 1 — STAGE 1</p>	<p>FLOOR PLAN LEVEL 1, J - K</p>	<p>Scale 1 : 50</p> <p>Drawn S. J. K.</p> <p>Traced H. M. N.</p> <p>Approved </p>	<p>D _____</p> <p>C _____</p> <p>B _____</p> <p>A 2: 2.76 footing - walls 116 &amp; 117</p> <p>2.9.75 Contract</p>	<p><b>629/S10A</b></p> <p><small>The Contractor shall verify all dimensions prior to commencing work.</small></p>
---	---	--	--------------------------------------	---	--	---












plan A - B




key plan


-  standard 150 block construction
-  special 150 insulated block construction
-  shrinkage control joints
-  wall number
-  floor level
-  unit number




plan B - C



standard details level 2 slabs



standard details level 2 slabs



standard details level 2 slab

**D A Cowey Associates**  
Registered Architects  
Christchurch

**Holmes Wood Poole & Johnstone**  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 - STAGE 1


FLOOR PLAN - CARCASS  
LEVEL 2, A - B, B - C

Scale 1 : 50  
1 : 20  
Drawn S.J.K.  
Traced D.K.R.  
Approved [Signature]


D  
C  
B  
A  
2.9.75 Contract

629 / S11







plan A - B



mesh sheet type A : 333 off




40 standard detail




41 standard details

42




43 standard detail



44 standard details

45



plan B - C

D A Cowey Associates  
Registered Architects  
Christchurch

Holmes Wood Poole & Johnstone  
Consulting Civil & Structural Engineers  
Christchurch & Wellington


BROUGHAM STREET  
URBAN RENEWAL 1 - STAGE 1

FLOOR REINFORCEMENT  
LEVEL 2, A-B, B-C


Scale 1 : 50  
D  
C  
B  
A  
2-9-75 Contract

629 / S12  
The Contractor shall verify all dimensions prior to commencing work






plan C-E




key plan

- standard 150 block construction
- special 150 insulated block construction
- shrinkage control joints
- wall number
- floor level
- unit number




<p><b>D A Cowey Associates</b> Registered Architects Christchurch</p>	<p><b>Holmes Wood Poole &amp; Johnstone</b> Consulting Civil &amp; Structural Engineers Christchurch &amp; Wellington</p>	<p>BROUGHAM STREET URBAN RENEWAL 1 — STAGE 1</p>	<p>FLOOR PLANS — CARCASS LEVEL 2, C-E</p>	<p>Scale 1:50 Drawn S.J.K. Traced C.C.P. Approved </p>	<p>D C B A 2.3.75 Contract</p>	<p><b>629/S13</b></p>
---	---	--	---	--	--	-----------------------





plan C - E  
(see dwg 512 for typical mesh sheet type A)



D A Cowey Associates  
Registered Architects  
Christchurch

Holmes Wood Poole & Johnstone  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 - STAGE 1



FLOOR REINFORCEMENT  
LEVEL 2, C-E

Scale 1 : 50  
1 : 20  
Drawn S. J. K.  
Traced D. K. R.  
Approved [Signature]  
2.9.75 Contract







629 / S14






The Contractor shall verify all dimensions prior to commencing work.





key plan

-  standard 190 block construction
-  special 190 insulated block construction
-  shrinkage control joints
-  wall number
-  floor level
-  unit number



**D A Cowey Associates**  
Registered Architects  
Christchurch

**Holmes Wood Poole & Johnstone**  
Consulting Civil & Structural Engineers  
Christchurch & Wellington

BROUGHAM STREET  
URBAN RENEWAL 1 — STAGE 1

FLOOR PLAN — CARCASS  
LEVEL 2, E — F

Scale 1:20  
1:50  
Drawn S.J.K.  
Traced H.M.N.  
Approved J.H.W.

D	
C	
B	
A	
2-5-75	Contract

629 / S15



## **Appendix C – DEE Spreadsheet**



Location Building Name: <input type="text" value="Single Storey Units"/> Unit No: <input type="text" value="1"/> Street: <input type="text" value="356-400 Brougham St."/> Building Address: <input type="text" value="356-400 Brougham St."/> Legal Description: <input type="text" value=""/>		Reviewer: <input type="text" value="John Mitchell"/> CPEng No: <input type="text" value="1096738"/> Company: <input type="text" value="Opus International Consultants"/> Company project number: <input type="text" value="6-OUCC-82"/> Company phone number: <input type="text" value="06-3569560"/>	
GPS south: <input type="text" value="43"/> <input type="text" value="32"/> <input type="text" value="E2,00"/> GPS east: <input type="text" value="172"/> <input type="text" value="38"/> <input type="text" value="35,00"/> Building Unique Identifier (CCI): <input type="text" value="BE-1072 E02"/>		Date of submission: <input type="text" value="1/10/2012"/> Inspection Date: <input type="text" value="Jul-12"/> Revision: <input type="text" value="Final V3"/> Is there a full report with this summary?: <input type="text" value="Yes"/>	

Site slope: <input type="text" value="flat"/> Soil type: <input type="text" value="mixed"/> Site Class (to NZS1170.5): <input type="text" value="D"/> Proximity to waterway (m, if <100m): <input type="text" value=""/> Proximity to cliff top (m, if <100m): <input type="text" value=""/> Proximity to cliff base (m, if <100m): <input type="text" value=""/>	Max retaining height (m): <input type="text" value="0"/> Soil Profile (if available): <input type="text" value="N/A"/> If Ground improvement on site, describe: <input type="text" value=""/> Approx site elevation (m): <input type="text" value="16,00"/>
--	--

No. of storeys above ground: <input type="text" value="1"/> Ground floor split? <input type="text" value="no"/> Storeys below ground: <input type="text" value="0"/> Foundation type: <input type="text" value="strip footings"/> Building height (m): <input type="text" value="4,20"/> Floor footprint area (approx): <input type="text" value="50"/> Age of Building (years): <input type="text" value="39"/>	single storey = 1 Ground floor elevation (Absolute) (m): <input type="text" value="varies"/> Ground floor elevation above ground (m): <input type="text" value="varies"/> if Foundation type is other, describe: height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value=""/> Date of design: <input type="text" value="1965-1976"/>
Strengthening present? <input type="text" value="no"/> Use (ground floor): <input type="text" value="multi-unit residential"/> Use (upper floors): <input type="text" value=""/> Use notes (if required): <input type="text" value=""/> Importance level (to NZS1170.5): <input type="text" value="IL2"/>	If so, when (year)? <input type="text" value=""/> And what load level (%)? <input type="text" value=""/> Brief strengthening description: <input type="text" value=""/>

Gravity Structure Gravity System: <input type="text" value="load bearing walls"/> Roof: <input type="text" value="timber framed"/> Floors: <input type="text" value="other (note)"/> Beams: <input type="text" value="none"/> Columns: <input type="text" value="load bearing walls"/> Walls: <input type="text" value="fully filled concrete masonry"/>	rafter type, purlin type and cladding: <input type="text" value="mixed (raft sizes up to 200mm deep)"/> describe system: <input type="text" value=""/> overall depth x width (mm x mm): <input type="text" value="600x190"/> typical dimensions (mm x mm): <input type="text" value="N/A"/>
--	--

Lateral load resisting structure Lateral system along: <input type="text" value="fully filled CMU"/> Ductility assumed, μ: <input type="text" value="1,25"/> Period along: <input type="text" value="0,40"/> Total deflection (ULS) (mm): <input type="text" value=""/> maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>	Note: Define along and across in detailed report! note total length of wall at ground (m): <input type="text" value=""/> wall thickness (m): <input type="text" value=""/> estimate or calculation? <input type="text" value="estimated"/> estimate or calculation? <input type="text" value=""/> estimate or calculation? <input type="text" value=""/>
Lateral system across: <input type="text" value="fully filled CMU"/> Ductility assumed, μ: <input type="text" value="1,25"/> Period across: <input type="text" value="0,40"/> Total deflection (ULS) (mm): <input type="text" value=""/> maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>	note total length of wall at ground (m): <input type="text" value=""/> wall thickness (m): <input type="text" value=""/> estimate or calculation? <input type="text" value=""/> estimate or calculation? <input type="text" value=""/> estimate or calculation? <input type="text" value=""/>

Separations: north (mm): <input type="text" value=""/> east (mm): <input type="text" value=""/> south (mm): <input type="text" value=""/> west (mm): <input type="text" value=""/>	Leave blank if not relevant
--	-----------------------------

Non-structural elements Stairs: <input type="text" value=""/> Wall cladding: <input type="text" value="Other (specify)"/> Roof cladding: <input type="text" value="aluminum frames"/> Cladding: <input type="text" value="aluminum frames"/> Ceilings: <input type="text" value="none"/> Services (list): <input type="text" value=""/>	describe: <input type="text" value="Woodtex Panels"/>
---	---

Available documentation Architectural: <input type="text" value="none"/> Structural: <input type="text" value="partial"/> Mechanical: <input type="text" value="none"/> Electrical: <input type="text" value="none"/> Geotech report: <input type="text" value=""/>	original designer name/date: <input type="text" value=""/> original designer name/date: <input type="text" value="Lidjms, Wood, Poole &amp; Johnstone"/> original designer name/date: <input type="text" value=""/> original designer name/date: <input type="text" value=""/> original designer name/date: <input type="text" value=""/>
--	---

Damage Site: Site performance: <input type="text" value="Poor"/> Settlement: <input type="text" value="25-100mm"/> Differential settlement: <input type="text" value="1:250-1:250"/> Liquefaction: <input type="text" value="2-5 m&lt;sup&gt;2&lt;/sup&gt;/100m&lt;sup&gt;2&lt;/sup&gt;"/> Lateral Spread: <input type="text" value="0-50mm"/> Differential lateral spread: <input type="text" value="1:400-1:100"/> Ground cracks: <input type="text" value="none apparent"/> Damage to areas: <input type="text" value="moderate to substantial (1 in 5)"/>	Describe damage: <input type="text" value="Lateral Spread and differential settlement"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/> notes (if applicable): <input type="text" value="Estimate (geotech report not available)"/>
---	--

Building: Current Placard Status: <input type="text" value="green"/>	Along Damage ratio: <input type="text" value="38%"/> Describe (summary): <input type="text" value="Damage ratio varies across units from worst case 38% to 0%"/>	Describe how damage ratio arrived at: <input type="text" value="refer to report"/>
Across Damage ratio: <input type="text" value="38%"/> Describe (summary): <input type="text" value="Damage ratio varies across units from worst case 38% to 0%"/>	$\text{Damage Ratio} = \frac{(\% \text{ NBS (before)} - \% \text{ NBS (after)})}{\% \text{ NBS (before)}}$	
Diaphragms: <input type="text" value="no"/> Describe: <input type="text" value=""/>	CSWs: <input type="text" value="no"/> Describe: <input type="text" value=""/>	Pounding: <input type="text" value="no"/> Describe: <input type="text" value=""/>
Non-structural: <input type="text" value="yes"/> Describe: <input type="text" value=""/>		

Recommendations Level of repair/strengthening required: <input type="text" value="significant structural"/> Building Consent required: <input type="text" value="yes"/> Interim occupancy recommendations: <input type="text" value="partial occupancy"/>	Describe: <input type="text" value="refer to report"/> Describe: <input type="text" value="Units closed by CCC are 25,26,33,34,37,39,40,43,44,45,47"/>
Along Assessed %NBS before: <input type="text" value="40%"/> Assessed %NBS after: <input type="text" value="25%"/>	##### %NBS from IEP below If IEP not used, please detail assessment methodology: <input type="text" value="DEE Assessment"/>
Across Assessed %NBS before: <input type="text" value="40%"/> Assessed %NBS after: <input type="text" value="25%"/>	##### %NBS from IEP below

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): <input type="text" value="1965-1976"/> Seismic Zone, if designed between 1965 and 1992: <input type="text" value=""/>	h <sub>s</sub> from above: <input type="text" value="m"/> not required for this age of building not required for this age of building																									
Period from above: <input type="text" value="0,4"/> (%NBS from Fig 3.3)	along: <input type="text" value="0,4"/> across: <input type="text" value="0,4"/>																									
Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1,25; 1965-1976, Zone A = 1,33; 1965-1976, Zone B = 1,2; all else 1,0 Note 2: for RC buildings designed between 1976-1984, use 1,2 Note 3: for buildings designed prior to 1935 use 0,8, except in Wellington (1,0)	along: <input type="text" value="1,0"/> across: <input type="text" value="1,0"/> across: <input type="text" value="1,2"/>																									
Final (%NBS) <sub>req</sub> : <input type="text" value="0%"/>	along: <input type="text" value="0%"/> across: <input type="text" value="0%"/>																									
2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, d 3.1.6: <input type="text" value=""/> Near Fault scaling factor (1/N(T,D), Factor A): <input type="text" value="#DIV/0!"/>	along: <input type="text" value=""/> across: <input type="text" value="#DIV/0!"/>																									
2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3: Zone, from NZS4203:1992: <input type="text" value=""/> Hazard scaling factor, Factor B: <input type="text" value="#DIV/0!"/>	along: <input type="text" value=""/> across: <input type="text" value="#DIV/0!"/>																									
2.4 Return Period Scaling Factor Building Importance level (from above): <input type="text" value="2"/> Return Period Scaling factor from Table 3.1, Factor C: <input type="text" value="1,00"/>	along: <input type="text" value="1,00"/> across: <input type="text" value="1,00"/>																									
2.5 Ductility Scaling Factor Assessed ductility (less than max in Table 3.2): <input type="text" value="1,00"/> Ductility scaling factor = 1 from 1976 onwards; or = μ, if pre-1976, from Table 3.3: Ductility Scaling Factor, Factor D: <input type="text" value="0,00"/>	along: <input type="text" value="1,00"/> across: <input type="text" value="1,00"/> along: <input type="text" value="0,00"/> across: <input type="text" value="0,00"/>																									
2.6 Structural Performance Scaling Factor: Sp: <input type="text" value=""/> Structural Performance Scaling Factor Factor E: <input type="text" value="#DIV/0!"/>	along: <input type="text" value="#DIV/0!"/> across: <input type="text" value="#DIV/0!"/>																									
2.7 Baseline %NBS, (NBS) <sub>0</sub> = (%NBS) <sub>req</sub> x A x B x C x D x E Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)	%NBS <sub>0</sub> : <input type="text" value="#DIV/0!"/>																									
3.1. Plan Irregularity, factor A: <input type="text" value="1"/>																										
3.2. Vertical irregularity, Factor B: <input type="text" value="1"/>																										
3.3. Short columns, Factor C: <input type="text" value="1"/>																										
3.4. Pounding potential Pounding effect D1, from Table to right: <input type="text" value="1,0"/> Height Difference effect D2, from Table to right: <input type="text" value="1,0"/> Therefore, Factor D: <input type="text" value="1"/>	<table border="1"> <tr> <th colspan="2">Table for selection of D1</th> <th>Severe</th> <th>Significant</th> <th>Insignificant/none</th> </tr> <tr> <td>Separation</td> <td>0 &lt; sep &lt; 0,05H</td> <td>0,05 &lt; sep &lt; 0,1H</td> <td>Sepp &gt; 0,1H</td> <td></td> </tr> <tr> <td>Alignment of floors within 20% of H</td> <td>0,4</td> <td>0,8</td> <td>1</td> <td></td> </tr> <tr> <td>Alignment of floors not within 20% of H</td> <td>0,4</td> <td>0,7</td> <td>0,8</td> <td></td> </tr> </table>	Table for selection of D1		Severe	Significant	Insignificant/none	Separation	0 < sep < 0,05H	0,05 < sep < 0,1H	Sepp > 0,1H		Alignment of floors within 20% of H	0,4	0,8	1		Alignment of floors not within 20% of H	0,4	0,7	0,8						
Table for selection of D1		Severe	Significant	Insignificant/none																						
Separation	0 < sep < 0,05H	0,05 < sep < 0,1H	Sepp > 0,1H																							
Alignment of floors within 20% of H	0,4	0,8	1																							
Alignment of floors not within 20% of H	0,4	0,7	0,8																							
3.5. Site Characteristics: <input type="text" value="1"/>	<table border="1"> <tr> <th colspan="2">Table for Selection of D2</th> <th>Severe</th> <th>Significant</th> <th>Insignificant/none</th> </tr> <tr> <td>Separation</td> <td>0 &lt; sep &lt; 0,05H</td> <td>0,05 &lt; sep &lt; 0,1H</td> <td>Sepp &gt; 0,1H</td> <td></td> </tr> <tr> <td>Height difference &gt; 4 storeys</td> <td>0,4</td> <td>0,7</td> <td>1</td> <td></td> </tr> <tr> <td>Height difference 2 to 4 storeys</td> <td>0,7</td> <td>0,9</td> <td>1</td> <td></td> </tr> <tr> <td>Height difference &lt; 2 storeys</td> <td>1</td> <td>1</td> <td>1</td> <td></td> </tr> </table>	Table for Selection of D2		Severe	Significant	Insignificant/none	Separation	0 < sep < 0,05H	0,05 < sep < 0,1H	Sepp > 0,1H		Height difference > 4 storeys	0,4	0,7	1		Height difference 2 to 4 storeys	0,7	0,9	1		Height difference < 2 storeys	1	1	1	
Table for Selection of D2		Severe	Significant	Insignificant/none																						
Separation	0 < sep < 0,05H	0,05 < sep < 0,1H	Sepp > 0,1H																							
Height difference > 4 storeys	0,4	0,7	1																							
Height difference 2 to 4 storeys	0,7	0,9	1																							
Height difference < 2 storeys	1	1	1																							
3.6. Other factors, Factor F For ≤ 3 storeys, max value = 2,5, otherwise max value = 1,5, no minimum Rationale for choice of F factor, if not 1: <input type="text" value=""/>	along: <input type="text" value=""/> across: <input type="text" value=""/>																									
Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6) List any: <input type="text" value=""/> Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses																										
3.7. Overall Performance Achievement ratio (PAR) PAR x Baseline %NBS: <input type="text" value="0,00"/>	along: <input type="text" value="0,00"/> across: <input type="text" value="0,00"/>																									
4.3 PAR x (%NBS) <sub>0</sub> : <input type="text" value="#DIV/0!"/>	along: <input type="text" value="#DIV/0!"/> across: <input type="text" value="#DIV/0!"/>																									
4.4 Percentage New Building Standard (%NBS) <sub>0</sub> (before): <input type="text" value="#DIV/0!"/>	along: <input type="text" value="#DIV/0!"/> across: <input type="text" value="#DIV/0!"/>																									

Location Building Name: 2-Storey Units Building Address: 356-400 Brougham St. Legal Description:		Reviewer: John Mitchell CPEng No: 1096738 Company: Opus International Consultants Company project number: 6-OUCC032 Company phone number: 06-3569560	
GPS south: 43 GPS east: 172		Date of submission: 1/10/2012 Inspection Date: Revision: Final V3 Is there a full report with this summary?: Yes	
Building Unique Identifier (CCI): BE 1072 EQ2			

Site Site slope: flat Soil type: mixed Site Class (to NZS1170.5): D Proximity to waterway (m, if <100m): Proximity to cliff top (m, if <100m): Proximity to cliff base (m, if <100m):	Max retaining height (m): Soil Profile (if available): If Ground improvement on site, describe: Approx site elevation (m): 15.00
---	---

Building No. of storeys above ground: 2 Ground floor split? no Storeys below ground: 0 Foundation type: strip footings Building height (m): 6.50 Floor footprint area (approx): 181 Age of Building (years): 39	single storey = 1 Ground floor elevation (Absolute) (m): varies Ground floor elevation above ground (m): varies if Foundation type is other, describe: height from ground to level of uppermost seismic mass (for IEP only) (m): Date of design: 1965-1976
Strengthening present? no Use (ground floor): parking Use (upper floors): multi-unit residential Use notes (if required): Importance level (to NZS1170.5): L2	If so, when (year)? And what load level (%g)? Brief strengthening description:

Gravity Structure Gravity System: load bearing walls Roof: timber framed Floors: concrete flat slab Beams: cast-in-situ concrete Columns: load bearing walls Walls: fully filled concrete masonry	rafter type, purlin type and cladding: mixed (dist sizes up to 200mm deep) slab thickness (mm): 150 overall depth x width (mm x mm): 400x190 typical dimensions (mm x mm): varies
---	--

Lateral load resisting structure Lateral system along: Ductility assumed, $\mu$ : 2.00 Period along: 0.40 Total deflection (ULS) (mm): maximum interstorey deflection (ULS) (mm):	Note: Define along and across in detailed report! note total length of wall at ground (m): wall thickness (m): estimate or calculation?: estimate or calculation?: estimate or calculation?:
Lateral system across: Ductility assumed, $\mu$ : 2.00 Period across: 0.40 Total deflection (ULS) (mm): maximum interstorey deflection (ULS) (mm):	note total length of wall at ground (m): wall thickness (m): estimate or calculation?: estimate or calculation?: estimate or calculation?:

Separations: north (mm): east (mm): south (mm): west (mm):	Leave blank if not relevant
--	-----------------------------

Non-structural elements Stairs: precast, full flight Wall cladding: Other (specify) Roof cladding: aluminum frames Cladding: plaster, fixed Services (st):	describe supports: describe: Woodtex Panels
---	--

Available documentation Architectural: none Structural: partial Mechanical: none Electrical: none Geotech report:	original designer name/date: original designer name/date: Lidjms, Wood, Poole & Johnstone original designer name/date: original designer name/date: original designer name/date:
--	--

Damage Site: Site performance: Poor Settlement: 25-100mm Differential settlement: 1:250-1:250 Liquefaction: 2.5 m <sup>2</sup> /100m <sup>2</sup> Lateral Spread: 0-50mm Differential lateral spread: 1:400-1:100 Ground cracks: none apparent Damage to area: moderate to substantial (1 in 5)	Describe damage: Lateral Spread and differential settlement notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available)
--	---

Building: Current Placard Status: yellow Along: Damage ratio: 38% Describe (summary): Damage ratio varies across units from worst case 38% to 0% Across: Damage ratio: 38% Describe (summary): Damage ratio varies across units from worst case 38% to 0% Diaphragms: no CSWs: yes Pounding: no Non-structural: yes	Describe how damage ratio arrived at: refer to report $Damage \text{ Ratio} = \frac{(\% NBS \text{ (before)}) - \% NBS \text{ (after)}}{\% NBS \text{ (before)}}$ Describe: Describe: Describe: Describe:
--	---

Recommendations Level of repair/strengthening required: significant structural and strengthening Building Consent required: yes Interim occupancy recommendations: partial occupancy	Describe: refer to report Describe: Units closed by CCC are 42 and 44. Units open are 5,6,11,12
Along: Assessed %NBS before: 48% Assessed %NBS after: 30%	IF IEP not used, please detail assessment methodology: DEE Assessment #### %NBS from IEP below
Across: Assessed %NBS before: 48% Assessed %NBS after: 30%	#### %NBS from IEP below

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1965-1976 Seismic Zone, if designed between 1965 and 1992:	h <sub>s</sub> from above: m not required for this age of building not required for this age of building																																				
Period from above: (%NBS) from Fig 3.3:	along: 0.4 across: 0.4																																				
Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0 Note 2: for RC buildings designed between 1976-1984, use 1.2 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)	along: 1.00 across: 1.00																																				
Final (%NBS) <sub>req</sub> :	along: 0% across: 0%																																				
2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, d 3.1.6:	along: #DIV/0! across: #DIV/0!																																				
2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3: Zone, from NZS4203:1992: Hazard scaling factor, Factor B:	along: #DIV/0! across: #DIV/0!																																				
2.4 Return Period Scaling Factor Building Importance level (from above): 2 Return Period Scaling factor from Table 3.1, Factor C:	along: 1.00 across: 1.00																																				
2.5 Ductility Scaling Factor Assessed ductility (less than max in Table 3.2): Ductility scaling factor = 1 from 1976 onwards; or = $\mu$ , if pre-1976, from Table 3.3: Ductility Scaling Factor, Factor D:	along: 0.00 across: 0.00																																				
2.6 Structural Performance Scaling Factor: Sp:	Structural Performance Scaling Factor Factor E: #DIV/0! across: #DIV/0!																																				
2.7 Baseline %NBS, (NBS) <sub>0</sub> = (%NBS) <sub>req</sub> x A x B x C x D x E Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)	%NBS <sub>0</sub> : #DIV/0! across: #DIV/0!																																				
3.1. Plan Irregularity, factor A: 1 3.2. Vertical irregularity, Factor B: 1 3.3. Short columns, Factor C: 1 3.4. Pounding potential Pounding effect D1, from Table to right: 1.0 Height Difference effect D2, from Table to right: 1.0 Therefore, Factor D: 1 3.5. Site Characteristics: 1	<table border="1"> <tr> <th colspan="4">Table for selection of D1</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; 0.05H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Alignment of floors within 20% of H</td> <td>0.4</td> <td>0.8</td> <td>1</td> </tr> <tr> <td>Alignment of floors not within 20% of H</td> <td>0.4</td> <td>0.7</td> <td>0.8</td> </tr> </table> <table border="1"> <tr> <th colspan="4">Table for Selection of D2</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; 0.05H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Height difference &gt; 4 storeys</td> <td>0.4</td> <td>0.7</td> <td>1</td> </tr> <tr> <td>Height difference 2 to 4 storeys</td> <td>0.7</td> <td>0.9</td> <td>1</td> </tr> <tr> <td>Height difference &lt; 2 storeys</td> <td>1</td> <td>1</td> <td>1</td> </tr> </table>	Table for selection of D1				Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Alignment of floors within 20% of H	0.4	0.8	1	Alignment of floors not within 20% of H	0.4	0.7	0.8	Table for Selection of D2				Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Height difference > 4 storeys	0.4	0.7	1	Height difference 2 to 4 storeys	0.7	0.9	1	Height difference < 2 storeys	1	1	1
Table for selection of D1																																					
Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Alignment of floors within 20% of H	0.4	0.8	1																																		
Alignment of floors not within 20% of H	0.4	0.7	0.8																																		
Table for Selection of D2																																					
Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Height difference > 4 storeys	0.4	0.7	1																																		
Height difference 2 to 4 storeys	0.7	0.9	1																																		
Height difference < 2 storeys	1	1	1																																		
3.6. Other factors, Factor F For ≤ 3 storeys, max value = 2.5, otherwise max value = 1.5, no minimum Rationale for choice of F factor, if not 1: Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6) List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses	Along: #DIV/0! Across: #DIV/0!																																				
3.7. Overall Performance Achievement ratio (PAR) PAR x Baseline %NBS: #DIV/0! 4.3 PAR x (%NBS) <sub>0</sub> : #DIV/0! 4.4 Percentage New Building Standard (%NBS) <sub>0</sub> (before): #DIV/0!	0.00 0.00 #DIV/0! #DIV/0!																																				

Location Building Name: 3-Storey Units Building Address: 356-409 Brougham St. Legal Description:		Reviewer: John Mitchell CPEng No: 1096738 Company: Opus International Consultants Company project number: 6-0000002 Company phone number: 06-3569500	
GPS south: 43 GPS east: 172		Date of submission: 1/10/2012 Inspection Date: Jul-12 Revision: Final V3 Is there a full report with this summary?: Yes	
Degrees: 43 Min: 32 Sec: 00		Building Unique Identifier (CCI): BE-1072 EQ2	

Site Site slope: flat Soil type: mixed Site Class (to NZS1170.5): D Proximity to waterway (m, if <100m): Proximity to cliff top (m, if <100m): Proximity to cliff base (m, if <100m):	Max retaining height (m): 0 Soil Profile (if available): If Ground improvement on site, describe: Approx site elevation (m): 16.00
---	---

Building No. of storeys above ground: 2 Ground floor split? no Storeys below ground: 0 Foundation type: strip footings Building height (m): 10.00 Floor footprint area (approx): 24 Age of Building (years): 39	single storey = 1 Ground floor elevation (Absolute) (m): Ground floor elevation above ground (m): if Foundation type is other, describe: height from ground to level of uppermost seismic mass (for IEP only) (m): Date of design: 1965-1976
Strengthening present? no Use (ground floor): other (specify) Use (upper floors): multi-unit residential Use notes (if required): Importance level (to NZS1170.5): L2	If so, when (year)? And what load level (%)? Brief strengthening description:

Gravity Structure Gravity System: load bearing walls Roof: timber framed Floors: concrete flat slab Beams: cast-in-situ concrete Columns: load bearing walls Walls: fully filled concrete masonry	rafter type, purlin type and cladding: mixed (dist sizes up to 200mm deep) slab thickness (mm): 150 overall depth x width (mm x mm): 400x190 typical dimensions (mm x mm): castes #N/A
---	--

Lateral load resisting structure Lateral system along: Ductility assumed, $\mu$ : 2.00 Period along: 0.40 Total deflection (ULS) (mm): maximum interstorey deflection (ULS) (mm):	Note: Define along and across in detailed report! note total length of wall at ground (m): wall thickness (m): estimate or calculation?: estimate or calculation?: estimate or calculation?:
Lateral system across: Ductility assumed, $\mu$ : 2.00 Period across: 0.40 Total deflection (ULS) (mm): maximum interstorey deflection (ULS) (mm):	note total length of wall at ground (m): wall thickness (m): estimate or calculation?: estimate or calculation?: estimate or calculation?:

Separations: north (mm): east (mm): south (mm): west (mm):	leave blank if not relevant
--	-----------------------------

Non-structural elements Stairs: precast, full flight Wall cladding: other (specify) Roof cladding: aluminum frames Cladding: aluminum frames Ceilings: plaster, fixed Services (st):	describe supports: describe: Woodtex Panels
--	--

Available documentation Architectural: none Structural: partial Mechanical: none Electrical: none Geotech report:	original designer name/date: original designer name/date: original designer name/date: original designer name/date: original designer name/date:
--	--

Damage Site: Site performance: Poor Settlement: 25-100mm Differential settlement: 1:250-1:250 Liquefaction: 2.5 m <sup>2</sup> /100m <sup>2</sup> Lateral Spread: 0-50mm Differential lateral spread: 1:400-1:100 Ground cracks: none apparent Damage to area: moderate to substantial (1 in 5)	Describe damage: Lateral Spread and differential settlement notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available) notes (if applicable): Estimate (geotech report not available)
--	---

Building: Current Placard Status: red Along: Damage ratio: 50% Describe (summary): Damage ratio varies across units from worst case 50% to 0% Across: Damage ratio: 36% Describe (summary): Damage ratio varies across units from worst case 36% to 0% Diaphragms: no CSWs: yes Pounding: no Non-structural: yes	Describe how damage ratio arrived at: $Damage \ Ratio = \frac{(\% NBS \ (before) - \% NBS \ (after))}{\% NBS \ (before)}$ Describe: Describe: Describe: Describe:
---	--

Recommendations Level of repair/strengthening required: significant structural and strengthening Building Consent required: yes Interim occupancy recommendations: do not occupy	Describe: refer to report Describe: All units are closed - Units 55,56,57,58,59,60 and 61.
Along: Assessed %NBS before: 100% Assessed %NBS after: 50%	IF IEP not used, please detail assessment methodology: DEE Assessment #### %NBS from IEP below
Across: Assessed %NBS before: 22% Assessed %NBS after: 14%	#### %NBS from IEP below

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1965-1976 Seismic Zone, if designed between 1965 and 1992:	h <sub>s</sub> from above: m not required for this age of building not required for this age of building																																				
Period from above: (%NBS) from Fig 3.3:	along: 0.4 across: 0.4																																				
Note 1: for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0 Note 2: for RC buildings designed between 1976-1984, use 1.2 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)	along: 1.00 across: 1.00																																				
Final (%NBS) <sub>req</sub> :	along: 0% across: 0%																																				
2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, d 3.1.6:	along: #DIV/0! across: #DIV/0!																																				
2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3: Zone, from NZS4203:1992: Hazard scaling factor, Factor B:	along: #DIV/0! across: #DIV/0!																																				
2.4 Return Period Scaling Factor Building Importance level (from above): 2 Return Period Scaling factor from Table 3.1, Factor C:	along: 1.00 across: 1.00																																				
2.5 Ductility Scaling Factor Assessed ductility (less than max in Table 3.2): Ductility scaling factor = 1 from 1976 onwards; or = $\mu$ , if pre-1976, from Table 3.3: Ductility Scaling Factor, Factor D:	along: 0.00 across: 0.00																																				
2.6 Structural Performance Scaling Factor: Sp:	Structural Performance Scaling Factor Factor E: #DIV/0! across: #DIV/0!																																				
2.7 Baseline %NBS, (NBS%) <sub>0</sub> = (%NBS) <sub>req</sub> x A x B x C x D x E Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)	%NBS <sub>0</sub> : #DIV/0! across: #DIV/0!																																				
3.1. Plan Irregularity, factor A: 1 3.2. Vertical irregularity, Factor B: 1 3.3. Short columns, Factor C: 1 3.4. Pounding potential Pounding effect D1, from Table to right: 1.0 Height Difference effect D2, from Table to right: 1.0 Therefore, Factor D: 1 3.5. Site Characteristics: 1	<table border="1"> <tr> <th colspan="4">Table for selection of D1</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; 0.05H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Alignment of floors within 20% of H</td> <td>0.4</td> <td>0.8</td> <td>1</td> </tr> <tr> <td>Alignment of floors not within 20% of H</td> <td>0.4</td> <td>0.7</td> <td>0.8</td> </tr> </table> <table border="1"> <tr> <th colspan="4">Table for Selection of D2</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; 0.05H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Height difference &gt; 4 storeys</td> <td>0.4</td> <td>0.7</td> <td>1</td> </tr> <tr> <td>Height difference 2 to 4 storeys</td> <td>0.7</td> <td>0.9</td> <td>1</td> </tr> <tr> <td>Height difference &lt; 2 storeys</td> <td>1</td> <td>1</td> <td>1</td> </tr> </table>	Table for selection of D1				Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Alignment of floors within 20% of H	0.4	0.8	1	Alignment of floors not within 20% of H	0.4	0.7	0.8	Table for Selection of D2				Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Height difference > 4 storeys	0.4	0.7	1	Height difference 2 to 4 storeys	0.7	0.9	1	Height difference < 2 storeys	1	1	1
Table for selection of D1																																					
Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Alignment of floors within 20% of H	0.4	0.8	1																																		
Alignment of floors not within 20% of H	0.4	0.7	0.8																																		
Table for Selection of D2																																					
Separation	Severe 0 < sep < 0.05H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Height difference > 4 storeys	0.4	0.7	1																																		
Height difference 2 to 4 storeys	0.7	0.9	1																																		
Height difference < 2 storeys	1	1	1																																		
3.6. Other factors, Factor F For ≤ 3 storeys, max value = 2.5, otherwise max value = 1.5, no minimum Rationale for choice of F factor, if not 1: Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6) List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses	Along: Across: PAR x Baseline %NBS: #DIV/0! across: #DIV/0!																																				
3.7. Overall Performance Achievement ratio (PAR) PAR x Baseline %NBS:	0.00 across: 0.00																																				
4.3 PAR x (%NBS) <sub>0</sub> :	#DIV/0! across: #DIV/0!																																				
4.4 Percentage New Building Standard (%NBS) <sub>0</sub> (before)	#DIV/0!																																				

# **Appendix D – Geotechnical Desk Study**

## **July 2012**

---

TO Lindsay Fleming  
COPY Greg Saul, Sheryl Keenan  
FROM Graham Brown/Danielle Belcher  
DATE 27 July 2012  
FILE 6-QUCCC.92/105SC  
SUBJECT Brougham Village - Geotechnical Desk Study Revised

---



## **1. Introduction**

This memo summarises the findings of a Geotechnical Desk Study and Site Walkovers completed on 10 May 2011 and 26 July 2012. The purpose of this desk study is to provide an initial appraisal of the suitability of the land and the future bearing capacity, in accordance with CCC email request of 18 April 2011.

This is the first geotechnical inspection undertaken at this site, following previous Structural Assessments completed by Opus.

## **2. Description of Facility**

The Brougham Village comprises the following units,

- Units 356 – 400 Brougham Street, up to 3 storeys.
- Units at 402 Brougham Street, single storey.
- Units 95 and 97 Hastings Street East, up to 3 storeys.
- Units 131 Hastings Street East, single storey.

Refer to the annotated Site Plan Appendix B.

The site is relatively flat and low lying and is bounded to the north by Brougham Street and to the south by Hastings Street East. The ground profile slopes gently down towards Brougham Street and the ground floor units are approximately 0.5m to 0.75m above footpath level. The buildings range from one storey to three story structures and are formed of masonry block. The structures are estimated to have been built in the 1960's or 70's.

The site between the buildings is covered extensively with asphalt and paving stones. There are some grassed areas along the Brougham Street frontage and to the west of the units at 131 Hastings Street.

### **3. Desk Study Results**

#### **3.1 Ground Conditions**

A desk study of geotechnical investigations in the area from Environment Canterbury and EQC identified four logs and five CPT tests within 200m of the site, refer to Location Plan Appendix A. Drill Hole M36/0964, drilled in 1899, was performed adjacent to Unit 402 Brougham Street.

A geological cross-section completed by EQC has been identified adjacent to the site along Brougham Street.

The borehole records, CPT test results and the geological cross-section are included in Appendix A.

The geological cross-section summarises the ground conditions in the area, which are Silty SAND from surface to a depth of 5m below ground level (bgl); SAND and GRAVEL to 7.5m bgl; Sandy GRAVEL to a depth of 11m bgl; Sandy SILT to a depth of 12m bgl; Gravelly SAND to a depth of 23.5m bgl and Sandy GRAVEL to a depth of 27.5m bgl.

The sloping ground, as indicated by the as built drawings is man-made. A specification for the hardfill material that comprises the sloping ground indicates that well graded, face-cut pitrun with a maximum grain size of 75mm has been used in conjunction with a crushed, "no fines" fill with a size range of 25mm and 40mm.

#### **3.2 Ground and Building Damage**

As built drawings have been provided and indicate that the foundation system for the Brougham Village is strip footings to varying depths between 250mm and 700mm bgl. The floor slab is unreinforced concrete, varying in thickness between 100mm and 250mm.

An inspection of an open excavation adjacent to Unit 396 identified that the hardfill is not face-cut, and is sub-rounded to rounded in nature with a maximum size of 100mm, refer to photographs.

No signs of foundation subsidence were observed. A maximum of 50mm to 100mm of horizontal and vertical displacement was observed in the tiled areas around units 356 to 400 Brougham Street, refer to photographs. The land movement has generally been downslope towards Brougham Street.

A number of units located at 356 – 400 Brougham Street have suffered significant structural damage, particularly the section of structure supporting the third storey. In contrast, there appears to be no structural damage to units 95 and 97 Hastings Street East. There has been significant damage to the buried services throughout the site.

There is evidence of moderate liquefaction throughout the site. Surface disruption and ground heave up to 100mm vertically was recorded at two locations on the asphalt driveway and also a service trench to the north of Unit 402.

It was recommended in May 2011 that the ground floor slabs within all the garages are checked for subsidence and liquefaction. Also the foundations for the 4 units at 131

Hastings Street East should be inspected as unit 2 was yellow stickered due to severe liquefaction. To date this has not been done.

### **3.3 Liquefaction Hazard**

The 2003 ECAN Liquefaction study<sup>1</sup> indicates Brougham Village as having a moderate to high liquefaction potential under high groundwater conditions. Based on a low groundwater table, ground damage is expected to be moderate, subsidence likely to be between 100mm and 300mm.

No liquefaction was reported following the Darfield Earthquake of 4 September 2010.

Liquefaction was identified on site following both the 22 February 2011 and 13 June 2011 earthquake events, by both road observations and interpretation of aerial photos by Tonkin & Taylor<sup>2</sup>. The liquefaction identified was stated as moderate to severe.

Brougham Village is bounded by residential properties to the east, south and west that are located in the CERA “green” zone. The “green” zone has been further categorised into technical categories by the Department of Building and Housing (DBH). This site is bounded by both “Technical Category 2” (TC2) and “Technical Category 3” (TC3) sites. The DBH technical categories are guidelines for residential foundations, however are likely to be used as a guideline by the Christchurch City Council for building consent. TC2 identifies the area may be subject to minor to moderate land damage from liquefaction in future large earthquakes, whilst TC3 identifies the area may be subject to moderate to significant land damage from liquefaction in future large earthquakes.

## **4 Appraisal**

In summary, minimal damage to building foundations has occurred as a result of liquefaction following the 22 February 2011 earthquake. The slab on grade and shallow foundations appear to have performed adequately with only minor damage being reported.

There are no streams or open watercourses within close proximity of the site, this minimises the potential for lateral spreading. However the site falls gently to Brougham Street as the units have been built on a man-made rise. This rise may provide a potential for lateral spreading which has resulted in the cracks between buildings at the north-eastern corner of the facility which indicates approximately 50mm of lateral movement.

GNS Science<sup>3</sup> indicates an elevated risk of seismic activity is expected in the Canterbury region as a result of the earthquake sequence following the 4 September 2010 earthquake. Recent advice (Geonet) indicates there is a 14% probability of another Magnitude 6 or greater earthquake occurring in the next 12 months in the Canterbury region. It is expected that the probability of occurrence is likely to decrease with time, following periods of reduced seismic activity. However, we would expect that similar

---

<sup>1</sup> ECAN, The Solid Facts on Christchurch Liquefaction

<sup>2</sup> Project Orbit, 2011, Interagency/Organisation Collaboration Portal for Christchurch Recovery Effort, <http://canterburyrecovery.projectorbit.com/sitepages/home.aspx>

<sup>3</sup> GNS Science reporting on Geonet Website: <http://www.geonet.org.nz/canterbury-quakes/aftershocks/> updated on 9 July 2012.

ground damage to that experienced could re-occur in a future earthquake, dependent on the location of the epicentre.

This report has identified a significant risk that liquefaction will occur again in the life of the buildings. We consider that this risk could be evaluated to inform CCC of the expected future performance of the land.

## **5 Proposed Geotechnical Investigations**

It is recommended that as a minimum, the following geotechnical inspections are undertaken for the repair of the buildings.

1. Inspect the ground floor slabs within all the Garages for units 356 to 400, to check for subsidence and liquefaction damage.
2. Excavate and inspect foundations in key areas to confirm there has been no damage or ground disruption.
3. Undertake a Level Survey of the buildings.

To determine the liquefaction potential of the site in future earthquakes and to identify the Technical Category of the site, the following site investigations are recommended:

1. Static Cone Penetration Tests (CPT) 12 No to confirm liquefaction potential.
2. Borehole 2 No – to a depth of about 25 m, with Standard Penetration Tests at 1.5 m depth intervals, and install piezometer to monitor groundwater level.
3. Assessment and reporting

Attachments:

Appendix A – Location Plan, BH and CPT Records

Appendix B – Annotated Site Plan



Photos showing liquefaction and site damage, Units 356 to 372 Brougham Street



South Elevation of Units 356 – 372



North Elevation of Units 356 – 372 from Brougham Street



View East, damage to Asphalt



General View



Structural Damage to 2<sup>nd</sup> and 3<sup>rd</sup> Storey at Unit 364



Ground Heave at footing adjacent to Unit 364



10mm crack, movement towards Brougham Street at Unit 368



Another example

**Units 372 to 400 Brougham Street**



South Elevation including



Heave and damage to driveway.



Garage 33 near Unit 388 crack in floor slab and liquefaction



Typical Structural Damage



10mm settlement of patio tiles



Typical damage to buried services



Open excavation showing rounded pit run.



## Units 402 Brougham Street



General View 402 Brougham



Ground Heave above service trench



## Units 131 Hastings Street East



No visible damage, unit 2 yellow stickered due to severe liquefaction

**Units 95 and 97 Hastings Street East**



Southern Elevation



Western limit, no damage visible




Northern elevation unit 95



Eastern Elevation





Key: Red Line: Outline of Brougham Village  
 Red Circle: Boreholes from ECan and EQC  
 Yellow Triangle: CPT



Opus International Consultants Ltd  
 Christchurch Office  
 20 Moorhouse Ave  
 PO Box 1482  
 Christchurch, New Zealand  
 Tel: +64 3 363 5400 Fax: +64 3 365 7857

**Project:** Brougham Village  
 Geotechnical Desktop Study  
**Project No.:**  
**Client:** Christchurch City Council

### Previous Investigations Plan

**Drawn:** Engineering Geologist

**Date:** 26-Jul-12









# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 2 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE	LOCATION: CENTRAL CITY	JOB No: 52000.3400
CO-ORDINATES 5739961.63 m 2481450.24 mE	DRILL TYPE: Direct Push	HOLE STARTED: 1/8/11
R.L. 5.58 m	DRILL METHOD: Sonic Vibration	HOLE FINISHED: 2/8/11
DATUM NZMG	DRILL FLUID: N/A	DRILLED BY: DC
		LOGGED BY: TH
		CHECKED: GSH

GEOLOGICAL				ENGINEERING DESCRIPTIO																			
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS WATER	CORE RECOVERY (%)	METHOD	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE CO DITIO	WEATHERI G	STRE GTHIDE SITY	CLASSIFICATIO	SHEAR STRE GTH (kPa)			COMPRESSIVE STRE GTH (MPa)			DEFECT SPACI G (mm)	SOIL DESCRIPTIO  Soil type, minor components, plasticity or particle size, colour.	ROCK DESCRIPTIO  Substance: Rock type, particle size, colour, minor components. Defects: Type, inclination, thickness, roughness, filling.	
														10	25	100	5	10	20				50
YALDHURST MEMBER OF THE SPRINGSTON FORMATION (ALLUVIAL)		86	SONIC VIBRATION				0.5		GW	M	D										4.95m to 5.1m no recovery		
				*FC			5.5		SP	M	MD										Sandy fine to coarse GRAVEL, bluish grey. Dense, moist. Gravel is rounded to sub-rounded. Sand is fine to coarse.	5.5	
					5/9/12 N=21		6.0														Fine SAND with some silt and trace organi fragments, grey. Medium dense, moist.		
							6.5														- sand becoming fine to coarse	6.0	
			100	SONIC VIBRATION	*FC		7.0		GW	M	D										Sandy, fine to coarse GRAVEL with rare cobbles, bluish grey. Dense, moist. Gravel is subrounded. Sand is fine to coarse.	7.0	
					9/16/24 N=40		7.5																
							8.0															7.85 to 7.95m no recovery	8.0
			100	SONIC VIBRATION	*FC		8.5		ML	M	F											Sandy SILT interbedded with sand lamina, grey. Firm, moist, low plasticity. Sand is fine to medium. Sand interbedding is extremely closely spaced.	8.5
					3/7/12 N=19		9.0		SW	M	MD											Fine to coarse SAND with trace silt, bluish grey. Medium dense, moist.	9.0
					*FC		9.5															9.35 to 9.45m no recovery	9.5
						10															- becoming gravelly SAND. Gravel is fine to coarse, rounded to subrounded.		

T-T DATATEMPLATE.GDT eek



# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 3 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE		LOCATION: CENTRAL CITY		JOB No: 52000.3400	
CO-ORDINATES 5739961.63 m 2481450.24 mE		DRILL TYPE: Direct Push		HOLE STARTED: 1/8/11	
R.L. 5.58 m		DRILL METHOD: Sonic Vibration		HOLE FINISHED: 2/8/11	
DATUM NZMG		DRILL FLUID: N/A		LOGGED BY: TH CHECKED: GSH	

GEOLOGICAL				ENGINEERING DESCRIPTIO																	
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS	WATER	CORE RECOVERY (%)	METHOD	CASI G	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE WEATHERI G CO DITTO	STRE GTHIDE SITY CLASSIFICATIO	SHEAR STRE GTH (kPa)			COMPRESSIVE STRE GTH (MPa)			DEFECT SPACI G (mm)	SOIL DESCRIPTIO Soil type, minor components, plasticity or particle size, colour.
														10	25	100	5	10	20		
YALDHURST MEMBER OF THE SPRINGSTON FORMATION (ALLUVIAL)				SPT		4/9/8 N=17		-4.5			GW	M	MD								Sandy, fine to coarse GRAVEL, bluish grey. Medium dense, moist. Gravel is subrounded. Sand is fine to coarse.
								10.5													- contains minor gravels
								11.0													10.85 to 10.95m no recovery
				100	SONIC VIBRATION				11.5												
						3/6/15 N=21		12.0													- contains trace fine gravels - sand becoming fine to medium
								12.5			SW	M	MD								Fine to medium SAND, grey. Medium dense, moist.
								13.0													
								13.5													
						3/4/9 N=13		14.0													
								14.5													
								15.0													
						*FC															

T-T DATATEMPLATE.GDT eek



# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 4 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE	LOCATION: CENTRAL CITY	JOB No: 52000.3400
CO-ORDINATES 5739961.63 m 2481450.24 mE	DRILL TYPE: Direct Push	HOLE STARTED: 1/8/11
R.L. 5.58 m	DRILL METHOD: Sonic Vibration	HOLE FINISHED: 2/8/11
DATUM NZMG	DRILL FLUID: N/A	DRILLED BY: DC
		LOGGED BY: TH
		CHECKED: GSH

GEOLOGICAL				ENGINEERING DESCRIPTIO																		
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS	WATER	CORE RECOVERY (%)	METHOD	CASI G	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE WEATHERI G CO DITTO	STRE GTHIDE SITY CLASSIFICATIO	SHEAR STRE GTH (kPa)			COMPRESSIVE STRE GTH (MPa)			DEFECT SPACI G (mm)	SOIL DESCRIPTIO Soil type, minor components, plasticity or particle size, colour.  ROCK DESCRIPTIO Substance: Rock type, particle size, colour, minor components. Defects: Type, inclination, thickness, roughness, filling.	
														10	25	100	5	10	20			50
YALDHURST MEMBER OF THE SPRINGSTON FORMATION (ALLUVIAL)				SPT		3/5/8 N=13		-9.5			GW	M	MD								15.5	Sandy, fine to coarse GRAVEL, grey. Medium dense, moist. Gravel is subrounded. Sand is fine to coarse. 15.15 to 15.6m no recovery
			86	SONIC VIBRATION		8/11/23 N=34		-10.0													16.0	
CHRISTCHURCH FORMATION (MARINE & ESTUARINE)				SPT				-11.0													16.5	16.65 to 16.95m no recovery
			100	SONIC VIBRATION		*FC		-11.5			SW	M	MD								17.0	Fine to medium SAND with trace gravel, bluish grey. Medium dense, moist. Gravel is fine to medium, rounded.
				SPT		4/7/18 N=25		-12.0													17.5	
			100	SONIC VIBRATION				-12.5														18.0
				SPT				-13.0													18.5	
				SPT		4/5/7 N=12		-13.5													19.0	- contains some fine to coarse gravel, subrounded.
				SPT				-14.0			ML	M	St								19.5	Sandy SILT, bluish grey. Stiff, moist, low plasticity. Sand is fine.
								20														

T-T DATA TEMPLATE.GDT eek



# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 5 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE	LOCATION: CENTRAL CITY	JOB No: 52000.3400
CO-ORDINATES 5739961.63 m 2481450.24 mE	DRILL TYPE: Direct Push	HOLE STARTED: 1/8/11
R.L. 5.58 m	DRILL METHOD: Sonic Vibration	HOLE FINISHED: 2/8/11
DATUM NZMG	DRILL FLUID: N/A	DRILLED BY: DC
		LOGGED BY: TH
		CHECKED: GSH

GEOLOGICAL		ENGINEERING DESCRIPTIO																		
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS WATER	CORE RECOVERY (%)	METHOD	CASI G	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE WEATHERI G CO DITIO	STRE GTHIDE SITY CLASSIFICATIO	SHEAR STRE GTH (kPa)			COMPRESSIVE STRE GTH (MPa)			DEFECT SPACI G (mm)	SOIL DESCRIPTIO Soil type, minor components, plasticity or particle size, colour.
													10	25	100	5	10	20		
YALDHURST MEMBER OF THE SPRINGSTON FORMATION (ALLUVIAL)		100	SONIC VIBRATION				-14.5		X	ML	M	St								
					1/1/3 N=4		-15.5		X			F								- becoming firm
		100	SONIC VIBRATION				-16.0		X											
					2/4/5 N=9		-17.0		X	OL	M	St								Organic SILT, brownish grey. Stiff, moist, low plasticity.
RICCARTON GRAVELS		100	SONIC VIBRATION				-17.5		X											
							-18.0		X											
					4/11/19 N=21		-18.5		X	GW	M	MD								Sandy, fine to coarse GRAVEL with trace rootlets, bluish grey. Medium dense. Gravel is subrounded. Sand is fine to coarse.
							-19.0		X											- contains trace cobbles

T-T DATA TEMPLATE.GDT eek



# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 6 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE		LOCATION: CENTRAL CITY		JOB No: 52000.3400																				
CO-ORDINATES 5739961.63 m 2481450.24 mE		DRILL TYPE: Direct Push		HOLE STARTED: 1/8/11																				
R.L. 5.58 m		DRILL METHOD: Sonic Vibration		HOLE FINISHED: 2/8/11																				
DATUM NZMG		DRILL FLUID: N/A		LOGGED BY: TH CHECKED: GSH																				
GEOLOGICAL			ENGINEERING DESCRIPTIO																					
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS WATER	CORE RECOVERY (%)	METHOD	CASI G	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE WEATHERI G CO DITIO	STRE GTHIDE SITY CLASSIFICATIO	SHEAR STRE GTH (kPa)					COMPRESSIVE STRE GTH (MPa)					DEFECT SPACI G (mm)	SOIL DESCRIPTIO Soil type, minor components, plasticity or particle size, colour.
													10	25	50	100	200	5	10	20	50	100		
RICCARTON GRAVELS							-19.5			GW	M	D											Sandy, fine to coarse GRAVEL with trace rootlets, bluish grey. Dense. Gravel is subrounded. Sand is fine to coarse.	
							25.5																25.5 to 25.95m no recovery	
				SPT		15/19/28 N=47	-20.0																	
						*FC	-26.0			SW	M	D											Fine to coarse SAND with trace silt, brown. Dense, moist.	
							-26.5			GW	M	D											Sandy, fine to coarse GRAVEL, brown. Dense, moist. Gravel is subrounded. Sand is fine to coarse.	
						-27.0						VD											- becoming very dense	
						-27.5																		
						24/25/27 N=52	-21.5																	
							-22.0																	
							-22.5																	
							-28.0																	
							-28.5																	
						50 for 90mm N>50	-23.0																	
							-23.5																	
							-29.0																	
							-29.5																	
							-24.0																	
							30																	

T-T DATA TEMPLATE.GDT eek





# TONKIN & TAYLOR LTD

## BOREHOLE LOG

BOREHOLE No: CBD 42

Hole Location: Cnr Brougham & Waltham Rds

SHEET 7 OF 7

PROJECT: CHRISTCHURCH CITY 2011 EARTHQUAKE      LOCATION: CENTRAL CITY      JOB No: 52000.3400

CO-ORDINATES 5739961.63 m      DRILL TYPE: Direct Push      HOLE STARTED: 1/8/11  
 2481450.24 mE

R.L. 5.58 m      DRILL METHOD: Sonic Vibration      DRILLED BY: DC


DATUM NZMG      DRILL FLUID: N/A      LOGGED BY: TH      CHECKED: GSH

GEOLOGICAL						ENGINEERING DESCRIPTIO																			
GEOLOGICAL UNT, GENERIC NAME, ORIGIN, MINERAL COMPOSITION	FLUID LOSS	WATER	CORE RECOVERY (%)	METHOD	CASI G	TESTS	SAMPLES	R.L. (m)	DEPTH (m)	GRAPHIC LOG	CLASSIFICATIO SYMBOL	MOISTURE CO DITIO	WEATHERI G	STRE GTHIDE SITY	CLASSIFICATIO	SHEAR STRE GTH (kPa)			COMPRESSIVE STRE GTH (MPa)			DEFECT SPACI G (mm)			SOIL DESCRIPTIO Soil type, minor components, plasticity or particle size, colour.
																10	25	100	5	10	20	50	100	200	
				SPT		50/70mm N>50		-24.5		X															
<b>End of borehole at 30.07mbgl. Open standpipe piezometer installed. Please see attached diagram in Appendix F.</b>																									
								30.5																	
								-25.0																	
								31.0																	
								-25.5																	
								31.5																	
								-26.0																	
								32.0																	
								-26.5																	
								32.5																	
								-27.0																	
								33.0																	
								-27.5																	
								33.5																	
								-28.0																	
								34.0																	
								-28.5																	
								34.5																	
								-29.0																	
								35																	

T-T DATA TEMPLATE.GDT.cek

# Borelog for well M36/0964 page 1 of 2

Gridref: M36:814-399 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.2 +MSD  
 Driller : Job Osborne (& Co/Ltd)  
 Drill Method : Hydraulic/Percussion  
 Drill Depth : -95.3m Drill Date : 6/05/1899



# Borelog for well M36/0964 page 2 of 2

Gridref: M36:814-399 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.2 +MSD  
 Driller : Job Osborne (& Co/Ltd)  
 Drill Method : Hydraulic/Percussion  
 Drill Depth : -95.3m Drill Date : 6/05/1899



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian			
-50			Sand br	br
		- 51.8m	Clay y	br
		- 53.9m	Gravel Brown wl +1.2m	br
-55				
-60				
-65				
-70		- 69.5m	Peat	li
		- 70.1m	Clay (Bl)	li-2
-75				
		- 75.9m	Gravel (Br) wl +2.1m	li-2
-80				
		- 79.2m	Yellow sandy gravel	li-3
		- 81.7m	Clay sandy y	li-3
		- 82.9m	Sand y	he
		- 84.7m	Gravel br	he
-85		- 85.6m	Yellow sand	he
-90				
		- 90.2m	Sand & clay y	he
		- 93.9m	Gravel Brown wl +7.9m	he
-95		- 95.3m		bu

# Borelog for well M36/1048 page 1 of 2

Gridref: M36:815-398 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 6.3 +MSD

Driller : not known

Drill Method : Unknown

Drill Depth : -99.3m Drill Date :




Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian	-1.20m	Surface soil & sand	sp
			Blue shingle	
-5		-6.00m	Blue clay	sp
		-7.59m	Blue sand	sp
-10				
-15		-15.2m	Blue shingle	ch
-20				
		-21.3m	Blue clay	sp
-25				
		-27.4m	Brown shingle	ch
-30				
-35				
		-39.6m	Blue clay & peat	ri
-40		-40.8m	Brown shingle	br
		-42.0m	Brown sand	br
-45				
		-49.9m		br



# Borelog for well M36/1048 page 2 of 2

Gridref: M36:815-398 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.3 +MSD  
 Driller : not known  
 Drill Method : Unknown  
 Drill Depth : -99.3m Drill Date :





# Borelog for well M36/1086 page 1 of 2

Gridref: M36:814-399 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.2 +MSD  
 Driller : not known  
 Drill Method : Unknown  
 Drill Depth : -121.3m Drill Date :



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian		Clay & sand	
		-9.10m		sp
-10			Blue shingle	
		-13.7m		sp
			Clay & sand	
-20				
		-25.8m		ch
			Brown shingle, water rises to surface	
-30				
		-38.4m		ri
			Blue clay	
-40		-40.8m		br
			Brown shingle, water rises to surface	
		-43.8m		br
			Brown sand	
-50				
		-51.8m		br
			Yellow clay	
		-53.6m		br
			Brown shingle, water rises to 0.6m at 68.5m	
-60				
		-70.1m		li

# Borelog for well M36/1086 page 2 of 2

Gridref: M36:814-399 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.2 +MSD  
 Driller : not known  
 Drill Method : Unknown  
 Drill Depth : -121.3m Drill Date :





Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian			
			Brown shingle, water rises to 0.6m at 68.5m	
-70		-70.1m		li
		-71.9m	Yellow clay	li-2
			Brown shingle, water rises 1.2m at 73.1m	
-80		-81.0m		li-3
			Brown sand	
-90		-91.4m		he
			Yellow clay	
		-94.4m		he
			Brown shingle, flow at 97.5m water rises 4.2m	
-100		-99.3m		bu
			Yellow clay	
		-102.4m		sh
			Blue clay & sand	
		-105.4m		sh
			Yellow clay	
		-107.2m		sh
			Brown shingle, flows at 109.7m & 112.7m, rises 5.1m	
-110		-117.3m		sh
			Yellow clay	
		-118.8m		sh
			Brown shingle flows at 262.0m <sup>3</sup> /d at the surface & rises 7.6m	
-120		-121.3m		wa

# Borelog for well M36/1097

Gridref: M36:813-398 Accuracy : 4 (1=best, 4=worst)  
 Ground Level Altitude : 6.6 +MSD  
 Driller : not known  
 Drill Method : Unknown  
 Drill Depth : -99m Drill Date : 12/02/1913



Scale(m)	Water Level	Depth(m)	Full Drillers Description	Formation Code
	Artesian		Clay & sand	
-10				
-20				
		- 24.3m		sp-ch
-30			Brown shingle	
-40		- 38.4m		ri
		- 42.6m	Blue clay & sand	br
			Blue sand	
-50		- 48.7m		br
		- 51.2m	Brown sand	br
		- 52.4m	Blue shingle	li-1
			Blue sand	
		- 57.3m		li-1
-60			Brown shingle	
		- 63.3m		li-2
			Blue clay & sand	
-70		- 68.2m		li-2
		- 70.1m	Blue shingle	li-2
			Blue shingle	
		- 76.2m		li-3
		- 79.2m	Brown shingle, water rises 1.8m	li-3
-80			Brown sand & shingle	
		- 93.2m		he
			Yellow & Blue clay	
		- 97.8m		he
		- 99.0m	Brown shingle, water flows 196.5m <sup>3</sup> /d & rises 6.7m	bu



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**



Location: **CBD - Christchurch City**

Date : **30-8-2011**

Cone no. : **C10CFIP.F56**

Project no. : **01TT26**

CPT no. : **CBD-137** 1/14



Soil behaviour type classification after Robertson 1990

CPTask V1.25



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**

Location: **CBD - Christchurch City**



Date : **30-8-2011**

Cone no. : **C10CFIP.F56**

Project no. : **01TT26**

CPT no. : **CBD-137**      13/14





Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**



Location: **CBD - Christchurch City**

Date : **30-8-2011**

Cone no. : **C10CFIP.F56**

Project no. : **01TT26**

CPT no. : **CBD-138** 1/14



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**



Location: **CBD - Christchurch City**

Date : **30-8-2011**

Cone no. : **C10CFIP.F56**

Project no. : **01TT26**

CPT no. : **CBD-138**      13/14



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**

Location: **Sydenham - Christchurch City**


Date : **6-5-2011**

Cone no. : **C10CFIP.F14**

Project no. : **01TT10**

CPT no. : **SYD-02** 1/14







Test according A.S.T.M. Standard D 5778-07		Date : 6-5-2011
Project : Site Investigations		Cone no. : C10CFIP.F14
Location: Sydenham - Christchurch City		Project no. : 01TT10
		CPT no. : SYD-03
		1/14

CPTask V1.25





CPTask V1.25



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**



Location: **Sydenham - Christchurch City**

Date : **6-5-2011**

Cone no. : **C10CFIP.F14**



Project no. : **01TT10**

CPT no. : **SYD-03**      13/14



Test according A.S.T.M. Standard D 5778-07		Date : 6-5-2011
Project : Site Investigations		Cone no. : C10CFIP.F14
Location: Sydenham - Christchurch City		Project no. : 01TT10
		CPT no. : SYD-04      1/14

CPTask V1.25



Soil behaviour type classification after Robertson 1990

CPTask V1.25



Test according A.S.T.M. Standard D 5778-07

Project : **Site Investigations**


Location: **Sydenham - Christchurch City**

Date : **6-5-2011**

Cone no. : **C10CFIP.F14**

Project no. : **01TT10**

CPT no. : **SYD-04**      13/14



- NOTE:**
1. Subsurface conditions are inferred from borehole logs and correlations from CPT data. The nature and continuity of the subsurface geology for the investigation locations are inferred and it must be appreciated that actual ground conditions could vary from the assumed model.
  2. Strength and density descriptions follow NZ Geotechnical Society "Guidelines for the Proper Classification and Description of Soil & Rock for Engineering Purposes" (December, 2008).
  3. No GPS available in top 1.2m due to services pre-drill.
  4. Original surface profile inferred from LIDAR data (taken by NZ Aerial Mapping 8-10 March 2010) where available.
  5. CPT and cone resistance measurements are relative to a datum (datum is as shown).
  6. Soil moisture base, density and strength have been inferred from CPT data using methodologies published in Lunne, Robertson & Powell (2002).



COMPILED DRAWN	JTC	02/11
DESIGNED	TAT	02/11
DRAWING CHECKED	HPF	02/11
CD-CBD-18 The Log		
SCALE (HORIZONTAL)	1:200	Horizontal
	1:200	Vertical
Sheet 1 of 1		

CHRISTCHURCH CITY COUNCIL		
GEOLOGICAL INTERPRETATIVE REPORT		
CHRISTCHURCH CENTRAL CITY		
GXS-CBD-18 (Brougham Street)		
PH. No.	C.23	1



APPENDIX B - SITE PLAN

WATKINSON NOTES 10/05/11 Waltham Brown.

20mm gap in tiles  
15mm GAP in tiles

100mm of ground heave.




Level of Damage

- (A) Wood heave 80mm
- (B) Damage to carpark area
- (C) Damage to buried services
- (D) Severe cracking in 1st Floor slab.
- (E) Heave in driveway 100mm
- (F) Heave 33 Cracking in ground floor slab.
- (G) Damaged services.

Unit 2 yellow sticker  
Severe liquefaction



## **Appendix E – Site Location and Damage Plan**







3 Storeys

1 Storey

2 Storeys



**D A COWEY ASSOCIATES**  
 REGISTERED ARCHITECTS  
 P O BOX 1687 CHRISTCHURCH

DRAWN PVL/M    TRACED PVL/BJ  
 CHECKED PVL/M    DATE 25.4.20

DISTRIBUTION  
 REVISIONS & NOTES

REVISIONS & NOTES

STRUCTURAL ENGINEERS:  
 HOLMES, WOOD, ROOPE & JOHNSTONE

SERVICES, ROADING  
 CITY ENGINEERS DEPT

SCALES 1:200  
 CONTRACTOR SHALL VERIFY ALL DIMENSIONS  
 BEFORE STARTING WORK

CONTENTS  
 PART SITE PLAN    C.I. & T.O.S.  
 LOCATION

PROJECT 416  
 BRIDGEMAN STREET  
 URBAN RENOVATION    STAGE 1

DRAWING REFERENCE  
 L [2-1]    02









