

Christchurch City Council
PRK_0572_BLDG_002 EQ2
Edgar McIntosh Park - Toilets
177 Condell Ave



QUALITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 12 March 2013



Christchurch City Council
PRK_0572_BLDG_002 EQ2
Edgar McIntosh Park - Toilets
177 Condell Ave

QUALITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 12 March 2013

Sinclair Knight Merz
142 Sherborne Street
Saint Albans
PO Box 21011, Edgeware
Christchurch, New Zealand
Tel: +64 3 940 4900
Fax: +64 3 940 4901
Web: www.skmconsulting.com

COPYRIGHT: The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

LIMITATION: This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.

Contents



1. Executive Summary	1
1.1. Background	1
1.2. Key Damage Observed	2
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
2. Introduction	3
3. Compliance	4
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
4. Earthquake Resistance Standards	8
5. Building Details	10
5.1. Building description	10
5.2. Gravity Load Resisting system	10
5.3. Seismic Load Resisting system	10
5.4. Geotechnical Conditions	10
6. Damage Summary	11
7. Initial Seismic Evaluation	12
7.1. The Initial Evaluation Procedure Process	12
7.2. Design Criteria and Limitations	14
7.3. Survey	14
7.4. Critical Structural Weaknesses	15
7.5. Qualitative Assessment Results	15
8. Further Investigation	16
9. Conclusion	17
10. Limitation Statement	18
11. Appendix 1 – Photos	19
12. Appendix 2 – IEP Reports	24
13. Appendix 3 – CERA Standardised Report Form	31
14. Appendix 4 – Geotechnical Desktop Study	33



Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	10 August 2012	C Paverd	N Calvert	10 August 2012	Draft for Client Approval
B	12 March 2013	N Calvert	N Calvert	12 March 2013	Final

Approval

	Signature	Date	Name	Title
Author		12/03/2013	Nigel Chan	Structural Engineer
Approver		12/03/2013	Nicholas Calvert	Senior Structural Engineer

Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	Christchurch City Council
B	1	1	Christchurch City Council

Printed:	12 March 2013
Last saved:	12 March 2013 03:35 PM
File name:	ZB01276.106.PRK_0572_BLDG_002 EQ2.Qualitative.Assmt.B.docx
Author:	Nigel Chan
Project manager:	Alexandra Martin
Name of organisation:	Christchurch City Council
Name of project:	Christchurch City Council Structures Panel
Name of document:	PRK_0572_BLDG_002 EQ2 Qualitative Assessment Report
Document version:	B
Project number:	ZB01276.106

1. Executive Summary

1.1. Background

A Qualitative Assessment was carried out on the building PRK_0572_BLDG_002 EQ2 located at 177 Condell Ave. The toilet comprises of masonry walls with a concrete roof covering a portion of the toilet, attached to the Merivale Papanui Cricket Club Pavilion. Because of this the assessment will include the Pavilion complex as a whole. The Pavilion is a 2 storey structure. The ground floor is constructed with masonry walls sitting on a concrete foundation. The first floor is timber framed. An aerial photograph illustrating the location of the building is shown below in Figure 1. Detailed descriptions outlining the buildings age and construction type are given in Section 5 of this report.



■ Figure 1: Aerial Photograph of PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park

The qualitative assessment includes a summary of the building damage as well as an initial assessment of the current seismic capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, and visual inspections on 26th July 2012.



1.2. Key Damage Observed

Key damage observed includes:-

No external or internal damage was observed during our site inspection

1.3. Critical Structural Weaknesses

No potential critical structural weaknesses were identified for this building.

1.4. Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the buildings original capacity has been assessed to be in the order of 61%NBS. No damage was observed during our site investigation therefore the post earthquake capacity is also in the order of 61%NBS. This assessment has been made without structural drawings and is accordingly limited.

Since the capacity is greater than 34%NBS the building is not considered earthquake prone.

Please note that structural strengthening is required by law for buildings that are confirmed to have a seismic capacity of less than 34% NBS.

1.5. Recommendations

It is recommended that:

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.

2. Introduction

Sinclair Knight Merz was engaged by Christchurch City Council to prepare a qualitative assessment report for the building located at 177 Condell Ave following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The Qualitative Assessment uses the methodology recommended in the Engineering Advisory Group document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury” (part 2 revision 5 dated 19/07/2011 and part 3 draft revision dated 13/12/2011). The qualitative assessment includes a summary of the building damage as well as an initial assessment of the likely current Seismic Capacity compared with current seismic code requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in 7

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to the New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3¹.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. No Construction drawings were made available. The building description below is based on our visual inspections.

¹ <http://www.dbh.govt.nz/seismicity-info>

3. Compliance

This section contains a summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

3.1. Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

3.2. Building Act

Several sections of the Building Act are relevant when considering structural requirements:

3.2.1. Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

3.2.2. Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

3.2.3. Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

3.2.4. Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

3.2.5. Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

3.2.6. Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

3.3. Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 34%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

3.4. Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



■ **Table 1: %NBS compared to relative risk of failure**

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

5. Building Details

5.1. Building description

Building PRK_0572_BLDG_002 EQ2 is a small toilet block comprising of masonry walls with a concrete roof covering a portion of the toilet. The structure is attached to the Merivale Papanui Cricket Club Pavilion. Because of this the assessment will include the Pavilion complex as a whole.

The Pavilion is a 2 storey structure. The ground floor is constructed with masonry walls sitting on a concrete foundation. The first floor is timber framed. The roof is timber framed clad with light weight corrugated iron.

Drawings of the structure were not made available. Our evaluation was based on the exterior and partial interior inspection on 26th July 2012. We have taken a post-1976 construction date for the purposes of our assessment

5.2. Gravity Load Resisting system

The roof structure is a timber framed roof truss supporting the lightweight corrugated iron cladding which is supported by the timber framed walls on the first floor. The first floor is then supported by the floor joists, masonry walls on the ground floor, and the concrete foundations.

5.3. Seismic Load Resisting system

For the purposes of this report the longitudinal direction of the building is defined as being in the east-west direction and the transverse direction is defined as being in the north-south direction.

Lateral loads acting in the longitudinal and the transverse direction will be resisted by the timber framed walls on the first floor, the masonry walls on the ground floor and the concrete footing foundations

5.4. Geotechnical Conditions

A geotechnical desktop study was carried out for this site. The main conclusions from this report are:

- The site has been assessed as NZS1170.5 Class D (deep or soft soil) from adjacent borehole logs.
- Liquefaction risk is low at this site.

Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed or a quantitative detailed engineering evaluation is carried out. If any excavations are required on the site further investigation of the potential for contamination should be undertaken. The full geotechnical desktop study can be found in Appendix 4 – Geotechnical Desktop Study



6. Damage Summary

SKM undertook inspections on 18th July 2012. The following was observed during the time of inspection:

- 1) No external or internal damage was observed during our site inspection.
- 2) No visual evidence of settlement was noted at this site. Therefore a level survey is not required at this stage of assessment.

7. Initial Seismic Evaluation

7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes'. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings².

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 2. The building grade is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. A building is earthquake prone for the purposes of this Act if, having regard to its condition and to the ground on which it is built, and because of its construction, the building—

- a) will have its ultimate capacity exceeded in a moderate earthquake (as defined in the regulations); and
- b) would be likely to collapse causing—
 - i. injury or death to persons in the building or to persons on any other property; or
 - ii. damage to any other property.

A moderate earthquake is defined as 'in relation to a building, an earthquake that would generate shaking at the site of the building that is of the same duration as, but that is one-third as strong as, the earthquake shaking (determined by normal measures of acceleration, velocity and displacement) that would be used to design a new building at the site.'

An earthquake prone building will have an increased risk that its strength will be exceeded due to earthquake actions of approximately 10 times (or more) than that of a building having a capacity in excess of 100% NBS (refer Table 1)³. Buildings in Christchurch City that are identified as being earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone⁴.

² <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

³ NZSEE June 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-13

⁴ <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>



Table 2: IEP Risk classifications

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without collapse or other forms of failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building⁵. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration.

The NZ Building Code describes that the relevant codes for determining %NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard
- NZS 3604:2011 Timber Framed Buildings

⁵ NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9

7.2. Design Criteria and Limitations

Following our inspection 18th July 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and inspection findings of the building. The inspection included an exterior inspection and a partial interior inspection. The partial interior inspection included the toilet area and the interior of the changing room area only. Please note no intrusive investigations were undertaken.
- Structural drawings were not available

The design criteria used to undertake the assessment include:

- Standard design assumptions for typical office and factory buildings as described in AS/NZS1170.0:2002
 - 50 year design life, which is the default NZ Building Code design life.
 - Structure importance level 2. This level of importance is described as 'normal' structures with medium or considerable consequence of failure
 - Ductility level of 1.25 has been used for both directions, based on our assessment and code requirements at the time of design. This represents a nominally ductile structure which is appropriate given the timber framing and masonry walls in this structure.
 - Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011

This IEP was based on our visual inspection of the building. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.
- The IEP does not involve a detailed analysis or an element by element code compliance check.

7.3. Survey

There was no visible settlement of the structure, nor were there any significant ground movement issues around the building. The site has been assessed as 'Rural and Unmapped' on the CERA 'Land Zone Technical Categories Map' for residential properties. The building is adjacent to land which is zoned TC2 under the CERA Residential Technical Categories Map. Due to these factors we do not recommend that any survey be undertaken at this stage of the assessment.



7.4. Critical Structural Weaknesses

No Structural weaknesses were identified in this building

7.5. Qualitative Assessment Results

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity expressed as a percentage of new building standard (%NBS) is in order of that shown below in Table 3: Qualitative Assessment Summary.

Table 3: Qualitative Assessment Summary

<u>Item</u>	<u>%NBS</u>
Likely Seismic Capacity of Building	61

Our qualitative assessment found that the building is likely to be classed as a 'Moderate Risk Building' (capacity between 34% and 67% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Reports.



8. Further Investigation

Due to access constraints there were areas inside the building that could not be accessed for inspection in the site investigation. The client may wish for SKM to further inspect these areas, however we anticipate if there was damage found it would be superficial minor damage.



9. Conclusion

A qualitative assessment was carried out on PRK_0572_BLDG_002 EQ2, located at 177 Condell Ave. The building has been assessed to have a likely seismic capacity in the order of 61% of NBS and is likely to be classified as a 'Moderate Risk Building' (seismic capacity between 34% and 67% of NBS).

It is recommended that

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.

10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

11. Appendix 1 – Photos



Photo 1: North Elevation



Photo 2: West Elevation



Photo 3: South Elevation



Photo 4: East Elevation



Photo 5: Toilets



Photo 6: Entrance to men's toilet



Photo 7: Entrance to men's toilet



Photo 8: Door way into changing rooms




Photo 9: Hallway of changing rooms (1)




Photo 10: Cricket changing rooms (1)




Photo 11: Cricket changing rooms (2)



Photo 12: Timber framed roof truss (1)



Photo 13: Timber framed roof truss (2)



Photo 14: Hallway of changing rooms (2)



Photo 15: Cricket changing rooms (3)



Photo 16: East elevation doorway into changing rooms on the right



Photo 17: View of concrete foundation beneath masonry



12. Appendix 2 – IEP Reports

Table IEP-1 Initial Evaluation Procedure – Step 1

(Refer Table IEP - 2 for Step 2; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)




Building Name:	<u>PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion & Toilet</u>	Ref.	<u>ZB01276.106</u>
Location:	<u>Edgar McIntosh Park, 177 Condell Ave</u>	By	<u>NLC</u>
		Date	<u>26/07/2012</u>

Step 1 - General Information

1.1 Photos (attach sufficient to describe building)



1.2 Sketch of building plan



1.3 List relevant features

The toilet comprises of masonry walls with a concrete roof covering a portion of the toilet, attached to the Merivale Papanui Cricket Club Pavillion. This assessment will therefore be for the entire building.

1.4 Note information sources

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

Tick as appropriate

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

Partial

Inspection Date: 26/07/2012

Table IEP-2 Initial Evaluation Procedure – Step 2
 (Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)

Building Name:	<u>PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion & 1</u>	Ref.	<u>ZB01276.106</u>
Location:	<u>Edgar McIntosh Park, 177 Condell Ave</u>	By	<u>NLC</u>
Direction Considered:	<u>Longitudinal & Transverse</u>	Date	<u>26/07/2012</u>
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

Step 2 - Determination of (%NBS)b

2.1 Determine nominal (%NBS) = (%NBS)nom

Pre 1935		<input type="radio"/>	See also notes 1, 3
1935-1965		<input type="radio"/>	
1965-1976	Seismic Zone; A	<input type="radio"/>	
	B	<input type="radio"/>	
	C	<input type="radio"/>	See also note 2
1976-1992	Seismic Zone; A	<input type="radio"/>	
	B	<input checked="" type="radio"/>	
	C	<input type="radio"/>	
1992-2004		<input type="radio"/>	

b) Soil Type

From NZS1170.5:2004, Cl 3.1.3	A or B Rock	<input type="radio"/>
	C Shallow Soil	<input type="radio"/>
	D Soft Soil	<input checked="" type="radio"/>
	E Very Soft Soil	<input type="radio"/>
From NZS4203:1992, Cl 4.6.2.2 (for 1992 to 2004 only and only if known)	a) Rigid	<input type="radio"/>
	b) Intermediate	<input checked="" type="radio"/>

c) Estimate Period, T

building Ht = 5.5 meters

Can use following:

- $T = 0.09h_n^{0.75}$ for moment-resisting concrete frames
- $T = 0.14h_n^{0.75}$ for moment-resisting steel frames
- $T = 0.08h_n^{0.75}$ for eccentrically braced steel frames
- $T = 0.06h_n^{0.75}$ for all other frame structures
- $T = 0.09h_n^{0.75}/A_c^{0.5}$ for concrete shear walls
- $T \leq 0.4\text{sec}$ for masonry shear walls

Where h_n = height in m from the base of the structure to the uppermost seismic weight or mass.
 $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$
 A_i = cross-sectional shear area of shear wall i in the first storey of the building, in m^2
 L_{wi} = length of shear wall i in the first storey in the direction parallel to the applied forces, in m
 with the restriction that L_{wi}/h_n shall not exceed 0.9

Ac =	Longitudinal	Transverse	m2
	<input type="radio"/> MRCF	<input type="radio"/> MRCF	
	<input type="radio"/> MRSF	<input type="radio"/> MRSF	
	<input type="radio"/> EBSF	<input type="radio"/> EBSF	
	<input type="radio"/> Others	<input type="radio"/> Others	
	<input type="radio"/> CSW	<input type="radio"/> CSW	
	<input checked="" type="radio"/> MSW	<input checked="" type="radio"/> MSW	

Longitudinal	Transverse	Seconds
0.4	0.4	

d) (%NBS)nom determined from Figure 3.3

- Note 1:** For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25. Factor
- For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B. Factor
- Note 2:** For reinforced concrete buildings designed between 1976 -1984 (%NBS)nom by 1.2. Factor
- Note 3:** For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1. Factor

Longitudinal	16.5	(%NBS)nom
Transverse	16.5	(%NBS)nom

Longitudinal	16.5	(%NBS)nom
Transverse	16.5	(%NBS)nom

Continued over page

Building Name:	PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion & T	Ref.	ZB01276.106
Location:	Edgar McIntosh Park, 177 Condell Ave	By	NLC
Direction Considered:	Longitudinal & Transverse	Date	26/07/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

2.2 Near Fault Scaling Factor, Factor A
If T < 1.5sec, Factor A = 1

a) Near Fault Factor, N(T,D) 1
(from NZS1170.5:2004, Cl 3.1.6)

b) Near Fault Scaling Factor = 1/N(T,D)

Factor A	1.00
----------	------

2.3 Hazard Scaling Factor, Factor B

Select Location Christchurch

a) Hazard Factor, Z, for site
(from NZS1170.5:2004, Table 3.3)

Z =	0.3		
Z 1992 =	0.8	Auckland 0.6	Palm Nth 1.2
		Wellington 1.2	Dunedin 0.6
		Christchurch 0.8	Hamilton 0.67

b) Hazard Scaling Factor

For pre 1992 = 1/Z
For 1992 onwards = Z 1992/Z

(Where Z 1992 is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B	3.33
----------	------

2.4 Return Period Scaling Factor, Factor C

a) Building Importance Level 2
(from NZS1170.0:2004, Table 3.1 and 3.2)

b) Return Period Scaling Factor from accompanying Table 3.1

Factor C	1.00
----------	------

2.5 Ductility Scaling Factor, D

a) Assessed Ductility of Existing Structure, μ
(shall be less than maximum given in accompanying Table 3.2)

Longitudinal	1.25	μ Maximum = 6
Transverse	1.25	μ Maximum = 6

b) Ductility Scaling Factor

For pre 1976 = k_u
For 1976 onwards = 1
(where k_u is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.00
Transverse	Factor D	1.00

2.6 Structural Performance Scaling Factor, Factor E

Select Material of Lateral Load Resisting System

Longitudinal
Transverse

Masonry Block
Masonry Block

a) Structural Performance Factor, S_p
from accompanying Figure 3.4

Longitudinal	S_p	0.90
Transverse	S_p	0.90

b) Structural Performance Scaling Factor

Longitudinal	1/ S_p	Factor E	1.11
Transverse	1/ S_p	Factor E	1.11

2.7 Baseline %NBS for Building, (%NBS)_b
(equals (%NSB)_{nom} x A x B x C x D x E)

Longitudinal	61.1	(%NBS) _b
Transverse	61.1	(%NBS) _b

Table IEP-3 Initial Evaluation Procedure – Step 3

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)

Building Name: PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion & Toilet	Ref. ZB01276.106
Location: <u>Edgar McIntosh Park, 177 Condell Ave</u>	By NLC
Direction Considered: a) Longitudinal	Date 26/07/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

Step 3 - Assessment of Performance Achievement Ratio (PAR)
(Refer Appendix B - Section B3.2)

Critical Structural Weakness

Effect on Structural Performance
(Choose a value - Do not interpolate)

Building Score

3.1 Plan Irregularity

Effect on Structural Performance
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

3.2 Vertical Irregularity

Effect on Structural Performance
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

3.3 Short Columns

Effect on Structural Performance
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect
Select appropriate value from Table

Note:
Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

		Factor D1	<input type="text" value="1"/>	
Table for Selection of Factor D1		Severe	Significant	Insignificant
	Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height		<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect
Select appropriate value from Table

		Factor D2	<input type="text" value="1"/>	
Table for Selection of Factor D2		Severe	Significant	Insignificant
	Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys		<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys		<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D
(Set D = lesser of D1 and D2 or..
set D = 1.0 if no prospect of pounding)

3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

3.6 Other Factors

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

3.7 Performance Achievement Ratio (PAR)
(equals A x B x C x D x E x F)

PAR

Building Name:	PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion &	Ref.	ZB01276.106
Location:	Edgar McIntosh Park, 177 Condell Ave	By	NLC
Direction Considered:	b) Transverse	Date	26/07/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

Step 3 - Assessment of Performance Achievement Ratio (PAR)
(Refer Appendix B - Section B3.2)

Critical Structural Weakness

Effect on Structural Performance
(Choose a value - Do not interpolate)

Building Score

3.1 Plan Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

3.2 Vertical Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

3.3 Short Columns

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:
Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1

Table for Selection of Factor D1	Separation		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2

Table for Selection of Factor D2	Separation		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D

(Set D = lesser of D1 and D2 or..
set D = 1.0 if no prospect of pounding)

3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

3.6 Other Factors

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

3.7 Performance Achievement Ratio (PAR)
(equals A x B x C x D x E x F)

PAR

Building Name:	PRK_0572_BLDG_002 EQ2 Edgar McIntosh Park - Pavilion & Toilet	Ref.	ZB01276.106
Location:	Edgar McIntosh Park, 177 Condell Ave	By	NLC
Direction Considered:	Longitudinal & Transverse	Date	26/07/2012
<small>(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)</small>			

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline (%NBS)_b (from Table IEP - 1)	61	61
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	1.00	1.00
4.3 PAR x Baseline (%NBS)_b	61	61
4.4 Percentage New Building Standard (%NBS) (Use lower of two values from Step 4.3)		61

Step 5 - Potentially Earthquake Prone?
(Mark as appropriate)

%NBS ≤ 33

Step 6 - Potentially Earthquake Risk?

%NBS < 67

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade

Evaluation Confirmed by

Signature

NICK CALVERT

Name

242062

CPEng. No

Relationship between Seismic Grade and % NBS :

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20



13. Appendix 3 – CERA Standardised Report Form

Location		Building Name: PRK_0572_BLDG_002_EQ2	Unit No: Street	Reviewer: NICK CALVERT
Building Address: Edgar McIntosh Park		177 Condell Ave		CPEng No: 242062
Legal Description:				Company: Sinclair Knight Merz
				Company project number: ZB01276.106
				Company phone number: 03 940 4900
GPS south: _____		Degrees	Min	Sec
GPS east: _____				
Building Unique Identifier (CCC): _____		Date of submission: 12-Mar		
		Inspection Date: 26th July 2012		
		Revision: B		
		Is there a full report with this summary? yes		

Site		Site slope: flat	Max retaining height (m): _____
Soil type: mixed		Soil Profile (if available): See geotech desktop report by SKM dated 1 August 2012	
Site Class (to NZS1170.5): D		If Ground improvement on site, describe: n/a	
Proximity to waterway (m, if <100m): _____		Approx site elevation (m): 0.00	
Proximity to cliff top (m, if <100m): _____			
Proximity to cliff base (m, if <100m): _____			

Building		No. of storeys above ground: 2	single storey = 1	Ground floor elevation (Absolute) (m): 0.00
Ground floor split?: no				Ground floor elevation above ground (m): 0.00
Storeys below ground: 0				if Foundation type is other, describe: _____
Foundation type: strip footings		height from ground to level of uppermost seismic mass (for IEP only) (m): 5.5		Date of design: 1976-1992
Building height (m): 5.50				Strengthening present?: no
Floor footprint area (approx): 245				If so, when (year)? _____
Age of Building (years): 30				And what load level (%g)? _____
Use (ground floor): other (specify) _____				Brief strengthening description: _____
Use (upper floors): _____				
Use notes (if required): Cricket Pavillion				
Importance level (to NZS1170.5): IL2				

Gravity Structure		Gravity System: load bearing walls	rafter type, purlin type and cladding: Timber rafters and purlins and corrugated iron roof cladding
Roof: timber framed		Floors: concrete flat slab	slab thickness (mm): _____
Beams: timber		Columns: load bearing walls	type: Timber beams in 1st storey, and timber beams assumed to support the 1st storey
Walls: partially filled concrete masonry			typical dimensions (mm x mm): _____
			thickness (mm): 200

Lateral load resisting structure		Lateral system along: partially filled CMU	Ductility assumed, μ : 1.25	Period along: 0.40	Total deflection (ULS) (mm): 5	maximum interstorey deflection (ULS) (mm): _____	Note: Define along and across in detailed report!	note total length of wall at ground (m): 0.6	wall thickness (m): _____	estimate or calculation?: estimated	estimate or calculation?: estimated	estimate or calculation?: estimated
							#DIV/0! enter height above at H31					
		Lateral system across: partially filled CMU	Ductility assumed, μ : 1.25	Period across: 0.40	Total deflection (ULS) (mm): 5	maximum interstorey deflection (ULS) (mm): _____	#DIV/0! enter height above at H31	note total length of wall at ground (m): 0.6	wall thickness (m): _____	estimate or calculation?: estimated	estimate or calculation?: estimated	estimate or calculation?: estimated

Separations:		north (mm): _____	east (mm): _____	south (mm): _____	west (mm): _____	leave blank if not relevant
---------------------	--	-------------------	------------------	-------------------	------------------	-----------------------------

Non-structural elements		Stairs: _____	describe: n/a
Wall cladding: exposed structure		Roof Cladding: Metal	describe: masonry wall on ground floor and timber cladding on 1st floor
Glazing: timber frames		Ceilings: fibrous plaster, fixed	describe: corrugated iron
Services(list): none			describe: n/a

Available documentation		Architectural: none	original designer name/date: _____
Structural: none		Mechanical: none	original designer name/date: _____
Electrical: none		Geotech report: partial	original designer name/date: Geotech desktop report by SKM dated 1 August 2012

Damage		Site performance: 1	Describe damage: no damage observed
Site: (refer DEE Table 4-2)		Settlement: none observed	notes (if applicable): _____
Differential settlement: none observed		Liquefaction: none apparent	notes (if applicable): _____
Lateral Spread: none apparent		Differential lateral spread: none apparent	notes (if applicable): _____
Ground cracks: none apparent		Damage to area: none apparent	notes (if applicable): _____

Building:		Current Placard Status: green	Describe how damage ratio arrived at: no damage observed on site
Along	Damage ratio: 0%	Describe (summary): Small structure with no structural damage	$Damage_Ratio = \frac{(\%NBS\ before) - \%NBS\ (after)}{\%NBS\ (before)}$
Across	Damage ratio: 0%	Describe (summary): Small structure with no structural damage	
Diaphragms	Damage?: no	Describe: n/a	
CSWs:	Damage?: no	Describe: n/a	
Pounding:	Damage?: no	Describe: n/a	
Non-structural:	Damage?: no	Describe: n/a	

Recommendations		Level of repair/strengthening required: none	Describe: n/a
Building Consent required: no		Interim occupancy recommendations: full occupancy	Describe: n/a
Along	Assessed %NBS before: 61%	Assessed %NBS after: 61%	%NBS from IEP
Across	Assessed %NBS before: 61%	Assessed %NBS after: 61%	%NBS from IEP
		If IEP not used, please detail assessment methodology: Qualitative Assessment carried out this includes the NZSEE IEP - refer to SKM report	



14. Appendix 4 – Geotechnical Desktop Study

Sinclair Knight Merz
142 Sherborne Street
Saint Albans
PO Box 21011, Edgware
Christchurch, New Zealand

Tel: +64 3 940 4900
Fax: +64 3 940 4901
Web: www.globalskm.com



Christchurch City Council - Structural Engineering Service

Geotechnical Desk Study

SKM project number	ZB01276
SKM project site number	106
Address	Toilets Edgar MacIntosh Park - 177 Condell Avenue
Report date	01 August 2012
Author	Ananth Balachandra
Reviewer	Leah Bateman
Approved for issue	YES

1. Introduction

This report outlines the geotechnical information that Sinclair Knight Merz (SKM) has been able to source from our database and other sources in relation to the property listed above. We understand that this information will be used as part of an initial qualitative Detailed Engineering Evaluation (DEE), and will be supplemented by more detailed information and investigations to allow detailed scoping of the repair or rebuild of the building.

2. Scope

This geotechnical desk top study incorporates information sourced from:

- Published geology
- Publically available borehole records
- Liquefaction records
- Aerial photography
- Council files
- A preliminary site walkover

3. Limitations

This report was prepared to address geotechnical issues relating to the specific site in accordance with the scope of works as defined in the contract between SKM and our Client. This report has been prepared on behalf of, and for the exclusive use of, our Client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and our Client. The findings presented in this report should not be applied to another site or another development within the same site without consulting SKM.

The assessment undertaken by SKM was limited to a desktop review of the data described in this report. SKM has not undertaken any subsurface investigations, measurement or testing of materials from the site. In preparing this report, SKM has relied upon, and presumed accurate, any information (or confirmation of the absence thereof) provided by our Client, and from other sources as described in the report. Except as otherwise stated in this report, SKM has not attempted to verify the accuracy or completeness of any such information.

Sinclair Knight Merz Limited


The SKM logo trade mark is a registered trade mark of Sinclair Knight Merz Pty Ltd.

Offices across Australia, New Zealand, UK, South East Asia, Middle East, the Pacific and Americas



This report should be read in full and no excerpts are to be taken as representative of the findings. It must not be copied in parts, have parts removed, redrawn or otherwise altered without the written consent of SKM.

4. Site location




■ **Figure 1 – Site location (courtesy of LINZ <http://viewers.geospatial.govt.nz>)**

The structure is located on 177 Condell Avenue at an approximate grid reference 1567092 E, 5183913 N (NZTM).



5. Review of available information

5.1 Geological maps



- Figure 2 – Regional geological map (Forsyth et al, 2008). Site marked in yellow.



■ **Figure 3 – Local geological map (Brown et al, 1992). Site marked in yellow.**


The site is shown to be underlain by Holocene deposits comprising predominantly alluvial sand and silt overbank deposits of the Springston Formation.

5.2 Liquefaction map

Following the 22 February 2011 event a drive through reconnaissance was undertaken from 23 February until 1 March by M Cubrinovsko and M Taylor of Canterbury University.

However, the reconnaissance did not extend to the location of the site.

5.3 Aerial photography



- **Figure 4 – Aerial photography from 24 Feb 2011 (<http://viewers.geospatial.govt.nz/>)**

There appears to be no evidence of any liquefied ejecta at surface or land damage that may be caused by cyclic ground motions induced by an earthquake event. Therefore, it is unlikely that any significant liquefaction of the underlying soil strata occurred on site.

5.4 CERA classification

A review of the LINZ website (<http://viewers.geospatial.govt.nz/>) shows that the site is:

- Zone: Green
- DBH Technical Category: N/A (Urban Non-residential) – adjacent properties are TC2

5.5 Historical land use

Reference to historical documents (eg Appendix A) shows that area approximately 200 m east and south east of the site was recorded as swamp or marshland in 1856.



It should be noted that the historical land use maps generally have a low level of accuracy. However, as no significant liquefaction was noted on site and as soft swamp or marshland deposits are likely to be highly susceptible to liquefaction, it is unlikely that the noted swamp area to the east extends to the location of the site.

5.6 Existing ground investigation data



- **Figure 5 – Local boreholes from Project Orbit and ECAN GIS** (<https://canterburyrecovery.projectorbit.com/>) and (<http://arcims.ecan.govt.nz/ecanmapping/>)

Where available logs from these investigation locations are attached to this report (Appendix B), and the results are summarised in Appendix C.

A summarised inference of the available geotechnical investigation data is provided in section 6.1. Only investigations to a depth of at least 3 m were considered.

5.7 Council property files

Council property files were not available for the site at the time of writing this report.



5.8 Site walkover

An external site walkover was conducted by an SKM engineer on 31 July 2012.

The toilet block was noted to be constructed using masonry walls with a concrete roof and slab on grade foundation. The toilet block is attached to the Merivale Papanui Cricket Club Pavilion. There was no apparent evidence of liquefaction or land damage around the toilet block and Pavilion structures. There was slight differential settlement of some concrete paving around the building. The nearby Condell Avenue appeared undamaged.



- **Figure 5 Overview of the pavilion with the toilet attached to the Pavilion structure**



■ **Figure 6 Observed settlement of pavement slabs**



■ **Figure 7 No apparent damage to the section of Condell Avenue near the site**



6. Conclusions and recommendations

6.1 Site geology

An interpretation of the most relevant local investigation suggests that the site is underlain by:

Depth range (mBGL)	Soil type
0 - 1	Top soil
1 - 4	Loose/ soft silt mixtures - mainly sandy silt with some clayey silt
4 - 7	Firm to stiff clayey silt and sandy silt
7 - 9	Loose to medium dense silty sand to sand
9 - 17.5	Firm to stiff clay and silty clay with thin soft organic layers
17.5 - 18	Dense silty sand to clean sand

It should be noted that all available investigation data for the site are located a considerable distance away from the site. Additionally, there was some variation in the soil profile indicated by the CPT undertaken approximately 240 m from the site and the one undertaken approximately 380 m from the site. Greater reliance was placed on the CPT undertaken closer to the site in providing the above inferred site geology.

However, it should be noted that there could be significant variations in the shallow geology of the area and site specific study would be needed to confirm the above geological model.

ECAN wells 500 to 600 m show ground water level to be approximately 1.5 to 2 m below ground level. Therefore, it is expected the ground water table beneath the site would be present at a similar depth.

6.2 Seismic site subsoil class

The site has been assessed as NZS1170.5 Class D (deep or soft soil).

As described in NZS1170, the preferred site classification method is from site periods based on four times the shear wave travel time through material from the surface to the underlying rock. The next preferred methods are from borelogs including measurement of geotechnical properties or by evaluation of site periods from Nakamura ratios or from recorded earthquake motions. Lacking this information, classification may be based on boreholes with descriptors but no geotechnical measurements. The least preferred method is from surface geology and estimates of the depth to underlying rock.

In this case a combination of second and third preferred methods has been used to make the assessment. However, we have a reasonable level of confidence in the assessed seismic site subsoil class, as the underlying bedrock layer is likely to be present at depths greater than 100 m.

6.3 Building Performance

Although detailed records of the existing foundations are not available, the performance to date suggests that they are adequate for their current purpose.



6.4 Ground performance and properties

Liquefaction risk is expected to be low for this site.

This assessment has been based on the fact that very little evidence of liquefaction was noted in the aerial photographs of the area taken shortly after the 22 February earthquake and other large recent earthquakes. Additionally, no significant evidence that liquefaction occurred on site was apparent during the external site walkover undertaken by an SKM engineer. The differential settlement of the pavement slabs is expected to be due to shaking damage or settlement due to increased vertical accelerations rather than post liquefaction consolidation of the soil strata.

However, from cone penetration tests located at a distance of greater than 200 m from the site, loose silt, silty sand and sand layers were inferred to be present in the respective areas and these layers may be present beneath the site. These layers, if located below the ground water table, are susceptible to liquefaction unless sufficient fine material is present.

Investigation data with geotechnical measurements were located a considerable distance away from the site. Additionally, there is significant level of uncertainty regarding the underlying soil profile due to conflicting soil profile indicated by available investigation data, the level of liquefaction that would be expected for sites underlain by the respective strata and the actual level of liquefaction noted.

Therefore if further assessment work is required for the structure on site, such as a quantitative DEE, site specific investigations would be needed to confirm the above liquefaction assessment.

6.5 Further investigations

If a quantitative DEE is to be performed for the site, additional investigations are recommended in order to confirm the level of liquefaction risk and provide likely shallow ground properties. Additional investigations recommended are:

- Two hand augers to a depth of 3m to identify the composition of the shallow soil layer and to determine if any very shallow gravel layer is present on site
- One CPT to refusal to confirm liquefaction assessment. From available investigation data there appears to be no shallow gravel layers. However, if very shallow gravel layers are encountered during the hand augers, pre drilling through this layer may be required before undertaking a CPT

A more detailed set of ground investigations may be required if consent is required or significant alteration to the structures on site is proposed.



7. References

Brown LJ, Weeber JH, 1992. Geology of the Christchurch urban area. Scale 1:25,000. Institute of Geological & Nuclear Sciences geological map 1.

Cubrinovski & Taylor, 2011. Liquefaction map summarising preliminary assessment of liquefaction in urban areas following the 2010 Darfield Earthquake.


Forsyth PJ, Barrell DJA, Jongens R, 2008. Geology of the Christchurch area. Institute of Geological & Nuclear Sciences geological map 16.

Land Information New Zealand (LINZ) geospatial viewer (<http://viewers.geospatial.govt.nz/>)

EQC Project Orbit geotechnical viewer (<https://canterburyrecovery.projectorbit.com/>)



Appendix A – Christchurch 1856 land use



The swamps and previous creeks/riders from 1856 have been overlaid onto a map of Christchurch in 2012


- Key**
- Previous creeks/riders
 - Existing creeks/riders
 - New creeks/riders
 - Swamp/Marshland






Appendix B – Existing ground investigation logs



Borelog for well M35/17562


Gridref: M35:77302-45508 Accuracy : 3 (1=high, 5=low)
 Ground Level Altitude : 15.93 +MSD
 Well name : CCC BorelogID 7641
 Drill Method : Not Recorded
 Drill Depth : -3.1m Drill Date : 19/07/2007



Project: Darfield 2010 Earthquake - EQC Ground Investigations			Page: 1 of 1	CPT-BDL-02	
Test Date: 3-Dec-2010	Location: Bishopdale	Operator: Perry		 	
Pre-Drill: 1.2m	Assumed GWL: 1.5mBGL	Located By: Survey GPS			
Position: 2477136.3mE	5745760.9mN	16.31mRL	Coord. System: NZMG & MSL		
Other Tests:			Comments:		



Project: Darfield 2010 Earthquake - EQC Ground Investigations				Page: 1 of 1	CPT-BDL-01	
Test Date: 3-Dec-2010		Location: Bishopdale		Operator: Perry		 
Pre-Drill: 1.2m		Assumed GWL: 1.5mBGL		Located By: Survey GPS		
Position: 2476938.2mE		5745873.3mN		16.38mRL		
Other Tests:				Comments:		





Appendix C – Geotechnical Investigation Summary



■ **Table 1 Summary of most relevant investigation data**

ID	1	2	3
Type *	BH	CPT	CPT
Ref	M35-17562	BDL-02	BDL - 01
Depth (m)	3.1	17.9	17.1
Distance from site (m)	200	240	380
Ground water level (mBGL)	N/A		N/A
Simplified recorded geological profile (depth below ground level to top of stratum, m)	0	N/A	N/A
	0.5		N/A
	1	L	L
	1.5	L	L
	2	L	L
	2.5		D
	3		D
	3.5		D
	4		D
	4.5	St	MD - D
	5	St	MD - D
	5.5	F - St	MD
	6	F - St	L
	6.5	St	So
	7	L - MD	So
	7.5	L - MD	L
	8	MD	L
	8.5	MD	F - St
	9	F	F - St
	9.5	F	L - MD
10	F	L - MD	
10.5	F	L - MD	
11	F	F	
11.5	F	So	
12	So	So	
12.5	F	F - St	
13	F	F - St	
13.5	F	F - St	
14	F	MD	
14.5	St	MD	
15	St	St	
15.5	St	St	
16	St	D	
16.5	St	D	
17	St		
17.5	D		
18			
18.5			

*BH: Borehole, HA: Hand Auger, WW: Water Well, CPT: Cone Penetration Test

Sensitive or organic clay/silt	Clay to silty clay	Clayey silt to silt	Silty sand to silt
Clayey sand	Sand	Gravelly sand or gravel	

VL = very loose, L = loose, MD = medium dense, D = dense, VD = very dense
 VS = very soft, So = soft, F = firm, St = stiff, VS = very stiff, H = hard