



*Christchurch City Council*

# **Hagley Park South – Storage Shed**

**PRK 1507 BLDG 021 EQ2**

**Detailed Engineering Evaluation**

**Quantitative Assessment Report**




*Christchurch City Council*

---

# Hagley Park South – Storage Shed

## Quantitative Assessment Report

Prepared By




.....

Timothy Day  
Graduate Structural Engineer

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail  
Centre, Christchurch 8140  
New Zealand

Reviewed By



.....

Simon Biggs  
Structural Engineer

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: April 2013  
Reference: 6-QUCC1.87  
Status: Final

Approved By



.....

Will Parker  
Principal Structural Engineer  
CPEng 144116

# Summary

Hagley Park South – Storage Shed  
PRK 1507 BLDG 021 EQ2

Detailed Engineering Evaluation  
Quantitative Report - Summary  
Final

## Background

This is a summary of the quantitative report for the Hagley Park South Storage Shed, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on the 27 July 2012 and 7 February 2013.

## Key Damage Observed

No seismic damage was identified at the time of inspection.

## Critical Structural Weaknesses

No potential critical structural weaknesses have been identified.

## Indicative Building Strength

Based on the information available, and from undertaking a quantitative assessment, the building's capacity has been assessed at greater than 63%NBS.

## Recommendations

We make the following recommendations:

- If strengthening is required to increase the seismic capacity of the building to at least 67%NBS, options should be investigated for strengthening the unreinforced sections of masonry wall for out-of-plane bending.
- The extent of corrosion of the porch posts should be investigated to determine if remedial or maintenance measures are required.

# Contents

<b>Summary .....</b>	<b>i</b>
<b>1 Introduction.....</b>	<b>1</b>
<b>2 Compliance .....</b>	<b>1</b>
<b>3 Earthquake Resistance Standards.....</b>	<b>4</b>
<b>4 Building Description .....</b>	<b>7</b>
<b>5 Survey .....</b>	<b>7</b>
<b>6 General Observations.....</b>	<b>8</b>
<b>7 Detailed Seismic Assessment .....</b>	<b>8</b>
<b>8 Summary of Geotechnical Appraisal .....</b>	<b>9</b>
<b>9 Remedial Options.....</b>	<b>10</b>
<b>10 Conclusions.....</b>	<b>10</b>
<b>11 Recommendations .....</b>	<b>10</b>
<b>12 Limitations.....</b>	<b>10</b>
<b>13 References .....</b>	<b>10</b>

## Appendix 1 - Photographs

## Appendix 2 – CERA DEE Spreadsheet

# 1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Hagley Park South Storage Shed, located at Hagley Park, Christchurch following the Canterbury Earthquake Sequence since September 2010.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [3] [4].

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

### Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].



A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

### 3.1.1 Occupancy

The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### 3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

### 3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### 3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

## 4 Building Description

### 4.1 Building Description




Figure 2 - Location of Hagley Park South – Storage Shed

The Hagley Park South Storage Shed is a single storey, partially reinforced, 20 series masonry building with a lightweight steel corrugated iron roof, and a timber framed subfloor supported by short concrete piles and a perimeter concrete foundation wall. The building has a new plasterboard ceiling that appeared to be under construction at the time.

## 5 Survey

Visual inspections were carried out on 27 July 2012 and 7 February 2013.

The building currently has no earthquake rapid assessment placard in place.

No copies of structural drawings have been obtained for the building. Our measure up and observations have been used to confirm the structural systems, to investigate potential critical structural weaknesses (CSW's) wherever possible, and identify details which would require particular attention.

## 6 General Observations

At the time of our inspection a new ceiling had recently been installed and not yet painted (refer to Appendix 1, photo 4). Our cover meter survey also determined that one wall was fully grouted and reinforced while the other walls in the building were not. We would expect that this is a result of renovation works to the building, however as no original drawings of the building were available, we have been unable to determine the extent of works undertaken.

Due to the non-intrusive nature of our investigation the extent of rust observed in the porch posts is unknown, and as such the impact on their capacity could not be determined.

## 7 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

### 7.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building. No CSW's were identified during this assessment.

### 7.2 Seismic Coefficient Parameters

The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class D, clause 3.1.3 NZS 1170.5:2004;
- Site hazard factor,  $Z=0.3$ , B1/VM1 clause 2.2.14B;
- Return period factor,  $R_u = 1.0$  from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life;
- Structural Ductility Factor,  $\mu_{max} = 1.25$

### 7.3 Detailed Seismic Assessment Results

A summary of the structural performance of the building is shown in the following table. Note that the values given represent the worst performing elements in the building, as these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

**Table 2: Summary of Seismic Performance**

<b>Structural Element/System</b>	<b>Failure mode and description of limiting criteria</b>	<b>% NBS based on calculated capacity</b>
Walls Across	Out-of-plane flexure	63%
	In plane shear and flexure	>100%
Walls Along	Out-of-plane flexure	63%
	In-plane shear and flexure	>100%
Posts - porch	Flexure	>100%

## 7.4 Limitations and Assumptions in Results

The observed level of damage suffered by the building was deemed low enough to not affect the capacity. Therefore the analysis and assessment of the building was based on it being in an undamaged state. There may have been damage to the building that was unable to be observed that could cause the capacity of the building to be reduced; therefore the current capacity of the building may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- a. Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- b. Assessments of material strengths based on limited drawings, specifications and site inspections
- c. The normal variation in material properties which change from batch to batch.
- d. Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.

## 8 Summary of Geotechnical Appraisal

Due to a lack of observed ground damage, no specific geotechnical assessment has been undertaken for this site. The site parameters used for the structural analysis have been taken as site subsoil class D, based on geotechnical advice. The existing foundations have performed satisfactorily, and no geotechnical testing is required.

## 9 Remedial Options

Strengthening work is not required unless deemed necessary to achieve a level of 67%NBS or more. Remedial strengthening options could include, but are not limited to, strengthening the existing walls for out-of-plane flexure and addressing the ungrouted, unreinforced sections of wall.

## 10 Conclusions

- a) The building has a seismic capacity of 63%NBS as limited by the unreinforced block masonry walls, and it is not an earthquake prone building.
- b) The existing foundations have performed satisfactorily, and no geotechnical testing is required.

## 11 Recommendations

We make the following recommendations:

- a) If strengthening is required to increase the seismic capacity of the building to at least 67%NBS, options should be investigated for strengthening the unreinforced sections of masonry wall for out-of-plane bending.
- b) The extent of corrosion of the porch posts should be investigated to determine if remedial or maintenance measures are required.

## 12 Limitations

- a) This report is based on an inspection of the structure with a focus on the damage sustained from the 22 February 2011 Canterbury Earthquake and aftershocks only. Some non-structural damage is mentioned but this is not intended to be a comprehensive list of non-structural items.
- b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- c) This report is prepared for the CCC to assist with assessing remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

## 13 References




- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.

- 
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
  - [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
  - [6] DBH (2012), Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch, Department of Building and Housing, June 2012.




## Appendix 1 - Photographs






## Hagley Park South Storage Shed – Detailed Engineering Evaluation

Hagley Park South Storage Shed		
No.	Item description	Photo
1.	South-east view of building	 A photograph showing the south-east view of a white storage shed. The building has a flat roof and two large white doors. It is situated on a grassy area with trees in the background.
2.	North-west view of building	 A photograph showing the north-west view of the storage shed. The building is white with a flat roof and is surrounded by trees and grass. The lighting suggests it is daytime.
3.	South-west view of building	 A photograph showing the south-west view of the storage shed. The building is white with a flat roof and is situated on a grassy area. A chain-link fence is visible in the foreground, and a paved area is visible to the right.

## Hagley Park South Storage Shed – Detailed Engineering Evaluation

4.	Inside room of building. Note new ceiling installed.	 A photograph showing the interior of a storage room. The ceiling is newly installed with a pattern of circular recessed lights. The room contains several large orange plastic drums, boxes, and other miscellaneous items. A timestamp in the bottom right corner reads "07/09/2013 09:42".
5.	Timber roof trusses and ceiling battens.	 A close-up photograph of the timber roof structure. It shows a network of wooden trusses and ceiling battens. A timestamp in the bottom right corner reads "07/09/2013 10:52".
6.	Top plate fixed to top of block wall under.	 A close-up photograph showing a wooden top plate fixed to a block wall. A metal bolt is visible through the plate. A yellow measuring tape is placed horizontally below the plate for scale. A timestamp in the bottom right corner reads "07/09/2013 10:52".

Hagley Park South Storage Shed – Detailed Engineering Evaluation

7.	Base of patio posts	
8.	Top fixing of patio posts. Posts significantly rusted.	
9.	Timber framed floor. No access.	

## **Appendix 2 – CERA DEE Spreadsheet**

<b>Location</b>		Building Name: <input type="text" value="Hagley Park South - Storage Shed"/>	Unit No: <input type="text" value=""/>	Street: <input type="text" value="Hagley Ave"/>	Reviewer: <input type="text" value="Will Parker"/>
Building Address: <input type="text" value="Hospital cnr"/>	Legal Description: <input type="text" value=""/>				CPEng No: <input type="text" value="144116"/>
					Company: <input type="text" value="Opus International Consultants"/>
					Company project number: <input type="text" value="6-QUCC1.87"/>
					Company phone number: <input type="text" value="03 363 5400"/>
					Date of submission: <input type="text" value="11-Apr-13"/>
					Inspection Date: <input type="text" value="27/07/2012 and 7/02/2013"/>
					Revision: <input type="text" value="Final"/>
Building Unique Identifier (CCC): <input type="text" value="PRK 0305 BLDG 003 EQ2"/>					Is there a full report with this summary? <input type="text" value="yes"/>

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value=""/>
		Soil type: <input type="text" value=""/>	Soil Profile (if available): <input type="text" value=""/>
		Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground improvement on site, describe: <input type="text" value=""/>
		Proximity to waterway (m, if <100m): <input type="text" value=""/>	Approx site elevation (m): <input type="text" value=""/>
		Proximity to cliff top (m, if <100m): <input type="text" value=""/>	
		Proximity to cliff base (m, if <100m): <input type="text" value=""/>	

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value=""/>
		Ground floor split?: <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value=""/>
		Storeys below ground: <input type="text" value="0"/>		if Foundation type is other, describe: <input type="text" value="foundation wall and conc piles"/>
		Foundation type: <input type="text" value="other (describe)"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value=""/>	Date of design: <input type="text" value=""/>
		Building height (m): <input type="text" value="2.40"/>		
		Floor footprint area (approx): <input type="text" value="90"/>		
		Age of Building (years): <input type="text" value="40"/>		
		Strengthening present?: <input type="text" value="no"/>		If so, when (year)? <input type="text" value=""/>
		Use (ground floor): <input type="text" value="other (specify)"/>		And what load level (%g)? <input type="text" value=""/>
		Use (upper floors): <input type="text" value=""/>		Brief strengthening description: <input type="text" value=""/>
		Use notes (if required): <input type="text" value="storage"/>		
		Importance level (to NZS1170.5): <input type="text" value="IL2"/>		

<b>Gravity Structure</b>		Gravity System: <input type="text" value="load bearing walls"/>	truss depth, purlin type and cladding: <input type="text" value="corrugated steel"/>
		Roof: <input type="text" value="timber truss"/>	joist depth and spacing (mm): <input type="text" value=""/>
		Floors: <input type="text" value="timber"/>	thickness (mm): <input type="text" value=""/>
		Beams: <input type="text" value=""/>	
		Columns: <input type="text" value=""/>	
		Walls: <input type="text" value="partially filled concrete masonry"/>	

<b>Lateral load resisting structure</b>		Lateral system along: <input type="text" value="partially filled CMU"/>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <input type="text" value=""/>
		Ductility assumed, μ: <input type="text" value="1.25"/>		wall thickness (m): <input type="text" value="0.19"/>
		Period along: <input type="text" value="0.25"/>		estimate or calculation? <input type="text" value=""/>
		Total deflection (ULS) (mm): <input type="text" value=""/>		estimate or calculation? <input type="text" value=""/>
		maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>	##### enter height above at H31	estimate or calculation? <input type="text" value=""/>
		Lateral system across: <input type="text" value="partially filled CMU"/>		note total length of wall at ground (m): <input type="text" value=""/>
		Ductility assumed, μ: <input type="text" value="1.25"/>		wall thickness (m): <input type="text" value="0.19"/>
		Period across: <input type="text" value="0.25"/>		estimate or calculation? <input type="text" value="estimated"/>
		Total deflection (ULS) (mm): <input type="text" value=""/>		estimate or calculation? <input type="text" value=""/>
		maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>		estimate or calculation? <input type="text" value=""/>

<b>Separations:</b>		north (mm): <input type="text" value=""/>	leave blank if not relevant
		east (mm): <input type="text" value=""/>	
		south (mm): <input type="text" value=""/>	
		west (mm): <input type="text" value=""/>	

<b>Non-structural elements</b>		Stairs: <input type="text" value=""/>	describe <input type="text" value="Corrugated sheet"/>
		Wall cladding: <input type="text" value=""/>	
		Roof Cladding: <input type="text" value="Metal"/>	
		Glazing: <input type="text" value="timber frames"/>	
		Ceilings: <input type="text" value="plaster, fixed"/>	
		Services(list): <input type="text" value=""/>	

<b>Available documentation</b>		Architectural: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Structural: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Electrical: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>
		Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text" value=""/>

<b>Damage</b>		Site performance: <input type="text" value="Very good"/>	Describe damage: <input type="text" value=""/>
Site: (refer DEE Table 4-2)		Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text" value=""/>
		Differential settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text" value=""/>
		Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>
		Damage to area: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text" value=""/>

<b>Building:</b>		Current Placard Status: <input type="text" value=""/>	Describe how damage ratio arrived at: <input type="text" value=""/>
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text" value=""/>	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
Across	Damage ratio: <input type="text" value="0%"/>		
Diaphragms	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
Non-structural:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	

<b>Recommendations</b>		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text" value="strengthen masonry walls"/>
		Building Consent required: <input type="text" value="no"/>	Describe: <input type="text" value="check steel posts"/>
		Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text" value=""/>
Along	Assessed %NBS before: <input type="text" value="63%"/>	Assessed %NBS after: <input type="text" value="63%"/>	##### %NBS from IEP below
Across	Assessed %NBS before: <input type="text" value="63%"/>	Assessed %NBS after: <input type="text" value="63%"/>	##### %NBS from IEP below
			If IEP not used, please detail assessment methodology: <input type="text" value="Quantitative"/>



**Opus International Consultants Ltd**  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400  
f: +64 3 365 7858  
w: [www.opus.co.nz](http://www.opus.co.nz)