

# Halswell Aquatic Centre – BBQ Shelter

## Detailed Engineering Evaluation

### BU 1691-006 EQ2

## Qualitative Report

**Prepared for Christchurch City Council (CCC)**

**By Beca Carter Hollings & Ferner Ltd (Beca)**

8 February 2013

© Beca 2013 (unless Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.



## Revision History

Revision N°	Prepared By	Description	Date
A	Andreas Trapezaris	Draft for CCC review	9 October 2012
B	Laura Chen	Building name change	17 October 2012
C	Andreas Trapezaris	Building age updated	23 November 2012
D	Andreas Trapezaris	Final	8 February 2013

## Document Acceptance

Action	Name	Signed	Date
Prepared by	Andreas Trapezaris		9 October 2012
Reviewed by	Nicholas Charman		9 October 2012
Approved by	David Whittaker		9 October 2012
on behalf of	Beca Carter Hollings & Ferner Ltd		

## **Halswell Aquatic Centre, BBQ Shelter BU 1691-006 EQ2**

### **Detailed Engineering Evaluation Qualitative Report – SUMMARY** Version 1

#### **Address**

339 Halswell Road  
Halswell  
Christchurch



## **Background**

This is a summary of the Qualitative report for the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) issued by the Engineering Advisory Group (EAG) on 19 July 2011.

The BBQ Shelter structure is located at 339 Halswell Road, Halswell. The drawing available indicates the BBQ shelter was designed in 1998 and has an approximate floor area of 60m<sup>2</sup> including the awning. The BBQ Shelter is a single storey standalone timber frame structure with a pitched roof clad with lightweight metal sheeting over plywood. The southern walls are timber framed clad with lightweight metal sheeting. The remainder of the structure is open and the floor is a concrete slab on grade.

## **Key Damage Observed**

Visual inspections on 29 August 2012 indicate the building has suffered minor earthquake damage. The key damage observed includes:

- Splitting / Cracking of timber columns.
- Cracking of timber columns near connections.
- Cracking to concrete floor slab near column locations
- Minor movement between the timber ridge beam and column.

## **Critical Structural Weaknesses (CSW)**

No potential Critical Structural Weaknesses have been identified during this Qualitative Assessment.

## **Indicative Building Strength (from Initial Evaluation Procedure and CSW assessment)**

The building has been assessed to have a seismic capacity of 60%NBS using the NZSEE Initial Evaluation Procedure (IEP) and is therefore classified as potentially Earthquake Risk and Seismic Grade C.

## **Recommendations**

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document '*Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch*', June 2012.

The building is considered to be earthquake risk, having an assessed capacity of between 34% and 67%NBS. The risk of collapse of an earthquake risk building is considered to be 5 to 10 times greater than that of an equivalent new building.

No significant damage or hazards were identified to the seismic or gravity load resisting system that would reduce its ability to resist further loads and therefore no restrictions on use or occupancy are recommended.

It is recommended that:

- A quantitative assessment could be undertaken on the building if there is any concern about the qualitative %NBS estimate.
- Repairs that would bring the building back to an "as new" condition are typically entitled under typical replacement insurance policies. We suggest you consult with your insurance advisor as to how you wish to proceed.
- Size of angle braces in the walls should be confirmed as part of the quantitative assessment.

## Table of Contents

<b>Qualitative Report – SUMMARY</b> .....	<b>ii</b>
<b>1 Background</b> .....	<b>1</b>
<b>2 Compliance</b> .....	<b>1</b>
2.1 Canterbury Earthquake Recovery Authority (CERA).....	1
2.2 Building Act .....	2
2.3 Christchurch City Council Policy .....	3
2.4 Building Code.....	3
<b>3 Earthquake Resistance Standards</b> .....	<b>4</b>
<b>4 Building Description</b> .....	<b>5</b>
4.1 General .....	5
4.2 Structural ‘Hot-spots’.....	6
<b>5 Site Investigations</b> .....	<b>6</b>
5.1 Previous Assessments.....	6
5.2 Level 4 Damage Inspection .....	6
<b>6 Damage Assessment</b> .....	<b>7</b>
6.1 Damage Summary .....	7
6.2 Surrounding Buildings .....	7
6.3 Residual Displacements and General Observations .....	7
6.4 Implication of Damage .....	8
<b>7 Generic Issues</b> .....	<b>8</b>
<b>8 Critical Structural Weaknesses</b> .....	<b>8</b>
<b>9 Geotechnical Consideration</b> .....	<b>8</b>
<b>10 Survey</b> .....	<b>8</b>
<b>11 Initial Capacity Assessment</b> .....	<b>8</b>
11.1 %NBS Assessment.....	8
11.2 Seismic Parameters .....	9
11.3 Expected Structural Ductility Factor.....	9
11.4 Discussion of results .....	9
<b>12 Initial Conclusions</b> .....	<b>9</b>
<b>13 Recommendations</b> .....	<b>9</b>
13.1 Occupancy .....	9
13.2 Further Investigations, Survey or Geotechnical Work .....	10
13.3 Damage Reinstatement .....	10
<b>14 Design Features Report</b> .....	<b>10</b>
<b>15 Limitations</b> .....	<b>10</b>

## **Appendices**

**Appendix A - Photographs**

**Appendix B - CERA DEE Summary Data**

**Appendix C - Previous Reports and Assessment**

**Appendix D - Drawings**

## 1 Background

Beca Carter Hollings & Ferner Ltd (Beca) has been engaged by Christchurch City Council (CCC) to undertake a qualitative Detailed Engineering Evaluation (DEE) of the BBQ Shelter building at Halswell Aquatic Centre located at 339 Halswell Road, Halswell.

This report is a Qualitative Assessment of the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) issued by the Engineering Advisory Group (EAG) on 19 July 2011.

A qualitative assessment involves inspections of the building, a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available and an assessment of the level of seismic capacity against current code using the Initial Evaluation Procedure (IEP).

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential Critical Structural Weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of New Building Standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure has been carried out. The building description below is based on our visual inspections and partial drawings.

The format and content of this report follows a template provided by CCC, which is based on the EAG document.

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building

Act). It is understood that CERA is adopting the Detailed Engineering Evaluation Procedure document (draft) issued by the Engineering Advisory Group on 19 July 2011, which sets out a methodology for both qualitative and quantitative assessments. We understand this report will be used in response to CERA Section 51.

The qualitative assessment includes a thorough visual inspection of the building coupled with a desktop review of available documentation such as drawings, specifications and IEP's. The quantitative assessment involves analytical calculation of the building's strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status that was assigned during the state of emergency following the 22 February 2011 earthquake
- The age and structural type of the building
- Consideration of any Critical Structural Weaknesses
- The extent of any earthquake damage

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

### Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- There is a risk that that other property could collapse or otherwise cause injury or death; or
- A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.



## Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

## Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

## Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

### 2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

It is understood that any building with a capacity of less than 33%NBS (including consideration of Critical Structural Weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

### 2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a. Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)

- b. Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

### 3 Earthquake Resistance Standards

For this assessment, the building’s Ultimate Limit State earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

No consideration has been given at this stage to checking the level of compliance against the increased Serviceability Limit State requirements.

The likely ultimate capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a building’s capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 3.1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (Improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

**Figure 3.1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 3.1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. on average 0.2% in any year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

**Table 3.1: %NBS compared to relative risk of failure**

Building Grade	Percentage of New Building Standard (%NBS)	Approx. Risk Relative to a New Building
A+	>100	<1
A	80-100	1-2 times
B	67-80	2-5 times
C	33-67	5-10 times
D	20-33	10-25 times
E	<20	>25 times

## 4 Building Description

### 4.1 General

Summary information about the building is given in the following table.

**Table 4.1: Building Summary Information**

Item	Details	Comment
Building name	BBQ Shelter at Halswell Aquatic Centre	
Street Address	339 Halswell Road, Halswell	
Age	Year built: 1998	From drawings available.
Description	Timber framed shelter with lightweight metal roof cladding and timber columns. Half of the walls are clad with lightweight metal cladding.	
Building Footprint / Floor Area	Approx. 60m <sup>2</sup> (6m x 10m)	
No. of storeys / basements	Single storey, no basement.	
Occupancy / use	Storage	Importance Level 2.
Construction	Timber	Based on visual inspection.
Gravity load resisting system	Gravity loads from the roof are resisted by timber rafters and transferred to timber beams and columns around the perimeter and down the centreline of the building.	
Seismic load resisting system	The lateral loads are likely resisted by a combination of cantilever columns and metal angle braces in the end walls and back wall.  The plywood sheeting in the roof will transfer the lateral loads from the roof to the columns.	Drawing indicates metal angle braces in walls and strip bracing in the roof.

Item	Details	Comment
Foundation system	Slab on grade with cantilever timber columns embedded in concrete piles.	
Stair system	No stairs.	
Other notable features	Open along the northern face.	
External works	Concrete footpath, grassed areas, trees and swimming pools.	
Construction information	Drawing by Ross Maguire Architects dated May 1998.	
Likely design standard	NZS 4203: 1992	Inferred from date noted on drawing.
Heritage status	Not heritage listed	
Other	May be wind governed.	

#### 4.2 Structural 'Hot-spots'

- Connections between timber elements.
- Potentially non-ductile timber lateral load resisting system.

## 5 Site Investigations

### 5.1 Previous Assessments

The building had a Level 2 rapid assessment undertaken following the February 2011 and June 2011 earthquake events (refer to Appendix D).

### 5.2 Level 4 Damage Inspection

Visual inspections as part of the Level 4 damage assessment were undertaken on 29 August 2012.

## 6 Damage Assessment

### 6.1 Damage Summary

The table below provides a summary of damage observed during our inspection. Refer to Appendix A for photographs.

**Table 6.1: Damage Summary**

Damage type	Unknown	Minor	Moderate	Major	Comment
Settlement of foundations	✓				None observed during visual inspection. Level survey may be required to confirm.
Tilt of building	✓				None observed during visual inspection. Verticality survey may be required to confirm.
Liquefaction	✓				None observed during visual inspection. The aerial reconnaissance on 24 Feb 2011 shows that liquefaction occurred on neighbouring sites, where the extent was considered minor.
Settlement of external ground	✓				None observed during visual inspection.
Lateral spread / ground cracks		✓			Minor cracks observed in concrete slab near column locations.
Frame		✓			Cracking and splitting of timber columns near connections and at base of columns. Splitting of the base of the column may have been existing prior to the earthquakes. Minor movement at a ridge beam to column connection.
Bracing					No damage observed during visual inspection
Cladding /envelope					No damage observed during visual inspection.
Building services	✓				No inspections of services were carried out.
Other					

### 6.2 Surrounding Buildings

The Halswell Aquatic Centre has a number of other buildings on the site (See Site Layout in Appendix A), however there are no adjacent structures that are close enough that may affect the BBQ Shelter during an earthquake.

### 6.3 Residual Displacements and General Observations

No evidence of permanent settlement or displacements were observed during our visual inspection, however a global settlement survey may reveal movement that could be described as damage under insurance entitlement.

## **6.4 Implication of Damage**

Based on our visual inspection the structure appears to have incurred minor damage only and therefore we believe the structural capacity has not been materially affected.

## **7 Generic Issues**

Generic issues referred to in Appendix A of the EAG guideline document are not applicable to the timber framed BBQ Shelter structure.

## **8 Critical Structural Weaknesses**

No Critical Structural Weaknesses (CSWs) have been identified for the BBQ Shelter.

## **9 Geotechnical Consideration**

No Geotechnical information was available for this site. During the inspection, any damage to the surrounding ground was noted and any affect to the structure was considered.

## **10 Survey**

No level or verticality surveys were carried out as there was no evidence of settlement or displacement observed during the inspection. CCC may wish to undertake a level survey as part of insurance entitlement considerations.

## **11 Initial Capacity Assessment**

### **11.1 %NBS Assessment**

The building has had its seismic capacity assessed using the Initial Evaluation Procedure based on the drawing available and visual assessment of the structural system. The building's capacity is expressed as a percentage of New Building Standard (%NBS) and is in the order of that shown below in Table 11.1. With only minor earthquake damage these capacities are subject to confirmation by a quantitative analysis which is more detailed. The post-damage capacity is considered to be the same as the original capacity.

**Table 11.1: Indicative Building Capacities**

System	Direction	Seismic Performance in %NBS	Notes
Cantilevering timber columns and metal angle braces	Longitudinal	60%	NZSEE Initial Evaluation Procedure. IL2, Z=0.3
Cantilevering timber columns and metal angle braces	Transverse	60%	NZSEE Initial Evaluation Procedure. IL2, Z=0.3

## 11.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2004 and the NZBC clause B1 for this building are:

- Site soil class: D – NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- Site hazard factor,  $Z = 0.3$  – NZBC, Clause B1 Structure, Amendment 11 effective from 19 May 2011
- Return period factor  $R_u = 1$  – NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.
- Near fault factor  $N(T,D) = 1$  – NZS 1170.5:2004, Clause 3.1.6, Distance more than 20 km from fault line.

## 11.3 Expected Structural Ductility Factor

The lateral load resisting system in both directions has been assumed to have a ductility factor of 1.0.

## 11.4 Discussion of results

Based on the assessment results, the BBQ Shelter is potentially Earthquake Risk as the result is less than 67%NBS and greater than 33%NBS and is Seismic Grade C. This assessment is qualitative and based on the NZSEE IEP only. Some assumptions have been made such as the adequacy of connections between the roof and walls/columns.

## 12 Initial Conclusions

- The building has been assessed to have a seismic capacity of 60%NBS and is therefore potentially Earthquake Risk.
- No Critical Structural Weaknesses have been identified.
- Minor earthquake damage was observed during the visual inspection.

## 13 Recommendations

### 13.1 Occupancy

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document '*Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch*', June 2012.

The building is considered to be earthquake risk, having an assessed capacity of between 34% and 67%NBS. The risk of collapse of an earthquake risk building is considered to be 5 to 10 times greater than that of an equivalent new building.

No significant damage or hazards were identified to the seismic or gravity load resisting system that would reduce its ability to resist further loads and therefore no restrictions on use or occupancy are recommended.

### **13.2 Further Investigations, Survey or Geotechnical Work**

It is recommended that:

- A quantitative assessment could be undertaken on the building if there is any concern about the qualitative %NBS estimate.
- Size of angle braces in the walls should be confirmed as part of the quantitative assessment.

### **13.3 Damage Reinstatement**

Repairs that would bring the building back to an “as new” condition are typically entitled under typical replacement insurance policies. We suggest you consult with your insurance advisor as to how you wish to proceed.

## **14 Design Features Report**

Repairs will be required to reinstate the existing structural system. No new load paths are expected. A repair methodology has not been prepared at this stage

## **15 Limitations**

The following limitations apply to this engagement:

- Beca and its employees and agents are not able to give any warranty or guarantee that all defects, damage, conditions or qualities have been identified.
- Inspections are primarily limited to visible structural components. Appropriate locations for invasive inspection, if required, will be based on damage patterns observed in visible elements, and review of the construction drawings and structural system. As such, there will be concealed structural elements that will not be directly inspected.
- The inspections are limited to building structural components only.
- Inspection of building services, pipework, pavement, and fire safety systems is excluded from the scope of this report.
- Inspection of the glazing system, linings, carpets, claddings, finishes, suspended ceilings, partitions, tenant fit-out, or the general water tightness envelope is excluded from the scope of this report.
- The preliminary assessment of the lateral load capacity of the building is limited by the completeness and accuracy of the drawings provided. Assumptions have been made in respect of the geotechnical conditions at the site and any aspects or material properties not clear on the drawings. Where these assumptions are considered material to the outcome further investigations may be recommended. It is noted the assessment has not been exhaustive, our analysis and calculations have focused on representative areas only to determine the level of provision made. At this stage we have not undertaken any checks of the gravity system, wind load capacity, or foundations.



- The information in this report provides a snapshot of building damage at the time the detailed inspection was carried out. Additional inspections required as a result of significant aftershocks are outside the scope of this work.

This report is of defined scope and is for reliance by CCC only, and only for this commission. Beca should be consulted where any question regarding the interpretation or completeness of our inspection or reporting arises.

Appendix A

# Photographs



Figure A1: Site Plan (BBQ Shelter indicated)



**Photo 1:** External view of the building with awning.



**Photo 2:** Internal view with the southern wall linings shown.





**Photo 3:** Timber column embedded into concrete slab.

**Damage Description:** Splitting/ Cracking of timber columns. Hairline cracks in concrete slab



**Photo 4:** Typical column/beam connection

**Damage Description:** Splitting /Cracking of timber column near connection.



**Photo 5:** Ridge beam and rafter typical connection.

**Damage Description:** Ridge beam connection movement.

Appendix B

## CERA DEE Summary Data

<b>Location</b>		Building Name: <input type="text" value="BBQ Shelter"/>	Unit: <input type="text" value=""/>	No: <input type="text" value=""/>	Street: <input type="text" value="339 Halswell Road"/>	Reviewer: <input type="text" value="David Whittaker"/>	CP/Eng No: <input type="text" value="123389"/>
Building Address: <input type="text" value="Halswell Aquatic Centre"/>						Company: <input type="text" value="Beca"/>	Company project number: <input type="text" value="5323355"/>
Legal Description: <input type="text" value=""/>						Company phone number: <input type="text" value="03 3663521"/>	
GPS south: <input type="text" value=""/>		Degrees: <input type="text" value=""/>		Min: <input type="text" value=""/>		Sec: <input type="text" value=""/>	
GPS east: <input type="text" value=""/>						Date of submission: <input type="text" value="29/08/2012"/>	
Building Unique Identifier (CCC): <input type="text" value="BU 1691-006 EQ2"/>						Is there a full report with this summary? <input type="text" value="yes"/>	

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value="0"/>
Soil type: <input type="text" value=""/>		Soil Profile (if available): <input type="text" value="Unknown"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		If Ground improvement on site, describe: <input type="text" value=""/>	
Proximity to waterway (m, if <100m): <input type="text" value=""/>		Approx site elevation (m): <input type="text" value="0.00"/>	
Proximity to cliff top (m, if < 100m): <input type="text" value=""/>			
Proximity to cliff base (m, if <100m): <input type="text" value=""/>			

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value=""/>
Ground floor split? <input type="text" value="no"/>				Ground floor elevation above ground (m): <input type="text" value="0.00"/>
Storeys below ground: <input type="text" value="0"/>				Foundation type is other, describe: <input type="text" value="Post holes assumed with slab on grade"/>
Foundation type: <input type="text" value="other (describe)"/>				height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="3.5"/>
Building height (m): <input type="text" value="3.50"/>				Date of design: <input type="text" value="1992-2004"/>
Floor footprint area (approx): <input type="text" value="50"/>				
Age of Building (years): <input type="text" value="14"/>				
Strengthening present? <input type="text" value="no"/>				If so, when (year)? <input type="text" value=""/>
Use (ground floor): <input type="text" value="other (specify)"/>				And what load level (%g)? <input type="text" value=""/>
Use (upper floors): <input type="text" value=""/>				Brief strengthening description: <input type="text" value=""/>
Use notes (if required): <input type="text" value="swimming club shelter"/>				
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

<b>Gravity Structure</b>		Gravity System: <input type="text" value="frame system"/>	
Roof: <input type="text" value="timber framed"/>		rafter type, purlin type and cladding: <input type="text" value="Timber rafters, plywood, metal sheeting"/>	
Floors: <input type="text" value="concrete flat slab"/>		slab thickness (mm): <input type="text" value="Slab on grade"/>	
Beams: <input type="text" value="timber"/>		type: <input type="text" value=""/>	
Columns: <input type="text" value="timber"/>		typical dimensions (mm x mm): <input type="text" value="0"/>	
Walls: <input type="text" value="non-load bearing"/>			

<b>Lateral load resisting structure</b>		<b>Note: Define along and across in detailed report!</b>	
Lateral system along: <input type="text" value="other (note)"/>		describe system: <input type="text" value="cantilevering timber posts and metal angle braces"/>	
Ductility assumed, $\mu$ : <input type="text" value="1.00"/>		estimate or calculation? <input type="text" value="estimated"/>	
Period along: <input type="text" value="0.40"/>		estimate or calculation? <input type="text" value=""/>	
Total deflection (ULS) (mm): <input type="text" value=""/>		estimate or calculation? <input type="text" value=""/>	
maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>			
Lateral system across: <input type="text" value="other (note)"/>		describe system: <input type="text" value="cantilevering timber posts and metal angle braces"/>	
Ductility assumed, $\mu$ : <input type="text" value="1.00"/>		estimate or calculation? <input type="text" value="estimated"/>	
Period across: <input type="text" value="0.40"/>		estimate or calculation? <input type="text" value=""/>	
Total deflection (ULS) (mm): <input type="text" value=""/>		estimate or calculation? <input type="text" value=""/>	
maximum interstorey deflection (ULS) (mm): <input type="text" value=""/>			

<b>Separations:</b>		leave blank if not relevant	
north (mm): <input type="text" value=""/>			
east (mm): <input type="text" value=""/>			
south (mm): <input type="text" value=""/>			
west (mm): <input type="text" value=""/>			

<b>Non-structural elements</b>			
Stairs: <input type="text" value=""/>		describe	<input type="text" value="None"/>
Wall cladding: <input type="text" value="other light"/>		describe	<input type="text" value="Lightweight metal"/>
Roof Cladding: <input type="text" value="Metal"/>		describe	<input type="text" value="Lightweight metal"/>
Glazing: <input type="text" value="other (specify)"/>			<input type="text" value="None"/>
Ceilings: <input type="text" value="none"/>			<input type="text" value="Plywood sheathing above rafters"/>
Services(list): <input type="text" value=""/>			

<b>Available documentation</b>			
Architectural: <input type="text" value="none"/>		original designer name/date	<input type="text" value=""/>
Structural: <input type="text" value="none"/>		original designer name/date	<input type="text" value=""/>
Mechanical: <input type="text" value="none"/>		original designer name/date	<input type="text" value=""/>
Electrical: <input type="text" value="none"/>		original designer name/date	<input type="text" value=""/>
Geotech report: <input type="text" value="none"/>		original designer name/date	<input type="text" value=""/>

<b>Damage</b>			
Site: <input type="text" value="Good"/>	Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text" value="No site damage was observed"/>	
Settlement: <input type="text" value="none observed"/>		notes (if applicable): <input type="text" value=""/>	
Differential settlement: <input type="text" value="none observed"/>		notes (if applicable): <input type="text" value=""/>	
Liquefaction: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>	
Lateral Spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>	
Differential lateral spread: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>	
Ground cracks: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>	
Damage to area: <input type="text" value="none apparent"/>		notes (if applicable): <input type="text" value=""/>	

<b>Building:</b>		Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value=""/>	Describe how damage ratio arrived at: <input type="text" value="No significant damage"/>	
	Describe (summary): <input type="text" value=""/>		
Across	Damage ratio: <input type="text" value=""/>	$Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$	
	Describe (summary): <input type="text" value=""/>		
Diaphragms	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	
Non-structural:	Damage?: <input type="text" value="no"/>	Describe: <input type="text" value=""/>	

<b>Recommendations</b>			
Level of repair/strengthening required: <input type="text" value="minor structural"/>		Describe: <input type="text" value="Column splitting/cracking"/>	
Building Consent required: <input type="text" value="no"/>		Describe: <input type="text" value=""/>	
Interim occupancy recommendations: <input type="text" value="full occupancy"/>		Describe: <input type="text" value=""/>	
Along	Assessed %NBS before: <input type="text" value="0%"/>	60% %NBS from IEP below	If IEP not used, please detail assessment methodology: <input type="text" value=""/>
	Assessed %NBS after: <input type="text" value="0%"/>		
Across	Assessed %NBS before: <input type="text" value="0%"/>	60% %NBS from IEP below	
	Assessed %NBS after: <input type="text" value="0%"/>		



IEP

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1992-2004

h<sub>s</sub> from above: 3.5m

Seismic Zone, if designed between 1965 and 1992: B

not required for this age of building: D soft soil  
Design Soil type from NZS4203:1992, cl 4.6.2.2: b) Intermediate

Period (from above):	along	across
(%NBS) <sub>nom</sub> from Fig 3.3:	0.4	0.4
	22.3%	22.3%

Note: 1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0  
 Note 2: for RC buildings designed between 1976-1984, use 1.2  
 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

Final (%NBS) <sub>nom</sub> :	along	across
	22%	22%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6: 1.00

Near Fault scaling factor (1/N(T,D), Factor A):	along	across
	1	1

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3: 0.30

Z<sub>req</sub> from NZS4203:1992: 0.8  
Hazard scaling factor, Factor B: 2.66666667

2.4 Return Period Scaling Factor

Building Importance level (from above): 2  
Return Period Scaling factor from Table 3.1, Factor C: 1.00

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2): 1.00  
Ductility scaling factor: =1 from 1976 onwards; or =k<sub>u</sub>, if pre-1976, from Table 3.3: 1.00

Ductility Scaling Factor, Factor D:	along	across
	1.00	1.00

2.6 Structural Performance Scaling Factor:

Sp: 1.000  
Structural Performance Scaling Factor Factor E: 1

2.7 Baseline %NBS, (NBS%)<sub>b</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E

%NBS<sub>b</sub>: 60%

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: insignificant 1

3.2. Vertical irregularity, Factor B: insignificant 1

3.3. Short columns, Factor C: insignificant 1

3.4. Pounding potential

Pounding effect D1, from Table to right	1.0
Height Difference effect D2, from Table to right	1.0

Therefore, Factor D: 1

3.5. Site Characteristics: insignificant 1

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum  
Rationale for choice of F factor, if not 1

	Along	Across
	1.0	1.0

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

	1.00	1.00
--	------	------

4.3 PAR x (%NBS)<sub>b</sub>:

PAR x Baseline %NBS: 60%

4.4 Percentage New Building Standard (%NBS), (before)

60%

Official Use only:

Accepted By: \_\_\_\_\_  
Date: \_\_\_\_\_

Appendix C

## Previous Reports and Assessments

# Christchurch Eq RAPID Assessment Form - LEVEL 2

Inspector Initials: MX      Date: 21/06/2011      Final Posting (e.g. UNSAFE): G2  
 Territorial Authority: Christchurch City      Time: 9:30

Building Name: <u>HALSWELL POOL</u>		Type of Construction	
Short Name: <u>RBC SHELTER</u>		<input checked="" type="checkbox"/> Timber frame	<input type="checkbox"/> Concrete shear wall
Address: <u>BU 1691-006 EQZ</u>		<input type="checkbox"/> Steel frame	<input type="checkbox"/> Unreinforced masonry
GPS Co-ordinates: S° _____ E° _____		<input type="checkbox"/> Tilt-up concrete	<input type="checkbox"/> Reinforced masonry
Contact Name: _____		<input type="checkbox"/> Concrete frame	<input type="checkbox"/> Confined masonry
Contact Phone: _____		<input type="checkbox"/> RC frame with masonry infill	<input type="checkbox"/> Other: _____
Stores at and above ground level: _____	Below ground level: _____	Primary Occupancy	
Total gross floor area (m <sup>2</sup> ): _____	Year built: _____	<input type="checkbox"/> Dwelling	<input type="checkbox"/> Commercial/ Offices
No of residential Units: _____		<input type="checkbox"/> Other residential	<input type="checkbox"/> Industrial
		<input type="checkbox"/> Public assembly	<input type="checkbox"/> Government
		<input type="checkbox"/> School	<input type="checkbox"/> Heritage Listed
		<input type="checkbox"/> Religious	<input type="checkbox"/> Other
Photo Taken: Yes <input type="checkbox"/> No <input type="checkbox"/>			

Investigate the building for the conditions listed on page 1 and 2, and check the appropriate column. A sketch may be added on page 3

Overall Hazards / Damage	Minor/None	Moderate	Severe	Comments
Collapse, partial collapse, off foundation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Building or storey leaning	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	* Timber
Wall or other structural damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	column cracking in misc locations
Overhead falling hazard	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ground movement, settlement, slips	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Neighbouring building hazard	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Electrical, gas, sewerage, water, hazmats	<input type="checkbox"/> N/A	<input type="checkbox"/>	<input type="checkbox"/>	

Record any existing placard on this building:

Existing Placard Type (e.g. UNSAFE)

GREEN (COMPLEX)

Choose a new posting based on the new evaluation and team judgement. Severe conditions affecting the whole building are grounds for an UNSAFE posting. Localised Severe and overall Moderate conditions may require a RESTRICTED USE. Place INSPECTED placard at main entrance. Post all other placards at every significant entrance. Transfer the chosen posting to the top of this page.

INSPECTED  
GREEN

G1  G2

RESTRICTED USE  
YELLOW

Y1  Y2

UNSAFE  
RED

R1  R2  R3

Record any restriction on use or entry:

Further Action Recommended:

Tick the boxes below only if further actions are recommended

- Barricades are needed (state location): \_\_\_\_\_
- Detailed engineering evaluation recommended
- Structural       Geotechnical       Other: \_\_\_\_\_
- Other recommendations: \_\_\_\_\_

*Minor concrete defect upgrade.*

Estimated Overall Building Damage (Exclude Contents)

None	<input type="checkbox"/>	31-60 %	<input type="checkbox"/>
0-1 %	<input type="checkbox"/>	61-99 %	<input type="checkbox"/>
2-10 %	<input checked="" type="checkbox"/>	100 %	<input type="checkbox"/>
11-30 %	<input type="checkbox"/>		

Sign here on completion

Koehnster

Date & Time  
ID

22/06/11

Inspection ID: \_\_\_\_\_ (Office Use Only)

PROP 1:

*WA*

Structural Hazards/ Damage	Minor/None	Moderate	Severe	Comments
Foundations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Roofs, floors (vertical load)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Columns, pilasters, corbels	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<i>cracked columns</i>
Diaphragms, horizontal bracing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Pre-cast connections	<input type="checkbox"/> <i>N/A</i>	<input type="checkbox"/>	<input type="checkbox"/>	
Beam	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>Non-structural Hazards / Damage</b>				
Parapets, ornamentation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Cladding, glazing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ceilings, light fixtures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Interior walls, partitions	<input type="checkbox"/> <i>N/A</i>	<input type="checkbox"/>	<input type="checkbox"/>	
Elevators	<input type="checkbox"/> <i>N/A</i>	<input type="checkbox"/>	<input type="checkbox"/>	
Stairs/ Exits	<input type="checkbox"/> <i>N/A</i>	<input type="checkbox"/>	<input type="checkbox"/>	
Utilities (eg. gas, electricity, water) <i>not checked</i>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>Geotechnical Hazards / Damage</b>				
Slope failure, debris	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Ground movement, fissures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Soil bulging, liquefaction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
<b>General Comment</b>				
_____				
_____				
_____				
_____				

**Usability Category**







Damage Intensity	Posting	Usability Category	Remarks
Light damage	Inspected (Green)	G1. Occupiable, no immediate further investigation required	
Low risk		G2. Occupiable, repairs required	<i>The rafter beam to column connection needs repair.</i>
Medium damage	Restricted Use (Yellow)	Y1. Short term entry	
Medium risk		Y2. No entry to parts until repaired or demolished	
Heavy damage	Unsafe (Red)	R1. Significant damage: repairs, strengthening possible	
High risk		R2. Severe damage: demolition likely	
		R3. At risk from adjacent premises or from ground failure	

2 Inspection ID: \_\_\_\_\_ (Office Use Only)



Appendix D

## Drawings



**SPECIFICATION NOTE:**

CONTRACTOR:

- ALL WORK SHALL BE CARRIED OUT IN ACCORDANCE WITH GOOD TRADE PRACTICES BY SKILLED TRADESMEN.
- ALL VARIATIONS SHALL BE IN WRITING ONLY.
- ALL MATERIALS WHETHER ON SITE OR NOT SHALL BE COVERED BY INSURANCE. THE MAIN CONTRACTOR SHALL OBTAIN AN ALL RISKS INSURANCE POLICY WHICH SHALL INDEMNIFY THE OWNER AGAINST ANY CLAIM RELATING TO THE CONTRACT.
- THE MAIN CONTRACTOR SHALL MAINTAIN ALL INSPECTIONS AS NECESSARY. ALL TESTS SHALL BE RUN BY OWNERS.
- TO OPERATE WITH OWNERS I MAINTAIN SECURITY AT ALL TIMES.
- ALL CONTRACTORS SHALL TAKE ALL REASONABLE PRECAUTIONS TO PROTECT THE FINISHED SURFACES OF OTHER TRADES.

CONSULTING ENGINEER:  
 BRIAN SPENCER  
 CIVIL CONSULTING  
 11 NEWBARDS RD  
 RYDALTON  
 DUNEDIN 8002

CHRISTCHURCH CITY COUNCIL  
 P.I.M. APPLICATION  
 Rec'd 2.2 MAY 1998  
 Civic Offices  
 PROJECT No. 980028



# HALSWELL SWIMMING POOL BARBECUE DAVILION

ROSS MAGUIRE  
 ARCHITECTS

CONTRACTOR SHALL VERIFY ALL DIMENSIONS BEFORE STARTING ANY WORK. DO NOT SCALE OFF THIS DRAWING.

DATE: MAY 1998

SCALE: 1:100, 1:50, 1:20