# City Care Milton Street Depot – Tradesmens Workshop Detailed Engineering Evaluation BU 1141-001 EQ2 Quantitative Report

Prepared for Christchurch City Council (Client)

By Beca Carter Hollings & Ferner Ltd (Beca)

4 October 2013

 $\ensuremath{\mathbb{C}}$  Beca 2013 (unless Beca has expressly agreed otherwise with the Client in writing).

This report has been prepared by Beca on the specific instructions of our Client. It is solely for our Client's use for the purpose for which it is intended in accordance with the agreed scope of work. Any use or reliance by any person contrary to the above, to which Beca has not given its prior written consent, is at that person's own risk.



## **Revision History**

Revision Nº	Prepared By	Description	Date		
А	Laura Chen	Draft for CCC review	26 September 2013		
В	Laura Chen	Final	4 October 2013		

## **Document Acceptance**

Action	Name	Signed	Date				
Prepared by	Laura Chen	Zn.	4 October 2013				
Reviewed by	Jonathan Barnett	SBarret	4 October 2013				
Approved by	David Whittaker	Derhittah	4 October 2013				
on behalf of	Beca Carter Hollings & Ferner Ltd						



## City Care Milton Street Depot –Tradesmens Workshop BU 1141-001 EQ2

**Detailed Engineering Evaluation Quantitative Report – SUMMARY** Version 1

Address 245 Milton Street Sydenham Christchurch



## Background

This is a summary of the Quantitative Assessment report for the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) Revision 7 issued by the Engineering Advisory Group (EAG) in 2012.

A Qualitative Assessment report for the Tradesmens Workshop was issued to CCC on 7 June 2012

The Tradesmens Workshop is located at the City Care Milton St Depot at 245 Milton Street, Sydenham, Christchurch. It is a steel portal frame building with precast concrete shear walls. The structural drawings available indicate the Tradesmens Workshop was designed in 1974. Calculations have been undertaken as part of the Quantitative Assessment.

The format and content of this report follows a template provided by CCC, which is based on the EAG document.

## **Key Damage Observed**

Visual inspections on 8 February 2012 and 9 October 2012 indicate the building has suffered moderate damage. Key damage observed include:

- Vertical cracking and spalling to the western and southern concrete walls adjacent to joints.
- Significant spalling to one columns' concrete encasement adjacent to the weld plate joints in the Sign Shop area. It was noted that this panel has been secured with steel brackets prior to our inspection.
- Diagonal cracking at the base of the concrete wall in the stairwell to the second storey office.
- Cracking and spalling to the column concrete encasement at various portal frame knee joints.
- Cracking to precast concrete wall panels at the portal frame knee cast in connections.

## **Critical Structural Weaknesses (CSW)**

The following Critical Structural Weaknesses have been identified:

Site characteristics due to liquefaction occurring on the Milton St site.



 Difference in stiffness between the western Sign Shop area and the rest of the building due to the portal frame orientation.

## Indicative Building Strength (from Detailed Assessment)

The building has been assessed to have a seismic capacity of 10%NBS in one localised area, using the New Zealand Society for Earthquake Engineering (NZSEE) Detailed Assessment guideline 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006, and is therefore Earthquake Prone and classified as Seismic Grade E.

Our assessment has identified the structural components that have governed/limited the building's seismic performance, and their potential failure mechanisms, are as follows:

- The beam supporting the southern Sign Shop portal frames achieve 10%NBS under longitudinal (out-of-plane) loading.
- The knee connection of the steel portal frames at the eastern end of the building achieve 35%NBS under transverse (in-plane) loading.
- The steel portal frame rafters at the eastern end of the building achieve 39%NBS under transverse (in-plane) loading.

There are a number of other elements in the building which have assessed seismic capacities greater than 33%NBS and less than 67%NBS.

The structural damage observed to the precast concrete panels is moderate and the seismic capacity of the precast concrete panels is considered to have reduced due to the damage from 100%NBS to 67%NBS. This reduction does not affect the overall seismic capacity of the building however, since this is limited by the Sign Shop portal frame support beam. No significant damage was noted to this element.

## Recommendations

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document 'Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch', June 2012.

The building is considered to be earthquake prone, having an assessed capacity less than 33%NBS, and is classified as Seismic Grade E. The risk of collapse of an earthquake prone building of this grade is considered to be more than 25 times greater than that of an equivalent new building.

For greater Christchurch the definition of a "dangerous" building in the Building Act has been extended (by the Canterbury Earthquake (Building Act) Order 2011) to include buildings at risk of collapsing in a moderate earthquake, that is earthquake prone buildings with a capacity at or below 33%NBS. Where council requires a dangerous building or an earthquake prone building to be upgraded, it may prohibit the use of the building until the works are carried out.

The structural damage observed to the precast concrete panels is moderate and the seismic capacity of the precast concrete panels is considered to have reduced due to the damage. This reduction does not affect the overall seismic capacity of the building. No significant damage was noted to the structural element that is the limiting capacity of the building.



It is recommended that:

- The immediate area under the southern Sign Shop portals is vacated or restricted use until local strengthening of the support beam is completed.
- The roof bracing in the trussed roof area should be installed as shown on the drawings.
- A full damage assessment is carried out for insurance purposes.
- A settlement survey could be carried out to determine the extent of settlement of the building for insurance purposes.
- According to the recent CCC Instructions to Engineers document (16 October 2012), Council's insurance provides for repairing damaged elements to a condition substantially as new. We suggest you consult further with your insurance advisor.



# **Table of Contents**

Qu	antita	tive Report – SUMMARY	ii
1	Bacl	‹ground	1
2	Com	pliance	1
	2.1	Canterbury Earthquake Recovery Authority (CERA)	1
	2.2	Building Act	2
	2.3	Christchurch City Council Policy	
	2.4	Building Code	3
3	Eart	hquake Resistance Standards	4
4	Buil	ding Description	5
	4.1	General	5
	4.2	Structural 'Hot-spots'	6
5	Site	Investigations	7
	5.1	Previous Assessments	7
	5.2	Level 5 Intrusive Investigations	7
6	Dam	age Assessment	7
	6.1	Damage Summary	7
	6.2	Surrounding Buildings	8
	6.3	Residual Displacements and General Observations	8
	6.4	Implication of Damage	8
7	Gen	eric Issues	9
8	Geo	technical Consideration	9
9	Surv	/ey	9
10		iled Seismic Capacity Assessment	
	10.1	Assessment Methodology	
	10.2	Assumptions	9
	10.3	Critical Structural Weaknesses 1	0
	10.4	Seismic Parameters 1	0
	10.5	Results of Seismic Assessment 1	0
	10.6	Discussion of results1	1
11	Reco	ommendations1	2
	11.1	Occupancy1	2
	11.2	Further Investigations, Survey or Geotechnical Work1	2
	11.3	Damage Reinstatement1	2
12	Desi	gn Features Report 1	3
13	Limi	tations1	3



## **Appendices**

Appendix A - Photographs

Appendix B - Existing Drawings

Appendix C - CERA DEE Summary Data

Appendix D - Previous Reports and Assessments



## 1 Background

Beca Carter Hollings & Ferner Ltd (Beca) has been engaged by Christchurch City Council (CCC) to undertake a Quantitative Detailed Engineering Evaluation (DEE) of the Tradesmens Workshop building located at 245 Milton Street, Sydenham, Christchurch.

This report is a Quantitative Assessment of the building structure, and is based on the document 'Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury – Part 2 Evaluation Procedure' (draft) Revision 7 issued by the Engineering Advisory Group in 2012.

A quantitative assessment involves analytical calculations of the building's strength and may involve material testing, geotechnical testing and intrusive investigation. The qualitative assessment previously carried out involved inspections of the building, a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available and an assessment of the level of seismic capacity against current code using the Initial Evaluation Procedure (IEP).

The purpose of these assessments is to determine the likely building performance and damage patterns, to identify any potential Critical Structural Weaknesses (CSW) or collapse hazards, and to make an assessment of the likely building strength in terms of percentage of New Building Standard (%NBS).

A full set of structural drawings (consent issue) was made available and has been used in our assessment of the building. The building description below is based on a review of the drawings and our visual inspections.

The format and content of this report follows a template provided by CCC, which is based on the EAG document.

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

## 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 - Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 - Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.



We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is understood that CERA is adopting the Detailed Engineering Evaluation Procedure document (draft) Revision 7 issued by the Engineering Advisory Group in 2012, which sets out a methodology for both qualitative and quantitative assessments. We understand this report will be used in response to CERA Section 51.

The qualitative assessment includes a thorough visual inspection of the building coupled with a desktop review of available documentation such as drawings, specifications and IEP's. The quantitative assessment involves analytical calculation of the building's strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status that was assigned during the state of emergency following the 22 February 2011 earthquake
- The age and structural type of the building
- Consideration of any Critical Structural Weaknesses
- The extent of any earthquake damage

### 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

#### Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

#### Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- There is a risk that that other property could collapse or otherwise cause injury or death; or



 A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 - Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

#### 2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

It is understood that any building with a capacity of less than 33%NBS (including consideration of Critical Structural Weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

### 2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.



On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a. Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b. Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

## **3 Earthquake Resistance Standards**

For this assessment, the building's Ultimate Limit State earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

No consideration has been given at this stage to checking the level of compliance against the increased Serviceability Limit State requirements.

The likely ultimate capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a building's capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 3.1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance		Improvement of Structural Performance			
					⊢	Legal Requirement	NZSEE Recommendation		
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)		The Building Act sets no required level of structural improvement	100%NBS desirable. Improvement should achieve at least 67%NBS		
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		(unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	Not recommended. Acceptable only in exceptional circumstances		
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement		Unacceptable	Unacceptable		

# Figure 3.1: NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 3.1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. on average 0.2% in any year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Building Grade	Percentage of New Building Standard (% <i>NBS</i> )	Approx. Risk Relative to a New Building						
A+	>100	<1						
A	80-100	1-2 times						
В	67-80	2-5 times						
С	33-67	5-10 times						
D	20-33	10-25 times						
E	<20	>25 times						

#### Table 3.1: %NBS Compared to Relative Risk of Failure

## 4 **Building Description**

#### 4.1 General

Summary information about the building is given in the following table.

Item	Details	Comment
Building name	City Care Milton Street Depot –	
	Tradesmens Workshop	
Street Address	245 Milton Street	
	Sydenham	
	Christchurch	
Age	Designed in 1974, approved in 1977	From drawings available
Description	Series of workshops for the Sign Shop, Building Services and Plant Pool Hire, offices for City Care Facilities Management, and storage	
Building Footprint / Floor Area	Approx. 72.1m x 15.5m and 6.3m x 30.9m. 1310m <sup>2</sup> internally	
No. of storeys / basements	Mostly 1 storey/no basement	Mezzanine storage floors in eastern workshop area. Second storey office above building services workshop
Occupancy / use	Workshops, offices and storage	Importance Level 2
Construction	Steel portal frames with glazed infill's and concrete walls	
Gravity load resisting system	Steel roof onto steel purlins, which are supported by steel portal frames	

## Table 4.1: Building Summary Information



Item	Details	Comment
Seismic load resisting system	Steel portal frames transversely with precast concrete shear walls longitudinally. Steel cross bracing in the roof. The direction of each system changes at the western end of the building.	The drawings indicate roof bracing in the trussed roof area of the building between gridlines 7 and 9. Site inspections revealed that only one of the bays of bracing was constructed in accordance with the drawings. Site inspections also revealed that the internal precast concrete wall along gridline 3 was also not constructed. These items have not been included in this assessment.
Foundation system	Reinforced concrete slab with concrete pads and tie beams.	Inferred from drawings.
Stair system	Timber stairs to upstairs office.	
Other notable features	Mezzanines at eastern end of building.	
External works		
Construction information	Structural drawings by City Engineer's Department dated 1974 and partial Architectural drawings by Lucking and Vial. Both consent copies dated 1977.	
Likely design standard	NZSS 1900, Chapter 8:1965	Inferred from age of building.
Heritage status	No known heritage status	
Other	Steel framed silo support adjacent to Building Services workshop.	Not attached and not considered part of the building.

## 4.2 Structural 'Hot-spots'

Areas in which damage may be expected to occur from earthquake shaking are outlined below;

- Precast concrete wall panels and column encasements due to out-of-plane movement.
- Cast-in wall connections to the portal frame column.
- Elements in the area where the Sign Shop and the main workshop area meet.
- Southern precast concrete wall panels orthogonal to the panels supporting the office mezzanine due to stiffness incompatibility between portal frames.
- Roof bracing connections.
- Connections between the Sign Shop portal frames and their support beam on gridline 2.



## **5** Site Investigations

### 5.1 **Previous Assessments**

It is understood that Opus International Consultants undertook rapid assessments of the buildings on the Milton St Depot site. These reports were not available for review. City Care carried out a damage assessment in April 2011 (refer Appendix D).

Visual inspections as part of the Level 4 assessment were undertaken on 8 February 2012. A Qualitative Report was issued to CCC on 7 June 2012.

#### 5.2 Level 5 Intrusive Investigations

A further inspection was carried out on 9 October 2012 as part of the Level 5 Quantitative Assessment. This inspection revealed the missing bay of roof bracing in the trussed roof area.

## 6 Damage Assessment

#### 6.1 Damage Summary

The table below provides a summary of damage that we observed on our inspection visit. Refer to Appendix A for photographs.

Damage type	Unknown	Minor	Moderate	Major	Comment
settlement of foundations	~				None observed during visual inspection. Level survey may be required to confirm.
tilt of building	1				No visual observation noted during visual inspection. Verticality survey may be required to confirm.
liquefaction		•			None observed during visual inspection. Contacts on site stated it had occurred in areas throughout the site. The aerial reconnaissance on 24 Feb 2011 indicates the extent was minor.
settlement of external ground					None observed during visual inspection.
lateral spread / ground cracks					None observed during visual inspection.
frame			•		Damage to a columns concrete encasement in the Sign Shop, possibly indicating pull-out of the panel connection, was observed. This was temporarily repaired prior to our visual inspections. Various other column concrete encasements
					had minor cracking and some spalling at the top of the encasement at the portal knee was observed.

#### Table 6.1: Damage Summary



Damage type	Unknown	Minor	Moderate	Major	Comment
concrete walls			*		Cracking and some spalling adjacent to the joints and connections of the precast concrete panels was observed. Minor diagonal cracking to the concrete walls of the second storey office and the Plant Hire area was observed.
cracking to concrete floors	*				None observed during inspection, however some areas could not be viewed due to carpet, heavy machinery and equipment etc.
bracing					No damage was observed during our visual inspection.
precast flooring seating					No damage was observed during our visual inspection.
stairs					No damage was observed during our visual inspection.
cladding /envelope		✓			Cracking to precast concrete wall panels observed as described above
internal fit out		✓			Minor plasterboard cracking observed.
building services	✓				No inspections of services were carried out.
adjacent building					No adjacent buildings are close enough to affect this building in an earthquake.
other					

## 6.2 Surrounding Buildings

There are no adjacent structures that are close enough that they may affect the Tradesmens Workshop during an earthquake.

The steel frame silo support adjacent to the Building Services Workshop has not been considered part of the building for the assessment. It is not attached to the Trademsens Workshop structure and a separate assessment may be required. No damage was observed to this during the visual inspection.

## 6.3 Residual Displacements and General Observations

No evidence of permanent settlement or displacements was observed during our visual inspection, however a global settlement survey may reveal movement that could be described as damage under insurance entitlement.

## 6.4 Implication of Damage

The structural damage observed to the precast concrete panels is moderate and the seismic capacity of the precast concrete panels is considered to have reduced due to the damage from 100%NBS to 67%NBS. This reduction does not affect the overall seismic capacity of the building



which is governed by the assessed capacity of the portal frame support beam, above the Sign Shop.

Where temporary works have been installed a full 'as new' repair, including strengthening as required, will need to be designed and constructed. A Building Consent will be required for any structural repair or strengthening. Fire and Access reports will also be required as part of the Building Consent process and a geotechnical report may also be required.

## 7 Generic Issues

The following generic issues referred to in Appendix A of the EAG guideline document have been identified as applicable to the Tradesmens Workshop building:

#### Single Level Tilt Panel

- Brittle panel connections and/or cracked panels at the connections.
- Panel span/thickness ratio too high, leading to panel buckling concerns.
- Steel bracing in adequate.

#### Welded and Bolted Steel Moment Frames

Inadequate stiffness as a whole meaning the building exceeds drift limits.

## 8 Geotechnical Consideration

No geotechnical information was available for this site. During the inspection, no damage to the surrounding pavement was noted and no effect to the structure was considered.

## 9 Survey

No level or verticality surveys were carried out as there was no visible evidence of settlement or displacement observed during the inspection. CCC may wish to undertake a level survey as part of insurance entitlement considerations.

A spirit level 'plumb' check should be done as a minimum as part of the full damage inspections.

## **10 Detailed Seismic Capacity Assessment**

#### 10.1 Assessment Methodology

The building has had its seismic capacity assessed using the Forced-based Detailed Assessment Procedures in the NZSEE 2006 AISPBE guidelines, based on the drawings and visual inspections.

The structure has suffered moderate damage to the precast concrete panels. The post-damage capacity of the panels is considered to be less than the original capacity, however this does not affect the overall seismic capacity of the building.

#### 10.2 Assumptions

The following assumptions were used in our quantitative assessment:



- Reinforcing steel yield strength f<sub>v</sub> = 275 MPa (as noted on the drawings)
- Concrete compressive strength f<sub>c</sub>' = 25 MPa (as noted on the drawings)
- Structural steel yield strength f<sub>v</sub> = 250 MPa
- Timber diaphragm strength of 5kN/m (as suggested in the NZSEE 2006 AISPBE guidelines)

#### 10.3 Critical Structural Weaknesses

The following Critical Structural Weaknesses have been identified:

- Site characteristics due to liquefaction occurring on the Milton St site
- Difference in stiffness between the western Sign Shop area and the rest of the building.

The site characteristics have been identified as a potential CSW in our earlier Qualitative Report. We note that liquefaction is still considered a potential CSW however has not been considered in this quantitative assessment as we believe it will not have a direct impact on the structure's ability to resist further loads or cause global failure of the structure.

The two areas have similar lateral load resisting systems, orientated in orthogonal directions. This will result in the buildings responding differently in each load direction and may be the cause of the damage to column in the Sign Shop area.

#### **10.4 Seismic Parameters**

The seismic design parameters based on current design requirements from NZS 1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class: D NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- Site hazard factor, Z = 0.3 NZBC, Clause B1 Structure, Amendment 11 effective from 19 May 2011
- Return period factor Ru = 1 NZS 1170.5:2004, Table 3.5, Importance Level 2 structure with a 50 year design life.
- Near fault factor N(T,D) = 1 NZS 1170.5:2004, Clause 3.1.6, Distance more than 20 km from fault line.

## 10.5 Results of Seismic Assessment

The results of our quantitative assessment indicate the building has a seismic capacity in the order of 10%NBS. This is lower than the IEP assessment of 36%NBS in the previous Qualitative Report. Table 10.1 presents the evaluated seismic capacity in terms of %NBS of the individual structural systems and components in each building direction.

ltem	Loading Direction	Ductility, µ	Seismic Performance	Notes
Overall %NBS adopted from DEE	Longitudinal	1.25	10%NBS	Governed by weak axis bending of the Sign Shop portal frame support beam
Portal frames – main area	Transverse	1.25	39%NBS	Eastern portal frame rafters in flexure
Portal frame connections – main area	Transverse	1.25	35%NBS	Knee connection stiffener yield capacity

#### Table 10.1: Summary of Seismic Assessment of Structural Systems



Item	Loading Direction	Ductility, µ	Seismic Performance	Notes
Portal frames – Sign Shop area	Longitudinal	1.25	57%NBS	Excessive deflection of the northern frames
Portal frame connections – Sign Shop area	Longitudinal	1.25	67%NBS	Knee connection stiffener yield capacity
Frames connecting the Sign Shop and main areas	Longitudinal	1.25	10%NBS	Weak axis bending of beam supporting Sign Shop portal frames
Precast panel, in- plane capacity	Longitudinal	1.25	69%NBS	Uplift resistance of foundations
Precast panel connections (damaged)	Longitudinal	1.0	67%NBS	Shear capacity of damaged welded connections under in- plane loading
Precast panel, out- of-plane capacity (damaged)	Both	1.25	100%NBS	Precast panels have been analysed as a part. Damaged connections have lost some resilience, however still achieve 100%NBS
Roof bracing and connections	Longitudinal	1.0	41%NBS	Tension capacity of flat bracing in main area
Two-storey office area walls	Longitudinal	1.25	96%NBS	Uplift resistance of foundations
Two-storey office area connections	Both	1.0	100%NBS	Between precast floor units and precast walls
Steel trussed roof area	Longitudinal	1.25	89%NBS	Minor axis bending of portal frame rafters supporting transverse PC panels
Southern mezzanine	Longitudinal	1.25	77%NBS	Flexural capacity of the columns
Main mezzanine	Longitudinal Transverse	1.25 3.0	100%NBS 100%NBS	Moment resisting steel frames Timber floor diaphragm
Eaves beam	Longitudinal	1.25	66%NBS	Axial compression

Note: Ductility factors are in accordance with values recommended in the NZSEE 2006 AISPBE guidelines.

## 10.6 Discussion of results

The key findings of the assessment are as follows:

- The beam supporting the southern Sign Shop portal frames achieve 10%NBS under longitudinal (out-of-plane) loading.
- The knee connection of the steel portal frames at the eastern end of the building achieve 35%NBS under transverse (in-plane) loading.



 The steel portal frame rafters at the eastern end of the building achieve 39%NBS under transverse (in-plane) loading.

There are a number of other elements in the building which have assessed seismic capacities greater than 33%NBS and less than 67%NBS.

Based on the results of our Quantitative Assessment, the Tradesmens Workshop is considered Earthquake Prone, as the seismic capacity was assessed to be less than 33%NBS, and is classified as Seismic Grade E.

## **11 Recommendations**

#### 11.1 Occupancy

In order that the owner can make an informed decision about the on-going use and occupancy of their building the following information is presented in line with the Department of Building and Housing document 'Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch', June 2012.

The building is considered to be earthquake prone, having an assessed capacity less than 33%NBS, and is classified as Seismic Grade E. The risk of collapse of an earthquake prone building of this grade is considered to be more than 25 times greater than that of an equivalent new building.

For greater Christchurch the definition of a "dangerous" building in the Building Act has been extended (by the Canterbury Earthquake (Building Act) Order 2011) to include buildings at risk of collapsing in a moderate earthquake, that is earthquake prone buildings with a capacity at or below 33%NBS. Where council requires a dangerous building or an earthquake prone building to be upgraded, it may prohibit the use of the building until the works are carried out.

The structural damage observed to the precast concrete panels is moderate and the seismic capacity of the precast concrete panels is considered to have reduced due to the damage. This reduction does not affect the overall seismic capacity of the building. No significant damage was noted to the structural element that is the limiting capacity of the building. Vacate the immediate area under the southern Sign Shop portals until the support beam is strengthened.

## 11.2 Further Investigations, Survey or Geotechnical Work

It is recommended that:

- The immediate area under the southern Sign Shop portals is vacated or restricted use until local strengthening of the support beam is completed.
- The roof bracing in the trussed roof area should be installed as shown on the drawings.
- A full damage assessment is carried out for insurance purposes.
- A verticality survey could be carried out to determine the extent of movement of the building for insurance purposes. A spirit level 'plumb' check should be done as a minimum as part of the full damage inspections.

#### 11.3 Damage Reinstatement

According to the recent CCC Instructions to Engineers document (16 October 2012), Council's insurance provides for repairing damaged elements to a condition substantially as new. We suggest you consult further with your insurance advisor.



## **12 Design Features Report**

Repairs will be required to reinstate the existing structural system. A repair methodology has not been prepared at this stage. No new load paths are expected as a result of the repairs required.

## **13** Limitations

The following limitations apply to this engagement:

- Beca and its employees and agents are not able to give any warranty or guarantee that all defects, damage, conditions or qualities have been identified.
- Inspections are primarily limited to visible structural components. Appropriate locations for invasive inspection, if required, will be based on damage patterns observed in visible elements, and review of the construction drawings and structural system. As such, there will be concealed structural elements that will not be directly inspected.
- The inspections are limited to building structural components only.
- Inspection of building services, pipework, pavement, and fire safety systems is excluded from the scope of this report.
- Inspection of the glazing system, linings, carpets, claddings, finishes, suspended ceilings, partitions, tenant fit-out, or the general water tightness envelope is excluded from the scope of this report.
- The assessment of the lateral load capacity of the building is limited by the completeness and accuracy of the drawings provided. Assumptions have been made in respect of the geotechnical conditions at the site and any aspects or material properties not clear on the drawings. Where these assumptions are considered material to the outcome further investigations may be recommended. It is noted the assessment has not been exhaustive, our analysis and calculations have focused on representative areas only to determine the level of provision made. At this stage we have not undertaken any checks of the gravity system, wind load capacity, or foundations.
- The information in this report provides a snapshot of building damage at the time the detailed inspection was carried out. Additional inspections required as a result of significant aftershocks are outside the scope of this work.

This report is of defined scope and is for reliance by CCC only, and only for this commission. Beca should be consulted where any question regarding the interpretation or completeness of our inspection or reporting arises.



Appendix A

Photographs



Figure 1A: Site Layout (North is to left of page)



Photo 1: Exterior view of Sign Shop and Building Services Workshop (North-west elevation)



Photo 2: Exterior view of Facilities Management (North elevation)



Photo 3: Exterior view of Hire Pool / Storage / Weed Spraying areas (North-east elevation)



Photo 4: Interior view of Sign Shop



Photo 5: Interior view of Building Services Workshop



Photo 6: Interior view of Hire Pool / Storage / Weed Spraying areas



Photo 7: Damage to column encasement


**Damage Description:** Possible pull out of connection causing damage to column encasement, with temporary repair bracket



Photo 8: Damage to wall on other side of Photo 7.

**Damage Description:** Possible pull out of connection causing damage to column encasement, with temporary repair bracket





Damage Description: Cracking to concrete wall panel adjacent to movement joint



Photo 10: Typical cracking to concrete wall panel

**Damage Description:** Cracking to concrete wall panel at bottom corner adjacent to movement joint



Photo 11: Typical cracking to concrete wall panel

Damage Description: Cracking to concrete wall panel protruding from weld plate at portal knee



Photo 12: Cracking to concrete wall

Damage Description: Diagonal crack to concrete wall in stairwell




Photo 13: Cracking to concrete wall

Damage Description: Cracking to concrete panels in Plant Hire area protruding from doorway





Damage Description: Cracking to concrete panels in Plant Hire area by doorway





Damage Description: Cracking to concrete panels in Plant Hire area

Appendix B

**Existing Drawings** 

# STAGE CENTRAL DEPOT JOHNSON ST. SYDENHAM NEW CHRISTCHURCH CITY COUNCIL FOR THE


architects LUCKING & VIAL CHRISTCHURCH


structural & electrical engineer CHRISTCHURCH CITY COUNCIL CITY ENGINEERS DEPARTMENT quantity surveyor


CHRISTCHURCH CITY COUNCIL CITY ENGINEERS DEPARTMENT


80 Crc 387 C C17 Jourson ST CINTRAL DEPOT amendment roted Call samitary Plenting or change & couply with regulation of C. D.B. By Cars. CHRISTCHURCH LAN No. ETTER REF. LH.S. ... INSP. DATE DRAINAGE BOARD































































.







															· · · · ·								
Sarkers	mar ST Scener	Par	1.8	An Levimont,	cas to 0	•	6	P	e lectude Da	e .		0.0	Approved				CHRISTC	HURCH	CITY COL	UNCIL	CITY EN	GINEER'S D	EPARTMENT
n P. Webs	LOUIS &	Sarvey				Ŀ	Surger and			Designed	D.J. Bates	10/74											
Broat .	i Elementer						revelies.			Oracan	A.E. Bainbrid	ga 12/74		. v	MAIN	STORE	-NF	WC	FNTRA		FPOT	-JOH	NSON
SSY Denotes							1999 - C. 1999 -			Traced	A.E. Bainbria	ga 12/74	Design Engineer	Date		JIOKL						•••	
C. 15										Dwg Chi	D.J. Batas	1/75			DI ANI OF	COUNDA	TION	CUO	MILAIC	1000	TIAN	AC WELD	DIATEC
Class (Bride)	5	-					contrasti p			Des Chk					PLAN UP	FOUNDA	ITUN .	SHU	<i>VV    </i> V Ca	LUCA	TION	JF WELD	PLAIES
0.01										Indexed	LB	9/4/75	·										









Use in Bays 2-3, 7-8 south side 2-only





C - D 5-6 10 -11 1-A















Use in Bay 13-14

















Use in Bays 5-6 7-8




				032 11	Day		14									
itials	Service	Dritial	ls	Amendments	Initial	s Date		Book P	Page Initia	ls Date			Date	Approved	CHRISTCHURCH CITY COUNCIL — CITY ENGINEER'S DEPART	MENT
	Lands & Surve	ev -					Surveyed				Designed	D.J. Batas	1/75			×
	Planning						Levelled				Drawn	A.E. Bainbridg	1/75	· · · · · · · · · · · · · · · · · · ·	MAIN STORE - NEW CENTRAL DEPOT - JOHN	SOI
	· · ·		٦.	•			B.M				Traced	A.E. Bainbridg	1/75	Dasign Enginaar Date	MAIN STORE NEW CENTRAL DETOT	501
						-	]				Dwg. Chk.				ATOMATINGAL ATECHNICON METAL DOOF (	2110
	-						Compiled	from			Des. Chk.				STRUCTURAL STEELWORK - METAL ROOF P	UK
											Indexed	L <sup>B</sup>	9/4/75	City Engineer	1	
															nice distance in the second	













Service	Initials	Service	Initia	ls	Amendments	Initial	s Date		Book	Page In	nitials Date			Date	Approved			CHRISTCHU	JRCH	CITY COUNCIL	L — CITY ENGIN	EER'S DEPARTMENT
H.P. Water		Lands & S	iurvey					Surveyed				Designed	M.J. Stockwell	11/76								
Sewer		Planning						Levelled				Drawn	A.E.Bainbridge	11/76			MAIN STOR	F - NFW	CF	NTPAI	DFPOT -	JOHNSON
S.W. Drainage								вм				Traced			Design Engineer	Date				N / NAC	22707	00////00//
Gas												Dwg. Chk.					DDFCACT	CONCOF	$\tau r$		DANELC	43 - 46 - WE
Cables (M.E.D.	1							Compiled	from .		•••••	Des. Chk					PRECASI	LUNCRE	15	IVALL	PANELS	45 - 40 - WE
(P.O.)												Indexed			City Engined	ar.						

		STCHURCH CITY COUNCL vered Subject to the By-Laws 17/11AY 1977 For City Engineer
	Scales	File No. 80/9/10
STREET <sup>.</sup> – LD PLATES 24–2 <b>6</b>	: 50   : 5	D. 1813





Appendix C

CERA DEE Summary Data

Detailed Engineering Evaluation Summary Data			V1.11
Location			
Building Name	Milton St Depot - Tradesmen Workshop Unit	No: Street CPEng No:	David Whittaker 123089
Building Address		245 Milton Street Company:	Beca
Legal Description	BU 1141-001 EQ2	Company project number: Company phone number:	5323355 03 3663521
000	Degrees	Min Sec	
GPS south GPS east		Date of submission: Inspection Date:	<u>22/07/2013</u> 9/10/2012
Puilding Unious Identifies (CCC)		Revision:	A
Building Unique Identifier (CCC)		Is there a full report with this summary?	yes
Site			
Site slope		Max retaining height (m):	0
Soil type Site Class (to NZS1170.5)		Soil Profile (if available):	
Proximity to waterway (m, if <100m) Proximity to clifftop (m, if < 100m)		If Ground improvement on site, describe:	
Proximity to cliff base (m, if < 100m) Proximity to cliff base (m, if <100m)		Approx site elevation (m):	
Building			
No. of storeys above ground Ground floor split?	1	single storey = 1 Ground floor elevation (Absolute) (m): Ground floor elevation above ground (m):	0.00
Storeys below ground		Ground floor elevation above ground (m):	0.00
Foundation type Building height (m)	pads with tie beams 6.75	if Foundation type is other, describe: height from ground to level of uppermost seismic mass (for IEP only) (m):	4.7
Floor footprint area (approx)			
Age of Building (years)	25	Date of design:	1976-1992
Strengthening present?	no	If so, when (year)? And what load level (%g)?	
Use (ground floor)	other (specify)	And what load level (%g)? Brief strengthening description:	N/A
Use (upper floors)			
Use notes (if required) Importance level (to NZS1170.5)	workshops, storage, office		
Gravity Structure Gravity System:	frame system		
			steel rafters and purlins and profiled
Roof	steel framed precast concrete with topping		90mm Unispan with 70mm topping
Beams	steel non-composite	beam and connector type	portal frames
Columns. Walls:	structural steel non-load bearing	typical dimensions (mm x mm) 0	
Lateral load resisting structure Lateral system along	single level tilt panel	Note: Define along and across note total length of wall at ground (m):	115
Ductility assumed, µ	1.25	in detailed report! wall thickness (m):	0.13
Period along Total deflection (ULS) (mm)	0.40	0.00 estimate or calculation? estimate or calculation?	estimated
maximum interstorey deflection (ULS) (mm)		estimate or calculation?	
Lateral system across	welded and bolted steel moment frame	note typical bay length (m)	6
Ductility assumed, µ	1.25		
Period across Total deflection (ULS) (mm)		0.00 estimate or calculation? estimate or calculation?	calculated
maximum interstorey deflection (ULS) (mm)		estimate or calculation?	
Separations:			
north (mm):		leave blank if not relevant	
east (mm): south (mm):			
south (mm) west (mm) Non-structural elements			
south (mm) west (mm) Non-structural elements Stairs	timber	describe supports	concrete walls and clazing
south (mm) west (mm) Non-structural elements Stairs Wall cladding Roof Cladding	limber exposed structure Metal		
south (mm) west (mm) Non-structural elements Val cladding Roof Cladding Glazing Glazing	timber exposed structure Metal timber frames	describe supports describe	concrete walls and glazing corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Stairs Wall cladding Roof Cladding	timber exposed structure Metal timber frames Light tiles	describe supports describe	concrete walls and glazing corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Wall cladding Roof Cladding Glazing Clading Clading	timber exposed structure Metal timber frames Light tiles	describe supports describe	concrete walls and glazing corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Wall cladding Roof Cladding Claizing Ceilings Services(list) Available documentation	timber exposed structure Metal timber frames Light tiles electrical	describe supports describe describe	corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Wall cladding Roof Cladding Glazing Clading Clading	timber exposed structure Metal timber frames Light tiles electrical	describe supports describe	corrugated metal roof sheeting
south (rm) west (rm) Non-structural elements Val cladding Roof Cladding Glazing Services(ist) Available documentation Architectura Structura	limber exposed structure Metal Umber frames light tiles electrical partial full	describe supports describe describe describe original designer name/date original designer name/date	Corrugated metal roof sheeting
south (rmm) west (rmm) Non-structural elements Wal cladding Roof Cladding Ceilings Services(itst) Available documentation Architectura Electrica Electrica	limber exposed structure Metal birber frames light tiles electrical partial full fone none	describe suports describe describe describe original designer name/date original designer name/date original designer name/date original designer name/date	Corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Wall cladding Roof Cladding Glazing Services(itst) Available documentation Architectura Structura	limber exposed structure Metal birber frames light tiles electrical partial full fone none	describe supports describe describe original designer name/date original designer name/date original designer name/date	Corrugated metal roof sheeting
south (mm) west (mm) Non-structural elements Wall cladding Roof Cladding Ceilings Services(itst) Available documentation Architectura Electrica	limber exposed structure Metal birber frames light tiles electrical partial full fone none	describe suports describe describe describe original designer name/date original designer name/date original designer name/date original designer name/date	Corrugated metal roof sheeting
south (rmm) west (rmm) Non-structural elements Wall cladding Collaring Services(list) Available documentation Architectura Electrica Geotech repor	Imber exposed structure Metal Imber frames electrical partial full none none none	describe supports describe describe describe original designer name/date original designer name/date original designer name/date original designer name/date	Corrugated metal roof sheeting
south (rmm) west (rmm) Non-structural elements Wall cladding Collaring Services(list) Available documentation Architectura Electrica Geotech repor Damage Site: Table 4-2) Site performance	Imber exposed structure Metal Imber frames electrical partial full none none none	describe supports describe describe describe original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date	Corrugated metal roof sheeting
South (imm) west (imm) Non-structural elements Wal cladding Roof Cladding Calings Services(list) Available documentation Architectura Mechanica Geotech repor Stre: Stre: Ster Site performance (refer DEE Table 4-2) Settiernent	Limber exposed structure Metal timber frames electrical partial full none none none slight fill none observed	describe supports describe describe describe original designer name/date original designer name/date	Corrugated metal roof sheeting
South (imm) west (imm) Non-structural elements Wal cladding Roof Cladding Calings Services(list) Available documentation Architectura Mechanica Electrica Geotech repor Damage Site: (refer DEE Table 4-2) Settiement Differential settiement Liquefaction	Limber exposed structure Metal timber franes electrical partial full none none none cone slightt slightt fore coserved none coserved fore coserved none coserved fore coserved for coserved	describe supports describe describe describe describe original designer name/date original designer name/date orig	Corrugated metal roof sheeting
South (rmm) west (rmm) Non-structural elements Wall cladding Roof Cladding Ceilings Services(itst) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread	Imber exposed structure Metal Imber frames electrical partial full none none none slight slight none observed none observed none observed none observed none apparent	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
South (imm) west (imm) Non-structural elements Wal cladding Collaring Services(list) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential stetlement Liquefaction Lateral Spread Differential stetlement	timber exposed structure Metal timber frames electrical partial full none none stight stight stight stight full none coserved 0-2 mr/100m cone supparent none supparent none supparent cone supparent cone supparent cose supparent coserved 0-2 mr/20m	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
south (imm) west (imm) Non-structural elements Wal cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Mechanica Electrica Geotech repor Site: Site performance (refer DEE Table 4-2) Settiernent Differential settiernent Liquefaction Lateral Spread Differential areal apread	timber exposed structure Metal timber frames electrical partial full none none stight stight stight stight full none coserved 0-2 mr/100m cone supparent none supparent none supparent cone supparent cone supparent cose supparent coserved 0-2 mr/20m	describe supports describe describe describe describe original designer name/date original designer name/date orig	Corrugated metal roof sheeting
south (rmm) west (rmm) Non-structural elements Wal icladding Ceilings Services(its) Available documentation Available documentation Available documentation Architectura Electrica Geotech repor Damage Site: (refer DEE Table 4-2) Site performance (refer DEE Table 4-2) Site performance Differential is settlement Differential settlement Lateral Spread Differential alexal Differential alexal Damage to area Building:	Limber exposed structure Metal timber franes electrical partial full cone none none cone cone cone cone cone	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
South (rmm) west (rmm) Non-structural elements Wall cladding Collaring Services(list) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance (refer DEE Table 4-2) Sterier I DE Table 4-2) Sterier alstream Differential settement Liquefaction Dataral Spread Differential settement Liquefaction Lateral Spread Differential settement Liquefaction Lateral Spread Differential settement Liquefaction Lateral Spread Differential settement Liquefaction Lateral Spread	Limber exposed structure Metal timber franes electrical partial full cone none none cone cone cone cone cone	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
South (rmm) Non-structural elements Wal cladding Roof Cladding Ceilings Services(ist) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance (refer DEE Table 4-2) Settement Liquefaction Lateral Spread Differential stetiment Liquefaction Lateral Spread Differential stetiment Electrical Status Building: Current Placard Status Along Damage ratio	timber exposed structure Metal timber frames electrical partial full none none slight	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     Estimated from 24th Feb aerial photo     units of the serial photo     units of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series     units of the series
South (mm) Non-structural elements Vali cladding Colligion Cellings Services(list) Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Architectura Bite: Comparison Damage Site: Site performance Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential alexal Differential alexal Differen	timber exposed structure Metal timber frames electrical partial full none none slight	describe supports describe describe original designer name/date original designer name	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     Estimated from 24th Feb aerial photo     units of the serial photo     units of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series     units of the series
South (rmm) Non-structural elements Non-structural elements Wal icladding Celings Services(its) Available documentation Architectura Electrica Geotech repor Damage Site: For DEE Table 4-2) Site performance Celence Electrica Geotech repor Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Differential settlement Damage to area Building: Current Placard Status Along Describe (surmary) Across Damage ratio	Limber       exposed structure       Metal       timber frances       Light tiles       electrical       partial       full       none       none       none       silaht       silaht       silaht       none apparent       none apparent       ono apparent       0-2 m/100m <sup>3</sup> green       0%	describe supports describe original designer name/date origin	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     Estimated from 24th Feb aerial photo     units of the serial photo     units of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series     units of the series
South (rmm) Non-structural elements Non-structural elements Wal cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance Inferential stellement Liquefaction Lateral Spread Differential stellement Liquefaction Lateral Spread Differential stellement Differential stellement Liquefaction Lateral Spread Differential stellement Sternal Spread Differential stellement Liquefaction Lateral Spread Ground cracks Damage to area Building: Along Describe (summary)	Limber       exposed structure       Metal       timber frances       Light tiles       electrical       partial       full       none       none       none       silaht       silaht       silaht       none apparent       none apparent       ono apparent       0-2 m/100m <sup>3</sup> green       0%	describe supports describe describe original designer name/date original designer name	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     Estimated from 24th Feb aerial photo     units of the serial photo     units of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series of the series of the series     units of the series of the series of the series     units of the series of the series     units of the series     units of the series
South (rmm) Non-structural elements Non-structural elements Vali cladding Celings Services(itst) Available documentation Architectura Structura Mechanica Electrica Geotech repor Damage Site: Site performance Lateral Spread Differential astitiment Differential astitiment Lateral Spread Differential astitiment Lateral Spread Differential astitiment Lateral Spread Differential activitient Lateral Spread Differential activitient Lateral Spread Damage to area Building: Current Placard Status Along Describe (summary) Across Damage ratio	Limber exposed structure Metal timber franes electrical partial full cone none none none cone cone cone cone	describe supports describe original designer name/date origin	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     Estimated from 24th Feb aerial photo     damage not to governing elements
Non-structural elements Statis Wal icadding Roof Cladding Celings Services(ist) Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Structura Belicetrica Geotech repor Damage Site: Site performance Electrica Geotech repor Differential settlement Liquefaction Damage Structural Status Damage to area Differential aterial spread Offerential aterial spread Damage to area Buildina: Current Placard Status Along Damage ratio Describe (summary) Across Damage ratio Describe (summary) Diaphragms Damage?	Limber exposed structure Metal timber franes electrical partial full cone cone cone cone cone cone cone cone	describe supports describe describe describe describe original designer name/date original designer name/date orig	Corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     Cracking to precast concrete panels     estimated from 24th Feb aerial photo     damage not to governing elements
Non-structural elements Non-structural elements Non-structural elements Nation Non-structural elements Nation Nati	imber exposed structure Metal timber franes electrical partial full cone cone cone cone cone cone cone cone	describe supports describe describe describe original designer name/date original desi	corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     cracking to precast concrete panels     damage not to governing elements
Non-structural elements Non-structural elements Non-structural elements National Calading Celings Services(itst) Available documentation Architectura Electrica Electr	imber exposed structure Metal timber franes electrical partial full cone cone cone cone cone cone cone cone	describe supports describe describe describe describe original designer name/date original designer name/date orig	corrugated metal roof sheeting     Lucking and Vial / 1977 approved     City Engineers Department / 1977     approved     not available     not available     not available     cracking to precast concrete panels     damage not to governing elements
Non-structural elements Statis Wal icadding Collision (Wal icadding Collision Collision Collision Cellings Services(list) Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Cellings Stervices(list) Cellings Stervices(list) Cellings Structura Mechanica Electrica Geotech report Damage Site: Site performance Electrica Geotech report Differential settlement Liquefaction Differential settlement Liquefaction Contracts Damage to area Damage to area Damage ratio Describe (summary) Across Damage 7 CSWs: Damage 7	Limber exposed structure Metal timber franes electrical partial full cone cone cone cone cone cone cone cone	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
Non-structural elements Statis Wall cladding Roof Cladding Cellings Services(itst) Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Structura Belectrica Geotech repor Damage Site: (refer DEE Table 4-2) Site: Site performance Differential stellement Liquefaction Lateral Spread Differential stellement Liquefaction Lateral Spread Differential stellement Liquefaction Lateral Spread Differential stellement Liquefaction Lateral Spread Differential stellement Liquefaction Lateral Spread Damage to area Buildina: Current Placard Status Along Damage ratio Describe (summary) Diaphragms Damage? Pounding: Damage?	Limber exposed structure Metal timber franes electrical partial full cone cone cone cone cone cone cone cone	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
Non-structural elements Non-structural elements Non-structural elements Nation Non-structural elements Nation Non-structural elements Nation Non-structural elements Nation Natio	Limber         exposed structure         Metal         timber frames         Light tiles         electrical         partial         full         none         none         none         coore         coore         coore         coore         coore         coore         coore         coore observed         coore apparent         none apparent         coore apparent         coore         0%         10%         10%         100	describe supports describe describe describe original designer name/date original desi	Corrugated metal roof sheeting
South (rmm) Non-structural elements Wal cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Electrica Geotech repor Damage Site: Site performance (refer DEE Table 4-2) Setter Table 4-2) Setter Site performance Current Placard Status Along Damage to area Building: Current Placard Status Damage ratio Describe (summary) Diaphragms Damage? Non-structural: Damage? Recommendations	Imber         sposed structure         Metal         timber frames         light tiles         electrical         partial         full         none         none         none         none observed         core abserved         core abserv	describe supports describe describe describe original designer name/date original designer name/date notes (if applicable): notes (if a	Corrugated metal roof sheeting
South (rmm) west (rma) Non-structural elements Val cladding Collings Services(itst) Available documentation Available documentation Available documentation Available documentation Available documentation Available documentation Celings Stervices(itst) Available documentation Available documentation Biter (refer DEE Table 4-2) Differential settlement Liquefaction Liquefaction Differential settlement Liquefaction Differential settlement Liquefaction Differential settlement Liquefaction Current Placard Status Damage ratio Describe (summary) Diaphraams Damage? Non-structurat: Damage? Recommendations	Limber exposed structure Metal timber frances light tiles electrical partial full none none none none silaht fone observed fone observed fone observed 0.2 m?100m? Tone apparent fone apparent fone apparent fone 0.2 m?20m silaht fore fone fone fone fone fone fone fone fon	describe supports describe describe describe describe describe describe describe describe describe original designer name/date notes (f applicable): notes (f applicab	Corrugated metal roof sheeting
South (rmm) west (rma) Non-structural elements Wal cladding Roof Cladding Celings Services(itst) Available documentation Available documentation Available documentation Available documentation Available documentation Celings Stervices(itst) Damage Electrica Geotech repor Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Offerential settlement Liquefaction Lateral Spread Offerential settlement Liquefaction Lateral Spread Offerential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Offerential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Describe (summary) Disptragers Damage 7 Disptragers Damage? Non-structural: Damage? Recommendations	Limber exposed structure Metal timber franes light tils electrical partial full none none none silaht fore observed fore observed cosestructural none observed 0.2 m?100m? tone apparent none apparent none apparent fore observed 0.2 m?100m? tone apparent fore observed 0.2 m?100m? fore apparent fore observed 0.2 m?100m? fore apparent fore observed 0.2 m?100m? fore apparent fore observed 0.2 m?100m? fore apparent fore observed fore observed for observed for observed fore observed for observed f	describe supports describe describe describe describe describe describe describe describe describe original designer name/date notes (f applicable): notes (f applicab	corrugated metal roof sheeting  Lucking and Vial / 1977 approved City Engineers Department / 1977 approved not available not available Cracking to precast concrete panels  Cracking to precast concrete panels  damage not to governing elements  damage not to governing elements  Concrete crack repair Cordon off under beam until strengthened
South (rmm) west (rma) Non-structural elements Val icading Roof Clading Celings Services(itst) Available documentation Available documentation Available documentation Available documentation Available documentation Celings Stervices(itst) Damage Stervices(itst) Damage Stervices(itst) Damage Stervices(itst) Damage Stervices(itst) Differential settlement Liquefaction Liquefaction Differential settlement Liquefaction Differential settlement Liquefaction Damage ratio Describe (summary) Across Damage ratio Describe (summary) Diaphraams Damage? Non-structural: Damage? Recommendations Liquefor (spair/strengthening required Building: Case (spair) Case (sp	Limber exposed structure Metal timber frances light tiles electrical partial full none none none none silaht fone observed fone observed fone observed 0.2 m?100m? Tone apparent fone apparent fone apparent fone 0.2 m?20m silaht freen 0% from 0%	describe supports describe describe describe describe describe describe describe describe describe original designer name/date notes (f applicable): notes (f applicab	corrugated metal roof sheeting  Lucking and Vial / 1977 approved  City Engineers Department / 1977 approved  not available not available  Cracking to precast concrete panels  Estimated from 24th Feb aerial photo  damage not to governing elements  Ana  Concrete crack repair Cordon off under beam until strengthened  Forced-based Quantitative Assessment
south (rm) Non-structural elements Stars Wal cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Structura Structura Mechanica Electrica Geotech repor Damage Site: Site: Site performance Licetrica Geotech repor Differential settlement Liquefaction Lateral Spread Differential settlement Differential settlement Describe (summary) Diaphragms Damage? Non-structural: Damage? Recommendations Level of repair/strengthening required Building Consent required: Building Assessed %NBS before:	Umber       timber       exposed structure       Metal       timber frames       light tiles       electrical       partial       full       none       none       none       none       2000       slight       fone observed       02-mm/100m       slight       green       0%       100	describe supports describe describe describe describe describe describe original designer name/date notes (if applicable):     notes (if appl	corrugated metal roof sheeting  Lucking and Vial / 1977 approved  City Engineers Department / 1977 approved  not available not available  Cracking to precast concrete panels  Estimated from 24th Feb aerial photo  damage not to governing elements  Ana  Concrete crack repair Cordon off under beam until strengthened  Forced-based Quantitative Assessment
South (rmm) Non-structural elements Wal cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech repor Damage Site: Site: Site performance (refer DEE Table 4-2) Settierment Differential stetlement Liquefaction Lateral Spread Differential settement Liquefaction Lateral Spread Differential settement Differential settement Liquefaction Lateral Spread Differential settement Differential settement Liquefaction Lateral Spread Ground cracks Damage ratio Describe (summary) Across Damage? Non-structural: Damage? Recommendations Level of repair/strengthening required Building Consent required: Non-structural: Along Assessed %NBS before: Assessed %NBS	Umber       timber       exposed structure       Metal       timber frames       light tiles       electrical       partial       full       none       none       none       none       2000       slight       fone observed       02-mm/100m       slight       green       0%       100	describe supports describe describe describe describe describe describe describe original designer name/date notes (if applicable):     notes	corrugated metal roof sheeting  Lucking and Vial / 1977 approved  City Engineers Department / 1977 approved  not available not available  Cracking to precast concrete panels  Estimated from 24th Feb aerial photo  damage not to governing elements  Ana  Concrete crack repair Cordon off under beam until strengthened  Forced-based Quantitative Assessment

	Period of design of building (from above):	1976-1992				he from at	ove: 4.7m	
Seis	smic Zone, if designed between 1965 and 1992:					d for this age of build for this age of build		
						along		across
			Period (fro (%NBS)nom fro			0.4		0.8
	Note:1 for specifically desi	ign public buildings, to the code of the day: p	re-1965 = 1.25; 1965-1976, Z Note 2: for F Note 3: for buildnas design	C buildings de	esigned betwe	een 1976-1984, use	9 1.2	
						along		across
			Final (%	NBS)nom:		0%		0%
	2.2 Near Fault Scaling Factor			Near Fault sca	aling factor, fr	om NZS1170.5, cl 3	3.1.6:	
		Near F	ault scaling factor (1/N(T,D),	Factor A:		along #DIV/0!		across #DIV/0!
	2.3 Hazard Scaling Factor	- Hour				om AS1170.5, Table	33	
	Lis rideard coarrig ractor				Zı	992, from NZS4203:	1992	11DB //01
					Hazard s	scaling factor, Factor	brв:	#DIV/0!
	2.4 Return Period Scaling Factor		Re	Bu turn Period Sca	uilding Import aling factor fr	ance level (from ab om Table 3.1, <b>Fact</b>	ove):	
						along		across
	2.5 Ductility Scaling Factor	Assess Ductility scaling factor: =1 from 1976 onwa	ed ductility (less than max in ards; or =kµ, if pre-1976, from	Table 3.2) Table 3.3:				
			Ductiity Scaling Factor,			1.00		1.00
	2.6 Structural Performance Scaling	g Factor:		Sp:				
		Structura	I Performance Scaling Factor	Factor E:		#DIV/0!		#DIV/0!
	2.7 Baseline %NBS, (NBS%)ь = (%N	NBS)nom x A x B x C x D x E		%NBS6:		#DIV/0!		#DIV/0!
	Global Critical Structural Weaknesses:							
	3.1. Plan Irregularity, factor A:		1					
	3.2. Vertical irregularity, Factor B:		1					
	3.3. Short columns, Factor C:		Table for selecti	on of D1		Severe	Significant	Insignificant/none
			<u> </u>	Se	eparation	0 <sep<.005h< td=""><td>.005<sep<.01h< td=""><td>Sep&gt;.01H</td></sep<.01h<></td></sep<.005h<>	.005 <sep<.01h< td=""><td>Sep&gt;.01H</td></sep<.01h<>	Sep>.01H
	3.4. Pounding potential Height	Pounding effect D1, from Table to right t Difference effect D2, from Table to right	Alignment of Alignment of floo	floors within 2 rs not within 2		0.7 0.4	0.8 0.7	1 0.8
		Therefore, Factor D:			2070 OF TT			
		·			eparation	Severe 0 <sep<.005h< td=""><td>Significant .005<sep<.01h< td=""><td>Insignificant/none Sep&gt;.01H</td></sep<.01h<></td></sep<.005h<>	Significant .005 <sep<.01h< td=""><td>Insignificant/none Sep&gt;.01H</td></sep<.01h<>	Insignificant/none Sep>.01H
	3.5. Site Characteristics			difference > 4	4 storeys	0.4	0.7	1
				ference 2 to 4 difference < 2		0.7 1	0.9	1
			Teight		1.0.090	Along		Across
	3.6. Other factors, Factor F	For $\leq$ 3 storeys, max value =2.5,						
			Rationale for choice of F fac					
	Detail Critical Structural Weaknesses: List any:		efer also section 6.3.1 of DEE	for discussion	of F factor m	odification for other	critical structural wea	aknesses
	3.7. Overall Performance Achieven					0.00		0.00
	4.3 PAR x (%NBS)b:		PAR x Baselli	ne %NBS:		#DIV/0!		#DIV/0!
	4.4 Percentage New Building Stand							#DIV/0!
		dard (%NBS), (before)						

Appendix D

Previous Reports and Assessments

## city¢care

15mp	Instruction:	-001 (E		ef/ File Note:	Sheet No Variation / Detail:	of
eilig parel Topped aviery. A-	Buil Paint Store	diz Servi	//ish) ies Workshop isq = Im isq = Im isq = Im print room	C.J 2. Sign Shop Nor Kejoom	rycare 10 Log on . Print Office	
1200 × 1200 : HT 14 .5 15 m2 					8 fill firewall git Illing Space ramp office. Upstairs	s cracles.
Approved Distribution:	Client Date Principal:	/ / Contractor:	_	Contractor Date / neer: Sub-	/ Contractor: Job	File:





## Scope of Works & Cost Estimate Form For EQ Damage

Building Name		Milton st Depot-Tradesmen Workshop							
Building BU No.		BU 1141-001 EQC				Date	4/0	5/2	011
U		· · · · · · · · · · · · · · · · · · ·		-	C	CL Fee	16	66	5%
Inspection Team	CCI	Brent williams				Page		1 1	
mspeetion ream		Scott Titheridge	_	Da	*~	Visited			2011
	CL	Scott Hthendge	-					-	
			_	310	ec	Contact	IVIIK	ec	lkey
DAMAGED	1				-	Ph		-	<b>0</b> /
DAMAGED AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)	Unit	Quantity	F	Rate (\$)	Rate Including CCI fee		Cost included CCL Fee
Tradesmen Work Shop									
Female Toilet		Ceiling Cracks - General any substrate - Rake, RTV and touch up.	Lm	2	\$	12.00	\$ 14		\$ 28
Paint Store	А	Re Screw Popped Nails	m2	2	\$	50.00	\$ 58		5 117
	А	Ceilings - Paint - Repaint -2 coats	m2	36	\$	17.00	\$ 20	1	5 714
	в	Wall - Cracks - Plasterboard - Rake & no more gaps	Lm	3	\$	10.00	\$ 12		\$ 35
		Scaffolding mobil	d	5	\$	25.00	\$ 29		5 146
		Stop ceiling	M2	3	\$	15.00		_	
Joinery Wok Room	С	Re Place Damaged Ceiling Tiles	day	3	\$	480.00		-	-
		Lift - Scissor lift 6m	day	3	\$	100.00		_	
		New Replacement Tiles	M2	15	\$	40.00			5 700
		Lift - Scissor lift 6m transport	Bothw ays	1	\$	90.00	\$ 105	;	5 105
	D+E	Repair cracks Concrete floor blow out and Grind andEpoxy	Lm	39	\$	14.00	\$ 16		637
Sign Shop Office	F	Wall - Cracks - Pre cast panels Structurally repaired using Epozy injection	Lm	1	\$	197.98	\$ 231		\$ 231
		Walls - Paint - Repaint	m2	3.7	\$	12.00	\$ 14		5 52
	G	Wall - Cracks - Plasterboard - Rake & Stop	Lm	2	\$	12.00		_	
	-	Walls - Paint - Repaint	m2	9	\$	12.00			
	Н	Wall - Cracks - Plasterboard - Rake & Stop	Lm	4	\$	12.00			5 56
	I	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	3	\$	14.50			5 51
		Ceilings - Paint - Repaint -2 coats	m2	20	\$	17.00	\$ 20	1	\$ 397
Sign Work Room	J	Wall Cracks - General any substrate - Rake, RTV and touch up.	Lm	20	\$	10.00	\$ 12		233
		Walls - Paint - Repaint	m2	2	\$	12.00	\$ 14		5 28
		Scaffolding mobil	Day	2	\$	25.00	\$ 29		58
Print Shop	k	Wall - Cracks - Plasterboard - Rake & Stop	Lm	5	\$	12.00		•,	
		Walls - Paint - Repaint	m2	14	\$	12.00	\$ 14		5 196
Sign Work Shop Floor		Blow out , install 10mm dia PF rod and fill with Seks Grey RTV.	Lm	15	\$	25.00	\$ 29		5 437
Column Sign Work Shop	L	Engineers Inspection, Report and Design Brief (Provisional Sum)	PS	1	\$	1,500.00	\$ 1,750		5 1,750
Temp Office Stair	А	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	6	\$	14.50	\$ 17		5 101
		Ceilings - Paint - Repaint -2 coats	m2	15.5	\$	17.00	\$ 20		5 307
Walls Stairs	В	Wall - Cracks - Plasterboard - Rake & Stop	Lm	8.2	\$	12.00	\$ 14		5 115
		Walls - Paint - Repaint	m2	32	\$	12.00	\$ 14		5 448
Cylinder Cupboard	С	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	3.6	\$	14.50	\$ 17		5 61
		Ceilings - Paint - Repaint -2 coats	m2	1.7	\$	17.00	\$ 20	1	5 34
		Wall - Cracks - Plasterboard - Rake & no more gaps	Lm	2.5	\$	10.00			5 29
	1	Baps Walls - Paint - Repaint	m2	9.2	\$	12.00	\$ 14		5 129
Store Room	D	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	9.2 11	\$ \$	12.00		_	
	1	Ceilings - Paint - Repaint -2 coats	m2	19	\$	17.00		_	

DAMAGED AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)	Unit	Quantity	R	ate (\$)	Rate Including CCL fee		Cost included CCL Fee
		Wall - Cracks - Plasterboard - Rake & Stop	Lm	1.4	\$	12.00	\$ 14		
		Walls - Paint - Repaint	m2	22.5	\$	12.00	\$ 14	- ·	
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38		
Mens Toilet	E	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	10.2	\$	14.50	\$ 17		-
L	-	Ceilings - Paint - Repaint -2 coats	m2	20	\$	17.00	\$ 20	\$	
Ladies Toilet	F	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	3.8	\$	14.50	\$ 17	\$	
Store 0	<u> </u>	Ceilings - Paint - Repaint -2 coats	m2	3 9.6	\$	17.00	\$ 20	- ·	
Store 2	G	Wall - Cracks - Plasterboard - Rake & Stop Walls - Paint - Repaint	Lm m2	9.6 30	\$ \$	12.00 12.00	\$ 14 \$ 14		-
		Labour - Handyman (Incl. Vehicle)	h	2	ې \$	32.90	\$ 14 \$ 38	- ·	
		Ceiling - Cracks - Junctions & Negative Details -	11	2	Ş	52.90	2 20	Ş	
Office	Н	RTV Fill	Lm	10	\$	5.50	\$6	\$	64
		Ceilings - Paint - Repaint -2 coats	m2	2	\$	17.00	\$ 20	\$	40
. <u></u>		Wall - Cracks - Plasterboard - Rake & Stop	Lm	5	\$	12.00	\$ 14	- ·	
		Walls - Paint - Repaint	m2	44	\$	12.00	\$ 14	- ·	
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90	\$ 38	- ·	
. <u></u>		Popped Screws/Nails Walls	Per	12	\$	4.00	\$ 5	· ·	
Roof Space Fire Walls	I	Ceiling - Cracks - Plasterboard - Rake, Stop & Touchup Paint	Lm	30	\$	24.50	\$ 29	\$	
Fire Hose	J	Re Fix Back to wall	Hr	0.5	\$	39.32	\$ 46	\$	23
Tradesmens Store	-	Wall Cracks - General any substrate - Rake, RTV						Ť	
Room	K	and touch up.	Lm	7.8	\$	10.00	\$ 12	\$	91
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$	5 154
		Mobil Scaffold	Day	2	\$	25.00	\$ 29	\$	58
Floor Repair to Floor at door		Grind sand cerment	Lm	2.3	\$	39.00	\$ 45	\$	105
Outside Building	А	Wall Cracks - General any substrate - Rake, RTV and touch up.	Lm	2	\$	10.00	\$ 12	\$	23
	В	Wall - Rake and repoint block walls	m2	1.5	\$	40.00	\$ 47	\$	5 70
		Walls - Paint - Repaint	m2	3	\$	12.00	\$ 14	\$	42
	~	Wall Cracks - General any substrate - Rake, RTV	1	0 F	ć	10.00	ć 13	÷	
1	С	and touch up.	Lm	0.5	\$	10.00	\$ 12	\$	6
	D	Wall - Rake and repoint block walls	m2	1.5	\$	40.00	\$ 47	\$	70
		Walls - Paint - Repaint	m2	1.5	\$	12.00	\$ 14	\$	21
		Walls - Paint - Repaint	m2	3	\$	12.00	\$ 14	\$	42
	E	Window Frame - Paint -Repaint	m2	40	\$	20.50	\$ 24	\$	957
Refer to J Sign Shop	F	Wall - Cracks - Pre cast panels Structurally	Lm	4.3	\$	197.98	\$ 231	\$	993
Kelel to 3 Sigh Shop	1	repaired using Epozy injection	LIII	4.5	<u> </u>	197.98			
		Walls - Paint - Repaint	m2	26.2	\$	12.00	\$ 14	\$	367
1	G	Wall - Cracks - Pre cast panels Structurally	Lm	4.5	\$	197.98	\$ 231	Ś	1,039
	0	repaired using Epozy injection	2111						
		Walls - Paint - Repaint	m2	26.2	\$	12.00	\$ 14	\$	367
1	н	Wall - Cracks - Pre cast panels Structurally	Lm	4.5	\$	197.98	\$ 231	\$	1,039
	••	repaired using Epozy injection						Ľ	
		Walls - Paint - Repaint	m2	26.2	\$	12.00		<u> </u>	
		Mobil Scaffold	Day	5	\$	25.00			
		Prune trees prior to painting	unit	1	\$	300.00	\$ 350	\$	350
Admin Office Tradesmens Building North Wall Entrance	А	Wall - Cracks - Plasterboard - Rake & Stop	Lm	12	\$	12.00	\$ 14	\$	168
		Walls - Paint - Repaint	m2	24	\$	12.00	\$ 14	\$	336
		Popped Screws/Nails Walls	Per	6	\$	4.00	\$5	\$	28
		Door & Frame - Paint - Repaint 2 coats	m2	4.5	\$	24.00	\$ 28	\$	126
South Wall	В	Window Frame - Paint -Repaint	m2	20	\$	20.50	\$ 24	\$	478
West Wall under stair	с	Wall - Cracks - Plasterboard - Rake & Stop	Lm	1.9	\$	12.00	\$ 14	\$	27
		Walls - Paint - Repaint	m2	29	\$	12.00	\$ 14	\$	406
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90		\$	5 77
Internal Office	D	Popped Screws/Nails Walls	Per	1	\$	4.00		\$	5
	1	Walls Interior - paint - <= 300mm	Lm	7	\$	9.00	\$ 10	\$	73
	1	Wall - Cracks - Plasterboard - Rake & Stop	Lm	0.3	\$	12.00		- ·	
				7		12.00			
		Walls - Paint - Repaint	m2	/	\$	12.00			50
Ceiling Tiles	E	Walls - Paint - Repaint Readjust Tiles	m2 hr	1	\$ \$	40.00			
Ceiling Tiles	E			-			\$ 47	\$	47
Ceiling Tiles Hire Pool North Wall Entrance	E G	Readjust Tiles	hr	1	\$	40.00	\$ 47 \$ 233	\$ \$	47 233

DAMAGED AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)	Unit	Quantity	R	ate (\$)	Rate Including CCL fee	Cost included CCL Fee
		Mobil Scaffold	Day	4	\$	25.00	\$ 29	\$ 117
		Walls - Paint - Repaint	m2	85	\$	12.00	\$ 14	\$ 1,190
Floor	1	Floor crack -Concrete-blow out -pf rod-RTV	Lm	11.7	\$	25.00	\$ 29	\$ 341
Store		Wall Cracks - General any substrate - Rake, RTV	Lm	8.1	\$	10.00	\$ 12	\$ 94
50016	2	and touch up.	2111	0.1	Ļ	10.00	γ 12	Ç 74
IT Room	К	Wall - Cracks - Plasterboard - Rake & Stop	Lm	4	\$	12.00	\$ 14	\$ 56
		Walls - Paint - Repaint	m2	27	\$	12.00	\$	\$ 378
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$ 154
	L	Floor crack -Concrete-blow out -pf rod-RTV	Lm	6	\$	25.00	\$ 29	\$ 175
		Carpert-Glued -Lift -Relay	Unit	6	\$	150.00	\$ 175	\$ 1,050
Foyer	М	Floor crack -Concrete-blow out -pf rod-RTV	Lm	2.9	\$	25.00	\$ 29	\$ 85
	N	Wall Cracks - General any substrate - Rake, RTV	Lm	7	\$	10.00	\$ 12	\$ 82
		and touch up.			Ľ			-
Office	0	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	1.2	\$	14.50	\$ 17	\$ 20
		Ceilings - Paint - Repaint -2 coats	m2	8.3	\$	17.00	\$ 20	\$ 165
	Р	Wall - Cracks - Plasterboard - Rake & Stop	Lm	1.4	\$	12.00	\$ 14	\$ 20
		Walls - Paint - Repaint	m2	17	\$	12.00	\$ 14	\$ 238
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$ 154
Toilet	Q	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	4.4	\$	14.50	\$ 17	\$ 74
		Ceilings - Paint - Repaint -2 coats	m2	5.6	\$	17.00	\$ 20	\$ 111
	R	Wall - Cracks - Plasterboard -Rake & RTV	Lm	5.6	\$	11.00	\$ 13	\$ 72
		Wall - Cracks - Plasterboard - Rake & Stop	Lm	8.3	\$	12.00	\$ 14	\$ 116
		Window Frame - Paint -Repaint	m2	22.2	\$	20.50	\$ 24	\$ 531
		Floor crack -Concrete-blow out -pf rod-RTV	Lm	1.8	\$	25.00	\$ 29	\$ 52
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90	\$ 38	\$ 77
		Vinyl-Remove-Relay New	m2	1.7	\$	100.00	\$ 117	\$ 198
Mezzanine	S	Cracks -Top-Columns	Lm	4.8	\$	20.00	\$ 23	\$ 112
Spray Shop	т	Wall Cracks - General any substrate - Rake, RTV	Lm	2	\$	10.00	\$ 12	\$ 23
Spray Shop	'	and touch up.	2111	2		10.00	γ 12	ې <sub>ک</sub> ې
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$ 154
Fammable liquids	U	Wall Cracks - General any substrate - Rake, RTV	Lm	4.2	\$	10.00	\$ 12	\$ 49
store	U	and touch up.	2111	4.2	Ļ	10.00	γ 12	Ç+ Ç
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90	\$ 38	\$ 77
Radioactive store	v	Wall Cracks - General any substrate - Rake, RTV	Lm	4.8	\$	10.00	\$ 12	\$ 56
	·	and touch up.					· ·	-
		Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$ 154
Outside Building B	А	Wall Cracks - General any substrate - Rake, RTV	Lm	7	\$	10.00	\$ 12	\$ 82
	~	and touch up.	2	, 	Ŷ	10.00	Ý 12	Ŷ 02
	в	Wall - Cracks - Pre cast panels Structurally	Lm	1	\$	197.98	\$ 231	\$ 231
	5	repaired using Epozy injection						
	С	Window Frame - Paint -Repaint	m2	3.2	\$	20.50		
		Mobil Scaffold	Day	2	\$	25.00	\$ 29	\$ 58
	D	Wall - Cracks - Pre cast panels Structurally	Lm	1	\$	197.98	\$ 231	\$ 231
	-	repaired using Epozy injection		-	Ŷ	107.000	Ŷ <b>1</b> 01	Ŷ _01
	Е	Wall - Cracks - Pre cast panels Structurally	Lm	1	\$	197.98	\$ 231	\$ 231
		repaired using Epozy injection					· ·	
	F	Tilt Panal Joins Reseal	Lm	4.5	\$	25.00		\$ 131
		Prune trees prior to painting	Unit	1	\$	300.00		
		Mobil Scaffold	Day	2	\$	25.00	\$ 29	\$ 58
Fleet Services Work shop Sheet D. Lube	А	Ceiling - Cracks - Lath & Plaster - Rake & Stop	Lm	0.9	\$	15.50	\$ 18	\$ 16
Store								
		Door & Frame - Paint - Repaint 2 coats	m2	1	\$	24.00	\$ 28	\$ 28
		Mobil Scaffold	Day	2	\$	25.00	\$ 29	\$ 58
Wall East	В	Tilt Panal Joins Reseal	Lm	21.5	\$	25.00	\$ 29	\$ 627
		Labour - Handyman (Incl. Vehicle)	h	8	\$	32.90		\$ 307
Block Wall	с	Wall Cracks - General any substrate - Rake, RTV and touch up.	Lm	3	\$	10.00	\$ 12	\$ 35
Wall West	D	Tilt Panal Joins Reseal	Lm	1.5	\$	25.00	\$ 29	\$ 44
Mezzanine	E	Wall - Cracks - Plasterboard - Rake & Stop	Lm	2	\$	12.00		
THE LLUITINE	-	Walls - Paint - Repaint	m2	4	\$ \$	12.00		
Office	F	Wall - Cracks - Plasterboard - Rake & Stop	Lm	2.4	\$ \$	12.00		-
Unice	<u> </u>	Walls - Paint - Repaint	m2	5	\$ \$	12.00		
Compressor room	G	Tilt Panal Joins Reseal	Lm	5 0.9	ې \$	25.00		\$ 70 \$ 26
			L111	0.5				-
		Walls - Paint - Repaint	m7	5	¢	12 00	\$ 1/	\$ 70
Lube Bay	Н	Walls - Paint - Repaint Tilt Panal Joins Reseal	m2 Lm	5 7	\$ \$	12.00 25.00		

DAMAGED AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)	Unit	Quantity	R	ate (\$)	Rate Including CCL fee	Cost included CCL Fee
Staff Room Café	J	Wall - Cracks - Plasterboard - Rake & Stop	Lm	13.2	\$	12.00	\$ 14	\$ 185
		Walls - Paint - Repaint	m2	66	\$	12.00	\$ 14	\$ 924
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90	\$ 38	\$ 77
Ladies Toilet	k	Wall - Cracks - Plasterboard - Rake & Stop	Lm	1.8	\$	12.00	\$ 14	\$ 25
		Walls - Paint - Repaint	m2	8	\$	12.00	\$ 14	\$ 112
Mens Toilet	L	Wall - Cracks - Plasterboard - Rake & Stop	Lm	2.1	\$	12.00	\$ 14	\$ 29
office	М	Walls - Paint - Repaint Popped Screws/Nails Walls	m2	7 6	\$ \$	12.00 4.00	\$ 14 \$ 5	\$ 98 \$ 28
once	IVI	Ceilings - Paint - Repaint -2 coats	Per m2	25	ې \$	17.00	\$ <u>5</u> \$ 20	\$ <u>28</u> \$ 496
	N	Wall - Cracks - Plasterboard - Rake & Stop	Lm	3	\$	12.00	\$ <u>20</u> \$ 14	\$ 42
		Walls - Paint - Repaint	m2	14.5	\$	12.00	\$ 14	\$ 203
		Labour - Handyman (Incl. Vehicle)	h	2	\$	32.90	\$ 38	\$ 77
Upstairs office stairs	0	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	11.8	\$	14.50	\$ 17	\$ 200
		Ceilings - Paint - Repaint -2 coats	m2	14.5	\$	17.00	\$ 20	\$ 288
		Scaffolding assembled on site with 2 weeks hire.	m2	25	\$	15.00	\$ 17	\$ 437
	Р	Wall - Cracks - Plasterboard - Rake & Stop	Lm	10	\$	12.00	\$ 14	\$ 140
		Walls - Paint - Repaint	m2	65	\$	12.00	\$ 14	\$ 910
		Popped Screws/Nails Walls	Per	6	\$	4.00	\$5	\$ 28
Office top of stairs	Q	Wall - Cracks - Plasterboard - Rake & Stop	Lm	0.6	\$	12.00	\$ 14	\$ 8
	-	Walls - Paint - Repaint	m2	8	\$	12.00	\$ 14	\$ 112
Main office	R	Window Frame - Paint -Repaint	m2	10.5	\$	20.50	\$ 24	\$ 251
Replace ceiling light fittings and Tile	S	Labour - Handyman (Incl. Vehicle)	h	4	\$	32.90	\$ 38	\$ 154
			m2	1	\$	52.30	\$ 61	\$ 61
Foyer	Т	Ceiling - Cracks - Plasterboard - Rake & Stop	Lm	1	\$	14.50	\$ 17	\$ 17
		Ceilings - Paint - Repaint -2 coats	m2	10.4	\$	17.00	\$ 20	\$ 206
		Popped Screws/Nails Walls	Per	8	\$ \$	4.00	\$ 5 \$ 14	\$ 37 \$ 14
	U	Wall - Cracks - Plasterboard - Rake & Stop Walls - Paint - Repaint	Lm Per	1 3	\$ \$	12.00 12.00	\$ 14 \$ 14	\$ 14 \$ 42
Computer Boom	v	Walls - Failt - Repailt Wall - Cracks - Plasterboard - Rake & Stop	Lm	5	ې \$	12.00	\$ 14 \$ 14	\$ 42 \$ 70
Computer Room	v	Walls - Paint - Repaint	m2	20	ې \$	12.00	\$ 14 \$ 14	\$ 70 \$ 280
		Popped Screws/Nails Walls	Per	6	\$	4.00	\$ 5	\$ 280
Middle West Office	w	Wall - Cracks - Plasterboard - Rake & Stop	Lm	0.15	\$	12.00	\$ 14	\$ 20
	**	Window Frame - Paint -Repaint	m2	6.5	\$	20.50	\$ 24	\$ 155
North West Office	х	Wall - Cracks - Plasterboard - Rake & Stop	Lm	10	\$	12.00	\$ 14	\$ 140
	~	Walls - Paint - Repaint	m2	30	\$	12.00		
North 10ffice	Y	Wall - Cracks - Plasterboard - Rake & Stop	Lm	17	\$	12.00		\$ 238
		Walls - Paint - Repaint	m2	41	\$	12.00		\$ 574
North 2 Office	Z	Wall - Cracks - Plasterboard - Rake & Stop	Lm	5.5	\$	12.00		\$ 77
		Walls - Paint - Repaint	m2	30	\$	12.00	\$ 14	\$ 420
		Popped Screws/Nails Walls	Per	2	\$	4.00	\$5	\$ 9
		Labour - Handyman (Incl. Vehicle) Wan Cracks - General any Substrate - Kake, KTV	h	8	\$	32.90	\$ 38	\$ 307
	А		Lm	2	\$	10.00	\$ 12	\$ 23
North	В	אווילנומלאלי ספוופומו מווץ substrate - המגפ, הו ע	Lm	12	\$	10.00	\$ 12	\$ 140
		Walls - Paint - Repaint	m2	31.5	\$	12.00		\$ 441
Office North Outside	С	Wall - Cracks - Exterior Stucco -	Lm	34	\$	17.00		\$ 674
	_	Walls - Paint - Repaint	m2	55	\$	12.00		\$ 770
Entrance Office	D	Grind And fill -Sealant	Lm	1.5	\$	25.00		\$ 44
South outside Building E Verhicle	E	Grind And fill -Sealant Concrete Glazing - Reinstall or replace rubber seals. Up to 1	Lm	1.5	\$	25.00	\$ 29	\$ 44
Work shop	A	m2 standerd glass	m2	0.5	\$	120.00		\$ 70
East Wall	В	Reseal joins Tilt Panals	Lm	8	\$ ¢	25.00	\$ 29 \$ 14	\$ 233
		Walls - Paint - Repaint Mobil Scaffold	m2 Dav	4	\$ \$	12.00 25.00	\$ 14 \$ 29	\$ 56 \$ 29
Workshop 2 SW corner	с	Weld Weld plates to Portal -Epoxy below bottom plate and reseal	Day Price	1	\$ \$	250.00		\$ 292
Ceiling	D	Re fit Tiles	Hr	1	\$	40.00	\$ 47	\$ 47
Coming		Lift - Scissor lift 6m	day	1	ې \$	100.00		\$ 47 \$ 117
		Lift - Scissor lift 6m transport	Bothw ays	1	\$	90.00		\$ 105
Workshop 3	E	Seal cracks east wall left side	Lm	6.2	\$	25.00	\$ 29	\$ 181
· · · ·	1	Wall Cracks - General any substrate - Rake, RTV	1	t	t i			

DAMAGED AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)	Unit	Quantity	Rate (\$)	Rate Including CCL fee	Cost included CCL Fee
East Wall	G	Wall Cracks - General any substrate - Rake, RTV and touch up.	Lm	4	\$ 10.00	\$ 12	\$ 47
		Walls - Paint - Repaint	m2	6.2	\$ 12.00	\$ 14	\$ 87
South	н	Ceiling Cracks - General any substrate - Rake, RTV and touch up.	Lm	3.4	\$ 12.00	\$ 14	\$ 48
		<select details="" from="" list="" or="" provide=""></select>			\$-	\$-	\$-
						\$-	\$-
						\$-	\$-
						\$-	\$-
						\$-	\$ -
						\$-	\$-
					EX GST	TOTAL	\$ 43,170

## **Clarifications / Notes**

Ref.

General	Rates assume works are carried out in normal works hours without penal labour rates.						
General	No Allowance for Resource or Buildings Consents as and if they prove to be necessary						
General	No allowance for removal of furniture and fixtures that may prove necessary (joinery shop)						
	Work can commence 2 - 4 weeks from receipt of PO.						
	The project will take approximately 4 weeks to complete.						

AREA (ROOM)	Ref No	WORK REQUIRED (DETAILED SCOPE OF WORK)         Unit <select details="" from="" list="" or="" provide=""></select>	Unit	Quantity	Rate (\$)	)	Rate Includin fee			
				\$	-	\$	-	\$		
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	
		<select details="" from="" list="" or="" provide=""></select>			\$	-	\$	-	\$	