



CLIENTS | PEOPLE | PERFORMANCE

Toilet/Pavilion Queenspark
PRK 0109 BLDG 001
Detailed Engineering Evaluation
Qualitative Report
Version Final

210 Queenspark Drive, Parklands



**Toilet/Pavilion Queenspark
PRK 0109 BLDG 001**

Detailed Engineering Evaluation
Qualitative Report
Version Final

210 Queenspark Drive, Parklands

Christchurch City Council

Prepared By
Simon Barker

Reviewed By
Stephen Lee

Date
17th May 2013



Contents

Qualitative Report Summary	i
1. Background	1
2. Compliance	2
2.1 Canterbury Earthquake Recovery Authority (CERA)	2
2.2 Building Act	3
2.3 Christchurch City Council Policy	4
2.4 Building Code	4
3. Earthquake Resistance Standards	5
4. Building Description	7
4.1 General	7
4.2 Gravity Load Resisting System	8
4.3 Lateral Load Resisting System	8
5. Assessment	9
6. Damage Assessment	10
6.1 Surrounding Buildings	10
6.2 Residual Displacements and General Observations	10
6.3 Ground Damage	10
7. Critical Structural Weakness	11
7.1 Short Columns	11
7.2 Lift Shaft	11
7.3 Roof	11
7.4 Staircases	11
7.5 Site Characteristics	11
7.6 Plan Irregularity	11
7.7 Vertical irregularity	11
8. Geotechnical Consideration	12
8.1 Site Description	12
8.2 Published Information on Ground Conditions	12



8.3	Seismicity	15
8.4	Slope Failure and/or Rockfall Potential	16
8.5	Liquefaction Potential	16
8.6	Recommendations	16
8.7	Conclusions & Summary	16
9.	Survey	17
10.	Initial Capacity Assessment	18
10.1	% NBS Assessment	18
10.2	Seismic Parameters	18
10.3	Expected Structural Ductility Factor	18
10.4	Discussion of Results	18
10.5	Occupancy	19
11.	Initial Conclusions	20
12.	Recommendations	21
13.	Limitations	22
13.1	General	22
13.2	Geotechnical Limitations	22

Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 2	ECan Borehole Summary	12
Table 4	Summary of Known Active Faults	15

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 2	Plan Sketch Showing Key Structural Elements	7
Figure 3	Map of Land Zoning Technical Categories	13
Figure 4	Post February 2011 Earthquake Aerial Photography	14

Appendices

A Photographs



B CERA Building Evaluation Form



Qualitative Report Summary

Toilet/Pavilion Queenspark

PRK 0109 BLDG 001

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version Final

210 Queenspark Drive, Parklands

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on the 19th of July 2012 and visual inspections on the 24th of May 2012.

Building Description

The toilet/pavilion is located in Queenspark Reserve on 210 Queenspark Drive, Parklands. The building is a single storey structure thought to be built in the early 1980's; it is believed no alterations have been made to the building since.

The pavilion toilet is constructed on what is assumed to be a strip foundation. Both the perimeter and partition walls are constructed from 20 series concrete masonry. A timber framed roof is connected to the top beam on the walls. This roof is built from trusses spanning in the transverse direction supporting metal sheet cladding. A 3m long canopy extends out of the buildings entire southern face forming a veranda.

The building, excluding the veranda, is approximately 8m wide and 14m long; the plan area is 112m². Its apex stands 5.2m above the ground.

Key Damage Observed

There was no structural damage observed.

Critical Structural Weaknesses

The following potential critical structural weaknesses have been identified in the structure.

- ▶ Liquefaction Potential (30% reduction) (42% NBS)

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be in the order of 42% NBS and post-earthquake capacity



also in the order of 42% NBS. The buildings post-earthquake capacity excluding critical structural weaknesses is in the order of 59% NBS.

The building has been assessed to have a seismic capacity in the order of 42% NBS and is therefore considered as being Earthquake Risk.

Recommendations

The building has not been assessed as being Earthquake Prone. As a result, the toilet/pavilion can remain occupied. CCC are not required to undertake a detailed seismic assessment, however due to the relatively low score, GHD recommend a detailed seismic assessment is carried out.



1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the toilet/pavilion.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.



2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The toilet/pavilion is located in Queenspark Reserve in one of the north-eastern suburbs of Christchurch, Parklands. The physical address of Queenspark Reserve is 210 Queenspark Drive, Parklands. The building is a single storey structure thought to be built in the early 1980's; it is believed no alterations have been made to the building since.

The pavilion toilet is constructed on what is assumed to be a strip foundation. Both the perimeter and partition walls are constructed from 20 series concrete masonry. A timber framed roof is connected to the top beam on the walls. This roof is built from irregularly shaped trusses (Appendix A) spanning in the transverse direction. The trusses are spaced at 0.9 meter centres and provide the support for the metal sheet cladding. A 3m long canopy extends out of the buildings entire southern face forming a veranda.




Figure 2 Plan Sketch Showing Key Structural Elements

The building, excluding the veranda, is approximately 8m wide and 14m long; the plan area is 112m². Its apex stands 5.2m above the ground.

There are no near waterways and the nearest building is ~10m to the pavilions north; there are however, tennis courts 2m to the east of the building. No damage was noted to either structure.

No plans were made available.



4.2 Gravity Load Resisting System

Gravity roof loads are carried by timber purlins spanning in the longitudinal direction. Gravity loads are then transferred to the timber roof trusses which span the building in the transverse direction. Loads from the trusses are transferred to the concrete masonry walls to the foundation and into the ground.

Internal gravity loads are transferred through the concrete foundation into the ground.

4.3 Lateral Load Resisting System

In the transverse direction the connection of the purlins to roof trusses, which connect to the wall top plates provide, a rigid frame which transfers lateral roof loads to the walls in the plane of loading. The lateral loads are then resisted by the panel action of the concrete masonry walls and are passed to the foundation and finally to the ground.

In the longitudinal direction the lateral roof loads are transferred from the purlins, via the roof trusses to the walls in the plane of loading. Panel action is used by these walls to transfer the longitudinal loads into the foundation.

Despite the lack of bracing in the roof the metal sheet cladding and the timber roof provide nominal diaphragm action which helps to redistribute out of plane lateral loads to the in plane walls.



5. Assessment

An inspection of the building was undertaken on the 24th of May 2012. Both the interior and exterior of the building were inspected. The main structural components of the roof of the building were able to be viewed as the majority of the interior had no ceiling. The foundations were unable to be viewed.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from a visual observation of the building.



6. Damage Assessment

6.1 Surrounding Buildings

No damage was noted to any surrounding buildings.

6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building.

There was some damage to the hot water cylinder.

6.3 Ground Damage

There was no evidence of ground damage on the property or surrounding neighbours land.



7. Critical Structural Weakness

7.1 Short Columns

No short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

Roof elements such as timber purlins and trusses were clearly visible and are expected to provide bracing to the roof structure. See photograph 5.

7.4 Staircases

The building does not contain a staircase.

7.5 Site Characteristics

Following the geotechnical appraisal it was found that the site has a high potential for liquefaction. For the purposes of the IEP assessment of the building and the determination of the %NBS score, the effects of soil liquefaction on the performance of the building has been assessed as a 'significant' site characteristic in accordance with the NZSEE guidelines.

7.6 Plan Irregularity

This building is not plan irregular.

7.7 Vertical irregularity

This building is not vertically irregular.



8. Geotechnical Consideration

8.1 Site Description

The pavilion/toilet is situated in Queenspark Park in Parklands, in north Christchurch. The site is relatively flat at approximately 3m above mean sea level. The site is approximately 2.5km north of the Avon River, and 2.0km west of the coast.

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by Holocene marine soils of the Christchurch Formation, dominantly sand of fixed and semi-fixed dunes and beaches.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that one borehole is located within a 200m radius of the site, (see Table 2), which indicates the area is typically underlain by 30m of sand, overlying layers of gravel and clay at depth.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/3418	39.9m	1.5m bgl	~100m NE of buildings

It should be noted that the borehole was sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The log has been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission hasn't undertaken geotechnical testing in the area of the site.

¹ Brown, L. J. and Weeber, J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.

8.2.4 CERA Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is within the Green Zone, meaning the land is generally suitable for repair and rebuilding to take place.

CERA have published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to perform in future earthquakes.

This site is categorised Technical Category Not Applicable, as the property is considered non-residential. However, as shown below in Figure 3, the site is located on the boundary of TC2 (yellow) and TC3 (blue).

Figure 3 Map of Land Zoning Technical Categories ²



8.2.5 Post February Aerial Photography

Aerial photography taken within days following the 22 February 2011 earthquake shows significant signs of liquefaction throughout the reserve, particularly to the southeast of the buildings, as shown in Figure 4.

² Origin of Map – CERA website, (insert URL address)

Figure 4 Post February 2011 Earthquake Aerial Photography³



8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise sand to ~30m depth, underlain by gravel, sand and clay st depth.

³ Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 3 Summary of Known Active Faults⁴⁵

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	130 km	NW	~8.3	~300 years
Greendale (2010) Fault	30 km	SW	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	110 km	NW	7.2	150 years
Porters Pass Fault	60 km	NW	7.0	1100 years

Recent earthquakes since 04 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains in close proximity to Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010

Since February 2011, seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

The presence of marine and/or estuarine sands of varying density and bedrock anticipated to be in excess of 500m deep with, a 475-year PGA (peak ground acceleration) of ~0.4 (Stirling et al, 2002⁴), , ground shaking is likely to be high.

⁴ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

⁵ GNS Active Faults Database



8.4 Slope Failure and/or Rockfall Potential

Given the site's location in Parklands, a flat suburb in north Christchurch, global slope instability and rockfall potential are considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

8.5 Liquefaction Potential

Due to the anticipated presence of sands, in addition to liquefaction evidence in post-earthquake aerial photography, it is considered likely that liquefaction will occur at the site in a moderate or significant seismic event.

8.6 Recommendations

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Given the site's anticipated susceptibility to liquefaction, it is recommended that intrusive investigation comprising at least one CPT should be conducted to target depth of 30m. This will allow a more detailed liquefaction assessment to be carried out.

8.7 Conclusions & Summary

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated predominantly on relatively loose sands to ~30m depth. Associated with this the site also has a high liquefaction potential.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

It is recommended that intrusive investigation be conducted, comprising at least one CPT to target depth of 20m.



9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.



10. Initial Capacity Assessment

10.1 % NBS Assessment

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity excluding critical structural weaknesses and the capacity of any identified weaknesses are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 4. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building excluding CSW's	59
Liquefaction Potential (30% reduction)	42

Table 4 Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 42% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered Earthquake Risk as it achieves greater than 33% and less than 67% NBS. This score has not been adjusted when considering damage to the structure as all damage observed was relatively minor and considered unlikely to adversely affect the load carrying capacity of the structural systems.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- Return period factor $R_u = 1.0$, NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age and construction type. Although the buildings construction date is unknown, we have assumed the building was built in the early 1980's and follows the code current at that time, NZS 4203:1976. The



design loads used in this standard are likely to have been less than those required by the current loading standard. When combined with the increase in the hazard factor for Christchurch to 0.3, it would be expected that the building would not achieve 100% NBS.

10.5 Occupancy

The toilet/pavilion has been assessed as not being Earthquake Prone and as a result, can remain occupied.



11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 42% NBS and is therefore potentially Earthquake Risk.



12. Recommendations

The recent seismic activity in Christchurch has only caused damage to this building's hot water cylinder. As the building suffered insignificant damage that would not compromise the load resisting capacity of the existing structural systems and has achieved between 33% and 67% NBS following an initial IEP assessment of the building, no further assessment is required by Christchurch City Council to comply with the building act.



13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ Visual inspections of the sub-floor space could not be completed.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A
Photographs

Photograph 1 View from the north.



Photograph 2 Northern elevation.



Photograph 3 Southern Elevation.



Photograph 4 Roof trusses.



Photograph 5 Roof trussse.



Photograph 6 Interior partition Wall.



Photograph 7 Interior.





Appendix B
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location		
Building Name:	Queenspark Toilet Pavillion	
Building Address:	Unit No: Street	210 Queenspark Drive, Parklands
Legal Description:	Lot 1 DP 35473	
	Degrees	Min Sec
GPS south:	43	28 30.00
GPS east:	172	41 47.00
Building Unique Identifier (CCC):	PRK 0109 BLDG 001	
Reviewer:	Stephen Lee	
CPEng No:	1006840	
Company:	GHD	
Company project number:	513090210	
Company phone number:	04 472 0799	
Date of submission:	18/09/2012	
Inspection Date:	24/05/2012	
Revision:	Final	
Is there a full report with this summary?	yes	

Site		
Site slope:	flat	
Soil type:	mixed	
Site Class (to NZS1170.5):	D	
Proximity to waterway (m, if <100m):		
Proximity to clifftop (m, if < 100m):		
Proximity to cliff base (m,if <100m):		
Max retaining height (m):		
Soil Profile (if available):		
If Ground improvement on site, describe:		
Approx site elevation (m):		

Building		
No. of storeys above ground:	single storey = 1	
Ground floor split?	no	
Storeys below ground:		
Foundation type:	strip footings	
Building height (m):	5.20	
Floor footprint area (approx):	112	
Age of Building (years):	32	
Ground floor elevation (Absolute) (m):		
Ground floor elevation above ground (m):		
if Foundation type is other, describe:	Assumed	
height from ground to level of uppermost seismic mass (for IEP only) (m):		
Date of design:	1976-1992	
Strengthening present?	no	
If so, when (year)?		
And what load level (%g)?		
Brief strengthening description:		
Use (ground floor):	public	
Use (upper floors):	public	
Use notes (if required):		
Importance level (to NZS1170.5):	IL2	

Gravity Structure		
Gravity System:	load bearing walls	
Roof:	timber framed	
Floors:	concrete flat slab	
Beams:	none	
Columns:		
Walls:	fully filled concrete masonry	
rafter type, purlin type and cladding		
slab thickness (mm)	Assumed strip footings	
overall depth x width (mm x mm)		
#N/A		

Lateral load resisting structure		
Lateral system along:	partially filled CMU	
Ductility assumed, μ :	1.25	
Note: Define along and across in detailed report!		
note total length of wall at ground (m):		

Period along:	0.40	##### enter height above at H31	estimate or calculation?	estimated
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):			estimate or calculation?	
Lateral system across:	partially filled CMU			
Ductility assumed, μ :	1.25			
Period across:	0.40	##### enter height above at H31	note total length of wall at ground (m):	estimated
Total deflection (ULS) (mm):			estimate or calculation?	
maximum interstorey deflection (ULS) (mm):			estimate or calculation?	

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:		
Wall cladding:		
Roof Cladding:	Metal	describe: Profiled metal sheeting
Glazing:	timber frames	
Ceilings:	none	
Services(list):		

Available documentation

Architectural	none	original designer name/date	
Structural	none	original designer name/date	
Mechanical	none	original designer name/date	
Electrical	none	original designer name/date	
Geotech report	full	original designer name/date	

Damage

Site: (refer DEE Table 4-2)

Site performance:	Good	Describe damage:	
Settlement:	none observed	notes (if applicable):	
Differential settlement:	none observed	notes (if applicable):	
Liquefaction:	none apparent	notes (if applicable):	
Lateral Spread:	none apparent	notes (if applicable):	
Differential lateral spread:	none apparent	notes (if applicable):	
Ground cracks:	none apparent	notes (if applicable):	
Damage to area:	none apparent	notes (if applicable):	

Building:

Current Placard Status:

Along	Damage ratio:	0%	Describe how damage ratio arrived at: <input type="text"/>
	Describe (summary):		
Across	Damage ratio:	0%	
	Describe (summary):		

$$Damage_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text" value="Nominal diaphragm action from roof bracing"/>
CSWs:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Pounding:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Non-structural:	Damage?:	<input type="text" value="yes"/>	Describe:	<input type="text" value="Non structural damage to H/W cilinder"/>

Recommendations				
	Level of repair/strengthening required:	<input type="text" value="none"/>	Describe:	<input type="text"/>
	Building Consent required:	<input type="text" value="no"/>	Describe:	<input type="text"/>
	Interim occupancy recommendations:	<input type="text" value="full occupancy"/>	Describe:	<input type="text"/>
Along	Assessed %NBS before e'quakes:	<input type="text" value="42%"/>	42% %NBS from IEP below	If IEP not used, please detail assessment methodology: <input type="text"/>
	Assessed %NBS after e'quakes:	<input type="text" value="42%"/>		
Across	Assessed %NBS before e'quakes:	<input type="text" value="42%"/>	42% %NBS from IEP below	
	Assessed %NBS after e'quakes:	<input type="text" value="42%"/>		

IEP				
Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.				
Period of design of building (from above): 1976-1992		h _n from above: m		
Seismic Zone, if designed between 1965 and 1992:	<input type="text" value="B"/>	not required for this age of building	<input type="text" value="D soft soil"/>	not required for this age of building
		along	across	
	Period (from above):	<input type="text" value="0.4"/>	<input type="text" value="0.4"/>	
	(%NBS) _{nom} from Fig 3.3:	<input type="text" value="16.5%"/>	<input type="text" value="16.5%"/>	
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0			<input type="text" value="1.00"/>	
Note 2: for RC buildings designed between 1976-1984, use 1.2			<input type="text" value="1.0"/>	
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)			<input type="text" value="1.0"/>	
	Final (%NBS) _{nom} :	<input type="text" value="17%"/>	<input type="text" value="17%"/>	
2.2 Near Fault Scaling Factor	Near Fault scaling factor, from NZS1170.5, cl 3.1.6:	<input type="text" value="1.00"/>		
	Near Fault scaling factor (1/N(T,D), Factor A):	along	across	
		<input type="text" value="1"/>	<input type="text" value="1"/>	
2.3 Hazard Scaling Factor	Hazard factor Z for site from AS1170.5, Table 3.3:	<input type="text" value="0.30"/>		
	Z ₁₉₉₂ , from NZS4203:1992	<input type="text" value="0.8"/>		
	Hazard scaling factor, Factor B :	<input type="text" value="3.33333333"/>		
2.4 Return Period Scaling Factor	Building Importance level (from above):	<input type="text" value="2"/>		
	Return Period Scaling factor from Table 3.1, Factor C :	<input type="text" value="1.00"/>		

2.5 Ductility Scaling Factor

	along	across
Assessed ductility (less than max in Table 3.2)	1.25	1.25
Ductility scaling factor: =1 from 1976 onwards; or = μ , if pre-1976, from Table 3.3:	1.00	1.00

Ductility Scaling Factor, **Factor D:**

2.6 Structural Performance Scaling Factor:

Sp:

Structural Performance Scaling Factor **Factor E:**

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS_b:

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential
 Pounding effect D1, from Table to right
 Height Difference effect D2, from Table to right

Therefore, Factor D:

3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum

Along Across

Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:

4.4 Percentage New Building Standard (%NBS), (before)

Official Use only:

Accepted By:
 Date:





GHD

GHD Office
226 Antigua Street, Christchurch 8011
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

© GHD Limited 2013

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Simon Barker	Rob Collins		Stephen Lee		17/05/13