



CLIENTS | PEOPLE | PERFORMANCE

Ruru Lawn Cemetery Garage
PRK_0895_BLDG_009 EQ2
Detailed Engineering Evaluation
Qualitative Report
Version Final

63 Ruru Road
Bromley

**Ruru Lawn Cemetery Garage
PRK 0895 BLDG 009 EQ2**

Detailed Engineering Evaluation
Qualitative Report
Version Final

63 Ruru Road
Bromley

Christchurch City Council

Prepared By
Christopher Wells

Reviewed By
Razel Ramilo

Date
18th September 2012

Contents

Qualitative Report Summary	5
1. Background	7
2. Compliance	8
2.1 Canterbury Earthquake Recovery Authority (CERA)	8
2.2 Building Act	9
2.3 Christchurch City Council Policy	10
2.4 Building Code	10
3. Earthquake Resistance Standards	11
4. Building Description	13
4.1 General	13
4.2 Gravity Load Resisting System	14
4.3 Lateral Load Resisting System	14
5. Assessment	15
6. Damage Assessment	16
6.1 Surrounding Buildings	16
6.2 Residual Displacements and General Observations	16
6.3 Ground Damage	16
7. Critical Structural Weakness	17
7.1 Short Columns	17
7.2 Lift Shaft	17
7.3 Roof	17
7.4 Staircases	17
7.5 Site Characteristics	17
8. Geotechnical Consideration	18
8.1 Site Description	18
8.2 Published Information on Ground Conditions	18
8.3 Seismicity	20
8.4 Slope Failure and/or Rockfall Potential	20

8.5	Liquefaction Potential	20
8.6	Conclusions & Recommendations	21
9.	Survey	22
10.	Initial Capacity Assessment	23
10.1	% NBS Assessment	23
10.2	Seismic Parameters	23
10.3	Expected Structural Ductility Factor	23
10.4	Discussion of Results	23
11.	Initial Conclusions	25
12.	Recommendations	26
13.	Limitations	27
13.1	General	27
13.2	Geotechnical Limitations	27

Table Index

Table 1	%NBS compared to relative risk of failure	12
Table 2	ECan Borehole Summary	18
Table 3	EQC Geotechnical Investigation Summary Table	19
Table 4	Summary of Known Active Faults'	20

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	11
Figure 2	Plan Sketch Showing Key Structural Elements	13
Figure 3	Post February 2011 Earthquake Aerial Photography	19

Appendices

- A Photographs
- B CERA Building Evaluation Form

Qualitative Report Summary

Ruru Lawn Cemetery Garage

PRK 0895 BLDG 009 EQ2

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version Final

63 Ruru Road

Bromley

Christchurch

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 19th July 2012.

Key Damage Observed

Key damage observed includes:-

- Extensive cracking to brickwork
- Cracking in foundations
- Opening in roofing iron from collapsed chimney
- Debris build-up on roof

Critical Structural Weaknesses

The following potential critical structural weaknesses have been identified in the structure.

- ▶ Liquefaction Potential (Significant, 30% Reduction) 15% NBS

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be in the order of 15% NBS and post-earthquake capacity also in the order of 8% NBS. The buildings post-earthquake capacity excluding critical structural weaknesses and damage is in the order of 21% NBS.

The building has been assessed to have a seismic capacity in the order of 8% NBS and is therefore Earthquake Prone.

Recommendations

The building has achieved less than 34% NBS seismic capacity according to the initial IEP assessment and as a result is classified as potentially an Earthquake Prone building in accordance with the NZSEE guidelines. Therefore it is recommended that further detailed assessment be carried out on the structure to more accurately assess the buildings %NBS. As the building has suffered a large amount of damage, it is recommended that occupancy of the building is prohibited.

1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Ruru lawn Cemetery Garage.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. As there are no available drawings, the building's evaluation is based on the visual inspection carried out on site. The date of construction of the building is unknown and therefore estimated for the purpose of this assessment. The results of the evaluation, however, may change should the exact construction date is made known.

2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The building is within Ruru Lawn Cemetery at 63 Ruru Road, Bromley. The date of construction is estimated as pre 1935. The current use of the building is as storage and also houses a DB board. The building has had a lean-to addition in approximately the last 20 years.

The original structure has approximately a 25 degree duo-pitch roof, formed by corrugated sheet metal on timber board and rafters, with 200mm thick external clay brick (URM) unreinforced walls. External walls are likely supported on strip footings and the floor is a concrete slab on grade.

The additional lean-to has approximately a 10 degree mono-pitch roof, formed by corrugated metal sheet on timber board and rafters, with timber framed walls clad in cement fibre board. External walls are supported on timber posts.




Figure 2 Plan Sketch Showing Key Structural Elements

The building is approximately 5.0m in length by 6.3m in width with a height of 3.0m. The building occupies a footprint of approximately 31.5m² and is over 10m from the nearest structure, a shed occupying the same site. The site is relatively flat at approximately 10m above mean sea level. It is approximately 2.5km west of Avon River, 2.5km north of the Heathcote River, and 4km west of the coast (Pegasus Bay). No plans are available for the structure.

4.2 Gravity Load Resisting System

Gravity loads are resisted by load bearing brick walls. Gravity loads on the roof are transferred via timber rafters and the propped timber ridge beam to walls. The gravity loads from the walls are then transferred to the strip footings and into the ground.

4.3 Lateral Load Resisting System

Lateral loads are resisted primarily by the panel action of load bearing brick walls. Nominal diaphragm action provided by timber roof boards on rafters serves to prop URM walls out-of-plane, carrying these loads and other roof self-loads to walls for in-plane transfer to the foundations.

5. Assessment

An inspection of the building was undertaken on the 19th July 2012. Both the interior and exterior of the building were inspected.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual inspection of the building. As there are no available drawings, the year of construction of the building was estimated for the purpose of this assessment.

6. Damage Assessment

6.1 Surrounding Buildings

The building is relatively isolated with the nearest structure approximately 10m away. The neighbouring buildings appeared to have not suffered any seismic damage.

6.2 Residual Displacements and General Observations

Severe residual displacements of the structure were noticed during our inspection of the building.

Cracking was noted to the exterior brick wall in several locations throughout the building. See photographs 1,4,5,7 and 8. These cracks are considered to be significant.

Cracking was also noted to the foundations; however these probably existed before the Christchurch earthquake. See photograph 3.

6.3 Ground Damage

There was no evidence of ground damage in the park area.

7. Critical Structural Weakness

7.1 Short Columns

No critical short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

Nominal diaphragms in the roof planes were formed by timber boards on rafters, providing internal stability. Hence, a critical structural weakness has not been denoted in the CERA IEP form.

7.4 Staircases

The building does not contain a staircase.

7.5 Site Characteristics

Following the geotechnical appraisal it was found that the site has a moderately to highly susceptible for liquefaction. For the purposes of the IEP assessment and the determination of the %NBS score of the building, the effects of soil liquefaction on the performance of the building has been assessed as a 'significant' site characteristic in accordance with the NZSEE guidelines.

8. Geotechnical Consideration

8.1 Site Description

The site is situated in the suburb of Bromley, east of Christchurch City centre. The site is relatively flat at approximately 10m above mean sea level. It is approximately 2.5km west of Avon River, 2.5km north of the Heathcote River, and 4km west of the coast (Pegasus Bay).

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by:

- Christchurch Formation, dominantly sand of fixed and semi-fixed dunes and beaches, Holocene in age.

Due to the low-lying location of the site, shallow ground water table is anticipated.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that there are thirteen boreholes located within 200m of the site. There are three boreholes with significant information summarised in the table below (see Table 2).

These indicate that the area is underlain by layers of sand and clay with layers of shingle.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35-16044-WC	2.9 m	Not indicated	170m NE
M35-1869-WC	60.29 m	0.28 m bgl	150m W
M35-1898-WC	90.5 m	0.6m bgl	170m SW

It should be noted that the boreholes were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has undertaken geotechnical testing in the area of the site. Information pertaining to this investigation is included in the Tonkin & Taylor Report for Bromley². One CPT investigation was undertaken within 100m of the site, as summarised below in Table 3.

¹ Forsyth, P. J., Barrell, D. J. A., & Jongens, R. (2008): *Geology of the Christchurch Urban Area*. Institute of Geological and Nuclear Sciences 1:250,000 Geological Map 16. IGNS Limited: Lower Hutt.

² Tonkin & Taylor Ltd., 2011: Christchurch Earthquake Recovery, *Geotechnical Factual Report, Linwood*.

Table 3 EQC Geotechnical Investigation Summary Table

Bore Name	Orientation from Site	Depth (m bgl)	Log Summary
CPT-BRY-21	50m SW	0-9.56	Sand to Silty Sand (GWL 2m bgl)

Initial observations of the CPT result indicate the site is underlain by sand to silty sand.

8.2.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has classified the site as “Green Zone, N/A – Urban Non-residential” category. Land in the green zone is generally considered suitable for residential construction. An “N/A” technical category indicates the site is a non-residential property in urban area beyond the extent of land damage mapping. However, the neighbouring properties are classified as “Technical Category 2 (TC2, yellow) means that minor to moderate land damage from liquefaction is possible in future significant earthquakes.

8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows signs of liquefaction close to the site, as shown in Figure 3.

Figure 3 Post February 2011 Earthquake Aerial Photography³



8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise multiple strata of sand and silty sand.

³ Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 4 Summary of Known Active Faults^{4,5}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	25 km	W	7.1	~15,000 years
Hope Fault	105 km	NW	7.2~7.5	120~200 years
Kelly Fault	105 km	NW	7.2	150 years
Porter Pass Fault	65 km	NW	7.0	1100 years

The recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains, including Christchurch City, and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

8.4 Slope Failure and/or Rockfall Potential

Given the site's location in Bromley, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

8.5 Liquefaction Potential

The site is considered to be moderately to highly susceptible to liquefaction, due to the following reasons:

⁴ Stirling, M.W., McVerry, G.H., and Berryman K.R. (2002): "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, June 2002, pp. 1878-1903.

⁵ GNS Active Faults Database, <http://maps.gns.cri.nz/website/af/viewer>

- Signs of significant liquefaction close to the site (evidence from the post-earthquake aerial photography);
- Anticipated presence of sand and silt deposits beneath the site; and,
- Anticipated shallow ground water table.

Due to the limited subsoil information, further investigation is recommended to better determine subsoil conditions. From this, a more comprehensive liquefaction assessment could be undertaken.

8.6 Conclusions & Recommendations

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on sand and silt deposits. Associated with this the site also has a moderate to high liquefaction potential, in particular where sands and/or silts are present.

A soil class of **D/E** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that intrusive investigation be conducted.

9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.

10. Initial Capacity Assessment

10.1 % NBS Assessment

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The building's capacity excluding critical structural weaknesses and the capacity of any identified weaknesses are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 5. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building excluding CSW's	21
Building's capacity including Liquefaction Potential (Significant, 30% Reduction)	15
Building's capacity including damage (50% Reduction)	8

Table 5 Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 8% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered Earthquake Prone as it achieves less than 33% NBS. The overall %NBS has been reduced by 30% significant liquefaction potential and 50% to account for the severe damage to the load bearing brick walls of the building.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- Site soil class: E, NZS 1170.5:2004, Clause 3.1.3, Very Soft Soil
- Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- Return period factor $R_u = 0.5$, NZS 1170.5:2004, Table 3.5, Importance level 1 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age, construction type and Importance Level founded on Class E soils. The design loads used in this standard are likely to have been less than those required by the current loading standard. When

combined with the increase in the hazard factor for Christchurch to 0.3, significant liquefaction potential and extensive damage to the building, it would be expected that the building would not achieve 100% NBS.

11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 8% NBS and is therefore potentially Earthquake Prone.

12. Recommendations

The building has achieved less than 34% NBS seismic capacity according to the initial IEP assessment and as a result is classified as potentially an Earthquake Prone building in accordance with the NZSEE guidelines. Therefore it is recommended that further detailed assessment be carried out on the structure to more accurately assess the buildings %NBS. As the building has suffered a large amount of damage, it is recommended that occupancy of the building is prohibited.

13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report. A specific limitations section.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.

Appendix A
Photographs



Photograph 1 Northeast elevation.



Photograph 2 Northeast elevation. Original structure to the right and added lean-to on the left.



Photograph 3 Cracks in original structure's slab.



Photograph 4 North corner of building showing vertical and horizontal cracking along brickwork joints.



Photograph 5 Northeast corner of building showing extensive vertical and horizontal cracking along brickwork joints.



Photograph 6 View of Rooftop showing original structure to the right and added lean-to on the left. Note debris build-up and collapsed section on the original iron roof.



Photograph 7 Northeast walls top row of bricks separating.



Photograph 8 Northeast walls top row of bricks separating at window.



Photograph 9 Temporary prop strengthening on the inside of the building with Ply and 4x2 timber.



Photograph 10 Temporary prop strengthening on outside of the building.



Photograph 11 Original structures underside of roof.



Photograph 12 Lean-to structures underside of roof.

Appendix B

CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <input type="text" value="Ruru Lawn Cemetery Garage"/>	Reviewer: <input type="text" value="Stephen Lee"/>
	Unit No: Street	CPEng No: <input type="text" value="1006840"/>	
Building Address: <input type="text"/>	<input type="text" value="63 Ruru Road"/>	Company: <input type="text" value="GHD"/>	
Legal Description: <input type="text"/>		Company project number: <input type="text" value="51 - 30902 - 51"/>	
		Company phone number: <input type="text" value="04 472 0799"/>	
	Degrees Min Sec	Date of submission: <input type="text"/>	
GPS south: <input type="text"/>	<input type="text"/>	Inspection Date: <input type="text" value="19/07/2012"/>	
GPS east: <input type="text"/>	<input type="text"/>	Revision: <input type="text"/>	
Building Unique Identifier (CCC): <input type="text" value="PRK_0895_BLDG_009_EQ2"/>		Is there a full report with this summary? <input type="text" value="yes"/>	

Site		Max retaining height (m): <input type="text"/>
Site slope: <input type="text" value="flat"/>	Soil type: <input type="text" value="mixed"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="E"/>	Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>
Proximity to cliff top (m, if < 100m): <input type="text"/>	Proximity to cliff base (m, if <100m): <input type="text"/>	Approx site elevation (m): <input type="text" value="10.00"/>

Building		single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="10.00"/>
No. of storeys above ground: <input type="text" value="1"/>	Ground floor split? <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value="10.00"/>
Stores below ground: <input type="text" value="0"/>	Foundation type: <input type="text" value="strip footings"/>	if Foundation type is other, describe: <input type="text"/>	
Building height (m): <input type="text" value="3.00"/>	Floor footprint area (approx): <input type="text" value="30"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>	
Age of Building (years): <input type="text" value="77"/>		Date of design: <input type="text" value="Pre 1935"/>	
Strengthening present? <input type="text" value="yes"/>	Use (ground floor): <input type="text" value="other (specify)"/>	If so, when (year)? <input type="text" value="2012 - Temporary"/>	
Use (upper floors): <input type="text"/>	Use notes (if required): <input type="text"/>	Brief strengthening description: <input type="text"/>	
Importance level (to NZS1170.5): <input type="text" value="IL1"/>			

Gravity Structure		rafter type, purlin type and cladding	<input type="text" value="Metal cladding on board and rafters"/>
Gravity System: <input type="text" value="load bearing walls"/>	Roof: <input type="text" value="timber framed"/>	slab thickness (mm)	<input type="text" value="Slab on grade."/>
Floors: <input type="text" value="concrete flat slab"/>	Beams: <input type="text"/>		
Columns: <input type="text"/>	Walls: <input type="text" value="load bearing brick"/>	#N/A	<input type="text" value="200"/>

Lateral load resisting structure		Note: Define along and across in detailed report!	note wall thickness and cavity	<input type="text"/>
Lateral system along: <input type="text" value="unreinforced masonry bearing wall - brick"/>	Ductility assumed, μ : <input type="text" value="1.25"/>	0.40 from parameters in sheet	estimate or calculation?	<input type="text"/>
Period along: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation?	<input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			estimate or calculation?	<input type="text"/>
Lateral system across: <input type="text" value="unreinforced masonry bearing wall - brick"/>	Ductility assumed, μ : <input type="text" value="1.25"/>	0.00	note wall thickness and cavity	<input type="text"/>
Period across: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation?	<input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			estimate or calculation?	<input type="text"/>

Separations:		north (mm):	<input type="text"/>	leave blank if not relevant
		east (mm):	<input type="text"/>	
		south (mm):	<input type="text"/>	
		west (mm):	<input type="text"/>	

Non-structural elements		Stairs:	<input type="text"/>	describe
		Wall cladding:	<input type="text"/>	
		Roof Cladding:	Metal	
		Glazing:	aluminium frames	
		Ceilings:	<input type="text"/>	
		Services(list):	<input type="text"/>	

Available documentation		Architectural:	none	original designer name/date:	<input type="text"/>
		Structural:	none	original designer name/date:	<input type="text"/>
		Mechanical:	none	original designer name/date:	<input type="text"/>
		Electrical:	none	original designer name/date:	<input type="text"/>
		Geotech report:	none	original designer name/date:	<input type="text"/>

Damage		Site performance:	<input type="text"/>	Describe damage:	<input type="text"/>
Site: (refer DEE Table 4-2)		Settlement:	none observed	notes (if applicable):	<input type="text"/>
		Differential settlement:	none observed	notes (if applicable):	<input type="text"/>
		Liquefaction:	none apparent	notes (if applicable):	Significant liquefaction potential
		Lateral Spread:	none apparent	notes (if applicable):	<input type="text"/>
		Differential lateral spread:	none apparent	notes (if applicable):	<input type="text"/>
		Ground cracks:	none apparent	notes (if applicable):	<input type="text"/>
		Damage to area:	none apparent	notes (if applicable):	<input type="text"/>

Building:		Current Placard Status:	<input type="text"/>	
Along	Damage ratio:	<input type="text" value="50%"/>	Describe how damage ratio arrived at:	<input type="text"/>
	Describe (summary):	Extensive damage to brick walls		
Across	Damage ratio:	<input type="text" value="50%"/>	$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$	
	Describe (summary):	Extensive damage to brick walls		
Diaphragms	Damage?:	no	Describe:	<input type="text"/>
CSWs:	Damage?:	yes	Describe:	Significant liquefaction potential
Pounding:	Damage?:	no	Describe:	<input type="text"/>
Non-structural:	Damage?:	no	Describe:	<input type="text"/>

Recommendations		Level of repair/strengthening required:	demolition	Describe:	Brick walls are too damaged to be repaired
		Building Consent required:	no	Describe:	<input type="text"/>
		Interim occupancy recommendations:	do not occupy	Describe:	<input type="text"/>
Along	Assessed %NBS before:	<input type="text" value="15%"/>	15% %NBS from IEP below	If IEP not used, please detail assessment methodology:	<input type="text"/>
	Assessed %NBS after:	<input type="text" value="8%"/>			
Across	Assessed %NBS before:	<input type="text" value="15%"/>	15% %NBS from IEP below		
	Assessed %NBS after:	<input type="text" value="8%"/>			

IEP

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): Pre 1935

 h_n from above: mSeismic Zone, if designed between 1965 and 1992: not required for this age of building
not required for this age of building

	along	across
Period (from above):	0.4	0.4
(%NBS) _{nom} from Fig 3.3:	2.9%	2.9%

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0 Note 2: for RC buildings designed between 1976-1984, use 1.2 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
Final (%NBS) _{nom} :	2%	2%

2.2 Near Fault Scaling FactorNear Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), Factor A):	1	1

2.3 Hazard Scaling FactorHazard factor Z for site from AS1170.5, Table 3.3: Z_{1992} , from NZS4203:1992 **2.4 Return Period Scaling Factor**Building Importance level (from above): Return Period Scaling factor from Table 3.1, **Factor C**: **2.5 Ductility Scaling Factor**Assessed ductility (less than max in Table 3.2) Ductility scaling factor: =1 from 1976 onwards; or = k_d , if pre-1976, from Table 3.3:

	along	across
Ductility Scaling Factor, Factor D :	1.25	1.25

2.6 Structural Performance Scaling Factor:Sp: Structural Performance Scaling Factor **Factor E**: **2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E**%NBS_b:

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: 3.2. Vertical irregularity, Factor B: 3.3. Short columns, Factor C: 3.4. Pounding potential
Pounding effect D1, from Table to right
Height Difference effect D2, from Table to right Therefore, Factor D: 3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum
Rationale for choice of F factor, if not 1

Along	Across
1.0	1.0

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.70	0.70
------	------

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:

15%	15%
-----	-----

4.4 Percentage New Building Standard (%NBS), (before)

15%



GHD

Level 11, Guardian Trust House
15 Willeston street, Wellington 6011
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	C. Wells	R.Ramilo		R. Collins		18/09/2012