



**aurecon**

Spencer Park – Amenity Building

Qualitative Engineering Evaluation

Functional Location ID: PRO\_0157\_B009

Address: 100 Heyders Road, Spencerville

**Reference:**

228604

**Prepared for:**

Christchurch City Council

**Revision:** 3

**Date:** 17 October 2013

# Document Control Record

Document prepared by:

Aurecon New Zealand Limited  
 Level 2, 518 Colombo Street  
 Christchurch 8011  
 PO Box 1061  
 Christchurch 8140  
 New Zealand

**T** +64 3 375 0761  
**F** +64 3 379 6955  
**E** christchurch@aurecongroup.com  
**W** aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control		aurecon				
<b>Report Title</b>		Qualitative Engineering Evaluation				
<b>Functional Location ID</b>		<b>PRO_0157_B009</b>	<b>Project Number</b>		228604	
<b>File Path</b>		P:\ 228604 - Spencer Park – Amenity Building.docx				
<b>Client</b>		Christchurch City Council	<b>Client Contact</b>		Michael Sheffield	
<b>Rev</b>	<b>Date</b>	<b>Revision Details/Status</b>	<b>Prepared</b>	<b>Author</b>	<b>Verifier</b>	<b>Approver</b>
1	13 June 2012	Draft	C. Bong	C. Bong	S. Manning	S. Manning
2	17 June 2013	Final	C. Bong	C. Bong	S. Manning	S. Manning
3	17 October 2013	Final	C. Bong	C. Bong	S. Manning	S. Manning
<b>Current Revision</b>		3				

Approval			
<b>Author Signature</b>		<b>Approver Signature</b>	
<b>Name</b>	Christopher Bong	<b>Name</b>	Simon Manning
<b>Title</b>	Structural Engineer	<b>Title</b>	Senior Structural Engineer



# Contents

<b>Executive Summary</b>	<b>2</b>
<b>1 Introduction</b>	<b>3</b>
1.1 General	3
<b>2 Description of the Building</b>	<b>3</b>
2.1 Building Age and Configuration	3
2.2 Building Structural Systems Vertical and Horizontal	3
2.3 Reference Building Type	3
2.4 Building Foundation System and Soil Conditions	4
2.5 Available Structural Documentation and Inspection Priorities	4
2.6 Available Survey Information	4
<b>3 Structural Investigation</b>	<b>5</b>
3.1 Summary of Building Damage	5
3.2 Record of Intrusive Investigation	5
3.3 Damage Discussion	5
<b>4 Building Review Summary</b>	<b>5</b>
4.1 Building Review Statement	5
4.2 Critical Structural Weaknesses	5
<b>5 Building Strength (refer Appendix C for background information)</b>	<b>6</b>
5.1 General	6
5.2 Initial %NBS Assessment	6
5.3 Results Discussion	6
<b>6 Conclusions and Recommendations</b>	<b>7</b>
<b>7 Explanatory Statement</b>	<b>7</b>

## Appendices

**Appendix A Site Map, Photos and Levels Survey**

**Appendix B References**

**Appendix C Strength Assessment Explanation**

**Appendix D Background and Legal Framework**

**Appendix E Standard Reporting Spread Sheet**

# Executive Summary

This is a summary of the Qualitative Engineering Evaluation for the Spencer Park – Amenity Building which is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

<b>Building Details</b>	<b>Name</b>	Spencer Park – Amenity Building			
<b>Building Location ID</b>	PRO_0157_B009	<b>Multiple Building Site</b>	Y		
<b>Building Address</b>	100 Heyders Road, Spencerville	<b>No. of residential units</b>	0		
<b>Soil Technical Category</b>	3	<b>Importance Level</b>	2	<b>Year Built</b>	1960s
<b>Foot Print (m<sup>2</sup>)</b>	220	<b>Stories above ground</b>	1	<b>Stories below ground</b>	0
<b>Type of Construction</b>	Corrugated steel roof, lightweight timber roof with purlins and rafters, steel roof frame, plasterboard ceiling, concrete masonry walls, concrete pad foundation				
<b>Qualitative L4 Report Results Summary</b>					
<b>Building Occupied</b>	Y	The Spencer Park – Amenity Building is currently in use			
<b>Suitable for Continued Occupancy</b>	Y	The Spencer Park – Amenity Building is considered suitable for continued occupation.			
<b>Key Damage Summary</b>	Y	Refer to summary of building damage in Section 3.1 report body.			
<b>Critical Structural Weaknesses (CSW)</b>	Y	Potentially unreinforced and unfilled load-bearing concrete masonry walls.			
<b>Levels Survey Results</b>	Y	With allowance for falls to wet areas levels were within allowable limits.			
<b>Building %NBS From Analysis</b>	Approx. 36%	Based on out of plane unreinforced masonry wall performance, the building is assessed as in the “moderate risk” category according to NZSEE guidelines refer Figure C1 in Appendix C.			
<b>Qualitative L4 Report Recommendations</b>					
<b>Geotechnical Survey Required</b>	N	A geotechnical survey is not required.			
<b>Proceed to L5 Quantitative DEE</b>	Y	Intrusive investigation and further analysis required to confirm the stability, robustness and future resilience of the loadbearing concrete masonry walls.			
<b>Approval</b>					
<b>Author Signature</b>			<b>Approver Signature</b>		
<b>Name</b>	Christopher Bong		<b>Name</b>	Simon Manning	
<b>Title</b>	Structural Engineer		<b>Title</b>	Senior Structural Engineer	

# 1 Introduction

## 1.1 General

On 25 May 2012, Aurecon engineers visited the Spencer Park – Amenity Building to undertake a qualitative building damage assessment on behalf of Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the earthquakes on 4 September 2010, 22 February 2011, 13 June 2011, 23 December 2011 and related aftershocks.

The scope of work included:

1. Assessment of the nature and extent of the building damage;
2. Visual assessment of the building strength particularly with respect to safety of occupants if the building is currently occupied; and
3. Assessment of requirements for detailed engineering evaluation including geotechnical investigation, level survey and any areas where linings and floor coverings need removal to expose structural damage.

This report outlines the results of our Qualitative Assessment of damage to the Spencer Park – Amenity Building and is based on the Detailed Engineering Evaluation Guidelines as issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation as appropriate are attached herein.

## 2 Description of the Building

### 2.1 Building Age and Configuration

The Spencer Park – Amenity Building is a camping ground amenity building, octagonal in shape, constructed of concrete masonry blocks. The building has a light weight timber framed roof with a central clerestory pop up roof supported on steel columns. It is estimated that building was constructed at some time during the 1960s. The approximate total floor area of the building is 220 square metres and is classified as Importance Level 2 Structure according to NZS 1170 Part 0: 2002.

### 2.2 Building Structural Systems Vertical and Horizontal

For the Spencer Park – Amenity Building vertical loads are resisted by the timber framed roof structure. A steel framed ring beam provides central support to a pop up clerestory roof. RHS posts supporting the steel ring rest on concrete masonry walls that divide the central laundry area. Timber rafters radiate out from the central ring beam onto radially oriented concrete masonry walls that form partitions between the toilets and showers.

Horizontal loads from the roof diaphragm are resisted by the concrete masonry walls that form the external perimeter of the building and the radially oriented partition walls that support the roof structure.

### 2.3 Reference Building Type

Originally built in the 1960s, the Spencer Park – Amenity Building is a multi-purpose, concrete masonry wall building. Concrete masonry wall buildings of this era are typically lightly reinforced and partially filled. However, it is important to note that unfilled and unreinforced cells are not uncommon.

Concrete masonry wall buildings have shown a wide range of performances in the Canterbury earthquake sequence. In general, concrete masonry walls of more recent construction have greater reinforcing steel content and higher ratios of concrete filled cells. These walls have shown greater levels of building performance and resilience when compared to their older lightly reinforced, partially



filled counterparts. This is in line with the ethos of the increasingly stringent building codes and standards which have progressively increased the robustness of the present building stock.

Cracking in the mortar joints is particularly common in concrete masonry buildings. This may imply inadequate shear or flexural strength of the concrete masonry walls. With this in mind, there was a particular emphasis on the finding mortar cracks in the damage assessment undertaken on 25 May 2012.

## **2.4 Building Foundation System and Soil Conditions**

The Spencer Park – Amenity Building has a concrete slab on grade foundation. Foundations of this nature are very common and have also been classified as “Type C” foundations in the Department of Building and Housing’s Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence.

The land surrounding the Spencer Park – Amenity Building is classified as “rural and unmapped” according to the DHB Technical Classes dated 23 March 2012. It is of note that the residential property to the immediate East has been classified as “Technical Category 3” or TC3 and according to CERA, “may suffer moderate to significant liquefaction in future significant earthquakes”.

## **2.5 Available Structural Documentation and Inspection Priorities**

Unfortunately, no architectural, structural or geotechnical documentation could be found in the Christchurch City Council Property files for the Spencer Park – Amenity Building. However, the generic nature of the building has allowed the structural performance to be deduced without the aid of this documentation.

The inspection priorities for this report pertain to the review of damage to the building and consideration of the building’s bracing adequacy as well as the out of plane performance of the concrete masonry walls.

## **2.6 Available Survey Information**

A levels survey was undertaken on the building to quantify the level of post-construction subsidence. With allowance for falls to wet areas there was no indication of earthquake induced differential settlement outside acceptable limits.



## 3 Structural Investigation

### 3.1 Summary of Building Damage

The Spencer Park – Amenity Building was in use at the time of the damage assessment. A thorough visual damage assessment has shown;

- Cracking in the concrete foundation pad
- Separation cracking between the radial concrete masonry wall returns and the concrete masonry perimeter wall.

Overall the damage to the Octagon was assessed as minor.

### 3.2 Record of Intrusive Investigation

An intrusive investigation has not been undertaken on the Spencer Park – Amenity Building due to the minor level of damage observed. However there remains a degree of uncertainty in relation to the level of reinforcing and concrete filling in the concrete masonry walls.

An intrusive investigation is recommended to determine the level of robustness and resilience in future earthquake sequences. This will involve drilling through the face shells of the concrete masonry wall to determine the level of reinforcement and grout filled cells. Thus allowing for more accurate predictions the strength and performance of the concrete masonry wall structure.

### 3.3 Damage Discussion

The level of damage observed on the Spencer Park – Amenity Building was minor. However, an intrusive investigation is recommended to better determine the building's seismic performance.

## 4 Building Review Summary

### 4.1 Building Review Statement

Not all of the primary structure of the Spencer Park – Amenity Building was immediately visible. A non-intrusive damage assessment was undertaken under the justification that the damage to brittle non-structural elements, cladding and finishes for the building would indicate the level of damage to the primary structure.

### 4.2 Critical Structural Weaknesses

The critical structural weakness identified for this building was the potential for unreinforced and unfilled concrete masonry which will be determined with the recommended intrusive investigation.

## 5 Building Strength (refer Appendix C for background information)

### 5.1 General

The Spencer Park – Amenity Building was, as discussed above, constructed in the 1960s. Older, unreinforced and unfilled concrete masonry wall buildings of this nature have often suffered damage in the Canterbury earthquake sequence.

### 5.2 Initial %NBS Assessment

The Spencer Park – Amenity Building has not been subject to specific engineering design (SED). Consequently, an Initial Evaluation Procedure (IEP) will not give a useful estimate of building capacity in terms of percentage of new building strength. Nevertheless an estimate of the percentage New Building Strength (%NBS) can be obtained by assuming that the critical performance criteria for the structure is out of plane capacity of the concrete masonry walls and calculating wall capacity in this direction.

Table 1: Parameters used in the Seismic Assessment

Seismic Parameter	Quantity	Comment/Reference
Site Soil Class	D	NZS 1170.5:2004, Clause 3.1.3, Deep or Soft Soil
Site Hazard Factor, $Z$	0.30	DBH Info Sheet on Seismicity Changes (Effective 19 May 2011)
Return period Factor, $R_u$	1.00	NZS 1170.5:2004, Table 3.5

The out of plane performance was found to be 36%NBS. This corresponds of a “moderate risk building” according to NZSEE guidelines. This value was obtained with the assumption that the walls are as they appear to be, unreinforced and unfilled.

### 5.3 Results Discussion

The out of plane analysis was inconsistent with the level of the damage observed in the damage assessment in as much as less damage was evident than the low calculated %NBS value would indicate there should be. This discrepancy is due to the lack of information with regards to the level of shaking experienced by the building and the degree of reinforcing and filling of the concrete masonry cells.

Lack of reinforcement and grout filled cells allows the potential for a rocking mechanism to form in the out of plane direction of the concrete masonry wall. Rocking mechanisms are dangerous as excessive rocking displacements can cause the heavy wall to fail out of plane in a brittle, sudden and dangerous failure mode. Out of plane wall failure has the potential to undermine roof support and this justifies the need for further investigation into wall construction and expected future performance.

## 6 Conclusions and Recommendations

As noted within the body of the report the levels survey has shown that floor levels for the Spencer Park – Amenity Building, given allowance for falls to wet areas, are within tolerable limits.

As only low levels of visible damage were observed in the damage, it is considered that the Spencer Park – Amenity Building is **suitable for continued occupation**.

There remains a degree of uncertainty surrounding the robustness and residual capacity of the concrete masonry walls. Accordingly it is recommended that **an intrusive investigation and a Level 5 Quantitative Detailed Engineering Investigation be undertaken**.

As there is no clear evidence of any liquefaction or ground movement in the vicinity of the Spencer Park – Amenity Building a **geotechnical investigation is currently not considered necessary**.

## 7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

To carry out the structural review, existing building drawings were obtained from the Christchurch City Council records. We have assumed that the building has been constructed in accordance with the drawings.

While this report may assist the client in assessing whether the building should be strengthened, that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.


# Appendices



# Appendix A

## Site Map, Photos and Levels Survey


Site photographs (25 May 2012)



Western elevation of the Spencer Park – Amenity Building.




Cracking in the concrete floor by the shower area.



Plan view of the crack in the concrete floor – approximately 1.5 mm wide.



Side view of the crack in the concrete floor.



Interior view of the Octagon – pop up roof held up by steel square hollow sections.



Steel square hollow sections are founded on waist-high concrete masonry walls.



Cracking in the interior roof linings.




Cracking in the joints of the concrete slab.




Weep holes at the foot concrete masonry walls indicating that the walls are unfilled and un-grouted.



Corner detail of the concrete masonry wall.



Client: CHCH CITY COUNCIL	Date: 5-6-12
Project/Job: S.P.C.G. OCTAGON	Job No: 228604
Subject: LEVELS SURVEY RESULTS (SKETCH)	Sheet No: A By: CB



SCALE: APPROX 1:100

# Appendix B

## References

1. Standards New Zealand, "AS/NZS 1170 Part 0, Structural Design Actions: General Principles", 2002
2. Standards New Zealand, "AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions", 2002
3. Standards New Zealand, "NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand", 2004
4. Standards New Zealand, "NZS 3101:2006, Concrete Structures Standard"
5. Standards New Zealand, "NZS 3404:1997, Steel Structures Standard"
6. Standards New Zealand, "NZS 3604:2011: Timber Framed Structures"
7. Standards New Zealand, "NZS 4229:1999, Concrete Masonry Buildings Not Requiring Specific Design"
8. Standards New Zealand, "NZS 4230:2004, Design of Reinforced Concrete Masonry Structures"
9. New Zealand Society for Earthquake Engineering (NZSEE), "Assessment and Improvement of the Structural Performance of Buildings in Earthquakes, June 2006"
10. Engineering Advisory Group, "Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-Residential Buildings in Canterbury. Part 2 Evaluation Procedure. Revision 5, 19 July 2011"

# Appendix C

## Strength Assessment Explanation

### New Building Standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

### Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

### Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

### Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22<sup>nd</sup> February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

# Appendix D

## Background and Legal Framework

### Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.

### Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage

- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

## Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

### **Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

# Appendix E

## Standard Reporting Spread Sheet

Detailed Engineering Evaluation Summary Data

V1.11

<b>Location</b>		Building Name: <u>Spencer Park - Amenity Building</u>	Unit No: <u>Street</u>	Reviewer: <u>Lee Howard</u>
Building Address: <u>Spencer Park Camping Ground</u>		100 Heyders Road		CPEng No: <u>1008889</u>
Legal Description: <u>Lot 1 DP 44484</u>				Company: <u>Aurecon</u>
				Company project number: <u>228604</u>
				Company phone number: <u>03 375 0761</u>
GPS south: <u>43</u>		Degrees	Min	Sec
GPS east: <u>172</u>		<u>26</u>		<u>17.14</u>
				Date of submission: <u>17-Oct-13</u>
				Inspection Date: <u>25-May-12</u>
				Revision: <u>3</u>
Building Unique Identifier (CCI): <u>PRO_0157_B009</u>				Is there a full report with this summary? <u>yes</u>

<b>Site</b>		Site slope: <u>flat</u>	Max retaining height (m): <u></u>
Soil type: <u>mixed</u>		Soil Profile (if available): <u></u>	
Site Class (to NZS1170.5): <u>D</u>		If Ground improvement on site, describe: <u></u>	
Proximity to waterway (m, if <100m): <u></u>			
Proximity to cliff top (m, if <100m): <u></u>			
Proximity to cliff base (m, if <100m): <u></u>			
		Approx site elevation (m): <u>1.00</u>	

<b>Building</b>		No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>1.00</u>
Ground floor split?: <u>0</u>		Stores below ground: <u>0</u>		Ground floor elevation above ground (m): <u>0.00</u>
Foundation type: <u>strip footings</u>		Building height (m): <u>3.00</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>3</u>	If Foundation type is other, describe: <u></u>
Floor footprint area (approx): <u>286</u>		Age of Building (years): <u>32</u>		Date of design: <u>1976-1992</u>
Strengthening present?: <u>no</u>				If so, when (year)? <u></u>
Use (ground floor): <u>public</u>				And what load level (%g)? <u></u>
Use (upper floors): <u></u>				Brief strengthening description: <u></u>
Use notes (if required): <u></u>				
Importance level (to NZS1170.5): <u>IL2</u>				

<b>Gravity Structure</b>		Gravity System: <u>load bearing walls</u>	rafter type, purlin type and cladding: <u></u>
Roof: <u>timber framed</u>		Floors: <u>concrete flat slab</u>	slab thickness (mm): <u></u>
Beams: <u>timber</u>		Columns: <u>timber</u>	type: <u></u>
Walls: <u>partially filled concrete masonry</u>			typical dimensions (mm x mm): <u></u>
			thickness (mm): <u>140</u>

<b>Lateral load resisting structure</b>		Lateral system along: <u>partially filled CMU</u>	Ductility assumed, $\mu$ : <u>1.25</u>	Period along: <u>0.40</u>	maximum interstorey deflection (ULS) (mm): <u></u>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <u></u>	wall thickness (m): <u></u>	estimate or calculation?: <u>estimated</u>
Lateral system across: <u>partially filled CMU</u>		Ductility assumed, $\mu$ : <u>1.25</u>	Period across: <u>0.40</u>	maximum interstorey deflection (ULS) (mm): <u></u>			note total length of wall at ground (m): <u></u>	wall thickness (m): <u></u>	estimate or calculation?: <u>estimated</u>

<b>Separations:</b>		north (mm): <u></u>	east (mm): <u></u>	south (mm): <u></u>	west (mm): <u></u>	leave blank if not relevant
---------------------	--	---------------------	--------------------	---------------------	--------------------	-----------------------------

<b>Non-structural elements</b>		Stairs: <u>exposed structure</u>	describe: <u>none</u>
Wall cladding: <u>metal</u>		describe: <u>corrugated iron</u>	
Roof Cladding: <u>metal</u>		describe: <u>none</u>	
Ceilings: <u>plaster, fixed</u>		describe: <u>none</u>	
Services (list): <u></u>			

<b>Available documentation</b>		Architectural: <u>partial</u>	original designer name/date: <u></u>
Structural: <u>partial</u>		Mechanical: <u>none</u>	original designer name/date: <u></u>
Electrical: <u>none</u>		original designer name/date: <u></u>	
Geotech report: <u>none</u>		original designer name/date: <u></u>	

<b>Damage</b>		Site performance: <u>Good</u>	Describe damage: <u></u>
Settlement: <u>none observed</u>		Differential settlement: <u>none observed</u>	notes (if applicable): <u></u>
Liquefaction: <u>none apparent</u>		Lateral Spread: <u>none apparent</u>	notes (if applicable): <u></u>
Differential lateral spread: <u>none apparent</u>		Ground cracks: <u>none apparent</u>	notes (if applicable): <u></u>
Damage to area: <u>none apparent</u>			notes (if applicable): <u></u>

<b>Building:</b>		Current Placard Status: <u>green</u>	
Along		Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: <u>Minimal Damage</u>
Across		Damage ratio: <u>0%</u>	$Damage\_Ratio = \frac{(\%NBS\ before) - (\%NBS\ after)}{\%NBS\ before}$
Diaphragms		Damage?: <u>no</u>	Describe: <u></u>
CSWs:		Damage?: <u>no</u>	Describe: <u></u>
Pounding:		Damage?: <u>no</u>	Describe: <u></u>
Non-structural:		Damage?: <u>no</u>	Describe: <u></u>

<b>Recommendations</b>		Level of repair/strengthening required: <u>none</u>	Describe: <u></u>
Building Consent required: <u>no</u>		Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u></u>
Along		Assessed %NBS before: <u>72%</u>	Assessed %NBS after: <u>72%</u>
Across		Assessed %NBS before: <u>72%</u>	Assessed %NBS after: <u>72%</u>

<b>IEP</b>		Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.	
Period of design of building (from above): <u>1976-1992</u>		$h_n$ from above: <u>3m</u>	
Seismic Zone, if designed between 1965 and 1992: <u>B</u>		not required for this age of building	
Period (from above): <u>0.4</u>		along	
(%NBS)norm from Fig 3.3:		across	
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0		Note 2: for RC buildings designed between 1976-1984, use 1.2	
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)			
Final (%NBS)norm:		along	
		across	
		<u>0%</u>	
		<u>0%</u>	

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), Factor A:  along  across  
#DIV/0! #DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:   
Z<sub>1992</sub>, from NZS4203:1992   
Hazard scaling factor, Factor B:  #DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above):  2  
Return Period Scaling factor from Table 3.1, Factor C:

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)  along  across  
Ductility scaling factor: =1 from 1976 onwards; or =k<sub>μ</sub>, if pre-1976, from Table 3.3:

Ductility Scaling Factor, Factor D:  1.00  1.00

2.6 Structural Performance Scaling Factor:

Sp:   
Structural Performance Scaling Factor Factor E:  #DIV/0!  #DIV/0!

2.7 Baseline %NBS, (NBS%)<sub>b</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E

%NBS<sub>b</sub>:  #DIV/0!  #DIV/0!

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:  insignificant  1

3.2. Vertical irregularity, Factor B:  insignificant  1

3.3. Short columns, Factor C:  insignificant  1

3.4. Pounding potential  
Pounding effect D1, from Table to right  1.0  
Height Difference effect D2, from Table to right  1.0

Therefore, Factor D:  1

3.5. Site Characteristics  significant  0.7

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	0.7	0.8
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	0.4	0.7
Height difference > 4 storeys	0.7	0.9	1
Height difference 2 to 4 storeys	1	1	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum  
Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any:  Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.00  0.00

4.3 PAR x (%NBS)<sub>b</sub>:

PAR x Baseline %NBS:  #DIV/0!  #DIV/0!

4.4 Percentage New Building Standard (%NBS), (before)

#DIV/0!

Official Use only:

Accepted By:   
Date:



**Aurecon New Zealand Limited**

**Level 2, 518 Colombo Street  
Christchurch 8011**

PO Box 1061  
Christchurch 8140  
New Zealand

**T** +64 3 375 0761

**F** +64 3 379 6955

**E** [christchurch@aurecongroup.com](mailto:christchurch@aurecongroup.com)

**W** [aurecongroup.com](http://aurecongroup.com)

Aurecon offices are located in:

Angola, Australia, Botswana, China,  
Ethiopia, Hong Kong, Indonesia,  
Lesotho, Libya, Malawi, Mozambique,  
Namibia, New Zealand, Nigeria,  
Philippines, Singapore, South Africa,  
Swaziland, Tanzania, Thailand, Uganda,  
United Arab Emirates, Vietnam.