



*Christchurch City Council*

**Sumner Beach Toilets**  
**PRK 1474 BLDG 009 EQ2**

**Detailed Engineering Evaluation**

**Quantitative Assessment Report**





*Christchurch City Council*

---

# Sumner Beach Toilets

## Quantitative Assessment Report

**Marriner Street, Sumner**

Prepared By

Tahu Taylor-Koolen  
Senior Structural Engineer

Reviewed By

Dave Dekker  
Senior Structural Engineer  
MIPENZ, CPEng 1003026

Approved By

Dave Dekker  
Senior Structural Engineer  
MIPENZ, CPEng 1003026

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail  
Centre, Christchurch 8140  
New Zealand

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: February 2013  
Reference: 6-QUCC1.75  
Status: Final

# Summary

Sumner Beach Toilets  
PRK 1474 BLDG 009 EQ2

Detailed Engineering Evaluation  
Quantitative Report - Summary  
Final

## **Background**

This is a summary of the quantitative report for the Sumner Beach Public Toilets, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 20 March 2012 and calculations.

## **Key Damage Observed**

No seismic damage was identified at the time of inspection.

## **Critical Structural Weaknesses**

No potential critical structural weaknesses have been identified.

## **Indicative Building Strength**

Based on the information available, and from undertaking a quantitative assessment, the building's original capacity has been assessed to be in the order of at least 100% NBS and is therefore classified as a low risk building.

## **Recommendations**

The building complies with current standards and no further action is required, although repairs to the cosmetic damage could be considered.

# Contents

<b>Summary .....</b>	<b>i</b>
<b>1 Introduction.....</b>	<b>1</b>
<b>2 Compliance .....</b>	<b>1</b>
<b>3 Earthquake Resistance Standards.....</b>	<b>4</b>
<b>4 Background Information.....</b>	<b>7</b>
<b>5 Detailed Seismic Assessment .....</b>	<b>7</b>
<b>6 Summary of Geotechnical Appraisal .....</b>	<b>9</b>
<b>7 Conclusions.....</b>	<b>9</b>
<b>8 Recommendations .....</b>	<b>9</b>
<b>9 Limitations.....</b>	<b>9</b>
<b>10 References .....</b>	<b>9</b>

## Appendix 1: PHOTOGRAPHS

## Appendix 2: CONSTRUCTION DRAWINGS

## Appendix 3: GEOTECHNICAL APPRAISAL

## Appendix 4: CERA DEE SPREADSHEET

# 1 Introduction

Opus International Consultants Limited (Opus) has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Sumner Beach Toilets located at Marriner Street, Sumner, Christchurch, following the M6.3 Christchurch earthquake on 22 February 2011.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [3] [4].

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

### Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].



A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

### 3.1.1 Occupancy

The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### 3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

### 3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### 3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

## 4 Background Information

### 4.1 Building Description

The Sumner Beach Toilets are located at the corner of Marriner Street and the Esplanade, Sumner, Christchurch. The construction drawings are dated May 2003 and it is assumed construction occurred the same year. The toilets contain two similar cubicles. The walls are constructed of 20 series stacker bond reinforced masonry block, solid filled, reinforced with D12 at 600mm spacing in both directions and supported on shallow strip footings. The floor is 100mm thick concrete slab-on-grade reinforced with 665 mesh. The roof is timber framed with 21mm plywood and butynol rubber.

### 4.2 Inspection

An inspection of the site was completed by Opus International Consultants on 12 July 2012. The building has suffered little visible damage. The only damage visible is minor spalling of the plaster finish at the base of the wall and cracking of the mortar around the small windows.

### 4.3 Original Documentation

Copies of the following construction drawings were provided by CCC:

- » Structural drawings 562/935 Sheets A01, A02 and A03; titled Marriner Street Public Toilets Changing Rooms & Wash Down; dated 27.05.03.

The drawings are included in Appendix 2. The assessment has been based on these drawings.

## 5 Detailed Seismic Assessment

The detailed seismic assessment has been based on the current codes NZS 1170 [1] and NZS 4230 [6].

### 5.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No critical structural weaknesses were identified for this building.

### 5.2 Quantitative Assessment Methodology

Static analysis was carried out using the spectral values established from NZS1170.5, with an updated Z factor of 0.3 (B1/VM1). These analyses were used to establish the actions on the structural elements. Based on the actions determined from the analysis a comparison with the building capacities was made.

### 5.3 Seismic Loads

Seismic loads have been calculated in accordance with NZS1170.5 [1].

The NZS1170.5 seismic parameters for the site were as listed below.

Soil Category:	D (deep soil)
Spectral shape factor $C_h$ :	3.0
Importance Level:	2
Return period factor R:	1.0 (500 year)
Hazard factor Z:	0.30
Near fault factor N:	1.0
Elastic site hazard spectrum for horizontal loading	0.90g

### 7.6 Assessment

A summary of the structural performance of the building is shown in the following table.

**Table 2: Summary of Seismic Performance,  $\mu = 1.25$**

Structural Element/System	Comments	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Roof	The light weight timber frame and plywood will act as a diaphragm. The roof is not assumed to resist any loads except to brace to the top of the two columns.	None	>100%
Walls	The walls will act to resist the lateral seismic loads in both directions through in-plane shear. The walls must resist out-of-plane bending resulting from self-weight. The critical aspect ratio for these is 1:1.25, thus they act as two-way slabs.	None	>100%
Slab-on-grade	The slab-on-grade must resist any tension forces and bending moments transferred from the walls.	None	>100%
Columns	These must resist their own self-weight.	None	>100%

The building has a calculated seismic capacity of greater than 100%NBS and is therefore classed as a low risk building in accordance with NZSEE guidelines.

## 6 Summary of Geotechnical Appraisal

A site walkover by a geotechnical engineer was undertaken on 17 August 2012 and a geotechnical desktop study has been completed (refer Appendix 3). Minor land damage has occurred at this site as a result of the Canterbury Earthquake sequence following the September 2010 earthquake.

Potential for ground damage, from liquefaction, is moderate for this site, indicating that the ground may be affected by between 100 – 300mm of subsidence. The Sumner Beach Toilets site is bounded by residential properties located in the CERA “green” zone.

Some 5 – 10mm cracks were observed in the nearby asphalted footpaths, concrete walkway and wall.

## 7 Conclusions

Calculations confirm that the building has a capacity of over 100% NBS and is therefore classed as a low risk building. The toilets are less than ten years old, performed well in the recent earthquakes and have only very minor cosmetic damage evident.

The liquefaction ground damage potential for this site is considered moderate for future seismic events.

## 8 Recommendations

The building complies with current standards and no further action is required, although repairs to the cosmetic damage could be considered.

## 9 Limitations

- a) This report is based on an inspection of the building and focuses on the structural damage resulting from the 22 February Canterbury Earthquake and aftershocks only. Some non-structural damage is noted but this is not intended to be a complete list of damage to non-structural items.
- b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- c) This report is prepared for CCC to assist with assessing the remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

## 10 References

- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.

- 
- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
  - [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
  - [5] SESOC, *Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes*, Structural Engineering Society of New Zealand, 21 December 2011.
  - [6] NZS 4230: 2004, *Design of Reinforced Concrete Masonry Structures*, Standards New Zealand.

## Appendix 1: PHOTOGRAPHS

## Sumner Beach Toilets – Detailed Engineering Evaluation

---



Photo 1: North-East view of Sumner Beach Toilets



Photo 2: North Wall Elevation



**Summer Beach Toilets – Detailed Engineering Evaluation**

---



Photo 3: East Wall Elevation  
(wash down area)




Photo 4: South Wall Elevation



Photo 5: East Toilet Cubicle (West similar)


## **Appendix 2: CONSTRUCTION DRAWINGS**

# Sumner Beach Toilets – Detailed Engineering Evaluation



	DATE: 01/18/13 DESIGNED: D. J. O'SHEA CHECKED: D. J. O'SHEA DRAWN: M. J. O'SHEA CONSULTANT: D. J. O'SHEA	APPROVED: [Signature] DATE: 01/18/13	CLIENT: CHRISTCHURCH CITY COUNCIL - PARKS & WATERWAYS	PROJECT TITLE: •Marriner Street Public Toilets Changing Rooms & Wash Down •Wash Down At Cave Rock - Sumner	DRAWING TITLE: Reinforcing Elevations Site / Service Plan Construction Details	CONTRACT NUMBER: 02/03-273 ORIGINAL DATE: 02/03 FILE NUMBER: AD-0159-02 DRAWING & PROJECT NUMBER: 562/935	SCALE: A1 AS SHOWN SHEET: A01 of A04
	© COPYRIGHT 2013 CHRISTCHURCH CITY COUNCIL. ALL RIGHTS RESERVED.					CONTRACTOR: [Name] DESIGNER: [Name]	

# Sumner Beach Toilets – Detailed Engineering Evaluation



DATE	NAME	DESIGN DATE	APPROVED
02/03/23	D. S. Smith	02/03/23	[Signature]
02/03/23	D. S. Smith	02/03/23	[Signature]
02/03/23	D. S. Smith	02/03/23	[Signature]
02/03/23	D. S. Smith	02/03/23	[Signature]




PROJECT TITLE: •Marriner Street Public Toilets Changing Rooms & Wash Down •Wash Down At Cave Rock - Sumner

DRAWING TITLE: Plan, Cross Sections Construction Details

CONTRACT NUMBER: 02/03-273	ORIGINAL SHEET: A1	SCALE: As Shown
FILE NUMBER: AD-0159-02	DRAWING & PROJECT NUMBER: 562/935	SHEET: A02 of A04

# Sumner Beach Toilets – Detailed Engineering Evaluation



DATE	NAME	SIGNED	DATE	APPROVED	CLIENT
2019/06/06	DESIGNED	[Signature]	02/03/2019	[Signature]	CHRISTCHURCH CITY COUNCIL - PAVES & WATERWAYS
2019/06/06	CHECKED	[Signature]	02/03/2019	[Signature]	
2019/06/06	DRAWN	[Signature]	02/03/2019	[Signature]	
2019/06/06	CONTR. BY	[Signature]	02/03/2019	[Signature]	



PROJECT TITLE: •Marriner Street Public Toilets Changing Rooms & Wash Down •Wash Down At Cave Rock - Sumner

DRAWING TITLE: Elevations Construction Details

DATE	NO.	BY	DATE	SCALE
02/03/2019	01	[Signature]	02/03/2019	As Shown
AD-0159-02				562/935 A03 OF A04

## **Appendix 3: GEOTECHNICAL APPRAISAL**

12 February 2013

Christchurch City Council  
C/O:- Michael Sheffield  
Property Asset Manager



6-QUCC1.75/005SC

Dear Michael

## **Geotechnical Desktop Study – Sumner Beach Toilets**

### **1. Introduction**

Christchurch City Council (CCC) has commissioned Opus International Consultants (Opus) to undertake a geotechnical desktop study and site walkover of the Sumner Beach Toilets located on the Esplanade, Christchurch. The purpose of this study is to collate existing subsoil information and undertake an appraisal of the potential geotechnical hazards at this site and to determine whether further investigations are required. The site walkover was completed by Opus on 17 August 2012. Refer to Appendix A for site photos.

This Geotechnical Desk Study has been prepared in accordance with the Engineering Advisory Group's Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Revision 5, 19 July 2011.

It is our understanding that this is the first geotechnical inspection of this property and forms part of a Detailed Engineering Evaluation prepared by Opus.

This geotechnical desk study has been undertaken without the benefit of any site specific investigations and is therefore preliminary in nature.

### **2. Desktop Study**

#### **2.1 Site Description**

The Sumner Beach Toilets is located close to the intersection of Marriner St and Esplanade, Richmond, Christchurch, and surrounded with shrubs plants to the south and west elevations, asphalted/concreted paths to the north and the beach and promenade to the east. The toilet is a single storey structure and is comprised of 20 series stacker bond reinforced concrete block walls filled with 20MPa block grout, resting on 30MPa reinforced concrete foundation walls and concrete slab on compacted AP40 backfill.

The building was designed in 2003 for CCC by City Solutions.

The ground profile is relatively flat and approximately level with the road.

## 2.2 Structural Drawings

Structural drawings showing plan, cross-section and elevation construction details have been available for review and are appended in Appendix D. The drawings indicated a 30MPa 130mm reinforced concrete floor slab reducing to 100mm on the edge on a 345mm AP40 hard fill, compacted in layers. The concrete perimeter foundations are a minimum of 345mm below ground level (bgl) and 225mm wide with central foundation being 270mm wide.

## 2.3 Regional Geology

The published geological map of the area, (Geology of the Christchurch Urban Area 1:25,000, Brown and Weeber, 1992) indicates the site is underlain by the Christchurch Formation with dominantly sand of fixed and semi-fixed dunes and beaches.

## 2.4 Expected Ground Conditions

A review of the Environmental Canterbury (ECan) wells database showed eleven wells located within approximately 270m of the Sumner Beach Toilets (refer to Site Location Plan in Appendix B). All ECan wells are shallow, maximum depth of only 4.2m bgl. It must be noted that the ground conditions of this area are variable; two of the eleven ECan wells indicate rock at 2m bgl and 300m to the north-west an approximately 10m high bedrock sea stack is located.

Material logs available from the wells have been used to infer the ground conditions at the site as shown in Table 1 below.

**Table 1: Inferred Ground Conditions**

Stratigraphy	Thickness (m)	Depth Encountered From (m)
FILL (brown sandy GRAVEL)	0.5 – 2m	Surface
SAND (grey, fine to coarse)	>4.2	Surface – 0.5m

An indication of the relative density of the sand layers has not been included in the well logs.

The Brown and Weeber “Geology of the Christchurch Urban Area” map suggests a water table less than 1m bgl.

## 2.5 Liquefaction Hazard

A liquefaction hazard study was conducted by the Canterbury Regional Council (ECan) in 2004 to identify areas of Christchurch susceptible to liquefaction during an earthquake. The Sumner Beach Toilets is located in an area identified as ‘moderate liquefaction ground damage potential’ for a low groundwater scenario. According to this study, the ground damage potential is moderate, indicating the ground may be affected by between 100 and 300mm of subsidence.

Tonkin and Taylor Ltd (T&T Ltd) have been engaged as the Earthquake Commission’s (EQC) geotechnical consultants and have prepared maps showing areas of liquefaction interpreted from high resolution aerial photos for the 4 September 2010 earthquake, and the aftershocks of February 2011 and June 2011. An interpretation of these maps indicates there was liquefaction in the Sumner area but none within the vicinity of the Sumner Beach Toilets.



Sumner Beach Toilets is bounded by residential properties located in the CERA “green” zone. The “green” zone has been further categorised into technical categories by the Department of Building and Housing (DBH). This site has been identified as “Technical Category 2” (TC2) released in October 2011. The DBH technical categories are guidelines for residential foundations, however are likely to be used as a guideline by the Christchurch City Council for building consent. TC2 identifies the area may be subject to minor to moderate land damage from liquefaction in future large earthquakes.

### **3. Site Walkover Inspection**

A walkover inspection of the exterior and interior was carried out by an Opus Geotechnical Engineer on 17 August 2012. The following observations were made (refer to Appendix A for Site Photos and Appendix C for the Site Walkover Plan):

- 5mm crack on the 20mm solid plaster of concrete on south side of building. Refer to Photograph 5.
- Some minor cracking (2mm wide hairline crack) on concrete slab on the wash down area, east elevation of the building. Refer to Photograph 6 in Appendix A.
- 2mm hairline crack on the concrete floor of the toilets. Refer to Photograph 7a and 7b in Appendix A.
- An approximate 5mm wide cracks around the right most 300mm x 300mm concrete column, cracks radiating outward the 20mm asphalt paving. Asphalt ground lifted roughly 5mm. Refer to Photograph 8 in Appendix A.
- Minor 5mm wide cracks on the asphalted footpath north of the toilets. Refer to Appendix C -Site Walkover Plan, Photograph 9.
- 10mm wide cracks from the top to base of the concrete wall separating the toilets from the promenade. This is also accompanied by a lift and subsidence of approximately 10mm as indicated by the arrows. Refer to Appendix C -Site Walkover Plan, Photograph 10.
- Small ground heave within 5mm to 10mm at the bottom of the concrete wall with estimated 10mm wide cracks separating bottom of wall and paved ground. Refer to Appendix C -Site Walkover Plan, Photograph 11.
- Approximately 10mm to 15mm wide cracks on the concrete walkway, north of the toilets, leading toward the promenade. Refer to Appendix C -Site Walkover Plan, Photograph 12.

### **4. Discussion**

Minor land damage has occurred at the Sumner Beach Toilet due to the Canterbury Earthquake Sequence following the 4 September 2010 earthquake.

The cracks in the paved areas (concreted/asphalted) outside the beach toilets, cracks on the solid plaster on the perimeter foundation and hairline cracks on the toilets’ floor slab and damaged areas on the wall separating the toilets and the promenade (e.g. cracks and lifts) are considered minor.

Cracks in the solid plaster on the east elevation of the toilet could not be observed in the perimeter footing, possibly shallow. There is no evidence of liquefaction at the site.

The hairline cracks in the toilets' floor slab appear to be negligible and have the no potential to affect the structural integrity of the building and its performance in future earthquakes.

ECan well logs indicate the building is likely to be founded on a capping of fill overlying sand to a depth of at least 4.2m bgl. The foundation system of a perimeter strip footing with a concrete slab on hard fill seem to have performed well for the majority of the building. However, CCC will have to accept that in future seismic events there is a risk of minor differential settlement.

GNS Science<sup>1</sup> indicates an elevated risk of seismic activity is expected in the Canterbury region as a result of the earthquake sequence following the 4 September 2010 earthquake. Recent advice (Geonet) indicates there is a 12% probability of another Magnitude 6 or greater earthquake occurring in the next 12 months in the Canterbury region. It is expected that the probability of occurrence is likely to decrease with time, following periods of reduced seismic activity. However, we would expect that similar ground damage could occur in a future earthquake, dependent on the location of the epicentre.

## **5. Recommendations**

The existing concrete perimeter slab foundations appear to have performed reasonably well and are considered suitable.

No further geotechnical investigations are recommended.

## **6. Limitation**

This report has been prepared solely for the benefit of CCC as our client with respect to the brief. The reliance by other parties on the information or opinions contained in the report shall, without our prior review and agreement in writing, be at such parties' sole risk.

It is recognised that the passage of time affects the information and assessment provided in this Document. The recommendations formed in this report are based upon the information that existed at the time of production of the Desktop Study. It is understood that the services provided allowed Opus to form no more than an opinion on the actual conditions of the site at the time the site was visited and cannot be used to assess the effect of any subsequent changes in the quality of the site, or its surroundings or any laws or regulations.

## **7. References:**

Brown, LJ; Webber, JH 1992: Geology of the Christchurch Urban Area. Scale 1:25,000. Institute of Geological and Nuclear Sciences geological map, 1 sheet + 104p.

---

<sup>1</sup> GNS Science reporting on Geonet Website: <http://www.geonet.org.nz/canterbury-quakes/aftershocks/> updated on 22 January 2013.

Environment Canterbury, Canterbury Regional Council (ECan) website:

ECan Well Card

<http://ecan.govt.nz/services/online-services/tools-calculators/Pages/well-card.aspx>

ECan 2004: The Solid Facts on Christchurch Liquefaction. Canterbury Regional Council, Christchurch, 1 sheet.

Project Orbit, 2011: interagency/organisation collaboration portal for Christchurch recovery effort. <https://canterburyrecovery.projectorbit.com/SitePages/Home.aspx>

Appendices:

Appendix A: Site Photos

Appendix B: Site Location Plan and ECan Well Logs

Appendix C: Site Walkover Plan

Appendix D: Structural Drawings

# APPENDIX A:

## Site Photos



**Photograph 1: North Elevation of Sumner Beach Toilet.**




**Photograph 2: South Elevation of Sumner Beach Toilet.**




**Photograph 3: East Elevation of Sumner Beach Toilet.**



**Photograph 4: West Elevation of Sumner Beach Toilet.**



**Photograph 5: 5mm crack on the 20mm solid plaster of concrete on south side of building.**



**Photograph 6: Some minor cracking (2mm wide hairline crack) on wash down area (east elevation).**




**Photograph 7a: 2mm wide cracks floor slab inside the toilets.**



**Photograph 7b: 2mm wide cracks floor slab inside the toilets.**





**Photograph 8: Approximate 5mm wide shallow cracks around the right most 300mm x 300mm concrete column, cracks radiating outward the 20mm asphalt paving. Asphalt ground lifted 5mm.**

# **APPENDIX B:**

Site Location Plan  
ECan Well Logs



SOURCE: canterburyrecovery.projectorbit.com (Accessed on 17/08/12)



Opus International Consultants Ltd  
 Christchurch Office  
 20 Moorhouse Ave  
 PO Box 1482  
 Christchurch, New Zealand  
 Tel: +64 3 363 5400 Fax: +64 3 365 7857


**Project:** CCC- Sumner Beach Toilets  
 Geotechnical Desktop Study  
**Project No.:** 6-QUCC1.75  
**Client:** Christchurch City Council

### Site Location Plan

**Date:** 17/09/2012  
**Drawn By:** Opus Geotechnical Engineer


# Borelog for well N36/0219

Gridref: N36:90467-37609 Accuracy : 3 (1=high, 5=low)  
 Ground Level Altitude : 13 +MSD  
 Well name : CCC BorelogID 7315  
 Drill Method : Not Recorded  
 Drill Depth : -2m Drill Date : 6/12/2005




# Borelog for well N36/0218

Gridref: N36:90491-37621 Accuracy : 3 (1=high, 5=low)  
 Ground Level Altitude : 13 +MSD  
 Well name : CCC BorelogID 7314  
 Drill Method : Not Recorded  
 Drill Depth : -1.9m Drill Date : 6/12/2005



# Borelog for well N36/0246

Gridref: N36:90532-37533 Accuracy : 2 (1=high, 5=low)  
 Ground Level Altitude : 1 +MSD  
 Driller : McMillan Water Wells Ltd  
 Drill Method : Rotary Rig  
 Drill Depth : -4.2m Drill Date : 2/04/2009



# Borelog for well N36/0039


Gridref: N36:905-375 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 4.2 +MSD

Driller : Canterbury Drilling Company

Drill Method : Auger Rig

Drill Depth : -2m Drill Date : 17/05/1994



# Borelog for well N36/0040


Gridref: N36:905-375 Accuracy : 4 (1=best, 4=worst)

Ground Level Altitude : 4.2 +MSD

Driller : Canterbury Drilling Company

Drill Method : Auger Rig


Drill Depth : -4m Drill Date : 15/05/1994






# Borelog for well N36/0041

Gridref: N36:905-375 Accuracy : 4 (1=best, 4=worst)  
Ground Level Altitude : 4.2 +MSD  
Driller : Canterbury Drilling Company  
Drill Method : Auger Rig  
Drill Depth : -3.5m Drill Date : 17/05/1994



# Borelog for well N36/0084

Gridref: N36:90525-37488 Accuracy : 2 (1=high, 5=low)  
Ground Level Altitude : 11 +MSD  
Driller : C W Drilling and Investigations Ltd  
Drill Method : Push Tube  
Drill Depth : -4m Drill Date : 20/10/2005



# Borelog for well N36/0085


Gridref: N36:90531-37489 Accuracy : 4 (1=high, 5=low)

Ground Level Altitude : 11 +MSD

Driller : C W Drilling and Investigations Ltd


Drill Method : Rotary Rig

Drill Depth : -4m Drill Date : 20/10/2005




# Borelog for well N36/0247

Gridref: N36:90542-37551 Accuracy : 2 (1=high, 5=low)  
 Ground Level Altitude : 1 +MSD  
 Driller : McMillan Water Wells Ltd  
 Drill Method : Rotary Rig  
 Drill Depth : -4.2m Drill Date : 3/04/2009



# Borelog for well N36/0248

Gridref: N36:90552-37553 Accuracy : 2 (1=high, 5=low)  
 Ground Level Altitude : 1 +MSD  
 Driller : McMillan Water Wells Ltd  
 Drill Method : Rotary Rig  
 Drill Depth : -4.2m Drill Date : 2/04/2009



# Borelog for well N36/0086


Gridref: N36:90552-37496 Accuracy : 2 (1=high, 5=low)

Ground Level Altitude : 10 +MSD

Driller : C W Drilling and Investigations Ltd


Drill Method : Rotary Rig

Drill Depth : -3m Drill Date : 20/10/2005



# **APPENDIX C:**



## Site Walkover Plan




Photograph 12



Photograph 11



Photograph 9



Photograph 10

SOURCE: [canterburyrecovery.projectorbit.com](http://canterburyrecovery.projectorbit.com) (Accessed on 17/09/12)



Opus International Consultants Ltd  
 Christchurch Office  
 20 Moorhouse Ave  
 PO Box 1482  
 Christchurch, New Zealand  
 Tel: +64 3 363 5400 Fax: +64 3 365 7857

**Project:** CCC- Sumner Bear Toilets  
 Geotechnical Desktop Study  
**Project No.:** 6-QUCC1.75  
**Client:** Christchurch City Council

### Site Walkover Plan


**Date:** 17/09/2012  
**Drawn by:** Opus Geotechnical Engineer




# **APPENDIX D:**

## Structural Drawings


PREPARED BY CIVIL ENGINEERS DRAWING 43 BUSINESS UNIT WITH THE ARCHITECTURE DIVISION




Top Section  
Cross Section  
DETAILS 2 FALSE VENT COVER  
SCALE 1:10




FRONT ELEVATION  
SCALE 1:10




WEST ELEVATION  
SCALE 1:10








EAST ELEVATION  
SCALE 1:10



SOUTH ELEVATION  
SCALE 1:10




NORTH ELEVATION  
SCALE 1:10



CONTRACT NUMBER	02/03/273	DATE	17.03.03
FILE NUMBER	AD-0159-02	SCALE	AS SHOWN
DRAWING & PROJECT NUMBER	562/935	SHEET	A03 OF A04

PROJECT TITLE  
**Elevations Construction Details**

•Marriner Street Public Toilets  
Changing Rooms & Wash Down  
•Wash Down At Cave Rock - Summer












DATE	BY	REVISION
17.03.03	AD	ISSUED FOR TENDER
17.03.03	AD	ISSUED FOR TENDER
17.03.03	AD	ISSUED FOR TENDER
17.03.03	AD	ISSUED FOR TENDER
17.03.03	AD	ISSUED FOR TENDER

**CITY SOLUTIONS**

APPROVED  
DATE 07/04/03  
SIGNED  
SIGNED  
SIGNED  
SIGNED  
SIGNED  
SIGNED

TERMINAL INTERNATIONAL LIMITED



<b>CITY SOLUTIONS</b> PREPARED BY CITY SOLUTIONS OPERATING AS A BUSINESS UNIT WITH THE CHRISTCHURCH CITY COUNCIL		<b>CHRISTCHURCH</b> CITY COUNCIL, PARS 1 & WATERWAY	
CONTRACT NUMBER: 02/03-273 PROJECT NUMBER: AD-0169-02 DRAWING PROJECT NUMBER: 5627/935		PROJECT TITLE: <b>Marriner Street Public Toilets Changing Rooms &amp; Wash Down</b> <b>Wash Down At Cave Rock - Summer</b>	
DRAWING TITLE: Plan, Cross Sections Construction Details		SCALE: As Shown SHEET: A02 OF A04	
DATE: 8/19/13 DRAWN BY: [Signature] CHECKED BY: [Signature] APPROVED BY: [Signature]	DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13	DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13	DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13 DATE: 8/19/13



## **Appendix 4: CERA DEE SPREADSHEET**

<b>Location</b>		Building Name: <input type="text" value="Sumner Beach Toilets"/>	Unit No: <input type="text"/>	Street: <input type="text"/>	Reviewer: <input type="text" value="Dave Dekker"/>
Building Address: <input type="text" value="Marriner St / Esplanade"/>		Legal Description: <input type="text"/>			CPEng No: <input type="text" value="1003026"/>
GPS south: <input type="text"/>		GPS east: <input type="text"/>		Company: <input type="text" value="Opus International Consultants"/>	
Degrees: <input type="text"/>		Min: <input type="text"/>		Sec: <input type="text"/>	
Building Unique Identifier (CCC): <input type="text" value="PRK 1474 BLDG 009 EQ2"/>		Company project number: <input type="text" value="6-QUCCC.75 / 25HC"/>			Company phone number: <input type="text" value="03 363 5400"/>
		Date of submission: <input type="text" value="27-Feb-13"/>			Inspection Date: <input type="text" value="12-Jul-12"/>
		Revision: <input type="text" value="Final"/>			Is there a full report with this summary? <input type="text" value="yes"/>

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Soil type: <input type="text"/>	Max retaining height (m): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>		Soil Profile (if available): <input type="text"/>		
Proximity to waterway (m, if <100m): <input type="text" value="80"/>		If Ground improvement on site, describe: <input type="text"/>		
Proximity to cliff top (m, if < 100m): <input type="text"/>		Approx site elevation (m): <input type="text" value="10.00"/>		
Proximity to cliff base (m,if <100m): <input type="text"/>				

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split?: <input type="text" value="no"/>		Storeys below ground: <input type="text" value="0"/>	Foundation type: <input type="text" value="mat slab"/>	Ground floor elevation above ground (m): <input type="text"/>
Building height (m): <input type="text" value="2.60"/>		Floor footprint area (approx): <input type="text" value="18"/>	Age of Building (years): <input type="text" value="9"/>	if Foundation type is other, describe: <input type="text"/>
Strengthening present?: <input type="text" value="no"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="2.6"/>		
Use (ground floor): <input type="text" value="public"/>		Date of design: <input type="text" value="1992-2004"/>		
Use (upper floors): <input type="text"/>		If so, when (year)? <input type="text"/>		
Use notes (if required): <input type="text" value="Public Toilets"/>		And what load level (%g)? <input type="text"/>		
Importance level (to NZS1170.5): <input type="text" value="IL2"/>		Brief strengthening description: <input type="text"/>		

<b>Gravity Structure</b>		Gravity System: <input type="text" value="load bearing walls"/>	Roof: <input type="text" value="timber framed"/>	rafter type, purlin type and cladding: <input type="text" value="65x75 Glulam, 150x50 rafters, 21mm ply"/>
Floors: <input type="text" value="concrete flat slab"/>		Beams: <input type="text" value="none"/>	Columns: <input type="text" value="cast-in-situ concrete"/>	slab thickness (mm): <input type="text" value="100-130 mmm"/>
Walls: <input type="text" value="fully filled concrete masonry"/>		overall depth x width (mm x mm): <input type="text" value="Not applicable"/>		
		typical dimensions (mm x mm): <input type="text" value="300 sq, 250 dia"/>		
		#N/A		

<b>Lateral load resisting structure</b>		Lateral system along: <input type="text" value="fully filled CMU"/>	Ductility assumed, μ: <input type="text" value="1.25"/>	Period along: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>	maximum interstorey deflection (ULS) (mm): <input type="text"/>	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): <input type="text" value="10.38"/>	wall thickness (m): <input type="text" value="0.19"/>	estimate or calculation? <input type="text" value="estimated"/>
		Lateral system across: <input type="text" value="fully filled CMU"/>	Ductility assumed, μ: <input type="text" value="1.25"/>	Period across: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>	maximum interstorey deflection (ULS) (mm): <input type="text"/>	0.03 from parameters in sheet	note total length of wall at ground (m): <input type="text" value="10.17"/>	wall thickness (m): <input type="text" value="0.19"/>	estimate or calculation? <input type="text"/>

<b>Separations:</b>		north (mm): <input type="text"/>	east (mm): <input type="text"/>	south (mm): <input type="text"/>	west (mm): <input type="text"/>	leave blank if not relevant
---------------------	--	----------------------------------	---------------------------------	----------------------------------	---------------------------------	-----------------------------

<b>Non-structural elements</b>		Stairs: <input type="text"/>	Wall cladding: <input type="text"/>	Roof Cladding: <input type="text"/>	Glazing: <input type="text"/>	Ceilings: <input type="text"/>	Services(list): <input type="text"/>
--------------------------------	--	------------------------------	-------------------------------------	-------------------------------------	-------------------------------	--------------------------------	--------------------------------------

<b>Available documentation</b>		Architectural: <input type="text"/>	Structural: <input type="text" value="full"/>	Mechanical: <input type="text"/>	Electrical: <input type="text"/>	Geotech report: <input type="text"/>	original designer name/date: <input type="text" value="City Solutions, 2003"/>
--------------------------------	--	-------------------------------------	---	----------------------------------	----------------------------------	--------------------------------------	--

<b>Damage</b>		Site performance: <input type="text"/>	Describe damage: <input type="text"/>
Site: (refer DEE Table 4-2)		Settlement: <input type="text"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text"/>		Liquefaction: <input type="text"/>	notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text"/>		Differential lateral spread: <input type="text"/>	notes (if applicable): <input type="text"/>
Ground cracks: <input type="text"/>		Damage to area: <input type="text"/>	notes (if applicable): <input type="text"/>

<b>Building:</b>		Current Placard Status: <input type="text"/>	Describe how damage ratio arrived at: <input type="text"/>
Along	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Across	Damage ratio: <input type="text" value="0%"/>	Describe (summary): <input type="text"/>	
Diaphragms	Damage?: <input type="text"/>	Describe: <input type="text"/>	
CSWs:	Damage?: <input type="text"/>	Describe: <input type="text"/>	
Pounding:	Damage?: <input type="text"/>	Describe: <input type="text"/>	
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text" value="Cracking of grout around windows"/>	

<b>Recommendations</b>		Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text" value="Cracked grout"/>
Building Consent required: <input type="text" value="no"/>		Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before: <input type="text" value="100%"/>	Assessed %NBS after: <input type="text" value="100%"/>	0% %NBS from IEP below
Across	Assessed %NBS before: <input type="text" value="100%"/>	Assessed %NBS after: <input type="text" value="100%"/>	0% %NBS from IEP below
		If IEP not used, please detail assessment methodology: <input type="text" value="Quantitative"/>	

$$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$$



**Opus International Consultants Ltd**  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400  
f: +64 3 365 7858  
w: [www.opus.co.nz](http://www.opus.co.nz)