

Christchurch City Council  
PRK\_2204\_BLDG\_001 EQ2  
Washington Reserve - Toilet  
Washington Way/ Waltham Rd



QUALITATIVE ASSESSMENT REPORT  
FINAL

- Rev B
- 23 May 2013



Christchurch City Council  
PRK\_2204\_BLDG\_001 EQ2  
Washington Reserve - Toilet  
Washington Way/ Waltham Rd  
QUALITATIVE ASSESSMENT REPORT  
FINAL

- Rev B
- 23 May 2013

Sinclair Knight Merz  
142 Sherborne Street  
Saint Albans  
PO Box 21011, Edgeware  
Christchurch, New Zealand  
Tel: +64 3 940 4900  
Fax: +64 3 940 4901  
Web: [www.skmconsulting.com](http://www.skmconsulting.com)

**COPYRIGHT:** The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

**LIMITATION:** This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.

## Contents

<b>1. Executive Summary</b>	<b>1</b>
1.1. Background	1
1.2. Key Damage Observed	2
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
<b>2. Introduction</b>	<b>3</b>
<b>3. Compliance</b>	<b>4</b>
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
<b>4. Earthquake Resistance Standards</b>	<b>8</b>
<b>5. Building Details</b>	<b>10</b>
5.1. Building description	10
5.2. Gravity Load Resisting system	10
5.3. Seismic Load Resisting system	10
5.4. Geotechnical Conditions	10
<b>6. Damage Summary</b>	<b>11</b>
<b>7. Initial Seismic Evaluation</b>	<b>12</b>
7.1. The Initial Evaluation Procedure Process	12
7.2. Design Criteria and Limitations	14
7.3. Survey	14
7.4. Critical Structural Weaknesses	14
7.5. Qualitative Assessment Results	15
<b>8. Further Investigation</b>	<b>16</b>
<b>9. Conclusion</b>	<b>17</b>
<b>10. Limitation Statement</b>	<b>18</b>
<b>11. Appendix 1 – Photos</b>	<b>19</b>
<b>12. Appendix 2 – IEP Reports</b>	<b>21</b>
<b>13. Appendix 3 – CERA Standardised Report Form</b>	<b>28</b>



## Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	15/10/2012	J Carter	N Calvert	15/10/2012	Draft for Client Approval
B	23/05/2013	N Calvert	N Calvert	23/05/2013	Final

## Approval

	Signature	Date	Name	Title
Author		23/05/2013	Nigel Chan	Structural Engineer
Approver		23/05/2013	Nick Calvert	Senior Structural Engineer

## Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	Christchurch City Council
B	1	1	Christchurch City Council

<b>Printed:</b>	23 May 2013
<b>Last saved:</b>	23 May 2013 04:03 PM
<b>File name:</b>	PRK 2204 BLDG 001 Washington Reserve Toilet Qualitative Final.docx
<b>Author:</b>	Nigel Chan
<b>Project manager:</b>	Alex Martin
<b>Name of organisation:</b>	Christchurch City Council
<b>Name of project:</b>	Christchurch City Council Structures Panel
<b>Name of document:</b>	ZB01276.192.PRK 2204-001 EQ2.Qualitative.Assmt.docx
<b>Document version:</b>	B
<b>Project number:</b>	ZB01276.192

# 1. Executive Summary

## 1.1. Background

A Qualitative Assessment was carried out on the toilet PRK\_2204\_BLDG\_001 EQ2 located at Washington Reserve on the corner of Washington Way, Waltham Road and Moorhouse Avenue. The building is a small single storey masonry toilet block. An aerial photograph illustrating the location of this building is shown below in Figure 1. Detailed descriptions outlining the buildings age and construction type are given in Section 5 of this report.



### ■ Figure 1 Aerial Photograph of Washington Reserve Toilets

The qualitative assessment includes a summary of the building damage as well as an initial assessment of the current seismic capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 18<sup>th</sup> September 2012 and architectural drawings dated July 1998.



## **1.2. Key Damage Observed**

Key damage observed includes:-

- Plaster material surrounding the bottom door hinge for the women's toilet has broken off  
See section 6 for the damage summary.

## **1.3. Critical Structural Weaknesses**

No potential critical structural weaknesses have been identified.

## **1.4. Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the buildings original capacity has been assessed to be in the order of 100%NBS and since the damage observed does not affect the structural performance of the building the post-earthquake capacity is also 100%NBS.

The building has been assessed to have a seismic capacity in the order of 100% NBS and is therefore not potentially earthquake prone.

## **1.5. Recommendations**

It is recommended that:

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.

## 2. Introduction

Sinclair Knight Merz was engaged by Christchurch City Council to prepare a qualitative assessment report for the toilet building located at Washington Reserve following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The Qualitative Assessment uses the methodology recommended in the Engineering Advisory Group document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury” (part 2 revision 5 dated 19/07/2011 and part 3 draft revision dated 13/12/2011). The qualitative assessment includes a summary of the building damage as well as an initial assessment of the likely current Seismic Capacity compared with current seismic code requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in section 7.

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to the New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3<sup>1</sup>.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings for this building were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.

---

<sup>1</sup> <http://www.dbh.govt.nz/seismicity-info>

### **3. Compliance**

This section contains a summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

#### **3.1. Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

##### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

##### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses



- The extent of any earthquake damage

### **3.2. Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

#### **3.2.1. Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

#### **3.2.2. Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’. Regarding seismic capacity ‘as near as reasonably practicable’ has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

#### **3.2.3. Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

#### **3.2.4. Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **3.2.5. Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **3.2.6. Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **3.3. Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4<sup>th</sup> September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 34%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.



### **3.4. Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



## 4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



■ **Table 1: %NBS compared to relative risk of failure**

<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## **5. Building Details**

### **5.1. Building description**

Our evaluation was based on the Christchurch City Council architectural drawings dated July 1998 and our visual inspection carried out on the 18 September 2012. For the purposes of the IEP we have used a design date of 1992-2004.

Building PRK\_2204\_BLDG\_001 EQ2 is a small single storey toilet block at Washington Reserve located at the corner of Washington Reserve, Waltham Road and Moorhouse Ave. The building is constructed from reinforced concrete block and a timber framed roof. The roof is clad with 0.55mm colorsteel zincalume. The structure is founded on a concrete raft foundation with a concrete slab on grade as the floor surface. There are concrete ramps leading up to the toilet entrances.

### **5.2. Gravity Load Resisting system**

The gable roof structure consists of 100x50 timber rafters at 600 centres and 75 x 50 timber purlins at 600 centres which are supported on the 15 series masonry walls. The block walls are supported by the concrete raft foundation.

### **5.3. Seismic Load Resisting system**

Lateral loads acting across and along this building will be resisted by the concrete block walls via out of plane bending and shear. Due to the span of the block walls and the detailing we believe that the block walls are spanning horizontally and therefore lateral loads generated by these walls will not need to be resisted by the roof structure.

Note that for this building the “across direction” has been taken as perpendicular to the ridge line whereas the “along direction” has been taken along the ridge line of the roof.

### **5.4. Geotechnical Conditions**

The geotechnical conditions that have been assumed for this site

- The site is NZS1170.5 Class D (deep or soft soil)
- Liquefaction risk appears to be low to moderate.



## 6. Damage Summary

SKM undertook a visual inspection on 18/09/12. The following areas of damage were observed during the time of inspection:

- 1) Plaster material surrounding the bottom door hinge for the women's toilet has broken off (see photo 8)

Photos of the above damage can be found in Appendix 1 – Photos.

## 7. Initial Seismic Evaluation

### 7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes'. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings<sup>2</sup>.

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 2. The building grade is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. A building is earthquake prone for the purposes of this Act if, having regard to its condition and to the ground on which it is built, and because of its construction, the building—

- a) will have its ultimate capacity exceeded in a moderate earthquake (as defined in the regulations); and
- b) would be likely to collapse causing—
  - i. injury or death to persons in the building or to persons on any other property; or
  - ii. damage to any other property.

A moderate earthquake is defined as 'in relation to a building, an earthquake that would generate shaking at the site of the building that is of the same duration as, but that is one-third as strong as, the earthquake shaking (determined by normal measures of acceleration, velocity and displacement) that would be used to design a new building at the site.'

An earthquake prone building will have an increased risk that its strength will be exceeded due to earthquake actions of approximately 10 times (or more) than that of a building having a capacity in excess of 100% NBS (refer Table 1)<sup>3</sup>. Buildings in Christchurch City that are identified as being earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone<sup>4</sup>.

---

<sup>2</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

<sup>3</sup> NZSEE June 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-13

<sup>4</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>





**Table 2: IEP Risk classifications**

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without collapse or other forms of failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building<sup>5</sup>. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration.

The NZ Building Code describes that the relevant codes for determining %NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard
- NZS 3604:2011 Timber Framed Buildings

<sup>5</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9

## 7.2. Design Criteria and Limitations

Following our inspection on the 18<sup>th</sup> September 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and inspection findings of the building. Please note no intrusive investigations were undertaken.
- Structural drawings for this building were not available however the design of the building is very similar to the toilet block PRK\_0348\_BLDG\_017 EQ2 dated October 1999. These drawings were available.

The design criteria used to undertake the assessment include:

- Standard design assumptions for typical office and factory buildings as described in AS/NZS1170.0:2002
  - 50 year design life, which is the default NZ Building Code design life.
  - Structure importance level 1 since the total floor area is <math><30\text{m}^2</math> and represents structures presenting a low degree of hazard to life and other property
  - Ductility level of 1.25, based on our assessment and code requirements at the time of design. This represents nominally ductile structures.
  - Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011

This IEP was based on our visual inspection of the building and a review of the available structural drawings. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.
- The IEP does not involve a detailed analysis or an element by element code compliance check.

## 7.3. Survey

There was no visible settlement of the structure, nor were there any significant ground movement issues around the building. We do not recommend that any survey be undertaken at this point.

## 7.4. Critical Structural Weaknesses

The building was not found to have any critical structural weaknesses:



## 7.5. Qualitative Assessment Results

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity expressed as a percentage of new building standard (%NBS) is in order of that shown below in Table 3.

**Table 3: Qualitative Assessment Summary**

<u>Item</u>	<u>%NBS</u>
Washington Reserve Toilet	100

Our qualitative assessment found that the building is likely to be classed as a ‘Low Risk Building’ (capacity between 67% and 100% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Reports.



## **8. Further Investigation**

Due to the likely seismic rating of this building being greater than 67% and the lack of any structural damage no further investigation is required at this stage of the assessment.



## 9. Conclusion

A qualitative assessment was carried out on the building PRK\_2204\_BLDG\_001 EQ2 located at Washington Reserve. This building has been assessed to have a likely seismic capacity in the order of 100%NBS and is therefore a 'low risk building'.

Due to the likely seismic rating of this building and the lack of any structural damage no further investigation is required.

It is recommended that:

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.



## 10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

## 11. Appendix 1 – Photos



Photo 1: Northwest elevation



Photo 2: Southwest elevation



Photo 3: Southeast elevation



Photo 4: Northeast elevation



Photo 5: Entrance to womens toilet



Photo 6: Interior view of womens toilet



Photo 7: Hinges for the womens toilet door




Photo 8: Close up view of the bottom hinge for the womens toilet door showing the missing plaster material





## **12. Appendix 2 – IEP Reports**


Building Name:	Toilet (PRK_2204_BLDG_001 EQ2)	Ref.	ZB01276.192
Location:	Washington Way Reserve	By	NLC
		Date	23/05/2013

**Step 1 - General Information**

**1.1 Photos (attach sufficient to describe building)**



**1.2 Sketch of building plan**



**1.3 List relevant features**

This is small single storey concrete block structure. It has a timber framed roof that is clad in lightweight corrugated coloursteel. The structure has concrete raft foundations. Drawings for this toilet block were available and are dated July 1998.

**1.4 Note information sources**

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

Tick as appropriate

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Arch/Strut \_\_\_\_\_

Inspection date: 18/9/2012  
 Drawings dated 7/1998

**Table IEP-2 Initial Evaluation Procedure – Step 2**

(Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)



Building Name:	Toilet (PRK_2204_BLDG_001 EQ2)	Ref.	ZB01276.192
Location:	Washington Way Reserve	By	NLC
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	23/05/2013
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 2 - Determination of (%NBS)b**

**2.1 Determine nominal (%NBS) = (%NBS)nom**

Pre 1935	Seismic Zone;	A	<input type="radio"/>	See also notes 1, 3
1935-1965		B	<input type="radio"/>	
1965-1976		C	<input type="radio"/>	
1976-1992	Seismic Zone;	A	<input type="radio"/>	See also note 2
		B	<input type="radio"/>	
		C	<input type="radio"/>	
1992-2004			<input checked="" type="radio"/>	

**b) Soil Type**

From NZS1170.5:2004, Cl 3.1.3	A or B Rock	<input type="radio"/>
	C Shallow Soil	<input type="radio"/>
	D Soft Soil	<input checked="" type="radio"/>
	E Very Soft Soil	<input type="radio"/>

From NZS4203:1992, Cl 4.6.2.2	a) Rigid	<input checked="" type="radio"/>	N-A
(for 1992 to 2004 only and only if known)	b) Intermediate	<input type="radio"/>	

**c) Estimate Period, T**

building Ht = **4** meters

Can use following:

$T = 0.09h_n^{0.75}$	for moment-resisting concrete frames
$T = 0.14h_n^{0.75}$	for moment-resisting steel frames
$T = 0.08h_n^{0.75}$	for eccentrically braced steel frames
$T = 0.06h_n^{0.75}$	for all other frame structures
$T = 0.09h_n^{0.75}/A_c^{0.5}$	for concrete shear walls
$T \leq 0.4\text{sec}$	for masonry shear walls

Where  $h_n$  = height in m from the base of the structure to the uppermost seismic weight or mass.  
 $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$   
 $A_i$  = cross-sectional shear area of shear wall  $i$  in the first storey of the building, in  $m^2$   
 $L_{wi}$  = length of shear wall  $i$  in the first storey in the direction parallel to the applied forces, in m  
 with the restriction that  $L_{wi}/h_n$  shall not exceed 0.9

Ac =	Longitudinal	Transverse	m2
	<input type="radio"/> MRCF	<input type="radio"/> MRCF	
	<input type="radio"/> MRSF	<input type="radio"/> MRSF	
	<input type="radio"/> EBSF	<input type="radio"/> EBSF	
	<input type="radio"/> Others	<input type="radio"/> Others	
	<input type="radio"/> CSW	<input type="radio"/> CSW	
	<input checked="" type="radio"/> MSW	<input checked="" type="radio"/> MSW	

Longitudinal	Transverse	Seconds
0.4	0.4	

**d) (%NBS)nom determined from Figure 3.3**

<b>Note 1:</b> For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25.	No	Factor	1
For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B	No		1
<b>Note 2:</b> For reinforced concrete buildings designed between 1976 -1984 (%NBS)nom by 1.2	No		1
<b>Note 3:</b> For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1.	No		1

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Continued over page

Building Name:	Toilet (PRK_2204_BLDG_001 EQ2)	Ref.	ZB01276.192
Location:	Washington Way Reserve	By	NLC
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	23/05/2013
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**2.2 Near Fault Scaling Factor, Factor A**  
If T < 1.5sec, Factor A = 1

a) Near Fault Factor, N(T,D) 1  
(from NZS1170.5:2004, Cl 3.1.6)

b) Near Fault Scaling Factor = 1/N(T,D) 

Factor A	1.00
----------	------

**2.3 Hazard Scaling Factor, Factor B**

Select Location

a) Hazard Factor, Z, for site  
(from NZS1170.5:2004, Table 3.3)

Z = 0.3  
Z 1992 = 0.8    Auckland 0.6    Palm Nth 1.2  
**Type Z 1992 above**    Wellington 1.2    Dunedin 0.6  
Christchurch 0.8    Hamilton 0.67

b) Hazard Scaling Factor  
# For pre 1992 = 1/Z  
For 1992 onwards = Z 1992/Z  
(Where Z 1992 is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B	2.67
----------	------

**2.4 Return Period Scaling Factor, Factor C**

a) Building Importance Level   
(from NZS1170.0:2004, Table 3.1 and 3.2)

b) Return Period Scaling Factor from accompanying Table 3.1 

Factor C	1.20
----------	------

**2.5 Ductility Scaling Factor, D**

a) Assessed Ductility of Existing Structure,  $\mu$   
(shall be less than maximum given in accompanying Table 3.2)

Longitudinal	1.25	$\mu$ Maximum = 6
Transverse	1.25	$\mu$ Maximum = 6

b) Ductility Scaling Factor  
For pre 1976 =  $k_{\mu}$   
For 1976 onwards = 1  
(where  $k_{\mu}$  is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.00
Transverse	Factor D	1.00

**2.6 Structural Performance Scaling Factor, Factor E**

Select Material of Lateral Load Resisting System

Longitudinal   
Transverse

a) Structural Performance Factor,  $S_p$   
from accompanying Figure 3.4

Longitudinal	$S_p$	0.90
Transverse	$S_p$	0.90

b) Structural Performance Scaling Factor

Longitudinal	$1/S_p$	Factor E	1.11
Transverse	$1/S_p$	Factor E	1.11

**2.7 Baseline %NBS for Building, (%NBS)<sub>b</sub>**  
(equals (%NSB)<sub>nom</sub> x A x B x C x D x E)

Longitudinal	78.9	(%NBS) <sub>b</sub>
Transverse	78.9	(%NBS) <sub>b</sub>

**Table IEP-3 Initial Evaluation Procedure – Step 3**

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)

Building Name: Toilet (PRK_2204_BLDG_001 EQ2)	Ref. ZB01276.192
Location: Washington Way Reserve	By NLC
Direction Considered: <b>a) Longitudinal</b>	Date 23/05/2013
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**

(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**

(Choose a value - Do not interpolate)

**Building Score**

**Score**

**3.1 Plan Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1

Table for Selection of Factor D1

Separation	Factor D1		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2

Table for Selection of Factor D2

Separation	Factor D2		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input type="radio"/> 1

Factor D

(Set D = lesser of D1 and D2 or..

set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

Compact design of the building with closely spaced reinforced masonry walls

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR

Building Name:	Toilet (PRK_2204_BLDG_001 EQ2)	Ref.	ZB01276.192
Location:	Washington Way Reserve	By	NLC
Direction Considered:	<b>b) Transverse</b>	Date	23/05/2013
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**  
(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**  
(Choose a value - Do not interpolate)

**Building Score**

**3.1 Plan Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Table for Selection of Factor D1	Factor D1 <input type="text" value="1"/>		
	Severe	Significant	Insignificant
Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Table for Selection of Factor D2	Factor D2 <input type="text" value="1"/>		
	Severe	Significant	Insignificant
Separation	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D

(Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

Compact design of the building with closely spaced reinforced masonry walls

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR

Building Name:	Toilet (PRK_2204_BLDG_001 EQ2)	Ref.	ZB01276.192
Location:	Washington Way Reserve	By	NLC
Direction Considered:	<b>Longitudinal &amp; Transverse</b>		Date
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 4 - Percentage of New Building Standard (%NBS)**

	Longitudinal	Transverse
<b>4.1 Assessed Baseline (%NBS)<sub>b</sub></b> (from Table IEP - 1)	78	78
<b>4.2 Performance Achievement Ratio (PAR)</b> (from Table IEP - 2)	1.50	1.50
<b>4.3 PAR x Baseline (%NBS)<sub>b</sub></b>	117	117
<b>4.4 Percentage New Building Standard (%NBS)</b> (Use lower of two values from Step 4.3)		117

**Step 5 - Potentially Earthquake Prone?**  
(Mark as appropriate)

%NBS ≤ 33 NO

**Step 6 - Potentially Earthquake Risk?**

%NBS < 67 NO

**Step 7 - Provisional Grading for Seismic Risk based on IEP**

**Seismic Grade** A+

Evaluation Confirmed by

Signature

James Carter

Name

1017618

CPEng. No

**Relationship between Seismic Grade and % NBS :**

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20



## **13. Appendix 3 – CERA Standardised Report Form**



<b>Location</b>		Building Name: Washington Reserve Toilet	Unit No: Street	Reviewer: J Carter
Building Address: [ ]		Washington Way/ Waltham Road/ Moorhouse Ave		CPEng No: 1017618
Legal Description: [ ]		Company: Sinclair Knight Merz		Company project number: ZB01276.182
GPS south: [ ]		Company phone number: 03 940 4900		Date of submission: 24-May
GPS east: [ ]		Degrees Min Sec		Inspection Date: 18/09/2012
Building Unique Identifier (CCC): FRK_2204 BLDG_001		Is there a full report with this summary?		Revision: B
				yes

<b>Site</b>		Site slope: flat	Max retaining height (m): 0
Soil type: mixed		Soil Profile (if available): [ ]	
Site Class (to NZS1170.5): D		If Ground improvement on site, describe: [ ]	
Proximity to waterway (m, if <100m): [ ]		Approx site elevation (m): 0.00	
Proximity to cliff top (m, if < 100m): [ ]			
Proximity to cliff base (m,if <100m): [ ]			

<b>Building</b>		No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m): [ ]
Ground floor split?: no		Stores below ground: 0		Ground floor elevation above ground (m): [ ]
Foundation type: raft slab		if Foundation type is other, describe: [ ]		height from ground to level of uppermost seismic mass (for IEP only) (m): 4
Building height (m): 4.00		Date of design: 1992-2004		
Floor footprint area (approx): 10				
Age of Building (years): 14				
Strengthening present?: no		If so, when (year)? [ ]		And what load level (%g)? [ ]
Use (ground floor): other (specify) [ ]		Brief strengthening description: [ ]		
Use (upper floors): [ ]				
Use notes (if required): Toilet Block				
Importance level (to NZS1170.5): IL1				

<b>Gravity Structure</b>		Gravity System: load bearing walls	0.55mm colorsteel zincalume supported on 75x50 timber purlins at 600 crs, supported on 100 x 50 timber rafters at 600 crs
Roof: timber framed		rafter type, purlin type and cladding	600 crs
Floors: concrete flat slab		slab thickness (mm)	125
Beams: steel non-composite		beam and connector type	SHS door lintels
Columns: load bearing walls		typical dimensions (mm x mm)	140
Walls: fully filled concrete masonry		#N/A	

<b>Lateral load resisting structure</b>		Lateral system along: fully filled CMU	<b>Note: Define along and across in detailed report!</b>	note total length of wall at ground (m): 10
Ductility assumed, μ: 1.25		0.08 from parameters in sheet		wall thickness (m): 0.14
Period along: 0.40				estimate or calculation? estimated
Total deflection (ULS) (mm): 5				estimate or calculation? estimated
maximum interstorey deflection (ULS) (mm): [ ]				estimate or calculation? [ ]
Lateral system across: fully filled CMU		0.40 from parameters in sheet		note total length of wall at ground (m): 2.5
Ductility assumed, μ: 1.25				wall thickness (m): 0.14
Period across: 0.40				estimate or calculation? estimated
Total deflection (ULS) (mm): 5				estimate or calculation? estimated
maximum interstorey deflection (ULS) (mm): [ ]				estimate or calculation? [ ]

<b>Separations:</b>		north (mm): [ ]	leave blank if not relevant
east (mm): [ ]			
south (mm): [ ]			
west (mm): [ ]			

<b>Non-structural elements</b>		Stairs: [ ]	describe: n/a
Wall cladding: plaster system		describe: plaster material on the exterior	
Roof Cladding: Metal		describe: 0.55mm coloursteel zincalume	
Glazing: [ ]		describe: n/a	
Ceilings: [ ]		describe: n/a	
Services(list): none			

<b>Available documentation</b>		Architectural: full	original designer name/date: Christchurch City Council, City Design - July 1998
Structural: none		original designer name/date: [ ]	
Mechanical: none		original designer name/date: [ ]	
Electrical: none		original designer name/date: [ ]	
Geotech report: none		original designer name/date: [ ]	

<b>Damage</b>		Site performance: 1	Describe damage: no damage observed on site
Settlement: none observed			notes (if applicable): [ ]
Differential settlement: none observed			notes (if applicable): [ ]
Liquefaction: none apparent			notes (if applicable): [ ]
Lateral Spread: none apparent			notes (if applicable): [ ]
Differential lateral spread: none apparent			notes (if applicable): [ ]
Ground cracks: none apparent			notes (if applicable): [ ]
Damage to area: none apparent			notes (if applicable): [ ]

<b>Building:</b>		Current Placard Status: green	
Along		Damage ratio: 0%	Describe how damage ratio arrived at: no structural damage observed on site
Describe (summary): small structure with no structural damage			
Across		Damage ratio: 0%	$Damage\_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$
Describe (summary): small structure with no structural damage			
Diaphragms		Damage?: no	Describe: [ ]
CSWs:		Damage?: no	Describe: [ ]
Pounding:		Damage?: no	Describe: [ ]
Non-structural:		Damage?: yes	Describe: plaster on the exterior around the door hinge for the womens toilet has fallen off

<b>Recommendations</b>		Level of repair/strengthening required: none	Describe: [ ]
Building Consent required: no		Describe: [ ]	
Interim occupancy recommendations: full occupancy		Describe: [ ]	
Along		Assessed %NBS before: 100%	%NBS from IEP below
Assessed %NBS after: 100%			If IEP not used, please detail assessment methodology: Qualitative Assessment carried out this includes the NZSEEE IEP - refer to SKM report
Across		Assessed %NBS before: 100%	%NBS from IEP below
Assessed %NBS after: 100%			