



CLIENTS | PEOPLE | PERFORMANCE

**Wigram Gymnasium**  
**BU 2556-001 EQ2**  
Detailed Engineering Evaluation  
Quantitative Report  
Version FINAL

29 Springs Road, Hornby



**Wigram Gymnasium  
BU 2556-001 EQ2**

Detailed Engineering Evaluation  
Quantitative Report  
Version FINAL

29 Springs Road, Hornby

Christchurch City Council

**Prepared By**  
Dioselo Cagandahan

**Reviewed By**  
Stephen Lee

**Date**  
2/10/12



# Contents

Quantitative Report Summary	1
1. Background	3
2. Compliance	4
2.1 Canterbury Earthquake Recovery Authority (CERA)	4
2.2 Building Act	5
2.3 Christchurch City Council Policy	6
2.4 Building Code	6
3. Earthquake Resistance Standards	7
4. Building Description	9
4.1 General	9
4.2 Gravity Load Resisting System	12
4.3 Lateral Load Resisting System	12
5. Assessment	14
5.1 Site Inspection	14
5.2 Site Measurement	14
5.3 Available Structural Drawings	14
6. Damage Assessment	16
6.1 Surrounding Buildings	16
6.2 Residual Displacements and General Observations	16
6.3 Ground Damage	16
7. Structural Analysis	17
8. Geotechnical Consideration	18
8.3 Field Investigations	20
8.4 Ground Conditions Encountered	21
8.5 Interpretation of Ground Conditions	21
9. Results of the Analysis	23
9.1 Gymnasium	23
9.2 Changing Room	23
9.3 External Storage Room	23



9.4	Discussion of Results	27
9.5	Occupancy	27
10.	Conclusions	28
10.1	Building Capacity Assessment	28
10.2	Occupancy	28
11.	Recommendations	29
12.	Limitations	30
12.1	General	30
12.2	Geotechnical Limitations	30

## Table Index

Table 1	%NBS compared to relative risk of failure	8
Table 2	Summary of Known Active Faults	20
Table 3	Coordinates of Investigation Locations	20
Table 4	Summary of CPT-Inferred Lithology	21
Table 5	Seismic Horizontal Deflection	23

## Figure Index

Figure 1	NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE	7
Figure 2	Plan Showing Key Structural Elements	10
Figure 3	Frame at Grid Line 4	11
Figure 4	Post February 2011 Earthquake Aerial Photography	19
Figure 5	Roof steel rafters rated less than 67%NBS	25
Figure 6	Gallery steel beam rated less than 67%NBS	26

## Appendices

- A Geotechnical Investigation Reports and Analysis
- B Photographs
- C Existing Drawings
- D Rebar Scanning Results
- E CERA Building Evaluation Form



# Quantitative Report Summary

**Wigram Gymnasium**

**BU 2556-001 EQ2**

**Detailed Engineering Evaluation**

**Quantitative Report - SUMMARY**

**Version FINAL**

**29 Springs Road, Hornby**

## **Background**

Wigram Gymnasium is located at 29 Springs Road, Hornby, Christchurch and has been assessed for its safety during an earthquake. We have assessed the structure of the building to determine the current level of safety it affords during an earthquake, and have compared that level to the legal requirements.

This is a summary of the Quantitative report for the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 18<sup>th</sup> January 2012 and available drawings as itemised in Section 5.3.

## **Building Description**

The Wigram Gymnasium is a one (1) storey structure constructed from structural steel and reinforced concrete masonry block walls. The building is approximately 50 m long by 35 m wide and 11 m tall. The overall footprint of the building is approximately 1300 m<sup>2</sup>.

## **Key Damage Observed**

Key damage observed included:-

- ▶ Minor cracks along the construction joint between the concrete masonry block walls of the external storage area to the north-west and the main building.
- ▶ Minor cracks in the long reinforced concrete masonry block wall along the north-east side of the building. These cracks were filled with dirt suggesting that they are not related to the recent seismic activity.

## **Building Capacity Assessment**

Based on the site inspection, available drawings and the results of quantitative assessment, the overall building capacity is rated at 43%NBS. The critical building is the gymnasium which has inadequate roof and wall bracing to transfer the roof lateral load down to the foundations in the longitudinal direction. The building overall is therefore classified as 'Earthquake Risk'.

Changing and External Storage Rooms are rated over 100% and 50%NBS respectively.



### **Recommendation**

GHD recommend that further work is undertaken in order to develop the scope of the strengthening and repair options. This work should involve:

- ▶ Minor repairs are undertaken to fill the cracks identified in the reinforced concrete masonry block walls.
- ▶ Developing a strengthening works scheme to increase the seismic capacity of the Wigram Gymnasium to as near as practicable to 100%NBS, and at least 67%NBS. This will need to consider compliance with accessibility and fire requirements.
- ▶ The Wigram Gymnasium is classified as 'Earthquake Risk' building and therefore is acceptable to occupy in accordance with CCC policy.



## 1. Background

GHD has been engaged by Christchurch City Council (CCC) to undertake a detailed engineering evaluation of Wigram Gymnasium.

This report is a Quantitative Assessment of the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.



## 2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

CERA now requires a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). The Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 has been adopted by CERA for evaluations. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

Factors determining the extent of evaluation and strengthening level required include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



## **2.2 Building Act**

Several sections of the Building Act 2004 are relevant when considering structural requirements:

### **Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS, however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

#### **2.2.1 Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## **2.4 Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

### 3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	% NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (Improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34% NBS.	100% NBS desirable. Improvement should achieve at least 67% NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally, Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement Required)	Unacceptable	Unacceptable

**Figure 1 NZSEE Risk Classifications Extracted from Table 2.2 of the NZSEE 2006 AISPBE**

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

**Table 1      %NBS compared to relative risk of failure**



## 4. Building Description

### 4.1 General

Wigram Gymnasium is located at 29 Springs Road, Hornby, Christchurch and is currently used by Olympia Gymnastics as a gymnastics sports hall, gallery, office space, changing facility and storage room.

The original building which houses the gymnastics hall, changing facilities, office space and internal storage room was constructed in 1985. Sometime later (year unknown), a single storey extension was added on the west of the original building. This now houses the external storage room.

The structure of the gymnastics area of the building consists of steel portal frames with reinforced concrete masonry block walls up to the level of the first bend in the portal frames. A portion of the middle steel portal frames extend towards the south, accommodating the mezzanine viewing and gallery platform. The building has a concrete ground slab and foundations consisting of pad footings under the portal frame columns connected by concrete strip footings which extend under the reinforced concrete masonry block walls.

The single storey changing room area and storage areas to the south and west of the gymnastics area consist of reinforced concrete masonry block walls supporting the timber framed roofing. These areas also have concrete ground slabs and concrete strip footings.

The structure of the external storage room located at the west of the gymnastics area also consists of reinforced concrete block masonry walls supporting the timber framed roofing. No drawings were found for this part of the structure. The building is believed to be supported by strip footings beneath the reinforced concrete masonry block walls.

Key structural details of the building are shown in Figure 2 below.




Figure 2 Plan Showing Key Structural Elements




Figure 3 Frame at Grid Line 4



The dimensions of the main gymnastics hall are approximately 45 m long by 20 m wide and 11 m tall. The gallery platform and reinforced concrete masonry changing room areas extend another 15 m to the south of the building resulting in an overall width of approximately 35 m. The overall footprint of the building is approximately 1300 m<sup>2</sup>.

## **4.2 Gravity Load Resisting System**

The gravity loads in the structure are carried by a steel portal frame system supporting the gymnastics hall roof section of the building and reinforced concrete masonry blockwork walls in the changing room and storage areas.

The roof structure of the gymnasium area consists of a light steel roof supported by steel purlins. The gravity loads from the roof are transferred through the steel purlins spanning between the portal frames. The loads are then transferred through the portal frames and into the foundations of the building. A reinforced concrete masonry block wall to the height of the first bend of the portal frames is present on all sides of the building. An external view of these walls is shown in Photograph 5. Steel girts span between the portal frames along the walls of the building as can be seen in Photograph 11. Steel angle cross bracing is present between the portal frames at roof level but is not present below this level, as shown in Photograph 16. The mezzanine viewing platform flooring system consists of a suspended timber floor supported by timber framed walls and SHS steel columns.

The gravity loads in the single story concrete masonry changing room and storage areas are resisted by reinforced concrete masonry block walls. The roof structure consists of light steel roofing supported by timber framing.

The foundation for the building based on the available drawings consists of reinforced concrete pads, beams and slabs.

## **4.3 Lateral Load Resisting System**

Lateral forces in the transverse direction of the main building are resisted by the moment resisting portal frames.

Lateral forces in the longitudinal direction of the main building are supposed to be transferred to the foundations of the building through the steel angle cross bracing down to the reinforced concrete masonry block walls and then down to the footings.

However there are two (2) issues of contention:

1. The steel portal frames that span over the gymnastics hall area have steel cross bracing at the roof level spanning between the portal frames as shown in Photograph 10. There is no steel cross bracing below the roof level of the building and as a result, the building relies on the columns of the portal frame and the wall girts to distribute the lateral forces from the bottom of cross bracing to the top of the reinforced concrete masonry block walls.
2. The roof cross bracing is expected to act in tension only and relies on the doubled purlins to provide the compression struts.

Both of these points may be suspect if the connection of the purlins and girts to the portal frame is not satisfactory.



In the changing room areas and the storage areas, lateral loads are resisted by reinforced concrete masonry block walls in both the longitudinal and transverse directions of the building.



## 5. Assessment

### 5.1 Site Inspection

An inspection of the building was undertaken on the 18<sup>th</sup> of January 2012. Both the interior and exterior of the building were inspected. The building was observed to have a green placard in place. Most of the main structural components of the building were able to be viewed due to the exposed nature of the structure. The reinforced concrete masonry block walls are unlined and the steel and timber framing is generally exposed. No inspection of the foundations of the structure was carried out.

The inspection consisted of observing the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including damage in areas where it would be expected for the structure type observed and noting general damage observed throughout the building in both structural and non-structural elements. Site assessment also included the ground condition observation.

### 5.2 Site Measurement

The external storage area building dimensions were measured due to unavailability of the drawings. In addition, rebar scanning using a HILTI Ferroskan was undertaken to determine approximately the rebar diameter and spacing in the reinforced concrete masonry block walls. The results of the scanning are attached in Appendix D.

### 5.3 Available Structural Drawings

There are available existing structural drawings provided to GHD and are itemised below:

Item #	Title	Sheet No.	Rev No.	Drawing Date
1	Reinforced Concrete – Standard Structural Details and Notes	200/1	-	Oct 1981
2	Masonry – Standard Structural Details and Notes	200/2	-	July 1979
3	Foundation Plan and Details	201	R1	April 1982
4	Foundation Details	202	-	April 1982
5	Blockwork Plan	203	-	April 1982
6	Blockwork Details	204	R2	April 1982
7	Portal and Steel Frame Layout	205	-	April 1982
8	Roof Plan and Steel Frame Layout	206	R1	April 1982
9	Steel Work Details and Sections	207	-	April 1982
10	Steel Work Details and Sections	208	-	April 1982



11	Steel Work Details and Sections	209	-	April 1982
12	Steel Work Details	210	R1	April 1982
13	Steel Work Details	211	R1	April 1982
14	Miscellaneous Steelwork Details	212	-	July 1982

## 5.4 Analysis and Modelling Methodology

### Mathematical Modelling

The three-dimensional frame modelling of the Wigram Gymnasium was undertaken to realistically simulate the effects of the applied loads on the structure under different loading conditions such as normal operation, earthquake and combinations thereof.

This modelling approach determines the adequacy of members or sections for the structure under various loading combinations.

Each section, member and node of the model was defined using the physical dimensions, material properties and connection details from the available drawings described in Section 5.3. Using the Etabs Version 9.7.2 structural analysis software, a computer model that incorporates all the properties of the steel portal frame and reinforced concrete masonry structure was prepared.

The Changing Room and External Storage Room were analysed separately using manual calculations and spread sheets.

### Loading Conditions

The loading conditions and load combinations used in the analysis of the structure are in accordance with AS/NZS 1170.

### Determination of %NBS

Upon determination of the critical loading conditions, each of the structural members that make up the Wigram Gymnasium was checked to determine %NBS of the members indicated as shown in the available drawings. Members demand and capacity ratio was computed and %NBS was calculated accordingly.

### Seismic Design

The Wigram Gymnasium structure was checked to the seismic design standards in accordance with the AS/NZ 1170.5:2004, NZBC Clause B1 Structure and New Zealand Society of Earthquake Engineering "Guidelines for Assessment and Improvement of the Structural Performance of Buildings in Earthquakes".



## 6. Damage Assessment

### 6.1 Surrounding Buildings

No damage to surrounding buildings was observed during site inspection.

### 6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during site inspection of the building.

Minor cracks were observed in the reinforced concrete masonry blockwork walls in several areas of the building. On the east face of the building there are minor cracks in the reinforced concrete masonry blockwork walls. These cracks can be seen in Photographs 6 and 7 in Appendix B. These cracks were filled with dirt and as a result it is unlikely that they have occurred as a result of the recent seismic activity. They can more likely be attributed to shrinkage effects.

Cracking was also observed around the construction joint between the main gymnasium hall and the external storage area to the west. The cracking is likely due to relative movement between the two different structures. The reinforced concrete masonry storage area was an extension to the existing gymnastics hall and may have not been tied in structurally to the existing building, resulting in the two structures behaving separately. Details of the cracking in this area can be seen in Photographs 3 and 4.

### 6.3 Ground Damage

No ground damage was observed during our inspection of the site.



## 7. Structural Analysis

### 7.1 Seismic Parameters

Earthquake loads were calculated using the criteria specified by New Zealand Code NZS 1170.5:2004.

▶ Site Classification	D
▶ Importance Level	2
▶ Seismic Zone factor (Z) (Table 3.3, NZS 1170.5:2004 and NZBC Clause B1 Structure)	0.30 (Christchurch)
▶ Annual Probability of Exceedance (Table 3.3, NZS 1170.0:2002)	1/500 (ULS) Importance Level 2
▶ Annual Probability of Exceedance (Table 3.3, NZS 1170.0:2002)	1/25 (SLS)
▶ Return Period Factor (Ru) (Table 3.5, NZS 1170.5:2004)	1.0 (ULS)
▶ Return Period Factor (Rs) (Table 3.5, NZS 1170.5:2004 and NZBC Clause B1 Structure)	0.33 (SLS)
▶ Ductility Factor ( $\mu$ )	2.00
▶ Performance Factor (Sp) (NZS 3404:1997)	0.70
▶ Gravitational Constant (g)	9.81 m/s <sup>2</sup>

An increased Z factor of 0.3 for Christchurch has been used in line with recommendations from the Department of Building and Housing recommendations resulting in a reduced % NBS score.

### 7.2 Structural Ductility Factor

A structural ductility factor of 2.0 has been assumed in both the longitudinal and transverse directions of the building based on the steel portal frame system as indicated on the available drawings. The steel portal frames have been assessed as the limiting structural elements in terms of the ductility of the structure and the ability to dissipate energy during an earthquake. As a result, the structural ductility factor of 2.0 associated with the moment resisting steel portal frame has been used for the purpose of this Detailed Engineering Evaluation Quantitative Assessment.



## 8. Geotechnical Consideration

The site is bordered by Springs Road to the northwest, with recreational park area to the south and east.

The terrain of the subject site is relatively flat at approximately 22m above mean sea level. It is <1km north of the Heathcote River, approximately 3.2km southwest of the Avon River, and approximately 13km west of the coast (Pegasus Bay) at New Brighton.

### 8.1 Published Information on Ground Conditions

#### 8.1.1 Published Geology

The geological map of the area<sup>1</sup> indicates that the site is underlain by:

- Dominantly alluvial sand and silt overbank deposits, being Holocene soils of the Yaldhurst Member, sub-group of the Springston formation.

#### 8.1.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that there are no boreholes within 200m of the site. Borehole lithographic logs from beyond this distance show predominantly gravel and sandy gravel with varying quantities of clay beneath the ground surface.

#### 8.1.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the site.

#### 8.1.4 CERA Land Zoning

Based on the known geology, subsurface investigations, and the absence of liquefaction and ground damage during the Canterbury earthquakes, the Canterbury Earthquake Recovery Authority (CERA) has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to perform in future earthquakes.

The site is classified as Green, N/A. This indicates that it is a non-residential property in an urban area that has not been given a Technical Category. However, nearby land has been classified as Technical category 1 (TC1) which means that liquefaction is unlikely in a future earthquake event.

#### 8.1.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake (Figure 1) shows no signs of liquefaction outside the building footprint or adjacent to the site and the site inspection commented that there was no noticeable ground damage.

<sup>1</sup> Brown, L. J. and Weeber J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.



**Figure 4**      **Post February 2011 Earthquake Aerial Photography<sup>2</sup>**

### **8.1.6      Summary of Ground Conditions**

From the information presented above, the ground conditions are likely to comprise of silty clay underlain at shallow depth by gravel and sandy gravel.

## **8.2      Seismicity**

### **8.2.1      Nearby Faults**

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

<sup>2</sup> Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



**Table 2 Summary of Known Active Faults<sup>34</sup>**

Known Active Fault	Distance from Site (km)	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	125 NW	~8.3	~300 years
Greendale (2010) Fault	14 W	7.1	~15,000 years
Hope Fault	110 N	7.2~7.5	120~200 years
Kelly Fault	110 NW	7.2	~150 years
Porters Pass Fault	58 NW	7.0	~1100 years

Recent earthquakes since 4 September 2010 have identified the presence of a new active fault system / zone underneath the Canterbury Plains, including Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available and average recurrence intervals are yet to be established.

### 8.2.2 Ground Shaking Hazard

The recent seismic activity has produced earthquakes of Magnitude 6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

New Zealand Standard NZS 1170.5:2004 now quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

## 8.3 Field Investigations

In order to further understand the ground conditions at the site, one piezocone CPT investigation was conducted at the site on 02 April 2012.

The location of the test is tabulated in Table 2.

Table 2 Coordinates of Investigation Locations

**Table 3 Coordinates of Investigation Locations**

Investigation	Depth (m bgl)	Easting (NZMG)	Northing (NZMG)
CPTU 001	0.9	2473167	5740044

<sup>3</sup> Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

<sup>4</sup> GNS Active Faults Database



The CPTU investigation was undertaken by McMillan Drilling Service on 02 April 2012, typically to a target depth of 20m below ground level. However, refusal was reached at depth of 0.9m due to the presence of dense gravels.

Interpretation of output graphs<sup>5</sup> from the investigation showing Cone Tip Resistance ( $q_c$ ), Friction Ratio (Fr), Inferred Lithology and Inferred Liquefaction Potential are presented in Table 3.

## 8.4 Ground Conditions Encountered

### 8.4.1 Summary of CPT-Inferred Lithology

**Table 4** Summary of CPT-Inferred Lithology

Depth (m)	Lithology <sup>1</sup>	Cone Tip Resistance $q_c$ (MPa)	Friction Ratio Fr (%)
0 – 0.9	Surface soil	~15.0	1.0 – 2.0
>0.9	Gravel	> 20.0	~0.0

## 8.5 Interpretation of Ground Conditions

### 8.5.1 Liquefaction assessment

It is considered that liquefaction at this site is unlikely to occur in future earthquake events. This is based on:

- ▶ No signs of liquefaction from post-earthquake aerial photography or during inspection on 18 January 2012
- ▶ Ground conditions encountered of dense shallow gravels
- ▶ TC1 classification

### 8.5.2 Slope Failure and/or Rockfall Potential

The site is located within Hornby, a flat suburb in western Christchurch. Global slope instability risk is considered negligible. However, any localised retaining structures and/or embankments should be further investigated to determine the site-specific slope instability potential.

### 8.5.3 Foundation Recommendations

Following the guidance provided by the Department of Housing and Building6 (DBH) in section 4 for repairing of foundations for TC1 dwellings, the following geotechnical recommendations are provided:

- ▶ A site subsoil Class of D, Deep or Soft Soil, should be adopted for the site (in accordance with NZS 1170.5:2004).

<sup>5</sup> McMillans Drilling CPT data plots, Appendix A.



- ▶ An allowable bearing Capacity of 100KPa can be used for standard shallow foundation solutions using timber and concrete floors, in accordance with New Zealand Building regulations and NZS 3604.
- ▶ If a re-build is deemed necessary a shallow investigation specific to the new building footprint should be undertaken. Shallow ground improvement is not required.



## 9. Results of the Analysis

The following are the results of structural analysis to Wigram Gymnasium structure.

### 9.1 Gymnasium

#### ***Steel Columns***

All steel columns rated above 100%NBS.

#### ***Roof Steel Rafters***

The rafters in five (5) of the steel portal frames rated lower than 67%NBS with the lowest on grid line 5 being 43%NBS. These are highlighted in red in Figure 5 on page 21.

#### ***Gallery Steel Beams***

One (1) gallery support steel beam rated below 67%NBS. It is highlighted in red in Figure 6 on page 22.

#### ***Roof Steel Braces (Tension Only)***

All roof steel angle braces met 100%NBS

#### ***Reinforced Concrete Masonry Block Walls***

All reinforced concrete masonry block wall panels were found to be above 100% NBS.

#### ***Seismic Horizontal Deflection***

The computed seismic horizontal defections of the Gymnasium structure are itemised in the table below.

**Table 5          Seismic Horizontal Deflection**

<b>Level</b>	<b>Seismic in Longitudinal Direction</b>	<b>Seismic in Transverse Direction</b>	<b>Height(H) (m)</b>	<b>Allowable, 2.5%xH (mm)</b>
Roof	98 mm	86 mm	10.15	253

### 9.2 Changing Room

#### ***Reinforced Concrete Masonry Block Wall***

All reinforced concrete masonry block wall panels were found to be above 100% NBS.

### 9.3 External Storage Room

#### ***Reinforced Concrete Masonry Block Wall***

All reinforced concrete masonry block wall panels were also found to be over 100%NBS.



### ***Seismic Horizontal Deflection***

The computed seismic horizontal deflection of the structure in the transverse direction is 1 mm. Similarly, the horizontal deflection of the Gymnasium in the longitudinal direction at roof level of External Storage Room is 10 mm. The two (2) horizontal deflections are then combined as per Appendix 4D.1 of NZSEE which resulted to a value of 10 mm.

Considering the approximate nominal gap of 5 mm between the External Storage Room and the Gymnasium, and the computed combined seismic horizontal deflection of 10 mm, the structure was rated 50% NBS.




Figure 5 Roof steel rafters rated less than 67%NBS




Figure 6 Gallery steel beam rated less than 67%NBS



## **9.4 Discussion of Results**

The results obtained from the quantitative assessment are consistent with those expected for a building of this age and construction type founded on Class D soils.

The original building was constructed in 1982 and was likely designed to the loading standard current at the time, NZS 4203:1976. The design loads used in this code are likely to have been less than those required by the current loading standard and the detailing requirements for ductile seismic behaviour that are present in the current codes would not have been considered in the design. As a result, it would be expected that the building would not achieve 100% NBS. The increase in the hazard factor for Christchurch to 0.3 further reduces the %NBS score.

## **9.5 Occupancy**

The building has been assessed as “Earthquake Risk”. As a result the building is still acceptable to be occupied.



## 10. Conclusions

### 10.1 Building Capacity Assessment

The building overall has been assessed as having a seismic capacity of 43% NBS and is therefore classified as 'Earthquake Risk'.

#### **Gymnasium**

The critical structural weakness for this building is the rafters of the steel portal frames which support the steel roof system and transfer the roof lateral load down to the foundations. These steel structural elements rated 43% NBS.

The steel portal frames lacks adequate roof and wall bracing to transfer the roof lateral load down to the foundation. The presence of reinforced concrete masonry walls along the perimeter of the portal frames helps to brace the lateral load resisting system but needs additional roof compression strut and wall bracing to make the building structurally robust.

#### **Changing Room**

The building rated above 100%NBS.

#### **External Storage Area**

The building also rated above 50%NBS.

#### ***Building Horizontal Deflection***

The computed seismic horizontal deflection of the Gymnasium roof is 98 mm and 86 mm in the longitudinal and transverse direction respectively. These values are within the requirements of AS/NZS 1170.5:2004.

#### ***Pounding Effect***

There is an approximately 5 mm seismic gap between the Gymnasium and External Storage Room in the longitudinal direction. In the event of earthquake, each building will produce different period, there is a risk that they will pound each other. The pounding may cause cracks, localised member and connection damage at the possible point or area of impact. It is also possible that the cracks along the construction joint mentioned in the key damage observed may be attributed to some minor pounding.

### 10.2 Occupancy

The Wigram Gymnasium has been assessed as "Earthquake Risk". As a result the building is still acceptable to be occupied.



## 11. Recommendations

### **Recommendation**

GHD recommend the following:

- ▶ Minor repairs are undertaken to fill the cracks identified in the reinforced concrete masonry block walls.
- ▶ A strengthening scheme is developed to increase the seismic capacity of the Wigram Gymnasium to as near as practicable to 100%NBS, and at least 67%NBS. This will need to consider compliance with accessibility and fire requirements.



## 12. Limitations

### 12.1 General

This report has been prepared subject to the following limitations:

- ▶ Available drawings itemised in Section 5.3 were used in the assessment.
- ▶ The roof structure and foundations of the building were unable to be inspected.
- ▶ Foundations were not checked.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

### 12.2 Geotechnical Limitations

The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data by third parties.

Where drill hole or test pit logs, cone tests, laboratory tests, geophysical tests and similar work have been performed and recorded by others under a separate commission, the data is included and used in the form provided by others. The responsibility for the accuracy of such data remains with the issuing authority, not with GHD.

The advice tendered in this report is based on information obtained from the desk study investigation location test points and sample points. It is not warranted in respect to the conditions that may be encountered across the site other than at these locations. It is emphasised that the actual characteristics of the subsurface materials may vary significantly between adjacent test points, sample intervals and at locations other than where observations, explorations and investigations have been made. Subsurface conditions, including groundwater levels and contaminant concentrations can change in a limited time. This should be borne in mind when assessing the data.

It should be noted that because of the inherent uncertainties in subsurface evaluations, changed or unanticipated subsurface conditions may occur that could affect total project cost and/or execution. GHD does not accept responsibility for the consequences of significant variances in the conditions and the requirements for execution of the work.

The subsurface and surface earthworks, excavations and foundations should be examined by a suitably qualified and experienced Engineer who shall judge whether the revealed conditions accord with both the assumptions in this report and/or the design of the works. If they do not accord, the Engineer shall modify advice in this report and/or design of the works to accord with the circumstances that are revealed.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based.




Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances which arise from the issue of the report which have been modified in any way as outlined in Section 8.



Appendix A

# Geotechnical Investigation Reports and Analysis

DEPTH IN METERS BELOW GROUND LEVEL




CLIENT : GHD  
LOCATION : Christchurch Various (CCC Properties)  
DATE : 2-4-2012  
OPERATOR : H. Pardoe  
REMARK 1 : CPTu23  
REMARK 2 : Effective Refusal

JOB # : 10386  
TEST # : 23

**McMILLAN**  
DRILLING SERVICES  
120 High St Southbridge CANTERBURY NZ  
Ph +64 3 324 2571 Fax +64 3 324 2431  
[www.drilling.co.nz](http://www.drilling.co.nz)

# PIEZOCONE PENETROMETER TEST (CPTU) INTERPRETIVE REPORT



Job No: 10386  
 CPT No: CPTu23  
 Project: GHD  
 Location: Christchurch Various (CCC Properties)

Date: 2-4-2012  
 Operator: H. Pardoe  
 Remark: Effective Refusal



## Appendix B

# Photographs



**Photograph 1** View from Corsair Drive.



**Photograph 2** Concrete masonry changing rooms.



**Photograph 3      Cracking between external storage room and main building.**



**Photograph 4      View of connection between external storage room and main building.**



**Photograph 5** North-eastern face of the building.




**Photograph 6** Cracking in concrete masonry wall.



**Photograph 7** Further cracking in concrete masonry wall.



**Photograph 8** South-eastern face of building.



**Photograph 9** Portal frame knee joint connection.



**Photograph 10** View of internal roof bracing.



**Photograph 11** Steel girts between portal frames.



**Photograph 12** Portal frame base connection.



**Photograph 13** Connection between steel portal frame and infill masonry wall.



**Photograph 14** Close-up of steel girts between portal frames.




**Photograph 15** Portal frame bracing connections.



**Photograph 16** Bracing between portal frames.



**Photograph 17**    **Extended roof area over mezzanine viewing platform.**



**Photograph 18**    **Connection between steel stairs and concrete masonry wall.**



**Photograph 19** Further connection between steel stairs and concrete masonry wall.




**Photograph 20** Steel RHS posts supporting steel stairs.



## Appendix C

# Existing Drawings



PLAN  
Scale 1:200

LEGEND

- KERB & CHANNEL
- KERB ONLY
- TIMBER BATTENING
- TK TOP OF KERB
- CL COVER LEVEL
- IL INVERT LEVEL

NOTES

1. ORIGIN OF LEVELS - N.E. CORNER OF BOTTOM STEP AT ENTRANCE TO N°2 OFFICERS MESS (RL 32.150 CDB)
2. CONTOURS SHOWN ARE EXISTING GROUND LEVEL CONTOURS
3. UNLESS INDICATED OTHERWISE LEVELS SHOWN THUS +32.15 ARE FINISHED SEAL LEVELS.
4. FOR DETAILS OF SOAKPIT REFER PLAN 6/2002/2/7634/1 R1
5. FOR DETAILS OF S.W. SUMP, KERB AND CHANNEL, KERB ONLY AND TIMBER BATTENING REFER PLAN 6/2002/4/7634/1 R6
6. ALL PIPEWORK IS TO BE CARRIED OUT IN ACCORDANCE WITH CDB STANDARD SPECIFICATION 1978 - SEWERAGE & STORMWATER WORKS AND CDB STANDARD DETAIL PLANS - 8000 SERIES
7. AREAS ADJACENT TO SITEWORKS DISTURBED BY CONSTRUCTION TO BE MARRIED INTO EXISTING GROUND LEVELS AND GRASSED.

BY	CHECKED	DATE	JBS HUIZING
Designed NJG			CHIEF CIVIL ENGINEER
Drawn NJG		2-82	
Supervised		3-82	
RECOMMENDED			
AMENDMENTS	BY	APPD. DATE	

Ministry of Works and Development  
CIVIL ENGINEERING CHRISTCHURCH  
CHRISTCHURCH RESIDENCY  
J.J. CHESTERMAN Commissioner

MINISTRY OF DEFENCE CHRISTCHURCH  
RNZAF BASE WIGRAM  
GYMNASIUM COMPLEX  
CONSTRUCTION DETAILS

ORIGINAL SCALES	AS SHOWN	FILE	
W.A.R. N° 8255		339-43.5	
JOB	CODE	SHEET	REVISION
6/300/97	7634	1	



Whole numbers x mm  
Decimalised expressions = m  
unless indicated otherwise



CONTRACTORS ACCESS FROM CAUDRON ROAD ENTRANCE

Springs Road

Women's Barracks

238

Grebe Place

Car Park

Harvard Lounge

Gymnasium FFL 32.300

Radio Building

LEGEND

- EXISTING TREES CONTRACTOR TO ENSURE THESE ARE NOT DAMAGED DURING CONTRACT
- TREES TO BE REMOVED BY CONTRACTOR AND REPLANTED - POSITIONS TO BE ADVISED

N.B.

THE CONTRACTOR SHALL BE RESTRICTED TO THE CONFINES OF THE SITE AND ACCESS TO THE SITE AS SHOWN ABOVE ACCESS TO ANY OTHER AREAS ON THE BASE WILL REQUIRE THE PRIOR APPROVAL OF THE BASE COMMANDER

NOTES

- SOAK PITS TO BE PROVIDED BY CONTRACTOR - 4M DEEP
- SUMPS AND STORMWATER DRAINAGE TO BE DONE BY THE CONTRACTOR
- LANDSCAPING & ROADING WORKS ARE SHOWN ON RELEVANT DRAWINGS
- ROADING, KERBS, CHANNELS, PATHS TO BE DONE BY CONTRACTOR
- WATER SUPPLY BY OTHERS TO END ADJACENT TO MANHOLE

R1 Sheet title will be changed		DAHS	2/8/81	DESIGNED	GMC	CHECKED	DATE
				DRAWN	JAS		11/81
				CHECKED			
				APPROVED			
AMENDMENTS		BY	APPD.	DATE			

GO MCKIMMIN  
GOVERNMENT ARCHITECT

RW TAYLOR  
DISTRICT ARCHITECT

Ministry of Works and Development

ARCHITECTURAL  
CHRISTCHURCH

JJ Chesterman Commissioner

MINISTRY OF DEFENCE - CHRISTCHURCH  
RNZAF BASE WIGRAM  
GYMNASIUM COMPLEX

SITE PLAN AND INDEX

INDEX OF DRAWINGS

ARCHITECTURAL

101	SITE PLAN AND INDEX	121	SECTIONS E,F,G,H
102	FLOOR PLANS AND DRAINAGE PLAN	122	SECTIONS I,J,K,L,M,N,O,P,Q,R
103	CARCASE PLANS	123	DETAILS
104	ELEVATIONS 1 AND 2	124	DETAILS
105	ELEVATIONS 3 AND 4		
106	SECTIONS A-A AND B-B		
107	SECTIONS C-C AND D-D		
108	CONSTRUCTION DETAILS 1-14, 37		SITEWORKS
109	CONSTRUCTION DETAILS 15-23, 38, 39	1	CONSTRUCTION DETAILS
110	CONSTRUCTION DETAILS 24-36	2	SETTING OUT AND IRRIGATION DETAILS
111	DOOR SCHEDULE AND DETAILS, WATER HEATER & CUPD SPACE 103	6/2002/4/7634/1 R6 STD DRAINAGE DETAILS	
112	WINDOW SCHEDULE, PLAN AND DETAILS		
113	PIPEWORK ISOMETRIC, PLUMBING FITTINGS, DRAINAGE DETAILS, ETC		
114	TILING PLAN AND DETAILS AND STAIR DETAILS		
115	MISCELLANEOUS DETAILS		
116	FITTINGS 1-8		
117	COURT MARKINGS, FLOOR FIXINGS AND EQUIPMENT		
118	INTERNAL FINISHING DETAILS AND ELEVATIONS, SHOE SHELF		
119	SCHEDULE OF FINISHES		
120	STAIRCASE PLAN, ELEVATION, SECTION AND DETAILS		

STRUCTURAL

200/1	STANDARD SHEET - REINFORCED CONCRETE	211	STEELWORK DETAILS
200/2	STANDARD SHEET - MASONRY	212	MISCELLANEOUS STEELWORK DETAILS
201	FOUNDATION PLAN AND DETAILS		
202	FOUNDATION DETAILS		
203	BLOCKWORK PLAN		
204	BLOCKWORK DETAILS		
205	PORTAL AND STEEL FRAME LAYOUT		
206	ROOF PLAN AND STEEL FRAME LAYOUT		
207	STEEL DETAILS		
208	STEEL DETAILS		
209	STEELWORK: DETAILS AND SECTIONS		
210	STEELWORK DETAILS AND SECTIONS		

ELECTRICAL

501	LOCATION OF LIGHTING, LUMINAIRE SCHEDULE AND SYMBOLS
502	LOCATION OF POWER AND SITE PLAN
503	DISTRIBUTION BOARD No. 1, NOTES AND CARPARK LIGHTING

MECHANICAL

601	HOT AND COLD WATER, F.H.R., AND VENTILATION LAYOUT
602	AMENITIES BLOCK - HOT AND COLD WATER LAYOUT

ORIGINAL  
SCALE 1:500

FILE 43/913

JOB	CODE	SHEET	REVISION
6/300/97	7601	101	R1

Whole numbers = mm.  
Decimalised expressions = m  
Unless indicated otherwise






Diagram illustrating the dimensions for offset lap joints. The diagram shows two overlapping bars. Key dimensions and labels include:







- FOR LAP LENGTHS SEE TABLE
- 12d MIN.
- 15d MAX.
- 9d MIN. RAD.
- 15d MAX. RAD.
- d=7mm

**NOTES**


1. NO TRIMMER BARS AT SIDES OF OPENINGS 300 mm OR LESS IN LENGTH.
2. TRIMMER BARS ARE ADDITIONAL TO WALL REINFORCEMENT.




SEE TABLE C  
LAP LENGTHS





INGS, THE FOLLOWING RULES APPLY —

RE ARE GIVEN IN MILLIMETRES. 

OVER ARE GIVEN IN METRES DECIMALISED TO THREE PLACES. 

EXCEPT —

e.g.  65 m










e.g.  24.5 mm



N.B. UNLESS OTHERWISE SPECIFIED OR DETAILED ON THE DRAWINGS, THESE NOTES AND DETAILS SHALL APPLY BUT INCLUSION OF THIS SHEET (200/1) IN THIS CONTRACT SET DOES NOT IMPLY THAT ALL DETAILS OCCUR IN THIS CONTRACT.  
DO NOT SCALE OFF DRAWINGS. IF IN DOUBT, ASK

AMENDMENTS		BY	APPD.	DATE	RD.	NUMBER	COMM.	DATE	REMARKS
1:1	LOCAL OR TRACING No.	1:1			1:2			1:5	
1977									

Whole numbers in  
Decimalised expressions & in  
unless indicated otherwise



NOTATIONS:- D12-12mm DIAMETER DEFORMED BAR  
- R4-4mm DIAMETER PLAIN ROUND BAR  
- LAR:- LAPPED AT RANDOM IN A STAGGERED PATTERN

2) THE FORMING OF CHASES, RECESSES OR THE EMBEDMENT OF TIMBER GROUNDS, PRES AND ELECTRICAL CONDUIT REQUIRE THE APPROVAL OF THE SITE SUPERVISOR.

3) CONSTRUCTION TO BE "ALL CELLS GROUTED" UNLESS OTHERWISE APPROVED.

4) MINIMUM GROUT STRENGTH 17.5 MPa AT 28 DAYS  
MINIMUM MORTAR STRENGTH 12.5 MPa AT 28 DAYS, BUT 8MPa FOR VENEERS

5) DEFINITIONS:

R.H.M	—	REINFORCED	HOLLOW	MASONRY.
R.C.M	—	"	CAVITY	"
R.M	—	"	MASONRY	"
R.C	—	"	CONCRETE	"

6) UNIT TYPES ARE REFERRED TO BY STANDARDS NUMBERS ALLOCATED BY THE NZ CONCRETE MASONRY ASSOCIATION eg TYPE 16 OPEN END BOND BEAM UNIT

7) THIS SHEET TO BE READ IN CONJUNCTION WITH SPECIFICATION AND DRAWINGS.

8) MATERIALS AND WORKMANSHIP TO BE IN ACCORDANCE WITH NZS 4210P UNLESS OTHERWISE SHOWN.

NOTES AND DETAILS SHALL APPLY BUT INCLUSION OF DETAILS OCCUR IN THIS CONTRACT.

						BY	CHECKED	DATE
						Drawn	<i>[Signature]</i>	7/79
						Dwg sup'd	<i>[Signature]</i>	7/79
2	GENERAL REVISION	<i>[Signature]</i>	<i>[Signature]</i>	9/82		Designed		
1	GENERAL REVISION	<i>[Signature]</i>	<i>[Signature]</i>	7/80		Rec'm'd		
AMENDMENTS					BY	APPD.	DATE	
STRUCTURAL DESIGN OFFICE								



J.B.S. HUIZING CHIEF CIVIL ENGINEER	 <b>Ministry of Works and Development</b>
G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER APPROVED	
<b>CIVIL ENGINEERING HEAD OFFICE</b>	
R.G. NORMAN Commissioner	


MINISTRY OF DEFENCE — CHRISTCHURCH.  
R.N.Z.A.F. BASE WIGRAM.  
GYMNASIUM COMPLEX.


---

MASONRY  
STANDARD STRUCTURAL DETAILS AND NOTES

ORIGINAL Scales		FILE PW 81/10/1	
TO	JOB 0 / 10 /	CODE 1 7002	SHEET 200/2
	JOB	CODE	SHEET
DESIGN	6 / 300 / 97	7602	200/2
			REVISION
			R2




				BY		CHECKED	DATE	J.B.S. HUIZING CHIEF CIVIL ENGINEER		 Ministry of Works and Development		MINISTRY OF DEFENCE - CHRISTCHURCH R.N.Z.A.F. BASE WIGRAM GYMNASIUM COMPLEX		ORIGINAL SCALE 1:100, 1:20		FILE 43/9/14				
				DRAWN		<i>G. J. Owen</i>	12/81	G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER		CIVIL ENGINEERING CHRISTCHURCH										
				SUPERVISED		<i>G. J. Owen</i>	4.82													
				DESIGNED		<i>G.H.F.</i>	4.82													
				RECOMMENDED		<i>G.H.F.</i>	4.82													
AMENDMENTS				BY	APPD.	DATE	APPROVED <i>P.R. Harrow</i> 4/92 P.R. HARROW D.S.E.		STRUCTURAL DESIGN OFFICE J.J. CHESTERMAN Commissioner		FOUNDATION PLAN & DETAILS		JOB 6 / 300 / 97		CODE 7602		SHEET 201		REVISION	
LOCAL OR TRADING No				THIS DRAWING IS THE PROPERTY OF THE CROWN AND IS NOT TO BE REPRODUCED OR DISTRIBUTED WITHOUT THE WRITTEN AUTHORITY OF THE GOVERNMENT OF THE ISLAND OF COOK																




Whole numbers > 9 mm  
Decimised expressions > 9 mm  
unless indicated otherwise


Whole numbers = mm  
Decimised expressions = m  
unless indicated otherwise





Tie beam added to 15-15.				10/83				BY				CHECKED				DATE			
DRAWN				G.H.F. McKENZIE				12/81				4.82				4.82			
SUPERVISED				G.H.F. McKENZIE				4.82				4.82				4.82			
DESIGNED				G.H.F. McKENZIE				4.82				4.82				4.82			
RECOMMENDED				G.H.F. McKENZIE				4.82				4.82				4.82			
APPROVED				G.H.F. McKENZIE				4.82				4.82				4.82			
PR. HARROW D.S.E.				G.H.F. McKENZIE				4.82				4.82				4.82			
AMENDMENTS				BY				APPD.				DATE							
LOCAL OR TRACING No.				1:1				1:2				1:5							
P.W. 482-A1				Rev. JAN 1997															
J.B. SHUIZING, CHIEF CIVIL ENGINEER				G.H.F. McKENZIE, CHIEF				STRUCTURAL ENGINEER				APPROVED				PR. HARROW D.S.E.			
Ministry of Works and Development				CIVIL ENGINEERING CHRISTCHURCH				STRUCTURAL DESIGN OFFICE				J.J. CHESTERMAN, Commissioner							
MINISTRY OF DEFENCE - CHRISTCHURCH				RNZAF BASE WIGRAM GYMNASIUM COMPLEX				FOUNDATION DETAILS											
ORIGINAL SCALES				1:20				FILE				43/9/14							
JOB				CODE				SHEET				REVISION							
6 / 300 / 97				7602				202				R1							
Whole numbers = mm				Decimalised expressions = m				unless indicated otherwise											



DRAWN BY: <i>[Signature]</i> CHECKED: <i>[Signature]</i> DATE: 12/81				J.B.S. HUIZING, CHIEF CIVIL ENGINEER		MINISTRY OF DEFENCE - CHRISTCHURCH		ORIGINAL SCALE: 1:50		FILE: 43/9/14	
SUPERVISED: <i>[Signature]</i> DATE: 4/82				G.H.F. MCKENZIE, CHIEF		R.N.Z.A.F. BASE WIGRAM					
DESIGNED: <i>[Signature]</i> DATE: 4/82				STRUCTURAL ENGINEER		GYMNASIUM COMPLEX					
RECOMMENDED: <i>[Signature]</i> DATE: 4/82				APPROVED: <i>[Signature]</i> DATE: 4/82		BLOCKWORK PLAN		JOB: 6/300/97		CODE: 7602	
AMENDMENTS				BY: APPD: DATE:		STRUCTURAL DESIGN OFFICE		SHEET: 203		REVISION:	
						J.J. CHESTERMAN, Commissioner					



1/3-3 added to sheet				J.B.S. HUIZING CHIEF CIVIL ENGINEER				MINISTRY OF DEFENCE - CHRISTCHURCH R.N.Z.A.F. BASE WIGRAM GYMNASIUM COMPLEX				ORIGINAL SCALES 1:100, 1:20, 1:10		FILE 43/9/14	
2/ Side wall bond beam detail & Detail E altered Notes on Details B & D added				G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER				CIVIL ENGINEERING CHRISTCHURCH				JOB 61300/97		CODE 7602	
				APPROVED P.R. HARROW, D.S.E.				STRUCTURAL DESIGN OFFICE J.J. CHESTERMAN Commissioner				SHEET 204		REVISION R2	
AMENDMENTS				BY	APPD.	DATE									








DRAWN BY CHECKED DATE				J.B. SHUIZING CHIEF CIVIL ENGINEER		Ministry of Works and Development		MINISTRY OF DEFENCE - CHRISTCHURCH		ORIGINAL SCALE 1:100		FILE 43/9/16	
SUPERVISED BY				G.H.F. MCKENZIE CHIEF		CIVIL ENGINEERING		R.N.Z.A.F. BASE WIGRAM					
DESIGNED BY				STRUCTURAL ENGINEER		CHRISTCHURCH		GYMNASIUM COMPLEX					
RECOMMENDED BY				APPROVED		STRUCTURAL DESIGN OFFICE		PORTAL & STEEL FRAME LAYOUT		JOB 6/300/97.		CODE 7602.	
AMENDMENTS				BY APPD. DATE		J.J. CHESTERMAN Commissioner				SHEET 205.		REVISION	
LOCAL OR TRADING No.													

INCHES  
CENTIMETRES


ORIGINAL SIZE  
A1

Rev JAN 97




1. 3/8" x 3/8" added to Plan at Datum +3.000				2. 1/2" x 1/2" added to Plan at Datum +3.000	3. 1/2" x 1/2" added to Plan at Datum +3.000	BY J.B.S. HUIZING CHECKED G.H.F. MCKENZIE DATE 12/81	J.B.S. HUIZING CHIEF CIVIL ENGINEER	 Ministry of Works and Development	CIVIL ENGINEERING CHRISTCHURCH	MINISTRY OF DEFENCE - CHRISTCHURCH	ORIGINAL SCALES 1:100	FILE 43/914		
DRAWN				12/81		G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER	MINISTRY OF DEFENCE - CHRISTCHURCH			R.N.Z.A.F. BASE WIGRAM				
SUPERVISED				4/82		APPROVED	STRUCTURAL DESIGN OFFICE			GYMNASIUM COMPLEX				
DESIGNED				4/82		J.J. CHESTERMAN Commissioner								
RECOMMENDED				4/82										
AMENDMENTS				BY	APPD.	DATE				ROOF PLAN & STEEL FRAME LAYOUT.	JOB 6/300/97.	CODE 7602	SHEET 206	REVISION R1

Whole number dimensions in millimetres unless indicated otherwise










4, 5, 6 added to sheet 210 altered P.W. 492-A1 Rev. JAN. 1977				3/84 3/82 4/82 4/82 4/82				J.B.S. HUIZING CHIEF CIVIL ENGINEER G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER APPROVED P.R. HARROW, D.S.E.				Ministry of Works and Development CIVIL ENGINEERING CHRISTCHURCH STRUCTURAL DESIGN OFFICE J.J. CHESTERMAN Commissioner				MINISTRY OF DEFENCE - CHRISTCHURCH R.N.Z.A.F. BASE WIGRAM GYMNASIUM COMPLEX STEELWORK DETAILS				ORIGINAL SCALES 1:10 FILE 43/9/14				JOB 6/300/97. CODE 7602 SHEET 210. REVISION R1.			
---	--	--	--	--------------------------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--




DRAWN BY: <i>[Signature]</i> 3/84				BY: <i>[Signature]</i> 3/82		CHECKED: <i>[Signature]</i> 3/82		DATE: 3/82		J.B.S. HUIZING CHIEF CIVIL ENGINEER		Ministry of Works and Development		MINISTRY OF DEFENCE - CHRISTCHURCH R.N.Z.A.F. BASE WIGRAM GYMNASIUM COMPLEX		ORIGINAL SCALES: 1:20, 1:10		FILE: 43/914	
SUPERVISED: <i>[Signature]</i> 4/82				DESIGNED: <i>[Signature]</i> 4/82		RECOMMENDED: <i>[Signature]</i> 4/82		APPROVED: <i>[Signature]</i> 4/82		G.H.F. MCKENZIE CHIEF STRUCTURAL ENGINEER		CIVIL ENGINEERING CHRISTCHURCH		STRUCTURAL DESIGN OFFICE		JOE: 6/300/97.		CODE: 7602	
AMENDMENTS				BY		APPD.		DATE		P.H. HARRISON D.S.E.		J.J. CHESTERMAN Commissioner		STEELWORK DETAILS.		SHEET: 211		REVISION: R1.	





## Appendix D

# Rebar Scanning Results



Customer: ---


Location: ---Operator: ---

Comment:

Date / Time: 2012-07-09 09:58:30

SSN: 31311003

[mm]




Customer: ---

Location: ---

Operator: ---

Comment:




Customer: ---

Location: ---

Operator: ---

Comment:



Customer: ---

Location: ---                      Operator: ---

Comment:



Appendix E

# CERA Building Evaluation Form

## Detailed Engineering Evaluation Summary Data

V1.11

## Location

Building Name:	Wigram Gymnasium		Reviewer:	Stephen Lee	
	Unit	No: Street	CPEng No:	1006840	
Building Address:	29 Springs Road				
Legal Description:					
	Degrees	Min	Sec	Company project number:	51/30596/23
GPS south:				Company phone number:	04 472 0799
GPS east:				Date of submission:	
				Inspection Date:	18/1/12
Building Unique Identifier (CCC):				Revision:	0
				Is there a full report with this summary?	yes

## Site

Site slope:	flat	Max retaining height (m):	
Soil type:	mixed	Soil Profile (if available):	
Site Class (to NZS1170.5):	D	If Ground improvement on site, describe:	
Proximity to waterway (m, if <100m):		Approx site elevation (m):	
Proximity to clifftop (m, if < 100m):			
Proximity to cliff base (m, if <100m):			

## Building

No. of storeys above ground:	1	single storey = 1	Ground floor elevation (Absolute) (m):	
Ground floor split?	no		Ground floor elevation above ground (m):	
Storeys below ground:	0		if Foundation type is other, describe:	
Foundation type:	strip footings	height from ground to level of uppermost seismic mass (for IEP only) (m):	11	
Building height (m):	11.00	Date of design:	1976-1992	
Floor footprint area (approx):				
Age of Building (years):	26			
Strengthening present?	no	If so, when (year)?		
Use (ground floor):	other (specify)	And what load level (%g)?		
Use (upper floors):	other (specify)	Brief strengthening description:		
Use notes (if required):	Recreation Gymnasium			
Importance level (to NZS1170.5):	IL2			

## Gravity Structure

Gravity System:	frame system	rafter type, purlin type and cladding	
Roof:	steel framed	slab thickness (mm)	
Floors:	concrete flat slab	beam and connector type	
Beams:	steel non-composite	typical dimensions (mm x mm)	
Columns:	structural steel	thickness (mm)	
Walls:	partially filled concrete masonry		

<u>Lateral load resisting structure</u>			
Lateral system along:	welded and bolted steel moment frame	<b>Note: Define along and across in detailed report!</b> 0.85 from parameters in sheet	note typical bay length (m)
Ductility assumed, $\mu$ :	2.00		
Period along:	0.85		
Total deflection (ULS) (mm):			estimate or calculation? <b>calculated</b>
maximum interstorey deflection (ULS) (mm):			estimate or calculation?
Lateral system across:	welded and bolted steel moment frame	0.00	note typical bay length (m)
Ductility assumed, $\mu$ :	2.00		
Period across:	0.85		estimate or calculation? <b>calculated</b>
Total deflection (ULS) (mm):			estimate or calculation?
maximum interstorey deflection (ULS) (mm):			estimate or calculation?
<u>Separations:</u>			
north (mm):		leave blank if not relevant	
east (mm):			
south (mm):			
west (mm):			
<u>Non-structural elements</u>			
Stairs:	steel		describe supports
Wall cladding:	profiled metal		describe
Roof Cladding:	Metal		describe
Glazing:	aluminium frames		
Ceilings:	none		
Services(list):			
<u>Available documentation</u>			
Architectural:	none		original designer name/date
Structural:	none		original designer name/date
Mechanical:	none		original designer name/date
Electrical:	none		original designer name/date
Geotech report:	none		original designer name/date
<u>Damage</u>			
Site:			Describe damage:
(refer DEE Table 4-2)	Site performance: No ground damage observed.		
Settlement:	none observed		notes (if applicable):
Differential settlement:	none observed		notes (if applicable):
Liquefaction:	none apparent		notes (if applicable):
Lateral Spread:	none apparent		notes (if applicable):
Differential lateral spread:	none apparent		notes (if applicable):
Ground cracks:	none apparent		notes (if applicable):
Damage to area:	none apparent		notes (if applicable):

<b>Building:</b>		Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio:	<input type="text" value="0%"/>	Describe how damage ratio arrived at: <input type="text"/>
	Describe (summary):	<input type="text" value="Less than 5% damage if at all."/>	
Across	Damage ratio:	<input type="text" value="0%"/>	$Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$
	Describe (summary):	<input type="text" value="Less than 5% damage if at all."/>	
Diaphragms	Damage?:	<input type="text" value="no"/>	Describe: <input type="text"/>
CSWs:	Damage?:	<input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:	Damage?:	<input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:	Damage?:	<input type="text" value="yes"/>	Describe: <input type="text"/>

<b>Recommendations</b>			
	Level of repair/strengthening required:	<input type="text" value="significant structural and strengthening"/>	Describe: <input type="text"/>
	Building Consent required:	<input type="text" value="no"/>	Describe: <input type="text"/>
	Interim occupancy recommendations:	<input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before:	<input type="text" value="43%"/>	##### %NBS from IEP below If IEP not used, please detail assessment methodology: <input type="text"/>
	Assessed %NBS after:	<input type="text" value="43%"/>	
Across	Assessed %NBS before:	<input type="text" value="43%"/>	##### %NBS from IEP below
	Assessed %NBS after:	<input type="text" value="43%"/>	

<b>IEP</b>			
Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.			
Period of design of building (from above): 1976-1992		h <sub>n</sub> from above: 11m	
Seismic Zone, if designed between 1965 and 1992:	<input type="text"/>	not required for this age of building	<input type="text"/>
		not required for this age of building	<input type="text"/>
	Period (from above):	along	across
	(%NBS) <sub>nom</sub> from Fig 3.3:	<input type="text" value="0.85"/>	<input type="text" value="0.85"/>
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0		<input type="text"/>	
Note 2: for RC buildings designed between 1976-1984, use 1.2		<input type="text"/>	
Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)		<input type="text"/>	
		along	across
	Final (%NBS) <sub>nom</sub> :	<input type="text" value="0%"/>	<input type="text" value="0%"/>
<b>2.2 Near Fault Scaling Factor</b>		Near Fault scaling factor, from NZS1170.5, cl 3.1.6: <input type="text"/>	
		along	across
	Near Fault scaling factor (1/N(T,D), <b>Factor A</b> :	<input type="text" value="#DIV/0!"/>	<input type="text" value="#DIV/0!"/>

**2.3 Hazard Scaling Factor**

Hazard factor Z for site from AS1170.5, Table 3.3:

Z<sub>1992</sub>, from NZS4203:1992Hazard scaling factor, **Factor B:**

#DIV/0!

**2.4 Return Period Scaling Factor**

Building Importance level (from above):

2

Return Period Scaling factor from Table 3.1, **Factor C:****2.5 Ductility Scaling Factor**

Assessed ductility (less than max in Table 3.2)

Ductility scaling factor: =1 from 1976 onwards; or =k<sub>μ</sub>, if pre-1976, from Table 3.3:

along

across

Ductility Scaling Factor, **Factor D:**

1.00

1.00

**2.6 Structural Performance Scaling Factor:**

Sp:

Structural Performance Scaling Factor **Factor E:**

#DIV/0!

#DIV/0!

**2.7 Baseline %NBS, (NBS%)<sub>b</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E**

%NBS:

#DIV/0!

#DIV/0!

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

**3.1. Plan Irregularity, factor A:**

Insignificant

1

**3.2. Vertical irregularity, Factor B:**

severe

0.4

**3.3. Short columns, Factor C:**

Insignificant

1

**3.4. Pounding potential**

Pounding effect D1, from Table to right

1.0

Height Difference effect D2, from Table to right

1.0

Therefore, Factor D:

1

**3.5. Site Characteristics**

Insignificant

1

Table for selection of D1	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

**3.6. Other factors, Factor F**

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum

Rationale for choice of F factor, if not 1

Along

Across

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any:

Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

**3.7. Overall Performance Achievement ratio (PAR)**

0.00

0.00

**4.3 PAR x (%NBS)<sub>b</sub>:**

PAR x Baseline %NBS:

#DIV/0!

#DIV/0!

**4.4 Percentage New Building Standard (%NBS), (before)**

#DIV/0!



## GHD

Level 11, Guardian Trust House  
15 Willeston street, Wellington 6011  
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

### © GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

### Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Dioselo Cagandahan	Stephen Lee		Nick Waddington		2/10/12