

Christchurch City Council BE 1119 EQ2 Andrews Crescent



QUANTITATIVE ASSESSMENT REPORT FINAL

- Rev B
- 04 June 2013



Christchurch City Council BE 1119 EQ2 Andrews Crescent

QUANTITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 04 June 2013

Sinclair Knight Merz 142 Sherborne Street Saint Albans PO Box 21011, Edgeware Christchurch, New Zealand Tel: +64 3 940 4900 Fax: +64 3 940 4901 Web: www.skmconsulting.com

COPYRIGHT: The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

LIMITATION: This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.



Contents

1.	Executive Summary	1
2.	Introduction	4
3.	Compliance	5
4.	Earthquake Resistance Standards	9
5.	Building Details	11
6.	Available Information and Assumptions	17
7.	Results and Discussions	22
8.	Conclusion	24
9.	Limitation Statement	25
10.	Appendix 1 – Photos	26
11.	Appendix 2 – CERA Standardised Report Form	74



Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
А	10/05/2013	G Fletcher	N Calvert	10/05/2013	Draft for Client Approval
В	04/06/2013	N Calvert	N Calvert	04/06/2013	Final for Issue

Approval

	Signature	Date	Name	Title
Author	Mal Mon	04/06/2013	Nigel Chan	Structural Engineer
Approver	Maurt	04/06/2013	Nick Calvert	Senior Structural Engineer

Distribution of copies

Revision	Copy no	Quantity	Issued to
А	1	1	Christchurch City Council
В	1	1	Christchurch City Council

Printed:	4 June 2013
Last saved:	4 June 2013 04:21 PM
File name:	PRO 1119 Andrews Crescent Housing Complex Quantitative Final.docx
Author:	Nigel Chan
Project manager:	Nick Calvert
Name of organisation:	Christchurch City Council
Name of project:	Christchurch City Council Structures Panel
Name of document:	Andrews Crescent Housing Complex – Quantitative Report
Document version:	В
Project number:	ZB01276.215



1. Executive Summary

1.1. Background

A Quantitative Assessment was carried out on the housing complex located at Andrews Crescent. The site comprises of nine buildings, with each building housing 4 separate living units, in total there are 36 livings units. An aerial photograph illustrating these areas is shown below in Figure 1. Detailed descriptions outlining the buildings age and construction type is given in Section 5 of this report.



Figure 1 Aerial Photograph of Andrews Crescent

This Quantitative report for the building structure is based on the Engineering Advisory Group's "Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings" (draft) July 2011, visual inspections on 16/10/12, cover meter survey 29/11/12 and an intrusive investigation on 20/12/12. Limited drawings of Andrews Crescent show proposed additional cottages dated 1970 which were not constructed.



1.2. Key Damage Observed

Key damage observed includes:

- Cracks in the perimeter foundations
- Cracks in the internal wall and ceiling lining
- Cracks in concrete steps
- Settlement of the foundations

Refer to section 5 for further details of the damage discovered and section 6 for survey results.

1.3. Critical Structural Weaknesses

No potential critical structural weaknesses have been identified for these buildings.

1.4. Indicative Building Strength

As described in the Engineering Advisory Group's "Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings" (draft) July 2011, we have assessed the capacity of the buildings as a percentage new building standard seismic resistance using the quantitative method. Our assessment included consideration of geotechnical conditions, existing earthquake damage to the buildings and structural engineering calculations to assess both strength and ductility/resilience.

The assessments were based on the following:

- On-site investigation to assess the extent of existing earthquake damage including limited intrusive investigation.
- Qualitative assessment of critical structural weaknesses (CSWs) based on review of available structural drawings and inspection where drawings were not available.
- An intrusive geotechnical investigation has been undertaken. We have based this report on the information contained within this report knowledge of the site.
- Assessment of the strength of the existing structures taking account of the current condition.

Any building that is found to have a seismic capacity less than 33% of the new building standard (NBS) is required to be strengthened up to a target capacity of 67%NBS but at least 34%.

Based on the information available, and using the Quantitative Assessment Procedure, the buildings original and post earthquake capacity has been assessed to be in the order of 86%NBS for Block D and 67% NBS for the other 8 buildings. The buildings are therefore not potentially earthquake prone.



1.5. Recommendations

Based on the findings of this assessment indicating the buildings are in the order of 86% for Block D and 67% for the other 8 buildings, no strengthening is required in order to comply with Christchurch City Council (CCC) policy – Earthquake-prone dangerous & insanitary buildings policy 2010.

It is recommended that:

- a) There is no damage to any of the buildings that would cause the buildings to be unsafe to occupy.
- b) We consider that barriers around the buildings are not necessary.
- c) The floors were found to be out of level and it is recommended the foundations be relevelled or rebuilt, however the levelness of the foundation does not affect the %NBS of the buildings.



2. Introduction

Sinclair Knight Merz were engaged by Christchurch City Council to carry out a Quantitative Assessment of the seismic performance of Andrews Crescent.

The scope of this quantitative analysis includes the following:

- Analysis of the seismic load carrying capacity of the buildings compared with current seismic loading requirements or New Buildings Standard (NBS). It should be noted that this analysis considers the buildings in its damaged state where appropriate.
- Identify any critical structural weaknesses which may exist in the buildings and include these in the assessed %NBS of the structure.
- Preparation of a summary report outlining the areas of concern in the buildings.

The recommendations from the Engineering Advisory Group^1 were followed to assess the likely performance of the structures in a seismic event relative to the New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3^2 .

At the time of this report, an intrusive site investigation had been carried out, looking inside the roof space and the sub floor. Construction drawings were not made available. The building description below is based on a review of our inspections.

² <u>http://www.dbh.govt.nz/seismicity-info</u>

¹ EAG 2011, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury - Draft*, p 10



3. Compliance

This section contains a summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

3.1. Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.



It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

3.2. Building Act

Several sections of the Building Act are relevant when considering structural requirements:

3.2.1. Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

3.2.2. Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.



3.2.3. Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

3.2.4. Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

3.2.5. Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

3.2.6. Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

3.3. Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.



The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 34%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

3.4. Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Ministry of Business, Innovation and Employment can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance		Improvement of St	ructural Performance
					▶	Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)		The Building Act sets no required level of structural improvement	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		(unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Ľ,	Unacceptable	Unacceptable

Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times



5. Building Details

5.1. Building description

The Andrews Crescent Housing Complex (BE 1119) is located on Andrews Crescent, Spreydon, it is made up of 9 buildings, with 4 self-contained 1 bedroom residential units in each building. For the ease of identification, the buildings have been named Blocks A-I. Refer to figure 1 for an aerial photograph showing these allocations.

- Block A: Units 1, 3, 5, 7
- Block I: Units 2, 4, 6, 8
- Block B: Units 9, 11, 13, 15
- Block H: Units 10, 12, 14, 16
- Block C: Units 17, 19, 21, 23
- Block B: Units 18, 20, 22, 24
- Block D: Units 25, 27, 29, 31
- Block E: Units 33, 35, 37, 39
- Block F: Units 41, 43, 45, 47

The design and construction of each of the buildings are nearly identical. All the buildings are clad with a timber weatherboard exterior. Roofs are clad with heavy tile cladding except for building 7 on the north end of the complex which is clad with corrugated metal. A timber disabled access ramp is provided for Block B for units 9 and 11, and also building 1 for unit 7. Sketches of the typical building have been prepared based on site measurements and visual inspections. See figure 3 and figure 4 for a sketch of the foundation plan and ground floor plan respectively.

Drawings provided by the Christchurch City Council indicated proposed additional buildings dated 1970, which have not been constructed. We estimate the existing buildings were constructed pre 1965.





Figure 3 Sketch of foundation plan for typical building in Andrews Crescent





Figure 4 Sketch of ground floor plan for typical building in Andrews Crescent



5.2. Gravity Load Resisting system

The gravity load resisting structure of the buildings is made up of a timber framed roof, supported by timber framed walls and double skin brick party walls. These walls are then supported by concrete pile and concrete perimeter beam foundations.

5.3. Seismic Load Resisting system

For the purposes of this report the longitudinal direction of the buildings are defined as being in the direction parallel to the longest sides of the building and transverse direction is defined as being parallel to the shortest sides of the building.

Lateral load on the building is resisted by the lathe and plaster lined timber framed walls in the longitudinal direction and by the double skin brick party walls in the transverse direction. These loads are then resisted by the concrete pile and perimeter beam foundations. The loads are able to be distributed to the foundation elements by the timber floor diaphragm.

5.4. Building Damage

5.5. Block A - PRO 1119 B001

Internal damage

- Unit 5 has cracks in the bathroom ceiling (see photo 20)
- Unit 5 has cracks in the kitchen party wall (see photo 21)

External damage

Cracks were found around the entire perimeter foundation these were found to have a maximum crack width of 3mm and were found at the perimeter foundation openings (see photos 9, 11, 12, 15, 16, 17, 19, 25, 27)

5.6. Block I - PRO 1119 B009

Internal damage

Unit 4 has ceiling cracks beside the roof manhole in the hallway and also in the bathroom (see photos 36, 37, 38)

External damage

Cracks were found around the entire perimeter foundation. (see photo 30, 33, 40, 41, 43, 46, 47, 49) A maximum crack width of 5mm was found at the rear of unit 2.

5.7. Block B - PRO 1119 B002

Internal damage

- Unit 9 has 1mm crack at corner of doorway in the lounge area (see photo 59)
- Unit 9 has diagonal cracks in the bathroom lining (see photo 60, 61)



- Unit 9 has vertical cracks between the door frame junctions (see photo 62, 63)
- Unit 9 has diagonal crack beside the manhole in the hallway (see photo 65)
- Unit 11 has cracks in the lounge area above the doorway and also in the ceiling (see photo 67, 68)
- Unit 11 has a crack above the electrical meter box in the kitchen (see photo 70)
- Unit 11 has a crack above the back entrance doorway in the kitchen (see photo 71)
- Unit 15 has a crack above the doorway in the lounge area (see photo 76)
- Unit 15 has a diagonal crack beside the manhole in the hallway crack (see photo 78)

External damage

• Cracks were found around the entire perimeter foundation. (see photo 53, 55, 59, 75) These were found to have a maximum size of 2.5mm.

5.8. Block H - PRO 1119 B008

Internal damage

 No internal damage was found during the inspection. The floor was seen to be severely out of level from initial inspections (see photo 97, 109). Refer to Section 6.2 Survey.

External damage

Cracks were found around the entire perimeter foundation. (see photo 85, 86, 87, 88, 90, 92, 94, 100, 101, 104, 106, 112, 113, 115) A maximum crack width of over 5mm was found at the rear of unit 12.

5.9. Block C - PRO 1119 B003

Internal damage

• Unit 23 has a vertical crack between the lounge and kitchen door frames. (photo 117)

External damage

- Cracks were found around the perimeter foundation. (see photo 124, 127, 129, 132, 136)
- Concrete has spalled from the concrete perimeter foundation, exposing rusted reinforcing at the rear entrance of unit 23 (see photo 124). This damage does not appear to have come as a direct result of the earthquakes
- Concrete render has been displaced from the concrete perimeter foundation at the rear corner of unit 23 (see photo 119)
- Concrete steps leading up to the entrances of units 19 and 17 have cracked 2.5mm and 1mm respectively (see photo 121, 134)



5.10. Block G - PRO 1119 B007

Internal damage

Unit 22 has cracks in the interior lining in the kitchen and bathroom areas. (see photo 154, 155)

External damage

Cracks were found around the perimeter foundation. (see photo 138, 141, 142, 145, 148, 150, 152, 153, 154, 155). A maximum crack width was measured to be 11mm located outside the front entrance to unit 20.

5.11. Block D - PRO 1119 B004

Internal damage

- Unit 31 has cracks in the wall and ceiling junction in the kitchen area. (photo 159)
- Unit 27 has cracks between the cupboard and party wall. (see photo 167

External damage

- Front entrance steps to unit 31 has cracks
- Cracks were found around the perimeter foundation. (see photo 161, 162, 164). A maximum crack width was measured to be 0.8mm.

5.12. Block E - PRO 1119 B005

Internal damage

• No internal damage was found on this building

External damage

- Front entrance steps to unit 39 has 0.8mm cracks
- Cracks were found around the perimeter foundation. (see photo 173, 176, 180, 182, 184).

5.13. Block F - PRO 1119 B006

Internal damage

No internal damage was found on this building

External damage

- Cracks were found on the exterior of unit 41 on the east end of the building at the perimeter foundation. (see photo 188, 189, 190) These were found to have a maximum crack width of 5mm.
- Concrete perimeter foundation reinforcing was exposed near the rear entrance of unit 41 (see photo 192)



6. Available Information and Assumptions

6.1. Available Information

SKM carried out a seismic review on the structure. This review was undertaken using the available information which was as follows:

- SKM visual inspections findings from 16th October 2012
- SKM cover meter survey results carried on the 29th November 2012
- Survey results by Woods dated 7th December 2012
- SKM intrusive inspection findings from 20th December 2012
- Geotechnical Report by Tonkin and Taylor dated April 2013

6.2. Survey

The buildings were surveyed on 26th and 27th November 2012 by Woods. Block H had an internal floor level survey and a wall verticality survey completed. Blocks A, B, C, D, E, F, G and I, were surveyed on the exterior of the building using the concrete perimeter foundation; therefore there may be inaccuracies in the level results. The difference in floor level of the buildings using these results ranged between 21mm to 203mm. A summary of the results is shown below in Table 2, along with the corresponding indicator criteria found in Table 2.3 of the Ministry of Business, Innovation and Employment, "Revised guidance on rebuilding houses affected by the Canterbury earthquake sequence".

Block	Change in Floor Level	Indicator criteria
А	51	Foundation re-level
В	115	Foundation re-build
C	77	Foundation re-level
D	65	Foundation re-level
E	76	Foundation re-level
F	21	No Foundation re-level
G	174	Foundation re-build
Н	203	Foundation re-build
Ι	64	Foundation re-level

Table 2: Survey Results Summary



If the indicator criteria for the variation in floor level as stated in Ministry of Business, Innovation and Employment, "Revised guidance on rebuilding houses affected by the Canterbury earthquake sequence" is the basis that is used to determine if the foundations require either re-level or rebuild. Blocks A, C, D, F and I require a foundation re-level, and blocks B, G and H require a foundation rebuild.

6.3. Design Criteria and Assumptions

The following design criteria and assumptions made in undertaking the assessment include:

- We have reviewed the building and from our visual inspection the structure appears to be built in accordance with good practice at the time.
- The soil on site is class [D] as described in AS/NZS1170.5:2004, Clause 3.1.3, Soft Soil, this is on the basis of the readily available geotechnical data. The ultimate bearing capacity for the perimeter foundation is 200kPa for area A and 120kPa for area B.
- Standard design criteria for residential buildings as described in AS/NZS1170.0:2002:
 - 50 year design life, which is the default NZ Building Code design life.
 - Structure Importance Level 2. This level of importance is described as 'normal' with medium or considerable consequence for loss of human life, or considerable economic, social or environmental consequence of failure.
- The building has a short period less than 0.4 seconds.
- Site hazard factor, Z = 0.3, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- The seismic demand of the building was calculated using NZS1170.5 using a ductility of 2 in the along direction and a ductility of 1.25 in the across direction. The ductility of 2 was used due to the inherent ductility of the timber framed walls in the along direction and a ductility of 1.25 was used in the across direction due to the brick walls providing nominal ductility.



• The following material properties were used in the analyses:

Table 3: Material Properties

Material	Material Property	Reference
Average mortar	5.5 MPa	Assessment and Improvement of
compressive strength for		unreinforced masonry buildings for
medium hardness (f' _j)		earthquake resistance, Faculty of
		Engineering, the University of Auckland
Masonry bed joint shear	0.25 MPa	Assessment and Improvement of
strength under zero axial		unreinforced masonry buildings for
compression (f' _{ms})		earthquake resistance, Faculty of
		Engineering, the University of Auckland
Ultimate bearing capacity	200 kPa for area A and	Tonkin and Taylor memo dated 22 nd April
of soil	120kPa for area B	2013
Gypsum wall lining	Shear capacity $= 3.0$	Table 11.1, NZSEE Assessment and
	kN/m (φ=0.7)	Improvement of the Structural Performance
		of Buildings in Earthquakes, June 2006

The detailed engineering analysis is a post construction evaluation therefore it has the following limitations:

- It is not likely to pick up on any concealed construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the structure will not be identified unless they are visible and have been specifically mentioned in this report.
- The detailed engineering evaluation deals only with the structural aspects of the structure. Other aspects such as building services are not covered.

6.4. The Detailed Engineering Evaluation (DEE) process

The DEE is a procedure written by the Ministry of Business, Innovation and Employment's Engineering Advisory Group and grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings³.

The procedure of the DEE is as follows:

³ <u>http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf</u>

SINCLAIR KNIGHT MERZ



- 1) Qualitative assessment procedure
 - a. Determine the building's status following any rapid assessment that have been done
 - b. Review any existing documentation that is available. This will give the engineer an understanding of how the building is expected to behave. If no documentation is available, site measurements may be required
 - c. Review the foundations and any geotechnical information available. This will include determining the zoning of the land and the likely soil behaviour, a site investigation may be required
 - d. Investigate possible Critical Structural Weaknesses (CSW) or collapse hazards
 - e. Assess the original and post earthquake strength of the building (this assessment is subsequently superseded by the quantitative assessment)
- 2) Quantitative procedure
 - a. Carry out a geotechnical investigation if required by the qualitative assessment
 - b. Analyse the building according to current building codes and standards. Analysis accounts for damage to the building.

The DEE assessment ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 4. The building rank is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. Earthquake prone buildings are defined as having less than 34 %NBS strength which correlates to an increased risk of approximately 20 times that of 100% NBS⁴. Buildings that are identified to be earthquake prone are required by law to be strengthened within 30 years of the owner being notified that the building is potentially earthquake prone⁵.

⁵ <u>http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf</u> SINCLAIR KNIGHT MERZ

⁴ NZSEE 2006, Assessment and Improvement of the Structural Performance of Buildings in Earthquakes, p 2-2



Table 4: DEE Risk classifications⁶

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may
				be desirable.
	А		100 to 80	
	В		80 to 67	
Moderate risk building	С	Moderate	67 to 33	Acceptable legally.
				Improvement recommended.
High risk building ⁷	D	High	33 to 20	Unacceptable. Improvement
				required.
	E		< 20	<u>^</u>

The DEE method rates buildings based on the plans (if available) and other information known about the building and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without catastrophic failure. The DEE does also consider Serviceability Limit State (SLS) performance of the building and or the level of earthquake that would start to cause damage to the building but this result is secondary to the ULS performance.

The NZ Building Code describes that the relevant codes for determining %NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard
- NZS 3604:2011 Timber Framed Buildings

⁶ NZSEE 2006, Assessment and Improvement of the Structural Performance of Buildings in Earthquakes, §2 pp.13-14

⁷ Although the NZSEE guidelines describe a building with a seismic capacity which is assessed as less than 34%NBS as a "High Risk Building", with the structural performance described as "Unacceptable"; note that, in accordance with the local authority *Earthquake-Prone, Dangerous And Insanitary Buildings Policy*, the building can continue to be occupied provided there is no structural damage that would cause all of parts of the building to be unsafe. Note also that it will need to be strengthened to at least 34%NBS in the future.



7. Results and Discussions

7.1. Critical Structural Weaknesses

No potential critical structural weaknesses have been identified for these buildings.

7.2. Analysis Results

The equivalent static force method was used to analyse the seismic capacity of the building. The results of the analysis are reported in the following table as %NBS. The results below are calculated for the building in its damaged state. The building results have been broken down into their seismic resisting elements.

(%NBS = probable strength / new building standards)

Block	Saismic Pasisting Flamont	Action	Seismic Pating %NBS
DIOCK	Seisine Resisting Element	Action	Seisinic Katnig 701NDS
	Gib lined walls	Along	86%
Block D	Gib lined walls and brick party	Across	100%
	walls		
	Foundation	Both directions	100%
	Gib lined walls	Along	67%
	Foundation	Along	92%
Blocks A, B, C	Foundation	Across	100%
	Gib lined walls and brick party	Across	100%
	walls		
	Gib lined walls	Along	67%
Blocks E, F, G,	Foundation	Both directions	100%
H, I	Gib lined walls and brick party	Across	100%
	walls		

Table 5: DEE Results



The buildings are found to have a seismic capacity of 86% for Block D and 67% for all other buildings. All the buildings are governed by the gib lined walls in the along direction.

7.3. Recommendations

Based on the findings of this assessment indicating the buildings are in the order of 86% NBS for Block D and 67% for all other buildings and are therefore classed as being in the category of 'Low Risk Buildings" no strengthening is required in order to comply with Christchurch City Council (CCC) policy – Earthquake-prone dangerous & insanitary buildings policy 2010.



8. Conclusion

SKM carried out a quantitative assessment on BE 1119, Andrews Crescent. This assessment concluded that the building is classified as not Earthquake Prone. No strengthening is required in order to comply with Christchurch City Council (CCC) policy – Earthquake-prone dangerous & insanitary buildings policy 2010.

Table 6: Quantitative assessment summary

Description	Grade	Risk	%NBS	Structural Performance
Block A, B, C, E, F, G, H, I	A	Low	67	Acceptable. Improvement may be desirable
Block D	В	Low	86	Acceptable. Improvement may be desirable

It is recommended that:

- a) There is no damage to any of the buildings that would cause it to be unsafe to occupy.
- b) We consider that barriers around the buildings are not necessary.
- c) The floors were found to be out of level and it is recommended the foundations be relevelled or rebuild, however the levelness of the foundation does not affect the %NBS of the buildings.



9. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property predating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.



10. Appendix 1 – Photos



side elevation for all the buildings)

rear elevation for all the buildings)





Photo 7: Front elevation of Block A showing
entrances to Units 1,3,5,7 respectivelyPhoto 8: Front view of unit 1, with crack in
foundation circled











SINCLAIR KNIGHT MERZ

PRO 1119 Andrews Crescent Quantitative Final.docx









Photo 21: View of cracks in kitchen party wall Photo 22: Close up view from photo 21 in unit 5







SINCLAIR KNIGHT MERZ

PRO 1119 Andrews Crescent Quantitative Final.docx








SINCLAIR KNIGHT MERZ





























Photo 62: Kitchen and lounge doorway junctionPhoto 63: Bathroom and kitchen doorwayshowing crackjunction showing crack



SINCLAIR KNIGHT MERZ





SINCLAIR KNIGHT MERZ









SINCLAIR KNIGHT MERZ





SINCLAIR KNIGHT MERZ

















Photo 97: Slope of floor in unit 12 kitchen area

Photo 98: Rear entrance of unit 12





















SINCLAIR KNIGHT MERZ





SINCLAIR KNIGHT MERZ





Photo 122: Rear entrance of unit 23

Photo 123: Perimeter foundation of unit 23 at rear entrance



Photo 124: Close up view from photo 123,
damage does not appear to be due to the
earthquakePhoto 125: Rear entrances of units 23 and 21
respectively









Photo 130: Rear entrance to unit 19 and 17 Photo 131: View of rear entrance to unit 19 respectively



















Photo 145: close up view from photo 144Photo 146: Rear entrance for unit 20 (1)showing 11mm crack



Photo 147: Rear entrance for unit 20 (2)Photo 148: Close up view from photo 147showing 0.7mm crack

























SINCLAIR KNIGHT MERZ








Photo 178: Close up view from photo 177Photo 179: Exterior side view of unit 39showing 0.8mm cracks



Photo 180: Close up view from photo 179Photo 181: Rear of unit 39showing 0.5mm crack in perimeter foundation















11. Appendix 2 – CERA Standardised Report Form

SINCLAIR KNIGHT MERZ

Detailed Engineering Evaluation Summary Data			V1.14
Location	Andrews Court (BE 1119)		
	Block A (units 1,3,5,7),		
	Block C (units 17, 19, 21, 23),		
	Block E (units 33,35,37,39), Block F (units 41,43,45,47),		
	Block G (units 18,20,22,24),		
Building Name:	Block I (units 10,12,14,16), Block I (units 2,4,6,8),	Reviewer:	N Calvert
Building Address:	Unit	No: Street CPEng No: Andrews Crescent Company:	242062 Sinclair Knight Merz
Legal Description		Company project number:	ZB01276.215
	Degrees	Min Sec	03 340 4313
GPS south: GPS east:	2	Date of submission: Inspection Date:	4/06/2013 16/10/2012
	PRO 1119 B001: PRO 1119 B002:	Revision:	В
	PRO 1119 B003; PRO 1119 B005; PRO		
Building Unique Identifier (CCC):	1119 B006; PRO 1119 B007; PRO 1119 B008; PRO 1119 B009;	Is there a full report with this summary?	ves
Site Site slope:	flat	Max retaining height (m):	
Soil type:	mixed	Soil Profile (if available):	
Proximity to waterway (m, if <100m):	D	If Ground improvement on site, describe:	
Proximity to clifftop (m, if < 100m): Proximity to cliff base (m, if <100m):		Approx site elevation (m):	
Building			
No. of storeys above ground:	1	single storey = 1 Ground floor elevation (Absolute) (m):	
Storeys below ground	0	Giouna noor elevation above giouna (m).	
Foundation type:	other (describe)	if Foundation type is other, describe:	Concrete Perimeter foundation with internal concrete piles.
Building height (m):		height from ground to level of uppermost seismic mass (for IEP only) (m):	
Age of Building (years):		Date of design:	1935-1965
Strengthening present?	no	If so, when (year)?	
Use (ground floor):	multi-unit residential	And what load level (%g)? Brief strengthening description:	
Use (upper floors): Use notes (if required):			
Importance level (to NZS1170.5):	IL2		
Gravity Structure			
Gravity System:	load bearing walls		100x50 rafters @ 450, purlins @ 300
			tiled cladding for all buildings except
Roof: Floors:	timber framed timber	rafter type, purlin type and cladding ioist depth and spacing (mm)	corrugated metal cladding for Block D bearings @ 1500
Beams	timber	joint depart and optioning (min) type	
Columns: Walls:	load bearing brick	#N/A	
Lateral load resisting structure	·		
Lateral system along:	lightweight timber framed walls	Note: Define along and across in note typical wall length (m)	2
Ductility assumed, μ: Period along	2.00	0.00 estimate or calculation?	estimated
Total deflection (ULS) (mm):	5	estimate or calculation?	estimated
maximum interstorey deflection (ULS) (mm):		estimate or calculation?	
Lateral system across: Ductility assumed up	unreinforced masonry bearing wall - brick	note wall thickness and cavity	230mm thick wall, with 26mm cavity
Period across	0.40	0.00 estimate or calculation?	estimated
Total deflection (ULS) (mm): maximum interstorev deflection (ULS) (mm):	5	estimate or calculation? estimate or calculation?	estimated
Separations:			
north (mm):		leave blank if not relevant	
east (mm): south (mm):			
west (mm):			
Non-structural elements	[
Starrs: Wall cladding:	plaster system	describe	gypsum plasterboard
Boof Cladding	Heavy tiles	describe	heavy tiles for all buildings except for
Glazing	timber frames		
Ceilings: Services(list):	plaster, fixed		
Available documentation			
Architectural Structural	none	original designer name/date original designer name/date	<u> </u>
Mechanica	none	original designer name/date	
Geotech report	full	original designer hame/date original designer name/date	Tonkin and Taylor, April 2013
Damage Site: Site performance		Describe demora	
(refer DEE Table 4-2)	none observed	Describe dallage.	
Settlement	none observed	notes (if applicable):	Assuming the buildings were level pre
Differential extrement	1:150 or more	potop // ganEaship)	earthquake. The difference in floor levels
Liquefaction	none apparent	notes (if applicable): notes (if applicable):	ranos between ale bullulings
Lateral Spread Differential lateral spread	none apparent	notes (if applicable): notes (if applicable):	
Ground cracks:	none apparent	notes (if applicable):	
Damage to area		notes (ir applicable):	
Current Placard Status:	green		
Along Damago mito		Describe how damage ratio proved at-	
Damagé fatto:	small cracks in gypsum plaster, and in		
Describe (summary):	perimeter toundation	$Damage _Ratio = \frac{(\% NBS (before) - \% NBS (after))}{(\% NBS (after))}$	
Across Damage ratio:	o%	% NBS (before)	
Describe (summary):	perimeter foundation		
Diaphragms Damage?	no	Describe:	
CSIMe			
Damage?		Describe:	
Pounding: Damage?:	no	Describe:	
Non-structural: Damage?	ves	Describe:	cracks in concrete entrance steps
Recommendations	significant structural	Describe:	rebuild and relevelling of foundation
Building Consent required	ves	Describe:	state the single rearband
Interim occupancy recommendations:	tull occupancy	Describe:	
Along Assessed %NBS before e'quakes:	67%	##### %NBS from IEP below If IEP not used, please detail assessment	SKM calculations
Assessed 70MDS aller e quakes		menodology:	
Across Assessed %NBS before e'quakes Assessed %NBS after e'quakes	100%	##### %NBS from IEP below	

	Andrews Court (BE 1119)]	
Building Name	Block D (units 25,27,29,31)	Reviewer: 1 CPEng No:	N Calvert 242062
Building Address	:	Andrews Crescent Company: S	Sinclair Knight Merz
Legal Description	:L	Company project number: 2	ZB01276.215
	Degrees	Min Sec	03 940 4919
GPS south		Date of submission:	4/06/2013
GPS easi	1	Revision: f	B
Building Unique Identifier (CCC)	PRO 1119 B004	Is there a full report with this summary?	yes
Site Site slope	flat	Max rotaining height (m)	
Soil type	mixed	Soil Profile (if available):	
Site Class (to NZS1170.5)	: D		
Proximity to waterway (m, if <100m) Proximity to clifftop (m, if < 100m)		It Ground improvement on site, describe:	
Proximity to cliff base (m,if <100m)	d	Approx site elevation (m):	
Building			
No. of storeys above ground	1	single storey = 1 Ground floor elevation (Absolute) (m):	
Ground floor split	yes 0	Ground floor elevation above ground (m):	
			Concrete Perimeter foundation with
Foundation type Building boint (m)	other (describe)	if Foundation type is other, describe: i	internal concrete piles.
Floor footprint area (approx)	d	negration gound to rever of uppermost setsinic mass (for her only) (in).	
Age of Building (years)	£	Date of design:	1935-1965
Strengthening present	no l	If so, when (year)?	
Lise (around floor)	multi-unit residential	And what load level (%g)?	
Use (upper floors)		bier strengthening description:	
Use notes (if required)	1.2		
Importance level (to NZS1170.5)			
Gravity Structure			
Gravity System:	load bearing walls		100x50 rafters @ 450. purlins @ 300.
		t	tiled cladding for all buildings except
Roof	timber framed	rafter type, purlin type and cladding	corrugated metal cladding for Block D
Floors Beams	timber	joist depth and spacing (mm) t type	Deamigs @ 1500
Columns	4		
Walls:	load bearing brick	#N/A	
Lateral load resisting structure			
Lateral system along	lightweight timber framed walls	Note: Define along and across in note typical wall length (m)	2
Ductility assumed, μ Period along	2.00	detailed report! 0.00 estimate or calculation?	estimated
Total deflection (ULS) (mm)	5	estimate or calculation?	estimated
maximum interstorey deflection (ULS) (mm)	۶ <u>ــــــــــــــــــــــــــــــــــــ</u>	estimate or calculation?	
Lateral system across	unreinforced masonry bearing wall - brick	note wall thickness and cavity	230mm thick wall, with 26mm cavity
Ductility assumed, µ	1.25		
Period across	0.40	0.00 estimate or calculation?	estimated
maximum interstorey deflection (ULS) (mm)	3	estimate or calculation?	estimated
Separations:		lanus blanti Kantanlaunat	
norm (mm)		leave plank it not relevant	
east (mm)		ieave blank il hot relevant	
norm (mm) east (mm) south (mm) west (mm)		leave blank il not relevant	
south (mm) south (mm) west (mm)		ieave diank il not relevant	
Non-structural elements			
Non-structural elements Val cladding Val cladding	plaster system	describe	gypsum plasterboard
Non-structural elements Stairs Wall cladding	plaster system	describe	gypsum plasterboard heavy tiles for all buildings except for
Non-structural elements Wall cladding Roof Cladding Clarating	plaster system Heavy tiles limber frames	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
North (mm) east (mm) south (mm) west (mm) Non-structural elements Val cladding Roof Cladding Celings Celings	Plaster system Heavy tiles timber frames plaster, fixed	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements Non-structural elements Non-structural elements Vall cladding Celings Services(list)	plaster system Heavy tiles timber frames plaster, fixed	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
North (mm) east (mm) south (mm) west (mm) Non-structural elements Stairs Wall cladding Roof Cladding Clazing Ceilings Services(list)	plaster system Heavy tiles timber frames plaster, fixed	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements Non-structural elements Non-structural elements Vall cladding Ceitings Services(iist) Available documentation	plaster system Heavy tiles timber frames plaster, fixed	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements Non-structural elements Val cladding Roof Cladding Ceilings Services(list) Available documentation Architectura	plaster system Heavy tiles imber frames plaster, fixed	describe	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Available documentation Available documentation Architectura	plaster system plaster system heavy tiles imber frames plaster, fixed	describe describe original designer name/date original designer name/date original designer name/date original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Available documentation Available documentation Available documentation Available documentation Architectura	Image: plaster system plaster system timber frames plaster, fixed	eriginal designer name/date original designer name/date original designer name/date original designer name/date original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements Non-structural elements Non-structural elements Vali cladding Cellings Services(list) Available documentation Architectura Mechanica Electrica Geotech report	plaster system Heavy tiles timber frames plaster, fixed	describe des	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements Non-structural elements Non-structural elements Vali cladding Caling Caling Services(list) Available documentation Architectura Electrica Geotech repor	plaster system Heavy tiles timber frames plaster, fixed none none none fone none fone none full	eave blank it not relevant describe describe original designer name/date original designer name/date original designer name/date original designer name/date	gypsum plasterboard beavy tiles for all buildings except for corrugated metal for Block D
Notin (Imit) east (Imit) south (Imit) west (Imit) Non-structural elements Stairs Wall clading Glazing Ceilings Services(list) Available documentation Available documentation Available documentation Damage Site: Site performance		eave blank in hor relevant describe describe describe describe describe describe describe describe designer name/date original designer name/date original designer name/date original designer name/date original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Notin (Imit) east (Imit) south (Imit) west (Imit) Non-structural elements Stairs Wall clading Roof Clading Glazing Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Damage Site: Crefer DEE Table 4-2)		eave blank in hor relevant describe describe original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D
Non-structural elements south (mm) Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Mechanica Electrica Geotech report Site: Site: Site performance (refer DEE Table 4-2) Settlement	plaster system plaster system teavy tiles timber frames plaster, fixed none none none tull none tull none tull	eave blank in hor relevant describe describe describe original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Bechanica Electrica Geotech report Site performance Site: (refer DEE Table 4-2) Settlement	Image: plaster system plaster system imber frames plaster, fixed	describe describe original designer name/date	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Structura Glazing Ceilings Services(list) Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Differential settlement	Image: plaster system plaster system imber frames plaster, fixed imber frames plaster, fixed none no	describe describe describe describe original designer name/date origi	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements Stairs Wall cladding Roof Cladding Ceilings Stairs Wall cladding Ceilings Services(list) Ceilings Available documentation Architectura Mechanica Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread	Image: plaster system Image: plaster system Image: plaster frames plaster, fixed Image:	describe describe describe describe describe describe original designer name/date original designer original designer nam	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements Non-structural elements Stairs Wall cladding Roof Cladding Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech repor Damage Site: Crefer DEE Table 4-2) Settlement Differential settlement Lateral Spread Differential settlement		describe describe describe describe describe describe original designer name/date original designer original designer nam	Oppsum plasterboard Peavy tiles for all buildings except for corrugated metal for Block D Tornkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements South (mm) Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Structura Mechanica Electrica Geotech report Damage Site: Site: Site performance Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Damage Damage terame Stateral Spread Differential settlement		deave blank in hor relevant describe describe describe describe original designer name/date oris(fapplicable): notes (fapplicable): notes (fapplicable):	<u>gypsum plasterboard</u> heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements South (mm) Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Stetric Site Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Liquefaction Liquefaction Liquefaction Lifferential settlement Liquefaction Liquefaction Lifferential aspread Differential asettal spread Differential asettal spread Differential asettal spread		describe describe describe describe describe describe describe original designer name/date orise original designer na	
Non-structural elements South (mm) Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential lateral spread Differential lateral spread Differential lateral spread Building: Current Placard Status		describe describe describe describe describe describe describe original designer name/date original designer original	<u>Gypsum plasterboard</u> heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Cellings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlemant Upferential settlemant Ground cracks Damage to area Building: Current Placard Status Current Placard Status	Image: plaster system plaster system Heavy tiles timber frames plaster, fixed Inone none none observed 1:150 or more none apparent	describe [describe] describe] describe] describe] describe] original designer name/date original designer n	<u>gypsum plasterboard</u> heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings
Non-structural elements Stairs Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Mechanica Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential settlerari spread Ground cracks Damage to area Building: Current Placard Status Along Damage ratio Current Placard Status		deave blank in hor relevant describe describe describe describe original designer name/date orites (if applicable); notes (if applicable); notes (if appl	
Non-structural elements Stairs Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Structura Structura Glazing Ceilings Services(list) Structura Damage Site Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Ground cracks Damage to areas Building: Current Placard Status Along Damage ratio Describe (summary)		deave blank in nor relevant describe describe describe original designer name/date original designer original designer name/date original designer name/date	
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Site: Site performance Certer DEE Table 4-2) Settlement Liquefacion Liquefacion Liquefacion Liquefacion Liquefacion Lateral Spread Differential lateral spread Differential lateral spread Building: Current Placard Status Along Damage ratio		describe designer name/date original designer name/date notes (if applicable): notes (if applicable): notes (if applicable): notes (if applicable): notes (if applic	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013
Non-structural elements Stairs Wall cladding Roof Cladding Roof Cladding Ceilings Services(list) Ceilings Available documentation Architectura Site: Site performance Cefer DEE Table 4-2) Settlement Liquefaction Liquefaction Liguefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Building: Current Placard Status Along Damage ratio Describe (summary) Across		describe describe describe describe describe describe original designer name/date original desig	
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceinings Stairs Wall cladding Roof Cladding Ceinings Services(list) Ceinings Available documentation Architectura Structural Mechanica Electrica Geotech report Damage Site Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Liquefacton Lateral Spread Differential settlement Liquefacton Liquefacton Lateral Spread Differential settlement		describe describe describe describe describe describe original designer name/date original desig	<u>Assuming the buildings were level preentiques in the buildings were level stated between the buildings</u>
In our num in a south (mm) south (mm) west (mm		describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes (if applicable); i	Sypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013
Non-structural elements Non-structural elements Stairs Wal cladding Roof Cladding Ceilings Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Lateral Spread Ground cracks Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Diaphragms Damage?		describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes (if appli	
Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Ceilings Available documentation Architectura Site: Site performance Crefer DEE Table 4-2) Settlement Differential settlement Liquefaction Liquefaction Lateral Spread Differential settlement Samage to area Building: Current Placard Status Along Damage ratio Describe (summary) Describe (summary) Diaphragms Damage? CSWs: Damage?		describe describe describe describe original designer name/date original designer name/date origi	
Non-structural elements Stairs Wall cladding Roof Cladding Official action Architectura Available documentation Architectura Static Stairs Wall cladding Ceilings Ceilings Services(list) Available documentation Architectura Structural Mechanica Electrica Geotech report Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential settlement Liquefactor Liquefactor Lateral Spread Differential settlement Liquefactor Lateral Spread Differential settlement Liquefactor Lateral Spread Differential ateral spread Differential settlement Liquefactor Lateral Spread Differential ateral spread Differential ateral spread Along Damage ratio Describe (summary) Describe (summary) Across Damage? CSWs: Damage?		describe describe describe describe describe describe describe original designer name/date original designer name/date orig	
Non-structural elements Stairs Wall cladding Roof Cladding Roof Cladding Ceilings Stairs Wall cladding Roof Cladding Ceilings Services(list) Architectura Mechanica Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Lateral Spread Differential settlement Liquefacton Liquefacton Lateral Spread Describe (summary) Across Damage ratio Describe (summary) Describe (summary) <t< td=""><td></td><td>describe describe describe describe describe describe describe original designer name/date original designer name/date orig</td><td></td></t<>		describe describe describe describe describe describe describe original designer name/date original designer name/date orig	
Non-structural elements Stairs Wall cladding Roof Cladding Glazing Glazing Ceilings Structural Available documentation Architectura Structural Electrica Geotech report Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential lateral spread Ground cracks Damage Current Placard Status Along Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Diaphragms Diaphragms Damage? CSWs: Damage? Pounding: Damage? Non-structural: Damage?		describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes	
notin (imi) east (mm) south (mm) west (mm) Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Site: Cifferential settlement Liquefaction Lateral Spread Differential lateral spread Ground cracks Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Along Describe (summary) Diaphragms Damage? CSWs: Damage? Pounding: Damage? Non-structural: Damage?		describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes (if applicable);	Sypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013
notin (imit) east (mm) south (mm) west (mm) Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech report Damage Site: (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Ground cracks Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Across Damage ratio Describe (summary) Diaphragms Damage? Pounding: Damage? Non-structural: Damage?		$describe \begin{bmatrix} describe \\ describe \end{bmatrix}$ $describe \begin{bmatrix} describe \\ describe \end{bmatrix}$ $describe \\ describe \\ describe \\ designer name/date \\ original designer name/date \\ original designer name/date \\ original designer name/date \\ original designer name/date \\ designer name/d$	
notin (imit) east (mm) south (mm) west (mm) Non-structural elements Stairs Wal cladding Calings Services(list) Available documentation Architectura Structural Bechanica Electrica Geotech report Damage Site: Site: Site: Site: Site: Differential settlement Liquefaction Lateral Spread Differential lateral spread Differential lateral spread Differential settlement Liquefacton Lateral Spread Differential lateral spread Differential settlement Liquefacton Lateral Spread Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Across Damage? CSWs: Damage? Non-structural:		describe describe describe describe original designer name/date original designer name/date origi	
Non-structural elements Stairs Wall cladding Roof Cladding Official commendation Architectura Available documentation Architectura Mechanica Electrica Geotech report Site Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential settlement Liquefaction Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Level To repair/strengtmenting required Describe (summary) Across Damage ratio Describe (summary) Damage? No		describe describe describe describe describe original designer name/date original designer name/d	
Non-structural elements Non-structural elements Stairs Wall cladding Roof Cladding Glazing Ceilings Services(list) Available documentation Architectura Structura Mechanica Electrica Geotech repor Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Cround cracks Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Diaphragms Damage? Non-structural: Damage? Recommendations Level of repair/strengthening required Building Consent required Building Consent required Electrica Cevel of repair/strengthening required Building Consent required Building Consent required Interim occupancy recommendations Along		deave blank if not relevant describe describe describe original designer name/date notes (if applicable); notes (if applicable); </td <td>Sypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Tonkin and Taylor, April 2013 Assuming the buildings were level preer earthquake. The difference in floor levels varied between the buildings earthquake. metal buildings were level preer earthquake. metal buildings carcks in concrete entrance steps rebuild and relevelling of foundation SKM calculations</td>	Sypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Tonkin and Taylor, April 2013 Assuming the buildings were level preer earthquake. The difference in floor levels varied between the buildings earthquake. metal buildings were level preer earthquake. metal buildings carcks in concrete entrance steps rebuild and relevelling of foundation SKM calculations
Non-structural elements Stairs Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(iist) Ceilings Available documentation Architectura Structura Mechanica Electrica Geotech report Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential lateral spread Ground cracks Damage to area Building: Current Placard Status Along Across Damage ratio Describe (summary) Diaphragms Damage? Non-structural: Damage? Along <t< td=""><td></td><td>describe describe describe describe describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes (if applicable); note</td><td></td></t<>		describe describe describe describe describe describe describe describe original designer name/date original designer name/date notes (if applicable); notes (if applicable); note	
Non-structural elements Stairs Non-structural elements Stairs Wal cladding Roof Cladding Glazing Ceilings Services(list) Architectura Available documentation Architectura Structura Mechanica Electrica Geotech report Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Lateral Spread Differential settlement Logentation Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Damage to area Building: Current Placard Status Along Damage ratio Describe (summary) Across Diaphragms Damage? CSWs: Damage? Pounding: Damage? Non-structural: Damage? Recommendations <t< td=""><td></td><td>describe describe describe describe original designer name/date original designer name/date neme/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date original designer n</td><td></td></t<>		describe describe describe describe original designer name/date original designer name/date neme/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date neme/date original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date original designer n	
Non-structural elements Stairs Wal cladding Roof Cladding Glazing Glazing Ceilings Steirs Wal cladding Colliding Glazing Ceilings Structural Structural Mechanica Electrica Geotech report Site Damage Site: Site: Site performance (refer DEE Table 4-2) Settlement Differential settlement Liquefaction Liquefacton Lateral Spread Differential settlement Liquefacton Liquefacton Lateral Spread Differential settlement Structural Spread Differential settlement Liquefacton Structural <		describe describe describe describe original designer name/date original designer name/date notes (if applicable): notes (if	gypsum plasterboard heavy tiles for all buildings except for corrugated metal for Block D Tonkin and Taylor, April 2013 Tonkin and Taylor, April 2013 Assuming the buildings were level pre earthquake. The difference in floor levels varied between the buildings Image: State of the state
Non-structural elements Stairs Wall cladding Roof Cladding Official commendation Architectural Available documentation Architectural Available documentation Architectural Site: Site performance Electrica Geotech report Damage Site: Site: Site performance Ceffer DEE Table 4-2) Settlement Liquefaction Lateral Spread Differential settlement Liquefaction Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefaction Lateral Spread Differential settlement Liquefactor Liquefactor Lateral Spread Differential settlement Liquefactor Liquefactor Lateral Spread Differential settlement Liquefactor Liquefactor Lateral Spread Differential settlement Liquefactor Level of repair/strengthening required Describe (summary) Across Damage? Non-str		describe gescribe	