



CLIENTS | PEOPLE | PERFORMANCE

**Botanic Gardens Irrigation Pump
House
PRK 1566 BLDG 031 EQ2
Detailed Engineering Evaluation
Qualitative Report
Version FINAL**

**Botanic Gardens Irrigation Pump House
PRK 1566 BLDG 031 EQ2**

Detailed Engineering Evaluation
Qualitative Report
Version FINAL

7 Rolleston Avenue, Christchurch
Central

Christchurch City Council

Prepared By
Cormac Joy

Reviewed By
Nate Oakes

Date
7/12/12

Contents

Qualitative Report Summary	1
1. Background	3
2. Compliance	4
2.1 Canterbury Earthquake Recovery Authority (CERA)	4
2.2 Building Act	5
2.3 Christchurch City Council Policy	6
2.4 Building Code	6
3. Earthquake Resistance Standards	7
4. Building Description	9
4.1 General	9
4.2 Gravity Load Resisting System	11
4.3 Lateral Load Resisting System	11
5. Assessment	12
6. Damage Assessment	13
6.1 Surrounding Buildings	13
6.2 Residual Displacements and General Observations	13
6.3 Ground Damage	13
7. Critical Structural Weakness	14
7.1 Short Columns	14
7.2 Lift Shaft	14
7.3 Roof	14
7.4 Plan Irregularity	14
7.5 Staircases	14
7.6 Liquefaction	14
8. Geotechnical Consideration	15
8.1 Site Description	15
8.2 Published Information on Ground Conditions	15
8.3 Seismicity	17
8.4 Slope Failure and/or Rockfall Potential	17

8.5	Liquefaction Potential	18
8.6	Recommendations	18
8.7	Conclusions & Summary	18
9.	Survey	19
10.	Initial Capacity Assessment	20
10.1	% NBS Assessment	20
10.2	Seismic Parameters	20
10.3	Expected Structural Ductility Factor	20
10.4	Discussion of Results	20
10.5	Occupancy	20
11.	Initial Conclusions	21
12.	Recommendations	22
13.	Limitations	23
13.1	General	23
13.2	Geotechnical Limitations	23

Table Index

Table 1	%NBS compared to relative risk of failure	8
Table 2	ECan Borehole Summary	15
Table 3	Summary of Known Active Faults	17

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	7
Figure 2	Plan Sketch Showing Key Structural Elements	10
Figure 3	Post February 2011 Earthquake Aerial Photography	15

Appendices

- A Photographs
- B Existing Drawings
- C CERA Building Evaluation Form

Qualitative Report Summary

Botanic Gardens Irrigation Pump House

PRK 1566 BLDG 031 EQ2

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version FINAL

7 Rolleston Avenue, Christchurch Central

Background

This is a summary of the Qualitative report for the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 4 April 2012.

Building Description

The single level timber framed structure consists of a Dutch hip roof with lightweight metal cladding on timber purlins spanning between six timber roof trusses. The roof trusses span onto the timber framed walls. Internal wall and ceiling linings consist of plywood. External cladding consists of both brickwork and timber weatherboard. The exterior walls sit on perimeter strip footings. The ground floor consists of a 100mm mesh reinforced concrete slab.

Key Damage Observed

No damage was observed to the structure.

Critical Structural Weaknesses

No critical structural weaknesses were observed to the structure.

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the building's original capacity has been assessed to be in the order of 86% NBS. The building's post-earthquake capacity excluding critical structural weaknesses as none were present is also in the order of 86% NBS. The building has been assessed to have a seismic capacity in the order of 86% NBS and is therefore not regarded as potentially Earthquake Prone or as a potential Earthquake Risk.

Recommendations

It is recommended that:

Due to the structure being assessed as not potentially Earthquake Prone or Risk the current green placard status is to remain as is. No further assessment is required.

1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Botanic Gardens Irrigation Pump House.

This report is a Qualitative Assessment of the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. The building description is based on the visual inspection carried out on site.

2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The Irrigation Pump House, constructed in 2007, is located in the Botanic Gardens at 7 Rolleston Avenue, Christchurch central. The site is located opposite the most southerly side of the Office Store with it bordering Christs College to the east. See Photograph 6 in Appendix A for building location on site.

The site is predominantly flat with insignificant variations in ground levels throughout.

The single level timber framed structure consists of a Dutch hip roof with lightweight metal cladding on timber purlins spanning between six timber roof trusses. The roof trusses span onto the timber framed walls. Internal wall and ceiling linings consist of plywood. External cladding consists of both brickwork and timber weatherboard. The exterior walls sit on perimeter strip footings. The floor to the structure consists of a 100mm mesh reinforced concrete slab. Contrary to the structural drawings a crane rail has not been installed.

The dimensions of the building are approximately 6m long 4.8m wide and 3.5m in height.




Figure 2 Plan Sketch Showing Key Structural Elements

4.2 Gravity Load Resisting System

The gravity loads acting on the structure are resisted by the timber framed walls. The gravity roof load is transferred from the roof via the timber purlins into the timber trusses spanning across the structure. The load is then distributed from the timber trusses to the side walls and down to the ground via the concrete strip perimeter foundations.

4.3 Lateral Load Resisting System

Lateral loads acting on the structure are resisted by the timber framed walls along and across the building. The lateral load at roof level is transferred from the roof to the side walls through diaphragm action of the plywood sarking ceiling. The load is then transferred down to the concrete foundations via diaphragm action of the plywood wall linings.

5. Assessment

A visual inspection of the building was undertaken on 4 April 2012. Both the interior and exterior of the building were inspected. The building was observed to have a green placard in place. The main structural components of the building were able to be viewed due to the exposed simple construction of the building.

The visual inspection consisted of observing the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including observing the ground conditions, checking for damage in areas where damage would be expected for the structure type observed and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score is determined using the IEP procedure described by the NZSEE which is based on the information obtained from visual observation of the building and a desktop review of the available structural and geotechnical information. No critical structural weaknesses were observed thus not reducing the overall %NBS.

6. Damage Assessment

6.1 Surrounding Buildings

The Irrigation Pump House located in the Botanic Gardens is surrounded by green field areas and walkways. The structure is located opposite the south facing end of the Office Store. Minor staircase cracking was noted to the Office Store. (See Photograph 8, Appendix A)

6.2 Residual Displacements and General Observations

No residual displacements of the structure were noted during the inspection of the building.

No damage was evident to the exterior and interior of the building.

No damage was evident to the roof structure.

No damage was evident to the substructure of the building.

6.3 Ground Damage

No ground damage was observed during the inspection of the site.

7. Critical Structural Weakness

7.1 Short Columns

The building does not contain any short columns.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

No critical structural weaknesses were observed in the roof structure.

7.4 Plan Irregularity

There is no plan irregularity.

7.5 Staircases

The building does not contain a staircase.

7.6 Liquefaction

Liquefaction is possible on site however due to the nature of the structure (timber framed, single storey and on reinforced perimeter footings) it has been assessed as an 'insignificant' site characteristic in accordance with NZSEE guidelines.

8. Geotechnical Consideration

8.1 Site Description

The site is situated within a recreational reserve, in central Christchurch. It is relatively flat at approximately 8m above mean sea level. The structures are situated between 50m and 100m south of the Avon River, and 9.5km west of the coast (Pegasus Bay) at New Brighton.

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, comprising alluvial sand and silt overbank deposits.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that three boreholes are located within 200m of the site (see Table 2). Of these, two contained adequate lithographic logs. The site geology described in the logs is stratified gravel, sand, silt and clay. Also present are layers of peat between 20m and 40m bgl.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/1936	100.9m	1.4m bgl	50m E of office buildings
M35/10619	104.5m	0.8m bgl	100m E of office buildings

It should be noted that the purpose of the boreholes the well logs are associated with, were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

8.2.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to

¹ Brown, L. J. and Weeber, J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.

perform in future earthquakes. The site is classified as Technical Category N/A. This is due to the site not being classified as within a residential area.

8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows moderate amounts of liquefaction on the northern side of the Avon and in Victoria Lake, in the top-left and top-right corners of Figure 3. However, there is no evidence of liquefaction at the surface within the botanic gardens themselves.

Figure 3 Post February 2011 Earthquake Aerial Photography²



8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to be alluvial deposits comprising multiple strata of gravel, sandy gravel and silt/clay. Occasional layers of peat are also anticipated to be present between 20 and 40m bgl.

The Avon River is immediately adjacent to the site, and hence groundwater levels are expected to be close to the surface.

² Aerial Photography Supplied by Coordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 3 Summary of Known Active Faults^{3,4}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	20 km	W	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	100 km	NW	7.2	150 years
Porters Pass Fault	55 km	NW	7.0	1100 years

Recent earthquakes since 22 February 2011 have identified the presence of a previously unmapped active fault system underneath Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

This recent seismic activity has produced earthquakes of Magnitude 6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city and has resulted in widespread liquefaction throughout Christchurch.

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

Ground conditions are anticipated to comprise stratified alluvial deposits of varying density, and a 475-year PGA (peak ground acceleration) of ~0.4 (Stirling et al, 2002⁴). In addition, bedrock is anticipated to be in excess of 500m deep, and hence ground shaking is likely to be moderate to high.

8.4 Slope Failure and/or Rockfall Potential

Given the site's elevation and location in Central Christchurch, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

³ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

⁴ GNS Active Faults Database

8.5 Liquefaction Potential

Due to the anticipated presence of alluvial deposits and evidence from the post-earthquake aerial photography, it is considered possible that liquefaction will occur at the site in layers where sands and silts are present.

However, due to the presence of gravel and clay layers, evidence may not necessarily propagate to the surface. This gives the site a moderate liquefaction potential.

Further investigation is recommended to better determine subsoil conditions. From this, a more comprehensive liquefaction assessment could be undertaken.

8.6 Recommendations

Given the anticipated ground conditions and limited existing investigation in the vicinity of the site, we recommend that further investigation is undertaken. Specifically, three CPT investigations should be conducted to a target depth of 20m bgl.

8.7 Conclusions & Summary

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, predominantly comprising gravel and sand, interlain by clay. Associated with this the site also has a moderate liquefaction potential, in particular where sands and/or silts are present.

It is recommended that intrusive investigation comprising of three piezocone CPT's be conducted.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

9. Survey

No level or verticality surveys have been undertaken for this building at this stage.

10. Initial Capacity Assessment

10.1 % NBS Assessment

Following an IEP assessment, the building has been assessed as achieving 86% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is not considered Earthquake Prone or a potential Earthquake Risk as it exceed 67% NBS. This score has not been adjusted when considering damage to the structure as no damage was observed.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- ▶ Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor $R_u = 1$, NZS 1170.5:2004, Table 3.5, Importance Level 1 structure with a 50 year design life.

Several key seismic parameters have influenced the %NBS score obtained from the IEP assessment. The building has been assessed as an Importance Level 2 building. An increased Z factor of 0.3 for Christchurch has been used in line with recommendations from the Department of Building and Housing recommendations. The site soil class D, for soft soils, also has a negative effect on the building's seismic activity.

10.3 Expected Structural Ductility Factor

A structural ductility factor of 3.0 would be achievable for a timber framed structure of this nature for along and across the structure. However this value is limited to 2.0 based on Table 3.2 of the NZSEE guidelines.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age, importance level and construction type founded on Class D soils. This building would have been designed to the most recent standards with only minor changes made due to the recent seismic activity in Christchurch reducing the %NBS. Due to this the structure has achieved a %NBS of 86% and is not regarded as potentially Earthquake Prone or Risk.

10.5 Occupancy

As the building has been assessed to have a % NBS exceeding 67% NBS, it is not deemed as potentially Earthquake Prone Risk. The Christchurch City Councils (CCC) policy is not to occupy potentially Earthquake Prone buildings. In accordance with this general access to the building is allowed.

11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 86% NBS and is not deemed to be potentially Earthquake Prone or a potential Earthquake Risk in accordance with the NZSEE guidelines. In accordance with CCC policy to not occupy potentially Earthquake Prone buildings, it is recommended that general access to the building is allowed.

12. Recommendations

No damage was observed to the building during the recent seismic activity in Christchurch. Due to the structure achieving over 67% NBS, no further assessment is required.

13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.

Appendix A
Photographs



Photograph 1: West facing elevation



Photograph 2: South facing elevation showing Dutch hip roof




Photograph 3: Skylights to Roof structure



Photograph 4: Timber truss roof structure



Photograph 5: Pumphouse equipment on reinforced concrete slab



Photograph 6: Building location on site

Appendix B
Existing Drawings/Sketches

Appendix C

CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <input type="text" value="Botanic Gardens Irrigation Pump House"/>	Reviewer: <input type="text" value="Stephen Lee"/>
		Unit No: Street	CPEng No: <input type="text" value="1006840"/>
Building Address: <input type="text" value="7 Rolleston Avenue"/>			Company: <input type="text" value="GHD"/>
Legal Description: <input type="text"/>			Company project number: <input type="text" value="513059685"/>
			Company phone number: <input type="text" value="6433780900"/>
		Degrees Min Sec	Date of submission: <input type="text"/>
GPS south: <input type="text"/>			Inspection Date: <input type="text" value="04/04/2012"/>
GPS east: <input type="text"/>			Revision: <input type="text" value="Final"/>
Building Unique Identifier (CC): <input type="text" value="PRK 1566 BLDG 031 EQ2"/>			Is there a full report with this summary? <input type="text" value="yes"/>

Site		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
		Soil type: <input type="text" value="gravel"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>			If Ground improvement on site, describe: <input type="text"/>
Proximity to waterway (m, if <100m): <input type="text"/>			Approx site elevation (m): <input type="text"/>
Proximity to clifftop (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m, if <100m): <input type="text"/>			

Building		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
		Ground floor split? <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value="3.50"/>
		Storeys below ground: <input type="text" value="0"/>		
		Foundation type: <input type="text" value="strip footings"/>		if Foundation type is other, describe: <input type="text"/>
		Building height (m): <input type="text" value="3.50"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="3"/>	
		Floor footprint area (approx): <input type="text" value="29"/>		Date of design: <input type="text" value="2004-"/>
		Age of Building (years): <input type="text" value="5"/>		
		Strengthening present? <input type="text" value="no"/>		If so, when (year)? <input type="text"/>
		Use (ground floor): <input type="text" value="commercial"/>		And what load level (%g)? <input type="text"/>
		Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>
		Use notes (if required): <input type="text" value="Pump House"/>		
		Importance level (to NZS1170.5): <input type="text" value="IL1"/>		

Gravity Structure		Gravity System: <input type="text" value="load bearing walls"/>	
		Roof: <input type="text" value="timber framed"/>	rafter type, purlin type and cladding
		Floors: <input type="text" value="concrete flat slab"/>	slab thickness (mm)
		Beams: <input type="text"/>	<input type="text" value="75x50 purlins, 150x50 rafters, colorsteel cladding"/>
		Columns: <input type="text"/>	<input type="text" value="100"/>
		Walls: <input type="text"/>	<input type="text" value="200"/>

Lateral load resisting structure

Lateral system along:
Ductility assumed, μ :
Period along:
Total deflection (ULS) (mm):
maximum interstorey deflection (ULS) (mm):

0.00

Note: Define along and across in detailed report!

note typical wall length (m)

estimate or calculation?
estimate or calculation?
estimate or calculation?

Lateral system across:
Ductility assumed, μ :
Period across:
Total deflection (ULS) (mm):
maximum interstorey deflection (ULS) (mm):

0.00

note typical wall length (m)

estimate or calculation?
estimate or calculation?
estimate or calculation?

Separations:

north (mm):
east (mm):
south (mm):
west (mm):

leave blank if not relevant

Non-structural elements

Stairs:
Wall cladding:
Roof Cladding:
Glazing:
Ceilings:
Services(list):

describe (note cavity if exists)
describe

Available documentation

Architectural:
Structural:
Mechanical:
Electrical:
Geotech report:

original designer name/date
original designer name/date
original designer name/date
original designer name/date
original designer name/date

Damage

Site:
(refer DEE Table 4-2)

Site performance:

Describe damage:

Settlement:
Differential settlement:
Liquefaction:
Lateral Spread:
Differential lateral spread:
Ground cracks:
Damage to area:

notes (if applicable):
notes (if applicable):

Building: Current Placard Status:

Along Damage ratio: Describe how damage ratio arrived at:

Describe (summary):

Across Damage ratio: $Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$

Describe (summary):

Diaphragms Damage?: Describe:

CSWs: Damage?: Describe:

Pounding: Damage?: Describe:

Non-structural: Damage?: Describe:

Recommendations

Level of repair/strengthening required: Describe:

Building Consent required: Describe:

Interim occupancy recommendations: Describe:

Along Assessed %NBS before: 86% %NBS from IEP below If IEP not used, please detail assessment

Assessed %NBS after: methodology:

Across Assessed %NBS before: 86% %NBS from IEP below

Assessed %NBS after:

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 2004- h_n from above: 3m

Seismic Zone, if designed between 1965 and 1992: Design Soil type from NZS1170.5:2004, cl 3.1.3:

not required for this age of building

	along	across
Period (from above):	0.1	0.1
(%NBS) _{nom} from Fig 3.3:	22.5%	22.5%
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0		1.00
Note 2: for RC buildings designed between 1976-1984, use 1.2		1.0
Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)		1.0
Final (%NBS)_{nom}:	23%	23%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), Factor A:	1	1

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:	0.30
Z ₁₉₉₂ , from NZS4203:1992	0.8
Hazard scaling factor, Factor B:	2.666666667

2.4 Return Period Scaling Factor

Building Importance level (from above):	2
Return Period Scaling factor from Table 3.1, Factor C:	1.00

2.5 Ductility Scaling Factor

	along	across
Assessed ductility (less than max in Table 3.2)	2.00	2.00
Ductility scaling factor: =1 from 1976 onwards; or =k _μ , if pre-1976, from Table 3.3:	1.57	1.57
Ductility Scaling Factor, Factor D:	1.00	1.00

2.6 Structural Performance Scaling Factor:

Sp:	0.700	0.700
Structural Performance Scaling Factor Factor E:	1.428571429	1.428571429

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS _b :	86%	86%
---------------------	-----	-----

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: insignificant 1

3.2. Vertical irregularity, Factor B: insignificant 1

3.3. Short columns, Factor C: insignificant 1

3.4. Pounding potential
 Pounding effect D1, from Table to right 1.0
 Height Difference effect D2, from Table to right 1.0

Therefore, Factor D: 1

3.5. Site Characteristics insignificant 1

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H		.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H		.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum	Along	Across
Rationale for choice of F factor, if not 1	1.0	1.0

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

1.00	1.00
------	------

4.3 PAR x (%NBS)_b:

PAR x Baseline %NBS:	86%	86%
----------------------	-----	-----

4.4 Percentage New Building Standard (%NBS), (before)

86%

GHD

226 Antigua Street, Christchurch 8011
T: 64 3 378 0900 F: 64 3 377 8575 E: chcmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
FINAL	Cormac Joy	Stephen Lee		Nick Waddington		7/12/12