



Bottle Lake Forest - Information
Centre
Qualitative Engineering Evaluation

Reference: 228589
Prepared for:
Christchurch City Council

Functional Location ID: PRK_0158_BLDG_017

Revision: 4

Address: 70 Waitikiri Drive

Date: 10 October 2013

Document Control Record

Document prepared by:

Aurecon New Zealand Limited
 Level 2, 518 Colombo Street
 Christchurch 8011
 PO Box 1061
 Christchurch 8140
 New Zealand

T +64 3 375 0821
F +64 3 379 6955
E christchurch@aurecongroup.com
W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control						aurecon	
Report Title		Qualitative Engineering Evaluation					
Functional Location ID		PRK_0158_BLDG_017	Project Number		228589		
File Path		P:\228589 - Bottle Lake Forest - Information Centre.docx					
Client		Christchurch City Council	Client Contact		Michael Sheffield		
Rev	Date	Revision Details/Status	Prepared	Author	Verifier	Approver	
1	11 May 2012	Preliminary	C. Bong	C. Bong	S. Manning	S. Manning	
2	23 May 2012	Preliminary	C. Bong	C. Bong	S. Manning	S. Manning	
3	2 May 2013	Final	C. Bong	C. Bong	L. Castillo	L. Castillo	
4	10 October 2013	Final	C. Bong	C. Bong	L. Castillo	L. Castillo	
Current Revision		4					

Approval			
Author Signature		Approver Signature	
Name	Chris Bong	Name	Luis Castillo
Title	Structural Engineer	Title	Senior Structural Engineer



Contents

Executive Summary	1
1 Introduction	2
1.1 General	2
2 Description of the Building	2
2.1 Building Age and Configuration	2
2.2 Building Structural Systems Vertical and Horizontal	2
2.3 Reference Building Type	2
2.4 Building Foundation System and Soil Conditions	3
2.5 Available Structural Documentation and Inspection Priorities	3
2.6 Available Survey Information	3
3 Structural Investigation	3
3.1 Summary of Building Damage	3
3.2 Record of Intrusive Investigation	3
3.3 Damage Discussion	3
4 Building Review Summary	4
4.1 Building Review Statement	4
4.2 Critical Structural Weaknesses	4
5 Building Strength (Refer to Appendix C for background information)	4
5.1 Initial %NBS Assessment	4
6 Conclusions and Recommendations	4
7 Explanatory Statement	5

Appendices

Appendix A Photos and Level Survey

Appendix B References

Appendix C Strength Assessment Explanation

Appendix D Background and Legal Framework

Appendix E Standard Reporting Spread Sheet

Executive Summary

This is a summary of the Qualitative Engineering Evaluation for the Bottle Lake Forest - Information Centre building and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

Building Details	Name	Bottle Lake Forest - Information Centre			
Building Location ID	PRK_0158_BLDG_017	Multiple Building Site	Y		
Building Address	70 Waitikiri Drive	No. of residential units	0		
Soil Technical Category	N/A	Importance Level	2	Approximate Year Built	2000
Foot Print (m²)	130	Storeys above ground	1	Storeys below ground	0
Type of Construction	Corrugated iron roof on timber sarking and timber rafters, Lockwood style timber wall panels founded on concrete slab on grade				
Qualitative L4 Report Results Summary					
Building Occupied	Y	The Bottle Lake Forest - Information Centre is currently in service.			
Suitable for Continued Occupancy	Y	The Bottle Lake Forest - Information Centre is suitable for continued use.			
Key Damage Summary	Y	Refer to summary of building damage Section 3.1 report body.			
Critical Structural Weaknesses (CSW)	N	No critical structural weaknesses were identified.			
Levels Survey Results	N	Levels survey results are not within acceptable limits. The level damage was present before the earthquakes. It is recommended that the floor is re-levelled.			
Building %NBS From Analysis	74%	Based on an analysis of bracing capacity and demand.			
Qualitative L4 Report Recommendations					
Geotechnical Survey Required	N	Geotechnical survey not required due to lack of observed ground damage on site.			
Proceed to L5 Quantitative DEE	N	A quantitative DEE is not required for this structure.			
Approval					
Author Signature			Approver Signature		
Name	Chris Bong		Name	Luis Castillo	
Title	Structural Engineer		Title	Senior Structural Engineer	



1 Introduction

1.1 General

On 14 March 2012, Aurecon engineers visited the Bottle Lake Forest - Information Centre to carry out a qualitative building damage assessment on behalf of Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the earthquakes on 4 September 2010, 22 February 2011, 13 June 2011, 23 December 2011 and their subsequent aftershocks.

The scope of work included:

- Assessment of the nature and extent of the building damage; and
- Visual assessment of the building strength particularly with respect to safety of occupants if the building is currently occupied.

This report outlines the results of our qualitative assessment of damage to the Bottle Lake Forest - Information Centre and is based on the Detailed Engineering Evaluation Procedure document issued by the Structural Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

2 Description of the Building

2.1 Building Age and Configuration

The Bottle Lake Forest - Information Centre is a lightweight, light roof single storey structure with Lockwood style timber wall panels founded on a concrete slab on grade. Available plans indicate that it was built in the year 2000.

The approximate floor area of the Bottle Lake Forest - Information Centre is 130 square metres and it is classified as an importance level 2 building according to NZS 1170 Part 0: 2002.

2.2 Building Structural Systems Vertical and Horizontal

Tracing the loads from top to bottom, the vertical loads originate from the corrugated iron roof on purlins on timber sarking. Loads are transferred to the walls via the timber rafters that run perpendicular to the roof slope. The rafters in turn rest on the corresponding load bearing timber wall panels supported by the concrete slab foundation.

Transverse and longitudinal lateral loads at roof level are resisted by the timber sarking roof diaphragm. These loads are transferred down on the concrete slab on grade via the timber wall panels.

2.3 Reference Building Type

The information centre is a prefabricated kitset structure in the Lockwood style. Being a light weight single story timber structure supported on a piled concrete slab foundation it is of a building type that has typically performed well throughout the Canterbury earthquakes.



2.4 Building Foundation System and Soil Conditions

The information centre has a concrete slab on grade foundation with concrete footings around the perimeter. Drawings were available and these show that driven piles have been provided at approximately 2.5 meter centres around the perimeter and internally below the slab. An extensive timber deck also supported in driven piles has been provided. Piles appear to have been driven to a depth of approximately 2.0 metres.

A soil report by O'Loughlin Taylor Spence was also available and this indicates that the underlying soil conditions consist of about 500 mm of topsoil and fill over about a metre of mixed sand and topsoil over light brown underlying sand.

CERA land zone maps indicate that Bottle Lake Forest Park currently sits on "Yet To be Classified Rural & Unmapped Land", however the land to the immediate south has classed as Technical Category 2 Land. By extrapolation, the land is deemed unlikely to be subject to significant liquefaction or settlement in to future earthquakes. The site inspection has shown no obvious ground disturbance or movement have been noted in the immediate vicinity of the information centre.

2.5 Available Structural Documentation and Inspection Priorities

The building drawings were available for review and a drawings review was undertaken. The Bottle Lake Information Centre was built in July 2000 by Fraemohs Homes who were manufacturers of kitset timber buildings in a similar style to Lockwood. The building is braced by internal and external walls constructed of timber planks stacked upon one another and interlocked at corners. The structure is stiffened by the return walls that occur at regular intervals around the building perimeter. Being slender and in some areas tall the external walls may be vulnerable to wind face loads but not so much from the seismic loads that this report is concerned with.

2.6 Available Survey Information

A levels survey was carried out and the results have been included in Appendix A. The results of the levels survey show that existing floor levels are within acceptable limits.

3 Structural Investigation

3.1 Summary of Building Damage

The interior of the information centre was inaccessible at the time of the visit and an exterior only visual inspection was undertaken. There were no obvious signs of damage to the building when the visual inspection was undertaken on 14 March 2012.

3.2 Record of Intrusive Investigation

The exterior only visual inspection limited the viewing of some of the primary structural elements. The damage assessment showed that the building had minimal damage to the exterior. The interior, where visible from the exterior, also appeared to be largely undamaged. As the majority of the primary structural elements were fully exposed there was no need for any intrusive investigation.

3.3 Damage Discussion

It appears that the building has suffered little damage as a result of the seismic activity. This is not surprising as buildings of this type, as discussed above, have stood up well to the Canterbury earthquakes.



4 Building Review Summary

4.1 Building Review Statement

Not all of the structural components for this building were assessable. As such the visual inspection focused primarily on damage to the non-structural linings and trimming as key indicators of displacement damage.

The observed displacement damage for this building was found to be minor implying a commensurate degree of damage to the corresponding structural elements.

4.2 Critical Structural Weaknesses

No critical structural weaknesses were identified in the Bottle Lake Forest - Information Centre.

5 Building Strength (Refer to Appendix C for background information)

5.1 Initial %NBS Assessment

Because the Bottle Lake Visitors Centre is not an optimised engineered structure that was subject to specific engineering design the initial engineering procedure or IEP is not an appropriate method of initial assessment. The approach taken to determine the approximate seismic capacity of this structure was to calculate demand from first principles and then estimate capacity by assuming approximate strengths for existing materials. The size of existing load resisting elements, walls, in each direction was measured and from this an approximate capacity was calculated.

This exercise resulted in a longitudinal capacity in terms of percentage new building strength (%NBS) of 100%NBS and a transverse capacity of 74%NBS. Accordingly in the critical direction the estimated capacity is 74%NBS and this is then the value that defines the strength of the existing building. This value places the building approximately in the middle of the range of values that represent low risk buildings.

6 Conclusions and Recommendations

The absence of obvious visible damage to this structure tends to confirm the assessment that this structure; has sufficient seismic capacity, does not require strengthening and is suitable for continued occupation.

As the levels survey carried out for the Bottle Lake Forest - Information Centre shows that existing floor levels are within acceptable limits it is considered that no further investigation work is required.



7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

To carry out the structural review, existing building drawings were obtained (where available) from the Christchurch City Council records. We have assumed that the building has been constructed in accordance with the drawings.

While this report may assist the client in assessing whether the building should be repaired, strengthened, or replaced that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.

Appendices



Appendix A

Photos and Level survey

14 March 2012 – Bottle Lake Forest - Information Centre Site Photographs

<p>Front elevation of the Bottle Lake Forest - Information Centre.</p>	
<p>Rear elevation of Bottle Lake Forest Information Centre</p>	
<p>Side elevation of Bottle Lake Forest information Centre</p>	

Side elevation of Bottle Lake Forest Information Centre.



Concrete slab on ground foundation.



Interior of the Bottle Lake Forest - Information Centre.



Interior of the Bottle Lake Forest - Information Centre.




Interior of the Bottle Lake Forest - Information Centre.



Interior of the Bottle Lake Forest - Information Centre.





4/2/2017 4:59:48 p.m.



REV	DATE	REVISION DETAILS	APPROVAL

DRAWN	DESIGNED
D.HUNIA	C.BONG
CHECKED	
L.CASTILLO	
APPROVED	
	DATE
L.CASTILLO	

PROJECT
BOTTLE LAKE FOREST CHRISTCHURCH
TITLE
INFORMATION CENTRE FLOOR LEVEL SURVEY

PRELIMINARY NOT FOR CONSTRUCTION	
PROJECT No. 228589	
SCALE 1:100	SIZE A4
DRAWING No. S-01-00	REV

Appendix B

References

1. Department of Building and Housing (DBH), "Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence", November 2011
2. New Zealand Society for Earthquake Engineering (NZSEE), "Assessment and Improvement of the Structural Performance of Buildings in Earthquakes", April 2012
3. Standards New Zealand, "AS/NZS 1170 Part 0, Structural Design Actions: General Principles", 2002
4. Standards New Zealand, "AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions", 2002
5. Standards New Zealand, "NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand", 2004
6. Standards New Zealand, "NZS 3101 Part 1, The Design of Concrete Structures", 2006
7. Standards New Zealand, "NZS 3404 Part 1, Steel Structures Standard", 1997
8. Standards New Zealand, "NZS 3603, Timber Structures Standard", 1993
9. Standards New Zealand, "NZS 3604, Timber Framed Structures", 2011
10. Standards New Zealand, "NZS 4229, Concrete Masonry Buildings Not Requiring Specific Engineering Design", 1999
11. Standards New Zealand, "NZS 4230, Design of Reinforced Concrete Masonry Structures", 2004

Appendix C

Strength Assessment Explanation

New Building Standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22nd February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Appendix D

Background and Legal Framework

Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

Appendix E

Standard Reporting Spread Sheet

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <u>Bottle Lake Forest - Information Centre</u>	Reviewer: <u>Lee Howard</u>
Building Address: <u>Unit No: Street</u>	CP/Eng No: <u>1008889</u>	Company: <u>Aurecon</u>	Company project number: <u>228589</u>
Legal Description: _____	Company phone number: <u>03 375 0761</u>	Date of submission: <u>10/10/2013</u>	Inspection Date: <u>14/03/2012</u>
GPS south: <u>43</u> Degrees <u>28</u> Min <u>57</u> Sec	GPS east: <u>172</u> <u>40</u> <u>57.56</u>	Revision: <u>4</u>	Is there a full report with this summary? <u>yes</u>
Building Unique Identifier (CCI): <u>PRK_0158_BLDG_017</u>			

Site	Site slope: <u>flat</u>	Max retaining height (m): _____
Soil type: <u>mixed</u>	Soil Profile (if available): _____	
Site Class (to NZS1170.5): <u>D</u>	If Ground improvement on site, describe: _____	
Proximity to waterway (m, if <100m): _____		
Proximity to cliff top (m, if < 100m): _____		
Proximity to cliff base (m, if <100m): _____	Approx site elevation (m): <u>3.30</u>	

Building	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>3.55</u>
Ground floor split? <u>no</u>	Foundation type: <u>raft slab</u>	if Foundation type is other, describe: <u>Concrete slab on driven piles</u>	Ground floor elevation above ground (m): <u>0.55</u>
Stores below ground: <u>0</u>	Building height (m): <u>6.00</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>6</u>	
Floor footprint area (approx): <u>130</u>	Age of Building (years): <u>10</u>	Date of design: <u>1992-2004</u>	
Strengthening present? <u>no</u>	Use (ground floor): <u>public</u>	If so, when (year)? _____	
Use (upper floors): _____	Use notes (if required): <u>information centre, visitors centre</u>	And what load level (%g)? _____	
Importance level (to NZS1170.5): <u>IL2</u>		Brief strengthening description: _____	

Gravity Structure	Gravity System: <u>load bearing walls</u>	
Floors: <u>timber framed</u>	rafter type, purlin type and cladding: _____	<u>solid timber walls and ceiling, light weight timber rafters, corrugated iron roof</u>
Beams: <u>concrete flat slab</u>	slab thickness (mm) type: _____	
Columns: <u>load bearing walls</u>	typical dimensions (mm x mm): <u>solid wood walls</u>	
Walls: _____		

Lateral load resisting structure	Lateral system along: <u>lightweight timber framed walls</u>	Note: Define along and across in detailed report!	note typical wall length (m): <u>9.5</u>
Ductility assumed, μ : <u>1.25</u>	Period along: <u>0.40</u>	0.00	estimate or calculation? <u>estimated</u>
Total deflection (ULS) (mm): _____	maximum interstorey deflection (ULS) (mm): _____		estimate or calculation? <u>estimated</u>
Lateral system across: <u>lightweight timber framed walls</u>	Ductility assumed, μ : <u>1.25</u>	0.00	note typical wall length (m): <u>9</u>
Period across: <u>0.40</u>	Total deflection (ULS) (mm): _____		estimate or calculation? <u>estimated</u>
maximum interstorey deflection (ULS) (mm): _____			estimate or calculation? <u>estimated</u>

Separations:	north (mm): _____	leave blank if not relevant
east (mm): _____		
south (mm): _____		
west (mm): _____		

Non-structural elements	Stairs: _____	<u>none</u>
Wall cladding: _____	<u>none, solid timber walls</u>	
Roof Cladding: _____	<u>corrugated iron</u>	
Glazing: _____	<u>solid timber</u>	
Ceilings: _____		
Services (list): _____		

Available documentation	Architectural: <u>none</u>	original designer name/date: _____
Structural: <u>none</u>	original designer name/date: _____	
Mechanical: <u>none</u>	original designer name/date: _____	
Electrical: <u>none</u>	original designer name/date: _____	
Geotech report: <u>none</u>	original designer name/date: _____	

Damage	Site performance: _____	Describe damage: <u>minor - none</u>
Site: (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): _____
Differential settlement: <u>none observed</u>	Liquefaction: <u>none apparent</u>	notes (if applicable): _____
Lateral Spread: <u>none apparent</u>	Differential lateral spread: <u>none apparent</u>	notes (if applicable): _____
Ground cracks: <u>none apparent</u>	Damage to area: <u>none apparent</u>	notes (if applicable): _____

Building:	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: _____
Describe (summary): _____		
Across	Damage ratio: <u>0%</u>	$Damage_Ratio = \frac{(\%NBS\ before) - \%NBS\ (after)}{\%NBS\ (before)}$
Describe (summary): _____		
Diaphragms	Damage?: <u>no</u>	Describe: _____
CSWs:	Damage?: <u>no</u>	Describe: _____
Pounding:	Damage?: <u>no</u>	Describe: _____
Non-structural:	Damage?: <u>no</u>	Describe: _____

Recommendations	Level of repair/strengthening required: <u>none</u>	Describe: _____
Building Consent required: <u>no</u>	Interim occupancy recommendations: <u>full occupancy</u>	Describe: _____
Along	Assessed %NBS before: <u>100%</u> ##### %NBS from IEP below	If IEP not used, please detail assessment methodology: _____
Assessed %NBS after: <u>100%</u>		
Across	Assessed %NBS before: <u>74%</u> ##### %NBS from IEP below	
Assessed %NBS after: <u>74%</u>		

IEP	Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.	
Period of design of building (from above): <u>1992-2004</u>	h_n from above: <u>6m</u>	
Seismic Zone, if designed between 1965 and 1992: _____	not required for this age of building	
	Design Soil type from NZS4203:1992, cl 4.6.2.2: _____	
	Period (from above): _____	along <u>0.4</u> across <u>0.4</u>
	(%NBS) from Fig 3.3: _____	
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0		
Note 2: for RC buildings designed between 1976-1984, use 1.2		
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)		

Final (%NBS)_{nom}:

along	0%
across	0%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), **Factor A**):

along	#DIV/0!
across	#DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:

Z₁₉₉₂, from NZS4203:1992
Hazard scaling factor, **Factor B**:

#DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above):
Return Period Scaling factor from Table 3.1, **Factor C**:

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)
Ductility scaling factor: =1 from 1976 onwards; or =k_y, if pre-1976, from Table 3.3:

along	
across	

Ductility Scaling Factor, **Factor D**:

1.00	1.00
------	------

2.6 Structural Performance Scaling Factor:

Sp:

Structural Performance Scaling Factor **Factor E**:

#DIV/0!	#DIV/0!
---------	---------

2.7 Baseline %NBS, (NBS%)_e = (%NBS)_{nom} x A x B x C x D x E

%NBS_e:

#DIV/0!	#DIV/0!
---------	---------

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

insignificant	1
---------------	---

3.2. Vertical irregularity, Factor B:

insignificant	1
---------------	---

3.3. Short columns, Factor C:

insignificant	1
---------------	---

3.4. Pounding potential

Pounding effect D1, from Table to right:

Height Difference effect D2, from Table to right:

Therefore, Factor D:

0

3.5. Site Characteristics

insignificant	1
---------------	---

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum
Rationale for choice of F factor, if not 1:

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

0.00	0.00
------	------

4.3 PAR x (%NBS)_e: PAR x Baseline %NBS:

#DIV/0!	#DIV/0!
---------	---------

4.4 Percentage New Building Standard (%NBS), (before)

#DIV/0!



Aurecon New Zealand Limited

**Level 2, 518 Colombo Street
Christchurch 8011**

PO Box 1061
Christchurch 8140
New Zealand

T +64 3 375 0821

F +64 3 379 6955

E christchurch@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:

Angola, Australia, Botswana, China,
Ethiopia, Hong Kong, Indonesia,
Lesotho, Libya, Malawi, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.