



Burwood Park South
Pavilion/Toilets
Qualitative Engineering Evaluation

Reference: 229604
Prepared for:
Christchurch City Council

Functional Location ID: PRK 0724 BLDG 002 EQ2

Revision: 2

Address: 45 Cresswell Avenue

Date: 24 June 2013

Document Control Record

Document prepared by:

Aurecon New Zealand Limited
 Level 2, 518 Colombo Street
 Christchurch 8011
 PO Box 1061
 Christchurch 8140
 New Zealand


T +64 3 375 0761
F +64 3 379 6955
E christchurch@aurecongroup.com
W aurecongroup.com

A person using Aurecon documents or data accepts the risk of:

- Using the documents or data in electronic form without requesting and checking them for accuracy against the original hard copy version.
- Using the documents or data for any purpose not agreed to in writing by Aurecon.

Document control				aurecon		
Report Title		Qualitative Engineering Evaluation				
Functional Location ID		PRK 0724 BLDG 002 EQ2	Project Number		229604	
File Path		P:\ 229604 - Burwood Park South Pavilion/Toilets.docx				
Client		Christchurch City Council	Client Contact		Michael Sheffield	
Rev	Date	Revision Details/Status	Prepared	Author	Verifier	Approver
1	15 January 2013	Draft	C. Bong	C. Bong	L. Castillo	L. Castillo
2	24 June 2013	Final	C. Bong	C. Bong	L. Castillo	L. Castillo
Current Revision		2				

Approval			
Author Signature			
Approver Signature			
Name	Christopher Bong	Name	Luis Castillo
Title	Structural Engineer	Title	Senior Structural Engineer



Contents

Executive Summary	1
1 Introduction	2
1.1 General	2
2 Description of the Building	2
2.1 Building Age and Configuration	2
2.2 Building Structural Systems Vertical and Horizontal	2
2.3 Reference Building Type	3
2.4 Building Foundation System and Soil Conditions	4
2.5 Available Structural Documentation and Inspection Priorities	4
2.6 Available Survey Information	4
3 Structural Investigation	5
3.1 Summary of Building Damage	5
3.2 Record of Intrusive Investigation	5
3.3 Damage Discussion	5
4 Building Review Summary	5
4.1 Building Review Statement	5
4.2 Critical Structural Weaknesses	5
5 Building Strength (Refer to Appendix C for background information)	6
5.1 General	6
5.2 Initial %NBS Assessment	6
5.3 Results Discussion	7
6 Conclusions and Recommendations	7
7 Explanatory Statement	7

Appendices

Appendix A Site Map, Photos and Levels Survey

Appendix B References

Appendix C Strength Assessment Explanation

Appendix D Background and Legal Framework

Appendix E Standard Reporting Spread Sheet

Executive Summary

This is a summary of the Qualitative Engineering Evaluation for the Burwood Park South Pavilion/Toilets building and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

Building Details	Name	Burwood Park South Pavilion/Toilets			
Building Location ID	PRK 0724 BLDG 002 EQ2			Multiple Building Site	N
Building Address	45 Cresswell Avenue			No. of residential units	0
Soil Technical Category	NA	Importance Level	1	Approximate Year Built	1970s
Foot Print (m²)	100	Storeys above ground	1	Storeys below ground	0
Type of Construction	Lightweight profiled sheet metal roof, timber purlins and rafters, concrete masonry walls and concrete slab on grade foundations.				
Qualitative L4 Report Results Summary					
Building Occupied	Y	The Burwood Park South Pavilion/Toilets is currently in service.			
Suitable for Continued Occupancy	Y	The Burwood Park South Pavilion/Toilets is suitable for continued use.			
Key Damage Summary	Y	Refer to summary of building damage Section 3.1 report body.			
Critical Structural Weaknesses (CSW)	N	No critical structural weaknesses were identified.			
Levels Survey Results	Y	The maximum slope was found to be 0.5% or 1 in 200 which is within the Department of Building and Housing Guidelines.			
Building %NBS From Analysis	38%	Based on an analysis of bracing capacity and demand.			
Qualitative L4 Report Recommendations					
Geotechnical Survey Required	N	Geotechnical survey not required due to lack of foundation damage noted.			
Proceed to L5 Quantitative DEE	N	A quantitative DEE is not required for this structure.			
Approval					
Author Signature			Approver Signature		
Name	Christopher Bong		Name	Luis Castillo	
Title	Structural Engineer		Title	Senior Structural Engineer	



1 Introduction

1.1 General

On 14 August 2012 Aurecon engineers visited the Burwood Park South Pavilion/Toilets to undertake a qualitative building damage assessment on behalf of Christchurch City Council. Detailed visual inspections were carried out to assess the damage caused by the Canterbury earthquake sequence.

The scope of work included:

- Assessment of the nature and extent of the building damage.
- Visual assessment of the building strength particularly with respect to safety of occupants if the building is currently occupied.
- Assessment of requirements for detailed engineering evaluation including geotechnical investigation, level survey and any areas where linings and floor coverings need removal to expose structural damage.

This report outlines the results of our Qualitative Assessment of damage to the Burwood Park South Pavilion/Toilets and is based on the Detailed Engineering Evaluation Procedure document issued by the Engineering Advisory Group on 19 July 2011, visual inspections, available structural documentation and summary calculations as appropriate.

2 Description of the Building

2.1 Building Age and Configuration

The Burwood Park South Pavilion/Toilets is medium-sized, single storey concrete masonry ablutions block, most likely constructed in the 1970s. The roof of the building consists of a profiled metal sheet roof on a lightweight timber frame. The building consists of two changing rooms, a storeroom and two public restrooms. All rooms are only assessable from the exterior.

The building has an approximate floor area of 100 square metres. It is considered as an “Importance Level 2 Structure” in accordance with AS/NZS 1170 Part 0:2002.

2.2 Building Structural Systems Vertical and Horizontal

The Burwood Park South Pavilion/Toilets is a partially filled concrete masonry wall building. The gravity loads from the timber framed roof are transferred into the ground via the concrete masonry walls and the concrete slab on grade foundations.

The lateral load resisting structure is identical to the gravity system in which the lateral loads in both principal directions are resisted by the concrete masonry walls.

2.3 Reference Building Type

A general overview of the reference building type, construction era and likely earthquake risk is presented in Figure 1 below. The Burwood Park South Pavilion/Toilets is a lightly reinforced partially filled concrete masonry wall building constructed in the 1970s and according to the figure below is “possibly earthquake prone”.



Figure 1: Timeline showing the building types, approximate time of construction and likely earthquake risk.
(From the Draft Guidance on DEEs of non-residential buildings by the Engineering Advisory Group)

The Burwood Park South Pavilion/Toilets have regularly spaced bracing lines and plan geometry. As such, it is anticipated that the structural performance will not be inhibited by a critical structural weakness.



2.4 Building Foundation System and Soil Conditions

The Burwood Park South Pavilion/Toilets is founded on a concrete slab on grade foundation.

The land in Burwood Park has been zoned green by the Canterbury Earthquake Recovery Authority (CERA). Although it should be noted that the adjacent land to the east has been zoned red.

As the land is currently non-residential, it has not been included in the Technical Category classification by the Building and Housing Group (formerly known as the Department of Building and Housing (DBH)) and has been classed as “N/A – Urban Non-residential”. It is of note however, that the adjacent residences due north, south and west of the park consist typically Technical Category 2 and 3 lands.

2.5 Available Structural Documentation and Inspection Priorities

There were no drawings available for the Burwood Park South Pavilion/Toilets.

The inspection priorities for the building are the review of damage to the mortar joints which are inherently weaker than the concrete masonry blocks. Additionally, the damage assessment focused on the building geometry and other forms of potential damage such as cracking in the concrete masonry block and concrete floor.

2.6 Available Survey Information

A floor level survey was undertaken to establish the level of unevenness across the floors. The results of the survey are presented on the attached sketch in Appendix A.

The Building and Housing Group (formerly known as the DBH) published the “Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence” in November 2011, which recommends some form of re-levelling or rebuilding of the floor

1. If the slope is greater than 0.5% for any two points more than 2m apart, or
2. If the variation in level over the floor plan is greater than 50mm, or
3. If there is significant cracking of the floor.

It is important to note that these figures are recommendations and are only intended to be applied to residential buildings. However, they provide useful guidance in determining acceptable floor level variations.

The maximum floor slope for the Burwood Park South Pavilion/Toilets noted was 0.5% or 1:200 which were within the aforementioned thresholds and are considered “acceptable”.



3 Structural Investigation

3.1 Summary of Building Damage

The noted damages to the Burwood Park South Pavilion/Toilets are as follows:-

- Step cracking in the mortar joints; and
- Cracking to the face shell of the concrete masonry unit.

There have also been noted instances of cracking to the apron of the building, which we consider to be non-seismic related.

3.2 Record of Intrusive Investigation

A non-destructive intrusive investigation was undertaken. A metal detector, HILTI PS 35, was used to confirm the locations for the reinforcing bars in the concrete masonry walls. It was found that

- The masonry units below the window had horizontal reinforcing bars;
- In the changing rooms (but not the toilets) the masonry units had horizontal reinforcing bars;
- The bond beams above the door way are reinforced;
- There is reinforcing in the bond beams above the gable walls.

3.3 Damage Discussion

Damage from seismic actions will typically be concentrated on the weaker elements of a structure. This explains the damage noted above as wall openings and unfilled spans of concrete masonry walls are inherently the weakest parts of lightly reinforced concrete masonry wall buildings.

4 Building Review Summary

4.1 Building Review Statement

A non-destructive intrusive investigation was undertaken on the Burwood Park South Pavilion/Toilets. In the intrusive investigation, a HILTI PS 35 metal detector was used to identify the reinforcing bar locations in the walls.

4.2 Critical Structural Weaknesses

No specific critical structural weaknesses were identified as part of the building qualitative assessment. The only damage identified was minor and does not affect the strength of the building.

5 Building Strength (Refer to Appendix C for background information)

5.1 General

The Burwood Park South Pavilion/Toilets is of lightly reinforced partially filled concrete masonry construction. The building has sustained some damage in the Canterbury earthquake sequence but has otherwise performed satisfactorily due to its regularly spaced bracing lines and plan geometry.

5.2 Initial %NBS Assessment

The Burwood Park South Pavilion/Toilets is unlikely to have been subject to specific engineering design and the initial evaluation procedure or IEP is not an appropriate method of assessment for this building. Nevertheless an estimate of lateral load capacity can be made by adopting assumed values for strengths of existing materials and calculating the capacity of existing walls.

The selected assessment seismic parameters are tabulated in the table1 below.

Table 1: Parameters used in the Seismic Assessment

Seismic Parameter	Quantity	Comment/Reference
Site Soil Class	D	NZS 1170.5:2004, Clause 3.1.3, Deep or Soft Soil
Site Hazard Factor, Z	0.30	DBH Info Sheet on Seismicity Changes (Effective 19 May 2011)
Return period Factor, R_u	1.00	NZS 1170.5:2004, Table 3.5, Importance Level 2 Structure with a Design Life of 50 years
Ductility Factor in the Along Direction, μ	1.25	Lightly reinforced partially filled concrete masonry walls.
Ductility Factor in the Across Direction, μ	1.25	Lightly reinforced partially filled concrete masonry walls.

The seismic demand for the Burwood Park South Pavilion/Toilets has been calculated based on the current code requirements of NZS 1170 Part 5:2004 (Structural Design Actions: Earthquake Actions – New Zealand). The capacity of the existing walls in the building was calculated from assumed strengths of existing materials and the number and length of walls present in each bracing line for both the along and across directions in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) 2011 Unreinforced Masonry Guidelines. The seismic demand was then compared with the building capacity in these directions. The building was found to have a sufficient number and length of walls in both the along and across directions to achieve a capacity of 38% NBS.



5.3 Results Discussion

The bracing check is in agreement with the observations of the damage assessment. The capacity of the building is limited by the in-plane strength of the concrete masonry walls in the across direction.

6 Conclusions and Recommendations

As the land in which the Burwood Park South Pavilion/Toilets lies within the buffer of red and green zones, we strongly recommend that **a geotechnical investigation be undertaken.**

The building has suffered no loss of functionality and in our opinion the Burwood Park South Pavilion/Toilets is repairable and **is considered suitable for continued use.**

7 Explanatory Statement

The inspections of the building discussed in this report have been undertaken to assess structural earthquake damage. No analysis has been undertaken to assess the strength of the building or to determine whether or not it complies with the relevant building codes, except to the extent that Aurecon expressly indicates otherwise in the report. Aurecon has not made any assessment of structural stability or building safety in connection with future aftershocks or earthquakes – which have the potential to damage the building and to jeopardise the safety of those either inside or adjacent to the building, except to the extent that Aurecon expressly indicates otherwise in the report.

This report is necessarily limited by the restricted ability to carry out inspections due to potential structural instabilities/safety considerations, and the time available to carry out such inspections. The report does not address defects that are not reasonably discoverable on visual inspection, including defects in inaccessible places and latent defects. Where site inspections were made, they were restricted to external inspections and, where practicable, limited internal visual inspections.

While this report may assist the client in assessing whether the building should be repaired, strengthened, or replaced that decision is the sole responsibility of the client.

This review has been prepared by Aurecon at the request of its client and is exclusively for the client's use. It is not possible to make a proper assessment of this review without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to and the assumptions made by Aurecon. The report will not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, Aurecon's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited as set out in the terms of the engagement with the client.

Appendices



Appendix A

Site Map, Photos and Levels Survey

14 August 2012 – Burwood Park South Pavilion/Toilets Site Photographs



Aerial Photograph courtesy of the Canterbury Geotechnical Database

Northern (front oblique) elevation of the Burwood Park South Pavilion/Toilets.



North eastern (end) elevation of the Burwood Park South Pavilion/Toilets.




Southern (side oblique) elevation of the Burwood Park South Pavilion/Toilets.



Typical veranda detail.



Typical window detail.





Typical roof frame detail.



Typical roof-gable wall detail.



<p>Typical wall–concrete slab on grade detail.</p>	
<p>Seismic damage – exterior view of cracking in the concrete masonry unit.</p>	
<p>Seismic damage – interior close up on the same crack indicating</p>	
<p>Seismic damage – exterior view of step cracking in the concrete masonry unit.</p>	
<p>Age-related damage – cracking in the concrete apron.</p>	



1:00/2013 2:39:24 pm



REV	DATE	REVISION DETAILS	APPROVAL

DRAWN	DESIGNED
D.HUNIA	C.BONG
CHECKED	
L.CASTILLO	
APPROVED	
	DATE
L.CASTILLO	

PROJECT
BURWOOD PARK SOUTH TOILETS
TITLE
LEVEL SURVEY

PRELIMINARY NOT FOR CONSTRUCTION	
PROJECT No. 229604	
SCALE 1:100	SIZE A4
DRAWING No. S-01-01	REV

Appendix B

References

1. Department of Building and Housing (DBH), "Revised Guidance on Repairing and Rebuilding Houses Affected by the Canterbury Earthquake Sequence", November 2011
2. New Zealand Society for Earthquake Engineering (NZSEE), "Assessment and Improvement of the Structural Performance of Buildings in Earthquakes", April 2012
3. Standards New Zealand, "AS/NZS 1170 Part 0, Structural Design Actions: General Principles", 2002
4. Standards New Zealand, "AS/NZS 1170 Part 1, Structural Design Actions: Permanent, imposed and other actions", 2002
5. Standards New Zealand, "NZS 1170 Part 5, Structural Design Actions: Earthquake Actions – New Zealand", 2004
6. Standards New Zealand, "NZS 3101 Part 1, The Design of Concrete Structures", 2006
7. Standards New Zealand, "NZS 3404 Part 1, Steel Structures Standard", 1997
8. Standards New Zealand, "NZS 3603, Timber Structures Standard", 1993
9. Standards New Zealand, "NZS 3604, Timber Framed Structures", 2011
10. Standards New Zealand, "NZS 4229, Concrete Masonry Buildings Not Requiring Specific Engineering Design", 1999
11. Standards New Zealand, "NZS 4230, Design of Reinforced Concrete Masonry Structures", 2004

Appendix C

Strength Assessment Explanation

New building standard (NBS)

New building standard (NBS) is the term used with reference to the earthquake standard that would apply to a new building of similar type and use if the building was designed to meet the latest design Codes of Practice. If the strength of a building is less than this level, then its strength is expressed as a percentage of NBS.

Earthquake Prone Buildings

A building can be considered to be earthquake prone if its strength is less than one third of the strength to which an equivalent new building would be designed, that is, less than 33%NBS (as defined by the New Zealand Building Act). If the building strength exceeds 33%NBS but is less than 67%NBS the building is considered at risk.

Christchurch City Council Earthquake Prone Building Policy 2010

The Christchurch City Council (CCC) already had in place an Earthquake Prone Building Policy (EPB Policy) requiring all earthquake-prone buildings to be strengthened within a timeframe varying from 15 to 30 years. The level to which the buildings were required to be strengthened was 33%NBS.

As a result of the 4 September 2010 Canterbury earthquake the CCC raised the level that a building was required to be strengthened to from 33% to 67% NBS but qualified this as a target level and noted that the actual strengthening level for each building will be determined in conjunction with the owners on a building-by-building basis. Factors that will be taken into account by the Council in determining the strengthening level include the cost of strengthening, the use to which the building is put, the level of danger posed by the building, and the extent of damage and repair involved.

Irrespective of strengthening level, the threshold level that triggers a requirement to strengthen is 33%NBS.

As part of any building consent application fire and disabled access provisions will need to be assessed.

Christchurch Seismicity

The level of seismicity within the current New Zealand loading code (AS/NZS 1170) is related to the seismic zone factor. The zone factor varies depending on the location of the building within NZ. Prior to the 22nd February 2011 earthquake the zone factor for Christchurch was 0.22. Following the earthquake the seismic zone factor (level of seismicity) in the Christchurch and surrounding areas has been increased to 0.3. This is a 36% increase.

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that

assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure C1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

Figure C1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table C1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% probability of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% probability of exceedance in the next year.

Table C1: Relative Risk of Building Failure In A

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Appendix D

Background and Legal Framework

Background

Aurecon has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the building

This report is a Qualitative Assessment of the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

Appendix E

Standard Reporting Spread Sheet

Detailed Engineering Evaluation Summary Data

V1.11

Location		Building Name: <input type="text" value="Burwood Park South Pavilion/Toilets"/>	Reviewer: <input type="text" value="Lee Howard"/>
	Unit No: Street		CPEng No: <input type="text" value="1008889"/>
Building Address: <input type="text" value="45 Cresswell Avenue"/>		Company: <input type="text" value="Aurecon NZ Ltd"/>	
Legal Description: <input type="text" value="Lot 6 DP 8140"/>		Company project number: <input type="text" value="229604"/>	
		Company phone number: <input type="text" value="03 366 0821"/>	
	Degrees Min Sec		Date of submission: <input type="text" value="Jun-13"/>
GPS south: <input type="text" value="43 30 26.38"/>			Inspection Date: <input type="text" value="Aug-12"/>
GPS east: <input type="text" value="172 40 19.34"/>			Revision: <input type="text" value="2"/>
Building Unique Identifier (CCC): <input type="text" value="PRK_0724_BLDG_002"/>			Is there a full report with this summary? <input type="text" value="yes"/>

Site		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value="0"/>
	Soil type: <input type="text" value="mixed"/>	Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>			
Proximity to waterway (m, if <100m): <input type="text"/>		If Ground improvement on site, describe: <input type="text"/>	
Proximity to clifftop (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m,if <100m): <input type="text"/>		Approx site elevation (m): <input type="text" value="5.00"/>	

Building		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="5.10"/>
Ground floor split? <input type="text" value="no"/>				Ground floor elevation above ground (m): <input type="text" value="0.10"/>
Storeys below ground: <input type="text" value="0"/>				
Foundation type: <input type="text" value="raft slab"/>				if Foundation type is other, describe: <input type="text"/>
Building height (m): <input type="text"/>		height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>		
Floor footprint area (approx): <input type="text"/>				Date of design: <input type="text"/>
Age of Building (years): <input type="text"/>				
Strengthening present? <input type="text" value="no"/>				If so, when (year)? <input type="text"/>
Use (ground floor): <input type="text" value="public"/>				And what load level (%g)? <input type="text"/>
Use (upper floors): <input type="text"/>				Brief strengthening description: <input type="text"/>
Use notes (if required): <input type="text" value="toilets"/>				
Importance level (to NZS1170.5): <input type="text" value="IL2"/>				

Gravity Structure		Gravity System: <input type="text" value="load bearing walls"/>	
Roof: <input type="text" value="timber framed"/>		rafter type, purlin type and cladding: <input type="text" value="timber purlins and rafters, profiled metal sheet roof"/>	
Floors: <input type="text" value="concrete flat slab"/>		slab thickness (mm): <input type="text" value="unknown"/>	
Beams: <input type="text"/>			
Columns: <input type="text" value="structural steel"/>		typical dimensions (mm x mm): <input type="text" value="timber framed"/>	
Walls: <input type="text" value="partially filled concrete masonry"/>		thickness (mm): <input type="text" value="190"/>	

Lateral load resisting structure		Lateral system along: <input type="text" value="partially filled CMU"/>	Note: Define along and across in detailed report!	
Ductility assumed, μ :	<input type="text" value="1.25"/>	Period along: <input type="text" value="0.40"/>	##### enter height above at H31	note total length of wall at ground (m): <input type="text"/>
Total deflection (ULS) (mm):	<input type="text"/>			estimate or calculation? <input type="text" value="estimated"/>
maximum interstorey deflection (ULS) (mm):	<input type="text"/>			estimate or calculation? <input type="text"/>
				estimate or calculation? <input type="text"/>

Lateral system across:	partially filled CMU		
Ductility assumed, μ :	1.25		
Period across:	0.40	##### enter height above at H31	note total length of wall at ground (m):
Total deflection (ULS) (mm):			estimate or calculation? estimated
maximum interstorey deflection (ULS) (mm):			estimate or calculation?
			estimate or calculation?

Separations:

north (mm):		leave blank if not relevant
east (mm):		
south (mm):		
west (mm):		

Non-structural elements

Stairs:		
Wall cladding:		
Roof Cladding:	Metal	describe profile sheet metal roof
Glazing:		
Ceilings:		
Services(list):	water and waste water	

Available documentation

Architectural	none	original designer name/date	
Structural	none	original designer name/date	
Mechanical	none	original designer name/date	
Electrical	none	original designer name/date	
Geotech report	none	original designer name/date	

Damage

Site performance: good

Site: (refer DEE Table 4-2)

Settlement:	none observed	Describe damage: none noted
Differential settlement:	none observed	
Liquefaction:	none apparent	
Lateral Spread:	none apparent	
Differential lateral spread:	none apparent	
Ground cracks:	none apparent	
Damage to area:	none apparent	

notes (if applicable):

Building:

Current Placard Status: green

Along

Damage ratio:

Describe (summary):

Across

Damage ratio: #DIV/0!

Describe (summary):

Diaphragms

Damage?: yes

Describe: crack in concrete masonry wall

CSWs:

Damage?: no

Describe:

Pounding:

Damage?: no

Describe:

Non-structural:

Damage?: no

Describe:

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Recommendations

Level of repair/strengthening required:
 Building Consent required:
 Interim occupancy recommendations:

Describe:
 Describe:
 Describe:

Along

Assessed %NBS before e'quakes:
 Assessed %NBS after e'quakes: ##### %NBS from IEP below

If IEP not used, please detail assessment methodology:

Across

Assessed %NBS before e'quakes:
 Assessed %NBS after e'quakes: ##### %NBS from IEP below

IEP

Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above):

h_n from above:

Seismic Zone, if designed between 1965 and 1992:

not required for this age of building
 not required for this age of building

	along	across
Period (from above):	<input type="text" value="0.4"/>	<input type="text" value="0.4"/>
(%NBS) _{nom} from Fig 3.3:	<input type="text"/>	<input type="text"/>

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
Final (%NBS) _{nom} :	<input type="text" value="0%"/>	<input type="text" value="0%"/>

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), Factor A):	<input type="text" value="#DIV/0!"/>	<input type="text" value="#DIV/0!"/>

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:

Z_{1992} , from NZS4203:1992
 Hazard scaling factor, **Factor B**:

2.4 Return Period Scaling Factor

Building Importance level (from above):
 Return Period Scaling factor from Table 3.1, **Factor C**:

2.5 Ductility Scaling Factor

	along	across
Assessed ductility (less than max in Table 3.2)	<input type="text"/>	<input type="text"/>
Ductility scaling factor: =1 from 1976 onwards; or = k_{μ} , if pre-1976, from Table 3.3:	<input type="text"/>	<input type="text"/>

Ductility Scaling Factor, Factor D :	<input type="text" value="0.00"/>	<input type="text" value="0.00"/>
---	-----------------------------------	-----------------------------------

2.6 Structural Performance Scaling Factor:

Sp:

Structural Performance Scaling Factor Factor E :	<input type="text" value="#DIV/0!"/>	<input type="text" value="#DIV/0!"/>
---	--------------------------------------	--------------------------------------

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS _b :	<input type="text" value="#DIV/0!"/>	<input type="text" value="#DIV/0!"/>
---------------------	--------------------------------------	--------------------------------------

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A:

3.2. Vertical irregularity, Factor B:

3.3. Short columns, Factor C:

3.4. Pounding potential
Pounding effect D1, from Table to right
Height Difference effect D2, from Table to right

Therefore, Factor D:

3.5. Site Characteristics

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum
Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)
List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

4.3 PAR x (%NBS)b: PAR x Baseline %NBS:

4.4 Percentage New Building Standard (%NBS), (before)



Aurecon New Zealand Limited

**Level 2, 518 Colombo Street
Christchurch 8011**

PO Box 1061
Christchurch 8140
New Zealand

T +64 3 366 0821

F +64 3 379 6955

E christchurch@aurecongroup.com

W aurecongroup.com

Aurecon offices are located in:

Angola, Australia, Botswana, China,
Ethiopia, Hong Kong, Indonesia,
Lesotho, Libya, Malawi, Mozambique,
Namibia, New Zealand, Nigeria,
Philippines, Singapore, South Africa,
Swaziland, Tanzania, Thailand, Uganda,
United Arab Emirates, Vietnam.