



CLIENTS | PEOPLE | PERFORMANCE

**Pavilion/Toilet – Lyttelton Street /
Centennial Park
PRK_1095_BLDG_002 EQ2
Detailed Engineering Evaluation
Qualitative Report
Version Final**

Lyttelton Street, Somerfield

**Centennial Park Pavilion/Toilet
PRK_1095_BLDG_002 EQ2**

Detailed Engineering Evaluation
Qualitative Report
Version Final

Lyttelton Street, Somerfield

Christchurch City Council

Prepared By
Dale Donovan

Reviewed By
David Lee

Date
1 October 2012

Contents

Qualitative Report Summary	i
1. Background	1
2. Compliance	2
2.1 Canterbury Earthquake Recovery Authority (CERA)	2
2.2 Building Act	3
2.3 Christchurch City Council Policy	4
2.4 Building Code	4
3. Earthquake Resistance Standards	5
4. Building Description	7
4.1 General	7
4.2 Gravity Load Resisting System	9
4.3 Lateral Load Resisting System	9
5. Assessment	10
6. Damage Assessment	11
6.1 Surrounding Buildings	11
6.2 Residual Displacements and General Observations	11
6.3 Ground Damage	11
7. Critical Structural Weakness	12
7.1 Short Columns	12
7.2 Lift Shaft	12
7.3 Roof	12
7.4 Staircases	12
7.5 Pounding effect	12
7.6 Liquefaction	12
8. Geotechnical Consideration	13
8.1 Site Description	13
8.2 Published Information on Ground Conditions	13
8.3 Seismicity	15

8.4	Slope Failure and/or Rockfall Potential	15
8.5	Liquefaction Potential	16
8.6	Conclusions & Recommendations	16
9.	Survey	17
10.	Initial Capacity Assessment	18
10.1	% NBS Assessment	18
10.2	Seismic Parameters	18
10.3	Expected Structural Ductility Factor	18
10.4	Discussion of Results	18
10.5	Occupancy	19
11.	Initial Conclusions	20
12.	Recommendations	21
13.	Limitations	22
13.1	General	22
13.2	Geotechnical Limitations	22

Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 1	ECan Borehole Summary	13
Figure 1	Post February 2011 Earthquake Aerial Photography	14
Table 2	Summary of Known Active Faults'	15

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 1	Post February 2011 Earthquake Aerial Photography	14

Appendices

- A Photographs
- B Existing Drawings
- C CERA Building Evaluation Form

Qualitative Report Summary

Centennial Park Pavilion/Toilet

PRK_1095_BLDG_002 EQ2

Detailed Engineering Evaluation

Qualitative Report - SUMMARY

Version Final

Lyttelton Street, Somerfield

Background

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 17 July 2012.

Key Damage Observed

- No damage was observed in the structure

Critical Structural Weaknesses

No potential critical structural weaknesses have been identified in the structure.

Due to the ground conditions on site it is possible that liquefaction will occur. However the effect liquefaction will have on the structure will not be a severe threat, therefore in terms of the IEP the site characteristics have been deemed to not be significant.

Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the building's original capacity has been assessed to be in the order of 61% NBS and post-earthquake capacity also in the order of 61% NBS. The building's post-earthquake capacity excluding critical structural weaknesses is in the order of 61% NBS.

The building has been assessed to have a seismic capacity in the order of 61% NBS and is therefore considered to be potentially an Earthquake Risk.

Recommendations

The recent seismic activity in Christchurch has caused no visible damage to the building. As the building has achieved between 34% NBS and 67% NBS following a qualitative Detailed Engineering Evaluation of the building, further assessment is not required. However, GHD recommended that a quantitative assessment be carried out and if necessary strengthening options explored.

The building can remain occupied as per CCC policy regarding the occupancy of potentially an Earthquake Risk building.

1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Centennial Park Pavilion/Toilet.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings were made available, and these have been considered in our evaluation of the building. The building description below is based on a review of the drawings and our visual inspections.

2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’. Regarding seismic capacity ‘as near as reasonably practicable’ has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The pavilion/toilet is located at Lyttelton Street, Centennial Park in Somerfield. The original construction date of the structure is unknown but based on site observation is estimated to be in late 1970's or early 1980's. The park site is bordered by residential properties in all directions. Lyttelton Street is on the eastern side of the park and is closest to the structure. The closest building to the pavilion/toilet is a residential property across Lyttelton Street to the East, approximately 25m away.

The site is flat with no visible evidence of liquefaction or ground damage.

The walls of the building are a single row of filled or partially filled concrete block work masonry. The single storey construction has a concrete slab on grade floor. The timber beam roof consists of lightweight metal cladding with two plastic skylights and clear panels supported by timber purlins and beams.

The dimensions of the pavilion/toilet building are 15m long by 7m wide and 3.6m high at the apex. This area includes a 1m wide veranda covered by a canopy on the western side of the building. The canopy is supported by a southern end wall and 5 steel support posts.

The internal layout of the pavilion/toilet consists of 3m wide toilets at the southern end of the structure. In centre area and northern end of the building are two 6m wide changing rooms containing seating and shower areas. Between the changing rooms is a 3m wide area used for the hot water cylinders.




Figure 2 Plan Sketch Showing Key Structural Elements

4.2 Gravity Load Resisting System

The gravity loads in the structure are resisted by timber beams across the structure. The roof cladding is supported by timber purlins spanning between the timber beams. These beams allow the transfer of the gravity load into a lintel/eaves beam that is bolted to and continuously supported by the reinforced, filled concrete block work external walls. The load is then transferred from the lintel/eaves beam into the external walls, through to the slab on grade, and into the ground.

4.3 Lateral Load Resisting System

Lateral loads acting on the structure are resisted by concrete masonry walls both along and across the dimensions of the building. The internal blockwork walls offer additional lateral resistance across the structure. These masonry walls transfer the lateral load from the roof down to the slab on grade foundation.

5. Assessment

An inspection of the building was undertaken on 16 July 2012. Both the interior and exterior of the building were inspected. The main structural components of the building were all able to be viewed due to the exposed straightforward construction of the building.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained solely from visual observation of the building due to the lack of available drawings.

6. Damage Assessment

6.1 Surrounding Buildings

The nearest residential building is located approximately 25m to the east. Based on visual inspections from property boundaries there was no damage evident to these buildings. There was no visible damage to the roof or walls of the attached structure.

6.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during the inspection of the building.

There was no visible damage to the concrete masonry block walls of the structure.

No damage was evident to the timber beam roof structure.

No visible evidence of liquefaction was found.

6.3 Ground Damage

There was no visible evidence of ground damage on the property or surrounding neighbours land.

7. Critical Structural Weakness

7.1 Short Columns

No short columns are present in the structure.

7.2 Lift Shaft

The building does not contain a lift shaft.

7.3 Roof

No roof bracing was visible. Roof elements such as the purlins and roof material were clearly visible and are expected to provide sufficient bracing to the roof structure. See photographs 4 and 5 in Appendix A. The edges of the canopy are securely bolted to steel support posts. See photographs 6 and 7.

7.4 Staircases

The building does not contain a staircase.

7.5 Pounding effect

No buildings are located near the Pavilion/Toilet so there is no pounding potential.

7.6 Liquefaction

No Liquefaction was observed on site or in the surrounding neighbourhood. However as noted in Section 8.5 of this report it is possible that liquefaction will occur on site. The effect liquefaction will have on the structure will not be a severe threat, therefore in terms of the IEP the site characteristics have been deemed to not be significant.

8. Geotechnical Consideration

8.1 Site Description

The site is situated in the suburb of Spreydon, south of Christchurch City centre. It is relatively flat at approximately 10m above mean sea level. It is approximately 200m west of Heathcote River, 3km south of the Main South Line Railway, and 7km west of the coast (Pegasus Bay).

8.2 Published Information on Ground Conditions

8.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by:

- Yaldhurst member of the Springston Formation, dominantly alluvial gravel, sand and silt of historic river flood channels, Holocene in age.

Figure 72 from Brown & Weeber indicates that groundwater is approximately 1m below ground level and liquefaction susceptibility is low.

8.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that six boreholes with lithographic logs are located within 300m of the site (see Table 2).

The soil condition in that location comprises of gravel and sand layers, with some lenses of clay and with ground water table at 1.5m bgl.

Table 2 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M36-0976-WC	103.6m	1.68m bgl	~285m N
M36-1055-WC	115.5m	1.7m bgl	~285m N
M36-1210-WC	104.5m	1.7m bgl	~285m N
M36-1225-WC	32.3m	3.6m bgl	~285m N
M36-1619-WC	115.7m	1.7m bgl	~285m N
M36-8288-WC	58m	Not indicated	~285m N

It should be noted the quality of soil logging descriptions included on the boreholes is unknown and were likely written by the well driller and not a geotechnical professional or to a recognised geotechnical standard. In addition strength data is not recorded.

¹ Brown, L. J. & Weeber, J.H. (1992): *Geology of the Christchurch Urban Area*. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. IGNS Limited: Lower Hutt.

8.2.3 EQC Geotechnical Investigations

The Earthquake Commission has undertaken one geotechnical testing within 200m of the site. However, shallow borehole was taken and deemed insignificant for this assessment.

8.2.4 CERA Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has classified the site as “Green Zone, N/A – Urban Non-residential” category. Land in the green zone is generally considered suitable for residential construction. An “N/A” technical category indicates the site is a non-residential property in urban area beyond the extent of land damage mapping. However, adjacent property to the east is classified as “Green Zone, Technical Category 2, yellow”. Land in this zone is generally considered suitable for residential construction, though some areas may require stronger foundations or design where rebuilding or repairs are required. Technical Category 2, yellow means that minor to moderate land damage from liquefaction is possible in future significant earthquakes.

8.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows minor to moderate signs of liquefaction close to the site, as shown in Figure 2.

Figure 2 Post February 2011 Earthquake Aerial Photography²



² Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>.

8.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise strata of gravel, sand and silt with lenses of clay.

8.3 Seismicity

8.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 3 Summary of Known Active Faults^{3,4}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	130 km	NW	~8.3	~300 years
Greendale (2010) Fault	20 km	W	7.1	~15,000 years
Hope Fault	109 km	NW	7.2~7.5	120~200 years
Kelly Fault	109 km	NW	7.2	~150 years
Porters Pass Fault	65 km	NW	7.0	~1100 years

The recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains, including Christchurch City, and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

8.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

8.4 Slope Failure and/or Rockfall Potential

Given the site's location in Spreydon, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

³ Stirling, M.W., McVerry, G.H., and Berryman K.R. (2002): "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, June 2002, pp. 1878-1903.

⁴ GNS Active Faults Database, <http://maps.gns.cri.nz/website/af/viewer>.

8.5 Liquefaction Potential

The site is considered to be minor to moderately susceptible to liquefaction, due to the following reasons:

- CERA classification of sites close to the site is Green Zone, TC2 – yellow;
- Anticipated presence of alluvial sand and silts deposits beneath the site; and,
- Shallow ground water level at approximately 2m bgl.

8.6 Conclusions & Recommendations

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on alluvial deposits, comprising gravel, sand and silt. Associated with this the site also has a minor to moderate liquefaction potential, in particular where sands and/or silts are present.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that intrusive investigation be conducted.

9. Survey

No level or verticality surveys have been undertaken for this building at this stage.

10. Initial Capacity Assessment

10.1 % NBS Assessment

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity excluding critical structural weaknesses and the capacity of any identified weaknesses are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 4. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building excluding CSW's	61

Table 4 Indicative Building and Critical Structural Weaknesses Capacities based on the NZSEE Initial Evaluation Procedure

Following an IEP assessment, the building has been assessed as achieving 61% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered an Earthquake Risk but not Earthquake Prone as it achieves greater than 33% NBS but less than 67% NBS. This score has not been adjusted when considering damage to the structure as all damage observed was relatively minor and considered unlikely to adversely affect the load carrying capacity of the structural systems.

10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Silty Sand
- ▶ Site hazard factor, Z = 0.3, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor $R_u = 1.0$, NZS 1170.5:2004, Table 3.5, Importance Level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

10.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the structural system observed and the date of construction.

10.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age and construction type. Although the original building construction date is unknown it was likely designed to the loading standard current at the time. The design loads used in this standard are likely to have been less than those required by the current loading standard. When combined with the increase in the hazard factor for Christchurch to 0.3, it would be expected that the building would not achieve

100% NBS. Due to the age of the building it is reasonable to expect the building to be classified as an Earthquake Risk.

10.5 Occupancy

As the structure achieve only 61% NBS, it is potentially an Earthquake Risk in accordance with the NZSEE guidelines. No critical structural weakness have been identified. The building does not pose an immediate risk to users and occupants. The structure can remain occupied as per Christchurch City Council's (CCC) policy regarding occupancy of potentially Earthquake Risk buildings

11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 61% NBS and is therefore potentially Earthquake Risk in accordance with the NZSEE guidelines. The effects of liquefaction on the pavilion/toilets are considered minor so the IEP risk has been deemed insignificant. The lack of any cracking in the building suggests that the pavilion/toilet block is well constructed. In addition the lack displacement of the block wall indicates that the walls are most likely fully grouted and reinforced. In accordance with CCC policy regarding occupancy of potentially at Earthquake Risk buildings, the building may remain occupied.

12. Recommendations

The recent seismic activity in Christchurch has caused no visible damage to the building. The building can remain occupied as per CCC policy regarding the occupancy of potentially at Earthquake Risk buildings. However, as the building has not achieved 67% NBS or higher, GHD recommend that a quantitative assessment and geotechnical investigation be carried out and if necessary strengthening options explored. The building also requires further investigation to confirm that the walls and floor slab on grade are adequately grouted and reinforced.

13. Limitations

13.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.

Appendix A

Photographs



Photograph 1 South west elevation.



Photograph 2 North elevation.



Photograph 3 View of the canopy and pavilion from the north west.



Photograph 4 Purlins, rafters and beams supporting the roof.



Photograph 5 Eaves beam and central beam bolted to the southern end of the block.



Photograph 6 Steel support posts holding up the canopy rafters.



Photograph 7 Connection between the steel support posts and canopy rafter.



Photograph 8 Shower areas in northern changing rooms.



Photograph 9 No visible damage to the slab on grade flooring.



Photograph 10 Toilet area on the southern end of the building.

Appendix B

Existing Drawings

No existing drawings were available for the building.

Appendix C

CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name: Centennial Park Pavilion/Toilet

Unit

No: Street

Reviewer: David Lee

112052

Building Address: Lyttleton Street, Somerfield

Legal Description: PRK_1095_BLDG_002 EQ2

CPEng No:

Company:

Project number:

Phone number:

GPS south: Degrees Min Sec

GPS east:

Company project number:

Company phone number:

Date of submission:

27/08/2012

Inspection Date:

17/07/2012

Revision:

Is there a full report with this summary? yes

Building Unique Identifier (CCC): PRK_1095_BLDG_002 EQ2

Site

Site slope: flat

Soil type: silty sand

Site Class (to NZS1170.5): D

Max retaining height (m):

Soil Profile (if available):

Proximity to waterway (m, if <100m):

If Ground improvement on site, describe:

Proximity to cliff top (m, if < 100m):

Approx site elevation (m):

Proximity to cliff base (m, if <100m):

Building

No. of storeys above ground: 1

single storey = 1

Ground floor elevation (Absolute) (m):

Ground floor split?: no

Ground floor elevation above ground (m):

Storeys below ground: 0

if Foundation type is other, describe: Slab on grade

Foundation type: mat slab

2.4

Building height (m): 4.00

height from ground to level of uppermost seismic mass (for IEP only) (m):

Floor footprint area (approx): 105

Date of design: 1976-1992

Age of Building (years):

Strengthening present?: no

If so, when (year)?

Use (ground floor): public

And what load level (%g)?

Use (upper floors):

Brief strengthening description:

Use notes (if required):

Importance level (to NZS1170.5): IL2

Gravity Structure

Gravity System: load bearing walls

rafter type, purlin type and cladding

Roof: timber framed

slab thickness (mm):

Floors: concrete flat slab

Beams:

Columns:

Walls: partially filled concrete masonry

thickness (mm):

200

Lateral load resisting structure

Lateral system along: partially filled CMU

Note: Define along and across in detailed report!
0.40 from parameters in sheet

note total length of wall at ground (m):

7

Ductility assumed, μ : 1.25

wall thickness (m):

0.2

Period along: 0.40

estimate or calculation?

Total deflection (ULS) (mm):

estimate or calculation?

maximum interstorey deflection (ULS) (mm):

estimate or calculation?

Lateral system across: partially filled CMU

note total length of wall at ground (m):

15

Ductility assumed, μ :	1.25	wall thickness (m):	0.2
Period across:	0.40	estimate or calculation?	
Total deflection (ULS) (mm):	0.40 from parameters in sheet	estimate or calculation?	
maximum interstorey deflection (ULS) (mm):		estimate or calculation?	
Separations:	north (mm): 0 east (mm): south (mm): west (mm):	leave blank if not relevant	
Non-structural elements	Stairs: Wall cladding: Roof Cladding: Glazing: Ceilings: Services(list):	describe exposed structure Metal timber frames none	Painted Block Walls Light corrugated steel
Available documentation	Architectural Structural Mechanical Electrical Geotech report	none none none none partial	original designer name/date original designer name/date original designer name/date original designer name/date original designer name/date
Damage Site: (refer DEE Table 4-2)	Site performance: Settlement: Differential settlement: Liquefaction: Lateral Spread: Differential lateral spread: Ground cracks: Damage to area:	Good none observed none observed none apparent none apparent none apparent none apparent none apparent	Describe damage: notes (if applicable): notes (if applicable): notes (if applicable): notes (if applicable): notes (if applicable): notes (if applicable): notes (if applicable):
Building:	Current Placard Status:	green	
Along	Damage ratio:	0%	Describe how damage ratio arrived at:
Across	Damage ratio:	0%	$\text{Damage_Ratio} = \frac{(\% \text{NBS}(\text{before}) - \% \text{NBS}(\text{after}))}{\% \text{NBS}(\text{before})}$
Diaphragms	Damage?:	no	Describe:
CSWs:	Damage?:	no	Describe:
Pounding:	Damage?:	no	Describe:
Non-structural:	Damage?:	no	Describe:

	Level of repair/strengthening required: <input type="text" value="none"/>	Building Consent required: <input type="text" value="no"/>	Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before: <input type="text" value="61%"/>	61% %NBS from IEP below	Assessed %NBS after: <input type="text" value="61%"/>	If IEP not used, please detail assessment methodology: <input type="text"/>
Across	Assessed %NBS before: <input type="text" value="61%"/>	61% %NBS from IEP below	Assessed %NBS after: <input type="text" value="61%"/>	

IEP *Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.*

Period of design of building (from above):	1976-1992		h _n from above: 2.4m	
Seismic Zone, if designed between 1965 and 1992:	<input type="text" value="B"/>		not required for this age of building <input type="text"/>	
	Period (from above):	along 0.4	across 0.4	
	(%NBS) _{nom} from Fig 3.3:	<input type="text" value="17.0%"/>	<input type="text" value="17.0%"/>	
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0				
Note 2: for RC buildings designed between 1976-1984, use 1.2				
Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)				
	Final (%NBS) _{nom} :	along <input type="text" value="17%"/>	across <input type="text" value="17%"/>	
2.2 Near Fault Scaling Factor	Near Fault scaling factor, from NZS1170.5, cl 3.1.6: along <input type="text" value="1.00"/> across <input type="text"/>			
2.3 Hazard Scaling Factor	Near Fault scaling factor (1/N(T,D), Factor A: <input type="text" value="1"/> along <input type="text" value="1"/> across <input type="text"/>			
	Hazard factor Z for site from AS1170.5, Table 3.3: Z ₁₉₉₂ , from NZS4203:1992 <input type="text" value="0.30"/> Hazard scaling factor, Factor B: <input type="text" value="0.8"/>			
2.4 Return Period Scaling Factor	Building Importance level (from above): <input type="text" value="2"/> Return Period Scaling factor from Table 3.1, Factor C: <input type="text" value="1.00"/>			
2.5 Ductility Scaling Factor	Assessed ductility (less than max in Table 3.2): <input type="text" value="1.25"/> Ductility scaling factor: =1 from 1976 onwards; or =k _μ , if pre-1976, from Table 3.3: <input type="text" value="1.14"/> along <input type="text" value="1.25"/> across <input type="text" value="1.14"/>			
2.6 Structural Performance Scaling Factor:	Ductility Scaling Factor, Factor D: <input type="text" value="1.00"/> along <input type="text" value="1.00"/> across <input type="text"/>			
	Sp: <input type="text" value="0.925"/>			
	Structural Performance Scaling Factor Factor E: <input type="text" value="1.081081081"/> along <input type="text" value="1.081081081"/> across <input type="text"/>			
2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E	%NBS _b : <input type="text" value="61%"/> along <input type="text" value="61%"/> across <input type="text"/>			
Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)				

3.1. Plan Irregularity, factor A:	insignificant	1
3.2. Vertical irregularity, Factor B:	insignificant	1
3.3. Short columns, Factor C:	insignificant	1
3.4. Pounding potential	Pounding effect D1, from Table to right Height Difference effect D2, from Table to right	1.0 1.0
	Therefore, Factor D:	1

3.5. Site Characteristics

3.6. Other factors, Factor F

For ≤ 3 storeys, max value =2.5, otherwise max value =1.5, no minimum

Rationale for choice of F factor, if not 1

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation 0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR)

Along	Across
1.0	1.0

4.3 PAR x (%NBS)b:

PAR x Baseline %NBS:

1.00 1.00

4.4 Percentage New Building Standard (%NBS), (before)

61% 61%

61%

GHD

Level 11, Guardian Trust House

15 Willeston street, Wellington 6011

T: 64 4 472 0799 F: 64 4 472 0833 E: wgnmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Dale Donovan	David Lee		Nick Waddington		01/10/12