



CLIENTS | PEOPLE | PERFORMANCE

**Ferrymead Reserve Toilet**  
**PRK 1750 BLDG 002**  
Detailed Engineering Evaluation  
Qualitative Report  
Version Final

281 Bridle Path Road



**Ferrymead Reserve Toilet  
PRK 1750 BLDG 002**

Detailed Engineering Evaluation  
Qualitative Report  
Version Final

281 Bridle Path Road

Christchurch City Council

**Prepared By**  
Alex Baylis

**Reviewed By**  
Paul Clarke

**Date**  
23<sup>rd</sup> May 2013



# Contents

Qualitative Report Summary	i
1. Background	1
2. Compliance	2
2.1 Canterbury Earthquake Recovery Authority (CERA)	2
2.2 Building Act	3
2.3 Christchurch City Council Policy	4
2.4 Building Code	4
3. Earthquake Resistance Standards	5
4. Building Description	7
4.1 General	7
4.2 Gravity Load Resisting System	7
4.3 Lateral Load Resisting System	8
5. Assessment	9
5.1 Damage Assessment	9
6. Critical Structural Weakness	10
6.1 Short Columns	10
6.2 Lift Shaft	10
6.3 Roof	10
6.4 Staircases	10
6.5 Site Characteristics	10
7. Geotechnical Consideration	11
7.1 Site Description	11
7.2 Published Information on Ground Conditions	11
7.3 Previous Nearby Investigations	12
7.4 Seismicity	12
7.5 Slope Failure and/or Rockfall Potential	13
7.6 Liquefaction Potential	13
7.7 Conclusions & Recommendations	14



8.	Initial Capacity Assessment	15
8.1	% NBS Assessment	15
8.2	Seismic Parameters	15
8.3	Expected Structural Ductility Factor	15
8.4	Discussion of Results	15
9.	Initial Conclusions & Recommendations	16
10.	Limitations	17
10.1	General	17
10.2	Geotechnical Limitations	17

### Table Index

Table 1	%NBS compared to relative risk of failure	6
Table 2	ECan Borehole Summary	11
Table 3	Summary of Known Active Faults	13

### Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	5
Figure 2	Plan Sketch Showing Key Structural Elements	7
Figure 3	Post February 2011 Earthquake Aerial Photography	12

### Appendices

- A Photographs
- B Sketch
- C CERA Building Evaluation Form



# Qualitative Report Summary

**Ferrymead Reserve Toilet**

**PRK 1750 BLDG 002**

**Detailed Engineering Evaluation**

**Qualitative Report - SUMMARY**

**Version Final**

**281 Bridle Path Road**

## **Background**

This is a summary of the Qualitative report for the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 14 September 2012.

## **Building Description**

The building is located at 281 Bridle Path Road, Ferrymead. The date of construction is estimated as 1980's and the sole use of the building is a public toilet.

The roof is formed by curved longrun corrugated sheet metal on timber rafters as can be seen in Photograph 3. Concrete masonry walls support the timber roof framing. The 190 mm thick external concrete walls consist of partially filled masonry units. The partial height internal walls consist of 90 mm thick partially filled concrete masonry units. External walls are likely supported on concrete strip footings and the floor is a concrete slab-on-grade.

## **Key Damage Observed**

No damage to the structure was observed.

## **Critical Structural Weaknesses**

No bracing of the timber roof structure has been provided. The lack of a diaphragm to transfer in-plane forces in the roof to the supporting walls is considered a Critical Structural Weakness. The absence of a roof diaphragm has been assessed as a 'significant' plan irregularity Critical Structural Weakness in accordance with NZSEE guidelines.

The top edges of the 190 mm main concrete masonry walls are effectively unrestrained due to the absence of a diaphragm or bracing in the roof structure. The internal 90 mm thick concrete masonry walls and the 190 mm thick concrete masonry entrance wing walls are unrestrained along the top edge and are susceptible to collapse from out-of-plane seismic actions.



### **Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the original capacity of the building has been assessed to be in the order of 42% NBS and post-earthquake capacity also in the order of 42% NBS. The buildings post-earthquake capacity excluding critical structural weaknesses is in the order of 59% NBS.

The building has been assessed to have a seismic capacity in the order of 42% NBS and is therefore potentially Earthquake Risk.

### **Recommendations**

No future action from Christchurch City Council is required to comply with the building code, however given the low %NBS score achieved, GHD recommend a detailed quantitative assessment.



## 1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Ferrymead Reserve Toilet.

This report is a Qualitative Assessment of the building structure, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. Construction drawings have not been made available. The building description below is based on our visual inspections only.



## 2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage



## **2.2 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

#### **2.2.1 Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



### **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

### **2.4 Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



### 3. Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

**Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE**

Table 1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times


**Table 1      %NBS compared to relative risk of failure**

## 4. Building Description

### 4.1 General

The building is located at 281 Bridle Path Road, Ferrymead. The date of construction is estimated as 1980's and the sole use of the building is a public toilet.

The roof is formed by curved longrun corrugated sheet metal on timber rafters as can be seen in Photograph 3. Concrete masonry walls support the timber roof framing. The 190 mm thick external concrete walls consist of partially filled masonry units. The partial height internal walls consist of 90 mm thick partially filled concrete masonry units. External walls are likely supported on concrete strip footings and the floor is a concrete slab-on-grade.



**Figure 2 Plan Sketch Showing Key Structural Elements**

The building is approximately 8.9 m in length by 3.9 m in width with a height of 2.7 m. The building occupies a footprint of approximately 34m<sup>2</sup>. The relatively flat site is approximately 110 m east of the Avon-Heathcote Estuary.

No plans of the building were made available.

### 4.2 Gravity Load Resisting System

Gravity loads acting on the building are resisted by load bearing concrete masonry walls. Gravity loads from the corrugated sheet metal roof are transferred via the timber rafters to the concrete masonry walls. The gravity loads are transferred through the concrete masonry walls to the concrete strip footings where they are distributed into the ground. Floor gravity loads are transferred through the concrete slab to the underlying ground.



### **4.3 Lateral Load Resisting System**

Lateral loads are resisted primarily by the panel action of concrete masonry walls in both the transverse and longitudinal directions of the building. The walls in the plane of loading resist lateral loads by panel action of the concrete masonry units. Loads are then transferred to the foundations through shear and bending of the masonry walls.

Most of the seismic mass of the building is attributed to the self-weight of the concrete masonry walls. As a result, each section of concrete masonry wall resists the in-plane and out-of-plane inertia forces corresponding to the self-weight of that particular section of wall.

The main 190 mm thick concrete masonry walls and the 90 mm thick partial height internal concrete masonry walls are effectively unrestrained along the top edge. Out-of-plane loading on these walls is likely to be resisted by a combination of the walls spanning horizontally between return walls and vertical cantilever action.



## 5. Assessment

An inspection of the building was undertaken on the 14 September 2012. Both the interior and exterior of the building were inspected.

The inspection consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score determined for this building has been based on the IEP procedure described by the NZSEE and based on the information obtained from visual observation of the building.

### 5.1 Damage Assessment

#### 5.1.1 Surrounding Buildings

No damage to surrounding buildings or structures was observed.

#### 5.1.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during our inspection of the building.

#### 5.1.3 Ground Damage

There is some minor cracking in the asphalt pavement outside the entrance wing of the toilets (see Photograph 2).

#### 5.1.4 Floor Level Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines



## 6. Critical Structural Weakness

### 6.1 Short Columns

No critical short columns are present in the structure.

### 6.2 Lift Shaft

The building does not contain a lift shaft.

### 6.3 Roof

The corrugated sheet metal roof is unlikely to have sufficient strength and stiffness to distribute the lateral in-plane seismic forces to the walls in the plane of loading through diaphragm action. The lack of a diaphragm to transfer in-plane forces through the roof to the supporting walls is considered a Critical Structural Weakness. The absence of a roof diaphragm has been assessed as a 'significant' plan irregularity Critical Structural Weakness in accordance with NZSEE guidelines.

The top edges of the 190 mm main concrete masonry walls are effectively unrestrained due to the absence of a diaphragm or bracing in the roof structure. The internal 90 mm thick concrete masonry walls (see Photograph 3) and the 190 mm thick concrete masonry entrance wing walls (see Photograph 2) are unrestrained along the top edge and are susceptible to collapse from out-of-plane seismic actions.

### 6.4 Staircases

The building does not contain a staircase.

### 6.5 Site Characteristics

Following the geotechnical appraisal it was found that the site has a minor potential for liquefaction. For the purposes of the IEP assessment of the building and the determination of the %NBS score, the effects of soil liquefaction on the performance of a building of this type and size has been assessed as an 'insignificant' site characteristic in accordance with the NZSEE guidelines.



## 7. Geotechnical Consideration

### 7.1 Site Description

The site is situated in the suburb of Ferrymead, in eastern Christchurch. It is relatively flat at approximately 1.5 m above mean sea level. It is approximately 110 m east of the Avon-Heathcote Estuary, and 350 m west of the coast (Pegasus Bay).

### 7.2 Published Information on Ground Conditions

#### 7.2.1 Published Geology

The geological map of the area<sup>1</sup> indicates that the site is underlain by Holocene alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, comprising of sand, silt and peat of the drained lagoons and estuaries.

Brown & Weeber (1992) indicates that groundwater is likely within 1 m of the ground surface.

#### 7.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that one borehole with a lithographic log is located within 200m of the site (see Table 2). The lithographic log is summarised below. The site geology described in the log shows the area is predominantly sandy silt, with some peat.

**Table 2 ECan Borehole Summary**

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M36/8887	7.62m	Not Recorded	20m E

It should be noted the logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

#### 7.2.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

#### 7.2.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is situated within the Green Zone, indicating that repair and rebuild may take place.

The site and surrounding area has been categorised as "N/A – Urban Non-residential". Three properties 130m northeast of the site are in the Red Zone due to rockfall or cliff collapse hazards.

<sup>1</sup> Brown, L. J. and Weeber J.H. 1992: Geology of the Christchurch Urban Area. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.

### 7.2.5 Post February Aerial Photography

Aerial photography<sup>2</sup> taken following the 22 February 2011 earthquake shows no signs of liquefaction outside the building footprint or directly adjacent to the site, however significant liquefaction is observed 120m to the southwest of the site, as shown in Figure 3.

**Figure 3 Post February 2011 Earthquake Aerial Photography**



### 7.2.6 Summary of Ground Conditions

The ground conditions in the area are anticipated to be silt and peat associated with drained lagoons and estuaries. No site specific geological data was available.

### 7.3 Previous Nearby Investigations

A test pit has been undertaken 30m east of the site during an investigation for a previous CCC site. The test pit revealed topsoil underlain by a sandy clay between 0.2 to 0.6m bgl considered to be fill, overlying a fill or estuarine deposit to 0.9m bgl, underlain by silt and sand to 2.7mbgl. Groundwater was encountered at 2.5m bgl

### 7.4 Seismicity

#### 7.4.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

<sup>2</sup> Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



**Table 3 Summary of Known Active Faults<sup>34</sup>**

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	13 km	W	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	100 km	NW	7.2	~150 years
Porters Pass Fault	54 km	NW	7.0	~1100 years

The recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains, including Christchurch City, and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

#### 7.4.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

#### 7.5 Slope Failure and/or Rockfall Potential

The site is located within Ferrymead, a flat suburb in eastern Christchurch. Global slope instability risk is considered negligible. However, it is located 110 m away from the Avon-Heathcote Estuary's southern bank. Due to the proximity to the estuary, and the underlying geology, there is a potential for lateral spreading.

The hill suburb of Mount Pleasant is located 50m east of the site, no boulders have been mapped upslope of the site and some of the hill slope above has been developed by residential properties reducing the rock outcrops. The site therefore has a low Rockfall potential.

#### 7.6 Liquefaction Potential

The site is considered to have a minor susceptibility to liquefaction, due to the following reasons:

- Evidence of no liquefaction directly adjacent to the site from post-earthquake aerial photography;
- Evidence of significant liquefaction 120m from site; and;

<sup>3</sup> Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

<sup>4</sup> GNS Active Faults Database



- Anticipated presence of saturated silts and sands beneath the site.

## 7.7 Conclusions & Recommendations

This assessment is based on a desktop review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on fill underlain by estuarine deposits, silt and sand. Associated with this the site also has a minor liquefaction potential, in particular where sands and silts are present.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that a site specific intrusive investigation be conducted.



## 8. Initial Capacity Assessment

### 8.1 % NBS Assessment

The building has had its capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity excluding critical structural weaknesses is in the order of 59% NBS. The assessed capacity including Critical Structural Weaknesses is in the order of 42% NBS. These capacities are subject to confirmation by a more detailed quantitative analysis.

Following an IEP assessment, the building has been assessed as achieving 42% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is considered potentially Earthquake Risk as it achieves greater than 33% and less than 67% NBS.

### 8.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS 1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil
- ▶ Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor  $R_u = 1.0$  NZS 1170.5:2004, Table 3.5, Importance level 2 structure with a 50 year design life.

An increased Z factor of 0.3 for Christchurch has been used in line with requirements from the Department of Building and Housing resulting in a reduced % NBS score.

### 8.3 Expected Structural Ductility Factor

A structural ductility factor of 1.25 has been assumed based on the concrete masonry wall system observed. The walls are expected to be nominally ductile as the units are likely to be partially filled and lightly reinforced.

### 8.4 Discussion of Results

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age and construction type. Based on the construction type and detailing observed, it is likely that the building was constructed during the 1980's and was likely designed to the loading standard current at the time, specifically NZS 4203:1976. The design loads used in accordance with this standard are likely to have been less than those required by the current loading standard. Combined with the increase in the seismic hazard factor for Christchurch to 0.3 and the presence of a critical structural weakness, it is reasonable to expect the building would achieve less than 100% NBS.



## 9. Initial Conclusions & Recommendations

The building has been assessed to have a seismic capacity in the order of 42% NBS and is therefore potentially Earthquake Risk.

Christchurch City Council are not required to undertake a detailed seismic assessment of the building, however due to the relatively low %NBS score, GHD recommend a detailed seismic assessment is carried out.



## 10. Limitations

### 10.1 General

This report has been prepared subject to the following limitations:

- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report or a specific limitations section.

### 10.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A  
Photographs



**Photograph 1** View of toilet entrance from the south



**Photograph 2** Entrance wing



**Photograph 3** 90mm thick internal walls



**Photograph 4** Timber roof rafters



**Photograph 5** Rear masonry wall




**Photograph 6** Drainage holes in external wall



Appendix B  
Sketch

- 190mm thick partially filled concrete masonry units
- - - 90mm thick partially filled concrete masonry units
- - - Timber rafters





Appendix C  
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

<b>Location</b>		Building Name: <input type="text" value="Ferrymead Reserve Toilet"/>	Reviewer: <input type="text" value="Stephen Lee"/>
Building Address: <input type="text" value="2 281 Bridle Path Road"/>	Unit No: <input type="text" value="281"/>	Street: <input type="text" value="Bridle Path Road"/>	CPEng No: <input type="text" value="1006840"/>
Legal Description: <input type="text" value="Lot 2 DP 28250"/>			Company: <input type="text" value="GHD"/>
		Company project number: <input type="text" value="513090264"/>	Company phone number: <input type="text" value="04 472 0799"/>
GPS south: <input type="text" value="43 33 48.02"/>	Degrees	Min	Sec
GPS east: <input type="text" value="172 42 31.73"/>			
Building Unique Identifier (CCC): <input type="text" value="PRK_1750_BLDG_002"/>	Is there a full report with this summary?		<input type="text" value="yes"/>
		Date of submission: <input type="text" value="23/05/2013"/>	Revision: <input type="text" value="Final"/>
		Inspection Date: <input type="text" value="14/09/2012"/>	

<b>Site</b>	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
	Soil type: <input type="text"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>		
Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>	
Proximity to clifftop (m, if < 100m): <input type="text"/>		
Proximity to cliff base (m,if <100m): <input type="text"/>	Approx site elevation (m): <input type="text" value="1.50"/>	

<b>Building</b>	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="1.60"/>
	Ground floor split?: <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value="0.10"/>
	Storeys below ground: <input type="text" value="0"/>		
	Foundation type: <input type="text" value="strip footings"/>	if Foundation type is other, describe: <input type="text"/>	
	Building height (m): <input type="text" value="2.70"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="2.7"/>	
	Floor footprint area (approx): <input type="text" value="34"/>		
	Age of Building (years): <input type="text" value="25"/>		Date of design: <input type="text" value="1976-1992"/>
	Strengthening present? <input type="text" value="no"/>		If so, when (year)? <input type="text"/>
	Use (ground floor): <input type="text" value="other (specify)"/>		And what load level (%g)? <input type="text"/>
	Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>
	Use notes (if required): <input type="text" value="Public Toilet"/>		
	Importance level (to NZS1170.5): <input type="text" value="IL2"/>		

<b>Gravity Structure</b>	Gravity System: <input type="text" value="load bearing walls"/>	rafter type, purlin type and cladding: <input type="text" value="Metal cladding on timber rafters."/>
	Roof: <input type="text" value="timber framed"/>	describe sytem: <input type="text" value="Slab on grade"/>
	Floors: <input type="text" value="other (note)"/>	
	Beams: <input type="text"/>	
	Columns: <input type="text"/>	
	Walls: <input type="text" value="partially filled concrete masonry"/>	thickness (mm): <input type="text" value="190"/>

<b>Lateral load resisting structure</b>	Lateral system along: <input type="text" value="partially filled CMU"/>	Note: Define along and across in <input type="text"/>
---	---	---

Ductility assumed,  $\mu$ :   
 Period along:   
 Total deflection (ULS) (mm):   
 maximum interstorey deflection (ULS) (mm):

**detailed report!**  
 ##### enter height above at H31

note total length of wall at ground (m):   
 estimate or calculation?   
 estimate or calculation?   
 estimate or calculation?

Lateral system across:   
 Ductility assumed,  $\mu$ :   
 Period across:   
 Total deflection (ULS) (mm):   
 maximum interstorey deflection (ULS) (mm):

note total length of wall at ground (m):   
 estimate or calculation?   
 estimate or calculation?   
 estimate or calculation?

Separations:

north (mm):   
 east (mm):   
 south (mm):   
 west (mm):

leave blank if not relevant

Non-structural elements

Stairs:   
 Wall cladding:   
 Roof Cladding:   
 Glazing:   
 Ceilings:   
 Services(list):

**Available documentation**

Architectural:   
 Structural:   
 Mechanical:   
 Electrical:   
 Geotech report:

original designer name/date:   
 original designer name/date:   
 original designer name/date:   
 original designer name/date:   
 original designer name/date:

**Damage**

Site:  
 (refer DEE Table 4-2)

Site performance:

Describe damage:

Settlement:   
 Differential settlement:   
 Liquefaction:   
 Lateral Spread:   
 Differential lateral spread:   
 Ground cracks:   
 Damage to area:

notes (if applicable):   
 notes (if applicable):

Building:

Current Placard Status:

Along

Damage ratio:   
 Describe (summary):

Describe how damage ratio arrived at:

Across

Damage ratio:   
 Describe (summary):

$$Damage\_Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
CSWs:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Pounding:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Non-structural:	Damage?:	<input type="text" value="no"/>	Describe:	<input type="text"/>

**Recommendations**

Level of repair/strengthening required:	<input type="text" value="none"/>	Describe:	<input type="text"/>
Building Consent required:	<input type="text" value="no"/>	Describe:	<input type="text"/>
Interim occupancy recommendations:	<input type="text" value="full occupancy"/>	Describe:	<input type="text"/>

Along	Assessed %NBS before e'quakes:	<input type="text" value="42%"/>	42% %NBS from IEP below	If IEP not used, please detail assessment methodology: <input type="text"/>
	Assessed %NBS after e'quakes:	<input type="text" value="42%"/>		
Across	Assessed %NBS before e'quakes:	<input type="text" value="42%"/>	42% %NBS from IEP below	
	Assessed %NBS after e'quakes:	<input type="text" value="42%"/>		

**IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.**

Period of design of building (from above): 1976-1992 h<sub>n</sub> from above: 2.7m

Seismic Zone, if designed between 1965 and 1992:  not required for this age of building

	along	across
Period (from above):	0.4	0.4
(%NBS) <sub>nom</sub> from Fig 3.3:	<input type="text" value="16.5%"/>	<input type="text" value="16.5%"/>

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A =1.33; 1965-1976, Zone B = 1.2; all else 1.0

Note 2: for RC buildings designed between 1976-1984, use 1.2

Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)

	along	across
<b>Final (%NBS)<sub>nom</sub>:</b>	<input type="text" value="17%"/>	<input type="text" value="17%"/>

**2.2 Near Fault Scaling Factor** Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), <b>Factor A:</b>	<input type="text" value="1"/>	<input type="text" value="1"/>

**2.3 Hazard Scaling Factor** Hazard factor Z for site from AS1170.5, Table 3.3:

	<input type="text" value="0.8"/>
Hazard scaling factor, <b>Factor B:</b>	<input type="text" value="3.33333333"/>

**2.4 Return Period Scaling Factor** Building Importance level (from above):

Return Period Scaling factor from Table 3.1, <b>Factor C:</b>	<input type="text" value="1.00"/>
---	-----------------------------------

**2.5 Ductility Scaling Factor**

Assessed ductility (less than max in Table 3.2)	along	1.25	across	1.25
Ductility scaling factor: =1 from 1976 onwards; or = $\kappa\mu$ , if pre-1976, from Table 3.3:		1.00		1.00

Ductility Scaling Factor, <b>Factor D:</b>	1.00	1.00
--	------	------

**2.6 Structural Performance Scaling Factor:**

Sp:	0.925	0.925
-----	-------	-------

Structural Performance Scaling Factor <b>Factor E:</b>	1.081081081	1.081081081
--	-------------	-------------

**2.7 Baseline %NBS,  $(NBS\%)_b = (\%NBS)_{nom} \times A \times B \times C \times D \times E$**

%NBS <sub>b</sub> :	59%	59%
---------------------	-----	-----

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

<b>3.1. Plan Irregularity, factor A:</b>	significant	0.7
--	-------------	-----

<b>3.2. Vertical irregularity, Factor B:</b>	insignificant	1
--	---------------	---

<b>3.3. Short columns, Factor C:</b>	insignificant	1
--------------------------------------	---------------	---

<b>3.4. Pounding potential</b>	Pounding effect D1, from Table to right	1.0
	Height Difference effect D2, from Table to right	1.0

Therefore, Factor D: 1

<b>3.5. Site Characteristics</b>	insignificant	1
----------------------------------	---------------	---

Table for selection of D1	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	0<sep<.005H	.005<sep<.01H	Sep>.01H
Separation			
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

**3.6. Other factors, Factor F**

For $\leq 3$ storeys, max value =2.5, otherwise max valule =1.5, no minimum	Along	1.0	Across	1.0
Rationale for choice of F factor, if not 1				

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any:  Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

<b>3.7. Overall Performance Achievement ratio (PAR)</b>	0.70	0.70
---	------	------

<b>4.3 PAR x (%NBS)<sub>b</sub>:</b>	PAR x Baseline %NBS:	42%	42%
--------------------------------------	----------------------	-----	-----

<b>4.4 Percentage New Building Standard (%NBS), (before)</b>	42%
--	-----

Official Use only:

Accepted By:   
Date:



**GHD**

Level 11, Guardian Trust House  
15 Willeston street, Wellington 6011  
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

**© GHD Limited 2013**

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

**Document Status**

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Alex Baylis	Paul Clarke		S Lee		23/05/2013