

Christchurch City Council

**Guise Lane
Housing Complex
PRO 1519**

**Detailed Engineering Evaluation
Quantitative Assessment Report**






Christchurch City Council

Guise Lane Housing Complex

Quantitative Assessment Report

6 Guise Lane, Hoon Hay,

Prepared By 
Chris Gilbert
Graduate Structural Engineer

Reviewed By 
Lachlan Howat
Structural Engineer

Approved for
Release By 
Mary Ann Halliday
Senior Structural Engineer

Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: March 2014
Reference: 6-QC349.00
Status: Final

Summary

Guise Lane Housing Complex
PRO 1519

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the Guise Lane Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 21 residential units on the site.

Key Damage Observed

The residential units have suffered minor damage to non-structural elements. This included cracking of the brick and weatherboard veneer. Minor gib cracking was observed in all units typically observed above doorways, windows and at the roofline. Cracking to the ceiling diaphragm was also observed. This damage was deemed low enough to not affect the capacities of the buildings.

Level Survey

All accessible floor slopes were assessed in a laser level survey. Less than half of the floor slopes were greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 250-350mm.

Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

Indicative Building Strength

Table A: Summary of Seismic Performance by Blocks

Block	NBS%	Indicative Floor Levels	Nail Spacings
PRO 1519 B001 (Block A)	52%	Fail	Pass
PRO 1519 B002 (Block B)	52%	Pass	Pass
PRO 1519 B003 (Block C)	52%	Fail	Pass
PRO 1519 B004 (Block D)	52%	Fail	Pass
PRO 1519 B005 (Block E)	52%	Fail	Pass
PRO 1519 B006 (Block F)	52%	Fail	Pass
PRO 1519 B007 (Block G)	52%	Fail	Pass

No buildings on the site are considered to be earthquake prone.

The residential units (Blocks A – G) have capacities of 52% NBS as limited by the in-plane shear capacity of the timber-framed shear walls in the longitudinal direction. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines.

Increasing the number of nails in the plasterboard will not significantly improve the strength of the buildings.

Recommendations

It is recommended that;

- Structural systems be developed to increase the seismic capacity of all blocks to at least 67%NBS.
- Cosmetic repairs be undertaken as required.
- Veneer at height (gable ends) have their veneer ties checked.

Contents

Summary	i
1 Introduction.....	4
2 Compliance	4
3 Earthquake Resistance Standards.....	8
4 Background Information.....	10
5 Damage	14
6 Detailed Seismic Assessment	15
7 Geotechnical Summary	18
8 Conclusions.....	18
9 Recommendations	18
10 Limitations.....	19
11 References	19
Appendix A – Photographs	
Appendix B – Level Survey	
Appendix C – Methodology and Assumptions	
Appendix D – CERA DEE Spreadsheet	

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Guise Lane Housing Complex, located at 6 Guise Lane, Hoon Hay, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 29 November 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death;
or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

4 Background Information

4.1 Building Descriptions

The site contains 21 residential units which were constructed in 1977. A site plan showing the location of the units, numbered 1 to 21, is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City. The units are grouped together to form seven blocks of two, three or four units.



Figure 2: Site plan of Guise Lane Housing Complex.



Figure 3: Location of Guise Lane (circled) relative to Christchurch City CBD (Source: Google Earth).

The residential units are timber-framed buildings with diagonal timber braces. The roof structure comprises of timber roof trusses supporting heavy, concrete tile roofs. The walls and ceilings are lined with plasterboard. External walls are clad with Summerhill stone veneer. Foundations are strip footings under fire walls and around the perimeter of reinforced concrete slabs.

The units are separated by 190mm block masonry fire walls which are reinforced with 12mm diameter rods at 400mm centres and to its perimeter. A reinforced bond beam is located at the ceiling line within the block fire wall.

Figure 4 shows a typical floor plan of a residential unit produced from site measurements by Opus. Figure 5 shows the cross section used in calculations, from original documentation.




Figure 4: Typical partial floor plan of residential unit blocks.




Figure 5: Cross section of Guise Lane.

4.2 Survey

4.2.1 Level Survey

A full level survey was not deemed to be necessary at Guise Lane as it is located in a TC2 zone. Properties in TC2 zones suffered minor to moderate damage due to liquefaction and/or settlement. In lieu of a full level survey, a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit. For this site, the maximum slope in a unit was 12.5mm/m (which exceeds the 5mm/m limitation imposed by MBIE guidelines), the general slope across all units was approximately 3mm/m.

Table 2: Summary of the Level Survey

Block	Unit No.	Comment	Maximum Fall*
A	1	Pass	-
	2	Fail	5 mm/m
	3	Pass	-
B	4	Pass	-
	5	Pass	-
	6	Pass	-
C	7	Pass	-
	8	Pass	-
	9	Fail	7 mm/m
D	10	Pass	-
	11	Pass	-
	12	Fail	13 mm/m
E	13	Fail	6 mm/m
	14	Pass	-
F	15	Pass	-
	16	Pass	-
	17	Fail	5 mm/m
G	18	Fail	13 mm/m
	19	Pass	-
	20	Fail	7 mm/m
	21	Fail	6 mm/m

* Values are only recorded if greater than 5mm/m

Orange results represent floor levels which fall outside the MBIE guidelines when using the laser level but may comply when surveyed using more accurate equipment.

4.2.2 Nail Spacings

The internal lining nail spacings were measured on site to vary between 250mm-350mm.

4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- 763 – Christchurch City Council – Proposed Homes for the Elderly - Halswell Road – Site plan, floor plan, elevations and sections – 1976.
- 1573 – Enterprise Homes Ltd – Standard Concrete Block Single Storey Firewall – Elevations and cross sections – 1975.

In addition a typical floor plan of the residential units has been produced by Opus from site measurements to help investigate potential critical structural weaknesses (CSWs) and identify details which required particular attention.

Copies of design calculations were not available for the site assessment.

5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

It is noticeable that some residential unit blocks, and individual units, have suffered more damage than others. Overall, Block G appears to have suffered the highest level of settlement.

Note: Any photo referenced in this section can be found in Appendix A.

5.1 Residual Displacements

Minor residual displacements were observed in all units. Displacements were more significant in Units 9, 12, 18, and 20 where the MBIE guideline of 5 mm/m was significantly exceeded. Units 12 and 20 suffered local residual displacements where in both cases the floor levels rose toward an exterior wall. Unit 18 experienced residual displacement over the entire unit, most notably, a 12.5 mm/m rise in the kitchen.

5.2 Foundations

Spalling of the foundation's outer render was observed (photo 22).

5.3 Primary Gravity Structure

No damage was observed to the primary gravity structure.

5.4 Primary Lateral-Resistance Structure

Minor cracking was observed to the plasterboard wall linings and ceiling diaphragm in most units (photos 12-15).

5.5 Non Structural Elements

Minor cracking was observed in both the Hardie board and Summerhill stone veneer (photos 17 and 19). A loose brick in the veneer was also observed at the corner of Blocks C and E. Slight splitting was observed between the veneer and the concrete block firewall (photo 21). Cracking to the concrete path surrounding the units was observed.

5.6 General Observations

The buildings appeared to have performed well as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor damage which is typical of the construction type and age of construction.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix C. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 6 and Figure 7, were used for bracing in their respective directions.




Figure 6: Walls used for bracing in the longitudinal direction.




Figure 7: Walls used for bracing in the transverse direction.

6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 3: Summary of Seismic Performance

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Residential Units (Blocks A- G)	Timber bracing in the longitudinal direction	52%	100%

7 Geotechnical Summary

CERA indicates that Guise Lane is located in a TC2 zone (as shown in Figure 8). This classification suggests future significant earthquakes will cause minor to moderate land damage due to liquefaction and settlement. Note that the proximity to the TC3 zone is consistent with the variations found with the floor levels.



Figure 8: CERA Technical Categories map (loc. starred).

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

8 Conclusions

- None of the buildings on site are considered to be Earthquake Prone.
- The residential units (Blocks A – G) have capacities of 52% NBS, as limited by the in-plane capacity of the bracing walls. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines. Their level of risk is 5-10 times that of a 100% NBS building (Figure 1).

9 Recommendations

It is recommended that;

- Structural systems be developed to increase the seismic capacity of all blocks to at least 67%NBS.
- Cosmetic repairs be undertaken as required.
- Veneer at height (gable ends) have their veneer ties checked.

10 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Guise Lane Housing Complex. It is not intended for any other party or purpose.

11 References


- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

Appendix A – Photographs

Guise Lane Housing Complex – Detailed Engineering Evaluation

Guise Lane Housing Complex		
Residential Units Layout		
1.	View of complex (Blocks D, E and F)	 A photograph showing a view of the housing complex from a perspective near a building. A paved path leads through a green lawn towards other residential units. Large trees are visible on the right side of the path, casting shadows on the grass.
2.	View of complex (Blocks A, B, C and G)	 A photograph showing a view of the housing complex from a distance. A paved path leads through a green lawn between rows of residential units. Large trees are visible in the background, and the sky is blue with some clouds.


Guise Lane Housing Complex – Detailed Engineering Evaluation

<p>3.</p>	<p>Typical unit elevation (front)</p>	
<p>4.</p>	<p>Typical unit elevation (end)</p>	
<p>5.</p>	<p>Typical lounge view</p>	

Guise Lane Housing Complex – Detailed Engineering Evaluation


6.	Typical bedroom view	 A photograph of a typical bedroom. The room features light-colored walls, a dark carpet, and a window with blinds on the right wall. A wooden door is visible on the left side of the frame.
7.	Typical kitchen view	 A photograph of a typical kitchen. The kitchen has light-colored cabinets, a white countertop, and a white stove with four burners. A window is visible above the sink, and a glass door is on the right side of the frame.
8.	Typical laundry view	 A photograph of a typical laundry room. The room features a white sink with a faucet, a white cabinet, and a window. A blue sign is visible on the left wall, and a doorway leads to a bathroom on the right.

Guise Lane Housing Complex – Detailed Engineering Evaluation

9.	Typical bathroom view	
10.	Typical roof space showing fire wall and truss system (note heavy tile roof)	
11.	Typical roof space showing fire wall and truss system	


<p>12.</p>	<p>Typical cracking above doorways</p>	 A photograph showing a vertical crack in a white wall above a doorway. The crack is jagged and extends upwards. To the right, there is a framed picture of a mountain landscape. Below the doorway, there is a decorative rope-like trim.
<p>13.</p>	<p>Typical cracking above windows</p>	 A photograph showing a vertical crack in a white wall above a window. The crack is thin and extends upwards. Below the window, there are white lace curtains.

Guise Lane Housing Complex – Detailed Engineering Evaluation

14.	Typical cracking at the roofline	
15.	Typical cracking of the ceiling diaphragm	
16.	Typical splitting of the concrete patio and veneer	

Guise Lane Housing Complex – Detailed Engineering Evaluation

<p>17.</p>	<p>Cracking of wooden veneer</p>	
<p>18.</p>	<p>Ground settlement at road end of block A</p>	
<p>19.</p>	<p>Cracking in summerhill stone veneer</p>	

20.	Loose brick insitu	
21.	Slight splitting between veneer and firewall	



Guise Lane Housing Complex – Detailed Engineering Evaluation

<p>22.</p>	<p>Spalling of render on concrete pad</p>	 A close-up photograph of the base of a wall where it meets a concrete pad. The wall is made of light-colored, textured masonry blocks. There is significant damage to the render at the base, with large areas missing, exposing the underlying concrete and aggregate. Debris, including small pieces of concrete and some dried leaves, is scattered on the concrete pad surface.
<p>23.</p>	<p>Cracking in concrete pathways</p>	 A photograph of a concrete pathway. The pathway is composed of several slabs separated by expansion joints. A prominent, irregular crack runs across one of the slabs. In the bottom left corner, the tip of a black and white sneaker is visible, providing a scale reference. There are some small pieces of debris and a dried leaf on the concrete surface.


24.	Typical nail spacings (200mm)	
-----	----------------------------------	---

Appendix B – Level Survey

Guise Lane Housing Complex – Detailed Engineering Evaluation




Guise Lane Housing Complex – Detailed Engineering Evaluation



Unit 10

Unit 11


Unit 12



Unit 13

Unit 14

Guise Lane Housing Complex – Detailed Engineering Evaluation



Appendix C – Methodology and Assumptions

Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$ (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$ (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a μ of 2 was assumed for the residential units.

Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

Appendix D – CERA DEE Spreadsheet

Location		Building Name: <input type="text" value="Guise Lane Housing Complex"/>	Unit No: <input type="text" value="6"/>	Street: <input type="text" value="Guise"/>	Reviewer: <input type="text" value="Mary Ann Halliday"/>
Building Address: <input type="text"/>		Legal Description: <input type="text"/>			CPEng No: <input type="text" value="67073"/>
GPS south: <input type="text" value="43 33 28.36"/>		GPS east: <input type="text" value="172 35 21.12"/>			Company: <input type="text" value="Opus International Consultants"/>
GPS east: <input type="text"/>		Building Unique Identifier (CCC): <input type="text" value="PRO1519"/>			Company project number: <input type="text" value="6-OC349.00"/>
Degrees Min Sec		Company phone number: <input type="text" value="3635400"/>			Date of submission: <input type="text" value="26-Feb-14"/>
Building Unique Identifier (CCC): <input type="text"/>		Is there a full report with this summary? <input type="text" value="yes"/>			Inspection Date: <input type="text" value="29/11/2013"/>
					Revision: <input type="text" value="1"/>

Site	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
Soil type: <input type="text"/>	Soil Profile (if available): <input type="text"/>	
Site Class (to NZS1170.5): <input type="text" value="D"/>		
Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>	
Proximity to cliff top (m, if < 100m): <input type="text"/>		
Proximity to cliff base (m,if <100m): <input type="text"/>	Approx site elevation (m): <input type="text"/>	

Building	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split?: <input type="text" value="no"/>	Storeys below ground: <input type="text" value="0"/>		Ground floor elevation above ground (m): <input type="text"/>
Foundation type: <input type="text" value="mat slab"/>	Building height (m): <input type="text" value="3.00"/>		if Foundation type is other, describe: <input type="text"/>
Floor footprint area (approx): <input type="text" value="170"/>	Age of Building (years): <input type="text" value="36"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>	Date of design: <input type="text" value="1965-1976"/>
Strengthening present?: <input type="text" value="no"/>			If so, when (year)? <input type="text"/>
Use (ground floor): <input type="text" value="multi-unit residential"/>			And what load level (%g)? <input type="text"/>
Use (upper floors): <input type="text"/>			Brief strengthening description: <input type="text"/>
Use notes (if required): <input type="text"/>			
Importance level (to NZS1170.5): <input type="text" value="IL2"/>			

Gravity Structure	Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text" value="timber sarking"/>
Roof: <input type="text" value="timber framed"/>	Floors: <input type="text" value="concrete flat slab"/>	slab thickness (mm): <input type="text"/>
Beams: <input type="text" value="none"/>	Columns: <input type="text" value="timber"/>	overall depth x width (mm x mm): <input type="text"/>
Walls: <input type="text" value="non-load bearing"/>		typical dimensions (mm x mm): <input type="text"/>

Lateral load resisting structure	Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period along: <input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			
Lateral system across: <input type="text" value="lightweight timber framed walls"/>			note typical wall length (m): <input type="text"/>
Ductility assumed, μ: <input type="text" value="2.00"/>	0.00		estimate or calculation? <input type="text" value="estimated"/>
Period across: <input type="text" value="0.10"/>			estimate or calculation? <input type="text"/>
Total deflection (ULS) (mm): <input type="text"/>			estimate or calculation? <input type="text"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>			estimate or calculation? <input type="text"/>

Separations:	north (mm): <input type="text"/>	leave blank if not relevant
east (mm): <input type="text"/>		
south (mm): <input type="text"/>		
west (mm): <input type="text"/>		

Non-structural elements	Stairs: <input type="text"/>	describe: <input type="text" value="Summerhill stone"/>
Wall cladding: <input type="text" value="other heavy"/>	Roof Cladding: <input type="text" value="Heavy tiles"/>	describe: <input type="text"/>
Glazing: <input type="text" value="aluminium frames"/>	Ceilings: <input type="text" value="strapped or direct fixed"/>	
Services(list): <input type="text"/>		

Available documentation	Architectural: <input type="text" value="partial"/>	original designer name/date: <input type="text"/>
Structural: <input type="text" value="partial"/>	Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
Electrical: <input type="text" value="none"/>	Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>
		original designer name/date: <input type="text"/>

Damage Site:	Site performance: <input type="text" value="Good"/>	Describe damage: <input type="text"/>
(refer DEE Table 4-2)	Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
Differential settlement: <input type="text" value="1:250-1:150"/>	Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Lateral Spread: <input type="text" value="none apparent"/>	Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
Ground cracks: <input type="text" value="none apparent"/>	Damage to area: <input type="text" value="slight"/>	notes (if applicable): <input type="text"/>

Building:	Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe how damage ratio arrived at: <input type="text"/>
Describe (summary): <input type="text"/>		
Across	Damage ratio: <input type="text" value="0%"/>	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
Describe (summary): <input type="text"/>		
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>

Recommendations	Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
Building Consent required: <input type="text" value="no"/>	Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="52%"/>	#### %NBS from IEP below
Assessed %NBS after e'quakes: <input type="text" value="52%"/>		If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	#### %NBS from IEP below
Assessed %NBS after e'quakes: <input type="text" value="100%"/>		



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz