

*Christchurch City Council*

**Jecks Place  
Housing Complex  
PRO 0702**

**Detailed Engineering Evaluation  
Quantitative Assessment Report**



*Christchurch City Council*


---

# **Jecks Place Housing Complex**

## **Quantitative Assessment Report**


**4-70 Jecks Place, Dallington,**

Prepared By

  
.....  
Rebecca Ford  
Engineering Assistant


Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail  
Centre, Christchurch 8140  
New Zealand

Reviewed By

  
.....  
Lachlan Howat  
Structural Engineer

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Approved for  
Release By

  
.....  
Mary Ann Halliday  
Senior Structural Engineer

Date: February 2014  
Reference: 6-QC363.00  
Status: Final

# Summary

Jecks Place Housing Complex  
PRO 0702

Detailed Engineering Evaluation  
Quantitative Report - Summary  
Final

## Background

This is a summary of the quantitative report for the Jecks Place Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 52 residential units and the Residents Lounge on the site.

## Key Damage Observed

The residential units have suffered minor to moderate damage to non-structural elements. This included cracking of the brick veneer cladding. There is also moderate cracking to the concrete foundation perimeter footing (render and concrete) in most residential unit blocks. This damage was deemed low enough to not affect the capacities of the buildings. Minor damage to structural elements included minor cracking of plasterboard linings.

The Residents Lounge has suffered very minor damage to non-structural elements. This involved a loose brick in the veneer and a single observed crack of the internal plasterboard cladding.

## Level Survey

All accessible floor slopes were assessed in a laser level survey. A total of nine units (over 4 blocks) had floor slopes greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

## Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 150-400mm.

## Critical Structural Weaknesses

No critical structural weaknesses were found in any of the buildings.

## Indicative Building Strength

**Table A: Summary of Seismic Performance by Blocks**

Block	NBS%	Indicative Floor Levels	Nail Spacings
PRO 0702 B001 (Block A)	58%	Pass	Pass
PRO 0702 B002 (Residents Lounge)	100%	Pass	Pass
PRO 0702 B003 (Block B)	58%	Pass	Pass
PRO 0702 B004 (Block C)	58%	Fail	Pass
PRO 0702 B005 (Block D)	58%	Pass	Pass
PRO 0702 B006 (Block E)	58%	Pass	Pass
PRO 0702 B007 (Block F)	58%	Pass	Pass
PRO 0702 B008 (Block G)	58%	Pass	Pass
PRO 0702 B009 (Block H)	58%	Fail	Pass
PRO 0702 B010 (Block I)	58%	Pass	Pass
PRO 0702 B011 (Block J)	58%	Fail	Pass
PRO 0702 B012 (Block K)	58%	Fail	Pass

No buildings on the site are considered to be earthquake prone.

The residential units have capacities of 58% NBS as limited by the in-plane shear capacity of the timber-framed shear walls in the longitudinal direction. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines.

The residents lounge has a capacity of 100% NBS as limited by the in-plane shear capacity of the timber-framed shear walls in the longitudinal direction. It is deemed to be a ‘low risk’ in a design seismic event according to NZSEE guidelines.

Increasing the number of nails in the plasterboard will not significantly improve the strength of the buildings.

## Recommendations

It is recommended that;

- Strengthening schemes be developed to increase seismic capacity of Blocks A - K to 67%NBS.
- Veneer at height (gable ends) have the veneer ties checked.
- Work to permanently stabilize the gable end veneer of Block I be undertaken.
- The concrete perimeter footings be repaired on blocks where cracking occurs.
- The porch at Unit 44 be repaired to cover exposed reinforcing.
- Cosmetic repairs be undertaken as required.

# Contents

<b>Summary .....</b>	<b>i</b>
<b>1 Introduction.....</b>	<b>5</b>
<b>2 Compliance .....</b>	<b>5</b>
<b>3 Earthquake Resistance Standards.....</b>	<b>9</b>
<b>4 Background Information.....</b>	<b>11</b>
<b>5 Damage .....</b>	<b>18</b>
<b>6 Detailed Seismic Assessment .....</b>	<b>19</b>
<b>7 Geotechnical Summary .....</b>	<b>22</b>
<b>8 Conclusions.....</b>	<b>22</b>
<b>9 Recommendations .....</b>	<b>23</b>
<b>10 Limitations.....</b>	<b>23</b>
<b>11 References .....</b>	<b>24</b>
<b>Appendix A – Photographs</b>	
<b>Appendix B – Methodology and Assumptions</b>	
<b>Appendix C – Level Survey</b>	
<b>Appendix D – CERA DEE Spreadsheet</b>	

# 1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Jecks Place Housing Complex, located at 4-70 Jecks Place, Dallington, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 19 November 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

## 2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.
2. The placard status and amount of damage.

3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

## 2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

### Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

### Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death;  
or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

## **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

## **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

## **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

### 3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

### 3.1.1 Occupancy

The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### 3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

### 3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### 3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

---

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

## 4 Background Information

### 4.1 Building Descriptions

The site contains 52 residential units which were constructed in 1964. It is unknown when the Residents Lounge was constructed but it is believed to be after the units. A site plan showing the location of the units is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City. The units are grouped together to form 11 blocks of either four or six units.

Units are numbered such that eastern units have even numbers and western units have odd numbers. The east group contains four more units than the west group, thus the evens run from 4 to 70 skipping 12, 14, 28, 42, 52, and 62, and the odds run from 5 to 59 skipping 13, 23, 37, and 51.



Figure 2: Site plan of Jecks Place Housing Complex.




Figure 3: Location of Jecks Place (circled) relative to Christchurch City CBD (Source: Google Earth).

The residential units are timber-framed buildings with diagonal timber braces. The roof structure comprises of timber roof framing supporting light-weight metal roofs with timber sarking. Units A, C, E, F, I and K have gable-end roofs while units B, D, G, H and J have hip roofs. The walls and ceilings are lined with plasterboard. External walls are clad with Summerhill Stone (Blocks A, B, C, I, J, and K) and brick veneer (Blocks D, E, F, G and H). The timber floors are supported by concrete piles with a concrete perimeter wall. It is assumed, based on other similar buildings of the same era that the units are separated by 190mm block masonry fire walls which are reinforced around their perimeter.

All units originally had fireplaces, however these have all been boarded up and the chimneys have been taken down to below roof height.

Units 29 and 31 have been combined to created office space for Richmond New Zealand Trust Ltd. These units have no chimney between them; they instead have an open doorway. All other features of the layout are the same.

Figure 4 shows a typical floor plan of a residential unit produced from site measurements by Opus (actual arrangement may differ). Figure 5 shows a comparable cross section used in calculations, from Mabel Howard Housing Complex.

The Residents’ Lounge is a timber-framed building with diagonal timber braces. The roof structure comprises of timber framing supporting a light-weight metal roof. The walls and ceiling are lined with plasterboard. External walls are clad with brick veneer. The foundation consists of strip footings around the perimeter of a reinforced concrete slab. Figure 6 shows a floor plan of the Residents Lounge produced from site measurements by Opus.




Figure 4: Typical partial floor plan of residential unit blocks.



## 4.2 Survey

### 4.2.1 Post 22 February 2011 Rapid Assessment

A structural (Level 2) assessment of the buildings/property was undertaken on 8 March 2011 by Opus International Consultants.

### 4.2.2 Level Survey

A full level survey was not deemed to be necessary at Jecks Place as it is located in a TC2 zone. Properties in TC2 zones suffered minor to moderate damage due to liquefaction and/or settlement. In lieu of a full level survey, a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit. For this site, the maximum slope in a unit was 8mm/m (which exceeds the 5mm/m limitation imposed by MBIE guidelines); the general slopes across all units were approximately 4mm/m.

It is noted that most of the failed floor slopes were in the halls of the units, where the floor rose towards the back door. This slope was observed even in units where the slope was measured to be less than the limitation.

The results of the level survey can be found in Appendix C. A summary is shown in Table 2.

**Table 2: Summary of the Level Survey**

Block	Unit No.	Comment	Maximum Fall*
A	5	Pass	-
	7	Pass	-
	9	Pass	-
	11	Pass	-
B	15	Pass	-
	17	Pass	-
	19	Pass	-
	21	Pass	-
C	25	Pass	-
	27	Pass	-
	29	Pass	-
	31	Pass	-
	33	Fail	6mm/m
	35	Pass	-
D	39	Pass	-
	41	Pass	-
	43	Pass	-
	45	Pass	-
	47	Pass	-
	49	Pass	-
E	53	Pass	-
	55	Pass	-
	57	Pass	-
	59	Pass	-
F	64	Pass	-
	66	Pass	-
	68	Pass	-
	70	Pass	-
G	54	Pass	-
	56	Pass	-
	58	Pass	-
	60	Pass	-
H	44	Fail	8mm/m
	46	Pass	-
	48	Pass	-
	50	Pass	-
I	30	Pass	-
	32	Pass	-
	34	Pass	-
	36	Pass	-
	38	Pass	-
	40	Pass	-

J	16	Fail	7mm/m
	18	Pass	-
	20	Fail	8mm/m
	22	Fail	6mm/m
	24	Not assessed	-
	26	Fail	6mm/m
K	4	Fail	7mm/m
	6	Pass	-
	8	Fail	8mm/m
	10	Fail	7mm/m
Residents Lounge		Pass	-

\* Values are only recorded if greater than 5mm/m

Orange results represent floor levels which fall outside the MBIE guidelines when using the laser level but may comply when surveyed using more accurate equipment.

#### 4.2.3 Nail Spacings

The internal lining nail spacings were measured on site to vary between 150-400mm.

### 4.3 Original Documentation

The following documentation was provided to Opus by the Christchurch City Council:

- A147/1 – Christchurch City Council – Jecks Place Pensioners Cottages – p. 1-3/3 – Plans, elevations, details – 1962-1964
- 166/1 – Christchurch City Council – Dunarnan Street Pensioners Cottages – p. 1/1 – Site plan – 1961

Note that the drawings were renamed as Jecks Place (rather than Dunarnan Street) after design.

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

The drawings were used to confirm the structural systems, investigate potential critical structural weaknesses (CSW) and identify details which required particular attention.

Copies of the design calculations were not provided. Documentation on the Residents Lounge was not provided.

## 5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

Note: Any photo referenced in this section can be found in Appendix A.

### 5.1 Residual Displacements

Minor land movement was observed in many of the units and the Residents Lounge. It was noted that there was evidence of land damage in garden plots and on the driveways (photos 17 and 18). As can be seen from the results of the level survey Blocks K and J were most affected by this residual displacement.

### 5.2 Foundations

Cracking of the strip footing was observed. This ranged from hairline cracks in the render on the perimeter walls to significant cracks approximately 7mm wide extending through the concrete (photos 19-23). Cracking was typically observed around grates and pipes. In some cases this connected to stepped cracking in the veneer (see section 5.5). The piles themselves could not be checked for damage as there was no subfloor access.

### 5.3 Primary Gravity Structure

No damage was evident in the timber framing or roof structure.

### 5.4 Primary Lateral-Resistance Structure

Cracking to the plasterboard ceiling diaphragm was observed in almost all units. This was characteristically a lateral crack running over the division between the living and bedroom areas (photo 24). Another typical crack was a lateral crack running through the living room from the corner of the chimney (photo 25). In some cases these lateral ceiling cracks have been plastered over (photo 26), although this damage was still noticeable.

### 5.5 Non Structural Elements

In addition to characteristic cracking described in section 5.4, a variety of other cracks were observed. This was predominately separation cracking around walls, ceilings and joinery (photos 27-29) and some walls. There was also short lateral and vertical cracking from the corners of doorways and windows in a number of units (photos 30-31).

Damage to external cladding was also observed on many units. A number of units showed stepped cracking in the veneer (photo 32). Loose bricks were observed in the gable ends of most units (photo 33). It was noted that the veneer on the north gable end of Block I has been temporarily braced (photo 34).

In the same manner as cracking of the foundations, cracking of the front porches was observed. This was predominately hairline cracking but was extensive in places (photos 35-36). Significant damage was observed on the front porch of Unit 44 (photo 37), to the extent

that metal reinforcing was exposed. Some cracking to the back steps was also noted. It should be noted that it is believed the back steps were poured at the same time as the foundations as there is no cold joint.

The only observable damage in the Residents Lounge was a vertical crack in the plasterboard lining extending from the centre beam in the main room (photo 39) and a loose brick in the veneer in the North West corner (photo 40).

## 5.6 General Observations

The buildings appeared to have performed reasonably well, as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor to moderate damage which is typical of the type and age of construction and consistent with the heavy nature of the cladding.

## 6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

### 6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

### 6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix B. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 7 and Figure 8, were used for bracing in their respective directions.




Figure 7: Walls used for bracing in the longitudinal direction.




Figure 8: Walls used for bracing in the transverse direction.

### 6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this

analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

## 6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building’s capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

**Table 3: Summary of Seismic Performance**

<b>Building Description</b>	<b>Critical element</b>	<b>% NBS based on calculated capacity in longitudinal direction</b>	<b>% NBS based on calculated capacity in transverse direction.</b>
All units (Blocks A – K)	Timber bracing in the longitudinal direction	58%	100%
Residents Lounge	Timber bracing walls in the longitudinal direction	100%	100%

## 7 Geotechnical Summary

CERA indicates that Jecks Place is located in a TC2 zone (as shown in Figure 9). This classification suggests future significant earthquakes will cause minor to moderate land damage due to liquefaction and settlement.




Figure 9: CERA Technical Categories map (loc. starred).

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

## 8 Conclusions

- None of the buildings on site are considered to be Earthquake Prone.
- The residential units (Blocks A – K) have capacities of 58% NBS, as limited by the in-plane capacity of the bracing walls. They are deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines. Their level of risk is 5-10 times that of a 100% NBS building (Figure 1).
- The Residents Lounge has a capacity of 100% NBS, as limited by the in-plane capacity of the bracing walls. It is deemed to be a ‘low risk’ in a design seismic event according to NZSEE guidelines.
- Based on the geotechnical appraisal, differential settlement as a result of liquefaction could result in further damage, similar in nature to that which has occurred in the recent earthquake sequence. However, based on the nature of construction, this is unlikely to result in the collapse of concrete ground beams beneath the masonry walls.

## 9 Recommendations

It is recommended that;

- Strengthening schemes be developed to increase seismic capacity of Blocks A - K to 67%NBS.
- Veneer at height (gable ends) have the veneer ties checked.
- Work to permanently stabilize the gable end veneer of Block I be undertaken.
- The concrete perimeter footings be repaired on blocks where cracking occurs.
- The porch at Unit 44 be repaired to cover exposed reinforcing.
- Cosmetic repairs be undertaken as required.

## 10 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Jecks Place Housing Complex. It is not intended for any other party or purpose.

## 11 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

## **Appendix A – Photographs**

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

Jecks Place Housing Complex		
No.	Item description	Photo
Residential Units Layout		
1.	Typical exterior elevation (front)	
2.	Typical exterior elevation (end)	

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

<p>3.</p>	<p>Typical exterior elevation (back)</p>	
<p>4.</p>	<p>Typical layout of living room and sleeping area</p>	
<p>5.</p>	<p>Typical layout of living room toward kitchen</p>	

<p>6.</p>	<p>Typical layout of hall</p>	
<p>7.</p>	<p>Typical layout of bathroom</p>	


**Jecks Place Housing Complex – Detailed Engineering Evaluation**

8.	Typical layout of kitchen	
<b>Residents Lounge Layout</b>		
9.	Residents Lounge exterior elevation (front)	
10.	Residents Lounge exterior elevation (east)	

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

<p>11.</p>	<p>Residents Lounge exterior elevation (back)</p>	
<p>12.</p>	<p>Residents Lounge exterior elevation (west)</p>	
<p>13.</p>	<p>Entrance to Residents Lounge</p>	

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

<p>14.</p> <p>Internal layout of Residents Lounge (west side)</p>		
<p>15.</p> <p>Internal layout of Residents Lounge (east side)</p>		
<p>16.</p> <p>Layout of kitchen in Residents Lounge</p>		

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

Damage		
17.	Land damage in garden plots	
18.	Land damage creating swelling and large crack in road	
19.	Typical hairline cracking of strip footing	


**Jecks Place Housing Complex – Detailed Engineering Evaluation**

20.	Lateral cracking in strip footing	
21.	Typical medium cracking of strip footing	
22.	Typical significant cracking of strip footing	

<p>23.</p>	<p>Cracking of strip footing through grate – shows cracking right through footing</p>	
<p>24.</p>	<p>Typical cracking in ceiling above division between living and sleeping spaces</p>	


**Jecks Place Housing Complex – Detailed Engineering Evaluation**


---

<p>25.</p>	<p>Typical cracking in ceiling above living room, running from corner of chimney</p>	
<p>26.</p>	<p>Attempted repair to ceiling crack</p>	
<p>27.</p>	<p>Typical separation cracking in corners</p>	

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

---

28.	Typical separation cracking between ceiling and walls	 A photograph showing a close-up of the junction between a white ceiling and a white wall. A distinct, slightly jagged horizontal crack runs along the top of the wall, indicating a separation between the two surfaces. There are some small brown spots on the wall surface.
29.	Typical cracking above doorways and windows	 A photograph showing a close-up of a white wall above a doorway or window frame. A horizontal crack runs across the wall, just above the top edge of the frame. The wall is otherwise plain and white.
30.	Typical lateral cracking from doorways and windows	 A photograph showing a corner of a room where a white wall meets a white door or window frame. A vertical crack runs down the wall, starting from the top of the frame and extending downwards. A colorful box is visible on the floor in the bottom left corner.

<p>31.</p>	<p>Typical vertical cracking above doorways and windows</p>	
<p>32.</p>	<p>Typical step cracking in veneer</p>	
<p>33.</p>	<p>Typical loose brick in gable end</p>	

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

<p>34.</p>	<p>Veneer bracing at end of Block I</p>	 A photograph showing the exterior of a building with grey brickwork. A section of the wall is covered with plywood veneer, which is supported by a metal bracing system consisting of diagonal beams and horizontal supports. A window is visible to the right of the braced area. The building is situated on a grassy area with a fence in the background.
<p>35.</p>	<p>Typical hairline cracking on porches.</p>	 A close-up photograph of a concrete surface, likely a porch. The concrete is light grey and shows several thin, vertical hairline cracks. The texture of the concrete is visible, and there is a horizontal joint or change in surface level across the middle of the image.
<p>36.</p>	<p>Lateral cracking on porches</p>	 A close-up photograph of a concrete surface, likely a porch. The concrete is light grey and shows a prominent, irregular lateral crack that runs horizontally across the surface. The crack is deeper than the hairline cracks seen in the previous image. A dark, possibly painted, area is visible at the top of the frame.


**Jecks Place Housing Complex – Detailed Engineering Evaluation**

---

37.	Extensive cracking in porch (Unit 44)	 A photograph showing a concrete porch area with significant structural damage. The concrete is cracked and crumbling, particularly along the edge of a raised section. A bicycle tire is visible in the upper right corner, resting on the damaged surface.
38.	Chipping of back steps	 A close-up photograph of concrete steps. The top surface of the steps is chipped and spalled, revealing the aggregate and rebar structure of the concrete. The damage is most prominent on the back edge of the steps.

**Jecks Place Housing Complex – Detailed Engineering Evaluation**

---

39.	Internal cracking in Residents Lounge	
40.	Loose brick in veneer of Residents Lounge (north-west corner)	

## **Appendix B – Methodology and Assumptions**

## Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$  (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$  (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a  $\mu$  of 2 was assumed for the residential units.

## Analysis Procedure


As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

## Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

## **Appendix C – Level Survey**




existing open drain along this boundary

an open drain exists along this boundary

an open drain exists along this boundary

x Sewer flusher repair & ad. supply.  
52 UNITS ON 412 PERCHES



LEGEND

- |   |  |      |                     |
|---|--|------|---------------------|
| — | MAIN SEWER AND BRANCHES                  | M.V. | MAIN VENT           |
| — | 4" GLAZED EARTHENWARE STORMWATER         | G.T. | GULLY TRAP          |
| — | WATER SUPPLY                             | I.J. | INSPECTION JUNCTION |
| — | ELECTRICITY SUPPLY UNDERGROUND CABLE     | I.P. | INSPECTION PIPE     |
| — | METER CABINET                            | B.E. | BLIND END           |
| — | LETTER AND MILK BOX (no of compartments) | W.C. | WATER CLOSET        |
| — | STREET LIGHT                             | D.P. | RAINWATER DOWNPIPE  |
| — | SEWER MANHOLE                            | P.C. | 1/2" PILLAR COCK    |
| — |  | ☐    | COAL BOX            |
| — |  | ⊙    | FIRE HYDRANT        |

GRANT SMITH

revised 3/1/44 Reading 4/108

CHRISTCHURCH CITY COUNCIL  
PLANNING DEPARTMENT

DUNARNAN STREET PENSIONERS COTTAGES

SCALE 1/16" = 1' 0"  
DATE JULY 1961

## **Appendix D – CERA DEE Spreadsheet**

<b>Location</b>		Building Name: <u>Jecks Place Housing Complex - 4 unit block</u>	Reviewer: <u>M A Halliday</u>
	Unit No: <u>                    </u>	Street: <u>                    </u>	CPEng No: <u>67073</u>
Building Address: <u>4-70 Jecks Place</u>			Company: <u>Opus Internation Consultants Ltd.</u>
Legal Description: <u>                    </u>			Company project number: <u>6-QC363.00</u>
			Company phone number: <u>03-363-5400</u>
	Degrees	Min	Sec
GPS south: <u>                    </u>	<u>43</u>	<u>31</u>	<u>17.52</u>
GPS east: <u>                    </u>	<u>172</u>	<u>40</u>	<u>42.82</u>
Building Unique Identifier (CCC): <u>PRO 0702</u>	Is there a full report with this summary?		<u>yes</u>
			Date of submission: <u>21-Feb-14</u>
			Inspection Date: <u>19/11/2013</u>
			Revision: <u>1</u>

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>                    </u>
	Soil type: <u>                    </u>	Soil Profile (if available): <u>                    </u>
	Site Class (to NZS1170.5): <u>D</u>	
	Proximity to waterway (m, if <100m): <u>                    </u>	If Ground improvement on site, describe: <u>                    </u>
	Proximity to cliff top (m, if < 100m): <u>                    </u>	
	Proximity to cliff base (m,if <100m): <u>                    </u>	Approx site elevation (m): <u>4.00</u>

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>                    </u>
	Ground floor split? <u>no</u>		Ground floor elevation above ground (m): <u>                    </u>
	Storeys below ground: <u>0</u>		
	Foundation type: <u>bored cast-insitu concrete piles</u>		if Foundation type is other, describe: <u>                    </u>
	Building height (m): <u>3.00</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>                    </u>	
	Floor footprint area (approx): <u>132</u>		Date of design: <u>1935-1965</u>
	Age of Building (years): <u>49</u>		
	Strengthening present? <u>no</u>		If so, when (year)? <u>                    </u>
	Use (ground floor): <u>multi-unit residential</u>		And what load level (%g)? <u>                    </u>
	Use (upper floors): <u>                    </u>		Brief strengthening description: <u>                    </u>
	Use notes (if required): <u>                    </u>		
	Importance level (to NZS1170.5): <u>IL2</u>		

<b>Gravity Structure</b>	Gravity System: <u>frame system</u>	
	Roof: <u>timber framed</u>	rafter type, purlin type and cladding: <u>                    </u>
	Floors: <u>timber</u>	joist depth and spacing (mm): <u>                    </u>
	Beams: <u>none</u>	overall depth x width (mm x mm): <u>                    </u>
	Columns: <u>timber</u>	typical dimensions (mm x mm): <u>                    </u>
	Walls: <u>non-load bearing</u>	<u>0</u>

<b>Lateral load resisting structure</b>	Lateral system along: <u>lightweight timber framed walls</u>	<b>Note: Define along and across in detailed report!</b>	note typical wall length (m): <u>1</u>
	Ductility assumed, μ: <u>2.00</u>		
	Period along: <u>0.10</u>		estimate or calculation? <u>estimated</u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	Lateral system across: <u>lightweight timber framed walls</u>		note typical wall length (m): <u>                    </u>
	Ductility assumed, μ: <u>2.00</u>		
	Period across: <u>0.10</u>		estimate or calculation? <u>estimated</u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>

<b>Separations:</b>	north (mm): <u>                    </u>	leave blank if not relevant
	east (mm): <u>                    </u>	
	south (mm): <u>                    </u>	
	west (mm): <u>                    </u>	

<b>Non-structural elements</b>	Stairs: <u>                    </u>	
	Wall cladding: <u>other heavy</u>	describe: <u>summerhill stone</u>
	Roof Cladding: <u>Metal</u>	describe: <u>                    </u>
	Glazing: <u>timber frames</u>	
	Ceilings: <u>fibrous plaster, fixed</u>	
	Services(list): <u>                    </u>	

<b>Available documentation</b>	Architectural: <u>partial</u>	original designer name/date: <u>Christchurch City Council/1962</u>
	Structural: <u>partial</u>	original designer name/date: <u>                    </u>
	Mechanical: <u>none</u>	original designer name/date: <u>                    </u>
	Electrical: <u>none</u>	original designer name/date: <u>                    </u>
	Geotech report: <u>none</u>	original designer name/date: <u>                    </u>

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>sinking in garden plots, damage to roads</u>
<b>Site:</b> (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Differential settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Liquefaction: <u>0-2 m<sup>3</sup>/100m<sup>2</sup></u>	notes (if applicable): <u>                    </u>
	Lateral Spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Differential lateral spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Ground cracks: <u>0-20mm/20m</u>	notes (if applicable): <u>                    </u>
	Damage to area: <u>slight</u>	notes (if applicable): <u>                    </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: <u>                    </u>
	Describe (summary): <u>                    </u>	
Across	Damage ratio: <u>0%</u>	$Damage \_ Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$
	Describe (summary): <u>                    </u>	
Diaphragms	Damage?: <u>yes</u>	Describe: <u>                    </u>
CSWs:	Damage?: <u>no</u>	Describe: <u>                    </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>                    </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>lining and veneer cracking</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Describe: <u>                    </u>
	Building Consent required: <u>no</u>	Describe: <u>                    </u>
	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u>                    </u>
Along	Assessed %NBS before e'quakes: <u>58%</u> ##### %NBS from IEP below	If IEP not used, please detail assessment methodology: <u>Equivalent Static</u>
	Assessed %NBS after e'quakes: <u>58%</u>	
Across	Assessed %NBS before e'quakes: <u>100%</u> ##### %NBS from IEP below	
	Assessed %NBS after e'quakes: <u>100%</u>	

Detailed Engineering Evaluation Summary Data

V1.14

<b>Location</b>		Building Name: <u>Jecks Place Housing Complex - 6 unit block</u>	Reviewer: <u>M A Halliday</u>
		Unit No: <u>                    </u> Street: <u>                    </u>	CPEng No: <u>67073</u>
	Building Address: <u>4-70 Jecks Place</u>		Company: <u>Opus Internation Consultants Ltd.</u>
	Legal Description: <u>                    </u>		Company project number: <u>6-QC363.00</u>
			Company phone number: <u>03-363-5400</u>
		Degrees Min Sec	Date of submission: <u>21-Feb-14</u>
	GPS south: <u>                    </u>	<u>43 31 17.52</u>	Inspection Date: <u>19/11/2013</u>
	GPS east: <u>                    </u>	<u>172 40 42.82</u>	Revision: <u>1</u>
	Building Unique Identifier (CCC): <u>PRO 0702</u>		Is there a full report with this summary? <u>yes</u>

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>                    </u>
	Soil type: <u>                    </u>	Soil Profile (if available): <u>                    </u>
	Site Class (to NZS1170.5): <u>D</u>	If Ground improvement on site, describe: <u>                    </u>
	Proximity to waterway (m, if <100m): <u>                    </u>	
	Proximity to cliff top (m, if < 100m): <u>                    </u>	
	Proximity to cliff base (m,if <100m): <u>                    </u>	Approx site elevation (m): <u>4.00</u>

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>                    </u>
	Ground floor split? <u>no</u>		Ground floor elevation above ground (m): <u>                    </u>
	Storeys below ground: <u>0</u>		if Foundation type is other, describe: <u>                    </u>
	Foundation type: <u>bored cast-insitu concrete piles</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>                    </u>	
	Building height (m): <u>3.00</u>		Date of design: <u>1935-1965</u>
	Floor footprint area (approx): <u>198</u>		
	Age of Building (years): <u>49</u>		
	Strengthening present? <u>no</u>		If so, when (year)? <u>                    </u>
	Use (ground floor): <u>multi-unit residential</u>		And what load level (%g)? <u>                    </u>
	Use (upper floors): <u>                    </u>		Brief strengthening description: <u>                    </u>
	Use notes (if required): <u>                    </u>		
	Importance level (to NZS1170.5): <u>IL2</u>		

<b>Gravity Structure</b>	Gravity System: <u>frame system</u>	rafter type, purlin type and cladding: <u>                    </u>
	Roof: <u>timber framed</u>	joist depth and spacing (mm): <u>                    </u>
	Floors: <u>timber</u>	overall depth x width (mm x mm): <u>                    </u>
	Beams: <u>none</u>	typical dimensions (mm x mm): <u>                    </u>
	Columns: <u>timber</u>	
	Walls: <u>non-load bearing</u>	

<b>Lateral load resisting structure</b>	Lateral system along: <u>lightweight timber framed walls</u>	<b>Note: Define along and across in detailed report!</b>	note typical wall length (m): <u>1</u>
	Ductility assumed, μ: <u>2.00</u>		estimate or calculation? <u>estimated</u>
	Period along: <u>0.10</u>		estimate or calculation? <u>                    </u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		
	Lateral system across: <u>lightweight timber framed walls</u>		note typical wall length (m): <u>                    </u>
	Ductility assumed, μ: <u>2.00</u>		estimate or calculation? <u>estimated</u>
	Period across: <u>0.10</u>		estimate or calculation? <u>                    </u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		

<b>Separations:</b>	north (mm): <u>                    </u>	leave blank if not relevant
	east (mm): <u>                    </u>	
	south (mm): <u>                    </u>	
	west (mm): <u>                    </u>	

<b>Non-structural elements</b>	Stairs: <u>                    </u>	describe: <u>summerhill stone</u>
	Wall cladding: <u>other heavy</u>	describe: <u>corrugated iron</u>
	Roof Cladding: <u>Metal</u>	
	Glazing: <u>timber frames</u>	
	Ceilings: <u>fibrous plaster, fixed</u>	
	Services(list): <u>                    </u>	

<b>Available documentation</b>	Architectural: <u>partial</u>	original designer name/date: <u>Christchurch City Council/1962</u>
	Structural: <u>partial</u>	original designer name/date: <u>                    </u>
	Mechanical: <u>none</u>	original designer name/date: <u>                    </u>
	Electrical: <u>none</u>	original designer name/date: <u>                    </u>
	Geotech report: <u>none</u>	original designer name/date: <u>                    </u>

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>sinking in garden plots, damage to roads</u>
<b>Site:</b> (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Differential settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Liquefaction: <u>0-2 m<sup>3</sup>/100m<sup>2</sup></u>	notes (if applicable): <u>                    </u>
	Lateral Spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Differential lateral spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Ground cracks: <u>0-20mm/20m</u>	notes (if applicable): <u>                    </u>
	Damage to area: <u>slight</u>	notes (if applicable): <u>                    </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	Describe how damage ratio arrived at: <u>                    </u>
Along	Damage ratio: <u>0%</u>	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary): <u>                    </u>	
Across	Damage ratio: <u>0%</u>	
	Describe (summary): <u>                    </u>	
Diaphragms	Damage?: <u>yes</u>	Describe: <u>                    </u>
CSWs:	Damage?: <u>no</u>	Describe: <u>                    </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>                    </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>lining and veneer cracking</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Describe: <u>                    </u>
	Building Consent required: <u>no</u>	Describe: <u>                    </u>
	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u>                    </u>
Along	Assessed %NBS before e'quakes: <u>58%</u> ##### %NBS from IEP below	If IEP not used, please detail assessment methodology: <u>Equivalent Static</u>
	Assessed %NBS after e'quakes: <u>58%</u>	
Across	Assessed %NBS before e'quakes: <u>100%</u> ##### %NBS from IEP below	
	Assessed %NBS after e'quakes: <u>100%</u>	

<b>Location</b>		Building Name: <u>Jecks Place Housing Complex - Residents Lounge</u>	Reviewer: <u>M A Halliday</u>
		Unit No: <u>                    </u> Street: <u>                    </u>	CPEng No: <u>67073</u>
		Building Address: <u>4-70 Jecks Place</u>	Company: <u>Opus Internation Consultants Ltd.</u>
		Legal Description: <u>                    </u>	Company project number: <u>6-QC363.00</u>
			Company phone number: <u>03-363-5400</u>
		GPS south: <u>                    </u>	Date of submission: <u>21-Feb-14</u>
		GPS east: <u>                    </u>	Inspection Date: <u>19/11/2013</u>
		Building Unique Identifier (CCC): <u>PRO 0702</u>	Revision: <u>1</u>
			Is there a full report with this summary? <u>yes</u>

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u>                    </u>
	Soil type: <u>                    </u>	Soil Profile (if available): <u>                    </u>
	Site Class (to NZS1170.5): <u>D</u>	If Ground improvement on site, describe: <u>                    </u>
	Proximity to waterway (m, if <100m): <u>                    </u>	Approx site elevation (m): <u>4.00</u>
	Proximity to cliff top (m, if < 100m): <u>                    </u>	
	Proximity to cliff base (m,if <100m): <u>                    </u>	

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u>                    </u>
	Ground floor split? <u>no</u>		Ground floor elevation above ground (m): <u>                    </u>
	Storeys below ground: <u>0</u>		if Foundation type is other, describe: <u>                    </u>
	Foundation type: <u>strip footings</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>                    </u>	Date of design: <u>1992-2004</u>
	Building height (m): <u>3.00</u>		
	Floor footprint area (approx): <u>145</u>		
	Age of Building (years): <u>                    </u>		
	Strengthening present? <u>no</u>		If so, when (year)? <u>                    </u>
	Use (ground floor): <u>multi-unit residential</u>		And what load level (%g)? <u>                    </u>
	Use (upper floors): <u>                    </u>		Brief strengthening description: <u>                    </u>
	Use notes (if required): <u>                    </u>		
	Importance level (to NZS1170.5): <u>IL2</u>		

<b>Gravity Structure</b>	Gravity System: <u>frame system</u>	rafter type, purlin type and cladding: <u>                    </u>
	Roof: <u>timber framed</u>	slab thickness (mm): <u>                    </u>
	Floors: <u>concrete flat slab</u>	type: <u>                    </u>
	Beams: <u>timber</u>	typical dimensions (mm x mm): <u>                    </u>
	Columns: <u>timber</u>	
	Walls: <u>non-load bearing</u>	

<b>Lateral load resisting structure</b>	Lateral system along: <u>lightweight timber framed walls</u>	<b>Note: Define along and across in detailed report!</b>	note typical wall length (m): <u>                    </u>
	Ductility assumed, μ: <u>2.00</u>		estimate or calculation? <u>estimated</u>
	Period along: <u>0.10</u>		estimate or calculation? <u>                    </u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		
	Lateral system across: <u>lightweight timber framed walls</u>		note typical wall length (m): <u>                    </u>
	Ductility assumed, μ: <u>2.00</u>		estimate or calculation? <u>estimated</u>
	Period across: <u>0.10</u>		estimate or calculation? <u>                    </u>
	Total deflection (ULS) (mm): <u>                    </u>		estimate or calculation? <u>                    </u>
	maximum interstorey deflection (ULS) (mm): <u>                    </u>		

<b>Separations:</b>	north (mm): <u>                    </u>	leave blank if not relevant
	east (mm): <u>                    </u>	
	south (mm): <u>                    </u>	
	west (mm): <u>                    </u>	

<b>Non-structural elements</b>	Stairs: <u>                    </u>	describe (note cavity if exists): <u>                    </u>
	Wall cladding: <u>brick or tile</u>	describe: <u>red brick</u>
	Roof Cladding: <u>Metal</u>	
	Glazing: <u>aluminium frames</u>	
	Ceilings: <u>fibrous plaster, fixed</u>	
	Services(list): <u>                    </u>	

<b>Available documentation</b>	Architectural: <u>partial</u>	original designer name/date: <u>Christchurch City Council/1962</u>
	Structural: <u>partial</u>	original designer name/date: <u>                    </u>
	Mechanical: <u>none</u>	original designer name/date: <u>                    </u>
	Electrical: <u>none</u>	original designer name/date: <u>                    </u>
	Geotech report: <u>none</u>	original designer name/date: <u>                    </u>

<b>Damage</b>	Site performance: <u>good</u>	Describe damage: <u>sinking in garden plots, damage to roads</u>
<b>Site:</b> (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Differential settlement: <u>none observed</u>	notes (if applicable): <u>                    </u>
	Liquefaction: <u>0-2 m<sup>3</sup>/100m<sup>2</sup></u>	notes (if applicable): <u>                    </u>
	Lateral Spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Differential lateral spread: <u>none apparent</u>	notes (if applicable): <u>                    </u>
	Ground cracks: <u>0-20mm/20m</u>	notes (if applicable): <u>                    </u>
	Damage to area: <u>slight</u>	notes (if applicable): <u>                    </u>

<b>Building:</b>	Current Placard Status: <u>green</u>	Describe how damage ratio arrived at: <u>                    </u>
Along	Damage ratio: <u>0%</u>	$Damage \_ Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$
	Describe (summary): <u>                    </u>	
Across	Damage ratio: <u>0%</u>	
	Describe (summary): <u>                    </u>	
Diaphragms	Damage?: <u>no</u>	Describe: <u>                    </u>
CSWs:	Damage?: <u>no</u>	Describe: <u>                    </u>
Pounding:	Damage?: <u>no</u>	Describe: <u>                    </u>
Non-structural:	Damage?: <u>yes</u>	Describe: <u>lining cracking</u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>minor non-structural</u>	Describe: <u>                    </u>
	Building Consent required: <u>no</u>	Describe: <u>                    </u>
	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u>                    </u>
Along	Assessed %NBS before e'quakes: <u>100%</u>	If IEP not used, please detail assessment methodology: <u>Equivalent Static</u>
	Assessed %NBS after e'quakes: <u>100%</u>	
Across	Assessed %NBS before e'quakes: <u>100%</u>	
	Assessed %NBS after e'quakes: <u>100%</u>	



**Opus International Consultants Ltd**  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

t: +64 3 363 5400  
f: +64 3 365 7858  
w: [www.opus.co.nz](http://www.opus.co.nz)