



**Le Bons Bay Community Hall**  
BU 3597-001 EQ2  
**Detailed Engineering Evaluation**  
**Quantitative Report**

Christchurch City Council



*Christchurch City Council*

# **Le Bons Bay Community Hall**

## **Detailed Engineering Evaluation Quantitative Report**

Opus International Consultants Ltd  
Christchurch Office  
20 Moorhouse Avenue  
PO Box 1482, Christchurch Mail Centre,  
Christchurch 8140  
New Zealand

Telephone: +64 3 363 5400  
Facsimile: +64 3 365 7858

Date: October 2012  
Reference: 6-QUCCC.73  
Status: Final

Le Bons Bay Community Hall Building  
BU 3597-001 EQ2

Detailed Engineering Evaluation  
Quantitative Report - SUMMARY  
Final

Le Bons Bay, Banks Peninsula

### **Background**

This is a summary of the quantitative report for the building structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections on 18 January 2012, available drawings and calculations.

### **Key Damage Observed**

There is no evidence of any seismic damage having occurred to the building.

### **Critical Structural Weaknesses**

No critical structural weaknesses have been identified for this building.

### **Indicative Building Strength**

Based on the information available, and from undertaking a quantitative assessment, the buildings original capacity has been assessed to be in the order of 46% NBS across the building and 63% NBS along the building and a post-earthquake capacity in the order of 46% NBS across the building and 63% NBS along the building.

The building has been assessed to have a seismic capacity in the order of 46% NBS and is therefore not classed as earthquake prone.

### **Recommendations**

It is recommended that:

- a) A strengthening scheme be developed to increase the overall capacity of the building to at least 67% NBS

## **Contents**

<b>1</b>	<b>Introduction.....</b>	<b>1</b>
<b>2</b>	<b>Compliance .....</b>	<b>1</b>
<b>3</b>	<b>Earthquake Resistance Standards .....</b>	<b>4</b>
<b>4</b>	<b>Building Description.....</b>	<b>7</b>
<b>5</b>	<b>Survey.....</b>	<b>7</b>
<b>6</b>	<b>Damage Assessment.....</b>	<b>8</b>
<b>7</b>	<b>General Observations.....</b>	<b>8</b>
<b>8</b>	<b>Detailed Seismic Assessment.....</b>	<b>8</b>
<b>9</b>	<b>Geotechnical Assessment .....</b>	<b>10</b>
<b>10</b>	<b>Remedial Options .....</b>	<b>11</b>
<b>11</b>	<b>Conclusions .....</b>	<b>11</b>
<b>12</b>	<b>Recommendations.....</b>	<b>11</b>
<b>13</b>	<b>Limitations.....</b>	<b>11</b>
<b>14</b>	<b>References .....</b>	<b>11</b>

**Appendix A – Photographs**

**Appendix B – Floor Plan**

**Appendix C – DEE Spreadsheet**

## **1 Introduction**

Opus International Consultants Limited has been engaged by Christchurch City Council (CCC) to undertake a detailed seismic assessment of the Le Bons Bay Community Hall building, located at Le Bons Bay, Banks Peninsula, following the M6.3 Christchurch earthquake on 22 February 2011.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011.

## **2 Compliance**

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### **2.1 Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Any building with a capacity of less than 34% of new building standard (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% as required by the CCC Earthquake Prone Building Policy.

## **2.2 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 - Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration.

This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) is satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'.

This is typically interpreted by CCC as being 67% of the strength of an equivalent new building. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

### **Section 121 – Dangerous Buildings**

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **2.3 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## 2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- 36% increase in the basic seismic design load for Christchurch (Z factor increased from 0.22 to 0.3);
- Increased serviceability requirements.

## 2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

*Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.*

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

## 3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

**Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

**Table 1: %NBS compared to relative risk of failure**

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

### 3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

#### 3.1.1 Occupancy

- The Canterbury Earthquake Order<sup>1</sup> in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once

<sup>1</sup> This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

they are made aware of our assessment. Based on information received from CERA to date, this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

### **3.1.2 Cordoning**

- Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/Christchurch City Council guidelines.

### **3.1.3 Strengthening**

- Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.
- It should be noted that full compliance with the current building code requires building strength of 100%NBS.

### **3.1.4 Our Ethical Obligation**

- In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

## **4 Building Description**

### **4.1 General**

The Le Bons Bay Community Hall building is a single storey timber framed structure with a timber weatherboard cladding and lightweight corrugated iron roof. The building sits on a concrete perimeter foundation and circular concrete tapered piles.

The building is situated on a flat sandy section. The building is approximately 16.1m long in the north-south direction and approximately 9.8m wide in the east-west direction. The building consists of bathrooms at the south end, an office and kitchen on the east side, and a main hall on the west side of the building. The building has a 1.8m concrete veranda extending around the east and north sides of the building. The apex of the building is approximately 5.2m off the ground and the building has wall stud heights of 2.4m to 3.4m.

The building age is unknown, but is expected to have been constructed approximately 35 to 40 years ago.

### **4.2 Gravity Load Resisting System**

The roof consists of two timber framed monoslope roofs at different levels, with exposed rafters at 1.2m centres.

The walls are timber framed with stud heights varying between 2.4-3.4m and a stud size of 100mm x 50mm. The stud spacing is unknown, but is assumed to be 600mm.

The building sits on a concrete perimeter beam and tapered concrete pile foundations.

The subfloor consists of a suspended timber floor with tongue in groove flooring.

### **4.3 Seismic Load Resisting System**

The main lateral support for the building is provided by the GIB lining to the walls.

The sub floor bracing is provided by the concrete perimeter beam under the exterior walls.

## **5 Survey**

The building currently has a green placard (not issued as part of this inspection and authorised by an engineer working for a company other than Opus International Consultants).

Copies of the following drawings were referred to as part of the assessment:

- One architectural sketch of the building completed by Opus Architecture, dated 22 February 2012.

No copies of the design calculations or structural drawings have been obtained for this building.

The drawings have been used to confirm the structural systems, investigate potential critical structural weaknesses (CSW) wherever possible and identify details which required particular attention.

## **6 Damage Assessment**

The building does not appear to have suffered any damage as a result of the recent earthquake events. A crack was observed in the concrete step on the veranda, however this appears to be historic damage.

## **7 General Observations**

Overall the building has performed well under seismic conditions which would be expected for a timber framed single storey structure. The building has sustained little damage and continues to be fully operational.

Due to the non-intrusive nature of the original survey, many connection details could not be ascertained.

## **8 Detailed Seismic Assessment**

### **8.1 Critical Structural Weaknesses**

As outlined in the Critical Structural Weakness and Collapse Hazards draft briefing document, issued by the Structural Engineering Society (SESOC) on 7 May 2011, the term 'Critical Structural Weakness' (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of the building.

We have identified no critical structural weaknesses in the building.

### **8.2 Seismic Coefficient Parameters**

The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this building are:

- Site soil class D, clause 3.1.3 NZS 1170.5:2004
- Site hazard factor,  $Z=0.3$ , B1/VM1 clause 2.2.14B
- Return period factor  $R_u = 1.0$  from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life.
- $\mu_{max} = 2$  for the gib lined, timber-framed building.

### **8.3 Detailed Seismic Assessment Results**

A summary of the structural performance of the building is shown in the following tables. Note that the values given represent the worst performing elements in the building, as these

effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing element.

**Table 2: Summary of Seismic Performance**

Structural Element/System	Failure mode and description of limiting criteria	Critical Structural Weakness and Collapse Hazard	% NBS based on calculated capacity
Walls in the east west direction i.e. across the building	Bracing capacity of wall linings along the building	No	45%
Walls in the north south direction i.e. along the building	Bracing capacity of wall linings across the building	No	63%
Roof diaphragm	Bracing capacity of the roof plane diaphragm in the hall area	No	61%
Perimeter foundation	Bracing capacity of the concrete perimeter foundation	No	>100%

#### 8.4 Discussion of Results

The building has a calculated capacity of 46% NBS, as limited by the GIB capacity in the wall between the kitchen and office rooms.

The capacity of the ceiling diaphragm is based on values published in the NZSEE 2006 document [2], and site verification of the diaphragm fixings will be required in order to confirm the actual capacity.

#### 8.5 Limitations and Assumptions in Results

Our analysis and assessment is based on an assessment of the building in its undamaged state. Therefore the current capacity of the building will be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity;
- Assessments of material strengths based on limited drawings, specifications and site inspections;
- The normal variation in material properties which change from batch to batch;
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.

## **9 Geotechnical Assessment**

### **9.1 Regional Geology**

The published geological map of the area, (Geology of the Christchurch Area 1:250,000, Forsyth, Barrell and Jongens, 2008) indicates the site is located on beach gravel and sand along the active shoreline.

### **9.2 Peak Ground Acceleration**

Interpolation of United States Geological Survey (USGS) Shakemap: South Island of New Zealand (22 Feb, 2011) indicates that this location has likely experienced a Horizontal Peak Ground Acceleration (PGA) of approximately 0.1g to 0.2g during the 22<sup>nd</sup> February 2011 Earthquake. Estimated PGA's have been cross checked with Geonets' Modified Mercalli intensity scale observations.

### **9.3 Expected Ground Conditions**

No relevant site investigation data is available from Environment Canterbury database in the vicinity of this building.

### **9.4 Site Observations**

The building was inspected by Opus structural engineers on the 19<sup>th</sup> January 2012. The following observations were made from site notes and photographs.

- The building is located on a flat site, 220m west of the beach and 250m north of the river.
- The building is founded on a perimeter strip footing of unknown dimensions and interior concrete cone piles. All concrete piles appear to be tied to the timber bearers.
- There does not appear to have been any ground movement in the vicinity of the building.
- The foundations appear to have been undermined at the south west corner of the building. A 5mm crack is present in this location. Settlement is not attributed to the recent seismic events. Refer to Photo 7.
- The building does not appear to have differentially settled.
- A 5mm crack has continued up a step on the east side, which connects to a concrete shrinkage cut line. Refer to Photo 8.

### **9.5 Discussion and Conclusions**

The existing foundations appear to have performed satisfactorily in the recent seismic events. No ground deformation or liquefaction has been observed at the site. The undermining of the foundations on the south west corner of the building is unlikely to have been caused by the recent seismic events. The 5mm crack that is also evident in this area is due to the extension of the building and not the recent seismic events. Due to the

adequate performance of the existing foundations, no further geotechnical testing is recommended.

## **10 Remedial Options**

We recommend a strengthening scheme is developed to increase the overall building capacity to at least 67% NBS.

The capacity of the ceiling diaphragm fixings would also need to be assessed.

## **11 Conclusions**

- (a) The building has a seismic capacity of 46% NBS and is therefore classed as a moderate risk building.
- (b) Strengthening work is required to increase the overall building capacity to at least 67% NBS.
- (c) The existing foundations have performed satisfactorily, and no further geotechnical testing is required.

## **12 Recommendations**

- (a) Strengthening options be developed for increasing the seismic capacity of the building to at least 67% NBS.

## **13 Limitations**

- (a) This report is based on an inspection of the structure with a focus on the damage sustained from the 22 February 2011 Canterbury Earthquake and aftershocks only. Some non-structural damage is mentioned but this is not intended to be a comprehensive list of non-structural items.
- (b) Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- (c) This report is prepared for the CCC to assist with assessing remedial works required for council buildings and facilities. It is not intended for any other party or purpose.

## **14 References**

- [1] NZS 1170.5: 2004, *Structural design actions, Part 5 Earthquake actions*, Standards New Zealand.
- [2] NZSEE: 2006, *Assessment and improvement of the structural performance of buildings in earthquakes*, New Zealand Society for Earthquake Engineering.

- [3] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure*, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.

## **Appendix A – Photographs**



**Photo 1 – The north perimeter wall**



**Photo 2 – The east perimeter wall**



**Photo 3 – The south perimeter wall**



**Photo 4 – View of the main hall room**



**Photo 5 – View of the exposed rafters in the main hall room**



**Photo 6 – View of the pile foundations and subfloor framing**



**Photo 7: Undermined footing and cracks**



**Photo 8: 5mm crack on step**

## **Appendix B – Floor Plan**



## **Appendix C – DEE Spreadsheet**

Location Building Name: <u>Le Bons Bay Community Hall</u> Building Address: <u>Le Bons Bay</u> Legal Description: _____ GPS south: _____ GPS east: _____ Building Unique Identifier (CCC): <u>BU 3597-001 EQ2</u>		Reviewer: <u>Alistair Boyce</u> CP/Eng No: <u>209890</u> Company: <u>Opus International Consultants</u> Company project number: <u>6-OUCC 73</u> Company phone number: <u>03 363 5400</u> Date of submission: <u>16-Oct-12</u> Inspection Date: <u>18-Jan-12</u> Revision: <u>Final</u> Is there a full report with this summary? <u>Yes</u>	
---	--	--	--

Site Site slope: <u>flat</u> Soil type: _____ Site Class (to NZS1170.5): <u>D</u> Proximity to waterway (m, if <100m): _____ Proximity to cliff top (m, if <100m): _____ Proximity to cliff base (m, if <100m): _____	Max retaining height (m): _____ Soil Profile (if available): _____ If Ground improvement on site, describe: _____ Approx site elevation (m): <u>20.00</u>
---	--

Building No. of storeys above ground: <u>1</u> Ground floor split? <u>no</u> Storeys below ground: <u>0</u> Foundation type: _____ Building height (m): <u>5.20</u> Floor footprint area (approx): <u>160</u> Age of Building (years): <u>35</u> Strengthening present? <u>no</u> Use (ground floor): <u>public</u> Use (upper floors): _____ Use notes (if required): _____ Importance level (to NZS1170.5): <u>IL2</u>	single storey = 1 Ground floor elevation (Absolute) (m): _____ Ground floor elevation above ground (m): _____ If Foundation type is other, describe: <u>Perimeter footing, concrete piles to timber subfloor</u> height from ground to level of uppermost seismic mass (for IEP only) (m): _____ Date of design: <u>1976-1992</u> If so, when (year)? _____ And what load level (% <sub>g</sub> )? _____ Brief strengthening description: _____
--	---

Gravity Structure Gravity System: <u>load bearing walls</u> Roof: <u>timber framed</u> Floors: <u>timber</u> Beams: <u>none</u> Columns: _____ Walls: _____	rafter type, purlin type and cladding: <u>timber rafters, profiled steel roof</u> joist depth and spacing (mm): _____ overall depth x width (mm x mm): _____
---	--

Lateral load resisting structure Lateral system along: <u>lightweight timber framed walls</u> Ductility assumed, $\mu$ : <u>2.00</u> Period along: <u>0.20</u> Total deflection (ULS) (mm): _____ maximum interstorey deflection (ULS) (mm): _____ Lateral system across: <u>lightweight timber framed walls</u> Ductility assumed, $\mu$ : <u>2.00</u> Period across: <u>0.20</u> Total deflection (ULS) (mm): _____ maximum interstorey deflection (ULS) (mm): _____	Note: Define along and across in detailed report! note typical wall length (m): <u>3</u> estimate or calculation? <u>calculated</u> estimate or calculation? _____ estimate or calculation? _____ note typical wall length (m): <u>3</u> estimate or calculation? <u>calculated</u> estimate or calculation? _____ estimate or calculation? _____
--	---

Separations: north (mm): _____ east (mm): _____ south (mm): _____ west (mm): _____	leave blank if not relevant
--	-----------------------------

Non-structural elements Stairs: _____ Wall cladding: <u>other light</u> Roof cladding: <u>Metal</u> Glazing: <u>aluminium frames</u> Ceilings: <u>fibrous plaster, fixed</u> Services (list): _____	describe: _____ describe: _____
---	------------------------------------

Available documentation Architectural: _____ Structural: _____ Mechanical: _____ Electrical: _____ Geotech report: _____	original designer name/date: _____ original designer name/date: _____ original designer name/date: _____ original designer name/date: _____ original designer name/date: _____
---	--

Damage Site performance: _____ Settlement: _____ Differential settlement: _____ Liquefaction: _____ Lateral Spread: _____ Differential lateral spread: _____ Ground cracks: _____ Damage to area: _____	Describe damage: _____ notes (if applicable): _____
---	--

Building: Current Placard Status: <u>green</u> Along Damage ratio: _____ Describe (summary): _____ Across Damage ratio: <u>#DIV/0!</u> Describe (summary): _____ Diaphragms Damage?: <u>no</u> Describe: _____ CSWs: Damage?: <u>no</u> Describe: _____ Pounding: Damage?: <u>no</u> Describe: _____ Non-structural: Damage?: <u>no</u> Describe: _____	$Damage\_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
--	--

Recommendations Level of repair/strengthening required: <u>significant structural and strengthening</u> Building Consent required: <u>yes</u> Interim occupancy recommendations: <u>full occupancy</u> Along Assessed %NBS before: _____ Assessed %NBS after: <u>63%</u> Across Assessed %NBS before: _____ Assessed %NBS after: <u>46%</u>	Describe: <u>Strengthening works recommended</u> Describe: _____ Describe: _____ If IEP not used, please detail assessment methodology: <u>Quantitative seismic assessment</u>
--	---

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.																																					
Period of design of building (from above): <u>1976-1992</u> Seismic Zone, if designed between 1965 and 1992: _____	h <sub>s</sub> from above: _____ not required for this age of building: _____ not required for this age of building: _____																																				
Period (from above): _____ (%NBS) <sub>nom</sub> from Fig 3.3: _____	along: <u>0.2</u> across: <u>0.2</u>																																				
Note 1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0 Note 2: for RC buildings designed between 1976-1984, use 1.2 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)	along: <u>1.00</u> across: <u>1.0</u>																																				
Final (%NBS) <sub>nom</sub> : _____	along: <u>0%</u> across: <u>0%</u>																																				
2.2 Near Fault Scaling Factor Near Fault scaling factor, from NZS1170.5, cl 3.1.6: _____ Near Fault scaling factor (1/N(T,D), Factor A): _____	along: <u>1.00</u> across: <u>1</u>																																				
2.3 Hazard Scaling Factor Hazard factor Z for site from AS1170.5, Table 3.3: _____ Z <sub>1%</sub> , from NZS4203:1992: _____ Hazard scaling factor, Factor B: _____	along: _____ across: <u>#DIV/0!</u>																																				
2.4 Return Period Scaling Factor Building Importance level (from above): _____ Return Period Scaling factor from Table 3.1, Factor C: _____	along: _____ across: _____																																				
2.5 Ductility Scaling Factor Assessed ductility (less than max in Table 3.2): _____ Ductility scaling factor = 1 from 1976 onwards; or = $\mu$ , if pre-1976, from Table 3.3: _____ Ductility Scaling Factor, Factor D: _____	along: <u>1.00</u> across: <u>1.00</u> along: <u>1.00</u> across: <u>1.00</u>																																				
2.6 Structural Performance Scaling Factor: Sp: _____ Structural Performance Scaling Factor E: _____	along: <u>1.000</u> across: <u>1.000</u> along: <u>1</u> across: <u>1</u>																																				
2.7 Baseline %NBS, (NBS) <sub>b</sub> = (%NBS) <sub>nom</sub> x A x B x C x D x E Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)	%NBS <sub>b</sub> : <u>#DIV/0!</u> %NBS <sub>b</sub> : <u>#DIV/0!</u>																																				
3.1 Plan Irregularity, factor A: _____ 3.2 Vertical irregularity, Factor B: _____ 3.3 Short columns, Factor C: _____ 3.4 Pounding potential Pounding effect D1, from Table to right: <u>1.0</u> Height Difference effect D2, from Table to right: <u>1.0</u> Therefore, Factor D: <u>1</u> 3.5 Site Characteristics: _____	<table border="1"> <tr> <th colspan="4">Table for selection of D1</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; .005H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Alignment of floors within 20% of H</td> <td><b>0.7</b></td> <td><b>0.8</b></td> <td><b>1</b></td> </tr> <tr> <td>Alignment of floors not within 20% of H</td> <td><b>0.4</b></td> <td><b>0.7</b></td> <td><b>0.8</b></td> </tr> </table> <table border="1"> <tr> <th colspan="4">Table for Selection of D2</th> </tr> <tr> <td>Separation</td> <td>Severe 0 &lt; sep &lt; .005H</td> <td>Significant .005 &lt; sep &lt; .01H</td> <td>Insignificant/none Sep &gt; .01H</td> </tr> <tr> <td>Height difference &gt; 4 storeys</td> <td>0.4</td> <td>0.7</td> <td>1</td> </tr> <tr> <td>Height difference 2 to 4 storeys</td> <td>0.7</td> <td>0.9</td> <td>1</td> </tr> <tr> <td>Height difference &lt; 2 storeys</td> <td>1</td> <td>1</td> <td>1</td> </tr> </table>	Table for selection of D1				Separation	Severe 0 < sep < .005H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Alignment of floors within 20% of H	<b>0.7</b>	<b>0.8</b>	<b>1</b>	Alignment of floors not within 20% of H	<b>0.4</b>	<b>0.7</b>	<b>0.8</b>	Table for Selection of D2				Separation	Severe 0 < sep < .005H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H	Height difference > 4 storeys	0.4	0.7	1	Height difference 2 to 4 storeys	0.7	0.9	1	Height difference < 2 storeys	1	1	1
Table for selection of D1																																					
Separation	Severe 0 < sep < .005H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Alignment of floors within 20% of H	<b>0.7</b>	<b>0.8</b>	<b>1</b>																																		
Alignment of floors not within 20% of H	<b>0.4</b>	<b>0.7</b>	<b>0.8</b>																																		
Table for Selection of D2																																					
Separation	Severe 0 < sep < .005H	Significant .005 < sep < .01H	Insignificant/none Sep > .01H																																		
Height difference > 4 storeys	0.4	0.7	1																																		
Height difference 2 to 4 storeys	0.7	0.9	1																																		
Height difference < 2 storeys	1	1	1																																		
3.6 Other factors, Factor F For ≤ 3 storeys, max value = 2.5, otherwise max value = 1.5, no minimum Rationale for choice of F factor, if not 1: _____ Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6) List any: _____ Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses	Along: _____ Across: _____																																				
3.7 Overall Performance Achievement ratio (PAR) PAR x (%NBS) <sub>b</sub> : _____ 4.3 PAR x (%NBS) <sub>b</sub> : _____ 4.4 Percentage New Building Standard (%NBS), (before): _____	along: <u>0.00</u> across: <u>0.00</u> along: <u>#DIV/0!</u> across: <u>#DIV/0!</u> along: <u>#DIV/0!</u> across: <u>#DIV/0!</u>																																				

