

CHRISTCHURCH CITY COUNCIL

Linwood Resource Centre – Toy Library
322 Linwood Avenue, Linwood
BU 0822-016



QUALITATIVE ASSESSMENT REPORT

- Rev 0
- 01 June 2012



CHRISTCHURCH CITY COUNCIL
Linwood Resource Centre – Toy Library
322 Linwood Avenue, Linwood
BU 0822-016

QUALITATIVE ASSESSMENT REPORT

- Rev 0
- 01 June 2012

Sinclair Knight Merz
142 Sherborne Street
Saint Albans
PO Box 21011, Edgeware
Christchurch, New Zealand
Tel: +64 3 940 4900
Fax: +64 3 940 4901
Web: www.skmconsulting.com

COPYRIGHT: The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

LIMITATION: This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.

Contents

1. Executive Summary	1
1.1. Background	1
1.2. Key Damage Observed	2
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
2. Introduction	3
3. Compliance	4
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
4. Earthquake Resistance Standards	8
5. Building Details	10
5.1. Building Description	10
5.2. Gravity Load Resisting System	10
5.3. Seismic Load Resisting System	10
5.4. Geotechnical Conditions	10
6. Damage Summary and Remediation	11
6.1. Damage Summary	11
6.2. Remediation Recommendations	11
7. Initial Seismic Evaluation	12
7.1. The Initial Evaluation Procedure Process	12
7.2. Design Criteria and Limitations	14
7.3. Survey	14
7.4. Critical Structural Weaknesses	14
7.5. Qualitative Assessment Results	14
8. Further Investigation	16
9. Conclusion	17
10. Limitation Statement	18
11. Appendix 1 – Photos	19
12. Appendix 2 – IEP Report	20
13. Appendix 3 – CERA Standardised Report Form	27
14. Appendix 4 – Geotechnical Desk Study	29

Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	12/4/2012	TW Robertson	NM Calvert	12/4/2012	Draft for Client Approval
0	01/06/2012	NM Calvert	NM Calvert	01/06/2012	Final

Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	CCC
0	1	1	CCC

Printed:	1 June 2012
Last saved:	1 June 2012 04:34 PM
File name:	D:\Documents and Settings\scastrillo\My Documents\Organice\scastrillo\http\dmca.skmconsulting.com\80\sites\ZB01276\DmcaConsult\ZB01276.02.BU_0822\Deliverables\ZB01276.05_CCC_BU_0822_016_EQ2_Qualitative Assmt_0.docx
Author:	Kimberley Wylie
Project manager:	Nick Calvert
Name of organisation:	Christchurch City Council
Name of project:	Christchurch City Council Structures Panel
Name of document:	CCC - BU 0822-016 – Qualitative Assessment
Document version:	0
Project number:	ZB01276.05

1. Executive Summary

1.1. Background

A Qualitative Assessment was carried out on building CCC-BU-0822-016 located at 322 Linwood Avenue, Linwood. This building is a single story timber framed garage that is used as a toy library. An aerial photograph illustrating the buildings location is shown below in Figure 1. Detailed descriptions outlining the buildings age and construction type are given in Section 5 of this report.



■ Figure 1 Aerial Photograph of Building CCC-BU-0822-016 Located at 322 Linwood Ave

The qualitative assessment broadly includes a summary of the buildings damage as well as an initial assessment of the current Seismic Capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and our visual inspection carried out on the 6 March 2012.

SINCLAIR KNIGHT MERZ

1.2. Key Damage Observed

No external damage was noted

1.3. Critical Structural Weaknesses

No critical structural weaknesses for the building were observed during our visual inspection.

1.4. Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the buildings original capacity has been assessed to be in the order of 100%NBS. No damage observed during our site investigation which was an external inspection only. Due to this the post earthquake capacity is also in the order of 100%NBS.

As noted above our analysis indicates that the current seismic capacity of the building is over 100% NBS and therefore is not a potentially earthquake prone building.

1.5. Recommendations

It is recommended that:

- a) No placard was displayed on the building however we recommend that the current placard status of the building be Green 1.
- b) We consider that barriers around the building are not necessary.

2. Introduction

Sinclair Knight Merz was engaged by the Christchurch City Council to prepare a qualitative assessment report for building CCC-BU-0822-016 located at 322 Linwood Avenue, Linwood following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The Qualitative Assessment uses the methodology recommended in the Engineering Advisory Group document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury” (part 2 revision 5 dated 19/07/2011 and part 3 draft revision dated 13/12/2011). The qualitative assessment includes a summary of the building damage as well as an initial assessment of the likely current Seismic Capacity compared with current seismic code requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in Section 7.2

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3¹.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure have been carried out. Partial Architectural drawings were made available detailing the mezzanine area. However these drawings show no structural details and have not been considered in our evaluation of the building. The buildings description outlined in Section 5 is based on our visual inspection.

¹ <http://www.dbh.govt.nz/seismicity-info>
SINCLAIR KNIGHT MERZ

3. Compliance

This section contains a summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

3.1. Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses
- The extent of any earthquake damage

3.2. Building Act

Several sections of the Building Act are relevant when considering structural requirements:

3.2.1. Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

3.2.2. Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’. Regarding seismic capacity ‘as near as reasonably practicable’ has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

3.2.3. Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

3.2.4. Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

3.2.5. Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

3.2.6. Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

3.3. Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 34%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

3.4. Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

4. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of 'normal' importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).

■ **Table 1: %NBS compared to relative risk of failure**

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

5. Building Details

5.1. Building Description

Building CCC-BU-0822-016 is a single storey 'Ideal' garage that is used as a toy library. It is constructed from timber framing and is externally clad with light weight profiled steel cladding. The ground floor is a concrete slab on grade with concrete strip footings.

5.2. Gravity Load Resisting System

Our evaluation was based on our site investigation conducted on the 26 March 2012 and the Ideal structural specification dated 1997.

Building CCC-BU-0822-016 is a single story garage. The roof structure consists of timber purlins and roof trusses which are supported on the timber framed walls. The ground floor is a concrete slab on grade with concrete strip footings. It is assumed that this structure was constructed sometime after 1997.

5.3. Seismic Load Resisting System

For the lateral analysis of this building the 'across direction' has been taken as east-west whereas the 'along direction' has been taken as north-south.

Lateral loads acting across and along the building will be resisted by steel strap bracing.

5.4. Geotechnical Conditions

A geotechnical desktop study was carried out for this site. The main conclusions from this report are:

- The site has been assessed as NZS1170.5 Class D (deep or soft soil) from adjacent borehole logs.
- It is expected that the allowable bearing capacity of a shallow pad footing on this site will be in the region of 200 kPa. We estimate a conservative ultimate bearing capacity to be in the order of 400 kPa. However, these may be revised by a site specific investigation.
- Liquefaction risk is low at this site.

Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed. If any excavations are required on the site further investigation of the potential for contamination should be undertaken. The full geotechnical desktop study can be found in Appendix 4 – Geotechnical Desk Study

6. Damage Summary and Remediation

SKM undertook inspections on the 26 March 2012 however we were unable to gain access to the inside of the building and as a result our inspection is an external inspection only. The following was observed during the time of inspection:

6.1. Damage Summary

- 1) No external damage was noted.
- 2) No visual evidence of settlement was noted at this site. Therefore a level survey is not required at this stage of assessment.

6.2. Remediation Recommendations

No remedial works is required at this stage. An internal inspection of the building can be carried out if requested by the Christchurch City Council.

7. Initial Seismic Evaluation

7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings².

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 2. The building grade is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. A building is earthquake prone for the purposes of this Act if, having regard to its condition and to the ground on which it is built, and because of its construction, the building:-

- a) will have its ultimate capacity exceeded in a moderate earthquake (as defined in the regulations); and
- b) would be likely to collapse causing:-
 - i. injury or death to persons in the building or to persons on any other property; or
 - ii. damage to any other property.

A moderate earthquake is defined as ‘in relation to a building, an earthquake that would generate shaking at the site of the building that is of the same duration as, but that is one-third as strong as, the earthquake shaking (determined by normal measures of acceleration, velocity and displacement) that would be used to design a new building at the site.’

An earthquake prone building will have an increased risk that its strength will be exceeded due to earthquake actions of approximately 10 times (or more) than that of a building having a capacity in excess of 100% NBS (refer Table 1)³. Buildings in Christchurch City that are identified as being earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone⁴.

² <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

³ NZSEE June 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-13

⁴ <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

Table 2: IEP Risk classifications

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without collapse or other forms of failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building⁵. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration.

The NZ Building Code describes that the relevant codes for determining %NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard
- NZS 3604:2011 Timber Framed Buildings

⁵ NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9
 SINCLAIR KNIGHT MERZ

7.2. Design Criteria and Limitations

Following our inspection on the 26 March 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and inspection findings of the building. Please note no intrusive or internal investigations were undertaken.

The design criteria used to undertake the assessment include:

- Standard design assumptions for typical office buildings as described in AS/NZS1170.0:2002
 - 50 year design life, which is the default NZ Building Code design life.
 - Structure importance level 2. This level of importance is described as ‘normal’ with medium or considerable consequence of failure.
- Ductility level of 1, based on our assessment and code requirements at the time of design.
- Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011

This IEP was based on our visual inspection of the building. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.

The IEP does not involve a detailed analysis or an element by element code compliance check.

7.3. Survey

There was no visible settlement of the structure, nor was there any significant ground movement issues around the building. The building is adjacent to land which is zoned TC2 under the CERA Residential Technical Categories Map. The combination of these factors means that we do not recommend that any survey be undertaken at this point.

7.4. Critical Structural Weaknesses

No critical structural weaknesses for the building were observed during our visual inspection.

7.5. Qualitative Assessment Results

The building has had its seismic capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity is expressed as a percentage of new building standard (%NBS) and is in the order of that shown below in Table 3. The capacity is subject to confirmation by a quantitative analysis.

SINCLAIR KNIGHT MERZ

Table 3: Qualitative Assessment Summary

<u>Item</u>	<u>%NBS</u>
Buildings likely Seismic Capacity	≈100

Our qualitative assessment found that the building is likely to be classed as a ‘Low Risk Building’ (capacity between greater than 67% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Reports.

8. Further Investigation

No further investigation is required at this stage, however an internal inspection of the building can be carried out to record damage and propose repairs methodology if requested by the Christchurch City Council.

9. Conclusion

A qualitative assessment was carried out on building 16 located at 180 Smith Street, Woolston. The building has been assessed to have a seismic capacity greater than 100% NBS and is likely to be classified as a 'Low Risk Building' (seismic capacity above 67% NBS).

No further investigation of this building is required at this stage.

It is recommended that:

- a) No placard was displayed on the building however we recommend that the current placard status of the building be Green 1.
- b) We consider that barriers around the building are not necessary.

10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

11. Appendix 1 – Photos



PHOTO 1: Eastern Elevation



PHOTO 2: North Elevation



Christchurch City Council
Linwood Resource Centre – Toy Library
322 Linwood Avenue, Linwood
CCC BU 0822-016
Qualitative Assessment Report
01 June 2012


12. Appendix 2 – IEP Report

SINCLAIR KNIGHT MERZ


Building Name:	Linwood Service Centre & Library Support - Building 16	Ref.	ZB01276.05
Location:	180 Smith Street, Woolston, Christchurch	By	KW
		Date	21/03/2012

Step 1 - General Information

1.1 Photos (attach sufficient to describe building)



1.2 Sketch of building plan



1.3 List relevant features

Building 16 is a single story ideal garage that is being used as a toy library. It is constructed from timber framing and is clad in a light weight profiled steel cladding. It has concrete foundations and a concrete floor slab on grade.

1.4 Note information sources

Tick as appropriate

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Table IEP-2 Initial Evaluation Procedure – Step 2

(Refer Table IEP - 1 for Step 1; Table IEP - 3 for Step 3, Table IEP - 4 for Steps 4, 5 and 6)



Page 2

Building Name:	Linwood Service Centre & Library Support - Building 16	Ref.	ZB01276.05
Location:	180 Smith Street, Woolston, Christchurch	By	KW
Direction Considered:	Longitudinal & Transverse	Date	21/03/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

Step 2 - Determination of (%NBS)b

2.1 Determine nominal (%NBS) = (%NBS)nom

Pre 1935
 1935-1965
 1965-1976 Seismic Zone; A
 B
 C
 1976-1992 Seismic Zone; A
 B
 C
 1992-2004

<input type="radio"/>
See also notes 1, 3
<input type="radio"/>
<input type="radio"/>
<input type="radio"/>
<input type="radio"/>
See also note 2
<input type="radio"/>
<input type="radio"/>
<input type="radio"/>
<input checked="" type="radio"/>

b) Soil Type

From NZS1170.5:2004, Cl 3.1.3
 A or B Rock
 C Shallow Soil
 D Soft Soil
 E Very Soft Soil

<input type="radio"/>
<input type="radio"/>
<input checked="" type="radio"/>
<input type="radio"/>

From NZS4203:1992, Cl 4.6.2.2
 (for 1992 to 2004 only and only if known)
 a) Rigid
 b) Intermediate

<input checked="" type="radio"/>
N-A
<input type="radio"/>

c) Estimate Period, T

building Ht = 4 meters

Can use following:

$T = 0.09h_n^{0.75}$ for moment-resisting concrete frames
 $T = 0.14h_n^{0.75}$ for moment-resisting steel frames
 $T = 0.08h_n^{0.75}$ for eccentrically braced steel frames
 $T = 0.06h_n^{0.75}$ for all other frame structures
 $T = 0.09h_n^{0.75}/A_c^{0.5}$ for concrete shear walls
 $T \leq 0.4\text{sec}$ for masonry shear walls

Longitudinal	Transverse
Ac =	m2
<input type="radio"/> MRCF	<input type="radio"/> MRCF
<input type="radio"/> MRSF	<input type="radio"/> MRSF
<input type="radio"/> EBSF	<input type="radio"/> EBSF
<input checked="" type="radio"/> Others	<input checked="" type="radio"/> Others
<input type="radio"/> CSW	<input type="radio"/> CSW
<input type="radio"/> MSW	<input type="radio"/> MSW

Where h_n = height in m from the base of the structure to the uppermost seismic weight or mass.
 $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$
 A_i = cross-sectional shear area of shear wall i in the first storey of the building, in m2
 L_{wi} = length of shear wall i in the first storey in the direction parallel to the applied forces, in m
 with the restriction that L_{wi}/h_n shall not exceed 0.9

Longitudinal	Transverse
0.2	0.2

Seconds

d) (%NBS)nom determined from Figure 3.3

Note 1: For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25.

For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B

Note 2: For reinforced concrete buildings designed between 1976 -1984 (%NBS)nom by 1.2

Note 3: For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1.

Factor
 No ☐ 1

No ☐ 1

No ☐ 1

No ☐ 1

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Continued over page

Building Name: Linwood Service Centre & Library Support - Building 16
 Location: 180 Smith Street, Woolston, Christchurch
 Direction Considered: **Longitudinal & Transverse**
 (Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)

Ref. ZB01276.05
 By KW
 Date 21/03/2012

2.2 Near Fault Scaling Factor, Factor A

If $T < 1.5\text{sec}$, Factor A = 1

a) Near Fault Factor, $N(T,D)$

(from NZS1170.5:2004, Cl 3.1.6)

1

b) Near Fault Scaling Factor

$$= 1/N(T,D)$$

Factor A	1.00
----------	------

2.3 Hazard Scaling Factor, Factor B

Select Location Christchurch

a) Hazard Factor, Z , for site

(from NZS1170.5:2004, Table 3.3)

$$Z = 0.3$$

$$Z_{1992} = 0.8$$

Auckland 0.6 Palm Nth 1.2

b) Hazard Scaling Factor

For pre 1992 = $1/Z$

For 1992 onwards = Z_{1992}/Z

#

(Where Z_{1992} is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Type Z 1992 above Wellington 1.2 Dunedin 0.6
 Christchurch 0.8 Hamilton 0.67

Factor B	2.67
----------	------

2.4 Return Period Scaling Factor, Factor C

a) Building Importance Level

(from NZS1170.0:2004, Table 3.1 and 3.2)

2

b) Return Period Scaling Factor from accompanying Table 3.1

Factor C	1.00
----------	------

2.5 Ductility Scaling Factor, D

a) Assessed Ductility of Existing Structure, μ

(shall be less than maximum given in accompanying Table 3.2)

Longitudinal 1

μ Maximum = 6

Transverse 1

μ Maximum = 6

b) Ductility Scaling Factor

For pre 1976

$$= k_{\mu}$$

For 1976 onwards

$$= 1$$

(where k_{μ} is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.00
Transverse	Factor D	1.00

2.6 Structural Performance Scaling Factor, Factor E

Select Material of Lateral Load Resisting System

Longitudinal

Transverse

Timber	▼
Timber	▼

a) Structural Performance Factor, S_p

from accompanying Figure 3.4

Longitudinal

S_p

1.00

Transverse

S_p

1.00

b) Structural Performance Scaling Factor

Longitudinal

$1/S_p$

Factor E

1.00

Transverse

$1/S_p$

Factor E

1.00

2.7 Baseline %NBS for Building, $(\%NBS)_b$

(equals $(\%NBS)_{nom} \times A \times B \times C \times D \times E$)

Longitudinal	59.2	$(\%NBS)_b$
Transverse	59.2	$(\%NBS)_b$

Table IEP-3 Initial Evaluation Procedure – Step 3

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)



Page 4

Building Name: <u>Linwood Service Centre & Library Support - Building 16</u>	Ref. <u>ZB01276.05</u>
Location: <u>180 Smith Street, Woolston, Christchurch</u>	By <u>KW</u>
Direction Considered: a) Longitudinal	Date <u>21/03/2012</u>
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

Critical Structural Weakness
Effect on Structural Performance

(Choose a value - Do not interpolate)

Building
Score
3.1 Plan Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

 Factor A
3.2 Vertical Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

 Factor B
3.3 Short Columns

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

 Factor C
3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

		Factor D1 <input type="text" value="1"/>		
		Severe	Significant	Insignificant
Table for Selection of Factor D1		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	Separation	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

		Factor D2 <input type="text" value="1"/>		
		Severe	Significant	Insignificant
Table for Selection of Factor D2		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	Separation	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys		<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys		<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

 Factor D

(Set D = lesser of D1 and D2 or..

set D = 1.0 if no prospect of pounding)

3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

 Factor E
3.6 Other Factors

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

 Factor F

Record rationale for choice of Factor F:

Light weight small timber structure

3.7 Performance Achievement Ratio (PAR)
 (equals A x B x C x D x E x F)

 PAR

Building Name:	Building Name:	Ref.	ZB01276.05
Location:	Location:	By	KW
Direction Considered:	b) Transverse	Date	21/03/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

Critical Structural Weakness
Effect on Structural Performance
 (Choose a value - Do not interpolate)

Building Score
3.1 Plan Irregularity

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A **1****3.2 Vertical Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B **1****3.3 Short Columns**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C **1****3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings (eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1 **1**

Table for Selection of Factor D1		Severe	Significant	Insignificant
Separation		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height		<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2 **1**

Table for Selection of Factor D2		Severe	Significant	Insignificant
Separation		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys		<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys		<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D **1**
 (Set D = lesser of D1 and D2 or..
 set D = 1.0 if no prospect of pounding)
3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E **1****3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F **2.5**

Record rationale for choice of Factor F:

Light weight small timber structure

3.7 Performance Achievement Ratio (PAR)
 (equals A x B x C x D x E x F)
PAR **2.5**

Building Name:	Linwood Service Centre & Library Support - Building 16	Ref.	ZB01276.05
Location:	180 Smith Street, Woolston, Christchurch	By	KW
Direction Considered:	Longitudinal & Transverse	Date	21/03/2012

(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline (%NBS)_b (from Table IEP - 1)	59	59
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	2.50	2.50
4.3 PAR x Baseline (%NBS)_b	148	148
4.4 Percentage New Building Standard (%NBS) (Use lower of two values from Step 4.3)		148

Step 5 - Potentially Earthquake Prone?

(Mark as appropriate)

%NBS ≤ 33

NO

Step 6 - Potentially Earthquake Risk?

%NBS < 67

NO

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade

A+

Evaluation Confirmed by



Signature

Trevor Robertson

Name

28892

CPEng. No

Relationship between Seismic Grade and % NBS :

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20



Christchurch City Council
Linwood Resource Centre – Toy Library
322 Linwood Avenue, Linwood
CCC BU 0822-016
Qualitative Assessment Report
01 June 2012

13. Appendix 3 – CERA Standardised Report Form

SINCLAIR KNIGHT MERZ

Detailed Engineering Evaluation Summary Data

V1.11

Location

Building Name:	CCC_0822_BLDG_016	Unit No:	180	Street	Smith Street
Building Address:	Building 16				
Legal Description:					
		Degrees	Min	Sec	
GPS south:					
GPS east:					
Building Unique Identifier (CCC):					

Reviewer:	Trevor Robertson
CPEng No:	28892
Company:	SKM
Company project number:	ZB01276.03
Company phone number:	09 940 4900
Date of submission:	
Inspection Date:	26/03/2012
Revision:	A
Is there a full report with this summary?	yes

Site

Site slope:	flat
Soil type:	
Site Class (to NZS1170.5):	D
Proximity to waterway (m, if <100m):	
Proximity to clifftop (m, if < 100m):	
Proximity to cliff base (m,if <100m):	

Max retaining height (m):	
Soil Profile (if available):	
If Ground improvement on site, describe:	
Approx site elevation (m):	

Building

No. of storeys above ground:	1
Ground floor split?	no
Storeys below ground:	0
Foundation type:	strip footings
Building height (m):	4.00
Floor footprint area (approx):	
Age of Building (years):	15
Strengthening present?	no
Use (ground floor):	public
Use (upper floors):	public
Use notes (if required):	Toy Library
Importance level (to NZS1170.5):	IL2

single storey = 1	Ground floor elevation (Absolute) (m):	0.00
	Ground floor elevation above ground (m):	0.00
	if Foundation type is other, describe:	
	height from ground to level of uppermost seismic mass (for IEP only) (m):	4.00
	Date of design:	1992-2004

Gravity Structure

Gravity System:	frame system
Roof:	timber truss
Floors:	concrete flat slab
Beams:	none
Columns:	
Walls:	

truss depth, purlin type and cladding:	Truss depth -600 DP (assumed), light weight profiled steel cladding
slab thickness (mm):	125
overall depth x width (mm x mm)	

Walls are load bearing timber frame

Lateral load resisting structure

Lateral system along:	lightweight timber framed walls
Ductility assumed, μ :	1.00
Period along:	0.20
Total deflection (ULS) (mm):	20
maximum interstorey deflection (ULS) (mm):	0
Lateral system across:	lightweight timber framed walls
Ductility assumed, μ :	1.00
Period across:	0.20
Total deflection (ULS) (mm):	20
maximum interstorey deflection (ULS) (mm):	0

Note: Define along and across in detailed report!

note typical wall length (m)	
estimate or calculation?	estimated
estimate or calculation?	estimated
estimate or calculation?	estimated
note typical wall length (m)	
estimate or calculation?	estimated
estimate or calculation?	estimated
estimate or calculation?	estimated

Separations:

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

Non-structural elements

Stairs:	
Wall cladding:	profiled metal
Roof Cladding:	Metal
Glazing:	aluminium frames
Ceilings:	plaster, fixed
Services(list):	lighting

describe:	Light weight profiled steel cladding
describe:	Light weight profiled steel cladding

Available documentation

Architectural:	none
Structural:	none
Mechanical:	none
Electrical:	none
Geotech report:	none

original designer name/date:	
original designer name/date:	
original designer name/date:	
original designer name/date:	
original designer name/date:	

Damage

Site:
(refer DEE Table 4-2)

Site performance:	1
Settlement:	none observed
Differential settlement:	none observed
Liquefaction:	none apparent
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	none apparent
Damage to area:	none apparent

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

Building:

Current Placard Status:	
-------------------------	--

Along	Damage ratio:	0%
	Describe (summary):	

Describe how damage ratio arrived at: no damage observed

Across	Damage ratio:	0%
	Describe (summary):	

$$Damage_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$$

Diaphragms	Damage?:	no
------------	----------	----

Describe:

CSWs:	Damage?:	no
-------	----------	----

Describe:

Pounding:	Damage?:	no
-----------	----------	----

Describe:

Non-structural:	Damage?:	yes
-----------------	----------	-----

Describe:

Recommendations

Level of repair/strengthening required:	none
Building Consent required:	yes
Interim occupancy recommendations:	full occupancy

Describe:	
Describe:	
Describe:	

Along	Assessed %NBS before:	100%	%NBS from IEP
	Assessed %NBS after:	100%	
Across	Assessed %NBS before:	100%	%NBS from IEP
	Assessed %NBS after:	100%	

If IEP not used, please detail assessment methodology: Qualitative Assesment carried out includes NZSEE IEP (refer to SKM report)

Official Use only:

Accepted By:	
Date:	



Christchurch City Council
Linwood Resource Centre – Toy Library
322 Linwood Avenue, Linwood
CCC BU 0822-016
Qualitative Assessment Report
01 June 2012

14. Appendix 4 – Geotechnical Desk Study

SINCLAIR KNIGHT MERZ



Christchurch City Council - Structural Engineering Service

Geotechnical Desk Study

SKM project number	ZB01276
SKM project site number	002 to 005 inclusive
Address	Linwood Resource Centre and Library, 180 Smith Street and 332 Linwood Ave
Report date	26 March 2012
Author	Ross Roberts / Ananth Balachandra
Reviewer	Leah Bateman
Approved for issue	Yes

1. Introduction

This letter outlines the geotechnical information that Sinclair Knight Merz (SKM) has been able to source from our database and other sources in relation to the property listed above. We understand that this information will be used as part of an initial qualitative assessment of whether the building can be economically repaired, and will be supplemented by more detailed information and investigations to allow detailed scoping of the repair or rebuild of the building.

2. Scope

This geotechnical desk top study incorporates information sourced from:

- Published geology
- Publically available borehole records
- Liquefaction records
- Aerial photography
- Council files
- A preliminary site walkover

3. Limitations

This report was prepared to address geotechnical issues relating to the specific site in accordance with the scope of works as defined in the contract between SKM and our Client. This report has been prepared on behalf of, and for the exclusive use of, our Client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and our Client. The findings presented in this report should not be applied to another site or another development within the same site without consulting SKM.

The assessment undertaken by SKM was limited to a desktop review of the data described in this report. SKM has not undertaken any subsurface investigations, measurement or testing of materials from the site. In preparing this report, SKM has relied upon, and presumed accurate, any information (or confirmation of the absence thereof) provided by our Client, and from other sources as described in the report. Except as otherwise stated in this report, SKM has not attempted to verify the accuracy or completeness of any such information.



This report should be read in full and no excerpts are to be taken as representative of the findings. It must not be copied in parts, have parts removed, redrawn or otherwise altered without the written consent of SKM.

4. Site location



■ **Figure 1 – Site location (courtesy of LINZ <http://viewers.geospatial.govt.nz>)**

These structures are located on the corner of Linwood Avenue and Smith Street at grid reference 1573957 E, 5179440 N (NZTM).




5. Review of available information

5.1 Geological maps



■ Figure 2 – Regional geological map (Forsyth et al, 2008). Site marked in red.




■ **Figure 3 – Local geological map (Brown et al, 1992). Site marked in red.**

The site is shown to be underlain by Holocene deposits comprising predominantly alluvial sand and silt overbank deposits of the Springston Formation. Immediately to the north west lies an area of Christchurch Formation sand of fixed dunes.



5.2 Liquefaction map



■ Figure 4 – Liquefaction map (Cubrinovski & Taylor, 2011). Site marked in red.

Following the 22 February 2011 event drive through reconnaissance was undertaken from 23 Feb until 1 Mar by M Cubrinovski and M Taylor of Canterbury University. Their findings show no liquefaction at this site.



5.3 Aerial photography



■ **Figure 5 – Aerial photography from 24 Feb 2011 (<http://viewers.geospatial.govt.nz/>)**

Aerial photography shows relatively little damage after the 22 Feb 2011 event. There appears to be a burst water main on Linwood Avenue, and what may be a single source of liquefied material in the tennis courts to the north west of the property. This coincides with a change of geology as identified on the geological maps.

5.4 CERA classification

A review of the LINZ website (<http://viewers.geospatial.govt.nz/>) shows that the site is:


- Zone: Green
- DBH Technical Category: N/A (Urban Non-residential) – adjacent properties are TC2



5.5 Historical land use

Reference to historical documents (eg Appendix A) shows that the site lies immediately south and east of land that was recorded as marshland or swamp in 1856. It is therefore likely that soft or liquefiable ground would be present near the site. Given the relatively low accuracy of these historical documents, it should be considered possible that old swamp deposits are present on the site.

5.6 Existing ground investigation data



- **Figure 6 – Local boreholes from Project Orbit and SKM files**
(<https://canterburyrecovery.projectorbit.com/>)

Where available logs from these investigation locations are attached to this report (Appendix B), and the results are summarised in Appendix C.



5.7 Council property files

The available council records were limited to building consents applied for the demolition of existing garage and shed and reconstruction of a double door garage and other documents relating to the above construction. The Council foundation record identifies top soil or sandy clay to be present to a depth of 0.5 m and medium sand from a depth of 0.5 m to 3.8 m for the site. No ground investigation for depth greater than 3.8 m was found in the council property files. The ground water table was estimated to be between 1.6 m to 3 m. The council record identifies an allowable bearing pressure of 200 kPa for the sand layer with comments stating that the identified allowable bearing pressure is adequate for the proposed buildings.

Drawings for the utility shed showed 500 mm square pad footings at a depth of 1 m. Drawings for the new garage at 180 Smith Street show a 100 mm thick reinforced raft foundation with edge thickening to 150 mm. Piles are shown inconsistently in the record. One drawing identifies 250 mm diameter piles are shown at each corner and at 2 m centres along the edge of the slab (depth not recorded). Another shows 150 mm 'piles' to 400 mm depth at 1.2 m spacing.

The council property files identify possible contamination under the "old work shop area" due to the presence of two tanks containing flammable liquid, which have since been removed.

5.8 Site walkover

An engineer from SKM undertook a site walkover in the week commencing 12 March 2012.

The Linwood Resource Centre and Library were mostly constructed using masonry block with an iron roof, Figure 7 shows the overview of the site. The buildings were both in good condition, with no external evidence of structural damage. The majority of the land on the site was asphalt, which showed no signs of land damage. There was no evidence that liquefaction occurred on the site.

Residents report that the only damage occurred to the footpaths, with paving slabs being displaced, (Figure 8) and that no liquefaction occurred on the site.



■ **Figure 7 Overview of Linwood Services Centre and Library**



■ **Figure 8 Damaged paving slabs at Linwood Resource Centre**



6. Conclusions and recommendations

6.1 Site geology

An interpretation of the most relevant local investigation suggests that the site is underlain by:

Depth range (mBLG)	Soil type
0 - 1	Sensitive fine grained soils (clay or silt)
1 - 8	Very stiff clays and loose to dense clayey sand
8 – 19	Dense sand
19 – 21	Interbedded clay and silt
21 - 23	Dense sand
23 +	Soft to firm clay or silt

6.2 Seismic site subsoil class

The site has been assessed as NZS1170.5 Class D (deep or soft soil) from adjacent borehole logs.

As described in NZS1170, the preferred site classification method is from site periods based on four times the shear wave travel time through material from the surface to the underlying rock. The next preferred methods are from borelogs including measurement of geotechnical properties or by evaluation of site periods from Nakamura ratios or from recorded earthquake motions. Lacking this information, classification may be based on boreholes with descriptors but no geotechnical measurements. The least preferred method is from surface geology and estimates of the depth to underlying rock.

In this case the second preferred method has been used to make the assessment utilising records from sites at least 50 m from the site. It is therefore possible that site specific investigation could revise the site class.

6.3 Building performance

Although detailed records of the existing foundations are not available, the performance to date suggests that they are adequate for their current purpose.

6.4 Ground performance and properties

It is expected that the allowable bearing capacity of a shallow pad footing on this site will be in the region of 200 kPa, as stated in the council records and supported by the findings of the nearby ground investigations. We estimate a conservative ultimate bearing capacity to be in the order of 400 kPa. However, these may be revised by a site specific investigation.

For the purposes of shallow foundation design, the following parameters are recommended for the near surface clayey sand:

- Effective angle of friction = 35 degrees
- Apparent cohesion = 1 kPa
- Unit weight = 18 kPa



Liquefaction risk is low at this site.

6.5 Further investigations

Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed. If any excavations are required on the site further investigation of the potential for contamination should be undertaken.

7. References

Brown LJ, Weeber JH, 1992. Geology of the Christchurch urban area. Scale 1:25,000. Institute of Geological & Nuclear Sciences geological map 1.

Cubrinovski & Taylor, 2011. Liquefaction map summarising preliminary assessment of liquefaction in urban areas following the 2010 Darfield Earthquake.


Forsyth PJ, Barrell DJA, Jongens R, 2008. Geology of the Christchurch area. Institute of Geological & Nuclear Sciences geological map 16.

Land Information New Zealand (LINZ) geospatial viewer (<http://viewers.geospatial.govt.nz/>)

EQC Project Orbit geotechnical viewer (<https://canterburyrecovery.projectorbit.com/>)



Appendix A – Christchurch 1856 land use



The swamps and previous creeks/ivers from 1856 have been overlayed onto a map of Christchurch in 2012



Key

- Previous creeks/ivers
- Existing creeks/ivers
- New creeks/ivers
- Swamp/Marshland



Appendix B – Existing ground investigation logs



**Classification by
Robertson 1986**



Cone No: 100KN 4341
Tip area [cm²]: 10
Sleeve area [cm²]: 150

Location:	LINWOOD	Position:	X: 0.00 m, Y: 0.00 m	Ground level:	0.00	Test no:	CPT-LWD-35
Project ID:		Client:	TONKIN & TAYLOR LTD	Date:	20/05/2011	Scale:	1 : 60
Project:	EQC SITES			Page:	1/1	Fig:	
				File:	CPT-LWD-35.CPT		



**Classification by
Robertson 1986**






Cone No: 100KN 4341
Tip area [cm²]: 10
Sleeve area [cm²]: 150




Location:	LINWOOD	Position:	X: 0.00 m, Y: 0.00 m	Ground level:	0.00	Test no:	CPT-LWD-34
Project ID:		Client:	TONKIN & TAYLOR LTD	Date:	20/05/2011	Scale:	1 : 60
Project:	EQC SITES			Page:	1/1	Fig:	
				File:	CPT-LWD-34.CPT		


Project: Christchurch 2011 Earthquake - EQC Ground Investigations				Page: 1 of 2		CPT-BRY-18			
Test Date: 17-Jun-2011		Location: Bromley		Operator: Opus					
Pre-Drill: 1.2m		Assumed GWL: 2.4mBGL		Located By: Survey GPS					
Position: 2484276.9mE		5741214.3mN		2.39mRL				Coord. System: NZMG & MSL	
Other Tests:				Comments:					



Project: Christchurch 2011 Earthquake - EQC Ground Investigations				Page: 2 of 2		CPT-BRY-18	
Test Date: 17-Jun-2011		Location: Bromley		Operator: Opus			
Pre-Drill: 1.2m		Assumed GWL: 2.4mBGL		Located By: Survey GPS			
Position: 2484276.9mE		5741214.3mN 2.39mRL		Coord. System: NZMG & MSL			
Other Tests:				Comments:			



Project: Christchurch 2011 Earthquake - EQC Ground Investigations			Page: 1 of 1	CPT-LWD-28
Test Date: 19-May-2011	Location: Linwood	Operator: Geotech		
Pre-Drill: 1.2m	Assumed GWL: 2mBGL	Located By: Survey GPS		
Position: 2483547.1mE	5741248.6mN	2.73mRL	Coord. System: NZMG & MSL	
Other Tests:			Comments:	



Borelog for well M35/2111


Gridref: M35:836-414 Accuracy : 4 (1=high, 5=low)

Ground Level Altitude : 3.1 +MSD

Driller : Job Osborne (& Co/Ltd)

Drill Method : Hydraulic/Percussion

Drill Depth : -66.4m Drill Date : 8/12/1944





Appendix C – Geotechnical investigation summary



ID	1	2	3	4	5
Type *	CPT	CPT	CPT	CPT	BH
Ref	LWD-35	LWD-34	BRY-18	LWD-28	M35-2111
Depth (m)	8	11	32	32	66
Distance from site (m)	100	200	375	450	500
Ground water level (mBGL)	4	3	2.5	2	Artesian
Simplified recorded geological profile (depth below ground level to top of stratum, m)	0	N/A	N/A	N/A	
	1			MD	
	2			MD	
	3			MD	
	4			So	
	5			So	
	6			MD	
	7			MD	
	8			MD	
	9			MD	
	10			MD	
	11			D	
	12			D	
	13			D	
	14			D	
	15			D	
	16			D	
	17			D	
	18			D	
	19			F	
	20			F	
	21			D	
	22			D	
	23			St	
	24			St	
	25			St	
Greater depths			Clay to 31 m	Clay to 32 m	

*BH: Borehole, HA: Hand Auger, WW: Water Well, CPT: Cone Penetration Test

Sensitive or organic clay/silt	Clay to silty clay	Clayey silt to silt	Silty sand to silt
Clayey sand	Sand	Gravelly sand or gravel	

VL = very loose, L = loose, MD = medium dense, D = dense, VD = very dense

VS = very soft, So = soft, F = firm, St = stiff, VS = very stiff, H = hard