



Structural Concepts

Detailed Engineering Evaluation Quantitative Report

**Monavale Gatehouse
Fendalton Road, Christchurch**

**Prepared For:
Christchurch City Council**

Ref: 1606
31 July 2013

1606 130731 Monavale Gatehouse DEE Quantitative

55 Dunlop Road, Onekawa, Napier
PO Box 3315, Napier, 4142, New Zealand
P (06) 842 0111 F (06) 842 0113
Info@structuralconcepts.co.nz

www.structuralconcepts.co.nz

MONAVALE GATEHOUSE

FENDALTON ROAD, CHRISTCHURCH

DETAILED ENGINEERING EVALUATION

31 JULY 2013

FOR:

CHRISTCHURCH CITY COUNCIL

Preamble

Scope of Investigation

Building Description

Structural System

Existing Structural Strengthening

Strength

Areas of Structural Vulnerability

Damage Description

Recommended Additional Investigations

Immediate Securing of the Building

Long Term Repair

Elements Not Inspected

Applicability

Appendices

Appendix A Photographs

Appendix B Marked-up Drawing Indicating Damaged Locations

Appendix C New Works and Examples

Appendix D Preliminary Calculations (extract only)

Appendix E LDE Geotechnical Report

Appendix F Level Survey

Appendix G CERA Building Evaluation Form

DETAILED ENGINEERING EVALUATION

31 JULY 2013

FOR:

MONAVALE GATEHOUSE

AT:

FENDALTON ROAD, CHRISTCHURCH

Preamble

This report covers our assessment of the structural condition of the Monavale Gatehouse building at Fendalton Road, Christchurch, following the magnitude 6.3 earthquake on 4 September 2010, 22nd February 2011 and 13th June 2011. Our assessment is based on a visual inspection of the outside and inside where it was deemed to be safe to enter. This was carried out on the June 2011 and July 2011 with other visits since to confirm findings.

This report describes the damage observed, and comments on remedial work options for both temporary securing of the building, and long term repair where appropriate. This report also covers a detailed structural strength assessment and provides some investigation and assumptions that will allow an assessment to be made as to whether to reconstruct or demolish. It does not cover any detailed design or specification of remedial works or temporary securing.

A Detailed Engineering Evaluation procedure (DEE) has recently been developed by CERA to provide consistent, comprehensive and auditable guidelines which help restore confidence in the remaining building stock in Canterbury. We have used these guidelines to form the basis for our detailed engineering evaluation.

The DEE process follows a two step process, firstly a qualitative assessment then a quantitative assessment, if necessary.

The qualitative assessment involves visual review of the structure and its conditions in order to ascertain whether the structure does or does not fall within required capacity limitations without completing any complex analysis.

The quantitative assessment involves analytically calculating the capacity of the structure in terms of the current code requirements i.e. to estimate the percentage of new building strength available (%NBS).

The overall objective of this assessment is to determine if a strengthening solution is required or not. This report covers a qualitative assessment.

More specifically, this report covers:

- Describes the existing building, its construction, and structural system
- Outlines the level of investigation undertaken and where information was obtained
- Summarises earthquake damage caused by the recent Canterbury earthquakes
- Reviews the building's performance in the recent Canterbury earthquakes
- Identifies critical structural weaknesses
- Assesses the building's seismic strength relative to New Building Standard (NBS), commonly referred to as "current code"
- Proposes repair works to reinstate the building as close as practically possible to pre earthquake levels.

2.0 Scope of Investigation

In June 2011 and again in July 2011, and subsequent visits to continually assess damage or movement and verify findings.

We visually inspected the building including:

- The exterior from ground level
- The interior

Existing building plans were not available to be reviewed and therefore were unable been utilized as part of this report.

Preliminary and detailed Geotechnical investigations and reports completed by Land Development and Exploration Ltd have been obtained.

We have reviewed these and included their recommendations into our reinstatement designs.

55 Dunlop Road, Onekawa, Napier
PO Box 3315, Napier, 4142, New Zealand
P (06) 842 0111 F (06) 842 0113
Info@structuralconcepts.co.nz

This report is based on our assessment of the building at the time it was inspected. Photos attached in Appendix A are indicative of the damage and findings. Any subsequent loading by aftershocks, or high winds, may initiate further damage.

3.0 Building Description

General description:

The Monavale Gatehouse is a two-storey unreinforced brick homestead built in 1905. In 1948, a single storey timber add-on was constructed in the North-West corner. There is a single storey brick and timber shed immediately adjacent to the West of the main house.

The Gatehouse is listed as a Category 2 Heritage building in the Christchurch City Plan and Historic Plans Trust. The building was being used as a residential dwelling, but is currently unoccupied due to earthquake damage.

Roof construction:

Clay tiles on timber purlins and rafters with lath and plaster ceiling to undersides.

External Wall construction:

Cavity brick construction with plastered finish to exterior.

Internal Wall construction:

Brick wall construction to part and timber framed walls line with lath and plaster with some hardboard linings.

First Floor construction:

Timber tongue and grooved flooring on timber joists with lath and plaster ceilings under.

Ground Floor construction:

Timber tongue and grooved flooring on timber joists and bearers.

Foundations:

Concrete ring foundation to external walls with concrete piles internally.

Structural System

Gravity Structural System:

The gravity structural system can be described as simple beams supported on walls. Clay tiles sit on battens and rafters transferring their load to brick walls with tongue & grooved flooring laid over timber joists sitting on brickwork.

Lateral Structural System:

The lateral structural system consists of nominal timber diaphragms to roof and first floor transferring loads from face loaded brick walls to in-plane brick walls acting in shear to concrete ring foundations.

5.0 Existing Structural Strengthening

No additional strengthening has been carried out on this structure.

6.0 Strength

The strength of the building has been determined as a % NBS using methodologies provided by NZSEE. A "Preliminary Detailed Assessment", which includes calculations, has been completed as opposed to an IEP ("Initial Evaluation Procedure") as this is deemed more accurate. We have compared the design code level at that time to that of today as an estimate at this time. Our assessments are as follows:

Assessment Parameters:

Before September 2010:

The strength of the building before September 2010 is estimated as

Hazard factor 0.3 (post 19th May 2011) **21% NBS**

On day of inspection:

The strength of the building on the day of inspection is estimated as

Hazard factor 0.3	Across	10% NBS	(estimated only)
	Along	15% NBS	(estimated only)
Single %NBS in current state		10% NBS	(estimated only)

It must be understood that this strength is based on the overall building strength and not individual elements.

Strength of Building after reconstruction is completed:

Hazard factor 0.3	> 67% NBS
-------------------	-----------

7.0 Areas of Structural Vulnerability

The areas of Structural Vulnerability include:

- Brick Chimneys.
- Narrow width brick walls at north wall bay window
- Lack of connection between floor/roof and walls.

8.0 Damage Description

Damage caused by the earthquakes to the Monavale Gatehouse is described below. Refer to Appendix B for marked-up drawings indicating damaged locations.

i. ***Damage to front porch:***

- The upper half of the front brick porch has moved outwards and shifted anti-clockwise.
- A horizontal crack with up to a 70mm offset through one of the porch columns, and cracking (up to 10mm wide) to the porch arches.

ii. ***Damage to exterior brick walls:***

- Cracks to Eastern brick walls. From the interior, the East wall has a lean outwards slightly.
- Significant cracks to Northern brick wall adjacent bay window. There is up to a 10mm offset across the crack to the upper-right of the window. From the interior, the North-West corner has moved West and outwards. This wall continues to move and deteriorate.

- Cracking to South and West walls. Cracks are visible both externally and internally.

iii. Collapse of brick chimneys:

- Both brick chimneys have collapsed off the building.
- The rear chimney has collapsed through the roof of the dining room addition. This room has been deconstructed.
- The gable dormer at the West rear chimney has collapsed with the chimney.

Interior damage:

- General cracking of plaster linings to ground floor walls.
- Significant cracking of plaster linings to ground floor walls adjacent chimneys
- Significant cracking of first floor lath and plaster walls and ceilings. Lath and plaster ceilings have spalled in some locations.

Other damage:

- Lateral spreading of ground to the East towards the Avon River. Loss of several roof tiles.
- Settlement to local areas particularly the single storey dining area.

Foundations:

- Minor cracking to exterior strip foundation supporting brickwork.
- Settlement and major cracking to dining room addition foundations.

Floor:

- Settlement of the building has caused unevenness in the ground floor.

Building Settlement:

- The level survey suggests that the building has settled evenly over its width by up to 150mm across the total length.

9.0 Recommended Additional Investigations

We recommend that the following further investigations be carried out. These can be in conjunction with the reconstruction works:

Vertical level survey of North-West and North walls.

10.0 Immediate Securing of the Building

The following works were required by Structex to mitigate immediate hazards, temporarily secure the building, and provide weather tightness: these have been completed.

- Remove loose chimney bricks to remove any fall hazard. Plywood line chimney roof openings and flash to provide weather-tightness.
- Repair tile roof locally where required to provide weather-tightness. Rrefix loose tiles to remove any fall hazard.
- Photograph and document timber dining extension, then take down to floor level and clear debris. Plywood line exposed internal walls and flash to provide weather-tightness where appropriate.
- Prop front porch by constructing a braced frame inside the porch from steel angles. Fix to porch concrete slab and arches.
- Clamp return walls adjacent North brick wall by bolting through with RB16 Reidbar, just above first floor level, to timber framing and plywood each side.
- Maintain existing cordons around the building.

Due care, safety equipment and precautions must be taken when carrying out the above work. Maintain awareness of fall hazards and escape routes if entering the building. The Gatehouse is a Heritage building therefore, retain Heritage features where possible.

11.0 Long Term Repair

This section outlines options for repair to restore the building to its pre-earthquake condition. Options for repair and/or strengthening will need to be discussed with the owner, and will be subject to revised local authority legislation.

1. Foundations and Floors:

- Survey foundation levels around the perimeter of the building to determine the extent of differential settlement, if any. If differential settlement has occurred, the following options can be considered:
 - a) if the floor slope from differential settlement is less than 1 in 400, no re-levelling action is necessary. Cracks to the foundation wall can be repaired as per the next bullet point.
 - b) if the floor slope exceeds 1 in 400, re-levelling is recommended. This can be done by either: jacking up the house, grouting underneath and re-piling; or reconstructing the foundation wall as appropriate. Alternatively foundations can be jacked using a structural resin injected into the soil (e.g. Uretek).

Re-levelling requires thorough consideration. While re-levelling may close some cracks, it may cause or open others. Any additional damage will require repair as outlined below:

Seal all cracks in concrete foundation wall larger than 0.2mm with a pressure injected epoxy (e.g. Sikadur injectokit and Sikadur52, or similar). Seal smaller cracks by painting over with a brushable crack filler (e.g. Resene Brushable Crack Filler).

2. Front Porch:

Either:

- a) Blow-out debris between cracks, and attempt to push porch arches back into place. Failing this, take down porch to cracked level and reconstruct. Note this will not restore the porch to above 67%NBS

Or,

55 Dunlop Road, Onekawa, Napier
PO Box 3315, Napier, 4142, New Zealand
P (06) 842 0111 F (06) 842 0113
Info@structuralconcepts.co.nz

- b)** Deconstruct and reconstruct from reinforced concrete plastered to suit.

3. Exterior Brick Walls:

- a)** Northern wall and returns: deconstruct and reconstruct from reinforced concrete with exterior plastered surface and new foundation.
- b)** For other walls below first floor level install new reinforced concrete piers at regular intervals with reinforced capping beam at first floor level and tie into existing brickwork.
- c)** Above first floor level deconstruct and reconstruct from lightweight timber framed construction.

4. Chimneys:

Reconstruct fallen chimneys using lightweight replicas in the form of plaster over plywood on timber framing with modern steel flues.
Reconstruct/repair damage gable dormer to match that which existed prior to the earthquake.

5. Dining Extension:

Reconstruct timber dining extension to match that which existed prior to the earthquake.
Deconstruct and reconstruct new reinforced concrete ring foundation.
Level remainder of floor.
Break out and reinstate sunken concrete porch steps.

6. General:

Seal cracks to low height balustrades using a pressure injected epoxy, and re-plaster over to match with existing surface profile.

Repair all cracked arch lintels by stitching with Helifix Helibars and Cemties in accordance with Helifix specifications. Re-plaster over to match original surface.

Remove cracked/peeling/bubbled wallpaper to expose damaged Internal walls linings. Repair as appropriate using one of the following:

- a) Grind-out v-shape into cracked plaster. Re-plaster and overlay crack with fibreglass reinforcing mesh. Re-plaster over to provide a smooth finish.
- b) Overlay lath and plaster with Braceline GIB. Fix through to timber framing in accordance with GIB specifications.
- c) Remove lath and plaster walls and replace with Braceline GIB, or plaster over corru-lath/rib-lath.

In all cases, wall ties and hold-down straps should be installed in accordance with GIB braced wall and ceiling diaphragm specifications.

Realign, re-fix and re-paint racked door frames and architraves.

Repair cracks to adjacent shed brick wall by stitching together with Helifix Helibars in accordance with Helifix specifications. Re-point mortar and re-paint to match existing.

Repair notes:

- i) Sika pressure-injected epoxies must be installed by a Sika certified contractor. Contact Sika for a list of certified applicators.
- ii) "Refer Department of Building and Housing repair guidance document 2010 for foundation wall repair method statements as a guide.
- iii) For Helifix specifications, refer to:
www.helifix.co.nz/masonryrepairdetails.html. Where the repair differs from online specifications, contact Helifix for further information.

7. To Mitigate Lateral Spread:

Install a new 3.0m deep 1310UB40 steel piles (at 800crs) palisade wall just beyond the Eastern side, adjacent to the access road, down to and into the gravel layer as a minimum. See also the recommendations in the report prepared by LDE.

The costs associated with the repairs would require the appropriate professional to visit the site to view the extent of damage.

12.0 Elements Not Inspected

The following is a list of elements not specifically inspected:

Soils (although the Geotechnical report completed by LDE has been reviewed and its recommendations implemented.)


Depth of existing foundations was not determined.

13.0 Applicability

Recommendations and opinions in this report are based on data and records obtained from Christchurch City Council, plus the non-destructive and destructive visual inspections. Although there is nothing to suggest otherwise, the nature and continuity of the structure hidden from sight (e.g. reinforcing steel, bolt depths etc.) is inferred but it must be appreciated that actual conditions could vary.

Findings presented in this report are for the sole use of the client. The findings may not contain sufficient information for use by other parties, and as such should not be relied upon unless discussed with Structural Concepts Ltd. We have exercised our services in a professional manner using a degree of care and skill normally, under similar circumstances, by reputable consultants practicing in this field at this time. No other warranty, expressed or implied, is made as to the professional advice presented in this report.

Prepared By:



Garry Newton
BE(Civil), MIPENZ(Civil,Structural), CPEng, IntPE

Managing Director

On behalf of Structural Concepts Ltd


APPENDIX A

MONAVALE GATEHOUSE FENDALTON ROAD, CHRISTCHURCH


PHOTOGRAPHS

Please note that the photographs provided in this report are not high quality and are for providing information that shows the indicative damage found around the building for structural engineering assessment only.
















































APPENDIX B

MONAVALE GATEHOUSE
FENDALTON ROAD, CHRISTCHURCH


MARKED-UP DRAWING INDICATING DAMAGED LOCATIONS



FIRST FLOOR Scale 1:100 @ A3



GROUND FLOOR Scale 1:100 @ A3



SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH

Photo Reference Ground Floor

Christchurch City Council
PROJECT ADDRESS

NELLIE SHELDON



chimney and ceiling damage



chimney and ceiling damage to bedroom 3



typical ceiling damage in staircase



typical ceiling damage



typical wall damage in staircase





chimney damage

APPENDIX C

MONAVALE GATEHOUSE FENDALTON ROAD, CHRISTCHURCH

NEW WORKS and EXAMPLES

SEISMIC STRENGTHENING OF MONAVALE GATEHOUSE CHRISTCHURCH



SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH
Cover Sheet

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV DATE DESCRIPTION


Structural Concepts

SCL NUMBER 1606
SHEET REV 000 0

Sheet List Table			
Sheet Number	Revision	Sheet Title	
020	0	Cover Sheet	
010	0	Site Plan	
100	0	Existing Floor Plans	
110	0	Photo Reference Ground Floor	
111	0	Photo Reference First Floor	
150	0	Deconstruction Ground Floor Plan	
151	0	Deconstruction First Floor Plan	
152	0	Deconstruction Roof Plan	
180	0	Existing North and East Elevations	
181	0	Existing South and West Elevations	
200	0	Proposed Ground Floor Plan	
201	0	Proposed First Floor Plan	
202	0	Proposed Roof Plan	
280	0	Proposed North and East Elevations	
281	0	Proposed South and West Elevations	
300	0	Proposed Foundation Plan	
311	0	Proposed Roof Framing Plan	
401	0	Section A-A	
401	0	Section B-B	
500	0	Structural Details	
501	0	Structural Details	
502	0	Structural Details	
503	0	Structural Details	
504	0	Structural Details	
505	0	Structural Details	
506	0	Structural Details	
510	0	Chimney Elevations	
550	0	Crack Stitching Details	
600	0	Cladding Details	
601	0	Cladding Details	
602	0	Cladding Details	
850	0	Window Schedule	




Structural Concepts 010 0



SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH
Site Plan

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV DATE DESCRIPTION



FIRST FLOOR Scale 1:100 @ A3




GROUND FLOOR Scale 1:100 @ A3

**SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH**
Photo Reference Ground Floor

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

FEV DATE DESPATCHED
FEB 2011






Estimación de celulas dañadas



chimney and ceiling damage to bedrock 3



typical ceiling damage




typical well damage in shale



chinney/demand2

**SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH**

CLIENT Christchurch City Council
PROJECT ADDRESS 63 Fendallion Road, Christchurch

**DECONSTRUCTION PLAN KEY:**

- some existing brick and internal timber walls, etc ceilings to remain, repair cracks and damage to plaster work as below.
- C1** Minor ceiling cracking - grind out 'V' shape along cracks to ceiling, re-plaster and overlay crack with fibreglass mesh reinforcing mesh, plaster to provide smooth finish
- C2** Major ceiling cracking - grind out 'V' shape along cracks to ceiling, similar, overlay joints between old plaster and new GIB or fibreglass reinforcing mesh, plaster area to provide smooth finish
- S03** Repair ceiling lining - strip back plaster to timber lath, remove all loose plaster, replace bare areas with Bracingine GIB or similar over existing lath, overlay joints between old plaster and new GIB with fibreglass reinforcing mesh, plaster area to a smooth finish
- W1** Remove loose plaster, re-plaster and overlay crack with fibreglass reinforcing mesh, plaster to provide smooth finish
- W2** Major wall cracking - remove cracked, pooling or bubbled wall paper; grind out 'V' shape along cracks, remove loose plaster, replace large gaps with Bracingine GIB or similar, overlay joints between old plaster and new GIB with fibreglass reinforcing mesh, plaster area to provide smooth finish
- SW3** Remove walls - remove all brick walls, retain bricks as directed by Heritage Architect, take care to support floors and roof above, retain items for re-use as shown, and as directed by Heritage Architect

NOTE: new wall thickness to match existing, and be located in exact location as existing walls, column framing same on site, and adjust to suit.

GENERAL SCOPE OF WORKS DECONSTRUCTION:

- remove sections of lower brick walls as shown on plans, in order to replace with concrete walls.
- cut G.I.A and remove sections of brick walls as shown on plans to allow for new concrete walls.
- remove all upper level brick walls down to upper floor level to allow for timber framed walls as shown.
- remove chimney to ceiling level, or ground floor, to allow for timber framed walls as shown.
- remove all areas of timber and brick calling to allow for new ceilings to be installed.
- remove and retain all root tiles, flashings, capping, etc to not be required to install new roof cladding.
- generally ensure all structure is supported as a quiet, contractor to determine extent of damage to all items on site, and confirm removal of all damaged items with Heritage Architect.

DECONSTRUCTION GROUND FLOOR PLAN

Scale 1:100 @ A3

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendall Road, Christchurch

SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH
Deconstruction Ground Floor Plan

REV DATE DESCRIPTION

SL NUMBER 1606
SHEET REV
Structural Concepts 150 0

ECONSTRUCTION PLAN KEY:

- some existing brick and thermal timber walls, and ceiling; to remain.

C1 Minor wall cracking - ground out 'V' shape along cracks to ceiling, re-plaster and overlay crack with fibreglass reinforcing mesh, plaster to provide smooth finish

C2 Major ceiling cracking - grind out 'V' shape along cracks to ceiling, remove loose plaster and replace with taut 30gms with Baseline Gib or similar, overlay joints between old plaster and new Gib with fibreless reinforcing mesh, denser areas to provide smooth finish


C3 Repair ceiling lining - strip back plaster to timber joist, remove all loose plaster, replace bare areas with Baseline Gib or similar over existing lath, overlay joints between old plaster and new Gib with fibreless reinforcing mesh, plaster area to a smooth finish

W1 Minor wall cracking - ground out 'V' shape along cracks to walls, remove loose plaster re-plaster, and overlay dry crack with fibreglass reinforcing mesh, plaster to provide smooth finish

W2 Major wall cracking - removes cracked, peeling, or bubbled wallpaper, ground out 'V' shape along a crack, remove loose plaster, replace large gaps with Baseline Gib and fibreglass, overlay joints between old plaster and new Gib with fibreglass reinforcing mesh, plaster areas to provide smooth finish

SMS Heritage Architect: Take care to support floors and roof above, retain items for reuse as shown, and as directed by Heritage Arch tec:

 - Remove all old tiles, retain bricks as directed by
 - CTE: new wall thickness to match existing, and be located in exact location as existing walls, common framing size on site, and adjust to suit



GENERAL SCOPE OF WORKS DECONSTRUCTION:

- remove sections of lower brick walls as shown or plan, in order to replace with concrete walls.
 - cut and remove sections of brick walls on plan to allow for new concrete piers.
 - re-move all upper level brick walls, down to upper "soffit" level, to allow for "under framed" walls as shown
 - re-move chimney to calling level of ground floor, to allow to be replaced with timber frame, see details.
 - remove all areas of damaged and broken ceiling joists to allow for new ceilings to be installed.
 - remove and replace all roof tiles, leadings, cappings, etc to roof as required to install new roof, damp proofing
 - generally ensure all structure & supports as required, contractor to determine extent of damage to all items on site, and confirm removal of all damaged items with Heritage Architect.


DECONSTRUCTION FIRST FLOOR PLAN

Scale 1:100 @ A3

SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH

Deconstruction First Floor Plan

Christchurch City Council
663 Fendall Road, Christchurch
CLIENT PROJECT ADDRESS



DECONSTRUCTION ROOF PLAN

Scale 1:100 @ A3

GENERAL SCOPE OF MEASUREMENTS


- Remove sections of lower brick walls as shown on plans, in order to replace with concrete walls.
 - Cut, butt and rezone sections of brick walls as shown on plans, to allow for new concrete piers.
 - Remove all upper level brick walls down to upper floor level, to allow for timber framed walls as shown on plans.
 - Remove chimney to ceiling level of ground floor, to allow for repair and to fit new chimney.
 - Remove all areas of dam and/or brittle feelings to allow for new castings to be installed.
 - Remove and replace all roof tiles, flashings, cappings, etc to roof as required to install new roof.
 - Guttering, fascia, soffit, and everything non-structural at damaged items with Heritage Am-Tech.

SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH


Reconstruction Roof Plan

Christchurch City Council
PROJECT ADDRESS
663 Fendall Road, Christchurch

RECEIPT NO. 34



East Elevation Scale 1:100 @ A3
existing damaged structure shown greyed - restore to existing condition



North Elevation Scale 1:100 @ A3

GENERAL SCOPE OF WORKS DECONSTRUCTION:	
- remove sections of lower brick walls as shown on plans, in order to replace with concrete walls.	
- cut out and remove sections of brick walls as shown on plans to allow for new concrete piers.	
- remove all upper level brick walls down to upper floor level, to allow to be replaced with timber frame, see details.	
- remove chimney to ceiling level of ground floor, to allow to be replaced with timber frame, see details.	
- remove all areas of damaged and broken ceilings to allow for new ceilings to be installed.	
- remove all roof tiles, flashings, cappings, etc to roof as required to install new roof diaphragm.	
- generally ensure all structure is supported as required, contractor to determine extent of damage to all items on site, and confirm removal of all damage items with Heritage Architect.	

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch


REV DATE DESCRIPTION

SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH Existing North and East Elevations


STRUCTURAL CONCEPTS LTD - SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH EXISTING NORTH AND EAST ELEVATIONS

emajineer Structural Concepts

SC. NUMBER 1606
SHIFT REV 0



South Elevation Scale 1:100 @ A3



West Elevation Scale 1:100 @ A3

**SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH
Existing South and West Elevations**

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendallton Road, Christchurch

GENERAL SCOPE OF WORKS DECONSTRUCTION:

- remove sections of lower brick walls as shown on plans, in order to replace with concrete walls.
- cut out, and remove sections of brick walls as shown on plans to allow for new concrete piers.
- remove all top brick walls down to upper floor level, to allow for timber framed walls as shown on plans.
- remove chimney, to ceiling level or ground floor, to allow to be replaced with timber frame, see details.
- remove all areas of damaged and broken ceilings to allow for new ceilings to be installed.
- remove and retain all roof tiles, fascia's, capping's, etc to as safe, fit to install new roof damaged.
- generally ensure all structure is supported as required, contractor to determine exact damage to all items on site, and confirm removal of all damaged items with Heritage Architect.

emagineer
Structural Concepts
181 0

SC. NUMBER
1606
SHEET REV
0

STRUCTURAL PLAN KEY:

- A** - new solid concrete walls to match existing thickness to replace all lower tier double brick ender or walls.
 - H012 bars @ 200 mm horizontal and -H015 bars @ 150mm 250 vertical - see details
 - Line interior walls with 12mm Glib board

B - exterior cladding to be Stucco plaster to match existing
 - new 45mm MSGB HT 2 timber framing, total width to match removed brick walls
 - new 45mm Glib cladding to replace start/grip timber walls to s/n room.
 - one layer of 13mm Glib Ultrafine to the inside face, and one layer of 7mm Glib Ultrafine to the outside face of timber frame exterior wall.

C - install H4.2 cavity battens over building wrap over pvc bracing,
 - exterior cladding to be Stucco plaster on fibre cement sheets,
 - existing brick walls, repair cracking with Hilti crack stitching system per manufacturer's specification, install concrete piers into brick walls as detailed.


D - existing internal lime walls and ceilings to remain, confirm extent of damage on site, repair cracks and damage to plaster work as below:
 Minor ceiling cracking - grind out 'V' shape along cracks to ceiling, re-plaster and overlay crack with fibreglass mesh.
 Major ceiling cracking - grind out 'V' shape along cracks to ceiling, remove loose plaster, replace ledge spans with Braceline 51m, 51m or similar, oriental joints between old plaster and new Glib with fibreglass reinforcing mesh, plaster area to provide smooth finish

E - Repair ceiling lining - strip back plaster to timber lath, remove all loose plaster, replace bare areas with Braceline 510 or similar over existing lath, overlay joints between old plaster and new Glib with fibreglass reinforcing mesh, plaster area to a smooth finish

F - Minor wall cracking - grind out 'V' shape along cracks to walls, remove loose plaster, new plaster and overlay crack with fibreglass reinforcing mesh, plaster to provide smooth finish

G - Major wall cracking - remove cracked, peeling or buckled plaster, grind out 'V' shape along cracks, remove loose plaster, repair large gaps with Braceline 510 or similar, overlay joints between old plaster and new Glib with fibreglass reinforcing mesh. Plaster area to provide smooth finish

H - new wall 'Z' blocks to match existing, and be located in exact location as existing walls, confirm framing size on site, and adjust to suit



GENERAL SCENE OF WORKS RECONSTRUCTION.

- concrete walls have been removed with timber frame as detailed, and install new roof tiles and roof structure to match timber frame as detailed, and ensure roof is weather-tight.
 - plaster to timber walls, finish of all walls and ceilings to be confirmed with architect as detailed.
 - plaster to timber wells, finish of all walls and ceilings to be confirmed with architect as detailed.
 - top of existing first floor flooring to all rooms, remove and make good part details.
 - replace with GIC board one ceiling battens fit/install now as detailed.

PROPOSED GROUND FLOOR PLAN

Scale 1:10 @ A3

SEISMIC STRENGTHENING OF MONAVALÉ GATE HOUSE CHRISTCHURCH

Proposed Ground Floor Plan

Christchurch City Council
663 Fendalton Road Christchurch
PROJECT ADDRESS


卷之三

SC. N. M. B. E.
1606
RE
SHEET
200 0

14

STRUCTURAL PLAN KEY:


- A**
 - new solid concrete walls to match existing thickness to relocate all lower floor double brick exterior walls.
 - I-Or2 bars @ 200 mm horizontal, and HD16 bars @ 150mm c/c vertical - see details.
 - Unit the ice walls with 13mm Gb board
 - exterior cladding to be Stucco plaster to match existing
- B**
 - new 15mm MSG8 I-2 timber framing, total width to match existing removed brick walls; studs @ 400 mm and dividers @ 300 mm, 90x15 framing to replace damaged lime walls to sun room.
 - one layer of 13mm Gb Ultrafine to the inside face, and one layer of 7mm bracing ply element to the outside face of timber framed exterior wall.
 - Install H3.2 earth battens over building walls over dry bracing,
 - exterior cladding to be Stucco plaster* on fire element's needs.
- C**
 - existing brick walls, repair cracking with Helbar track stitching system as per manufacturer's specification. Install concrete piers into thick walls as detailed.
 - existing internal timber walls and earthings to remain, confirm extent of damage on site, repair cracks and damage to plaster work as below:

**GENERAL SCOPE OF WORKS RECONSTRUCTION:**

- * replace brick walls that have been removed with 200mm walls.
- * replace upper level brick walls with timber framed walls in locations as shown and detailed on the plans.
- * install floor diaphragm over top of existing floor joists to match existing floor joist spans.
- * install non diagonal timber joists to rafters as detailed.
- * generally repair all cracked plaster to walls, finish off walls and ceilings to be confirmed with the Heritage Architect.
- * replace existing chimney with timber frame as detailed, and install new roof tiles and roof structure to roof as required, make good, ensure roof is weather-tight.
- * rebuild sun room with new structure as detailed.
- * generally ensure all doors and windows open and close properly, replace broken glass as required.
- * generally ensure all structure, finishes, plumbing, electrical and services are repaired or replaced as required.
- * generally ensure all structural items to determine extent of damage to all items on site, and confirm repair and replacement of all items with Heritage Architect.

PROPOSED FIRST FLOOR PLAN

Scale 1:100 @ A3



PROPOSED ROOF PLAN

Scale 1:100 @ A3

GENERAL SCOPE OF WORKS RECONSTRUCTION;


- replace brick walls that have been removed with concrete walls.
 - replace upper level brick walls with timber framed walls in locations as shown and detailed on the plans.
 - install timber diaphragm over top of existing first floor flooring to all rooms, remove and make good part ceilings as required, as per details.
 - install new ceiling joists to rafters as detailed, replace with G4 board over ceiling battens (install new batten if required).
 - generally retain all cracked plaster to timber walls, finish of all walls and ceilings to be confirmed with the Heritage Architect.
 - replace existing chimney with timber frame as detailed, and install new roof tiles and roof structure to not as required to make good, ensure roof is weather-tight.
 - rebuild sun room with new structure as detailed.
 - ensure all doors and windows open and close properly, replace broken glass as required.
 - generally e sure all structure, finishes, plumbing, electrical and joinery items are repaired or replaced as required, contractor to determine extent of damage to all items on site, and confirm repair and replacement of all items with Heritage Architect.

CLIENT Christchurch City Council
PROJECT ADDRESS 63 Fendalton Road, Christchurch


SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH

Proposed Roof Plan

ED. NUMBER
1606
SHEET
REF.
202 0



East Elevation Scale 1:100 @



North Elevation Scale 1:100 © A3


卷之三

- GENERAL SCOPE OF WORKS RECONSTRUCTION:**


 - replace brick walls that have been removed with concrete walls.
 - replace upper level brick walls with timber framed walls in locations as shown and detailed on the plans.
 - install floor diagonal over top of existing first floor flooring to all rooms, remove and make good part ceilings as required, as per details.
 - install new drylining to reflect as detailed, replace with GIB board over ceiling batten (install new battens if required).
 - generally repair all cracked plaster to interior walls, finish off all walls and ceilings to be confirmed with the Heritage Architect.
 - repair and paint all exterior walls.
 - repair and paint all roof trusses.
 - repair and paint all exterior doors and windows open and close properly, replace broken glass as required.
 - repair and paint all exterior fascia, soffit, brackets, eaves, and cornices.
 - generally ensure all structure, finishes, plumbing, electrical and joinery items are repaired or replaced as required, contractor to determine extent of damage to all items on site, and confirm repair and replacement of all items with Heritage Architect.

**SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH**
Proposed North and East Elevations

CLIENT Christchurch City Council
PROJECT NUMBER 666666
63 Fendalton Road, Christchurch



South Elevation Scale 1:100 @ A3



West Elevation Scale 1:100 @ A3

**SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH**
Proposed South and West Elevations

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch



eengineer
STRUCTURAL Concepts

SC. NUMBER
1606
SHEET REV
281 0

DATE 04/12 2020 PITCH
V12020 04-12-2020 PITCH

GENERAL SCOPE OF WORKS RECONSTRUCTION:

- replace brick walls that have been removed with concrete walls.
- replace upper level brick walls with timber framed walls in locations as shown and detail on the p. 10.
- install floor diaphragm over 2nd floor framing to all rooms, remove and make good floor ceilings as required, as per details.
- install roof diaphragm to rafters as detailed, replace with GIC board over ceiling batters (install new battens if required)
- generally repair all cracked plaster to timber walls, finish of all walls and ceilings to be confirmed with the Heritage Architect.
- replace existing chimney with timber frame at 2nd floor, and install new roof tiles and roof structure to new chimney with new structure as detailed.
- ensure all doors and windows open and close properly, replace broken glass as required.
- replace existing plumbing, electrical and joinery items are repaired or replaced as required, as per details.
- generally ensure all structures, finishes, plumbing, electrical and joinery items are repaired or replaced as required, contractor to determine extent of damage to all fixtures on site, and do final repair and replacement of all items with Heritage Architect.



GENERAL SCOPE OF WORKS RECONSTRUCTION:

- replace brick walls that have been removed with concrete walls.
- replace upper level brick walls with timber framed walls in locations as shown and detailed on the plans.
- install floor diaphragm over top of existing first floor flooring to all rooms, remove and make good part ceilings as required, as per detail.
- install roof diaphragm to rafters as detailed, replace with Gb board over ceiling batons (install new batons if required).
- generally repair all cracked plaster to timber walls, finish off all walls and ceilings to be confirmed with the Fe-Te-Age Architect.
- replace existing chimney with timber frame as detailed, and install new roof tiles and mact structure to suit as required, make good, ensure not is weather tight.
- rebuild sun room with new structure as detailed.
- enlarge all doors and windows open and close properly, replace broken glass as required.
- generally renew all structure, finishes, plumbing, electrical and joinery items are replaced or replaced as required, contractor to determine extent of damage to all items on site, and confirm repair and replacement of all items with Heritage Architect.

PROPOSED FOUNDATION PLAN

Scale 1:100 @ A3


CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV E-T-D DESIGNER
STRUCTURAL CONCEPTS LTD

STRUCTURAL CONCEPTS LTD - Web based design software - Version 1.1 - 01/02/2013 16:00:00 AM - PO Box 3035, Otago Central, Dunedin, New Zealand

SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH
Proposed Foundation Plan

STRUCTURAL CONCEPTS LTD - Web based design software - Version 1.1 - 01/02/2013 16:00:00 AM - PO Box 3035, Otago Central, Dunedin, New Zealand



GENERAL SCOPE OF WORKS RECONSTRUCTION:

- replace brick walls that have been removed with concrete walls.
- replace upper level brick walls with timber framed walls in locations as shown and detailed on the plans.
- install floor diaphragm over top of existing first floor flooring to all rooms, remove and make good joist ceilings as required, as per details.
- install new diaphragm to rafters as detailed, replace with C18 boards over ceiling battens (install new batten if required).
- generally repair all cracked plaster to timber walls, finish of all walls and ceilings to be confirmed with the Heritage Architect.
- replace existing chimney with timber frame as detailed, and install new roof tiles and roof structure to roof as required, make good, ensure roof is weathertight.
- rebuild sun room with new structure as detailed.
- ensure all doors and windows open and close properly, replace broken glass as required.
- generally ensure all structure, finishes, plumbing, electrical and joinery items are repaired or replaced as required, contractor to determine extent of damage to all items on site, and confirm repair and replacement of all items with Heritage Architect.

PROPOSED ROOF FRAMING PLAN

Scale 1:100 @ A3


CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV: AWT: 22/03/2012
DATE: 11/03/12
REV: 0

STRUCTURAL CONCEPTS LTD - MONAVALE GATE HOUSE CHRISTCHURCH
Proposed Roof Framing Plan
Structural Concepts 310 0



ED. NUMBER
1606
SHEET
REV
0




Section A-A Scale 1:50 @ A3

**SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH**

Christchurch City Council
PO BOX 7 ADDRESS
63 Fendalton Road, Christchurch

RECD DATE DESCRIPTION





Section B-B Scale 1:50 @ A3

**SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH**

Christchurch City Council
PROJECT ADDRESS
663 Fendalton Road, Christchurch

POLY-DUT-SCHEMEN




FLOOR DIAPHRAGM DETAILS

SEISMIC STRENGTHENING OF MONAVALÉ GATE HOUSE CHRISTCHURCH

Structural Details

(1) FLOOR DIAPHRAGM NAIL LAYOUT
2011 120 mil AS


Christchurch City Council
63 Fendalton Road Christchurch
PROJECT ADDRESS



MONAVALÉ GATE HOUSE CHRISTCHURCH

Structural Details

CLIENT Christchurch City Council
PROJECT ADDRESS 663 Foundation Road, Christchurch




SEISMIC STRENGTHENING OF MONA VALE GATE HOUSE CHRISTCHURCH


Structural Details

Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch


EEG DATE 06/26/03



08a DETAIL
1:10 at A3



08b DETAIL
1:10 at A3




07 DETAIL
1:10 at A3

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF MONAVALÉ GATE HOUSE CHRISTCHURCH Structural Details

STRUCTURAL CONCEPTS 503
emajineer
DETAIL 08b
4C3 1:10 at A3
EC. NUMBER 1606
SHEET REV




SEISMIC STRENGTHENING OF MONAVALÉ GATE HOUSE CHRISTCHURCH

Structural Details

Christchurch City Council
PROJECT ADDRESS:
63 Fendalton Road, Christchurch

EPILOGUE




CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch


DESCRIPTION
874 1016

SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH
Structural Details

STRENGTHENING OF
CHRISTCHURCH
Structural Details

CLIENT Christchurch City Council
PROJECT ADDRESS 63 Fendallton Road, Christchurch





Chimney Top Detail scale 1:10 @ A3

Side Elevation Scale 1:2) @ A3


Front Elevation Scale 1:20 @ A3

CHRISTCHURCH CITY COUNCIL
PROJECT ADDRESS
663 Fendalton Road, Christchurch

**SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH**
Chimney Elevations

FEY 247 CECERI, TAY

Attached line represents crack to brick wall. If cracks are closer than 500mm apart, the Helitar can span more than one crack. Ensure the bar extends 500mm or more from the crack, see manufacturer's specifications for more information



Elevation
Typical Crack Stitch Detail
Scale 1:10 A3


9

NOTES.

- NOTES.** - exact locations of where crack stitching is to be used must be confirmed by the engineer on site before work commences

dashed the reagent, crack to brick wall. If cracks are closer than 50mm apart, the Helebar can span more than one crack. Ensure the bar extends 500mm or more from the crack; see manufacturer's specification for more information.

Section A, Through Well




Crack Stitch Detail at Corners

Scale 1:10 000


Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF THE GATE HOUSE CHRISTCHURCH


Crack Stitching Details




Stucco Cladding Details - Typical Base



Stucco Cladding Details - Window Jamb



Stucco Cladding Details - Window Head
Scale 1:5 @ A3




Stucco Cladding Details - Window Sill


SEISMIC STRENGTHENING OF MONA VALE GATE HOUSE CHRISTCHURCH

Cladding Details


CLIENT Christchurch City Council
PROJECT ADDRESS 663 Fendalton Road, Christchurch




Stucco Cladding Details - To Soffit
Scale 1:5 @ A3



Stucco Cladding Details - Control Joint
Scale 1:2 @ A3



Stucco Cladding Details - Internal Corner
Scale 1:5 @ A3



Stucco Cladding Details - External Corner
Scale 1:5 @ A3

SUBJECT
Christchurch City Council
PROJECT ADDRESS
63 Fendallion Road, Christchurch

DATE

DESCRIPTION


REV DATE DESCRIPTION

**SEISMIC STRENGTHENING OF
MONAVALE GATE HOUSE CHRISTCHURCH**
Cadding Details


DATE

DESCRIPTION


SC. NUMBER
1605
SHEET
0
STRUCTURAL CONCEPTS LTD
emagineer
Structural Concepts




Stucco Cladding Details - Apron Flashing Tiled Roof
Scale 1:5 @ A3



Stucco Cladding Details - Apron Flashing Tiled Roof
Scale 1:5 @ A3



Stucco Cladding Details - Apron Flashing Stop End



Stucco Cladding Details - Horizontal Joint
Scale 1:5 @ A3

Christchurch City Council
63 Fendallton Road, Christchurch
CLIENT PRODUCT ADDRESS

SEISMIC STRENGTHENING OF MONAVALE GATE HOUSE CHRISTCHURCH

Cladding Details

63 F6

1


133

31

22

2

TABLE 7 E2/JAS1 Metal Flashings - general dimensions	
Type	Description
Awnings:	Low, Med & High wind, Roof Pitch >10°
General	Transverse Flashing over roof of Parallel Flashing over roof
Ridges / Hips	Transverse Flashing over roof of Overlap to barge boards
Banges	Membrane Lags under cladding
Roof & Deck	Flange - Direct feed, fine cement & ply on cavity
Windows	Corbel to window/door Jamf flange Cover to window/door sill flange Sill flashing slope Head flashing slope
Sill Flashing	910 mm Min. excluding dip edge 10mm Min. excluding dip edge 8mm Min. excluding dip edge 10° for direct fixed jolley - 10°sizing to extend past the condensation channel
Head Flashings	15° Min.
Corners	Lap under cladding above Anti-cadillary tap to cladding above tacking Comar Flashing
Junction Flashing:	50 x 50mm Min. Min.
Inter-story cladding junctions	Lap over cladding below Lap under cladding above Clearance under cladding Total Upstand 45mm



Window Schedule

Scale 1:50 @ A3

SEISMIC STRENGTHENING OF
MONAVALÉ GATE HOUSE CHRISTCHURCH
Window Schedule

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

APPENDIX D

MONAVALE GATEHOUSE FENDALTON ROAD, CHRISTCHURCH

PRELIMINARY CALCULATIONS (extract only)



55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND, P (06) 842 0111 F (06) 842 0113, E info@structuralconcepts.co.nz

Client: Christchurch City Council

**Project: Mona Vale Gatehouse
63 Fendalton Road, Christchurch**

Ref: 1606

Date: 23-Jun-13

CALCULATIONS

BY GARRY NEWTON

BE (Civil), MIPENZ(Civil, Structural), CPEng, IntPE(NZ)

CONTENTS

STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1606
Project: Mona Vale Gatehouse	Date: 23/6/13
63 Fendalton Road, Christchurch	BY: GN
Subject: Gravity Loads	

Sheet No.: 2

Loads

Roof

Clay tiles	0.670
Timber 20.6	0.092
Purlins 05 .4	0.034
Battens 05 1.2	0.011
Rockwool Insu.	0.002
Gib Board 13	0.120
Timber 15.6	0.069

0.998 kPa

External Walls

Portland Plaster	0.290
Timber 15.4	0.103
140. Nogs & plates	0.104
Rockwool Insu.	0.002
Gib Board 13	0.120

0.619 kPa

Timber floor

25mm Pine deck	0.138
Timber 20.6	0.092
90. Nogs & plates	0.067
Battens 05 1.2	0.011
Rockwool Insu.	0.002
Gib Board 13	0.120

0.429 kPa

Partitions

Timber 15.4	0.103
140. Nogs & plates	0.104
Gib Board 13	0.120
Gib Board 13	0.120

0.447 kPa


Exterior Brick Walls

100 Brick veneer	1.900
215 Med Brick	4.600
Battens 03 .4	0.021
Fibrous plaster	0.090

6.611 kPa

Live loads

Domestic Floor	1.50	kPa
R2 Roofs	0.25	kPa



STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315
 NAPIER, 4142, NEW ZEALAND
 P (06) 842 0111 F (06) 842 0113
 E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1606
Project: Mona Vale Gatehouse 63 Fendalton Road, Christchurch	Date: 23/6/13
Subject: Seismic loads to NZS1170	BY: GN

Seismic Loads to NZS 1170.5

Ref:	Design	Output																																				
	Design working live Importance level Annual Probability of exceedance (inverse) Ultimate Annual Probability of exceedance (inverse) Service	50 Years 2 500 25																																				
	<table border="1"> <thead> <tr> <th>Element</th> <th>Area/length</th> <th>Load kPa</th> <th>Total kN</th> </tr> </thead> <tbody> <tr> <td>Roof</td> <td>60.00</td> <td>1.00</td> <td>59.90</td> </tr> <tr> <td>Partitions</td> <td>20.00</td> <td>0.45</td> <td>8.94</td> </tr> <tr> <td>Exterior Brick Walls</td> <td>16.00</td> <td>6.61</td> <td>105.77</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>1.00</td> <td>0.40</td> <td>0.00</td> </tr> </tbody> </table>	Element	Area/length	Load kPa	Total kN	Roof	60.00	1.00	59.90	Partitions	20.00	0.45	8.94	Exterior Brick Walls	16.00	6.61	105.77		0.00	0.00	0.00		0.00	0.00	0.00		0.00	0.00	0.00		1.00	0.40	0.00	Live load reduction				
Element	Area/length	Load kPa	Total kN																																			
Roof	60.00	1.00	59.90																																			
Partitions	20.00	0.45	8.94																																			
Exterior Brick Walls	16.00	6.61	105.77																																			
	0.00	0.00	0.00																																			
	0.00	0.00	0.00																																			
	0.00	0.00	0.00																																			
	1.00	0.40	0.00																																			
		Total floor area 60.0																																				
		$.3 + \frac{3}{\sqrt{A}} = 0.687$																																				
		But not less than .5																																				
		174.61 kN																																				
	<table border="1"> <thead> <tr> <th>Element</th> <th>Area/length</th> <th>Load kPa</th> <th>Total kN</th> </tr> </thead> <tbody> <tr> <td>Timber floor</td> <td>60.00</td> <td>0.43</td> <td>25.77</td> </tr> <tr> <td>External Walls</td> <td>12.00</td> <td>0.62</td> <td>7.43</td> </tr> <tr> <td>Exterior Brick Walls</td> <td>37.00</td> <td>6.61</td> <td>244.59</td> </tr> <tr> <td>Roof</td> <td>16.00</td> <td>1.00</td> <td>15.97</td> </tr> <tr> <td>Interior Brick Walls</td> <td>12.00</td> <td>4.60</td> <td>55.20</td> </tr> <tr> <td>Partitions</td> <td>30.00</td> <td>0.45</td> <td>13.41</td> </tr> <tr> <td>Domestic Floor</td> <td>0.69</td> <td>0.30</td> <td>60.00</td> </tr> <tr> <td></td> <td>0.69</td> <td>0.40</td> <td>0.00</td> </tr> </tbody> </table>	Element	Area/length	Load kPa	Total kN	Timber floor	60.00	0.43	25.77	External Walls	12.00	0.62	7.43	Exterior Brick Walls	37.00	6.61	244.59	Roof	16.00	1.00	15.97	Interior Brick Walls	12.00	4.60	55.20	Partitions	30.00	0.45	13.41	Domestic Floor	0.69	0.30	60.00		0.69	0.40	0.00	380.93 kN
Element	Area/length	Load kPa	Total kN																																			
Timber floor	60.00	0.43	25.77																																			
External Walls	12.00	0.62	7.43																																			
Exterior Brick Walls	37.00	6.61	244.59																																			
Roof	16.00	1.00	15.97																																			
Interior Brick Walls	12.00	4.60	55.20																																			
Partitions	30.00	0.45	13.41																																			
Domestic Floor	0.69	0.30	60.00																																			
	0.69	0.40	0.00																																			
		Total building weight 555.54 kN																																				

STRUCTURAL CONCEPTS

*55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz*

Client: Christchurch City Council	Ref:	1606
Project: Mona Vale Gatehouse 63 Fendalton Road, Christchurch	Date:	23/6/13
	BY:	GN

Ref:	Design	Output
Soil type	D. Deep or soft soil	<input checked="" type="checkbox"/>
<u>Across the building</u>		
Period of building across the building	0.40	<input checked="" type="checkbox"/>
Does the seismic bracing have ductile capabilities but is designed as nominally ductile		
Structural ductility factor (Ultimate)	$\mu = 1.00$	
Structural ductility factor (Service SLS1)	$\mu = 1.00$	
Hazard Factor	Christchurch	$Z = 0.3$
Return period factor		$R_u = 1.00$
Return period factor		$R_s = 0.25$
Structural Performance factor (Ultimate)		$S_p = 0.65$
Structural Performance factor (Service)		$S_p = 0.70$
Spectral Shape Factor (across)		$Ch(T) = 3.00$
Near Fault factor		$N(T,D) = 1.0$ n/a
Elastic site spectra (Ultimate)		$C(T) = 0.90$
Elastic site spectra (Service)		$C(T) = 0.23$
Ultimate		$k_\mu = 1.00$
Service		$k_\mu = 1.00$
<u>Ultimate</u>		
Horizontal design action coefficients (Across)	$Cd(T) = 0.59$	But not less than 0.030Ru
Ultimate force across the building	$Cd(T) \times Wi = 324.99$	kN Total
<u>Service</u>		
Horizontal design action coefficients (Across)	$Cd(T) = 0.16$	
Service force across the building	$Cd(T) \times Wi = 87.50$	kN Total
<u>Along the building</u>		
Period of building along the building	0.40	<input checked="" type="checkbox"/>
Does the seismic bracing have ductile capabilities but is designed as nominally ductile		
Structural ductility factor (Ultimate)	$\mu = 1.00$	
Structural ductility factor (Service SLS1)	$\mu = 1.00$	
Structural Performance factor (Ultimate)		$S_p = 0.65$
Spectral Shape Factor (across)		$Ch(T) = 3.00$
Near Fault factor		$N(T,D) = 1.0$
Elastic site spectra (Ultimate)		$C(T) = 0.90$
Elastic site spectra (Service)		$C(T) = 0.23$
Ultimate		$k_\mu = 1.00$
Service		$k_\mu = 1.00$
<u>Ultimate</u>		
Horizontal design action coefficients (Across)	$Cd(T) = 0.59$	But not less than 0.030Ru
Ultimate force along the building	$Cd(T) \times Wi = 324.99$	kN Total
<u>Service</u>		
Horizontal design action coefficients (Across)	$Cd(T) = 0.15$	
Service force across the building	$Cd(T) \times Wi = 81.25$	kN Total



STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315
 NAPIER, 4142, NEW ZEALAND
 P (06) 842 0111 F (06) 842 0113
 E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1606
Project: Mona Vale Gatehouse 63 Fendalton Road, Christchurch	Date: 23/6/13
Subject: Seismic Forces	BY: GN

Seismic Loads to NZS 1170.5

Sheet No.: 5

Ref:	Design	Output
Seismic weight at level i	Wi 174.61 kN	
Height at level i	hi 5.0 m	
Seismic weight at level l	Wi 380.93 kN	
Height at level l	hi 3.0 m	
Sum of Wihi	2015.8	
Base shear ultimate	324.99 kN	
Base shear service	87.50 kN	
8% of base shear to be applied at top level	26.00 kN	
8% of base shear to be applied at top level	7.00 kN	
$F_i = .92V \frac{Wihi}{\sum(Wihi)}$		
<u>Ultimate</u>		
Equivalent Lateral force at level i (Roof)	155.49	3110
Equivalent Lateral force at level i	169.50	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
	324.99	kN base V
	6499.78	
<u>Service</u>		
Equivalent Lateral force at level i (Roof)	41.86	
Equivalent Lateral force at level i	45.63	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
	87.50	kN base V

STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1606
Project: Mona Vale Gatehouse 63 Fendalton Road, Christchurch	Date: 23/6/13
Subject: West Wall - Seismic loads to NZS1170	BY: GN

Seismic Loads to NZS 1170.5

Ref:	Design	Output																																				
	Design working live Importance level Annual Probability of exceedance (inverse) Ultimate Annual Probability of exceedance (inverse) Service	50 Years 2 500 25																																				
	<table border="1"> <thead> <tr> <th>Element</th> <th>Area/length</th> <th>Load kPa</th> <th>Total kN</th> </tr> </thead> <tbody> <tr> <td>Roof</td> <td>11.00</td> <td>1.00</td> <td>10.98</td> </tr> <tr> <td>Partitions</td> <td>0.00</td> <td>0.45</td> <td>0.00</td> </tr> <tr> <td>Exterior Brick Walls</td> <td>6.00</td> <td>6.61</td> <td>39.66</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>0.00</td> <td>0.00</td> <td>0.00</td> </tr> <tr> <td></td> <td>1.00</td> <td>0.40</td> <td>0.00</td> </tr> </tbody> </table>	Element	Area/length	Load kPa	Total kN	Roof	11.00	1.00	10.98	Partitions	0.00	0.45	0.00	Exterior Brick Walls	6.00	6.61	39.66		0.00	0.00	0.00		0.00	0.00	0.00		0.00	0.00	0.00		1.00	0.40	0.00	Live load reduction				
Element	Area/length	Load kPa	Total kN																																			
Roof	11.00	1.00	10.98																																			
Partitions	0.00	0.45	0.00																																			
Exterior Brick Walls	6.00	6.61	39.66																																			
	0.00	0.00	0.00																																			
	0.00	0.00	0.00																																			
	0.00	0.00	0.00																																			
	1.00	0.40	0.00																																			
		Total floor area 0.0																																				
		.3 + $\frac{3}{\sqrt{A}}$ = 1.000																																				
		But not less than .5																																				
	<table border="1"> <thead> <tr> <th>Element</th> <th>Area/length</th> <th>Load kPa</th> <th>Total kN</th> </tr> </thead> <tbody> <tr> <td>Timber floor</td> <td>11.00</td> <td>0.43</td> <td>4.72</td> </tr> <tr> <td>External Walls</td> <td>0.00</td> <td>0.62</td> <td>0.00</td> </tr> <tr> <td>Exterior Brick Walls</td> <td>16.00</td> <td>6.61</td> <td>105.77</td> </tr> <tr> <td>Roof</td> <td>8.00</td> <td>1.00</td> <td>7.99</td> </tr> <tr> <td>Interior Brick Walls</td> <td>0.00</td> <td>4.60</td> <td>0.00</td> </tr> <tr> <td>Partitions</td> <td>0.00</td> <td>0.45</td> <td>0.00</td> </tr> <tr> <td>Domestic Floor</td> <td>1.00</td> <td>0.30</td> <td>11.00</td> </tr> <tr> <td></td> <td>1.00</td> <td>0.40</td> <td>0.00</td> </tr> </tbody> </table>	Element	Area/length	Load kPa	Total kN	Timber floor	11.00	0.43	4.72	External Walls	0.00	0.62	0.00	Exterior Brick Walls	16.00	6.61	105.77	Roof	8.00	1.00	7.99	Interior Brick Walls	0.00	4.60	0.00	Partitions	0.00	0.45	0.00	Domestic Floor	1.00	0.30	11.00		1.00	0.40	0.00	50.64 kN
Element	Area/length	Load kPa	Total kN																																			
Timber floor	11.00	0.43	4.72																																			
External Walls	0.00	0.62	0.00																																			
Exterior Brick Walls	16.00	6.61	105.77																																			
Roof	8.00	1.00	7.99																																			
Interior Brick Walls	0.00	4.60	0.00																																			
Partitions	0.00	0.45	0.00																																			
Domestic Floor	1.00	0.30	11.00																																			
	1.00	0.40	0.00																																			
		123.43 kN																																				
		Total building weight 174.07 kN																																				

STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4412, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1606
Project: Mona Vale Gatehouse 63 Fendalton Road, Christchurch	Date: 23/6/13
Subject: West Wall - Seismic loads to NZS1170	BY: GN

Sheet No.: 7

Ref:	Design	Output
Soil type	D. Deep or soft soil	
<u>Across the building</u>		
Period of building across the building	0.40	<input checked="" type="checkbox"/>
Does the seismic bracing have ductile capabilities but is designed as nominally ductile		
Structural ductility factor (Ultimate)	$\mu = 1.00$	
Structural ductility factor (Service SLS1)	$\mu = 1.00$	
Hazard Factor	Christchurch	$Z = 0.3$
Return period factor		$R_u = 1.00$
Return period factor		$R_s = 0.25$
Structural Performance factor (Ultimate)		$S_p = 0.65$
Structural Performance factor (Service)		$S_p = 0.70$
Spectral Shape Factor (across)		$Ch(T) = 3.00$
Near Fault factor		$N(T,D) = 1.0$ n/a
Elastic site spectra (Ultimate)		$C(T) = 0.90$
Elastic site spectra (Service)		$C(T) = 0.23$
Ultimate		$k_\mu = 1.00$
Service		$k_\mu = 1.00$
<u>Ultimate</u>		
Horizontal design action coefficients (Across)	$Cd(T1) = 0.59$	But not less than 0.030Ru
Ultimate force across the building	$Cd(T1) \times Wi = 101.83$	kN Total
<u>Service</u>		
Horizontal design action coefficients (Across)	$Cd(T1) = 0.16$	
Service force across the building	$Cd(T1) \times Wi = 27.42$	kN Total
<u>Along the building</u>		
Period of building along the building	0.40	
Does the seismic bracing have ductile capabilities but is designed as nominally ductile		<input checked="" type="checkbox"/>
Structural ductility factor (Ultimate)	$\mu = 1.00$	
Structural ductility factor (Service SLS1)	$\mu = 1.00$	
Structural Performance factor (Ultimate)	$S_p = 0.65$	15% damping
Spectral Shape Factor (across)		$Ch(T) = 3.00$
Near Fault factor		$N(T,D) = 1.0$
Elastic site spectra (Ultimate)		$C(T) = 0.90$
Elastic site spectra (Service)		$C(T) = 0.23$
Ultimate		$k_\mu = 1.00$
Service		$k_\mu = 1.00$
<u>Ultimate</u>		
Horizontal design action coefficients (Across)	$Cd(T1) = 0.59$	But not less than 0.030Ru
Ultimate force along the building	$Cd(T1) \times Wi = 101.83$	kN Total
<u>Service</u>		
Horizontal design action coefficients (Across)	$Cd(T1) = 0.15$	
Service force across the building	$Cd(T1) \times Wi = 25.46$	kN Total

STRUCTURAL CONCEPTS

LIMITED

55 DUNLOP ROAD, PO BOX 3315

NAPIER, 4142, NEW ZEALAND

P (06) 842 0111 F (06) 842 0113

E info@structuralconcepts.co.nz

Client: Christchurch City Council

Ref: 1606

Project: Mona Vale Gatehouse

Date: 23/6/13

63 Fendalton Road, Christchurch

BY: GN

Subject: West Wall - Seismic Forces

Seismic Loads to NZS 1170.5

Sheet No.: 8


Ref:	Design	Output
Seismic weight at level i	Wi 50.64 kN	
Height at level i	hi 5.0 m	
Seismic weight at level I	Wi 123.43 kN	
Height at level I	hi 3.0 m	
Sum of Wihi	623.5	
Base shear ultimate	101.83 kN	
Base shear service	27.42 kN	
8% of base shear to be applied at top level	8.15 kN	
8% of base shear to be applied at top level	2.19 kN	
$F_i = .92V \frac{Wihi}{\sum(Wihi)}$		
<u>Ultimate</u>		
Equivalent Lateral force at level i (Roof)	46.20	924
Equivalent Lateral force at level i	55.64	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
	101.83	kN base V
	50.92	
<u>Service</u>		
Equivalent Lateral force at level i (Roof)	12.44	
Equivalent Lateral force at level i	14.98	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
Equivalent Lateral force at level i	0.00	
	27.42	kN base V

Client: **Christchurch City Council**
 Project: **Mona Vale Gatehouse**
63 Fendalton Road, Christchurch
 Subject: **West Wall URM Pier in-plane**

Ref: **1606**
 Date: **23/6/13**
 BY: **GN**

In-Plane strength of walls and piers to FEMA URM seismic guidelines

Sheet No.: **9**

Ref:	Design	Output																				
	<p>The following calculation follows the FEMA 273 guild lines for seismic rehabilitation of existing unreinforced masonry buildings (URM). This calculation is for piers or walls between window and door openings. Typically these piers are limited by diagonal tension in the panel or toe compressive stress, but bed-joint sliding shear or expected rocking strength can also limit the capacity.</p>  <p>Effective height and pier geometry may vary in the same wall assembly</p>																					
(7-1)	<p>Expected axial gravity force on pier</p> <p><u>Pier dimentions</u></p> <table> <tr> <td>Effective height of pier</td> <td>heff</td> <td>2.00</td> <td>m</td> </tr> <tr> <td>Pier length (net mortared length)</td> <td>L</td> <td>0.90</td> <td>m</td> </tr> <tr> <td>Pier thickness (net mortared width)</td> <td>Tm</td> <td>325</td> <td>mm</td> </tr> <tr> <td>Net mortared area</td> <td></td> <td>292500</td> <td>mm²</td> </tr> <tr> <td>Average bed-joint shear strength</td> <td>Vte</td> <td>1.00</td> <td>Mpa</td> </tr> </table> <p>Expected shear strength</p> $\frac{0.75 \left(0.75 V_{te} + \frac{P_{ce}}{A_n} \right)}{1.5} = V_{me} \quad 0.421 \text{ Mpa}$	Effective height of pier	heff	2.00	m	Pier length (net mortared length)	L	0.90	m	Pier thickness (net mortared width)	Tm	325	mm	Net mortared area		292500	mm ²	Average bed-joint shear strength	Vte	1.00	Mpa	
Effective height of pier	heff	2.00	m																			
Pier length (net mortared length)	L	0.90	m																			
Pier thickness (net mortared width)	Tm	325	mm																			
Net mortared area		292500	mm ²																			
Average bed-joint shear strength	Vte	1.00	Mpa																			
(7-3)	<p>Expected lateral strength is the lesser of:-</p> <p>Bed-joint shear strength</p> $V_{me} \times A_n = Q_{ce} \quad 123.2 \text{ kN}$ <p>$\alpha = 0.5$ for cantilever or 1.0 for fixed pier</p> α 1.0																					
(7-4)	<p>Expected rocking strength</p> $0.9 \alpha P_{ce} \left(\frac{L}{h_{eff}} \right) = Q_{ce} \quad 10.9 \text{ kN}$ <p>Masonry compressive strength</p> $f_m \quad 4.0 \text{ Mpa}$ <p>Diagonal tension strength</p> $V_{me} = f_{dt} \text{ in eq. (7-5) only} \quad f_{dt} \quad 0.421 \text{ Mpa}$ <p>Vertical axial compressive stress</p> $f_a \quad 0.092 \text{ Mpa}$ <p>Aspect ratio</p> $(L / h_{eff}) = 0.45$																					

Client: Christchurch City Council
 Project: Mona Vale Gatehouse
 63 Fendalton Road, Christchurch
 Subject: West Wall URM Pier in-plane

Ref: 1606
 Date: 23/6/13
 BY: GN

In-Plane strength of walls and piers continued

Sheet No.: 10

Ref:	Design	Output
(7-5)	Expected lateral strength of pier is lesser of:- Diagonal tension stress $Vdt = fdt \cdot An \left(\frac{L}{heff} \right) \sqrt{1 + \frac{fa}{fdt}}$	= QCL 61.2 kN
(7-6)	Toe compressive stress $Vtc = \alpha Pcl \left(\frac{L}{heff} \right) \left(1 - \frac{fa}{0.7 fm} \right)$	= QCL 11.7 kN
	The governing lateral force for this pier is Actual force on pier is % of NBS, proportion of NZS1170.5	10.9 kN 51.0 kN %NBS 21 %
		<u>Not acceptable</u>

APPENDIX E

MONAVALE GATEHOUSE FENDALTON ROAD, CHRISTCHURCH

LDE GEOTECHNICAL REPORT



CHRISTCHURCH CITY COUNCIL

MONA VALE GATE HOUSE, 73 FENDALTON ROAD, FENDALTON

DETAILED GEOTECHNICAL INVESTIGATION REPORT

Project Reference: 10048
12 September 2011

1 INTRODUCTION

Land Development & Exploration Ltd was engaged by Insight Unlimited on behalf of Christchurch City Council to undertake a detailed geotechnical investigation of the ground beneath buildings and land at Mona Vale Gate House, 73 Fendalton Road, Fendalton. The buildings and land were damaged by earthquake shaking, particularly from the 22 February 2011 earthquake event.

The purpose of the investigation was to assess the stratigraphy and strength distribution of the materials beneath the property to assist with the foundation design to remediate the building on it and to reduce the potential for damage that may result from future earthquake events. This included an assessment of the potential for future liquefaction and lateral spreading arising from earthquake shaking.

This work follows on from a preliminary assessment of the property in July 2011.

2 SITUATION

2.1 Location

The Gate House comprises a relatively small, predominantly two storey masonry building adjacent to Fendalton Road and the Avon River (Figure 1 and 2). LiDAR data indicates that the ground surface is about 9m above sea level.



Figure 1: View of Gate House. Main tension crack from lateral spreading in foreground (arrowed).

2.2 Building Foundations

The building foundations appear to comprise largely strip footings under load bearing walls, with suspended internal timber floors on pile foundations.



Figure 2: Aerial view of property. Fendalton Road passes along the northern side of the property and the Avon River to the right. Main tension cracks from lateral spreading shown in red.

2.3 Earthquake Damage

Much of the damage to the house appears to have been the result of extensive earthquake shaking.

However, minor to moderate settlement of the building has occurred as a result of liquefaction of the underlying ground and the subsequent loss of bearing support.

Localised lateral spreading has also occurred within the area between the house and the stream resulting in the formation of a meandering tension crack up to some 150mm wide passing along within 4m of the full length of the house (Figure 1). Minor lateral spreading has also occurred beneath the house resulting in the formation of a crack <10mm wide in the footing adjacent to Fendalton Road. A hairline crack along which sand has ejected also exists adjacent to the southwestern corner of the building.

In our opinion there is a moderate potential for the regression of the main zone of lateral spreading beneath the house from future large earthquake events.

2.4 Geotechnical Recommendations for Property

Based on the visual assessment undertaken the following recommendations were made with respect to the geotechnical issues affecting the property:

1. Repair of the footings and re-level floors as required.
2. Install a palisade wall down to the gravel layer along the river side of the building to minimise the potential for regression of lateral spreading.

3 DETAILED INVESTIGATIONS

The detailed investigation of the site included the following work:

- A desk top study of published and unpublished information of the site.
- A walkover assessment of the site and surrounding area to assess its geomorphology and any features which may potentially influence the long term behaviour of the site.
- Two electronic cone penetrometer tests (CPTs) put down to refusal (2.5m to 2.8m depth) using a specialist rig.
- Three 50mm handaugered boreholes put down to refusal ranging between 1.2m and 1.7m depth. Measurements of the undrained shear strength were taken at 200mm intervals within cohesive soils encountered down through the boreholes using a calibrated shear vane. The soils encountered were generally logged to NZ Geotechnical Society Logging Guidelines for the field classification of soil and rock for engineering purposes.
- One dynamic penetrometer test put down to refusal (1.9m depth). The penetrometer tests were measured in 50mm increments to better identify lower strength zones beneath the surface.
- Observations and measurements of the soil moisture content and levels of groundwater encountered down through the boreholes. The possible seasonal variation of these levels was noted and compared to the regional groundwater table expected for the area and the timing of the investigation.

The locations of the subsurface investigations are shown in the Geotechnical Investigation Plan appended. Logs of the boreholes and penetrometer tests are also appended.

The field work was completed in winter.

All work was completed by qualified geological/geotechnical specialists.

4 ENGINEERING GEOLOGY

4.1 General

The engineering geology of the site is summarised below and in the appended cross section (Appendix B). It is based on an integration of published and unpublished data, the geomorphology of the site, and subsurface investigations carried out at discrete locations. The nature of the ground between the investigation points is inferred and may vary from that described. For details of the materials encountered and measurements of their respective strengths please review the appended investigation logs.

4.2 Subsurface Conditions

The investigations show that the building is generally underlain by generally low strength soils overlying very dense sand and gravel present from 1.7m depth,

More specifically, stiff to very stiff silty clay, clayey silt and silt generally underlie the site down to about 0.8m depth.

These low strength layers overlie loose to medium dense sand and gravel down to 1.7m depth beneath the western side and central building areas and firm silty clay down to 1.7m depth beneath the road (Cross Section).

Very dense sand and gravel is present below 1.7m depth and was not able to be penetrated by the boreholes and penetrometer tests. However regional investigations undertaken by the Earthquake Commission indicate it is some 2.5m thick and extends down to 6.5m RL. Loose silt, firm clayey silt and loose to medium dense sand some 3m thick are indicated to underlie the gravel down to some 4m RL, and to overlie a thick layer of dense gravelly sand.

Non-engineered fill up to 1.2m thick is present beneath the eastern side of the building and possibly extends out towards the river bank to the east. Fill was also encountered to 0.3m depth along the northern side. Fill was absent at the rear of the property. The fill includes brick and concrete, and is variable in strength ranging between 50kPa and 160kPa (average 120kPa).




Figure 3: CPT 2 put down to the east of building showing typical ground profile beneath property

4.3 Soil Moisture Profile and Groundwater Conditions

Groundwater was encountered at 1.0m to 1.2m depth in the boreholes, which is consistent with the level of the Avon River. However, wet to saturated soils were encountered from 0.5m depth.

4.4 Site Subsoil Category

We consider that the site is a Class D deep soil site as defined by NZS 1170.5 (2004) "Structural Design Actions: Part 5: Earthquake actions – New Zealand".

Assuming a building importance level of 2, the following peak ground accelerations are considered appropriate for seismic analyses and design:

Ultimate Limit State event: 0.34g
Serviceability Limit State: 0.11g

Note that the SLS value has been calculated using a risk factor (R_s) of 0.33.

The following earthquake magnitudes are estimated¹ from the peak ground accelerations assuming rupture on a fault line beneath the Port Hills, some 10km to the southeast of the site.

Ultimate Limit State event: M 6.6

Serviceability Limit State: M 5.1

5 GROUND DEFORMATION POTENTIAL

5.1 Liquefaction Potential and Resultant Deformations

Analyses have been carried out using specialist software to determine what material layers beneath the site are likely to be prone to liquefaction under ULS and SLS design conditions, the resultant potential settlement at the surface due to consolidation of the liquefied sand layers, possible dry settlement due to shaking, building settlement due to the potential loss of ground bearing capacity as a result of the liquefaction of the near surface soils, and the potential for sand boil development at the surface. A review of the layers that are likely to have liquefied during the 22 February and 13 June 2011 earthquake events was also carried out using measured peak ground acceleration data.

5.1.1 Layers Subject to Liquefaction

SLS Conditions

No layers are predicted to liquefy during a SLS seismic event.

ULS Conditions

The analyses show that the saturated sandy layer at 1.4m to 1.6m beneath the surface building is likely to be prone to liquefaction during an ULS seismic event (see Figure 5). The underlying very dense layer is not shown to have the potential to liquefy.

We expect that the silt and sand layers within the 3m of fine alluvium below the gravel layer are also likely to be prone to liquefaction under ULS seismic loads.

22 February M6.3 earthquake

The analyses show that the medium dense to dense layers beneath the site at depth are likely to have liquefied during the February 22 M6.3 earthquake event (see Figure 6). Despite this, the dense sand from 3.8m to 6.4m depth is unlikely to have liquefied and is therefore expected to be a suitable bearing layer.

¹ Estimation using chart in Youd, Leslie, and Bartlett (2002) 'Revised Multilinear Regression Equations for Prediction of Lateral Spread Displacement'




Figure 4: Layer beneath site shown to be prone to liquefaction.

5.1.2 Surface Settlement due to Liquefaction and Dry Settlement

The predicted surface settlement for each test location is presented below in Table 1.

Table 1: Potential surface settlements due to liquefaction *

CPT	Settlement (mm) for Serviceability Limit State	Settlement (mm) for Ultimate Limit State
	Event	Event
CPT1	0mm	2mm
CPT2	0mm	1mm

* surface settlement potential may be greater due to liquefaction potential of layers below gravel layer.

Serviceability Limit State Conditions

In summary, no settlement is predicted to occur as result of a SLS earthquake event.

Ultimate Limit State Conditions

The potential surface settlement beneath the building under ULS conditions is shown to be negligible. The magnitude of surface settlement may be higher due to the potential for liquefaction of the fine alluvium beneath the gravel layer. However, we expect that the total settlement would be less than 25mm. We also expect that the very dense gravel layer would inhibit adverse surface deformation due to settlement of the layers at depth.

Negligible differential settlement is expected from future ULS seismic events.

5.1.3 Building Settlement due to Loss of Bearing Capacity

The potential for punching failure or settlement of the building foundations due to liquefaction of the ground at 1.4m to 1.6m depth beneath the building has been assessed for each seismic condition. A footing width of 0.3m has been assumed, as has an undrained shear strength of the liquefied layer of 5kPa estimated using the Seed and Harder (1990) methodology.

SLS conditions

Building settlement due to a loss of ground strength beneath the foundations or punching shear failure is not expected under SLS seismic conditions.

ULS Conditions

The analyses indicate that the bearing capacity of the near surface soils is likely to be reduced under ULS seismic conditions due to the loss of strength of the liquefied layer below the groundwater table. Assuming 0.4m deep foundations are used analyses show that settlement of the building foundations could occur under ULS seismic conditions (estimated up to 75mm), which is consistent with the observed foundation settlement of parts of the building following the 22 February 2011 earthquake event.

Accordingly, to avoid adverse settlements following a future ULS seismic event we recommend that the replacement strip footings be limited to depths less than 0.4m, unless supported on piled foundations taken to the dense sand and gravel from 1.6m depth.

5.1.4 Sand Boil Potential

No sand boiling is expected for a SLS earthquake event, however given the potential for liquefaction within the near surface soils below the groundwater table there is some potential for the development of sand boils and fissures at the surface as a result of a ULS seismic event. However, as the near surface soil layer is thin the volume of sand ejecta is not expected to be great. This is consistent with the limited extent of sand ejecta adjacent to the building following the 22 February and 13th June earthquake events.

5.2 Lateral Spreading Potential

A tension crack up to 150mm wide passes along the eastern side of the building. The size of the crack is consistent with the magnitude of lateral spreading calculated for the liquefied layer at 1.4m depth.

Lateral spreading through the alluvium beneath the gravel may have occurred from the February event although the effects of this are not evident. We expect that deformations from future event will be restricted to the upper 1.6m of soils.

For a future ULS event 150mm is predicted to occur 10m from the river, while 80mm may occur at the rear of the site 30m from the river. Some 70mm of extension may occur across the site from future ULS events, which should be taken into account with the design of any replacement foundations.

5.3 Compressible Ground and Consolidation Settlement

While the 1.1m to 1.2m thick layer of fill encountered beneath the southern end of the site appears to be non-engineered, it was found to be stiff to very stiff in strength with an estimated allowable bearing capacity of 70kPa. Limiting the foundation pressures to this is recommended.

5.4 Ground Shrinkage and Swelling Potential

The near surface soils appear to be slightly expansive to non-expansive soils with a liquid limit below 50% based on their physical characteristics determined during testing. We consider that the effects of soil shrinkage and swelling on the foundations due to seasonal changes in soil moisture is not likely to adversely affect the building.

6 ENGINEERING RECOMMENDATIONS

6.1 Strip and Pad Footings

Should replacement strip or pad footings be required for the reconstruction of the house we make the following recommendations.

Depth

For design we recommend strip footings and any pad footings be taken to a depth of 0.4m depth.

Bearing Capacity

At that depth a geotechnical ultimate, factored [ULS, $\Phi=0.5$] and allowable [FoS=3] bearing capacity of 210kPa, 140kPa and 70kPa is recommended.

6.2 Piles

Purpose

Piles taken into the dense sand and gravel layer present from 1.7m depth are recommended along the eastern side of the property to provide shear resistance against lateral spreading through the overlying low strength sediments immediately above that depth, and also to provide resistance for regression of tension cracking beneath the eastern wing of the building.

Pile Depth

A minimum pile depth of 2.0m is recommended.

Lateral Load Considerations

Potential lateral movement of 100mm towards the river of the soils to 1.6m depth can be assumed.

Fixity can be assumed to exist at 1.7m depth.

End Bearing Capacity

Should the piles be used for bearing, at 2m depth geotechnical ultimate, factored (ULS, $\Phi=0.5$) and allowable ($FoS=3$) end bearing capacities of 5400kPa, 2700kPa, and 1800kPa respectively can be used for bored and cast insitu piles.

Skin Friction

A geotechnical ultimate, factored (ULS, $\Phi=0.5$) and allowable ($FoS=3$) skin friction of 50kPa, 25kPa, and 17kPa can be assumed for static load conditions. This should be reduced by 25% for ULS seismic conditions.

Construction Issues

The excavations for bored piles may be subject to collapse below the groundwater table, although the cohesive nature of some of the alluvial layers may limit this to a certain degree.

Driven piles are unlikely to be able to be driven into the dense sand and gravel and excessive shaking could damage the building as a result.

6.3 Verification Checks

Verification testing of the ground by a Christchurch City Council Building Inspector or Suitably Qualified Professional is recommended to ensure that the ground conditions at


the base of the foundation excavations are as described in this report, and that all unsuitable and loose materials have been removed. We should be contacted immediately if these conditions vary from that described in this report. A modification to the recommendations or design may be required.

7 OTHER CONSIDERATIONS

This report has been prepared exclusively for Insight Unlimited on behalf of the Christchurch City Council with respect to the particular brief given to us. Information, opinions and recommendations contained in it can not be used for any other purpose or by any other entity without our review and written consent. Land Development & Exploration Ltd accepts no liability or responsibility whatsoever for or in respect of any use or reliance upon this report by any third party.

Opinions given in this report are based on visual methods, and subsurface investigations at discrete locations. The nature and continuity of the subsurface materials between these locations are inferred and it must be appreciated that actual conditions could vary from that described herein. We should be contacted immediately if the conditions are found to differ from that described in this report.

Yours faithfully
LAND DEVELOPMENT & EXPLORATION LTD



Georg Winkler
Geological & Geotechnical Engineer
MIPENZ, CPEng
Managing Director

\\sbs\documents\LDE Projects\10000 to 10099\10048 Insight Chch Building Investigations\Stes\Mona Vale\Gate House\Detailed Investigation Report\10048 GEW 07092011 Mona Vale Gate House Detailed Investigation Report.doc

APPENDIX A
GEOTECHNICAL INVESTIGATION PLAN


APPENDIX F

MONAVALE GATEHOUSE FENDALTON ROAD, CHRISTCHURCH


LEVEL SURVEY

1650

Mona Vale - Gate house Interior
heights Survey



Mona Vale - Gate house exterior
heights survey



APPENDIX G

MONAVALE GATEHOUSE
FENDALTON ROAD, CHRISTCHURCH

CERA BUILDING EVALUATION FORM

Location	Building Name: <input type="text" value="Monavale Gatehouse"/>	Unit No.: <input type="text" value="Street"/>	Reviewer: <input type="text" value="Garry Newton"/>
Building Address: <input type="text" value="63 Fendalton Road"/>	Legal Description: <input type="text"/>	CPEng No.: <input type="text" value="65305"/>	
GPS south: <input type="text"/>	GPS east: <input type="text"/>	Company: <input type="text" value="Structural Concepts Ltd"/>	
Degrees: <input type="text"/>	Min: <input type="text"/>	Company project number: <input type="text" value="1605"/>	
Sec: <input type="text"/>	Company phone number: <input type="text" value="08420111"/>		
Building Unique Identifier (CCC): <input type="text"/>	Date of submission: <input type="text" value="30/03/2013"/>		
	Inspection Date: <input type="text" value="5-Aug"/>		
	Revision: <input type="text"/>		
Is there a full report with this summary? <input type="checkbox"/> yes			
Site	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text" value="0"/>	
Soil type: <input type="text" value="soft sand"/>	Soil Profile (if available): <input type="text"/>		
Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground Improvement on site, describe: <input type="text" value="settlement locality"/>		
Proximity to waterway (m, if <100m): <input type="text" value="50"/>	Approx site elevation (m): <input type="text" value="6.00"/>		
Proximity to cliff top (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m, if <100m): <input type="text"/>			
Building	No. of storeys above ground: <input type="text" value="2"/>	single storey = <input type="checkbox"/>	Ground floor elevation (Absolute) (m): <input type="text" value="6.00"/>
Ground floor sp?: <input type="checkbox"/> no	Ground floor elevation above ground (m): <input type="text" value="6.00"/>		
Storeys below ground: <input type="text" value="0"/>			
Foundation type: <input type="text" value="strip footings"/>	if Foundation type is other, describe: <input type="text"/>		
Building height (m): <input type="text" value="7.00"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>		
Floor footprint area (approx): <input type="text" value="60"/>	Date of design: <input type="text" value="Pre 1935"/>		
Age of Building (years): <input type="text" value="103"/>			
Strengthening present? <input type="checkbox"/> no	If so, when (year)? <input type="text"/>		
Use (ground floor): <input type="text" value="other (specify)"/>	And what load level (%)? <input type="text"/>		
Use (upper floors): <input type="text" value="public"/>	Brief strengthening description: <input type="text"/>		
Use notes (if required): <input type="text" value="Residential"/>			
Importance level (to NZS1170.5): <input type="text" value="L2"/>			
Gravity Structure	Gravity System: <input type="text" value="load bearing walls"/>	rafter type, purlin type and cladding: <input type="text" value="timber/camber/clay tiles on sarking"/>	
Roof: <input type="text" value="timber framed"/>	joist depth and spacing (mm): <input type="text" value="300x450"/>		
Floors: <input type="text" value="timber"/>	type: <input type="text" value="timber"/>		
Beams: <input type="text" value="timber"/>	typical dimensions (mm x mm): <input type="text" value="300x100"/>		
Columns: <input type="text" value="brick masonry"/>	#NA: <input type="text"/>		
Walls: <input type="text" value="load bearing brick"/>			
Lateral load resisting structure	Lateral system along: <input type="text" value="other (note)"/>	Note: Define along and across in detailed report! <input type="text"/>	describe system: <input type="text" value="URM shear walls"/>
Ductility assumed, μ : <input type="text" value="1.00"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Period along: <input type="text" value="0.40"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Total deflection (ULS) (mm): <input type="text" value="30"/>	estimate or calculation?: <input type="checkbox"/> estimated		
maximum interstorey deflection (ULS) (mm): <input type="text" value="10"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Lateral system across: <input type="text" value="other (note)"/>	describe system: <input type="text" value="URM shear walls"/>		
Ductility assumed, μ : <input type="text" value="1.00"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Period across: <input type="text" value="0.40"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Total deflection (ULS) (mm): <input type="text" value="30"/>	estimate or calculation?: <input type="checkbox"/> estimated		
maximum interstorey deflection (ULS) (mm): <input type="text" value="10"/>	estimate or calculation?: <input type="checkbox"/> estimated		
Separations:	north (mm): <input type="text"/>	leave blank if not relevant	
east (mm): <input type="text"/>			
south (mm): <input type="text"/>			
west (mm): <input type="text"/>			
Non-structural elements	Stairs: <input type="text" value="timber"/>	describe supports: <input type="text" value="walls"/>	
Wall cladding: <input type="text" value="other heavy"/>	describe: <input type="text" value="stone"/>		
Roof Cladding: <input type="text" value="heavy tiles"/>	describe: <input type="text" value="concrete tiles"/>		
Glassing: <input type="text" value="timber frames"/>			
Ceilings: <input type="text" value="fibrous plaster, fixed"/>			
Services (list): <input type="text" value="lights"/>			
Available documentation	Architectural: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="unknown"/>	
Structural: <input type="text" value="none"/>	original designer name/date: <input type="text"/>		
Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text"/>		
Electrical: <input type="text" value="none"/>	original designer name/date: <input type="text"/>		
Geotech report: <input type="text" value="full"/>	original designer name/date: <input type="text" value="LDE"/>		
Damage	Site performance: <input type="text" value="average"/>	Describe damage: <input type="text" value="some lateral spreading away from the main building not in the direction of the main fault line"/>	
(refer DEE Table 4-2)	Settlement: <input type="text" value="25-100mm"/>	Notes (if applicable): <input type="text" value="settlement to one corner"/>	
	Differential settlement: <input type="text" value="1.350-1.250"/>	notes (if applicable): <input type="text"/>	
	Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
	Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
	Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
	Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>	
	Damage to area: <input type="text" value="moderate to substantial (1 in 5)"/>	notes (if applicable): <input type="text"/>	
Building:	Current Placard Status: <input type="text" value="red"/>		
Along:	Damage ratio: <input type="text" value="43%"/>	Describe how damage ratio arrived at: <input type="text" value="assumed level of cracking and loss of chimneys assessed"/>	
	Describe (summary): <input type="text" value="cracking to walls and ceilings, Collapse of chimneys, Collapse of some URM"/>		
Across:	Damage ratio: <input type="text" value="67%"/>	Damage Ratio = $\frac{(\%NBS\text{ (before)} - \%NBS\text{ (after)})}{\%NBS\text{ (before)}}$	
	Describe (summary): <input type="text" value="cracking to walls and ceilings, Collapse of chimneys, Collapse of some URM"/>		
Diaphragms:	Damage?: <input type="checkbox"/> yes	Describe: <input type="text" value="cracking to lath and plaster"/>	
CSWs:	Damage?: <input type="checkbox"/> yes	Describe: <input type="text" value="diaphragm connection"/>	
Pounding:	Damage?: <input type="checkbox"/> no	Describe: <input type="text"/>	
Non-structural:	Damage?: <input type="checkbox"/> yes	Describe: <input type="text" value="cracks to walls and ceilings"/>	
Recommendations	Level of repair/strengthening required: <input type="text" value="significant structural"/>	Describe: <input type="text" value="cracking to walls and replacing of URM"/>	
	Building Consent required: <input type="checkbox"/> yes	Describe: <input type="text" value="loss of chimneys"/>	
	Interim occupancy recommendations: <input type="text" value="do not occupy"/>	Describe: <input type="text"/>	
Along:	Assessed %NBS Before: <input type="text" value="21%"/>	Assessed %NBS After: <input type="text" value="12%"/> ##### %NBS from IEP below	
Across:	Assessed %NBS Before: <input type="text" value="21%"/>	Assessed %NBS After: <input type="text" value="7%"/> ##### %NBS from IEP below	
		If IEP not used, please detail: <input type="text" value="static analysis and spreadsheet calculation assessment methodology"/>	