

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

Our Ref: 1605

31 July 2011

Insight Unlimited Ltd
P.O Box 1219
GISBORNE 4040

Attention: John Radburn

Dear John,

Re: Mona Vale Homestead – POST-EARTHQUAKE INSPECTION

Scope of this Report

This report covers our assessment of the structural condition of the Mona Vale Homestead building at Fendalton Road, Fendalton, Christchurch, following the magnitude 6.3 earthquakes on 2nd February 2011 and that of the 13 June 2011. Our assessment is based on a visual inspection of the outside and inside where it was deemed to be safe to enter. This was carried out on the 22nd June 2011 and 28th July 2011.

This report describes the damage observed, and comments on remedial work options for both temporary securing of the building, and long term repair where appropriate. This report is preliminary only and does not cover a detailed structural strength assessment or detailed specification of remedial works but does provide some investigation and assumptions that will allow an assessment to be made as to whether to reconstruct or demolish.

1. Scope of Investigation

On the 22nd June 2011 and 28th July 2011, we visually inspected the building including:

The exterior from ground level
The interior

This report is based on our assessment of the building at the time stated. Photos attached in Appendix A are indicative of the damage. Any subsequent loading by aftershocks, or high winds, may initiate further damage.

2. Building Description

General description:

The Mona Vale Homestead is a two storey gable roof structure consisting of double skin unreinforced brick walls with timber framed floors to the lower level, solid plaster walls on

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

timber framing with timber framed floors to the upper level, and timber framed roof structure with clay tile roofing. The building is constructed in an “L” shape structural form. The building is shown in the attached plans in appendix C and is approximately 280m² first floor and 390m² ground floor.

The building was first constructed 1910.

The building was being used as a Restaurant, but is currently unoccupied due to earthquake damage. The main occupancy classification in NZS1170 is C1 (Restaurants) and B (Communal Kitchens) and importance level of 2. The occupant load is calculated at 170 as classified by the Building Code Clause C table 2.2.

Roof construction:

Clay Tiles on sarking on timber framing.

First Floor External Wall construction:

Solid Plaster walls on timber framed walls with sarking and plaster board over to inside face.

First Floor Internal Wall construction:

Light timber framed walls with plaster linings.

First Floor Floor construction:

T&G Flooring on timber floor joists supported on timber beams, timber walls and brick walls.

Ground Floor External Wall construction:

Double skin unreinforced brick walls with sarking and plaster board over to inside face.

Ground Floor Internal Wall construction:

Unreinforced brick walls with sarking and plaster board over plus light timber framed walls with plaster linings.

Ground Floor Floor and Foundation construction:

T&G Flooring on timber floor joists supported on timber bearers on piles, with a concrete perimeter foundation wall (assumed unreinforced).

Structural System:

The gravity structural system can be described as simple beam and post/wall support. The structural system can be described as face loaded unreinforced masonry supported at foundation level and ceiling/roof level with nominal diaphragms taking loads back to unreinforced masonry walls acting in-plane. Load then transfers to mass concrete foundations to the ground.

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

3. Strength

The strength of the building has been determined as a % NBS using methodologies provided by NZSEE.

Before September 2010:

The strength of the building before September 2010 is estimated as

Dining Wing

First Floor

Hazard factor 0.22 (pre 19th May 2011) 56% NBS

Hazard factor 0.3 (post 19th May 2011) 41% NBS

Ground Floor

Hazard factor 0.22 (pre 19th May 2011) 45% NBS

Hazard factor 0.3 (post 19th May 2011) 33% NBS

Office Wing

First Floor

Hazard factor 0.22 (pre 19th May 2011) 65% NBS

Hazard factor 0.3 (post 19th May 2011) 88% NBS

Ground Floor

Hazard factor 0.22 (pre 19th May 2011) 57% NBS (governed by face loading on brick walls)

Hazard factor 0.3 (post 19th May 2011) 42% NBS (governed by face loading on brick walls)

On day of inspection:

The strength of the building on the day of inspection is estimated as

Dining Wing

First Floor

Hazard factor 0.3 (post 19th May 2011) 35% NBS (estimated only)

Ground Floor

Hazard factor 0.3 (post 19th May 2011) 5% NBS (estimated only)

Office Wing

First Floor

Hazard factor 0.3 (post 19th May 2011) 50% NBS (estimated only)

Ground Floor

Hazard factor 0.3 (post 19th May 2011) 35% NBS (estimated only)

It must be understood that this strength is based on the overall building strength and not individual elements. It is clear that some individual elements in fact have an even lower strength due to local cracking etc and as low as 0% in places. Furthermore this estimate is based on the fact that there is now significant cracking and lose of adhesion between bricks thus making the structure vulnerable as was shown on the north west wall of the dining wing with the continual collapse of the wall veneer and structural wall.

3. Damage Description

Damage caused by the February earthquake to the Mona Vale Homestead is described below. Damage described is that observed on the day and indicated on the L2 reports. Refer to Appendix B for marked-up drawings and sketches from the L2 reports indicating damaged locations.

i. General Damage to Exterior Walls:

General damage includes cracking of masonry walls, foundations and columns.

ii. Damage to Dining Wing:

This Section has suffered severe cracking to the brick walls both in the veneer and structural elements. The northwest wall veneer has partially collapsed and the structural wall has bricks dislodging. This section of wall is at high risk of collapse. The stair outer wall has partially collapsed.

The other walls have diagonal cracking with widths of up to 10mm to 20mm in places.

Bricks have become dislodged in some arch areas.

Ceilings have large cracks and are significantly damaged.

iii. Damage to Office Wing:

The brick walls have general cracking only with plaster walls also suffering general damage. Ceilings have general cracking.

iv. Damage to Internal Walls:

There is severe cracking to all internal brick walls in the Dining wing in the north south direction. The fire place and toilet block walls have large structural cracks. Plastered timber framed walls have suffered general damage.

v. Damage to Ceilings:

Ceilings have been significantly damaged at the Dining wing of the building with a lesser degree of damage occurring to ceilings in the Office wing. Damage ranges from severe across the whole ceiling to severe around edges to minor cracking.

vi. Collapse of brick chimneys:

The brick chimneys have collapsed or are damaged and have been removed. The chimneys have caused significant damage to the roof immediately adjacent where they pass through same.

vii. Damage to Roof:

The roof has remained relatively undamaged to the naked eye. However with the amount of relative movement in the walls some damaged is likely to have occurred.

viii. Other damage:

Cracked glass to some windows.

Minor cracking was found in the ring foundation.

4. Immediate Securing of the Building

The following works are required to mitigate immediate hazards, temporarily secure the building, and provide weather tightness:

Fence off site completely and restrict access up to 10m from exterior face of gables and 6m from eaves.

Provide temporary support and bracing to the Northern end of the dining wing to the where walls have fallen away. Remove remainder of bricks.

Provide temporary support and bracing to the roof to the stairwell exterior wall where bricks have dislodged or fallen away. Remove remainder of bricks.

This wall is to be either deconstructed or propped temporarily as described in the L2 report.

Provide temporary support and bracing to the upper floor where there support is collapsing.

Further calculations and detail confirming this is still required and should be discussed in conjunction with the Contractor who will carrying out this work and yourselves.

Due care, safety equipment and precautions must be taken when carrying out the above work. Maintain awareness of fall hazards and escape routes if entering the building.

5. Long Term Repair

This section of the report outlines options for repair to restore the building to a minimum 67% NBS. In most areas over 100%NBS is obtained especially where we have added new elements. We are of the opinion that if the repair costs were within acceptable budget and the building was deemed significant enough to repair then this is possible. However we are of the opinion that the internal masonry walls and structural portions of the exterior masonry walls need to be replaced in the Dining area to remove these hazards. Options for repair and/or strengthening will ultimately need to be discussed with the owner, and will be subject to revised local authority legislation.

i. Exterior Walls:

Two options are available

1. Strengthening could be successfully completed by removing the internal brick skin and replacing it with a new timber framed wall. Tying the external skin to the new framing. Install new linings to provide any bracing required. Install conventional ceiling diaphragms. Steel studs will be required adjacent windows to support any concrete lintels. This option is likely to bring the building back up to 100%NBS by default.
2. Strengthening could be completed the installation of ceiling diaphragms and substantial fixings between diaphragm and walls. Walls will require strengthening for face loading via ties being installed between the brick skins (e.g. Helifix Cementie)

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

and either filling the cavity or installing steel mullions internally. This option is likely to bring the building back up to 67%NBS without.

The exterior brick veneer is heavily damaged in places and repair would be by complete deconstruction of these section and reconstruction using modern methods and design tying properly to new or strengthened structural walls either timber or strengthened masonry. Where crack widths are less than 3mm then these can be stitching outer masonry veneer skin to the main inner structural brickwall or new timber framed wall with Helifix Helibars and Cemties in accordance with Helifix specifications at 400mm vertically by 600mm horizontally. All ties to be grouted both sides. Install ties through mortar lines on exterior face so that this can be easily re-plastered over to match original surface.

ii. Interior Walls:

Two options are available

1. Strengthening could be completed the installation of ceiling diaphragms and substantial fixings between diaphragm and walls. Walls will require strengthening for face loading via ties being installed between the brick skins (e.g. Helifix Cemtie) and either filling the cavity or installing steel mullions internally.
2. Strengthening could be successfully completed by completely removing the brick walls and replacing them with new timber framed walls. Install new linings to provide any bracing required. Install conventional ceiling diaphragms. Steel studs will be required to support any internal concrete beams.

Either option is likely to bring the building back up to 100%NBS by default.

We recommend that all internal Brick walls be demolished and reconstructed using modern materials and design.

iii. Foundations General Cracking:

Seal all cracks in concrete foundation wall larger than 0.2mm with a pressure injected epoxy (e.g. Sikadur injectokit and Sikadur520), or similar). Seal smaller cracks by painting over with a brushable crack filler (e.g. Resene Brushable Crack Filler).

iv. Veneer Face of Masonry walls General and Office Wing Masonry Walls:

Repair cracks that are less than 3mm width by filling cracks with grout and stitching with Helifix Helibars in accordance with Helifix specifications. Repair all cracked arch lintels by stitching with Helifix Helibars and Cemties in accordance with Helifix specifications. Stitch outer masonry veneer skin to the main inner structural brickwall with Helifix Helibars and Cemties in accordance with Helifix specifications at 600mm vertically by 800mm horizontally. All ties to be grouted both sides. Install ties through mortar lines on exterior face so that this can be easily re-plastered over to match original surface.

v. General cracks to plaster Walls and Ceilings generally:

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

Remove cracked/peeling/bubbled wallpaper to expose damaged Internal walls linings. Repair as appropriate using one of the following: Grind-out v-shape into cracked plaster. Re-plaster and overlay crack with fibreglass reinforcing mesh. Re-plaster over to provide a smooth finish. Remove lath and plaster walls and replace with Braceline GIB, or plaster over corru-lath/rib-lath. In all cases, wall ties and hold-down straps should be installed in accordance with GIB braced wall and ceiling diaphragm specifications. Realign, re-fix and re-paint racked door frames and architraves.

Reducing the weight of the building will assist in the above options so replacement of the structural and internal brickwalls will play an important part in these decisions.

The costs associated with the repairs would require the appropriate professional to visit the site to view the extent of damage. At this stage we have not provided any specific detailing for repair works but can so at your request.

7. Elements Not Inspected

The following is a list of elements not specifically inspected:

- Subfloor construction
- Piles
- Soils (Geotechnical preliminary report by others was reviewed)

8. Limitations

Findings presented in this report are for the sole use of the client. The findings may not contain sufficient information for use by other parties, and as such should not be relied upon unless discussed with Structural Concepts Ltd. We have exercised our services in a professional manner using a degree of care and skill normally, under similar circumstances, by reputable consultants practicing in this field at this time. No other warranty, expressed or implied, is made as to the professional advice presented in this report.

Yours faithfully
STRUCTURAL CONCEPTS LTD



Garry Newton
BE (Civil), MIPENZ(Civil, Structural), CPEng, IntPE(NZ)

Director

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

APPENDIX A. PHOTOGRAPHS

Please note that the photographs provided in this report are not high quality and are for providing information that shows the indicative damage found around the building for structural engineering assessment only.

















STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

APPENDIX B. L2 REPORT & MARKED-UP DRAWING INDICATING DAMAGED LOCATIONS

Christchurch Eq RAPID Assessment Form - LEVEL 2

Inspector Initials
Territorial Authority

SG
Christchurch City

Date
Time

3/3/2011
3:30pm

Final Posting
(e.g. UNSAFE)

R1 UNSAFE

Building Name

Mona Vale Homestead

Short Name

Address

Fendolton Rd.

GPS Co-ordinates

S^e E^e

Contact Name

Greg Ward

Contact Phone

021 221 7022

Storeys at and above
ground-level

2

Below
ground
level

0

Total gross floor area
(m²)

Year built

1899 -

1903

No of residential Units

Nil

Type of Construction

☒ Timber frame (1st floor)

☐ Steel frame

☐ Tilt-up concrete

☐ Concrete frame

☐ RC frame with masonry infill

☐ Concrete shear wall

☒ Unreinforced masonry (ground floor)

☐ Reinforced masonry

☐ Confined masonry

☐ Other:

Primary Occupancy

☐ Dwelling

☒ Commercial/ Offices

☐ Other residential

☐ Industrial

☐ Public assembly

☐ Government

☐ School

☒ Heritage Listed

☐ Religious

☐ Other

Photo Taken

Yes

No

Investigate the building for the conditions listed on page 1 and 2, and check the appropriate column. A sketch may be added on page 3

Overall Hazards / Damage

Minor/None

Moderate

Severe

Comments

Collapse, partial collapse, of foundation

☒

☐

☐

Building or storey leaning

☒

☐

☐

Wall or other structural damage

☐

☐

☒

Overhead falling hazard

☐

☐

☒

Ground movement, settlement, slips

☒

☐

☐

Neighbouring building hazard

☒

☐

☐

Electrical, gas, sewerage, water, hazards

☒

☐

☐

Record any existing placard on this building:

Existing
Placard Type
(e.g. UNSAFE)

INSPECTED

Choose a new posting based on the new evaluation and team judgement. Severe conditions affecting the whole building are grounds for an UNSAFE posting. Localised Severe and overall Moderate conditions may require a RESTRICTED USE. Place INSPECTED placard at main entrance. Post all other placards at every significant entrance. Transfer the chosen posting to the top of this page.

INSPECTED

GREEN

G1

G2

RESTRICTED USE

YELLOW

Y1

Y2

UNSAFE

RED

R1

R2

R3

Record any restriction on use or entry

Further Action Recommended

Tick the boxes below only if further action is recommended

☒ Sanitisation is needed (state location) In place

☒ Detailed engineering evaluation recommended

☒ Structural

☐ Geotechnical

☐ Other:

☐ Other recommendations:

Estimated Overall Building Damage (Exclude Contents)

None

☐

0-1 %

☐

31-60 %

☒

2-10 %

☐

61-99 %

☐

11-30 %

☐

100 %

☐

Inspection ID: (Office Use Only)

Sign here on completion

Date & Time
ID

3/3/2011 3:50pm
SG-Stratex
021 462 723

Structural Hazards/ Damage

	Minor/None	Moderate	Severe	Comments
Foundations	☒	☐	☐	Minor cracking to foundation wall at isolated location?
Roofs, floors (vertical load)	☒	☒	☐	Brick arches supporting first floor cracked and leaning outwards.
Columns, pilasters, corbels	☐	☒	☐	Severe damage to brick bay window adjacent stairwell - wall partially collapsed.
Diaphragms, horizontal bracing	☐	☐	☒	Moderate to severe cracking to brick walls around restaurant area.
Pre-cast connections	N/A ☒	☐	☐	Chimneys taken down. Several loose roof tiles.
Beam	☒	☐	☐	Cracked window panels around restaurant.
Non-structural Hazards / Damage				Cracking to bath & plaster ceiling in place.
Parapets, ornamentation	☒	☐	☐	Minor cracking to internal walls.
Cladding, glazing	☒	☐	☐	Brick pier supporting balcony dislocated at top and on lean.
Ceilings, light fixtures	☐	☒	☐	
Interior walls, partitions	☒	☐	☐	
Elevators	N/A ☐	☐	☐	
Stairs/ Exits	☒	☐	☐	
Utilities (eg. gas, electricity, water)	☒	☐	☐	
Other	☐	☐	☐	
Geotechnical Hazards / Damage				
Slope failure, debris	☒	☐	☐	
Ground movement, fissures	☒	☐	☐	
Soil bulging, liquefaction	☒	☐	☐	


General Comment

Usability Category

Damage Intensity		Posting	Usability Category	Remarks
Light damage	Inspected (Green)	G1. Occupiable, no immediate further investigation required		
Low risk		G2. Occupiable, repairs required		
Medium damage	Restricted Use (Yellow)	Y1. Short term entry		
Medium risk		Y2. No entry to parts until repaired or demolished		
Heavy damage	Unsafe (Red)	R1. Significant damage: repairs, strengthening possible		
High risk		R2. Severe damage: demolition likely		
		R3. At risk from adjacent premises or from ground failure		

2 Inspection ID: _____ (Office Use Only)

Sketch (optional)
Provide a sketch of the entire building or damage points. Indicate damage points.



Recommendations for Repair and Reconstruction or Demolition (Optional): temporary remedial works

- Take photos of building to allow accurate reconstruction.
- Prop brick archways.
- Prop balcony.
- Remove outer top bricks of leaning balcony column.
- Attempt to push balcony column back into place.
- ~~Attempt to push~~ Clear debris between cracks in ^{adjacent entrance arch} brick wall. Attempt to push brick in archway and wall back in place.
- Remove outer brick veneer at restaurant walls which are diagonally cracked to expose interior structural walls for engineer to view. Further works to then be advised.
- Remove exterior brick veneer from damaged bay window. Prop roof with forklift/rack loader. Expose damaged brick wall behind for engineer to view.
- Engineer to complete detailed seismic assessment and strengthening report.

Note: In all cases, retain existing brick for re-use.



damage to walls to drawing room



damage to walls to drawing room



damage to columns to patio area



damage to walls to drawing room



damage to walls to dining room



damage to chimney in entry lobby



damage to wall in office



damage to wall around stair lobby



CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF
MONVALE HOMESTEAD CHRISTCHURCH
Reference Plan Ground Floor



Structural Concepts S03 0

REV/DATE DESCRIPTION

PRELIMINARY
for client approval
10th August 2011
SHEET 1805
REV 0

DATE Aug 2011
ACA2011 A3
DES -
DRG TT/DJA

STRUCTURAL CONCEPTS | E: info@structuralconcepts.co.nz | P: +64 6 8420111 | F: +64 6 8420113 | 55 DUNLOP RD, PO BOX 3315, ONEKAWA, NAPIER 4142, NEW ZEALAND

emajineer

SEISMIC STRENGTHENING OF
MONAVALLE HOMESTEAD CHRISTCHURCH
Reference Plan First Floor

CLIENT
Christchurch City Council

PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV/DATE

DESCRIPTION





STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

APPENDIX C. FLOOR PLANS





Existing Ground Floor Scale 1:200 @ A3


CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF
MONA VALE HOMESTEAD CHRISTCHURCH
Existing Ground Floor Plans

emajineer
PRELIMINARY
for client approval
19th August 2011
SCL NUMBER
1605
SHEET
REV
0



Existing First Floor Scale 1:200 @ A3



Existing Roof Plan Scale 1:200 @ A3

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF
MONA VALE HOMESTEAD CHRISTCHURCH
Existing First Floor and Roof Plans



Structural Concepts S02 0

SCL NUMBER
1605
SHEET
REV



PRELIMINARY
for client approval
19th August 2011

STRUCTURAL CONCEPTS LIMITED

Emajineer™ Conceptualisers

55 DUNLOP ROAD, PO BOX 3315, NAPIER, 4142, NEW ZEALAND – P (06) 842 0111 – F (06) 842 0113 – E info@structuralconcepts.co.nz

APPENDIX D. NEW WORKS EXAMPLES




Proposed Ground Floor Scale 1:200 @ A3

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF
MONA VALE HOMESTEAD CHRISTCHURCH
Proposed Ground Floor Plans

- GENERAL SCOPE OF WORKS:**
This is not an exhaustive list of work to be done, confirm full extent of work with Architect prior to commencement of construction.
- remove all internal and external brick walls to lower floor supporting first floor, retaining brick as for re-use
 - Remove and re-construct columns and arches to match existing with new structural support.
 - Rebuild all existing brick walls as above with timber framed walls as shown, with brick veneer cladding to external walls to match existing, taking care to replace brick window linings to match existing
 - install crack stitching (Helibar system) to cracking of bricks to exterior and interior brick walls. Contractor to assess all damage on site to determine extent of damage to brick walls not being replaced
 - generally repair all cracked plaster to timber walls on the first floor, finish of all walls and ceilings to be confirmed with client.
 - remove chimney to floor level of ground floor, and replace with timber framed walls as detailed.
 - inspect existing roof tile, replace damaged and broken roof tiles, install new roof tiles and roof structure to roof as required, ensure all tiles are held in place firmly, ensure roof is weather-tight.
 - carefully remove and retain all timber wall cladding, skirting, soles and doors, along with all architraves to doors and windows, to all existing brick walls being replaced, reinstall after new timber walls are constructed.
 - ensure all doors and windows open and close properly, repair if required, replace broken glass as required.
 - generally ensure all structure, finishes, plumbing and drainage, electrical gas, and joinery items are repaired or replaced as required. Any existing exposed pipework and services shall be hidden inside the new timber framed walls.
 - contractor to determine extent of work and damage to all items on site, in accordance to the direction of the heritage Architect.



GENERAL SCOPE OF WORKS:

This is not an exhaustive list of work to be done. confirm full extent of work with Architect prior to commencement of construction.

- remove **all** internal and external brick walls to lower floor supporting first floor, retaining brick as for re-use

- Remove and re-construct columns and arches to match existing with new structural support.

- Rebuild **all** existing brick walls as above with timber framed walls as shown, with brick veneer cladding to external walls to match existing, taking care to replace brick window linels to match existing

- install crack stitching (Helibar system) to cracking of bricks to exterior and interior brick walls. Contractor to assess **all** damage on site to determine extent of damage to brick walls not being replaced

- generally repair **all** cracked plaster to timber walls on the first floor, finish of **all** walls and ceilings to be confirmed with client.

- remove chimney to floor level of ground floor, and replace with timber framed walls as detailed.

- inspect existing roof tile, replace damaged and broken roof tiles, install new roof tiles and roof structure to roof as required, ensure **all** tiles are held in place firmly, ensure roof is weather-tight.

- carefully remove and retain **all** timber wall cladding, skirting, soles and doors, along with **all** architraves to doors and windows, to **all** existing brick walls being replaced, reinstall after new timber walls are constructed.

- ensure **all** doors and windows open and close properly, repair if required, replace broken glass as required.

- generally ensure **all** structure, finishes, plumbing and drainage, electrical gas, and joinery items are repaired or replaced as required. Any existing exposed pipework and services shall be hidden inside the new timber framed walls.

- contractor to determine extent of work and damage to **all** items on site, in accordance to the direction of the heritage Architect.

Proposed First Floor Scale 1:200 @ A3

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

SEISMIC STRENGTHENING OF
MONA VALE HOMESTEAD CHRISTCHURCH
Proposed First Floor Plans

Structural Concepts S10 0
SHEET REV
1605
for client approval
19th August 2011

DATE Aug 2011 A3 DES - | DRG TT/DJA

| STRUCTURAL CONCEPTS | E: info@structuralconcepts.co.nz | P: +64 6 8420111 | F: +64 6 8420113 | 55 DUNLOP RD, PO BOX 3315, ONEKAWA, NAAPER 4142, NEW ZEALAND |


REV/DATE DESCRIPTION

SEISMIC STRENGTHENING OF
MONA VALE HOMESTEAD CHRISTCHURCH
Section

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV/DATE DESCRIPTION

Section A-A Scale 1:100 @ A3






Structural Concepts S21 0

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch


CLIENT
Chris
PROJECT




Section B-B
Scale 1:100 @ A3




W02
S20
External Wall Mid Floor Detail
Scale 1:10 @ A3




W01
S20
External Wall Foundation Detail
Scale 1:10 @ A3




W04
S20
Internal Wall Mid Floor Detail
Scale 1:10 @ A3



W03
S20
Internal Wall Foundation Detail
Scale 1:10 @ A3



W06
S20
External Wall Mid Floor Detail
Scale 1:10 @ A3



W05
S20
External Wall Foundation Detail
Scale 1:10 @ A3



PRELIMINARY
for client approval
19th August 2017

emajineer
SCL NUMBER 1605
SHEET REV 0
Structural Concepts S25

SEISMIC STRENGTHENING OF
MONAVALLE HOMESTEAD CHRISTCHURCH
Structural Details

CLIENT
Christchurch City Council
PROJECT ADDRESS
63 Fendalton Road, Christchurch

REV/DATE DESCRIPTION



Typical Column Post Section Detail



Typical Door Head Detail




Typical Door Sill Detail




Typical Window Head Detail



Typical Window Sill Detail




S06
S12
290PFC Column in Wall Detail Scale 1:10 @ A3




Section A - Typical SHS Post Base Scale 1:10 @ A3

S03
S12
Flinch Beam Over Arch Detail Scale 1:10 @ A3



S04
S12
Typical Arch Beam Section Detail Scale 1:10 @ A3

S02
S12
Flinch Beam Over Arch Detail Scale 1:10 @ A3



S01
S12
Typical Arch Beam Section Detail Scale 1:10 @ A3

PRILIMINARY
for client approval
19th August 2011

Client: Christchurch City Council

Project: Mona Vale Homestead
63 Fendalton Road, Christchurch

Ref: 1605 prelim

Date: 23-Jun-11

CALCULATIONS

BY GARRY NEWTON

BE (Civil) , MIPENZ(Civil, Structural), CPEng, IntPE(NZ)

CONTENTS

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
 NAPIER, 4142, NEW ZEALAND
 P (06) 842 0111 F (06) 842 0113
 E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Gravity Loads	

Sheet No.: 2

Loads

Roof

Clay tiles	0.670
Timber 20.6	0.092
Purlins 05 .4	0.034
Battens 05 1.2	0.011
Rockwool Insu.	0.002
Gib Board 13	0.120
Timber 15.6	0.069

0.998 kPa

Upper External Walls

Portland Plaster	0.290
Timber 15.4	0.103
140. Nogs & plates	0.104
Rockwool Insu.	0.002
Gib Board 13	0.120

0.619 kPa

Timber floor

25mm Pine deck	0.138
Timber 20.6	0.092
90. Nogs & plates	0.067
Battens 05 1.2	0.011
Rockwool Insu.	0.002
Gib Board 13	0.120

0.429 kPa

Partitions

Timber 15.4	0.103
140. Nogs & plates	0.104
Gib Board 13	0.120
Gib Board 13	0.120

0.447 kPa

Lower Exterior Brick Walls

100 Brick veneer	1.900
215 Med Brick	4.600

6.500 kPa

Live loads

A2 other rooms	2.00	kPa
Office Utility	3.00	kPa
Com. Kitchens	3.00	kPa
R2 Roofs	0.25	kPa



55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Gravity Loads	

Sheet No.:	3
------------	---

Loads

Interior Brick Walls
215 Med Brick 4.600

4.600 kPa

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Seismic loads to NZS1170 - Office areas	BY: GN

Seismic Loads to NZS 1170.5

Ref:	Design	Sheet No.: 4	Output
------	--------	--------------	--------

Design working live 50 Years
Importance level 2
Annual Probability of exceedance (inverse) Ultimate 500
Annual Probability of exceedance (inverse) Service 25

Element	Area/length	Load Kpa	Total kN
Roof	80.00	1.00	79.86
Partitions	20.00	0.45	8.94
Upper External Walls	42.00	0.62	26.00
	0.00	0.00	0.00
	0.00	0.00	0.00
	0.00	0.00	0.00
	1.00	0.40	0.00

114.80 kN

Element	Area/length	Load Kpa	Total kN
Timber floor	80.00	0.43	34.36
Upper External Walls	42.00	0.62	26.00
Lower Exterior Brick Walls	72.00	6.50	468.00
Roof	105.00	1.00	104.82
Interior Brick Walls	36.00	4.60	165.60
Partitions	36.00	0.45	16.09
Office Utility	0.50	0.40	80.00
	0.50	0.40	0.00

862.87 kN

Live load reduction

Total floor area 270.0

$$.3 + \frac{3}{\sqrt{A}} = 0.500$$

But not less than .5

Total building weight
977.67 kN

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Seismic loads to NZS1170 - Office areas	

Ref:	Design	Sheet No.: 5	Output
	Soil type D. Deep or soft soil ▼ <u>Across the building</u> Period of building across the building 0.40 Does the seismic bracing have ductile capabilities but is designed as nominally ductile ☒ Structural ductility factor (Ultimate) m = 2.00 Structural ductility factor (Service SLS1) m = 1.25 Hazard Factor Christchurch Z = 0.3 Return period factor Ru = 1.00 Return period factor Rs = 0.25 Structural Performance factor (Ultimate) Sp = 0.70 Structural Performance factor (Service) Sp = 0.70 Spectral Shape Factor (across) Ch(T) = 3.00 Near Fault factor N(T,D) = 1.0 n/a Elastic site spectra (Ultimate) C(T) = 0.90 Elastic site spectra (Service) C(T) = 0.23 Ultimate km = 1.57 Service km = 1.14 <u>Ultimate</u> Horizontal design action coefficients (Across) Cd(T1) = 0.40 But not less than 0.030Ru Ultimate force across the building Cd(T1) x Wi = 391.96 kN Total <u>Service</u> Horizontal design action coefficients (Across) Cd(T1) = 0.14 Service force across the building Cd(T1) x Wi = 134.74 kN Total <u>Along the building</u> Period of building along the building 0.40 Does the seismic bracing have ductile capabilities but is designed as nominally ductile ☒ Structural ductility factor (Ultimate) m = 2.00 Structural ductility factor (Service SLS1) m = 1.25 Structural Performance factor (Ultimate) Sp = 0.70 Spectral Shape Factor (across) Ch(T) = 3.00 Near Fault factor N(T,D) = 1.0 Elastic site spectra (Ultimate) C(T) = 0.90 Elastic site spectra (Service) C(T) = 0.23 Ultimate km = 1.57 Service km = 1.14 <u>Ultimate</u> Horizontal design action coefficients (Across) Cd(T1) = 0.40 But not less than 0.030Ru Ultimate force along the building Cd(T1) x Wi = 391.96 kN Total <u>Service</u> Horizontal design action coefficients (Across) Cd(T1) = 0.14 Service force across the building Cd(T1) x Wi = 134.74 kN Total		

NAPIER, 4142, NEW ZEALAND

P (06) 842 0111 F (06) 842 0113

E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Seismic Forces	

Seismic Loads to NZS 1170.5						Sheet No.:	6
Ref:	Design					Output	
	Seismic weight at level i	Wi	114.80 kN				
	Height at level i	hi	6.0 m				
	Seismic weight at level I	Wi	862.87 kN				
	Height at level I	hi	3.0 m				
	Sum of Wihi		3277.4				
	Base shear ultimate		391.96 kN				
	Base shear service		134.74 kN				
	8% of base shear to be applied at top level		31.36 kN				
	8% of base shear to be applied at top level		10.78 kN				
	$Fi = .92V \frac{Wihi}{\sum(Wihi)}$						
	<u>Ultimate</u>						
	Equivalent Lateral force at level i (Roof)				107.14	2143	
	Equivalent Lateral force at level i				284.81		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
					<u>391.96</u>	kN base V	
					7839.14	BU's	
	<u>Service</u>						
	Equivalent Lateral force at level i (Roof)				36.83		
	Equivalent Lateral force at level i				97.90		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
	Equivalent Lateral force at level i				0.00		
					<u>134.74</u>	kN base V	

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz


Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Bracing Capacity - Upper Office Wing	

Ref:	Design	Sheet No.: 7	Output
	All walls have been lined with gypsum wall boards (Fixing at nominal 300 spacings) therefore utilising the allowable strength values determined by NZSEE Table 11.1 we have assessed the strength of the walls independent of the Gib manual. From table 11.1 a strength value of 3 kN/m per side with a strength reduction factor of 0.7 can be used. $R = 3 \text{ kN/m per side}$ $\phi = 1$ $\phi R = 3 \text{ kN/m per side}$ 60 BU's/m Along length of wall available 6 one side 10 two sides $R_{total} = 6 \times 60 \times 2.4/2.7 + 10 \times 60 \times 2.4/2.7 \times 2$ $= 1387 \text{ BU's}$ 69.33 kN OK Across length of wall available 7 one side 12.5 two sides $R_{total} = 7 \times 60 \times 2.4/2.7 + 12.5 \times 60 \times 2.4/2.7 \times 2$ $= 1707 \text{ BU's}$ 85.33 kN OK Therefore it is determined that the wall linings will provide the strength required without necessarily strictly complying with the Gib brace requirements. Also it is noted that the main building structure is also capable of carrying some of this load and therefore reduce the requirements of the gypsum wall strength.		required 2143 BU's provided 1387 BU's 65 %NBS $z = 0.3$ 88 %NBS $z = 0.22$ required 2143 BU's provided 1707 BU's 80 %NBS $z = 0.3$ 100 %NBS $z = 0.22$

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Office Wing Masonry Walls In Plane	BY: GN

In-Plane strength of walls and piers to FEMA URM seismic guidelines		Sheet No.:	8
Ref:	Design	Output	
(7-1)	The following calculation follows the FEMA 273 guild lines for seismic rehabilitation of existing unreinforced masonry buildings (URM). This calculation is for piers or walls between window and door openings. Typically these piers are limited by diagonal tension in the panel or toe compressive stress, but bed-joint sliding shear or expected rocking strength can also limit the capacity.  Effective height and pier geometry may vary in the same wall assembly		
	Expected axial gravity force on pier	PCE	207 kN
	<u>Pier dimentions</u>		
	Effective height of pier	heff	3.00 m
	Pier length (net mortared length)	L	34.50 m
	Pier thickness (net mortared width)	Tm	200 mm
	Net mortared area		6900000 mm²
	Average bed-joint shear strength	Vte	1.00 Mpa
	Expected shear strength		
	$\frac{0.75 \left(0.75 v_{te} + \frac{P_{ce}}{A_n} \right)}{1.5}$	= Vme	0.390 Mpa
	Expected lateral strength is the lesser of:-		
	Bed-joint shear strength	Vme x An = QCE	2691.0 kN
	a = 0.5 for cantilever or 1.0 for fixed pier	a	0.5
	Expected rocking strength	$.9a P_{ce} \left(\frac{L}{heff} \right)$ = QCE	1071.2 kN
Masonry compressive strength	fm	4.0 Mpa	
Diagonal tension strength			
Vme = fdt in eq. (7-5) only	fdt	0.390 Mpa	
Vertical axial compressive stress	fa	0.030 Mpa	
Aspect ratio	(L / heff) =	11.50	

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Office Wing Masonry Walls In Plane	

In-Plane strength of walls and piers continued

Sheet No.: 9

Ref:	Design	Output
(7-5)	Expected lateral strength of pier is lesser of:- Diagonal tension stress $V_{dt} = f_{dt} \cdot A_n \left(\frac{L}{h_{eff}} \right) \sqrt{1 + \frac{fa}{f_{dt}}} = Q_{CL} \quad 32114.7 \text{ kN}$	
(7-6)	Toe compressive stress $V_{tc} = aP_{cl} \left(\frac{L}{h_{eff}} \right) \left(1 - \frac{fa}{0.7 f_m} \right) = Q_{CL} \quad 1177.5 \text{ kN}$	
	The governing lateral force for this pier is 1071.2 kN Actual force on pier is 392.0 kN	
	% of NBS, proportion of NZS1170.5 %NBS 273 % <u>Low Hazard</u>	

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Internal Brick Walls Out of Plane	BY: GN

Vertically spanning wall panel out-of-plane dynamic loads to NZSEE					Sheet No.:	10
Ref:	Design				Output	
(3)	Height of the upper most seismic mass	hn	6.0	m		
	Height of support for wall (from ground level)	hi	0.0	m		
	Mass of masonry used in design		22	kN/m³		
	Height of panel between supports	h	3.50	m		
	Length of panel between supporting walls	L	2.00	m		
	Thickness of wall	tnom	225	mm		
	Weight acting on top of the panel	P	6.0	kN		
	Assuming a hinge forms at mid height of the panel we have:-					
	Weight of top part of panel	Wt	17.3	kN		
	Weight of Bottom part of panel	Wb	17.3	kN		
	Effective thickness of wall (.975 - 0.025P/W) =	t	218.4	mm		
	<u>Eccentricities</u>					
	Eccentricity of P measured from centroid of Wt	ep	109.2	mm		
	Eccentricity of bott pivot measured from centroid of Wb	eb	109.2	mm		
	Eccentricity of mid-height pivot measured centroid of Wt	et	109.2	mm		
	Eccentricity of mid-height pivot measured centroid of Wb	eo	109.2	mm		
10(7)	<u>Mid-Height deflection</u>					
		$\frac{bh}{2a}$	=	Di		
	Where:-					
	b = Wb.eb + Wt(eo+eb+et) + P(eo+eb+et+ep) - C(Wbyb + WtYt)					
	a = Wb.yb + Wt(h/2 + Yt) + Ph					
	Interstorey slope divided by storey height	C	0.01	% Drift		
	Vertical Eccentricity of Wt to top pivot	Yt	875	mm		
	Vertical Eccentricity of Wb to bottom pivot	Yb	875	mm		
	Coefficient for formula 10(8)	b	9885.2			
	Coefficient for formula 10(9)	a	81637.5			
	Instability deflection is:-	$\frac{bh}{2a}$	=	Di	212	mm
	Maximum usable deflection is	.6Di	127.1	mm		
	Approximate period of vibration	Tp	1.209	s		
	<u>Seismic coefficient for elastically responding part</u>					
	Design working live				50 Years	▼
	Importance level				▼	
Annual Probability of exceedance (inverse) Ultimate				500		
<u>Soil type</u>		<u>Location</u>				
D. Deep or soft soil ▼		Christchurch ▼				
<u>For Parts</u>						
Floor acceleration is such to causing yielding of part See table C8.2						
Structural ductility of part (Table C8.2)	mp=		1.00		NZSEE recommendation	

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Internal Brick Walls Out of Plane	BY: GN

Vertically spanning wall panel out-of-plane continued

Sheet No.: 11

Ref:	Design	Output
T 3.3	Hazard Factor $Z = 0.3$	
T 3.5	Return period factor $R_u = 1.00$	
T 3.1	Spectral Shape Factor for parts $Ch(0) = 1.12$	
T 3.7	Near Fault factor $N(T,D) = 1.0$	
	Site Hazard coefficient $Ch(0) \times Z \times R \times N(T,D) = C(0) = 0.34$	
T 8.1	Part risk factor $R_p = 1.0$	
8.3	Floor height coefficient	
	Eq 8.3(1) $\left(1 + \frac{h_i}{6}\right)$ Chi 1.000	
	Eq 8.3(2) $\left(1 + 10 \frac{h_i}{h_n}\right)$ Chi 1.0	
	Chi 1.000	
	Period of part $T_p = 1.21$ Sec	
8.4	Part spectral shape coefficient $C_i(T_p) = 1.1$	
8.2	Design response coefficient for wall	
	$C(0) \cdot Chi \cdot C_i(T_p) = C_p(T_p) = 0.36$	
(9)	Participation factor for rocking system	
	Rotational inertia of the mass	
	$J_{bo} + J_{to} + \frac{1}{g} [W_b(eb^2 + yb^2) + W_t(eo + eb + et)^2 + yt^2] + P[(eo + eb + et + ep)^2] + J_{anc}$	
	And is:- $\frac{(W_b \cdot yb + W_t \cdot yt)h}{2Jg}$ J 3036	
10(12)	Participation factor $= g$ 1.781	
	Displacement response $= D_{ph}$ 0.229	
	% of NBS, proportion of NZS1170.5 $[(1.2)(0.6)\Delta i] / D_{ph}$ = %NBS 66.5 %	
	<u>Low Hazard</u>	NZSEE guidelines

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: External Brick Walls Out of Plane	BY: GN

Vertically spanning wall panel out-of-plane dynamic loads to NZSEE					Sheet No.:	12
Ref:	Design				Output	
(3)	Height of the upper most seismic mass	hn	6.0	m		
	Height of support for wall (from ground level)	hi	0.0	m		
	Mass of masonry used in design		22	kN/m³		
	Height of panel between supports	h	3.50	m		
	Length of panel between supporting walls	L	2.00	m		
	Thickness of wall	tnom	225	mm		
	Weight acting on top of the panel	P	6.0	kN		
	Assuming a hinge forms at mid height of the panel we have:-					
	Weight of top part of panel	Wt	17.3	kN		
	Weight of Bottom part of panel	Wb	17.3	kN		
	Effective thickness of wall (.975 - 0.025P/W) =	t	218.4	mm		
	<u>Eccentricities</u>					
	Eccentricity of P measured from centroid of Wt	ep	109.2	mm		
	Eccentricity of bott pivot measured from centroid of Wb	eb	109.2	mm		
	Eccentricity of mid-height pivot measured centroid of Wt	et	109.2	mm		
	Eccentricity of mid-height pivot measured centroid of Wb	eo	109.2	mm		
10(7)	<u>Mid-Height deflection</u>					
		$\frac{bh}{2a}$	=	Di		
	Where:-					
	b = Wb.eb + Wt(eo+eb+et) + P(eo+eb+et+ep) - C(Wbyb + WtYt)					
	a = Wb.yb + Wt(h/2 + Yt) + Ph					
	Interstorey slope divided by storey height	C	0.01	% Drift		
	Vertical Eccentricity of Wt to top pivot	Yt	875	mm		
	Vertical Eccentricity of Wb to bottom pivot	Yb	875	mm		
	Coefficient for formula 10(8)	b	9885.2			
	Coefficient for formula 10(9)	a	81637.5			
	Instability deflection is:-	$\frac{bh}{2a}$	=	Di	212	mm
	Maximum usable deflection is	.6Di	127.1	mm		
	Approximate period of vibration	Tp	1.209	s		
	<u>Seismic coefficient for elastically responding part</u>					
	Design working live				50 Years	▼
	Importance level				2	▼
Annual Probability of exceedance (inverse) Ultimate				500		
<u>Soil type</u>		<u>Location</u>				
D. Deep or soft soil ▼		Christchurch ▼				
<u>For Parts</u>						
Floor acceleration is such to causing yielding of part See table C8.2						
(8)	Structural ductility of part (Table C8.2)	mp=	1.00		NZSEE recommendation	

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: External Brick Walls Out of Plane	

Vertically spanning wall panel out-of-plane continued

Sheet No.: 13

Ref:	Design	Output
T 3.3	Hazard Factor $Z = 0.3$	
T 3.5	Return period factor $R_u = 1.00$	
T 3.1	Spectral Shape Factor for parts $Ch(0) = 1.12$	
T 3.7	Near Fault factor $N(T,D) = 1.0$	
	Site Hazard coefficient $Ch(0) \times Z \times R \times N(T,D) = C(0) = 0.34$	
T 8.1	Part risk factor $R_p = 1.0$	
8.3	Floor height coefficient	
	Eq 8.3(1) $\left(1 + \frac{h_i}{6}\right)$ Chi 1.000	
	Eq 8.3(2) $\left(1 + 10 \frac{h_i}{h_n}\right)$ Chi 1.0	
	Chi 1.000	
	Period of part $T_p = 1.21$ Sec	
8.4	Part spectral shape coefficient $C_i(T_p) = 1.1$	
8.2	Design response coefficient for wall	
	$C(0) \cdot Chi \cdot C_i(T_p) = C_p(T_p) = 0.36$	
(9)	<u>Participation factor for rocking system</u>	
	Rotational inertia of the mass	
	$J_{bo} + J_{to} + \frac{1}{g} [W_b(eb^2 + yb^2) + W_t(eo + eb + et)^2 + yt^2] + P[(eo + eb + et + ep)^2] + J_{anc}$	
	And is:- $\frac{(W_b \cdot yb + W_t \cdot yt)h}{2Jg}$ J 3036	
10(12)	Participation factor $= g$ 2.652	
	Displacement response $= D_{ph} = 0.341$	
	% of NBS, proportion of NZS1170.5 $[(1.2)(0.6)\Delta i] / D_{ph} = \%NBS = 44.7 \%$	
	<u>Moderate hazard</u>	NZSEE guidelines

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Stir Brick wall	BY: GN

Vertically spanning wall panel out-of-plane dynamic loads to NZSEE

Sheet No.: 14

Ref:	Design	Output
	Height of the upper most seismic mass Height of support for wall (from ground level) Mass of masonry used in design Height of panel between supports Length of panel between supporting walls Thickness of wall Weight acting on top of the panel Assuming a hinge forms at mid height of the panel we have:- Weight of top part of panel Weight of Bottom part of panel (3) Effective thickness of wall $(.975 - 0.025P/W) =$ <u>Eccentricities</u> Eccentricity of P measured from centroid of Wt Eccentricity of bott pivot measured from centroid of Wb Eccentricity of mid-height pivot measured centroid of Wt Eccentricity of mid-height pivot measured centroid of Wb <u>Mid-Height deflection</u> $\frac{bh}{2a} = Di$ Where:- $b = Wb.eb + Wt(eo+eb+et) + P(eo+eb+et+ep) - C(Wbyb + WtYt)$ $a = Wb.yb + Wt(h/2 + Yt) + Ph$ Interstorey slope divided by storey height Vertical Eccentricity of Wt to top pivot Vertical Eccentricity of Wb to bottom pivot 10(8) Coefficient for formula 10(8) 10(9) Coefficient for formula 10(9) $\frac{bh}{2a} = Di$ 10(7) Instability deflection is:- Maximum usable deflection is 10(10) Approximate period of vibration <u>Seismic coefficient for elastically responding part</u> Design working live Importance level Annual Probability of exceedance (inverse) Ultimate <u>Soil type</u> D. Deep or soft soil <u>Location</u> Christchurch <u>For Parts</u> Floor acceleration is such to causing yielding of part See table C8.2 (8) Structural ductility of part (Table C8.2)	hn 6.0 m hi 0.0 m 22 kN/m ³ h 6.00 m L 1.00 m tnom 225 mm P 0.0 kN Wt 14.9 kN Wb 14.9 kN t 219.4 mm ep 109.7 mm eb 109.7 mm et 109.7 mm eo 109.7 mm C 0.01 % Drift Yt 1500 mm Yb 1500 mm b 6069.9 a 89100 Di 204 mm .6Di 122.6 mm Tp 1.758 s 50 Years 2 500 Christchurch NZSEE recommendation

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Stir Brick wall	BY: GN

Vertically spanning wall panel out-of-plane continued

Sheet No.: 15

Ref:	Design	Output
T 3.3	Hazard Factor $Z = 0.3$	
T 3.5	Return period factor $R_u = 1.00$	
T 3.1	Spectral Shape Factor for parts $Ch(0) = 1.12$	
T 3.7	Near Fault factor $N(T,D) = 1.0$	
	Site Hazard coefficient $Ch(0) \times Z \times R \times N(T,D) = C(0) = 0.34$	
T 8.1	Part risk factor $R_p = 1.0$	
8.3	Floor height coefficient	
	Eq 8.3(1) $\left(1 + \frac{h_i}{6}\right)$ Chi 1.000	
	Eq 8.3(2) $\left(1 + 10 \frac{h_i}{h_n}\right)$ Chi 1.0	
	Period of part Chi 1.000	
	$T_p = 1.76$ Sec	
8.4	Part spectral shape coefficient $C_i(T_p) = 0.5$	
8.2	Design response coefficient for wall	
	$C(0).Chi.C_i(T_p) = C_p(T_p) = 0.17$	
(9)	Participation factor for rocking system	
	Rotational inertia of the mass	
	$J_{bo} + J_{to} + \frac{1}{g} [W_b(eb^2 + yb^2) + W_t(eo + eb + et)^2 + yt^2] + P[(eo + eb + et + ep)^2] + J_{anc}$	
	And is:- $\frac{(W_b.yb + W_t.yt)h}{2Jg} = J = 7004$	
10(12)	Participation factor $= g = 2.896$	
	Displacement response $= D_{ph} = 0.364$	
	% of NBS, proportion of NZS1170.5 $[(1.2)(0.6)\Delta i] / D_{ph} = \%NBS = 40.4 \%$	
	<u>Moderate hazard</u>	NZSEE guidelines

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead	Date: 23/6/11
63 Fendalton Road, Christchurch	BY: GN
Subject: Seismic loads to NZS1170 - dining areas	

Seismic Loads to NZS 1170.5

Ref:	Design	Output																																																																				
	Design working live50 Years Importance level2 Annual Probability of exceedance (inverse) Ultimate500 Annual Probability of exceedance (inverse) Service25 <table><tr><td>Element</td><td>Area/length</td><td>Load Kpa</td><td>Total kN</td></tr><tr><td>Roof</td><td>216.00</td><td>1.00</td><td>215.62</td></tr><tr><td>Partitions</td><td>45.00</td><td>0.45</td><td>20.12</td></tr><tr><td>Upper External Walls</td><td>81.00</td><td>0.62</td><td>50.15</td></tr><tr><td></td><td>0.00</td><td>0.00</td><td>0.00</td></tr><tr><td></td><td>0.00</td><td>0.00</td><td>0.00</td></tr><tr><td></td><td>0.00</td><td>0.00</td><td>0.00</td></tr><tr><td></td><td>1.00</td><td>0.40</td><td>0.00</td></tr></table> 285.89 kN <table><tr><td>Element</td><td>Area/length</td><td>Load Kpa</td><td>Total kN</td></tr><tr><td>Timber floor</td><td>216.00</td><td>0.43</td><td>92.76</td></tr><tr><td>Upper External Walls</td><td>81.00</td><td>0.62</td><td>50.15</td></tr><tr><td>Lower Exterior Brick Walls</td><td>70.00</td><td>6.50</td><td>455.00</td></tr><tr><td>Roof</td><td>0.00</td><td>1.00</td><td>0.00</td></tr><tr><td>Interior Brick Walls</td><td>54.00</td><td>4.60</td><td>248.40</td></tr><tr><td></td><td>0.00</td><td>0.00</td><td>0.00</td></tr><tr><td>A2 other rooms</td><td>0.50</td><td>0.60</td><td>432.00</td></tr><tr><td></td><td>0.50</td><td>0.40</td><td>0.00</td></tr></table> 975.91 kN	Element	Area/length	Load Kpa	Total kN	Roof	216.00	1.00	215.62	Partitions	45.00	0.45	20.12	Upper External Walls	81.00	0.62	50.15		0.00	0.00	0.00		0.00	0.00	0.00		0.00	0.00	0.00		1.00	0.40	0.00	Element	Area/length	Load Kpa	Total kN	Timber floor	216.00	0.43	92.76	Upper External Walls	81.00	0.62	50.15	Lower Exterior Brick Walls	70.00	6.50	455.00	Roof	0.00	1.00	0.00	Interior Brick Walls	54.00	4.60	248.40		0.00	0.00	0.00	A2 other rooms	0.50	0.60	432.00		0.50	0.40	0.00	Live load reduction Total floor area270.0 .3 + $\frac{3}{\sqrt{A}}$ = 0.500 But not less than .5
Element	Area/length	Load Kpa	Total kN																																																																			
Roof	216.00	1.00	215.62																																																																			
Partitions	45.00	0.45	20.12																																																																			
Upper External Walls	81.00	0.62	50.15																																																																			
	0.00	0.00	0.00																																																																			
	0.00	0.00	0.00																																																																			
	0.00	0.00	0.00																																																																			
	1.00	0.40	0.00																																																																			
Element	Area/length	Load Kpa	Total kN																																																																			
Timber floor	216.00	0.43	92.76																																																																			
Upper External Walls	81.00	0.62	50.15																																																																			
Lower Exterior Brick Walls	70.00	6.50	455.00																																																																			
Roof	0.00	1.00	0.00																																																																			
Interior Brick Walls	54.00	4.60	248.40																																																																			
	0.00	0.00	0.00																																																																			
A2 other rooms	0.50	0.60	432.00																																																																			
	0.50	0.40	0.00																																																																			
		Total building weight 1261.79 kN																																																																				

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Seismic loads to NZS1170 - dining areas	

Ref:	Design	Sheet No.: 17	Output
	Soil type D. Deep or soft soil ▼ <u>Across the building</u> Period of building across the building 0.40 Does the seismic bracing have ductile capabilities but is designed as nominally ductile ☒ Structural ductility factor (Ultimate) $m = 2.00$ Structural ductility factor (Service SLS1) $m = 1.25$ Hazard Factor Christchurch $Z = 0.3$ Return period factor $R_u = 1.00$ Return period factor $R_s = 0.25$ Structural Performance factor (Ultimate) $S_p = 0.70$ Structural Performance factor (Service) $S_p = 0.70$ Spectral Shape Factor (across) $Ch(T) = 3.00$ Near Fault factor $N(T,D) = 1.0$ n/a Elastic site spectra (Ultimate) $C(T) = 0.90$ Elastic site spectra (Service) $C(T) = 0.23$ Ultimate $k_m = 1.57$ Service $k_m = 1.14$ <u>Ultimate</u> Horizontal design action coefficients (Across) $C_d(T1) = 0.40$ But not less than $0.030R_u$ Ultimate force across the building $C_d(T1) \times W_i = 505.86$ kN Total <u>Service</u> Horizontal design action coefficients (Across) $C_d(T1) = 0.14$ Service force across the building $C_d(T1) \times W_i = 173.89$ kN Total <u>Along the building</u> Period of building along the building 0.40 Does the seismic bracing have ductile capabilities but is designed as nominally ductile ☒ Structural ductility factor (Ultimate) $m = 2.00$ Structural ductility factor (Service SLS1) $m = 1.25$ Structural Performance factor (Ultimate) $S_p = 0.70$ Spectral Shape Factor (across) $Ch(T) = 3.00$ Near Fault factor $N(T,D) = 1.0$ Elastic site spectra (Ultimate) $C(T) = 0.90$ Elastic site spectra (Service) $C(T) = 0.23$ Ultimate $k_m = 1.57$ Service $k_m = 1.14$ <u>Ultimate</u> Horizontal design action coefficients (Across) $C_d(T1) = 0.40$ But not less than $0.030R_u$ Ultimate force along the building $C_d(T1) \times W_i = 505.86$ kN Total <u>Service</u> Horizontal design action coefficients (Across) $C_d(T1) = 0.14$ Service force across the building $C_d(T1) \times W_i = 173.89$ kN Total		

NAPIER, 4142, NEW ZEALAND

P (06) 842 0111 F (06) 842 0113

E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead	Date: 23/6/11
63 Fendalton Road, Christchurch	BY: GN
Subject: Seismic Forces - Dining Areas	

Seismic Loads to NZS 1170.5					Sheet No.:		18		
Ref:	Design					Output			
	Seismic weight at level i					Wi	285.89 kN		
	Height at level i					hi	6.0 m		
	Seismic weight at level I					Wi	975.91 kN		
	Height at level I					hi	3.0 m		

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz


Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Bracing Capacity - Upper Dining Wing	

Ref:	Design	Sheet No.: 19	Output
	All walls have been lined with gypsum wall boards (Fixing at nominal 300 spacings) therefore utilising the allowable strength values determined by NZSEE Table 11.1 we have assessed the strength of the walls independent of the Gib manual. From table 11.1 a strength value of 3 kN/m per side with a strength reduction factor of 0.7 can be used. $R = 3 \text{ kN/m per side}$ $\phi = 1$ $\phi R = 3 \text{ kN/m per side}$ 60 BU's/m Along length of wall available 11 one side 11 two sides $R_{total} = 11 \times 60 \times 2.4/2.7 + 11 \times 60 \times 2.4/2.7 \times 2$ $= 1760 \text{ BU's}$ 88.00 kN OK Across length of wall available 15 one side 10 two sides $R_{total} = 15 \times 60 \times 2.4/2.7 + 10 \times 60 \times 2.4/2.7 \times 2$ $= 1867 \text{ BU's}$ 93.33 kN OK Therefore it is determined that the wall linings will provide the strength required without necessarily strictly complying with the Gib brace requirements. Also it is noted that the main building structure is also capable of carrying some of this load and therefore reduce the requirements of the gypsum wall strength.		required 4249 BU's provided 1760 BU's 41 %NBS $z = 0.3$ 56 %NBS $z = 0.22$ required 4249 BU's provided 1867 BU's 44 %NBS $z = 0.3$ 60 %NBS $z = 0.22$

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Dining Wing Masonry Walls In Plane Across	BY: GN

In-Plane strength of walls and piers to FEMA URM seismic guidelines		Sheet No.:	20
Ref:	Design	Output	
	The following calculation follows the FEMA 273 guild lines for seismic rehabilitation of existing unreinforced masonry buildings (URM). This calculation is for piers or walls between window and door openings. Typically these piers are limited by diagonal tension in the panel or toe compressive stress, but bed-joint sliding shear or expected rocking strength can also limit the capacity.  Effective height and pier geometry may vary in the same wall assembly		
	Expected axial gravity force on pier	PCE	100 kN
	<u>Pier dimentions</u>		
	Effective height of pier	heff	3.00 m
	Pier length (net mortared length)	L	17.00 m
	Pier thickness (net mortared width)	Tm	200 mm
	Net mortared area		3400000 mm²
	Average bed-joint shear strength	Vte	1.00 Mpa
(7-1)	Expected shear strength		
	$\frac{0.75 \left(0.75 v_{te} + \frac{P_{ce}}{A_n} \right)}{1.5}$	= Vme	0.390 Mpa
	Expected lateral strength is the lesser of:-		
(7-3)	Bed-joint shear strength	Vme x An = QCE	1325.0 kN
	a = 0.5 for cantilever or 1.0 for fixed pier	a	0.5
(7-4)	Expected rocking strength	$.9a P_{ce} \left(\frac{L}{heff} \right)$	= QCE 255.0 kN
	Masonry compressive strength	fm	4.0 Mpa
	Diagonal tension strength		
	Vme = fdt in eq. (7-5) only	fdt	0.390 Mpa
	Vertical axial compressive stress	fa	0.029 Mpa
	Aspect ratio	(L / heff) =	5.67

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Dining Wing Masonry Walls In Plane Across	

In-Plane strength of walls and piers continued


Sheet No.: 21

Ref:	Design	Output
(7-5)	Expected lateral strength of pier is lesser of:- Diagonal tension stress $V_{dt} = f_{dt} \cdot A_n \left(\frac{L}{h_{eff}} \right) \sqrt{1 + \frac{f_a}{f_{dt}}}$	= QCL 7786.5 kN
(7-6)	Toe compressive stress $V_{tc} = a P_{cl} \left(\frac{L}{h_{eff}} \right) \left(1 - \frac{f_a}{0.7 f_m} \right)$	= QCL 280.4 kN
	The governing lateral force for this pier is	255.0 kN
	Actual force on pier is	505.9 kN
	% of NBS, proportion of NZS1170.5	%NBS 50 %
		<u>Moderate hazard</u>

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
Subject: Dining Wing Masonry Walls In Plane Along	BY: GN

In-Plane strength of walls and piers to FEMA URM seismic guidelines		Sheet No.:	22
Ref:	Design	Output	
	The following calculation follows the FEMA 273 guild lines for seismic rehabilitation of existing unreinforced masonry buildings (URM). This calculation is for piers or walls between window and door openings. Typically these piers are limited by diagonal tension in the panel or toe compressive stress, but bed-joint sliding shear or expected rocking strength can also limit the capacity.  Effective height and pier geometry may vary in the same wall assembly		
	Expected axial gravity force on pier	PCE	80 kN
	<u>Pier dimentions</u>		
	Effective height of pier	heff	3.00 m
	Pier length (net mortared length)	L	14.00 m
	Pier thickness (net mortared width)	Tm	200 mm
	Net mortared area		2800000 mm²
	Average bed-joint shear strength	Vte	1.00 Mpa
(7-1)	Expected shear strength		
	$\frac{0.75 \left(0.75 v_{te} + \frac{P_{ce}}{A_n} \right)}{1.5}$	= Vme	0.389 Mpa
(7-3)	Expected lateral strength is the lesser of:-		
	Bed-joint shear strength	Vme x An = QCE	1090.0 kN
	a = 0.5 for cantilever or 1.0 for fixed pier	a	0.5
(7-4)	Expected rocking strength	$.9a P_{ce} \left(\frac{L}{heff} \right)$	= QCE 168.0 kN
	Masonry compressive strength	fm	4.0 Mpa
	Diagonal tension strength		
	Vme = fdt in eq. (7-5) only	fdt	0.389 Mpa
	Vertical axial compressive stress	fa	0.029 Mpa
	Aspect ratio	(L / heff) =	4.67

STRUCTURAL CONCEPTS LIMITED

55 DUNLOP ROAD, PO BOX 3315
NAPIER, 4142, NEW ZEALAND
P (06) 842 0111 F (06) 842 0113
E info@structuralconcepts.co.nz

Client: Christchurch City Council	Ref: 1605 prelim
Project: Mona Vale Homestead 63 Fendalton Road, Christchurch	Date: 23/6/11
	BY: GN
Subject: Dining Wing Masonry Walls In Plane Along	

In-Plane strength of walls and piers continued

Sheet No.: 23

Ref:	Design	Output
(7-5)	Expected lateral strength of pier is lesser of:- Diagonal tension stress $V_{dt} = f_{dt} \cdot A_n \left(\frac{L}{h_{eff}} \right) \sqrt{1 + \frac{fa}{f_{dt}}}$	= QCL 5270.0 kN
(7-6)	Toe compressive stress $V_{tc} = aP_{cl} \left(\frac{L}{h_{eff}} \right) \left(1 - \frac{fa}{0.7 f_m} \right)$	= QCL 184.8 kN
	The governing lateral force for this pier is	168.0 kN
	Actual force on pier is	505.9 kN
	% of NBS, proportion of NZS1170.5	%NBS 33 %
		<u>Moderate hazard</u>