



Christchurch City Council

**Purau Recreation
Reserve Toilets
PRK 3577 BLDG 001 EQ2**

Detailed Engineering Evaluation

Quantitative Assessment Report





Christchurch City Council

Purau Recreation Reserve Toilets

Quantitative Assessment Report

185 Purau Avenue

Opus International Consultants Ltd
Opus House
Princes Street
Private Bag 3057
Hamilton
3240
New Zealand

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: December 2012
Reference: 6-QUCC1.45
Status: Final

Reviewed and
Approved By  Jan Stanway
Senior Structural Engineer
CPEng 222291

Summary

Purau Recreation Reserve Toilets
PRK 3577 BLDG 001 EQ2

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the Purau Recreation Reserve Toilets structure, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011, visual inspections and measurements taken in July 2012 by Opus international and calculations.

Key Damage Observed

No structural damage was noted during our inspection of 12 July 2012.

Critical Structural Weaknesses

No critical structural weaknesses have been identified.

Indicative Building Strength

Based on the information available, and from undertaking a quantitative assessment, the structure's original capacity has been assessed to be 25%NBS in the transverse direction (across) and 28%NBS in the longitudinal direction (along). Therefore the building is classed as an earthquake prone building.

The capacity in both directions is limited by a lack of steel reinforcement in the concrete masonry walls.

Recommendations

It is recommended that strengthening works be carried out to increase the seismic capacity of the building to at least 67% NBS. However, due to its small size consideration should be given to demolition and rebuilding as an alternative to strengthening.

Contents

Summary	i
1 Introduction.....	1
2 Compliance	1
3 Earthquake Resistance Standards.....	4
4 General Observations.....	7
5 Structural Damage	8
6 Detailed Seismic Assessment	8
7 Conclusions.....	9
8 Recommendations	10
9 Limitations.....	10
10 References	10
 Appendix 1 - Photographs	
 Appendix 2 – Building Plan	
 Appendix 3 – CERA DEE Spreadsheet	

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Purau Recreation Reserve toilet building located at 185 Purau Ave, Purau Bay following the Canterbury Earthquake Sequence since September 2010.

The purpose of the assessment is to determine if the building is classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [3] [4].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Canterbury at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Canterbury using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death; or

5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake on 4 September 2010.

The 2010 amendment includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.

- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the DBH guidance document dated 12 June 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority

4 General Observations

4.1 Building Description

The building is a small single storey concrete masonry structure, approximately 3.7m long (north-south) by 2.4m (east-west), containing male and female toilet facilities separated by a full length central spine wall.

The perimeter walls on three sides of the building together with the central spine wall are constructed from 200mm thick concrete masonry blocks. A smaller 100mm thick concrete masonry blockwork wall has been used for the north elevation.

All of the masonry walls extend to a height of 2.2m above the ground floor slab.

The roof consists of a light weight corrugated metal sheet supported on small timber joists.

We have no information relating to the foundations but the building is situated on level ground and all of the blockwork walls have been constructed directly off a concrete ground bearing slab. This slab is approximately 150mm thick and appears to have been constructed without thickenings beneath the perimeter walls or central spine wall.

We have no information relating to the date of construction.

4.2 Gravity Load Resisting System

The rafters carrying the roof span in the east-west direction and are supported by the concrete masonry walls forming the east and west flanks together with the internal concrete masonry spine wall.

4.3 Seismic Load Resisting System

Lateral resistance for the structure in both directions is provided by the concrete masonry walls. From our inspection of 11 July 2012 it appears that the concrete masonry walls do not contain any steel reinforcement except for a single starter bar projecting from the concrete slab at each corner of the building.

4.4 Survey

A non-intrusive inspection was undertaken by Opus International on 11 July 2012 to confirm the structural systems, and to identify details which may require particular attention, including undertaking a cover meter survey.

Due to a lack of observed ground damage, a geotechnical assessment has not been completed for this site.

4.5 Original Documentation

No copies of the original structural drawings or design calculations are available for this building and its date of construction is unknown.

5 Structural Damage

No damage to the structure was noted during our inspection and the building appears to be in good condition.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

6.1 Seismic Coefficient Parameters

The seismic design parameters based on current design requirements from NZS1170.5:2004 and the NZBC clause B1 for this structure are:

- » Site soil class D, clause 3.1.3 NZS 1170.5:2004
- » Site hazard factor, $Z=0.3$, B_1/VM_1 clause 2.2.14B
- » Return period factor $R_u = 1.0$ from Table 3.5, NZS 1170.5:2004, for an Importance Level 2 structure with a 50 year design life.
- » Ductility factor $\mu_{max} = 1.25$ for the masonry building.

6.2 Quantitative Assessment Methodology

As previously noted, the concrete masonry walls that act as the main lateral load resisting elements of the building do not appear to contain any significant quantities of reinforcing steel.

As such we have assessed the walls as completely unreinforced and have also assumed that all of the internal grout pockets remain unfilled.

Without an intrusive investigation the capacity of the foundation cannot be determined but, due to the small loads being imparted on them, it is assumed that their capacity is greater than 100% NBS.

6.3 Assessment

A summary of the structural performance of the building is shown in the following table. Note that the values given represent the worst performing elements in the building, as these effectively define the building’s capacity. Other elements within the building may have significantly greater capacity when compared with the governing.

Table 2: Summary of Seismic Performance

Structural Element/System	Description/discussion	% NBS based on calculated capacity
Transverse direction, masonry walls	In-plane capacity of the masonry walls (200 Series)	39%
	In-plane capacity of the masonry walls (100 Series)	25%
	Out-of-plane capacity of the masonry walls	65%
Longitudinal direction, masonry walls	In-plane capacity of the masonry walls	>100%
	Out-of-plane capacity of the masonry walls (200 Series)	65%
	Out-of-plane capacity of the masonry walls (100 Series)	28%

6.4 Discussion of Results

The building has a calculated seismic capacity of 25% NBS and is therefore classed as an earthquake prone building. The seismic capacity is governed by the bending capacity of the 100mm thick internal masonry partition wall that creates the front of the cubicles.

Due to its calculated capacity, the building is classed as grade E, high risk. As such the relative risk of failure in a moderate earthquake is more than 25 times greater than that of building complying with current codes.

6.5 Limitations and Assumptions in Results

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- a. Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- b. Assessments of material strengths based on limited drawings, specifications and site inspections
- c. The normal variation in material properties which change from batch to batch.
- d. Approximations made in the assessment of the capacity of each element.

7 Conclusions

The building has a seismic capacity of 25%NBS and is therefore classed as an earthquake prone building. The building is classed as grade E, high risk. As such the relative risk of failure in a moderate earthquake is more than 25 times greater than that of building complying with current codes

8 Recommendations

It is recommended that strengthening works be carried out to increase the seismic capacity of the building to at least 67% NBS. However, due to its small size consideration should be given to demolition and rebuilding as an alternative to strengthening.

9 Limitations

- This report is based on an inspection of the structure with a focus on the damage sustained from the 22 February 2011 Canterbury Earthquake and aftershocks only.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the time.
- This report is prepared for the CCC to assist with assessing remedial works required for council structures and facilities. It is not intended for any other party or purpose.

10 References

- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] DBH (2012), Guidance for engineers assessing the seismic performance of non-residential and multi-unit residential buildings in greater Christchurch, Department of Building and Housing, June 2012.

Appendix 1 - Photographs

Purau Recreation Reserve Toilets – Detailed Engineering Evaluation



Photo 1: North Elevation



Photo 2: East Elevation



Photo 3: South Elevation



Photo 4: West Elevation



Photo 5: Entrance (External)



Photo 6: Entrance (Internal)

Purau Recreation Reserve Toilets – Detailed Engineering Evaluation



Photo 7: Roof and Wall Plate



Photo 8: Main Roof




Photo 9: Door Head Restraint







Photo 10: DPC beneath Wall Plate

Appendix 2 – Building Plan

300mm
200mm
100
50
0 10mm



Elevation 4
SCALE 1 : 20
200



Notes:
= Starter bar at each corner of the building

Revision	Amendment	Approved	Revision Date



Drawn	Designed	Approved	Revision Date
J.W			
Project No.	Scale	Drawing No.	Sheet No.
6-QUCC1.45	1 : 20	6/1366/282/ 8602	200

Project		Title	
Christchurch City Council 185 Purau Ave, Purau Bay, Canterbury		Toilet Block Layout	
Project		Title	
Christchurch City Council 185 Purau Ave, Purau Bay, Canterbury		Layout & Elevations	
Project No.	Scale	Drawing No.	Sheet No.
6-QUCC1.45	1 : 20	6/1366/282/ 8602	200
Revision			

Site Measure

Appendix 3 – CERA DEE Spreadsheet

Location		Building Name: Purau Recreation Reserve Toilets	Unit No: Street	Reviewer: Jan Stanway
Building Address: 185	Purau Avenue	CPEng No: 222291	Company: Opus International	Company project number: 6-QUCC1.45
Legal Description:		Company phone number: +64 3 363 5400	Date of submission: 12-May-14	Inspection Date: 12-Jul-12
GPS south: 43 38 20.00	GPS east: 172 45 0.00	Building Unique Identifier (CCC): PRK 3577 BLDG 001 EQ2	Revision: Final V2	Is there a full report with this summary? yes

Site	Site slope: flat	Max retaining height (m): 0
Soil type: silt	Soil Profile (if available):	
Site Class (to NZS1170.5): D	Proximity to waterway (m, if <100m): 10	If Ground improvement on site, describe:
Proximity to cliff top (m, if < 100m):	Proximity to cliff base (m, if <100m):	Approx site elevation (m): 0.00

Building	No. of storeys above ground: 1	single storey = 1	Ground floor elevation (Absolute) (m):
Ground floor split? no	Storeys below ground: 0	Foundation type: raft slab	Ground floor elevation above ground (m): 0.00
Building height (m): 2.30	Floor footprint area (approx): 9	Age of Building (years): 20	if Foundation type is other, describe:
Strengthening present? no	Use (ground floor): other (specify)	Use (upper floors): Toilets	height from ground to level of uppermost seismic mass (for IEP only) (m): 2.3
Use notes (if required): IL2	Importance level (to NZS1170.5): IL2	Date of design: 1976-1992	Date of design: 1976-1992

Gravity Structure	Gravity System: load bearing walls	rafter type, purlin type and cladding: timber
Roof: timber framed	Floors: concrete flat slab	slab thickness (mm): 150mm (ground bearing)
Beams: none	Columns: partially filled concrete masonry	overall depth x width (mm x mm): n/a
Walls: partially filled concrete masonry		thickness (mm): 190

Lateral load resisting structure	Lateral system along: partially filled CMU	Note: Define along and across in detailed report!	note total length of wall at ground (m): 9
Ductility assumed, μ: 1.25	Period along: 0.40	##### enter height above at H31	estimate or calculation? estimated
Total deflection (ULS) (mm):	maximum interstorey deflection (ULS) (mm):		estimate or calculation? estimated
Lateral system across:	Ductility assumed, μ: 1.25	#N/A enter height above at H31 and lateral system	estimate or calculation? 4.8
Period across: 0.40	Total deflection (ULS) (mm):		estimate or calculation? estimated
maximum interstorey deflection (ULS) (mm):			estimate or calculation? estimated

Separations:	north (mm):	east (mm):	south (mm):	west (mm):	leave blank if not relevant
---------------------	-------------	------------	-------------	------------	-----------------------------

Non-structural elements	Stairs:	Wall cladding:	Roof Cladding: Metal	Glazing: timber frames	Ceilings: none	Services(list):	describe: Metal sheet on rafters
--------------------------------	---------	----------------	----------------------	------------------------	----------------	-----------------	----------------------------------

Available documentation	Architectural: none	Structural: none	Mechanical: none	Electrical: none	Geotech report: none	original designer name/date:
--------------------------------	---------------------	------------------	------------------	------------------	----------------------	------------------------------

Damage	Site performance:	Describe damage:
Site: (refer DEE Table 4-2)	Settlement: none observed	notes (if applicable):
Differential settlement: none observed	Liquefaction:	notes (if applicable):
Lateral Spread:	Differential lateral spread:	notes (if applicable):
Ground cracks:	Damage to area:	notes (if applicable):

Building:	Current Placard Status:	Describe how damage ratio arrived at:
Along	Damage ratio: 0%	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
Describe (summary):		
Across	Damage ratio: 0%	
Describe (summary):		
Diaphragms	Damage?:	Describe:
CSWs:	Damage?:	Describe:
Pounding:	Damage?:	Describe:
Non-structural:	Damage?:	Describe:

Recommendations	Level of repair/strengthening required: significant structural and strengthening	Describe: Reinforcement to walls required		
Building Consent required:	Interim occupancy recommendations: do not occupy	Describe: Brittle mechanism		
Along	Assessed %NBS before e'quakes: 28%	Assessed %NBS after e'quakes: 28%	##### %NBS from IEP below	If IEP not used, please detail assessment methodology: Quantitative
Across	Assessed %NBS before e'quakes: 25%	Assessed %NBS after e'quakes: 25%	##### %NBS from IEP below	



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz