



CLIENTS | PEOPLE | PERFORMANCE

**Barn - Styx River Reserve #2**  
**PRK 2546 BLDG 005-EQ2**  
Detailed Engineering Evaluation  
Qualitative Report  
Version Final

Styx River Reserve, 303 Radcliffe Road,  
Belfast, Christchurch

**Barn - Styx River Reserve #2  
PRK 2546 BLDG 005-EQ2**

Detailed Engineering Evaluation  
Qualitative Report  
Version Final

303 Radcliffe Road, Belfast,  
Christchurch

Christchurch City Council

**Prepared By**  
Nate Oakes

**Reviewed By**  
Derek Chinn

**Date**  
06/03/13



# Contents

Qualitative Report Summary	1
1. Background	3
2. Compliance	4
2.0 Canterbury Earthquake Recovery Authority (CERA)	4
2.1 Building Act	5
2.2 Christchurch City Council Policy	6
2.3 Building Code	6
3. Earthquake Resistance Standards	7
4. Building Description	9
4.0 General	9
4.1 Gravity Load Resisting System	10
4.2 Lateral Load Resisting System	10
5. Assessment	12
6. Damage Assessment	13
6.0 Surrounding Buildings	13
6.1 Residual Displacements and General Observations	13
6.2 Ground Damage	13
7. Critical Structural Weakness	14
7.1 Short Columns	14
7.2 Lift Shaft	14
7.3 Roof	14
7.4 Staircases	14
7.5 Plan Irregularity	14
7.6 Liquefaction and Lateral Spreading	14
8. Geotechnical Consideration	15
8.0 Site Description	15
8.1 Published Information on Ground Conditions	15
8.2 Seismicity	17
8.3 Slope Failure and/or Rockfall Potential	17



8.4	Liquefaction Potential	18
8.5	Conclusions & Summary	18
9.	Survey	19
10.	Initial Capacity Assessment	20
10.1	% NBS Assessment	20
10.2	Seismic Parameters	20
10.3	Expected Structural Ductility Factor	21
10.4	Discussion of Results	21
10.5	Occupancy	21
11.	Initial Conclusions	22
12.	Recommendations	23
13.	Limitations	24
13.1	General	24
13.2	Geotechnical Limitations	24

## Table Index

Table 1	%NBS compared to relative risk of failure	8
---------	---	---

## Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	7
Figure 2	Plan Sketch Showing Key Structural Element	10

## Appendices

A	Photographs
B	Existing Drawings
C	CERA Building Evaluation Form



# Qualitative Report Summary

**Barn-Styx River Reserve #2**

**PRK 2546 BLDG 005-EQ2**

**Detailed Engineering Evaluation**

**Qualitative Report - SUMMARY**

**Version Final**

**303 Radcliffe Road, Belfast, Christchurch**

## **Background**

This is a summary of the Qualitative report for the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 16 April 2012.

## **Building Description**

The timber Barn (004) at Styx River Reserve #2 is assumed to have been constructed in 1970. It is located among similar sheds and barns on flat ground alongside the Styx River and alongside Radcliffe Road in Belfast, Christchurch.

The general structure is an open barn which is rectangular in plan. The roof is clad in corrugated steel and consists of two sections: a duo-pitch trussed roof consisting of longitudinal timber roof trusses on the western side, and a mono-slope roof consisting of almost flat timber rafters on the eastern side. Timber purlins span between the trusses and rafters in the transverse direction. There are two rows of posts with transverse timber lintels along the western edge and down the middle of the barn, and a cross-braced timber wall clad in corrugated steel along the eastern edge of the structure. There are no other walls to the barn. There is a partial-height (1.2m estimated) braced wall along the northern edge of the structure, underneath the mono-slope portion of the roof, which extends down from the roof and spans between the eastern wall and the northern timber post at the roof junction. There is knee bracing in both directions at all of the timber posts. The timber posts sit atop concrete pads, which are connected via foundation beams in the transverse direction. The eastern wall sits atop a continuous concrete footing. There is no structural floor to the barn, only on-grade soil. The dimensions of the building are approximately 17.5m long by 13m wide and 6m in height.

## **Key Damage Observed**

Some damage was observed on-site, but it is believed that the damage is due to poor workmanship and not caused by seismic action. Key damage observed includes partial separation of knee bracing to the posts along the western edge of the building.



### Critical Structural Weaknesses

The building exhibits the following critical structural weakness:

- Plan Irregularity (lack of cross-bracing in the roof structure) 30% reduction

### Indicative Building Strength (from IEP and CSW assessment)

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the building's original capacity has been assessed to be in the order of 75% NBS. The building's capacity excluding critical structural weaknesses and damage is in the order of 96% NBS.

Because the buildings is not earthquake prone because it exceeds 33% of NBS, but because the building capacity (including CSW's) is less than 67% the building is a potential Earthquake Risk.

<u>Item</u>	<u>%NBS</u>
Building Capacity excluding CSW's	75%
Building Capacity including:	
Plan Irregularity (Significant, lack of cross bracing, 30% Reduction)	53%
Damage (Disrepair of Knee Bracing, 25% Reduction)	39%

### Recommendations

It is recommended that the building be subjected to a detailed quantitative assessment and geotechnical investigation, as the building is a potential Earthquake Risk. Building occupancy should not be restricted.



## 1. Background

GHD has been engaged by the Christchurch City Council (CCC) to undertake a detailed engineering evaluation of several buildings at the Styx River Reserve #2. This report covers the Barn (005).

This report is a Qualitative Assessment of the building structure, and is based in general on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure had been carried out. The building description is based on the visual inspection carried out on site.



## 2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

### 2.0 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

#### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

#### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

## **2.1 Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

### **Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

### **Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

#### **2.1.1 Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

### **Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.



## **2.2 Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

## **2.3 Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

### 3. Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 3.1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

**Figure 1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE**

Table 3.1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.



<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

**Table 1 %NBS compared to relative risk of failure**

## 4. Building Description


### 4.0 General

The timber Barn (005) at Styx River Reserve #2 is assumed to have been constructed in 1970. The site is located on mostly flat ground alongside the Styx River and alongside Radcliffe Road in Belfast, Christchurch. The surrounding area consists of rural lands with occasional barns and other structures.

The site is generally flat with some variation in the topography due to the river and some short, gentle hills to the north. The shed is located roughly 20m from a creek which feeds into the Styx River.

The general structure is an open barn which is rectangular in plan. The roof is clad in corrugated steel and consists of two sections: a duo-pitch trussed roof on the western side, and a mono-slope roof on the eastern side. There are four equally-spaced longitudinal timber roof trusses in the duo-pitch section, and the trusses feature steel rod vertical members. The mono-slope roof section consists of equally-spaced longitudinal timber rafters. Timber purlins span between the trusses and rafters in the transverse direction. Timber lintels span in the transverse direction between the timber posts, along the western edge and the internal line of posts, to support intermediate timber purlins from the duo-pitch roof section and the main rafters from the mono-pitch roof section. No cross-bracing was noted in the roof structure. The eastern (transverse) side of the structure contains a solid braced wall, while the other three sides are open. The eastern timber wall features timber cross-bracing and is clad in corrugated steel. There is a partial-height (1.2m estimated) braced wall along the northern edge of the structure, underneath the mono-slope portion of the roof, which extends down from the roof and spans between the eastern wall and the timber post at the roof junction. The timber roof trusses span in the longitudinal direction and feature knee bracing. The edges of the trussed roof section also feature knee bracing to the roof support members in the transverse direction. Except for the eastern wall, the roof structure is supported by two rows of timber posts. The timber posts sit atop concrete pads, which are connected via foundation beams in the transverse direction. The eastern wall sits atop a continuous concrete footing. There is no structural floor to the barn, only on-grade soil. The dimensions of the building are approximately 17.5m long by 13m wide and 6m in height.

A plan sketch is provided in the following Figure 2 to illustrate the main structural members of the building.



**Figure 2 Plan Sketch Showing Key Structural Elements**

#### **4.1 Gravity Load Resisting System**

The gravity loads in the structure are carried through the steel roof cladding to the timber roof purlins and down through the rafters and trusses. Gravity loads are then translated down through the timber posts and wall to the concrete foundations and into the ground.

#### **4.2 Lateral Load Resisting System**

In the longitudinal direction, lateral loads on the building will be translated in-plane through the roof cladding into the purlins, trusses and rafters. Lateral loads will be carried through these timber members via truss action and axial load transfer, and into the timber posts via frame action through the knee braced connections. The lateral loads will then be transferred axially through the posts into the concrete foundations and into the ground. The partial wall along the northern wall will provide some lateral bracing against lateral loads in this direction via diaphragm action in the timber cross-bracing and steel cladding.



In the transverse direction, lateral loads on the building will be translated through the steel roof cladding into the timber purlins. The purlins will combine with the steel roof cladding to form some diaphragm action, which will carry lateral loads to the two transverse lintels and eastern exterior wall. The eastern cross-braced exterior wall will translate lateral loads through diaphragm action in the timber cross-bracing and corrugated steel cladding into the concrete foundations and into the ground. Lateral loads in the two transverse lintels will be translated through portal action in the knee-braced connections into the timber posts. Lateral loads will then be translated axially through these posts into the concrete foundations and into the ground. Foundation walls along the two lines of posts and under the eastern braced wall will provide additional bracing against lateral loads in the transverse direction.



## 5. Assessment

A visual inspection of the building was undertaken on 16 April 2012. Both the interior and exterior of the building were inspected. There was no placard observed in place at the building. Most of the main structural components of the building were able to be viewed due to the exposed nature of the structure. No detailed inspection of the foundation of the structure was able to be undertaken, though the top of the concrete footings and part of the concrete foundation walls were visible.

The visual inspection consisted of observing the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including observing the ground conditions, checking for damage in areas where damage would be expected for the structure type observed and noting general damage observed throughout the building in both structural and non-structural elements.

The %NBS score is determined using the IEP procedure described by the NZSEE which is based on the information obtained from visual observation of the building. A critical structural weakness in plan irregularity was observed, which reduced the overall %NBS.



## 6. Damage Assessment

### 6.0 Surrounding Buildings

The Barn (005) at Styx River Reserve is located in a rural area with open lands adjacent to the site. There are a few other small sheds and barns on the same property. Most of the surrounding buildings showed little sign of seismic damage, but one of the nearby concrete sheds showed severe signs of damage.

### 6.1 Residual Displacements and General Observations

The barn displayed residual displacements in the knee-braced connections along the western edge of the building. Three of the knee-braced connections were disconnected from the posts and left hanging from the roof structure. These displacements appeared to be due to a lack of maintenance and not due to seismic damage.

### 6.2 Ground Damage

No ground damage was observed during the inspection of the site.



## 7. Critical Structural Weakness

### 7.1 Short Columns

The building does not contain any significant short columns.

### 7.2 Lift Shaft

The building does not contain a lift shaft.

### 7.3 Roof

The duo-pitch roof structure features timber trusses with deep purlins running continuously atop the trusses, clad in corrugated steel. The mono-pitch roof structure features timber rafters and timber purlins, clad in corrugated steel. Neither of the two roof sections contain any cross-bracing. It is expected that very limited diaphragm action can be expected from the roof structure, though not enough to eliminate the presence of a critical structural weakness. A significant critical structural weakness has been noted as plan irregularity in the IEP assessment.

### 7.4 Staircases

The building does not contain a staircase.

### 7.5 Plan Irregularity

The building shape in plan is a simple rectangle. The stiff eastern wall is balanced by knee braced portal connections along the western edge and the internal line of posts. However, the lack of bracing in the roof structure necessitates a significant critical structural weakness in the form of plan irregularity, as noted above.

### 7.6 Liquefaction and Lateral Spreading

No liquefaction was observed at the site. The geotechnical investigation has identified a high liquefaction potential for the site, as well as the potential for lateral spreading. It is not expected, however, that liquefaction occurring at the site will lead to a premature collapse of the structure. Accordingly, no critical structural weakness has been noted in the IEP assessment for site characteristics.



## 8. Geotechnical Consideration

This desktop geotechnical study outlines the ground conditions, as indicated from sources quoted within. This is a desktop study report and no site visit has been undertaken by geotechnical personnel.

This report is only specific to the south-western section of the property at 303 Radcliffe Rd, Harewood. The property is located off Radcliffe road. It is bounded by residential and agricultural properties. The property is owned and maintained by the Christchurch City Council.

### 8.0 Site Description

The site is situated within a large property on the banks of the Styx River. The site is relatively flat at approximately 5m above mean sea level. It is located approximately 5km south of the Waimakariri River, and 5km west of the coast (Pegasus Bay). Running through the property there is what appears to be an old river channel, which may also have been altered mechanically in size and shape. A section of this appears to be used as a small lake, perhaps for irrigation.

### 8.1 Published Information on Ground Conditions

#### 8.1.1 Published Geology

The geological map of the area<sup>1</sup> indicates that the site is underlain by grey river alluvium beneath plains or low-level terraces (Q1a), Holocene in age.

#### 8.1.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates three boreholes are located within a 200m of the site. However, these boreholes do not have records of the strata encountered. One borehole approximately 250m from the site indicates the ground to comprise layers of gravelly sand, sand and clay, clay-bound gravels and sand.

**Table 2 ECan Borehole Summary**

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M35/8937	~30m	~0.72m bgl	250m NE

It should be noted that the purpose of the boreholes the well logs are associated with, were sunk for groundwater extraction and not for geotechnical purposes. Therefore, the amount of material recovered and available for interpretation and recording will have been variable at best and may not be representative. The logs have been written by the well driller and not a geotechnical professional or to a standard. In addition strength data is not recorded.

<sup>1</sup> Forsyth P.J., Barrell D.J.A., & Jongens R. 2008: Geology of the Christchurch Area. Institute of Geological and Nuclear Sciences 1:250,000 Geological Map 16. Lower Hutt. Institute of Geological and Nuclear Sciences Limited.

### 8.1.3 EQC Geotechnical Investigations

The Earthquake Commission has not undertaken geotechnical testing in the area of the subject site.

### 8.1.4 Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has published areas showing the Green Zone Technical Category in relation to the risk of future liquefaction and how these areas are expected to perform in future earthquakes. The site is classified as Technical Category Not Applicable (TC N/A). This means that non-residential properties in urban areas, properties in rural areas or beyond the extent of land damage mapping have not been given a Technical Category.

### 8.1.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows a large amount of material on site (and properties adjacent) that maybe liquefaction as shown in Figure 3, although this material could also be evident on the surface due to a dry summer. However, lateral spreading is visible to the south along the Styx River. Material in the base of the drainage channel appears to be sand ejected from liquefaction.

**Figure 3 Post February 2011 Earthquake Aerial Photography**<sup>2</sup>



### 8.1.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise layers of gravelly sand, sand and clay, clay-bound gravels, and sand.

<sup>2</sup> Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>



## 8.2 Seismicity

### 8.2.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

**Table 3 Summary of Known Active Faults<sup>3,4</sup>**

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	120 km	NW	~8.3	~300 years
Greendale (2010) Fault	26 km	W	7.1	~15,000 years
Hope Fault	100 km	N	7.2~7.5	120~200 years
Kelly Fault	100 km	NW	7.2	150 years
Porters Pass Fault	60 km	NW	7.0	1100 years

Recent earthquakes since 22 February 2011 have identified the presence of a previously unmapped active fault system underneath Christchurch City and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

### 8.2.2 Ground Shaking Hazard

This seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

In addition, anticipation of recent alluvial deposits, a 475-year PGA (peak ground acceleration) of ~0.4 (Stirling et al, 2002<sup>3</sup>), and bedrock anticipated to be in excess of 500m deep, ground shaking is expected to be moderate to high.

## 8.3 Slope Failure and/or Rockfall Potential

The topography surrounding the site is typically flat, and hence rockfalls are not considered to be a hazard at this site. However, given the site's proximity to the Styx River, it is considered possible that lateral spreading may occur in the area.

<sup>3</sup> Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002) A New Seismic Hazard Model for New Zealand, Bulletin of the Seismological Society of America, Vol. 92 No. 5, pp 1878-1903, June 2002.

<sup>4</sup> GNS Active Faults Database



In addition, any localised retaining structures should be investigated to better establish the site-specific slope instability.

#### **8.4 Liquefaction Potential**

Due to the presence of alluvial deposits, and evidence from the post-earthquake aerial photography it is possible and likely that liquefaction will occur where sands and silts are present.

This may result in lateral spreading along and towards the Styx River, which was evident following 4 September and 22 February earthquakes, south of the subject site, or along the old river channel.

Further investigation is recommended to better determine subsoil conditions. An intrusive investigation comprising one piezocone CPT test to 20m bgl is recommended to allow a more comprehensive liquefaction assessment to be undertaken.

#### **8.5 Conclusions & Summary**

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, comprising gravel, sand and silt. Associated with this the site also has a moderate to high liquefaction potential, in particular where sands and/or silts are present. There is the potential for liquefaction to manifest as lateral spreading at this site.

To allow a more comprehensive liquefaction and/or ground condition assessment to be undertaken, it is recommended that an intrusive investigation comprising of at least one piezocone CPT be conducted.

A soil class of **D/E** (in accordance with NZS 1170.5:2004) should be adopted for the site. Further refinement can only be made by reviewing intrusive investigation data.



## 9. Survey

No level or verticality surveys have been undertaken for this building at this stage as indicated by Christchurch City Council guidelines.



## 10. Initial Capacity Assessment

### 10.1 % NBS Assessment

The building's capacity was assessed using the Initial Evaluation Procedure based on the information available. The building's capacity including and excluding any critical structural weaknesses and damage are expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 4. These capacities are subject to confirmation by a more detailed quantitative analysis.

<u>Item</u>	<u>%NBS</u>
Building Capacity excluding CSW's	75%
Building Capacity including:	
Plan Irregularity (Significant, 30% Reduction)	53%
Damage (Disrepair of Knee Bracing, 25% Reduction)	39%

**Table 4 Indicative Capacities based on the NZSEE Initial Evaluation Procedure**

Following an IEP assessment, the building has been assessed as achieving 39% New Building Standard (NBS). Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the building is not considered potentially Earthquake Prone as it achieves greater than 33% NBS, but it is considered a potential Earthquake Risk as it has scored less than 67% NBS. The overall %NBS has been reduced by 30% for significant Plan Irregularity, owing to the lack of cross-bracing in the roof structure. The overall %NBS was also decreased by 25% in the Factor F portion of the IEP assessment to account for the state of disrepair of the knee bracing along the western transverse side of the structure.

### 10.2 Seismic Parameters

The seismic design parameters based on current design requirements from NZS1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class: E, NZS 1170.5:2004, Clause 3.1.3, Very Soft Soil
- ▶ Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011
- ▶ Return period factor  $R_u = 0.5$ , NZS 1170.5:2004, Table 3.5, Importance Level 1 structure with a 50-year design life.

Some key seismic parameters have influenced the %NBS score obtained from the IEP assessment. The building has been assessed as an Importance Level 1 building. An increased Z factor of 0.3 for Christchurch has been used in line with recommendations from the Department of Building and Housing recommendations.



### **10.3 Expected Structural Ductility Factor**

A structural ductility factor of 2.0 has been assumed based on the timber portal frame structure and date of construction.

### **10.4 Discussion of Results**

The results obtained from the initial IEP assessment are consistent with those expected for a building of this age, construction type, and Importance Level founded on Class E soils. This building would have been designed to the standards at the time, namely NZS1900:1965. The design loads used in this code would have been significantly less than those required by the current loading standard. When combined with the increase in the hazard factor for Christchurch to 0.3 and the significant Plan Irregularity of the building, it is reasonable to expect the building to be classified as a potential Earthquake Risk.

### **10.5 Occupancy**

The building does not pose an immediate risk to users and occupants as no extant collapse hazards due to seismic damage have been identified. The building is not Earthquake Prone, and it is not prone to premature collapse from the critical structural weakness or state of disrepair to the knee bracing. Occupancy of the building should not be restricted.



## 11. Initial Conclusions

The building has been assessed to have a seismic capacity in the order of 39% NBS and is therefore not potentially Earthquake Prone. As a result, occupancy of the building is allowed.



## 12. Recommendations

The building has achieved less than 67% NBS capacity but greater than 34% NBS capacity according to an initial IEP assessment, which classifies the building as a potential Earthquake Risk. The building does not present any collapse hazard, though it does exhibit a critical structural weakness. The building should be subjected to further detailed seismic assessment, and occupancy of the building should be allowed.



## 13. Limitations

### 13.1 General

This report has been prepared subject to the following limitations:

- ▶ No inspection of the bracing in the timber framed walls could be undertaken.
- ▶ No intrusive structural investigations have been undertaken.
- ▶ No intrusive geotechnical investigations have been undertaken.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those included as part of the IEP in the CERA Building Evaluation Report, have been undertaken. No modelling of the building for structural analysis purposes has been performed.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

### 13.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.



Appendix A  
Photographs



**Photograph 1: West elevation.**



**Photograph 2: Southeast corner elevation.**



**Photograph 3: South elevation.**



**Photograph 4: View of interior at north end. Note braced eastern wall.**



**Photograph 5: Interior view of cross-braced east wall and timber roof members.**



**Photograph 6: Interior view of knee-braced timber and steel rod trusses.**



**Photograph 7: Interior view of junction between flat and trussed roof sections.**



**Photograph 8: Interior view of flat roof section.**



**Photograph 9: Typical post and concrete pad.**



**Photograph 10: Timber posts and pad foundations at western edge.**



## Appendix B

# Existing Drawings

*Note: no existing drawings for this building were able to be located.*



Appendix C  
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

<b>Location</b>		Building Name: <input type="text" value="Barn 005 - Styx River Reserve #2"/>	Reviewer: <input type="text" value="Derek Chinn"/>
	Unit No: Street		CPEng No: <input type="text" value="177243"/>
Building Address: <input type="text" value="303 Radcliffe Rd, Belfast, Christchurch"/>		Company: <input type="text" value="GHD"/>	Company project number: <input type="text" value="513059654"/>
Legal Description: <input type="text"/>		Company phone number: <input type="text" value="6433780900"/>	Date of submission: <input type="text" value="6/3/2013"/>
	Degrees Min Sec		Inspection Date: <input type="text" value="16/4/2012"/>
GPS south: <input type="text" value="43 27 53.87"/>			Revision: <input type="text" value="Draft"/>
GPS east: <input type="text" value="172 38 58.52"/>			Is there a full report with this summary? <input type="text" value="yes"/>
Building Unique Identifier (CCC): <input type="text" value="PRK 2456 BLDG 005-EQ2"/>			

<b>Site</b>		Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
	Soil type: <input type="text" value="sandy silt"/>		Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="E"/>			If Ground improvement on site, describe: <input type="text"/>
Proximity to waterway (m, if <100m): <input type="text"/>			Approx site elevation (m): <input type="text"/>
Proximity to clifftop (m, if < 100m): <input type="text"/>			
Proximity to cliff base (m,if <100m): <input type="text"/>			

<b>Building</b>		No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
Ground floor split? <input type="text" value="no"/>				Ground floor elevation above ground (m): <input type="text"/>
Storeys below ground: <input type="text" value="0"/>				if Foundation type is other, describe: <input type="text"/>
Foundation type: <input type="text" value="pads with tie beams"/>			height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="6"/>	Date of design: <input type="text" value="1965-1976"/>
Building height (m): <input type="text" value="6.00"/>				If so, when (year)? <input type="text"/>
Floor footprint area (approx): <input type="text"/>				And what load level (%g)? <input type="text"/>
Age of Building (years): <input type="text" value="42"/>				Brief strengthening description: <input type="text"/>
Strengthening present? <input type="text" value="no"/>				
Use (ground floor): <input type="text" value="public"/>				
Use (upper floors): <input type="text"/>				
Use notes (if required): <input type="text" value="Hay barn"/>				
Importance level (to NZS1170.5): <input type="text" value="IL1"/>				

<b>Gravity Structure</b>		Gravity System: <input type="text" value="frame system"/>	rafter type, purlin type and cladding: <input type="text"/>
Roof: <input type="text" value="timber framed"/>			Floor on-grade: <input type="text"/>
Floors: <input type="text"/>			type: <input type="text"/>
Beams: <input type="text" value="timber"/>			typical dimensions (mm x mm): <input type="text"/>
Columns: <input type="text" value="timber"/>			thickness (mm): <input type="text"/>
Walls: <input type="text" value="timber framed"/>			

**Lateral load resisting structure**

Lateral system along:	timber moment frame
Ductility assumed, $\mu$ :	2.00
Period along:	0.12
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	
Lateral system across:	timber moment frame
Ductility assumed, $\mu$ :	2.00
Period across:	0.12
Total deflection (ULS) (mm):	
maximum interstorey deflection (ULS) (mm):	

**Note: Define along and across in detailed report!**

0.00

0.00

note typical bay length (m)	11.4
estimate or calculation?	calculated
estimate or calculation?	
estimate or calculation?	
note typical bay length (m)	6.2
estimate or calculation?	calculated
estimate or calculation?	
estimate or calculation?	

**Separations:**

north (mm):	
east (mm):	
south (mm):	
west (mm):	

leave blank if not relevant

**Non-structural elements**

Stairs:	
Wall cladding:	profiled metal
Roof Cladding:	Metal
Glazing:	
Ceilings:	none
Services(list):	

describe	Corrugated steel
describe	Corrugated steel
	Diagonal cross-bracing

**Available documentation**

Architectural	partial
Structural	none
Mechanical	
Electrical	
Geotech report	

original designer name/date	Adjacent property records
original designer name/date	

**Damage**

Site:  
(refer DEE Table 4-2)

Site performance:	
Settlement:	none observed
Differential settlement:	none observed
Liquefaction:	none apparent
Lateral Spread:	none apparent
Differential lateral spread:	none apparent
Ground cracks:	none apparent
Damage to area:	none apparent

Describe damage:	
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	High Liquefaction Potential
notes (if applicable):	Lateral Spread Potential
notes (if applicable):	
notes (if applicable):	
notes (if applicable):	

**Building:** Current Placard Status:

Along Damage ratio:  Describe how damage ratio arrived at:   
 Describe (summary):

Across Damage ratio:   $Damage\_Ratio = \frac{(\%NBS(before) - \%NBS(after))}{\%NBS(before)}$   
 Describe (summary):

Diaphragms Damage?:  Describe:

CSWs: Damage?:  Describe:

Pounding: Damage?:  Describe:

Non-structural: Damage?:  Describe:

**Recommendations**

Level of repair/strengthening required:  Describe:

Building Consent required:  Describe:

Interim occupancy recommendations:  Describe:

Along Assessed %NBS before:  39% %NBS from IEP below If IEP not used, please detail assessment methodology:   
 Assessed %NBS after:

Across Assessed %NBS before:  39% %NBS from IEP below  
 Assessed %NBS after:

**IEP** Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1965-1976 h<sub>n</sub> from above: 6m

Seismic Zone, if designed between 1965 and 1992:  not required for this age of building   
not required for this age of building

	along	across
Period (from above):	0.12	0.12
(%NBS) <sub>nom</sub> from Fig 3.3:	5.0%	5.0%
Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0	1.00	1.00
Note 2: for RC buildings designed between 1976-1984, use 1.2	1.0	1.0
Note 3: for buildngs designed prior to 1935 use 0.8, except in Wellington (1.0)	1.0	1.0
<b>Final (%NBS)<sub>nom</sub>:</b>	<b>5%</b>	<b>5%</b>

**2.2 Near Fault Scaling Factor** Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

	along	across
Near Fault scaling factor (1/N(T,D), <b>Factor A</b> ):	1	1

**2.3 Hazard Scaling Factor**

Hazard factor Z for site from AS1170.5, Table 3.3:	0.30
Z <sub>1992</sub> , from NZS4203:1992	
Hazard scaling factor, <b>Factor B:</b>	3.333333333

**2.4 Return Period Scaling Factor**

Building Importance level (from above):	1
Return Period Scaling factor from Table 3.1, <b>Factor C:</b>	2.00

**2.5 Ductility Scaling Factor**

Assessed ductility (less than max in Table 3.2) Ductility scaling factor: =1 from 1976 onwards; or =k <sub>μ</sub> , if pre-1976, from Table 3.3:	along	across
	2.00	2.00
	1.57	1.57
Ductility Scaling Factor, <b>Factor D:</b>	1.57	1.57

**2.6 Structural Performance Scaling Factor:**

Sp:	0.700	0.700
Structural Performance Scaling Factor <b>Factor E:</b>	1.428571429	1.428571429

**2.7 Baseline %NBS, (NBS%)<sub>b</sub> = (%NBS)<sub>nom</sub> x A x B x C x D x E**

%NBS <sub>b</sub> :	75%	75%
---------------------	-----	-----

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

**3.1. Plan Irregularity, factor A:** significant 0.7

**3.2. Vertical irregularity, Factor B:** insignificant 1

**3.3. Short columns, Factor C:** insignificant 1

**3.4. Pounding potential**  
Pounding effect D1, from Table to right 1.0  
Height Difference effect D2, from Table to right 1.0

Therefore, Factor D: 1

**3.5. Site Characteristics** insignificant 1

Table for selection of D1	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
	Separation	0<sep<.005H	.005<sep<.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

**3.6. Other factors, Factor F**

For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum	Along	Across
Rationale for choice of F factor, if not 1	0.8	0.8
	25% Reduction due to Damage	25% Reduction due to Damage

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

**3.7. Overall Performance Achievement ratio (PAR)**

0.53	0.53
------	------

**4.3 PAR x (%NBS)<sub>b</sub>:**

PAR x Baseline %NBS:	39%	39%
----------------------	-----	-----

**4.4 Percentage New Building Standard (%NBS), (before)**

39%
-----



**GHD**

226 Antigua Street, Christchurch 8011

T: 64 3 378 0900 F: 64 3 377 8575 E: chcmail@ghd.com

**© GHD Limited 2012**

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

**Document Status**

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
FINAL	Nate Oakes	Derek Chinn		Nick Waddington		06/03/13