



CLIENTS | PEOPLE | PERFORMANCE

Sydenham Park - Toilet Block
PRK 1143 BLDG 001 EQ2
Detailed Engineering Evaluation
Quantitative Report
Version FINAL

230 Brougham Street, Sydenham



**Sydenham Park – Toilet Block
PRK 1143 BLDG 001 EQ2**

Detailed Engineering Evaluation
Quantitative Report
Version FINAL

230 Brougham Street, Sydenham

Christchurch City Council

Prepared By
Dale Donovan

Reviewed By
Atheel Allos

Date
28 January 2013



Contents

Quantitative Report Summary	i
1. Background	2
2. Compliance	3
2.1 Canterbury Earthquake Recovery Authority (CERA)	3
2.2 Building Act	4
2.3 Christchurch City Council Policy	5
2.4 Building Code	5
3. Earthquake Resistance Standards	6
4. Building Description	8
4.1 General	8
4.2 Gravity Load Resisting System	9
4.3 Lateral Load Resisting System	9
5. Damage Assessment	10
5.1 Surrounding Buildings	10
5.2 Residual Displacements and General Observations	10
5.3 Ground Damage	10
6. Geotechnical Consideration	11
6.1 Site Description	11
6.2 Published Information on Ground Conditions	11
6.3 Seismicity	13
6.4 Slope Failure and/or Rockfall Potential	14
6.5 Liquefaction Potential	14
6.6 Conclusions & Recommendations	14
7. Assessment	15
7.1 Quantitative Assessment	15
7.2 Seismic Coefficient	15
7.3 Bracing capacity of Reinforced Masonry Walls	16
7.1 Calculation of %NBS	17
8. Initial Capacity Assessment	18



8.1	Seismic Parameters	18
8.2	Wall Investigation	18
8.3	Sydenham Park Toilet Block Analysis Results	19
8.4	Discussion of Results	19
9.	Recommendations	21
10.	Limitations	22
10.1	General	22
10.2	Geotechnical Limitations	22

Table Index

Table 1	%NBS compared to relative risk of failure	7
Table 2	ECan Borehole Summary	11
Table 3	EQC Geotechnical Investigation Summary Table	12
Table 4	Summary of Known Active Faults'	13
Table 5	In Plane Analysis Results	19
Table 6	Out Of Plane Analysis Results	19

Figure Index

Figure 1	NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE	6
Figure 2	Post February 2011 Earthquake Aerial Photography	13
Figure 3	Plan Details and Wall Locations	18

Appendices

- A Photographs
- B Existing Drawings
- C CERA Building Evaluation Form

Quantitative Report Summary

Sydenham Park - Toilet Block

PRK_1143_BLDG_001 EQ2

Detailed Engineering Evaluation

Quantitative Report - SUMMARY

Version FINAL

230 Brougham Street, Sydenham

Background

This is a summary of the Quantitative report for the Sydenham Park Toilet Block, and is based in part on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and visual inspections on 16th July 2012 and 18th October 2012.

Building Description

The overall structure comprises of a single level toilet block. The roof and wall construction is consistent throughout. The roof is formed by lightweight asphalt tiles on plywood supported by timber purlins and beams. The western end of the roof is simply supported by the masonry walls. The eastern edge of the roof has a large cantilever section over the footpath and is supported by short steel posts fastened to the top of the wall with moment connections. Walls extending from strip footings to eaves level are formed by reinforced fully filled 190mm wide concrete masonry units.

Key Damage Observed

Key damage observed includes:-

- No key damage was observed.

Critical Structural Weaknesses

Liquefaction was identified as a potential Critical Structural Weakness in the structure.

Due to the ground conditions on site it is possible that liquefaction will occur. However the effect liquefaction will have on the structure will not be a major threat, and in terms of the IEP the site characteristics have been deemed to not be significant. Therefore no Critical Structural Weaknesses have been identified.

Building Strength

Based on the information available, and using the NZSEE guidelines for a Quantitative Assessment, the building's baseline post-earthquake capacity (including critical structural weaknesses and earthquake damage) has been assessed to be in the order of 100% NBS.

There were no critical structural weaknesses identified in the inspection; consequently there has been no reduction of the baseline %NBS. The building has been assessed to have a seismic capacity in the order of 100% NBS and is therefore considered neither Earthquake Prone nor potentially an Earthquake Risk building.

Recommendations

The recent seismic activity in Christchurch has not caused visible damage to the building. The building has achieved approximately 100% NBS following a Quantitative Detailed Engineering Evaluation. Further assessment is not required. No further works to the building are required in accordance with the NZSEE guidelines.

As no immediate collapse hazards or Critical Structural Weaknesses have been identified and the building has achieved 100% NBS there is no change to the normal occupancy.

1. Background

GHD has been engaged by Christchurch City Council (CCC) to undertake a detailed engineering evaluation of the Sydenham Park toilet block at 230 Brougham Street, Sydenham.

This report is a Quantitative Assessment and is based on NZS 1170.5: 2004 and NZS 4230: 2004.

The quantitative assessment of the building comprises an investigation of in-plane and out-of-plane strength of the reinforced masonry block walls. The investigation is based on the analysis of the seismic loads that the structure is subjected to, the analysis of the distribution of these forces throughout the structure and the analysis of the capacity of existing structural elements to resist the forces applied. The capacity of the existing structural elements is compared to the demand placed on the elements to give the percentage of New Building Standard (%NBS) of each of the structural elements.

Electromagnetic scans have been carried out on site to ascertain the extent of the reinforcement in the walls.

At the time of this report, no finite element modelling of the building structure has been carried out.

2. Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- ▶ The importance level and occupancy of the building
- ▶ The placard status and amount of damage
- ▶ The age and structural type of the building
- ▶ Consideration of any critical structural weaknesses
- ▶ The extent of any earthquake damage

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 – Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

Section 115 – Change of Use

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67% NBS however where practical achieving 100% NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67% NBS.

2.2.1 Section 121 – Dangerous Buildings

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- ▶ In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- ▶ In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- ▶ There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- ▶ There is a risk that that other property could collapse or otherwise cause injury or death; or
- ▶ A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4th September 2010.

The 2010 amendment includes the following:

- ▶ A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- ▶ A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
- ▶ A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- ▶ Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33% NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67% NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- ▶ The accessibility requirements of the Building Code.
- ▶ The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

2.4 Building Code

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- ▶ Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- ▶ Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

3. Earthquake Resistance Standards

For this assessment, the building's earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines 'Assessment and Improvement of the Structural Performance of Buildings in Earthquakes' (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 3-1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement)	Unacceptable	Unacceptable

Figure 3-1 NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE

Table 3-1 compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year). It is noted that the current seismic risk in Christchurch results in a 6% risk of exceedance in the next year.

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

Table 3-1 %NBS compared to relative risk of failure

4. Building Description

4.1 General

The toilet block is located at 230 Brougham Street, Sydenham Park in Sydenham. The original construction date of the structure is unknown but based on site observation is estimated to be the mid to late 1970's. The toilet block is not connected to any other structure in the park. The park site is bordered by residential properties in the south and west directions. The closest structure to the toilet block is a commercial property to the south approximately 10m away.




Figure 4-1 Plan Sketch Showing Key Structural Elements

The building is a single level of fully filled 200 series concrete masonry block walls. The single storey construction has a concrete slab on grade floor. The lightweight asphalt tile roof is supported by timber beams. The timber beams are supported at the front by steel posts and at the rear by the concrete masonry block walls.

The dimensions of the toilet block are approximately 7m long by 5m wide and 3.0m in height. Concrete footpaths lead to the entrances on the east and north sides of the block.

The structure appears to have been upgraded in the last 2 to 5 years. The toilets on the eastern side of the structure are lined with plaster on the walls. The roof over the toilets has been replaced with an angled roof cantilevering approximately 1.0m over the pedestrian access area. The rear storage area has plywood ceiling lining and a steel equal angle reinforcing one corner. The walls appear to be the original concrete masonry block walls.

In the storage area on the western side of the structure metal bracing has been installed on the northwest corner of the structure and a steel plate has been bolted above the doorway. See photographs 5 and 6 in Appendix A. There is no visible cracking in the block work at either of these locations. It is unclear if this is seismic strengthening work. However as the steel bracing has only been installed in two places any effect on the structure will be negligible.

No plans were made available for the structure.

4.2 Gravity Load Resisting System

The gravity loads in the structure are resisted by timber beams along the structure. The membrane type roof is supported by timber purlins on timber beams. The rear 2/3 of the roof is supported directly on the block walls. The timber beams are supported by steel posts at the front, connected to the top of the concrete masonry wall. The steel posts are attached to the roof with bolted moment joints. It was not possible to determine if the bolts were adequately embedded or fixed. The loads at the front are then transferred from the steel posts into the concrete block walls. From the block walls the loads travel into the slab on grade pad footings and then into the ground. The masonry wall loads are supported by the concrete floor slab and strip footings.

4.3 Lateral Load Resisting System

The roof consists of a timber frame. The connections at the eastern end of the building consist of circular hollow sections bolted to the top of the block walls. The connections for the remainders of the roof are not visible.

The masonry walls are the primary lateral load resistance system in this structure and serve to carry wall and roof seismic loads through to foundation level. The walls provide this function by in-plane panel action in shear and moment resistance. Upon reaching the foundations these lateral loads are dispersed into the founding soils via bearing and frictional resistance. The masonry walls are not propped at the eaves level by the roof structure. The masonry walls are considered to be acting as vertical cantilever walls connected to the foundations. Return walls can provide restraint to out-of-plane face loading to the masonry walls, but this action has been treated as negligible and disregarded as a support mechanism.

5. Damage Assessment

5.1 Surrounding Buildings

The Sydenham toilets are located in Sydenham Park in an area that is largely commercial. There are residential properties to the west and east of the toilet block. To the north and south of the park are commercial areas. The nearest commercial building is located approximately 10m to the south of the toilet block. Based on visual inspections from property boundaries there was no damage evident to these buildings.

5.2 Residual Displacements and General Observations

No residual displacements of the structure were noticed during the inspection of the building.

No damage was evident to the concrete masonry block walls of the building.

No damage was evident to the timber beam roof structure.

No cracks were visible in the slab on grade floors.

5.3 Ground Damage

There was no visible evidence of ground damage on the property or surrounding neighbours land.

6. Geotechnical Consideration

6.1 Site Description

The site is situated in the suburb of Sydenham, in central Christchurch. It is relatively flat at approximately 10m above mean sea level. It is approximately 750m south of the main southern railway line, 1.50km south of the Avon River, and 9km west of the coast (Pegasus Bay).

6.2 Published Information on Ground Conditions

6.2.1 Published Geology

The geological map of the area¹ indicates that the site is underlain by:

- Dominantly sand and silt overbank deposits, being alluvial soils of the Yaldhurst Member, sub-group of the Springston Formation, Holocene in age.

Figure 72 from Brown & Weeber indicates that groundwater is likely within 1m.

6.2.2 Environment Canterbury Logs

Information from Environment Canterbury (ECan) indicates that seven boreholes exist with lithographic logs within 250m of the site (Table 6-1).

These indicate the area is underlain by sandy gravels, with some silt and clay lenses, underlain by layers of gravel. Varying amounts of clay and peat are also indicated to be present. Groundwater was found between 1.06 and 9.9 mbgl.

Table 6-1 ECan Borehole Summary

Bore Name	Log Depth	Groundwater	Distance & Direction from Site
M36/1047	174.3m	9.9m	220m SE
M36-0967	99.1m	3.35m	265m SE
M36-0968	99.1m	3.35m	230m SW
M36-1001	120.7m	4.9m	230m SW
M36-4250	44.2m	3.2m	230m SW
M36-0982	44.2m	1.06m	230m S
M36-0973	161.5m	9.1m	250m SE

¹ Brown, L. J. & Weeber, J.H. (1992): *Geology of the Christchurch Urban Area*. Institute of Geological and Nuclear Sciences 1:25,000 Geological Map 1. IGNS Limited: Lower Hutt.

It should be noted the quality of soil logging descriptions included on the boreholes is unknown and were likely written by the well driller and not a geotechnical professional or to a recognised geotechnical standard. In addition strength data is not recorded.

6.2.3 EQC Geotechnical Investigations

The Earthquake Commission has undertaken geotechnical testing in the area of the site. Information pertaining to this investigation is included in the Tonkin & Taylor Report for Sydenham2. One investigation point was undertaken within 200m of the site, as summarised below in Table 6-2.

Table 6-2 EQC Geotechnical Investigation Summary Table

Bore Name	Orientation from Site	Depth (m bgl)	Log Summary
CPT-SYD-15	60m NE	0 – 1.2	Pre-drilled
		1.2 – 9.0	SILT and SAND mixtures, very loose to loose
		9.0 – 12.5	SANDS, medium dense
		12.5 – 13.2	SILT mixtures, very loose
		13.2 – 15.8	SANDS, medium dense

(WT at 1.5mbgl)

Initial observations of the CPT results indicate the soils are fine to medium grained, and are very loose to medium dense. Groundwater was encountered at 1.5mbgl.

6.2.4 CERA Land Zoning

Canterbury Earthquake Recovery Authority (CERA) has indicated the site is situated within the Green Zone, indicating that repair and rebuild may take place.

Land in the CERA green zone has been divided into three technical categories. These categories describe how the land is expected to perform in future earthquakes.

The site has been categorised as “N/A – Rural and Unmapped”. However, the neighbouring properties are indicated as being within the TC2 (yellow) zone³. This means that minor to moderate land damage from liquefaction is possible in future significant earthquakes.

6.2.5 Post February Aerial Photography

Aerial photography taken following the 22 February 2011 earthquake shows moderate liquefaction outside the building footprint and adjacent to the site, as shown in **Figure 6-1**.

² Tonkin & Taylor Ltd., 2011: Christchurch Earthquake Recovery, *Geotechnical Factual Report, Sydenham*.

³ CERA Landcheck website, <http://cera.govt.nz/my-property>

Figure 6-1 Post February 2011 Earthquake Aerial Photography⁴



6.2.6 Summary of Ground Conditions

From the information presented above, the ground conditions underlying the site are anticipated to comprise multiple strata of silt and sand, with varying amounts of clay. Groundwater is anticipated to be within 1.5m bgl.

6.3 Seismicity

6.3.1 Nearby Faults

There are many faults in the Canterbury region, however only those considered most likely to have an adverse effect on the site are detailed below.

Table 6-3 Summary of Known Active Faults^{5,6}

Known Active Fault	Distance from Site	Direction from Site	Max Likely Magnitude	Avg Recurrence Interval
Alpine Fault	130 km	NW	~8.3	~300 years

⁴ Aerial Photography Supplied by Koordinates sourced from <http://koordinates.com/layer/3185-christchurch-post-earthquake-aerial-photos-24-feb-2011/>

⁵ Stirling, M.W, McVerry, G.H, and Berryman K.R. (2002): "A New Seismic Hazard Model for New Zealand", *Bulletin of the Seismological Society of America*, Vol. 92 No. 5, June 2002, pp. 1878-1903.

⁶ GNS Active Faults Database, <http://maps.gns.cri.nz/website/af/viewer>

Ashley Fault	30 km	N	7.2	~2000 years
Greendale (2010) Fault	20 km	E	7.1	~15,000 years
Hope Fault	110 km	NW	7.2~7.5	120~200 years
Kelly Fault	110 km	NW	7.2	~150 years
Porters Pass Fault	60 km	NW	7.0	~1100 years

The recent earthquakes since 4 September 2010 have identified the presence of a previously unmapped active fault system underneath the Canterbury Plains, including Christchurch City, and the Port Hills. Research and published information on this system is in development and not generally available. Average recurrence intervals are yet to be estimated.

6.3.2 Ground Shaking Hazard

New Zealand Standard NZS 1170.5:2004 quantifies the Seismic Hazard factor for Christchurch as 0.30, being in a moderate to high earthquake zone. This value has been provisionally upgraded recently (from 0.22) to reflect the seismicity hazard observed in the earthquakes since 4 September 2010.

The recent seismic activity has produced earthquakes of Magnitude-6.3 with peak ground accelerations (PGA) up to twice the acceleration due to gravity (2g) in some parts of the city. This has resulted in widespread liquefaction throughout Christchurch.

6.4 Slope Failure and/or Rockfall Potential

Given the site's location, global slope instability is considered negligible. However, any localised retaining structures or embankments should be further investigated to determine the site-specific slope instability potential.

6.5 Liquefaction Potential

The site is considered to be moderately susceptible to liquefaction, due to the following reasons:

- Evidence of liquefaction from the post-earthquake aerial photography.
- Neighbouring properties technical category is TC2 yellow. This means that moderate to significant land damage from liquefaction is possible in future significant earthquakes.
- Presence of predominately sands and silts beneath the site.

6.6 Conclusions & Recommendations

This assessment is based on a review of the geology and existing ground investigation information, and observations from the Christchurch earthquakes since 4 September 2010.

The site appears to be situated on stratified alluvial deposits, comprising sand and silt. Associated with this the site also has a moderate liquefaction potential, in particular where sands are present.

A soil class of **D** (in accordance with NZS 1170.5:2004) should be adopted for the site.

Should a more comprehensive liquefaction and/or ground condition assessment be required, it is recommended that intrusive investigation be conducted.

7. Assessment

An initial inspection of the building was undertaken on the 16th July 2012. A further inspection of the building and scan of the reinforcement was carried out on 18th October 2012. No placard was evident during the inspection, however based on the inspection carried out it would be expected to have a green placard. Both the interior and exterior of the building were inspected. The main structural components of the building were not able to be viewed due to the nature of the walls and the fully clad ceilings.

Electro-magnetic scanning to the reinforced concrete was undertaken to confirm the presence, size, and spacing of reinforcement in the block walls. No drawings were made available for the structure.

The inspection also consisted of scrutinising the building to determine the structural systems and likely behaviour of the building during an earthquake. The site was assessed for damage, including examination of the ground conditions, checking for damage in areas where damage would be expected for the type of structure and noting general damage observed throughout the building in both structural and non-structural elements.

Magnetic scanning indicates vertical reinforcement to be D12 bars at 800mm centres and D20 horizontal bars at top, mid-height, and bottom of the concrete masonry block walls.

7.1 Quantitative Assessment

The quantitative assessment of the building includes the investigation of in-plane and out-of-plane strength of the masonry block walls. The investigation was based on the analysis of the seismic loads that the structure is subjected to, distribution of these forces throughout the structure and the analysis of the capacity of existing structural elements to resist the forces applied. A Hilti PS 200 Ferroskan was used to determine the level of reinforcement present in the walls. The capacity of the existing structural elements was compared to the demand placed on the elements to give the %NBS of each of the structural elements. A full methodology of the calculation process is attached in Appendix D.

7.2 Seismic Coefficient

The elastic site hazard spectrum for horizontal loading, $C(T)$, for the building was derived from Equation 3.1(1) of NZS 1170:2004

$$C(T) = C_h Z R N(T,D)$$

Where

$C_h(T)$ = the spectral shape factor determined from CL 3.1.2

Z = the hazard factor from CL 3.1.4 and the subsequent amendments which increased the hazard factor to 0.3 for Christchurch

$R = 1.0$, the return period factor from Table 3.5 for an annual probability of exceedance of 1/500 for an Importance Level 2 building

$N(T,D)$ = the near-fault scaling factor from CL 3.1.6

The structural performance factor, S_p , was calculated in accordance with CL 4.4.2

$$S_p = 1.3 - 0.3\mu$$

Where μ is the structural ductility factor. A structural ductility factor of 1.25 has been taken for lateral loading across and along the building; this is due to the walls being constructed of reinforced, filled concrete blocks.

For $T_1 < 0.7s$ and soil class D, the seismic weight coefficient was determined in accordance with Cl 5.2.1.1 of NZS 1170.5: 2011. For the purposes of calculating the seismic weight coefficient a period, T_1 , of 0.4 was assumed for the in-plane masonry walls. The coefficient was then calculated using Equation 5.2(1);

$$C_d(T_1) = \frac{C(T_1)S_p}{k_\mu}$$

Where

$$k_\mu = \frac{(\mu - 1)T_1}{0.7} + 1$$

7.3 Bracing capacity of Reinforced Masonry Walls

7.3.1 Shear Capacity

The shear capacity of the reinforced filled masonry wall was determined using NZS 4230: 2004. As there are no details as to the level of supervision during the construction stage, the Observation Type was classed in accordance with Table 3.1. The strength reduction factor, ϕ , for shear and shear friction was taken as 0.75 in accordance with Cl 3.4.7. The overall shear capacity of the wall was calculated from Cl 10.3.2.1, Equation 10-4;

$$V_n = v_n b_w d \phi$$

Where

v_n = the total shear stress which consists of the contribution of the masonry, v_m , the axial load, v_p and the contribution of the shear reinforcement, v_s .

b_w = the thickness of the wall

d = 0.8 times the length of the wall

7.3.2 In-Plane Moment Capacity

The moment capacity of the reinforced filled masonry wall was determined using NZS 4230: 2004 and the user's guide to NZS 4230: 2004. The strength reduction factor, ϕ , for flexure with or without axial tension or compression was taken as 0.85 in accordance with Cl 3.4.7. The overall moment capacity of the wall was calculated using the formula;

$$M_n = (N_n + A_s f_y) \times \left(\frac{t - a}{2} \right) \times \phi$$

Where

$$a = \frac{N_n + A_s f_y}{0.85 f'_m 1.0}$$

N_n = the axial load due to the self-weight of the wall

A_s = the area of steel reinforcement

f_y = the strength of steel as specified by the NZSEE guidelines

f'_m = specified compressive strength of masonry from Table 10.1

t = thickness of the masonry wall

7.3.3 Building Demand

The out-of-plane effects on the individual walls have been checked by analysing the wall as cantilever sections. The walls self-weight was modelled as a uniformly distributed load and multiplied by the elastic response factor, $C_d(T_1)$ per metre width. Structural analysis then determined the critical shear and moment demand.

The wall's out-of-plane capacity has been determined using the methodology for a singly-reinforced wall, as outlined in Sections 7.3.1 and 7.3.2 above, and then checked against the demand.

7.1 Calculation of %NBS

The shear and moment capacity of the concrete masonry walls, the axial, bending and shear capacity of the concrete masonry as well as the bracing capacity of the walls both in the along and across directions were then compared to their respective demands to assess which were the most critical and thus determine the overall %NBS for the building.

8. Initial Capacity Assessment

8.1 Seismic Parameters

The seismic design parameters based on current design requirements from NZS1170:2002 and the NZBC clause B1 for this building are:

- ▶ Site soil class assumed to be: D, NZS 1170.5:2004, Clause 3.1.3, Soft Soil;
- ▶ Site hazard factor, $Z = 0.3$, NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011;
- ▶ Return period factor $R_u = 1.0$, NZS 1170.5:2004, Table 3.5, Importance Level 2 structure with a 50 year design life.

8.2 Wall Investigation

The position of each wall is indicated in the plans below and each wall is named accordingly.




Figure 8-1 Plan Details and Wall Locations

8.3 Sydenham Park Toilet Block Analysis Results

The results of the in plane analysis and subsequent earthquake designation under the NZSEE guidelines are listed below in Table 8-1.

Wall number	V*	ϕV_n	%NBS	Earthquake Status	M*	ϕM_n	%NBS	Earthquake Status
	kN	kN			kNm	kNm		
1	100.9	3476	>100%	Not at Risk	232.1	2565	>100%	Not at Risk
2	91.1	637.2	>100%	Not at Risk	209.5	2565	>100%	Not at Risk
3	108.9	1321	>100%	Not at Risk	250.6	2565	>100%	Not at Risk
4	133.9	945.9	>100%	Not at Risk	308.1	921.1	>100%	Not at Risk
5	133.4	945.9	>100%	Not at Risk	306.9	921.1	>100%	Not at Risk
6	22.2	328.4	>100%	Not at Risk	51.1	169.2	>100%	Not at Risk
7	21.6	328.4	>100%	Not at Risk	49.6	169.2	>100%	Not at Risk

Table 8-1 In Plane Analysis Results

The results of the out of plane displacement response capability analysis and subsequent earthquake designation under the NZSEE guidelines are listed in Table 8-2.

Wall number	V*	ϕV_n	%NBS	Earthquake Status	M*	ϕM_n	%NBS	Earthquake Status
	kN	kN			kNm	kNm		
1	60.0	434.6	>100%	Not at Risk	3.88	7.11	100%	Not at Risk
2	60.0	79.7	>100%	Not at Risk	0.71	7.11	100%	Not at Risk
3	60.0	165.2	>100%	Not at Risk	0.71	7.11	100%	Not at Risk
4	64.3	84.5	>100%	Not at Risk	2.66	7.11	100%	Not at Risk
5	64.3	84.5	>100%	Not at Risk	2.66	7.11	100%	Not at Risk
6	49.9	68.4	>100%	Not at Risk	2.66	7.11	100%	Not at Risk
7	49.9	68.4	>100%	Not at Risk	2.66	7.11	100%	Not at Risk

Table 8-2 Out Of Plane Analysis Results

8.4 Discussion of Results

The loading standards following the Christchurch earthquakes have been modified with increased seismic requirements. The additional requirements has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.

Following a detailed assessment, the toilet block has been assessed as achieving 100 %NBS for both along and across the building. However this value is correct provided the bolted connections for the roof supports are capable of resisting seismic loads. Under the New Zealand Society for Earthquake Engineering (NZSEE) guidelines the Sydenham Park Toilet Block is considered neither Earthquake Prone nor a potential Earthquake Risk building. No critical structural weaknesses or collapse hazards have been identified in the building.

9. Recommendations

The recent seismic activity in Christchurch has caused no visible damage to the building. Because the building has no Critical Structural Weaknesses or collapse hazards the building can remain occupied. No further work is required in accordance with the NZSEE guidelines.

10. Limitations

10.1 General

This report has been prepared subject to the following limitations:

- ▶ Drawings of the building were unavailable. As a result the information contained in this report has been inferred from visual inspections of the building and site only.
- ▶ No intrusive structural investigations have been undertaken. Electro-magnetic scanning of the walls was conducted to determine the levels of steel reinforcement present.
- ▶ No level or verticality surveys have been undertaken.
- ▶ No material testing has been undertaken.
- ▶ No calculations, other than those detailed in Section 8 have been carried out on the structure.

It is noted that this report has been prepared at the request of Christchurch City Council and is intended to be used for their purposes only. GHD accepts no responsibility for any other party or person who relies on the information contained in this report.

10.2 Geotechnical Limitations

This report presents the results of a geotechnical appraisal prepared for the purpose of this commission, and for prepared solely for the use of Christchurch City Council and their advisors. The data and advice provided herein relate only to the project and structures described herein and must be reviewed by a competent geotechnical engineer before being used for any other purpose. GHD Limited (GHD) accepts no responsibility for other use of the data.

The advice tendered in this report is based on a visual geotechnical appraisal. No subsurface investigations have been conducted. An assessment of the topographical land features have been made based on this information. It is emphasised that Geotechnical conditions may vary substantially across the site from where observations have been made. Subsurface conditions, including groundwater levels can change in a limited distance or time. In evaluation of this report cognisance should be taken of the limitations of this type of investigation.

An understanding of the geotechnical site conditions depends on the integration of many pieces of information, some regional, some site specific, some structure specific and some experienced based. Hence this report should not be altered, amended or abbreviated, issued in part and issued incomplete in any way without prior checking and approval by GHD. GHD accepts no responsibility for any circumstances, which arise from the issue of the report, which have been modified in any way as outlined above.

Appendix A

Photographs



Photograph 1 North elevation.



Photograph 2 View of the toilet block from the south east.



Photograph 3 View of the toilet block from the west.



Photograph 4 One of the areas where wall reinforcement was checked.



Photograph 5 Steel angle bolted to north west corner of the toilet block.



Photograph 6 Steel angle bolted to north west corner of the toilet block.



Photograph 7 Raised roof structure on the eastern side of the toilet block.



Photograph 8 Steel posts supporting roof beams on the eastern side of the structure.



Photograph 9 Middle and western sections of the roof rest directly on the concrete block walls.



Photograph 10 The roof appears to be covered with asphalt sheets.

Appendix B

Existing Drawings

No existing drawings were available for the building.

Appendix C
CERA Building Evaluation Form

Detailed Engineering Evaluation Summary Data

V1.11

Location			Reviewer: <input type="text" value="Atheel Allos"/>
Building Name: <input type="text" value="Sydenham Park Toilets"/>	Unit No: <input type="text" value="230"/>	Street: <input type="text" value="Brougham Street"/>	CPEng No: <input type="text" value="228984"/>
Building Address: <input type="text" value="Brougham Street"/>	230		Company: <input type="text" value="GHD"/>
Legal Description: <input type="text" value="PRK_1143_BLDG_001 EQ2"/>			Company project number: <input type="text"/>
			Company phone number: <input type="text"/>
	Degrees	Min	Sec
GPS south: <input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
GPS east: <input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Building Unique Identifier (CCC): <input type="text" value="PRK_1143_BLDG_001 EQ2"/>			Date of submission: <input type="text" value="28/01/2013"/>
			Inspection Date: <input type="text" value="16/07/2012"/>
			Revision: <input type="text" value="final"/>
			Is there a full report with this summary? <input type="text" value="yes"/>

Site		Max retaining height (m): <input type="text"/>
Site slope: <input type="text" value="flat"/>	Soil type: <input type="text" value="silty sand"/>	Soil Profile (if available): <input type="text"/>
Site Class (to NZS1170.5): <input type="text" value="D"/>	Proximity to waterway (m, if <100m): <input type="text"/>	If Ground improvement on site, describe: <input type="text"/>
Proximity to clifftop (m, if < 100m): <input type="text"/>	Proximity to cliff base (m,if <100m): <input type="text"/>	Approx site elevation (m): <input type="text"/>

Building		single storey = 1	Ground floor elevation (Absolute) (m): <input type="text"/>
No. of storeys above ground: <input type="text" value="1"/>	Ground floor split? <input type="text" value="no"/>	Stores below ground: <input type="text" value="0"/>	Ground floor elevation above ground (m): <input type="text"/>
Foundation type: <input type="text" value="mat slab"/>	Building height (m): <input type="text" value="3.20"/>	Floor footprint area (approx): <input type="text" value="35"/>	if Foundation type is other, describe: <input type="text" value="Slab on grade"/>
Age of Building (years): <input type="text"/>	Strengthening present? <input type="text" value="no"/>	Importance level (to NZS1170.5): <input type="text" value="IL2"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text" value="1.5"/>
	Use (ground floor): <input type="text" value="public"/>		Date of design: <input type="text" value="1976-1992"/>
	Use (upper floors): <input type="text"/>		If so, when (year)? <input type="text"/>
	Use notes (if required): <input type="text"/>		And what load level (%g)? <input type="text"/>
			Brief strengthening description: <input type="text"/>

Gravity Structure		rafter type, purlin type and cladding: <input type="text"/>
Gravity System: <input type="text" value="load bearing walls"/>	Roof: <input type="text" value="timber framed"/>	slab thickness (mm): <input type="text"/>
Floors: <input type="text" value="concrete flat slab"/>	Beams: <input type="text" value="none"/>	overall depth x width (mm x mm): <input type="text"/>
Columns: <input type="text"/>	Walls: <input type="text" value="partially filled concrete masonry"/>	thickness (mm): <input type="text" value="200"/>

Lateral load resisting structure		Note: Define along and across in detailed report!	note total length of wall at ground (m): <input type="text" value="7"/>
Lateral system along: <input type="text" value="partially filled CMU"/>	Ductility assumed, μ : <input type="text" value="1.25"/>	0.40 from parameters in sheet	wall thickness (m): <input type="text" value="0.2"/>
Period along: <input type="text" value="0.40"/>	Total deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text" value="estimated"/>
maximum interstorey deflection (ULS) (mm): <input type="text"/>	Lateral system across: <input type="text" value="partially filled CMU"/>		estimate or calculation? <input type="text"/>
			estimate or calculation? <input type="text"/>
			note total length of wall at ground (m): <input type="text" value="5"/>

Ductility assumed, μ :	<input type="text" value="1.25"/>	0.40 from parameters in sheet	wall thickness (m):	<input type="text" value="0.2"/>
Period across:	<input type="text" value="0.40"/>		estimate or calculation?	<input type="text" value="estimated"/>
Total deflection (ULS) (mm):	<input type="text"/>		estimate or calculation?	<input type="text"/>
maximum interstorey deflection (ULS) (mm):	<input type="text"/>		estimate or calculation?	<input type="text"/>

Separations:

north (mm):	<input type="text"/>	leave blank if not relevant
east (mm):	<input type="text"/>	
south (mm):	<input type="text"/>	
west (mm):	<input type="text"/>	

Non-structural elements

Stairs:	<input type="text"/>	describe:	<input type="text"/>
Wall cladding:	<input type="text" value="plaster system"/>	describe:	<input type="text" value="Lined toilets, unlined storage area"/>
Roof Cladding:	<input type="text" value="Shingles or shakes"/>	describe:	<input type="text" value="Asphalt Tiles"/>
Glazing:	<input type="text" value="timber frames"/>		
Ceilings:	<input type="text" value="heavy tiles"/>		<input type="text" value="Plywood or tongue and groove ceilings"/>
Services(list):	<input type="text"/>		

Available documentation

Architectural:	<input type="text" value="none"/>	original designer name/date:	<input type="text"/>
Structural:	<input type="text" value="none"/>	original designer name/date:	<input type="text"/>
Mechanical:	<input type="text" value="none"/>	original designer name/date:	<input type="text"/>
Electrical:	<input type="text" value="none"/>	original designer name/date:	<input type="text"/>
Geotech report:	<input type="text" value="partial"/>	original designer name/date:	<input type="text"/>

Damage

Site: (refer DEE Table 4-2)

Site performance:

Describe damage:

Settlement:	<input type="text" value="none observed"/>	notes (if applicable):	<input type="text"/>
Differential settlement:	<input type="text" value="none observed"/>	notes (if applicable):	<input type="text"/>
Liquefaction:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Lateral Spread:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Differential lateral spread:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Ground cracks:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>
Damage to area:	<input type="text" value="none apparent"/>	notes (if applicable):	<input type="text"/>

Building:

Current Placard Status:

Along

Damage ratio:

Describe (summary):

Describe how damage ratio arrived at:

Across

Damage ratio:

Describe (summary):

$$Damage _ Ratio = \frac{(\% NBS (before) - \% NBS (after))}{\% NBS (before)}$$

Diaphragms

Damage?:

Describe:

CSWs:

Damage?:

Describe:

Pounding:

Damage?:

Describe:

Non-structural:

Damage?:

Describe:

Recommendations

Level of repair/strengthening required: none
 Building Consent required: no
 Interim occupancy recommendations: full occupancy

Describe:
 Describe:
 Describe:

Along Assessed %NBS before: 100% ##### %NBS from IEP below
 Assessed %NBS after: 100%

Across Assessed %NBS before: 100% ##### %NBS from IEP below
 Assessed %NBS after: 100%

If IEP not used, please detail assessment methodology: Quantitative Assessment

IEP Use of this method is not mandatory - more detailed analysis may give a different answer, which would take precedence. Do not fill in fields if not using IEP.

Period of design of building (from above): 1976-1992

h_n from above: 1.5m

Seismic Zone, if designed between 1965 and 1992: B

not required for this age of building
 not required for this age of building

Period (from above): along 0.4 across 0.4
 (%NBS)_{nom} from Fig 3.3:

Note:1 for specifically design public buildings, to the code of the day: pre-1965 = 1.25; 1965-1976, Zone A = 1.33; 1965-1976, Zone B = 1.2; all else 1.0
 Note 2: for RC buildings designed between 1976-1984, use 1.2
 Note 3: for buildings designed prior to 1935 use 0.8, except in Wellington (1.0)

Final (%NBS)_{nom}: along 0% across 0%

2.2 Near Fault Scaling Factor

Near Fault scaling factor, from NZS1170.5, cl 3.1.6:

Near Fault scaling factor (1/N(T,D), **Factor A**): along #DIV/0! across #DIV/0!

2.3 Hazard Scaling Factor

Hazard factor Z for site from AS1170.5, Table 3.3:
 Z₁₉₉₂, from NZS4203:1992
 Hazard scaling factor, **Factor B**: #DIV/0!

2.4 Return Period Scaling Factor

Building Importance level (from above): 2
 Return Period Scaling factor from Table 3.1, **Factor C**:

2.5 Ductility Scaling Factor

Assessed ductility (less than max in Table 3.2)
 Ductility scaling factor: =1 from 1976 onwards; or =k_μ, if pre-1976, from Table 3.3:
 Ductility Scaling Factor, **Factor D**: along 1.00 across 1.00

2.6 Structural Performance Scaling Factor:

Sp:
 Structural Performance Scaling Factor **Factor E**: #DIV/0! #DIV/0!

2.7 Baseline %NBS, (NBS%)_b = (%NBS)_{nom} x A x B x C x D x E

%NBS_b: #DIV/0! #DIV/0!

Global Critical Structural Weaknesses: (refer to NZSEE IEP Table 3.4)

3.1. Plan Irregularity, factor A: insignificant 1

3.2. Vertical irregularity, Factor B: insignificant 1

3.3. Short columns, Factor C: insignificant 1

3.4. Pounding potential
Pounding effect D1, from Table to right
Height Difference effect D2, from Table to right

Therefore, Factor D: 0

3.5. Site Characteristics insignificant 1

Table for selection of D1	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Alignment of floors within 20% of H	0.7	0.8	1
Alignment of floors not within 20% of H	0.4	0.7	0.8

Table for Selection of D2	Severe	Significant	Insignificant/none
Separation	0<sep<.005H	.005<sep<.01H	Sep>.01H
Height difference > 4 storeys	0.4	0.7	1
Height difference 2 to 4 storeys	0.7	0.9	1
Height difference < 2 storeys	1	1	1

3.6. Other factors, Factor F For ≤ 3 storeys, max value =2.5, otherwise max valule =1.5, no minimum
Rationale for choice of F factor, if not 1

Detail Critical Structural Weaknesses: (refer to DEE Procedure section 6)

List any: Refer also section 6.3.1 of DEE for discussion of F factor modification for other critical structural weaknesses

3.7. Overall Performance Achievement ratio (PAR) 0.00 0.00

4.3 PAR x (%NBS)b: PAR x Baselline %NBS: #DIV/0! #DIV/0!

4.4 Percentage New Building Standard (%NBS), (before) #DIV/0!



GHD

Level 11, Guardian Trust House
15 Willeston street, Wellington 6011
T: 64 4 472 0799 F: 64 4 472 0833 E: wgtnmail@ghd.com

© GHD Limited 2012

This document is and shall remain the property of GHD Limited. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

Document Status

Rev No.	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
Final	Dale Donovan	David Lee		Nick Waddington		28/01/2013