

CHRISTCHURCH CITY COUNCIL  
BU 1662-005 EQ2  
Templeton Pool – Toddlers Pool Plant Room  
62 Kirk Road, Templeton



QUALITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 23 May 2013



CHRISTCHURCH CITY COUNCIL  
BU 1662-005 EQ2  
Templeton Pool – Toddlers Pool Plant Room  
62 Kirk Roads, Templeton

## QUALITATIVE ASSESSMENT REPORT

FINAL

- Rev B
- 23 May 2013

---

Sinclair Knight Merz  
142 Sherborne Street  
Saint Albans  
PO Box 21011, Edgeware  
Christchurch, New Zealand  
Tel: +64 3 940 4900  
Fax: +64 3 940 4901  
Web: [www.skmconsulting.com](http://www.skmconsulting.com)

**COPYRIGHT:** The concepts and information contained in this document are the property of Sinclair Knight Merz Limited. Use or copying of this document in whole or in part without the written permission of Sinclair Knight Merz constitutes an infringement of copyright.

**LIMITATION:** This report has been prepared on behalf of and for the exclusive use of Sinclair Knight Merz Limited's Client, and is subject to and issued in connection with the provisions of the agreement between Sinclair Knight Merz and its Client. Sinclair Knight Merz accepts no liability or responsibility whatsoever for or in respect of any use of or reliance upon this report by any third party.

## Contents



<b>1. Executive Summary</b>	<b>1</b>
1.1. Background	1
1.2. Key Damage Observed	1
1.3. Critical Structural Weaknesses	2
1.4. Indicative Building Strength (from IEP and CSW assessment)	2
1.5. Recommendations	2
<b>2. Introduction</b>	<b>3</b>
<b>3. Compliance</b>	<b>4</b>
3.1. Canterbury Earthquake Recovery Authority (CERA)	4
3.2. Building Act	5
3.3. Christchurch City Council Policy	6
3.4. Building Code	7
<b>4. Earthquake Resistance Standards</b>	<b>8</b>
<b>5. Building Details</b>	<b>10</b>
5.1. Building Description	10
5.2. Gravity Load Resisting System	10
5.3. Seismic Load Resisting System	10
5.4. Geotechnical Conditions	10
<b>6. Damage Summary</b>	<b>11</b>
<b>7. Initial Seismic Evaluation</b>	<b>12</b>
7.1. The Initial Evaluation Procedure Process	12
7.2. Available Information, Assumptions and Limitations	13
7.3. Survey	14
7.4. Critical Structural Weaknesses	14
7.5. Qualitative Assessment Results	14
<b>8. Further Investigation</b>	<b>15</b>
<b>9. Conclusion</b>	<b>16</b>
<b>10. Limitation Statement</b>	<b>17</b>
<b>11. Appendix 1 – Photos</b>	<b>18</b>
<b>12. Appendix 2 – IEP Report</b>	<b>19</b>
<b>13. Appendix 3 – CERA Standardised Report Form</b>	<b>26</b>
<b>14. Appendix 4 – Geotechnical Desk Study</b>	<b>28</b>



## Document history and status

Revision	Date issued	Reviewed by	Approved by	Date approved	Revision type
A	25/5/2013	BJ Donnell	N Calvert	25/5/2013	Draft
B	23/05/2013	N Calvert	N Calvert	23/05/2013	Final Issue

## Approval

	Signature	Date	Name	Title
Author		23/05/2013	Kimberley Wylie	Structural Engineer
Approver		23/05/2013	Nick Calvert	Senior Structural Engineer

## Distribution of copies

Revision	Copy no	Quantity	Issued to
A	1	1	CCC
B	1	1	CCC

<b>Printed:</b>	23 May 2013
<b>Last saved:</b>	23 May 2013 09:56 AM
<b>File name:</b>	PRO 1662 B005 Templeton Pool Toddlers Pool Plant Room Qualitative Final.docx
<b>Author:</b>	Kimberley Wylie
<b>Project manager:</b>	Alex Martin
<b>Name of organisation:</b>	Christchurch City Council
<b>Name of project:</b>	Christchurch City Council Structures Panel
<b>Name of document:</b>	BU 1662-005 EQ2 – Templeton Pool Toddlers Pool Plant Room
<b>Document version:</b>	B
<b>Project number:</b>	ZB01276.054

# 1. Executive Summary

## 1.1. Background

A Qualitative Assessment was carried out on building BU 1662-005 EQ2 located at 62 Kirk Road, Templeton. This building is a single story timber framed structure that is used as a plant room for the toddlers pool located at Templeton Pool. An aerial photograph illustrating the buildings location is shown below in Figure 1. Detailed descriptions outlining the building's age and construction type are given in Section 5 of this report.



### ■ **Figure 1 Aerial Photograph of Building BU 1662-005 EQ2 Located at 62 Kirk Road**

The qualitative assessment broadly includes a summary of the buildings damage as well as an initial assessment of the current Seismic Capacity compared with current seismic code loads using the Initial Evaluation Procedure (IEP).

This Qualitative report for the building structure is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011 and our visual inspection carried out on the 27 April 2012.

## 1.2. Key Damage Observed

Key damage observed includes:-

- No damage was observed during our inspection.



### **1.3. Critical Structural Weaknesses**

This structure contains no critical structural weaknesses.

### **1.4. Indicative Building Strength (from IEP and CSW assessment)**

Based on the information available, and using the NZSEE Initial Evaluation Procedure, the buildings original capacity has been assessed to be approximately 100%NBS. No damage was observed during our site investigation. Due to this the post-earthquake capacity is also approximately 100%NBS.

As noted above our analysis indicates that the current seismic capacity of the building is approximately 100% NBS and therefore is not a potentially earthquake prone building.

### **1.5. Recommendations**

It is recommended that:

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.

## 2. Introduction

Sinclair Knight Merz was engaged by the Christchurch City Council to prepare a qualitative assessment report for building BU 1662-005 EQ2 located at 62 Kirk Road, Templeton following the magnitude 6.3 earthquake which occurred in the afternoon of the 22nd of February 2011 and the subsequent aftershocks.

The qualitative assessment uses the methodology recommended in the Engineering Advisory Group document “Guidance on Detailed Engineering Evaluation of Earthquake affected Non-residential Buildings in Canterbury”. The qualitative assessment broadly includes a summary of the building damage as well as an initial assessment of the current likely Seismic Capacity compared with current seismic requirements.

A qualitative assessment involves inspections of the building and a desktop review of existing structural and geotechnical information, including existing drawings and calculations, if available.

The purpose of the assessment is to determine the likely building performance and damage patterns, to identify any potential critical structural weaknesses or collapse hazards, and to make an initial assessment of the likely building strength in terms of percentage of new building standard (%NBS).

This report describes the structural damage observed during our inspection and indicates suggested remediation measures. The inspection was undertaken from floor levels and was a visual inspection only. Our report reflects the situation at the time of the inspection and does not take account of changes caused by any events following our inspection. A full description of the basis on which we have undertaken our visual inspection is set out in Section 7.2

The NZ Society for Earthquake Engineering (NZSEE) Initial Evaluation Procedure (IEP) was used to assess the likely performance of the building in a seismic event relative to New Building Standard (NBS). 100% NBS is equivalent to the strength of a building that fully complies with current codes. This includes a recent increase of the Christchurch seismic hazard factor from 0.22 to 0.3<sup>1</sup>.

At the time of this report, no intrusive site investigation, detailed analysis, or modelling of the building structure have been carried out. No structural drawings were available for this structure and as a result the buildings description outlined in Section 5 is based only on our visual inspection carried out on the 27 April 2012.

---

<sup>1</sup> <http://www.dbh.govt.nz/seismicity-info>

### **3. Compliance**

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

#### **3.1. Canterbury Earthquake Recovery Authority (CERA)**

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

##### **Section 38 – Works**

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

##### **Section 51 – Requiring Structural Survey**

This section enables the chief executive to require a building owner, insurer or mortgagee carry out a full structural survey before the building is re-occupied.

We understand that CERA will require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). It is anticipated that CERA will adopt the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This document sets out a methodology for both qualitative and quantitative assessments.

The qualitative assessment is a desk-top and site inspection assessment. It is based on a thorough visual inspection of the building coupled with a review of available documentation such as drawings and specifications. The quantitative assessment involves analytical calculation of the buildings strength and may require non-destructive or destructive material testing, geotechnical testing and intrusive investigation.

It is anticipated that factors determining the extent of evaluation and strengthening level required will include:

- The importance level and occupancy of the building
- The placard status and amount of damage
- The age and structural type of the building
- Consideration of any critical structural weaknesses



- The extent of any earthquake damage

### **3.2. Building Act**

Several sections of the Building Act are relevant when considering structural requirements:

#### **3.2.1. Section 112 – Alterations**

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to any alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

#### **3.2.2. Section 115 – Change of Use**

This section requires that the territorial authority (in this case Christchurch City Council (CCC)) be satisfied that the building with a new use complies with the relevant sections of the Building Code 'as near as is reasonably practicable'. Regarding seismic capacity 'as near as reasonably practicable' has previously been interpreted by CCC as achieving a minimum of 67%NBS however where practical achieving 100%NBS is desirable. The New Zealand Society for Earthquake Engineering (NZSEE) recommend a minimum of 67%NBS.

#### **3.2.3. Section 121 – Dangerous Buildings**

The definition of dangerous building in the Act was extended by the Canterbury Earthquake (Building Act) Order 2010, and it now defines a building as dangerous if:

- in the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
- in the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
- there is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a 'moderate earthquake' (refer to Section 122 below); or
- there is a risk that that other property could collapse or otherwise cause injury or death; or
- a territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

#### **3.2.4. Section 122 – Earthquake Prone Buildings**

This section defines a building as earthquake prone if its ultimate capacity would be exceeded in a 'moderate earthquake' and it would be likely to collapse causing injury or death, or damage to other property. A moderate earthquake is defined by the building regulations as one that would generate ground shaking 33% of the shaking used to design an equivalent new building.

### **3.2.5. Section 124 – Powers of Territorial Authorities**

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

### **3.2.6. Section 131 – Earthquake Prone Building Policy**

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

## **3.3. Christchurch City Council Policy**

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in 2006. This policy was amended immediately following the Darfield Earthquake of the 4<sup>th</sup> September 2010.

The 2010 amendment includes the following:

- A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
- A strengthening target level of 67% of a new building for buildings that are Earthquake Prone. Council recognises that it may not be practicable for some repairs to meet that target. The council will work closely with building owners to achieve sensible, safe outcomes;
- A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
- Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

We anticipate that any building with a capacity of less than 33%NBS (including consideration of critical structural weaknesses) will need to be strengthened to a target of 67%NBS of new building standard as recommended by the Policy.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply 'as near as is reasonably practicable' with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.



### **3.4. Building Code**

The building code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

After the February Earthquake, on 19 May 2011, Compliance Document B1: Structure was amended to include increased seismic design requirements for Canterbury as follows:

- a) Hazard Factor increased from 0.22 to 0.3 (36% increase in the basic seismic design load)
- b) Serviceability Return Period Factor increased from 0.25 to 0.33 (80% increase in the serviceability design loads when combined with the Hazard Factor increase)

The increase in the above factors has resulted in a reduction in the level of compliance of an existing building relative to a new building despite the capacity of the existing building not changing.



## 4. Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The new building standard load requirements have been determined in accordance with the current earthquake loading standard (NZS 1170.5:2004 Structural design actions - Earthquake actions - New Zealand).

The likely capacity of this building has been derived in accordance with the New Zealand Society for Earthquake Engineering (NZSEE) guidelines ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’ (AISPBE), 2006. These guidelines provide an Initial Evaluation Procedure that assesses a buildings capacity based on a comparison of loading codes from when the building was designed and currently. It is a quick high-level procedure that can be used when undertaking a Qualitative analysis of a building. The guidelines also provide guidance on calculating a modified Ultimate Limit State capacity of the building which is much more accurate and can be used when undertaking a Quantitative analysis.

The New Zealand Society for Earthquake Engineering has proposed a way for classifying earthquake risk for existing buildings in terms of %NBS and this is shown in Figure 2 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use) This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement	Unacceptable	Unacceptable

■ **Figure 2: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines**

Table 1 below provides an indication of the risk of failure for an existing building with a given percentage NBS, relative to the risk of failure for a new building that has been designed to meet current Building Code criteria (the annual probability of exceedance specified by current earthquake design standards for a building of ‘normal’ importance is 1/500, or 0.2% in the next year, which is equivalent to 10% probability of exceedance in the next 50 years).



■ **Table 1: %NBS compared to relative risk of failure**

<b>Percentage of New Building Standard (%NBS)</b>	<b>Relative Risk (Approximate)</b>
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

## **5. Building Details**

### **5.1. Building Description**

Building BU 1662-005 EQ2 is a single storey timber framed building that is used as a plant room for the toddlers pool located at Templeton Pool. The roof is constructed from timber purlins that are supported on the timber framed walls. The roof and wall cladding consists of a light weight corrugated steel cladding. The building sits on concrete foundations and a concrete floor slab. The footprint of this building is approximately 3.0m x3.0m and is 3.0m high. Due to the lack of any structural drawings a post 2000 construction date has been assumed based on the architecture and the condition of the structure.

### **5.2. Gravity Load Resisting System**

Our evaluation was based on our site investigation conducted on the 27 April 2012.

The roof structure consists of timber purlins which are supported on the timber stud wall. The building sits on concrete foundations and a concrete floor slab.

### **5.3. Seismic Load Resisting System**

For the lateral analysis of this building the ‘across direction’ has been taken as north-south whereas the ‘along direction’ has been taken as east-west.

Lateral loads acting across and along the building will be resisted by the roof and wall cladding. If the building is subjected to large shaking it may go out of plumb due to the lack of structural bracing. However due to the light weight nature and intermittent occupancy of the structure this is unlikely to be life threatening.

### **5.4. Geotechnical Conditions**

A geotechnical desktop study was carried out for this site. The main conclusions from this report are:

- The site has been assessed as NZS 1170.5 Class D (soft or deep soil, including gravel exceeding 100 m in depth) using nearby borehole investigation data
- Liquefaction risk is low at this site.

Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed. The full geotechnical desktop study can be found in Appendix 4.



## **6. Damage Summary**

SKM undertook inspections on the 27 April 2012. The following was observed during the time of inspection:

- 1) No external or internal damage was noted.
- 2) No visual evidence of settlement was noted at this site. Therefore a level survey is not required at this stage of assessment.



## 7. Initial Seismic Evaluation

### 7.1. The Initial Evaluation Procedure Process

This section covers the initial seismic evaluation of the building as detailed in the NZSEE ‘Assessment and Improvement of the Structural Performance of Buildings in Earthquakes’. The IEP grades buildings according to their likely performance in a seismic event. The procedure is not yet recognised by the NZ Building Code but is widely used and recognised by the Christchurch City Council as the preferred method for preliminary seismic investigations of buildings<sup>2</sup>.

The IEP is a coarse screening process designed to identify buildings that are likely to be earthquake prone. The IEP process ranks buildings according to how well they are likely to perform relative to a new building designed to current earthquake standards, as shown in Table 2. The building grade is indicated by the percent of the required New Building Standard (%NBS) strength that the building is considered to have. Earthquake prone buildings are defined as having less than 33 %NBS strength which correlates to an increased risk of approximately 10 times that of 100% NBS (refer Table 1)<sup>3</sup>. Buildings in Christchurch City that are identified as being earthquake prone are required by law to be followed up with a detailed assessment and strengthening work within 30 years of the owner being notified that the building is potentially earthquake prone<sup>4</sup>.

**Table 2: IEP Risk classifications**

Description	Grade	Risk	%NBS	Structural performance
Low risk building	A+	Low	> 100	Acceptable. Improvement may be desirable.
	A		100 to 80	
	B		80 to 67	
Moderate risk building	C	Moderate	67 to 33	Acceptable legally. Improvement recommended.
High risk building	D	High	33 to 20	Unacceptable. Improvement required.
	E		< 20	

The IEP is a simple desktop study that is useful for risk management. No detailed calculations are done and so it relies on an inspection of the building and its plans to identify the structural members and describe the likely performance of the building in a seismic event. A review of the

<sup>2</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>

<sup>3</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p 2-2

<sup>4</sup> <http://resources.ccc.govt.nz/files/EarthquakeProneDangerousAndInsanitaryBuildingsPolicy2010.pdf>



plans is also likely to identify any critical structural weaknesses. The IEP assumes that the building was properly designed and built according to the relevant codes at the time of construction. The IEP method rates buildings based on the code used at the time of construction and some more subjective parameters associated with how the building is detailed and so it is possible that %NBS derived from different engineers may differ.

This assessment describes only the likely seismic Ultimate Limit State (ULS) performance of the building. The ULS is the level of earthquake that can be resisted by the building without catastrophic failure. The IEP does not attempt to estimate Serviceability Limit State (SLS) performance of the building, or the level of earthquake that would start to cause damage to the building<sup>5</sup>. This assessment concentrates on matters relating to life safety as damage to the building is a secondary consideration. SLS performance of the building can be estimated by scaling the current code levels if required.

The NZ Building Code describes that the relevant codes for NBS are primarily:

- AS/NZS 1170 Structural Design Actions
- NZS 3101:2006 Concrete Structures Standard
- NZS 3404:1997 Steel Structures Standard
- NZS4230:2004 Design of Reinforced Concrete Masonry Structures
- NZS 3603:1993 Timber Structures Standard
- NZS 3604:2011 Timber Framed Buildings

## **7.2. Available Information, Assumptions and Limitations**

Following our inspection on the 27 April 2012, SKM carried out a preliminary structural review. The structural review was undertaken using the available information which was as follows:

- SKM site measurements and inspection findings of the building.
- No structural drawings were available for this building.

The assumptions and design criteria were used during our assessment:

- The building was built according to good practices at the time.
- Standard design assumptions as described in AS/NZS1170.0:2002
  - 50 year design life, which is the default NZ Building Code design life.
  - Structure Importance Level 1 since the total floor area is <math><30\text{m}^2</math> and represents structures presenting a low degree of hazard to life and other property.
- Ductility level of 1, based on our assessment and code requirements at the time of design.

---

<sup>5</sup> NZSEE 2006, *Assessment and Improvement of the Structural Performance of Buildings in Earthquakes*, p2-9



- Site hazard factor,  $Z = 0.3$ , NZBC, Clause B1 Structure, Amendment 11 effective from 1 August 2011

This IEP was based on our visual inspection of the building. Since it is not a full design and construction review, it has the following limitations:

- It is not likely to pick up on any original design or construction errors (if they exist)
- Other possible issues that could affect the performance of the building such as corrosion and modifications to the building will not be identified
- The IEP deals only with the structural aspects of the building. Other aspects such as building services are not covered.
- The IEP does not involve a detailed analysis or an element by element code compliance check.

### 7.3. Survey

There was no visible settlement of the structure, nor were there any significant ground movement issues around the building. The building is zoned as TC1 on the CERA ‘Technical Categories Map’ for residential properties. Due to both these factors we do not recommend that any survey be undertaken at this stage of the assessment.

### 7.4. Critical Structural Weaknesses

No critical structural weaknesses for the building were observed during our visual inspection.

### 7.5. Qualitative Assessment Results

The building has had its seismic capacity assessed using the Initial Evaluation Procedure based on the information available. The buildings capacity is expressed as a percentage of new building standard (%NBS) and are in the order of that shown below in Table 3.

**Table 3: Qualitative Assessment Summary**

<u>Item</u>	<u>%NBS</u>
Buildings likely Seismic Capacity	≈100

Our qualitative assessment found that the building is likely to be classed as a ‘Low Risk Building’ (capacity between 67% and 100% of NBS). The full IEP assessment form is detailed in Appendix 2 – IEP Report.



## **8. Further Investigation**

Due to the likely seismic rating of this building being greater than 67%, and the lack of any structural damage, no further investigation is recommended.



## 9. Conclusion

A qualitative assessment was carried out on building BU 1662-005 EQ2, located at 62 Kirk Road, Templeton. This building has been assessed to have a likely seismic capacity of approximately 100% NBS and is therefore a 'Low Risk Building' (capacity greater than 67% of NBS).

Due to the likely seismic rating of this building and the lack of any structural damage no further investigation is required.

It is recommended that:

- a) There is no damage to the building that would cause it to be unsafe to occupy.
- b) We consider that barriers around the building are not necessary.

## 10. Limitation Statement

This report has been prepared on behalf of, and for the exclusive use of, SKM's client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and the Client. It is not possible to make a proper assessment of this report without a clear understanding of the terms of engagement under which it has been prepared, including the scope of the instructions and directions given to, and the assumptions made by, SKM. The report may not address issues which would need to be considered for another party if that party's particular circumstances, requirements and experience were known and, further, may make assumptions about matters of which a third party is not aware. No responsibility or liability to any third party is accepted for any loss or damage whatsoever arising out of the use of or reliance on this report by any third party.

Without limiting any of the above, in the event of any liability, SKM's liability, whether under the law of contract, tort, statute, equity or otherwise, is limited in as set out in the terms of the engagement with the Client.

It is not within SKM's scope or responsibility to identify the presence of asbestos, nor the responsibility of SKM to identify possible sources of asbestos. Therefore for any property pre-dating 1989, the presence of asbestos materials should be considered when costing remedial measures or possible demolition.

There is a risk of further movement and increased cracking due to subsequent aftershocks or settlement.

Should there be any further significant earthquake event, of a magnitude 5 or greater, it will be necessary to conduct a follow-up investigation, as the observations, conclusions and recommendations of this report may no longer apply. Earthquake of a lower magnitude may also cause damage, and SKM should be advised immediately if further damage is visible or suspected.

## 11. Appendix 1 – Photos



Photo 1: Front Elevation of Building



Photo 2: Side Elevation of Building



Photo 3: Internal View



Photo 4: Typical Roof Structure Details

Christchurch City Council  
BU 1662-005 EQ2  
Templeton Pool – Toddlers Pool Plant Room  
62 Kirk Road, Templeton  
Qualitative Assessment Report  
23 May 2013



## **12. Appendix 2 – IEP Report**

Building Name:	BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref.	ZB01276.54
Location:	Templeton Pool, 62 Kirk Road, Templeton	By	KW
		Date	27/04/2012

**Step 1 - General Information**

**1.1 Photos (attach sufficient to describe building)**



**1.2 Sketch of building plan**



**1.3 List relevant features**

Building BU 1662-005 is a single storey timber framed building that is used as a plant room for the toddlers pool located at Templeton Pool. The roof is constructed from timber purlins that are supported on the timber framed walls. The roof and wall cladding consists of a light weight corrugated steel cladding. The building sits on concrete foundations and a concrete floor slab. The footprint of this building is approximately 3.0m x3.0m and is only 3.0m high.

Lateral loads acting across and along the building will be resisted by the roof and wall cladding. If the building is subjected to large shaking it may go out of plumb due to the lack of bracing. However due to the light weight nature of the structure this is unlikely to be a life threatening

**1.4 Note information sources**

Tick as appropriate

- Visual Inspection of Exterior
- Visual Inspection of Interior
- Drawings (note type)
- Specifications
- Geotechnical Reports
- Other (list)

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>

Inspection Date - 27/04/2012



Building Name:	BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref.	ZB01276.54
Location:	Templeton Pool, 62 Kirk Road, Templeton	By	KW
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	27/04/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 2 - Determination of (%NBS)b**

**2.1 Determine nominal (%NBS) = (%NBS)nom**

Pre 1935		<input type="radio"/>	See also notes 1, 3
1935-1965		<input type="radio"/>	
1965-1976	Seismic Zone; A	<input type="radio"/>	
	B	<input type="radio"/>	
	C	<input type="radio"/>	See also note 2
1976-1992	Seismic Zone; A	<input type="radio"/>	
	B	<input type="radio"/>	
	C	<input type="radio"/>	
1992-2004		<input checked="" type="radio"/>	

**b) Soil Type**

From NZS1170.5:2004, Cl 3.1.3	A or B Rock	<input type="radio"/>
	C Shallow Soil	<input type="radio"/>
	D Soft Soil	<input checked="" type="radio"/>
	E Very Soft Soil	<input type="radio"/>
From NZS4203:1992, Cl 4.6.2.2 (for 1992 to 2004 only and only if known)	a) Rigid	<input checked="" type="radio"/>
	b) Intermediate	<input type="radio"/>

**c) Estimate Period, T**

building Ht = **3** meters

Can use following:

$T = 0.09h_n^{0.75}$	for moment-resisting concrete frames
$T = 0.14h_n^{0.75}$	for moment-resisting steel frames
$T = 0.08h_n^{0.75}$	for eccentrically braced steel frames
$T = 0.06h_n^{0.75}$	for all other frame structures
$T = 0.09h_n^{0.75}/A_c^{0.5}$	for concrete shear walls
$T \leq 0.4\text{sec}$	for masonry shear walls

Where  $h_n$  = height in m from the base of the structure to the uppermost seismic weight or mass.  
 $A_c = \sum A_i(0.2 + L_{wi}/h_n)^2$   
 $A_i$  = cross-sectional shear area of shear wall  $i$  in the first storey of the building, in  $m^2$   
 $L_{wi}$  = length of shear wall  $i$  in the first storey in the direction parallel to the applied forces, in m  
 with the restriction that  $L_{wi}/h_n$  shall not exceed 0.9

Ac =	Longitudinal	Transverse	m2
3	3	3	
	<input type="radio"/> MRCF	<input type="radio"/> MRCF	
	<input type="radio"/> MRSF	<input type="radio"/> MRSF	
	<input type="radio"/> EBSF	<input type="radio"/> EBSF	
	<input checked="" type="radio"/> Others	<input checked="" type="radio"/> Others	
	<input type="radio"/> CSW	<input type="radio"/> CSW	
	<input type="radio"/> MSW	<input type="radio"/> MSW	

Longitudinal	Transverse	Seconds
0.1	0.1	

**d) (%NBS)nom determined from Figure 3.3**

<b>Note 1:</b> For buildings designed prior to 1965 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.25.	No	Factor	1
For buildings designed 1965 - 1976 and known to be designed as public buildings in accordance with the code of the time, multiply (%NBS)nom by 1.33 - Zone A or 1.2 - Zone B	No	Factor	1
<b>Note 2:</b> For reinforced concrete buildings designed between 1976 -1984 (%NBS)nom by 1.2	No	Factor	1
<b>Note 3:</b> For buildings designed prior to 1935 multiply (%NBS)nom by 0.8 except for Wellington where the factor may be taken as 1.	No	Factor	1

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Longitudinal	22.2	(%NBS)nom
Transverse	22.2	(%NBS)nom

Continued over page

Building Name:	BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref.	ZB01276.54
Location:	Templeton Pool, 62 Kirk Road, Templeton	By	KW
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	27/04/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**2.2 Near Fault Scaling Factor, Factor A**  
If T < 1.5sec, Factor A = 1

a) Near Fault Factor, N(T,D) 1  
(from NZS1170.5:2004, Cl 3.1.6)

b) Near Fault Scaling Factor = 1/N(T,D) 

Factor A	1.00
----------	------

**2.3 Hazard Scaling Factor, Factor B**

Select Location

a) Hazard Factor, Z, for site  
(from NZS1170.5:2004, Table 3.3)

Z = 0.3  
Z 1992 = 0.8    Auckland 0.6    Palm Nth 1.2  
**Type Z 1992 above**    Wellington 1.2    Dunedin 0.6  
Christchurch 0.8    Hamilton 0.67

b) Hazard Scaling Factor  
# For pre 1992 = 1/Z  
For 1992 onwards = Z 1992/Z  
(Where Z 1992 is the NZS4203:1992 Zone Factor from accompanying Figure 3.5(b))

Factor B	2.67
----------	------

**2.4 Return Period Scaling Factor, Factor C**

a) Building Importance Level   
(from NZS1170.0:2004, Table 3.1 and 3.2)

b) Return Period Scaling Factor from accompanying Table 3.1 

Factor C	2.00
----------	------

**2.5 Ductility Scaling Factor, D**

a) Assessed Ductility of Existing Structure,  $\mu$   
(shall be less than maximum given in accompanying Table 3.2)

Longitudinal	1	$\mu$ Maximum = 6
Transverse	1	$\mu$ Maximum = 6

b) Ductility Scaling Factor  
For pre 1976 =  $k_{\mu}$   
For 1976 onwards = 1  
(where  $k_{\mu}$  is NZS1170.5:2005 Ductility Factor, from accompanying Table 3.3)

Longitudinal	Factor D	1.00
Transverse	Factor D	1.00

**2.6 Structural Performance Scaling Factor, Factor E**

Select Material of Lateral Load Resisting System

Longitudinal   
Transverse

a) Structural Performance Factor,  $S_p$   
from accompanying Figure 3.4

Longitudinal	$S_p$	1.00
Transverse	$S_p$	1.00

b) Structural Performance Scaling Factor

Longitudinal	$1/S_p$	Factor E	1.00
Transverse	$1/S_p$	Factor E	1.00

**2.7 Baseline %NBS for Building, (%NBS)<sub>b</sub>**  
(equals (%NSB)<sub>nom</sub> x A x B x C x D x E)

Longitudinal	118.4	(%NBS) <sub>b</sub>
Transverse	118.4	(%NBS) <sub>b</sub>

**Table IEP-3 Initial Evaluation Procedure – Step 3**

(Refer Table IEP - 1 for Step 1; Table IEP - 2 for Step 2, Table IEP - 4 for Steps 4, 5 and 6)



Building Name: BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref. ZB01276.54
Location: Templeton Pool, 62 Kirk Road, Templeton	By KW
Direction Considered: <b>a) Longitudinal</b>	Date 27/04/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)	

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**  
(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**  
(Choose a value - Do not interpolate)

**Building Score**

**3.1 Plan Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance  
Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect  
Select appropriate value from Table

Note:  
Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

		<b>Factor D1</b> <input type="text" value="1"/>		
Table for Selection of Factor D1		Severe	Significant	Insignificant
Separation		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height		<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect  
Select appropriate value from Table

		<b>Factor D2</b> <input type="text" value="1"/>		
Table for Selection of Factor D2		Severe	Significant	Insignificant
Separation		0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys		<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys		<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

**Factor D**

(Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

Corrugated exterior cladding provides lateral bracing to the structure and may be susceptible to buckling or tearing around fixings. Since the building is a small, light structure, the design seismic load demand is still unlikely to damage the cladding to the point of causing collapse.

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR

Building Name:	BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref.	ZB01276.54
Location:	Templeton Pool, 62 Kirk Road, Templeton	By	KW
Direction Considered:	<b>b) Transverse</b>	Date	27/04/2012
(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)			

**Step 3 - Assessment of Performance Achievement Ratio (PAR)**  
(Refer Appendix B - Section B3.2)

**Critical Structural Weakness**

**Effect on Structural Performance**  
(Choose a value - Do not interpolate)

**Building Score**

**3.1 Plan Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor A

**3.2 Vertical Irregularity**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor B

**3.3 Short Columns**

Effect on Structural Performance

Comment

Severe	Significant	Insignificant
<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>

Factor C

**3.4 Pounding Potential**

(Estimate D1 and D2 and set D = the lower of the two, or =1.0 if no potential for pounding)

a) Factor D1: - Pounding Effect

Select appropriate value from Table

Note:

Values given assume the building has a frame structure. For stiff buildings ( eg with shear walls), the effect of pounding may be reduced by taking the co-efficient to the right of the value applicable to frame buildings.

Factor D1

Table for Selection of Factor D1	Separation		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Alignment of Floors within 20% of Storey Height	<input type="radio"/> 0.7	<input type="radio"/> 0.8	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

b) Factor D2: - Height Difference Effect

Select appropriate value from Table

Factor D2

Table for Selection of Factor D2	Separation		
	Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1

Factor D

(Set D = lesser of D1 and D2 or..  
set D = 1.0 if no prospect of pounding)

**3.5 Site Characteristics - (Stability, landslide threat, liquefaction etc)**

Effect on Structural Performance

Severe	Significant	Insignificant
<input type="radio"/> 0.5	<input type="radio"/> 0.7	<input checked="" type="radio"/> 1

Factor E

**3.6 Other Factors**

For < 3 storeys - Maximum value 2.5,

otherwise - Maximum value 1.5. No minimum.

Factor F

Record rationale for choice of Factor F:

Corrugated exterior cladding provides lateral bracing to the structure and may be susceptible to buckling or tearing around fixings. Since the building is a small, light structure, the design seismic load demand is still unlikely to damage the cladding to the point of causing collapse.

**3.7 Performance Achievement Ratio (PAR)**  
(equals A x B x C x D x E x F)

PAR



Building Name:	BU 1662-005 EQ2 - Toddlers Pool Plant Room	Ref.	ZB01276.54
Location:	Templeton Pool, 62 Kirk Road, Templeton	By	KW
Direction Considered:	<b>Longitudinal &amp; Transverse</b>	Date	27/04/2012
<small>(Choose worse case if clear at start. Complete IEP-2 and IEP-3 for each if in doubt)</small>			

**Step 4 - Percentage of New Building Standard (%NBS)**

	Longitudinal	Transverse
<b>4.1 Assessed Baseline (%NBS)<sub>b</sub></b> (from Table IEP - 1)	118	118
<b>4.2 Performance Achievement Ratio (PAR)</b> (from Table IEP - 2)	0.85	0.85
<b>4.3 PAR x Baseline (%NBS)<sub>b</sub></b>	100	100
<b>4.4 Percentage New Building Standard (%NBS)</b> ( Use lower of two values from Step 4.3)		100

**Step 5 - Potentially Earthquake Prone?**  
(Mark as appropriate)

%NBS ≤ 33 NO

**Step 6 - Potentially Earthquake Risk?**

%NBS < 67 NO

**Step 7 - Provisional Grading for Seismic Risk based on IEP**

**Seismic Grade** A+

Evaluation Confirmed by

Signature

**Brendan Donnell**

Name

**246971**

CPEng. No

**Relationship between Seismic Grade and % NBS :**

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	80 to 67	67 to 33	33 to 20	< 20

Christchurch City Council  
BU 1662-005 EQ2  
Templeton Pool – Toddlers Pool Plant Room  
62 Kirk Road, Templeton  
Qualitative Assessment Report  
23 May 2013



## **13. Appendix 3 – CERA Standardised Report Form**

<b>Location</b>		Building Name: <u>Templeton Pool Toddlers Pool Plant Room</u>	Reviewer: <u>B. Donnell</u>
	Unit No: <u>Street</u>	CPEng No: <u>246971</u>	
Building Address: <u>62 Kirk Road, Templeton</u>		Company: <u>SKM</u>	
Legal Description: <u></u>		Company project number: <u>ZB01276.54</u>	
		Company phone number: <u>03 940 4900</u>	
	Degrees Min Sec	Date of submission: <u>24-May</u>	
GPS south: <u></u>		Inspection Date: <u>27/04/2012</u>	
GPS east: <u></u>		Revision: <u>B. Donnell</u>	
Building Unique Identifier (CCC): <u>PRO 1662-005</u>		Is there a full report with this summary? <u>yes</u>	

<b>Site</b>	Site slope: <u>flat</u>	Max retaining height (m): <u></u>
	Soil type: <u>silty sand</u>	The regional geological map shows the area to be underlain by grey river alluvium, comprising gravel, sand and silt, in active flood plains
	Soil Class (to NZS1170.5): <u>D</u>	Soil Profile (if available): <u></u>
	Proximity to waterway (m, if <100m): <u></u>	If Ground improvement on site, describe: <u>n/a</u>
	Proximity to cliff top (m, if <100m): <u></u>	Approx site elevation (m): <u></u>
	Proximity to cliff base (m, if <100m): <u></u>	

<b>Building</b>	No. of storeys above ground: <u>1</u>	single storey = 1	Ground floor elevation (Absolute) (m): <u></u>
	Ground floor split? <u>no</u>		Ground floor elevation above ground (m): <u></u>
	Storeys below ground: <u>0</u>		
	Foundation type: <u>strip footings</u>		if Foundation type is other, describe: <u></u>
	Building height (m): <u>3.00</u>	height from ground to level of uppermost seismic mass (for IEP only) (m): <u>3</u>	
	Floor footprint area (approx): <u>9</u>		
	Age of Building (years): <u>10</u> (max)		Date of design: <u>1992-2004</u>
	Strengthening present? <u>no</u>		If so, when (year)? <u></u>
	Use (ground floor): <u>other (specify)</u>		And what load level (%g)? <u></u>
	Use (upper floors): <u></u>		Brief strengthening description: <u></u>
	Use notes (if required): <u>Storage/pump shed</u>		
	Importance level (to NZS1170.5): <u>IL1</u>		

<b>Gravity Structure</b>	Gravity System: <u>load bearing walls</u>	
	Roof: <u>timber framed</u>	100x50 timber purlins bearing straight onto timber framed walls. Light weight corrugated steel cladding present.
	Floors: <u></u>	rafter type, purlin type and cladding
	Beams: <u></u>	
	Columns: <u></u>	
	Walls: <u></u>	<u>Timber framed walls - no interior linings</u>

<b>Lateral load resisting structure</b>	Lateral system along: <u>other (note)</u>	<b>Note: Define along and across in detailed report!</b>	describe system: <u>cladding will provide diaphragm</u>
	Ductility assumed, $\mu$ : <u>1.00</u>	0.00	estimate or calculation? <u>estimated</u>
	Period along: <u>0.10</u>		estimate or calculation? <u>estimated</u>
	Total deflection (ULS) (mm): <u>25</u>		estimate or calculation? <u>estimated</u>
	maximum interstorey deflection (ULS) (mm): <u></u>		
	Lateral system across: <u>other (note)</u>	0.00	describe system: <u>cladding will provide diaphragm</u>
	Ductility assumed, $\mu$ : <u>1.00</u>		estimate or calculation? <u>estimated</u>
	Period across: <u>0.10</u>		estimate or calculation? <u>estimated</u>
	Total deflection (ULS) (mm): <u>25</u>		estimate or calculation? <u>estimated</u>
	maximum interstorey deflection (ULS) (mm): <u></u>		

<b>Separations:</b>	north (mm): <u></u>	leave blank if not relevant
	east (mm): <u></u>	
	south (mm): <u></u>	
	west (mm): <u></u>	

<b>Non-structural elements</b>	Stairs: <u></u>	n/a
	Wall cladding: <u>profiled metal</u>	describe: <u>light weight corrugate</u>
	Roof Cladding: <u>Metal</u>	describe: <u>light weight corrugate</u>
	Glazing: <u></u>	n/a
	Ceilings: <u></u>	n/a
	Services (list): <u>Pool pumps etc</u>	

<b>Available documentation</b>	Architectural: <u>none</u>	original designer name/date: <u></u>
	Structural: <u>none</u>	original designer name/date: <u></u>
	Mechanical: <u>none</u>	original designer name/date: <u></u>
	Electrical: <u>none</u>	original designer name/date: <u></u>
	Geotech report: <u>none</u>	original designer name/date: <u></u>

<b>Damage</b>	Site performance: <u>1</u>	Describe damage: <u>none observed</u>
Site: (refer DEE Table 4-2)	Settlement: <u>none observed</u>	notes (if applicable): <u></u>
	Differential settlement: <u>none observed</u>	notes (if applicable): <u></u>
	Liquefaction: <u>none apparent</u>	notes (if applicable): <u></u>
	Lateral Spread: <u>none apparent</u>	notes (if applicable): <u></u>
	Differential lateral spread: <u>none apparent</u>	notes (if applicable): <u></u>
	Ground cracks: <u>none apparent</u>	notes (if applicable): <u></u>
	Damage to area: <u>none apparent</u>	notes (if applicable): <u></u>

<b>Building:</b>	Current Placard Status: <u>green</u>	
Along	Damage ratio: <u>0%</u>	Describe how damage ratio arrived at: <u>no damage was observed</u>
	Describe (summary): <u></u>	
Across	Damage ratio: <u>0%</u>	$Damage\_Ratio = \frac{(\% NBS\ (before) - \% NBS\ (after))}{\% NBS\ (before)}$
	Describe (summary): <u></u>	
Diaphragms	Damage?: <u>no</u>	Describe: <u></u>
CSWs:	Damage?: <u>no</u>	Describe: <u></u>
Pounding:	Damage?: <u>no</u>	Describe: <u></u>
Non-structural:	Damage?: <u>no</u>	Describe: <u></u>

<b>Recommendations</b>	Level of repair/strengthening required: <u>none</u>	Describe: <u></u>
	Building Consent required: <u>no</u>	Describe: <u></u>
	Interim occupancy recommendations: <u>full occupancy</u>	Describe: <u></u>
Along	Assessed %NBS before: <u>100%</u>	#### %NBS from IEP
	Assessed %NBS after: <u>100%</u>	If IEP not used, please detail assessment methodology: <u>NZSEE IEP used, refer to SKM Qualitative Report</u>
Across	Assessed %NBS before: <u>100%</u>	#### %NBS from IEP
	Assessed %NBS after: <u>100%</u>	

Christchurch City Council  
BU 1662-005 EQ2  
Templeton Pool – Toddlers Pool Plant Room  
62 Kirk Road, Templeton  
Qualitative Assessment Report  
23 May 2013



## **14. Appendix 4 – Geotechnical Desk Study**



Sinclair Knight Merz  
142 Sherborne Street  
Saint Albans  
PO Box 21011, Edgware  
Christchurch, New Zealand

Tel: +64 3 940 4900  
Fax: +64 3 940 4901  
Web: [www.globalskm.com](http://www.globalskm.com)



## Christchurch City Council - Structural Engineering Service

### Geotechnical Desk Study

SKM project number	ZB01276
SKM project site number	053 to 055 inclusive
Address	Templeton Pool, 62 Kirk Road
Report date	13 April 2012
Author	Ross Roberts / Ananth Balachandra
Reviewer	Leah Bateman
Approved for issue	Yes

### 1. Introduction

This report outlines the geotechnical information that Sinclair Knight Merz (SKM) has been able to source from our database and other sources in relation to the property listed above. We understand that this information will be used as part of an initial qualitative Detailed Engineering Evaluation (DEE), and will be supplemented by more detailed information and investigations to allow detailed scoping of the repair or rebuild of the building.

### 2. Scope

This geotechnical desk top study incorporates information sourced from:

- Published geology
- Publically available borehole records
- Liquefaction records
- Aerial photography
- Council files
- A preliminary site walkover

### 3. Limitations

This report was prepared to address geotechnical issues relating to the specific site in accordance with the scope of works as defined in the contract between SKM and our Client. This report has been prepared on behalf of, and for the exclusive use of, our Client, and is subject to, and issued in accordance with, the provisions of the contract between SKM and our Client. The findings presented in this report should not be applied to another site or another development within the same site without consulting SKM.

The assessment undertaken by SKM was limited to a desktop review of the data described in this report. SKM has not undertaken any subsurface investigations, measurement or testing of materials from the site. In preparing this report, SKM has relied upon, and presumed accurate, any information (or confirmation of the absence thereof) provided by our Client, and from other sources as described in the report. Except as otherwise stated in this report, SKM has not attempted to verify the accuracy or completeness of any such information.

Sinclair Knight Merz Limited


The SKM logo trade mark is a registered trade mark of Sinclair Knight Merz Pty Ltd.

Offices across Australia, New Zealand, UK, South East Asia, Middle East, the Pacific and Americas



This report should be read in full and no excerpts are to be taken as representative of the findings. It must not be copied in parts, have parts removed, redrawn or otherwise altered without the written consent of SKM.

#### 4. Site location




■ **Figure 1 – Site location (courtesy of LINZ <http://viewers.geospatial.govt.nz>)**

These structures are located on 62 Kirk road at grid reference 1557295 E, 5177988 N (NZTM).

## 5. Review of available information

### 5.1 Geological maps



- **Figure 2 – Regional geological map (Forsyth et al, 2008). Site marked in red.**

The local geological map for Christchurch did not extend to the location of the site.

The regional geological map shows the area to be underlain by grey river alluvium, comprising gravel, sand and silt, in active flood plains.

### 5.2 Liquefaction map

Following the 22 February 2011 earthquake event a drive through reconnaissance of the general Christchurch area was undertaken from 23 February until 1 March by M Cubrinovsko and M Taylor of Canterbury University.

However, this reconnaissance did not extend to Templeton.

### 5.3 Aerial photography

Aerial photography of Christchurch from 24<sup>th</sup> February 2011, available on <http://viewers.geospatial.govt.nz/> did not extend to this area.

### 5.4 CERA classification

A review of the LINZ website (<http://viewers.geospatial.govt.nz/>) shows that the site is:


- Zone: Green
- DBH Technical Category: N/A (Rural & Unmapped) – adjacent properties are classified as TC1 with the exception of the site directly opposite to the structure, which is classified as N/A (Urban Non-residential)



## 5.5 Historical land use

Available historical reference document is shown in Appendix A. However, no record for historical land use of this was available.

## 5.6 Existing ground investigation data



- **Figure 3 - Local Borehole from environment Canterbury online GIS (<http://arcims.ecan.govt.nz/ecanmapping/>)**

Where available logs from these investigation locations are attached to this report (Appendix B), and the results are summarised in Section 6.1 and Appendix C. Only investigations within 300m have been summarised however our existing knowledge of the area and wider boreholes have been used to draw conclusions regarding ground condition

## 5.7 Council property files

The available council property files for the site relate to the building consent documents drawn up in 1974 and warrant of fitness documents for the Templeton pool.

No relevant information for this desk study was evident from the review of available council property files.



## 5.8 Site walkover

A site walkover was conducted by an SKM engineer on the 16 April 2012.

The toilets, changing rooms and other structures are all masonry block buildings with constructed slab on grade foundations and sheet metal roof. There are two shaded BBQ areas, one a canvas construction suspended on timber poles, the other a timber framed construction on slab. The plant shed appears to be corrugated iron on timber frame on slab. The pool looks to be poured in-situ cement with cement seating/bleachers on the southern side. The site is surrounded by a masonry block fence to on the western and southern sides and sheet metal on the northern and eastern sides.

There is no evidence of damage to any of the structures /fences from the external inspection. There is no evidence of any land damage.



■ **Figure 4 Overview of the pool**



■ **Figure 5 Overview of Toilet block and changing rooms**

## 6. Conclusions and recommendations

### 6.1 Site geology

An interpretation of the most relevant geotechnical investigation data suggests that the site is underlain by:

Depth range (mBLG)	Soil type
0 - 1	Top soil
1 - 5.5	Dense Gravels of the Springston formation
5.5 - 13	Medium to coarse Riccarton gravels
13 +	Fine to medium sandy gravels of the Riccarton formation

A calculated minimum water table of 17.7m below ground level is shown in the available investigation data. This is a relatively deep water table for the general area and if further information is required regarding this it would need to be confirmed with additional investigations.

### 6.2 Seismic site subsoil class

The site has been assessed as NZS 1170.5 Class D (soft or deep soil, including gravel exceeding 100 m in depth) using nearby borehole investigation data. As no information regarding the composition of the top soil layer is available, Class D is recommended as a conservative estimate of the seismic site subsoil class.



As described in NZS1170, the preferred site classification method is from site periods based on four times the shear wave travel time through material from the surface to the underlying rock. The next preferred methods are from borelogs including measurement of geotechnical properties or by evaluation of site periods from Nakamura ratios or from recorded earthquake motions. Lacking this information, classification may be based on boreholes with descriptors but no geotechnical measurements. The least preferred method is from surface geology and estimates of the depth to underlying rock.

The third preferred method has been used in the assessment of site subsoil class. It should be noted that only one borehole sufficient near the site was available however we are relatively confident of ground conditions in this area.

### 6.3 Building Performance

The performance to date suggests that they are adequate for their current purpose.

### 6.4 Ground performance and properties

The liquefaction risk for the site is likely to be low. The gravel layers inferred to be underlying the site are not liquefiable and no evidence of land damage or liquefaction was observed during the external inspection of the site. However, there may be lenses of sand present in the sandy gravel layers are potentially liquefiable.

Although there is limited ground investigation data within the direct area of the site, the ground conditions in the Templeton region are relatively consistent. With interbedded gravels and sand from a depth of one metre.

For the purposes of carrying out a Quantitative Detailed Engineering Evaluation the engineer can assume this site is 'good ground' (as defined in NZS3604:2011) and therefore the following parameters are recommended for the shallow materials:

Parameter	Estimated value
Effective angle of friction	35 degrees
Apparent cohesion	0 kPa
Unit weight	18 kPa
Ultimate bearing capacity of a shallow square pad footing	300 kPa

NOTE: These figures are based on historical geotechnical data from outside the site for the purposes of preliminary structural assessment. These parameters should not be relied upon for any design work. Site specific investigations are required to confirm that these assumed values are correct. Additionally, further geotechnical investigation could potentially increase the ultimate bearing capacity stated above.

### 6.5 Further investigations

Unless a change of use is intended for the site we do not believe that any further geotechnical investigations are required. Specific ground investigation should be undertaken if significant alterations or new structures are proposed.



## 7. References

Brown LJ, Weeber JH, 1992. Geology of the Christchurch urban area. Scale 1:25,000. Institute of Geological & Nuclear Sciences geological map 1.

Cubrinovski & Taylor, 2011. Liquefaction map summarising preliminary assessment of liquefaction in urban areas following the 2010 Darfield Earthquake.

Forsyth PJ, Barrell DJA, Jongens R, 2008. Geology of the Christchurch area. Institute of Geological & Nuclear Sciences geological map 16.


Land Information New Zealand (LINZ) geospatial viewer (<http://viewers.geospatial.govt.nz/>)

EQC Project Orbit geotechnical viewer (<https://canterburyrecovery.projectorbit.com/>)





## Appendix A – Christchurch 1856 land use



The swamps and previous creeks/riders from 1856 have been overlaid onto a map of Christchurch in 2012

- Key**
- Previous creeks/riders
  - Existing creeks/riders
  - New creeks/riders
  - Swamp/Marshland




## **Appendix B – Existing ground investigation logs**



**Borelog for well M36/0111 page 1 of 2**


Gridref: M36:67260-39620 Accuracy : 2 (1=best, 4=worst)  
 Ground Level Altitude : 41.4 +MSD  
 Driller : A M Bisley & Co  
 Drill Method : Cable Tool  
 Drill Depth : -61m Drill Date : 4/02/1965





**Borelog for well M36/0111 page 2 of 2**

Gridref: M36:67260-39620 Accuracy : 2 (1=best, 4=worst)  
 Ground Level Altitude : 41.4 +MSD  
 Driller : A M Bisley & Co  
 Drill Method : Cable Tool  
 Drill Depth : -61m Drill Date : 4/02/1965












## **Appendix C – Geotechnical Investigation Summary**



■ **Table 1 Summary of most relevant investigation data**

ID	1
Type *	BH
Ref	M36 - 0111
Depth (m)	61
Distance from site (m)	30
Ground water level (mBGL)	17.7
Simplified recorded geological profile (depth below ground level to top of stratum, m)	0
	1
	2
	3
	4
	5
	6
	7
	8
	9
	10
	11
	12
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
Greater depths	

\*BH: Borehole, HA: Hand Auger, WW: Water Well, CPT: Cone Penetration Test

 Sensitive or organic clay/silt	 Clay to silty clay	 Clayey silt to silt	 Silty sand to silt
 Clayey sand	 Sand	 Gravelly sand or gravel	

VL = very loose, L = loose, MD = medium dense, D = dense, VD = very dense  
 VS = very soft, So = soft, F = firm, St = stiff, VS = very stiff, H = hard