

Christchurch City Council

**Gayhurst Road
Housing Complex
PRO 0712**

**Detailed Engineering Evaluation
Quantitative Assessment Report**





Christchurch City Council

Gayhurst Road Housing Complex

Quantitative Assessment Report

154 Gayhurst Road, Dallington,

Prepared By

.....
Claire Ford
Engineering Assistant

Reviewed By

.....
Lachlan Howat
Structural Engineer

Approved for
Release By

.....
Mary Ann Halliday
Senior Structural Engineer

Opus International Consultants Ltd
Christchurch Office
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail
Centre, Christchurch 8140
New Zealand

Telephone: +64 3 363 5400
Facsimile: +64 3 365 7858

Date: February 2014
Reference: 6-QC343.00
Status: Final

Summary

Gayhurst Road Housing Complex
PRO 0712

Detailed Engineering Evaluation
Quantitative Report - Summary
Final

Background

This is a summary of the quantitative report for the Gayhurst Road Housing Complex, and is based on the Detailed Engineering Evaluation Procedure document (draft) issued by the Structural Advisory Group on 19 July 2011. This assessment covers the 4 residential units on the site.

Key Damage Observed

The residential units have suffered minor damage to non-structural elements. This included stepped cracking of the brick veneer cladding and loose bricks in the gable ends of the block. Minor cracking of the interior plasterboard was also observed, particularly along firewalls. This damage was deemed low enough to not affect the capacity of the building.

Level Survey

All floor slopes were assessed in a laser level survey. None of the floor slopes were greater than the 5mm/m limitation set out in the MBIE guidelines [6], as shown below.

Internal Lining Nail Spacings

The internal lining nail spacings were measured on site to vary between 300 – 400 mm.

Critical Structural Weaknesses

No critical structural weaknesses were found in the building.

Indicative Building Strength

Table A: Summary of Seismic Performance by Blocks

Block	NBS%	Indicative Floor Levels	Nail Spacings
PRO 0712 B001 (Block A)	43%	Pass	Pass

Block A has a capacity of 43% NBS as limited by the in-plane shear capacity of the timber-framed shear walls in the longitudinal direction. It is deemed to be a ‘moderate risk’ in a design seismic event according to NZSEE guidelines, are therefore is not considered to be earthquake prone.

Increasing the number of nails in the plasterboard will not significantly improve the strength of the building.

Recommendations

It is recommended that;

- A strengthening scheme be developed to increase the seismic capacity of Block A to at least 67%NBS.
- Veneer at height (gable ends) have the veneer ties checked, loose bricks are to be repaired.
- Cosmetic repairs be undertaken as required.

Contents

Summary	i
1 Introduction.....	4
2 Compliance	4
3 Earthquake Resistance Standards.....	8
4 Background Information.....	10
5 Damage	13
6 Detailed Seismic Assessment	14
7 Geotechnical Summary	17
8 Conclusions.....	17
9 Recommendations	17
10 Limitations.....	18
11 References	18
Appendix A – Photographs	
Appendix B – Methodology and Assumptions	
Appendix C – CERA DEE Spreadsheet	

1 Introduction

Opus International Consultants Limited has been engaged by Christchurch City Council to undertake a detailed seismic assessment of the Gayhurst Road Housing Complex, located at 154 Gayhurst Road, Dallington, following the Canterbury earthquake sequence since September 2010. The site was visited by Opus International Consultants on 22 November 2013.

The purpose of the assessment is to determine if the buildings in the complex are classed as being earthquake prone in accordance with the Building Act 2004.

The seismic assessment and reporting have been undertaken based on the qualitative and quantitative procedures detailed in the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) [2] [3] [4] [5].

2 Compliance

This section contains a brief summary of the requirements of the various statutes and authorities that control activities in relation to buildings in Christchurch at present.

2.1 Canterbury Earthquake Recovery Authority (CERA)

CERA was established on 28 March 2011 to take control of the recovery of Christchurch using powers established by the Canterbury Earthquake Recovery Act enacted on 18 April 2011. This act gives the Chief Executive Officer of CERA wide powers in relation to building safety, demolition and repair. Two relevant sections are:

Section 38 – Works

This section outlines a process in which the chief executive can give notice that a building is to be demolished and if the owner does not carry out the demolition, the chief executive can commission the demolition and recover the costs from the owner or by placing a charge on the owners' land.

Section 51 – Requiring Structural Survey

This section enables the chief executive to require a building owner, insurer or mortgagee to carry out a full structural survey before the building is re-occupied.

We understand that CERA require a detailed engineering evaluation to be carried out for all buildings (other than those exempt from the Earthquake Prone Building definition in the Building Act). CERA have adopted the Detailed Engineering Evaluation Procedure (DEEP) document (draft) issued by the Structural Engineering Society (SESOC) on 19 July 2011. This document sets out a methodology for both initial qualitative and detailed quantitative assessments.

It is anticipated that a number of factors, including the following, will determine the extent of evaluation and strengthening level required:

1. The importance level and occupancy of the building.

2. The placard status and amount of damage.
3. The age and structural type of the building.
4. Consideration of any critical structural weaknesses.

Christchurch City Council requires any building with a capacity of less than 34% of New Building Standard (including consideration of critical structural weaknesses) to be strengthened to a target of 67% as required under the CCC Earthquake Prone Building Policy.

2.2 Building Act

Several sections of the Building Act are relevant when considering structural requirements:

Section 112 - Alterations

This section requires that an existing building complies with the relevant sections of the Building Code to at least the extent that it did prior to the alteration. This effectively means that a building cannot be weakened as a result of an alteration (including partial demolition).

The Earthquake Prone Building policy for the territorial authority shall apply as outlined in Section 2.3 of this report.

Section 115 – Change of Use

This section requires that the territorial authority is satisfied that the building with a new use complies with the relevant sections of the Building Code ‘as near as is reasonably practicable’.

This is typically interpreted by territorial authorities as being 67% of the strength of an equivalent new building or as near as practicable. This is also the minimum level recommended by the New Zealand Society for Earthquake Engineering (NZSEE).

Section 121 – Dangerous Buildings

This section was extended by the Canterbury Earthquake (Building Act) Order 2010, and defines a building as dangerous if:

1. In the ordinary course of events (excluding the occurrence of an earthquake), the building is likely to cause injury or death or damage to other property; or
2. In the event of fire, injury or death to any persons in the building or on other property is likely because of fire hazard or the occupancy of the building; or
3. There is a risk that the building could collapse or otherwise cause injury or death as a result of earthquake shaking that is less than a ‘moderate earthquake’ (refer to Section 122 below); or
4. There is a risk that other property could collapse or otherwise cause injury or death;
or
5. A territorial authority has not been able to undertake an inspection to determine whether the building is dangerous.

Section 122 – Earthquake Prone Buildings

This section defines a building as earthquake prone (EPB) if its ultimate capacity would be exceeded in a ‘moderate earthquake’ and it would be likely to collapse causing injury or death, or damage to other property.

A moderate earthquake is defined by the building regulations as one that would generate loads 33% of those used to design an equivalent new building.

Section 124 – Powers of Territorial Authorities

This section gives the territorial authority the power to require strengthening work within specified timeframes or to close and prevent occupancy to any building defined as dangerous or earthquake prone.

Section 131 – Earthquake Prone Building Policy

This section requires the territorial authority to adopt a specific policy for earthquake prone, dangerous and insanitary buildings.

2.3 Christchurch City Council Policy

Christchurch City Council adopted their Earthquake Prone, Dangerous and Insanitary Building Policy in October 2011 following the Darfield Earthquake on 4 September 2010.

The policy includes the following:

1. A process for identifying, categorising and prioritising Earthquake Prone Buildings, commencing on 1 July 2012;
2. A strengthening target level of 67% of a new building for buildings that are Earthquake Prone;
3. A timeframe of 15-30 years for Earthquake Prone Buildings to be strengthened; and,
4. Repair works for buildings damaged by earthquakes will be required to comply with the above.

The council has stated their willingness to consider retrofit proposals on a case by case basis, considering the economic impact of such a retrofit.

If strengthening works are undertaken, a building consent will be required. A requirement of the consent will require upgrade of the building to comply ‘as near as is reasonably practicable’ with:

- The accessibility requirements of the Building Code.
- The fire requirements of the Building Code. This is likely to require a fire report to be submitted with the building consent application.

Where an application for a change of use of a building is made to Council, the building will be required to be strengthened to 67% of New Building Standard or as near as is reasonably practicable.

2.4 Building Code

The Building Code outlines performance standards for buildings and the Building Act requires that all new buildings comply with this code. Compliance Documents published by The Department of Building and Housing can be used to demonstrate compliance with the Building Code.

On 19 May 2011, Compliance Document B1: Structure, was amended to include increased seismic design requirements for Canterbury as follows:

- Increase in the basic seismic design load for the Canterbury earthquake region (Z factor increased to 0.3 equating to an increase of 36 – 47% depending on location within the region);
- Increased serviceability requirements.

2.5 Institution of Professional Engineers New Zealand (IPENZ) Code of Ethics

One of the core ethical values of professional engineers in New Zealand is the protection of life and safeguarding of people. The IPENZ Code of Ethics requires that:

Members shall recognise the need to protect life and to safeguard people, and in their engineering activities shall act to address this need.

- 1.1 *Giving Priority to the safety and well-being of the community and having regard to this principle in assessing obligations to clients, employers and colleagues.*
- 1.2 *Ensuring that responsible steps are taken to minimise the risk of loss of life, injury or suffering which may result from your engineering activities, either directly or indirectly.*

All recommendations on building occupancy and access must be made with these fundamental obligations in mind.

3 Earthquake Resistance Standards

For this assessment, the building’s earthquake resistance is compared with the current New Zealand Building Code requirements for a new building constructed on the site. This is expressed as a percentage of new building standard (%NBS). The loadings are in accordance with the current earthquake loading standard NZS1170.5 [1].

A generally accepted classification of earthquake risk for existing buildings in terms of %NBS that has been proposed by the NZSEE 2006 [2] is presented in Figure 1 below.

Description	Grade	Risk	%NBS	Existing Building Structural Performance	Improvement of Structural Performance	
					Legal Requirement	NZSEE Recommendation
Low Risk Building	A or B	Low	Above 67	Acceptable (improvement may be desirable)	The Building Act sets no required level of structural improvement (unless change in use). This is for each TA to decide. Improvement is not limited to 34%NBS.	100%NBS desirable. Improvement should achieve at least 67%NBS
Moderate Risk Building	B or C	Moderate	34 to 66	Acceptable legally. Improvement recommended		Not recommended. Acceptable only in exceptional circumstances
High Risk Building	D or E	High	33 or lower	Unacceptable (Improvement required under Act)	Unacceptable	Unacceptable

Figure 1: NZSEE Risk Classifications Extracted from table 2.2 of the NZSEE 2006 AISPBE Guidelines [2]

Table 1 below compares the percentage NBS to the relative risk of the building failing in a seismic event with a 10% risk of exceedance in 50 years (i.e. 0.2% in the next year).

Table 1: %NBS compared to relative risk of failure

Percentage of New Building Standard (%NBS)	Relative Risk (Approximate)
>100	<1 time
80-100	1-2 times
67-80	2-5 times
33-67	5-10 times
20-33	10-25 times
<20	>25 times

3.1 Minimum and Recommended Standards

Based on governing policy and recent observations, Opus makes the following general recommendations:

3.1.1 Occupancy

The Canterbury Earthquake Order¹ in Council 16 September 2010, modified the meaning of “dangerous building” to include buildings that were identified as being EPB’s. As a result of this, we would expect such a building would be issued with a Section 124 notice, by the Territorial Authority, or CERA acting on their behalf, once they are made aware of our assessment. Based on information received from CERA to date and from the MBIE guidance document dated December 2012 [6], this notice is likely to prohibit occupancy of the building (or parts thereof), until its seismic capacity is improved to the point that it is no longer considered an EPB.

3.1.2 Cordoning

Where there is an overhead falling hazard, or potential collapse hazard of the building, the areas of concern should be cordoned off in accordance with current CERA/territorial authority guidelines.

3.1.3 Strengthening

Industry guidelines (NZSEE 2006 [2]) strongly recommend that every effort be made to achieve improvement to at least 67%NBS. A strengthening solution to anything less than 67%NBS would not provide an adequate reduction to the level of risk.

It should be noted that full compliance with the current building code requires building strength of 100%NBS.

3.1.4 Our Ethical Obligation

In accordance with the IPENZ code of ethics, we have a duty of care to the public. This obligation requires us to identify and inform CERA of potentially dangerous buildings; this would include earthquake prone buildings.

¹ This Order only applies to buildings within the Christchurch City, Selwyn District and Waimakariri District Councils authority.

4 Background Information

4.1 Building Descriptions

The site contains 4 residential units which were constructed in 1976. A site plan showing the location of the units, numbered 1 to 4, is shown in Figure 2. Figure 3 shows the location of the site in Christchurch City. The units are grouped together to form one block of four units.



Figure 2: Site plan of Gayhurst Road Housing Complex.




Figure 3: Location of Gayhurst Road (circled) relative to Christchurch City CBD (Source: Google Earth).

The residential units are timber-framed buildings with diagonal braces. The roof structure comprises of timber roof trusses supporting heavy, concrete tiles. The walls and ceilings are lined with plasterboard. External walls are clad with Summerhill Stone veneer. Foundations are strip footings under fire walls and around the perimeter of reinforced concrete slabs.

The units are separated by 190mm block masonry fully filled fire walls. These are reinforced with 12mm mild steel bars at 600mm centres. A reinforced bond beam is located within the block fire wall at ceiling height.

Figure 4 shows a typical floor plan of a residential unit produced from site measurements by Opus. Figure 5 shows the cross section used in calculations.




Figure 4: Typical partial floor plan of residential unit blocks.




Figure 5: Cross section of Gayhurst Road Housing Complex.

4.2 Survey

4.2.1 Post 22 February 2011 Rapid Assessment

A structural (Level 2) assessment of the buildings/property was undertaken on 4 March 2011 by Opus International Consultants.

4.2.2 Level Survey

A full level survey was not deemed to be necessary at Gayhurst Road although it is located in a TC3 zone. Generally properties in TC3 zones suffered significant damage due to liquefaction and/or settlement. As an initial survey a laser level was placed in each unit so that differentials in vertical levels could be measured at the extreme ends of the unit. These values could then be used to determine the floor slope of the entire unit.

Results from this laser level survey showed no indication of displacements, therefore a full survey was not required. For this site, all floor slopes were less than the 5mm/m limitation imposed by MBIE guidelines.

Table 2: Summary of the level survey

Block	Unit No.	Comment	Maximum Fall
A	1	Pass	-
	2	Pass	-
	3	Pass	-
	4	Pass	-

* Values are only recorded if greater than 5mm/m

4.2.3 Nail Spacings

The internal lining nail spacings were measured on site to vary between 300 – 400 mm.

4.3 Original Documentation

The following documentation was provided by the Christchurch City Council:

- 75-3423 – Merritt-Beazley Homes Ltd. – Proposed Merritt-Beazley Cottages for the Elderly, Gayhurst Road, Christchurch – p. 1-5/5 – Location plan; Site plan; Elevations, floor plan, electrical plan; Cross-sections, joinery details; Handrail details – 1976.

In addition, a typical floor plan has been produced by Opus to help confirm as-built measurements.

Copies of the design calculations were not provided.

5 Damage

This section outlines the damage to the buildings that was observed during site visits. It is not intended to be a complete summary of the damage sustained by the buildings due to the earthquakes. Some forms of damage may not be able to be identified with a visual inspection only.

Note: Any photo referenced in this section can be found in Appendix A.

5.1 Residual Displacements

No displacements were observed in all units inspected, these were all less than the 5mm/m MBIE guideline.

5.2 Foundations

No damage was observed to the foundations of these units.

5.3 Primary Gravity Structure

No damage was observed to the primary gravity structure.

5.4 Primary Lateral-Resistance Structure

Cracking of interior wall linings, especially surrounding the corners of doors and windows (photo 10) and where wall linings meet the fire wall (photo 11).

5.5 Non Structural Elements

Damage was also observed to the external stone veneers including stepped cracking (photo 12) and several loose bricks at the top of the gable ends of the building (photo 13). It was also observed that there was a minor crack in the path outside Unit 4 (photo 14).

5.6 General Observations

The buildings appeared to have performed reasonably well, as would be expected for buildings of this type, during the earthquakes. They have suffered distributed amounts of minor damage which is typical of the age and type of construction.

6 Detailed Seismic Assessment

The detailed seismic assessment has been based on the NZSEE 2006 [2] guidelines for the “Assessment and Improvement of the Structural Performance of Buildings in Earthquakes” together with the “Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure” [3] draft document prepared by the Engineering Advisory Group on 19 July 2011, and the SESOC guidelines “Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes” [5] issued on 21 December 2011.

As the residential units have the same floor plan, the analysis was simplified by conducting the analysis of one multi-unit block with similar cladding and using this for all multi-unit blocks.

6.1 Critical Structural Weaknesses

The term Critical Structural Weakness (CSW) refers to a component of a building that could contribute to increased levels of damage or cause premature collapse of a building.

No CSWs were identified in the buildings.

6.2 Quantitative Assessment Methodology

The assessment assumptions and methodology have been included in Appendix B. A brief summary follows:

Hand calculations were performed to determine seismic forces from the current building codes. These forces were applied globally to the structure and the capacities of the walls were calculated and used to estimate the %NBS. The walls, highlighted in Figure 6 and Figure 7, were used for bracing in their respective directions.




Figure 6: Walls used for bracing in the longitudinal direction.




Figure 7: Walls used for bracing in the transverse direction.

6.3 Limitations and Assumptions in Results

The observed level of damage suffered by the buildings was deemed low enough to not affect their capacity. Therefore the analysis and assessment of the buildings was based on them being in an undamaged state. There may have been damage to the buildings that was unable to be observed that could cause the capacity of the buildings to be reduced; therefore the current capacity of the buildings may be lower than that stated.

The results have been reported as a %NBS and the stated value is that obtained from our analysis and assessment. Despite the use of best national and international practice in this analysis and assessment, this value contains uncertainty due to the many assumptions and simplifications which are made during the assessment. These include:

- Simplifications made in the analysis, including boundary conditions such as foundation fixity.
- Assessments of material strengths based on limited drawings, specifications and site inspections.
- The normal variation in material properties which change from batch to batch.
- Approximations made in the assessment of the capacity of each element, especially when considering the post-yield behaviour.
- Construction is consistent with normal practise of the era in which constructed.

6.4 Assessment

A summary of the structural performance of the buildings is shown in Table 3. Note that the values given represent the worst performing elements in the building, where these effectively define the building's capacity. Other elements within the building may have significantly greater capacity when compared with the governing elements.

Table 3: Summary of Seismic Performance

Building Description	Critical element	% NBS based on calculated capacity in longitudinal direction	% NBS based on calculated capacity in transverse direction.
Residential Units (Block A)	Timber bracing in the longitudinal direction	43%	100%

7 Geotechnical Summary

CERA indicates that Gayhurst Road is located in a TC3 zone (as shown in Figure 8). This classification suggests future significant earthquakes will cause moderate to significant land damage due to liquefaction and settlement.



Figure 8: CERA Technical Categories map (loc. starred).

There is no evidence to suggest that further geotechnical investigation is warranted for this site.

8 Conclusions

- Block A has a capacity of 43% NBS, as limited by the in-plane capacity of the bracing walls. It is deemed to be a 'moderate risk' in a design seismic event according to NZSEE guidelines. The level of risk is 5-10 times that of a 100% NBS building (Figure 1) and is not considered to be Earthquake Prone.
- Based on the geotechnical appraisal, differential settlement as a result of liquefaction could result in further damage, similar in nature to that which has occurred in the recent earthquake sequence. However, based on the nature of construction, this is unlikely to result in the collapse of concrete ground beams beneath the masonry walls.

9 Recommendations

It is recommended that;

- A strengthening scheme be developed to increase the seismic capacity of Block A to at least 67% NBS.
- Veneer at height (gable ends) have the veneer ties checked, loose bricks are to be fixed.
- Cosmetic repairs be undertaken as required.

10 Limitations

- This report is based on an inspection of the buildings and focuses on the structural damage resulting from the Canterbury Earthquake sequence since September 2010. Some non-structural damage may be described but this is not intended to be a complete list of damage to non-structural items.
- Our professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time.
- This report is prepared for the Christchurch City Council to assist in the assessment of any remedial works required for the Gayhurst Road Housing Complex. It is not intended for any other party or purpose.

11 References



- [1] NZS 1170.5: 2004, Structural design actions, Part 5 Earthquake actions, Standards New Zealand.
- [2] NZSEE (2006), Assessment and improvement of the structural performance of buildings in earthquakes, New Zealand Society for Earthquake Engineering.
- [3] Engineering Advisory Group, Guidance on Detailed Engineering Evaluation of Earthquake Affected Non-residential Buildings in Canterbury, Part 2 Evaluation Procedure, Draft Prepared by the Engineering Advisory Group, Revision 5, 19 July 2011.
- [4] Engineering Advisory Group, *Guidance on Detailed Engineering Evaluation of Non-residential buildings, Part 3 Technical Guidance*, Draft Prepared by the Engineering Advisory Group, 13 December 2011.
- [5] SESOC (2011), Practice Note – Design of Conventional Structural Systems Following Canterbury Earthquakes, Structural Engineering Society of New Zealand, 21 December 2011.
- [6] MBIE (2012), Repairing and rebuilding houses affected by the Canterbury earthquakes, Ministry of Building, Innovation and Employment, December 2012.

Appendix A – Photographs

Gayhurst Road Housing Complex – Detailed Engineering Evaluation

Gayhurst Road Housing Complex		
1.	Typical exterior elevation (front)	
2.	Typical exterior elevation (side)	
3.	Typical exterior elevation (back)	

Gayhurst Road Housing Complex – Detailed Engineering Evaluation

4.	Typical lounge	
5.	Typical hallway	
6.	Typical kitchen	

Gayhurst Road Housing Complex – Detailed Engineering Evaluation

7.	Typical bathroom	
8.	Typical bedroom	
9.	Typical roof space showing trusses and concrete block fire wall	

Gayhurst Road Housing Complex – Detailed Engineering Evaluation

10.	Cracking to interior wall linings from windows and doors	
11.	Cracking to interior wall linings where they are separating from firewall	
12.	Stepped cracking to exterior veneers	

Gayhurst Road Housing Complex – Detailed Engineering Evaluation

<p>13.</p>	<p>Loose veneer bricks at the tops of gable ends</p>	
<p>14.</p>	<p>Crack in path outside Unit 4</p>	

Appendix B – Methodology and Assumptions

Seismic Parameters

As per NZS 1170.5:

- $T < 0.4s$ (assumed)
- Soil: Category D
- $Z = 0.3$
- $R = 1.0$ (IL2, 50 year)
- $N(T,D) = 1.0$

For the analyses, a μ of 2 was assumed for the residential units.

Analysis Procedure

As the units are small and have a number of closely spaced walls in both directions, the fibrous plaster board ceilings are assumed to be capable of transferring loads to all walls. It was therefore assumed that a global method could be used to carry the forces down to ground level in each direction. Bracing capacities were found by assuming a certain kN/m rating for the walls along each line. Due to the relatively unknown nature of the walls, the kN/m rating was taken as 3 kN/m for all timber walls with an aspect ratio (height: length) of less than 2:1. This was scaled down to zero kN/m at an aspect ratio of 3.5:1 as per NZSEE guidelines. %NBS values were then found through the ratio of bracing demand to bracing capacity for all walls in each direction.

Additional Assumptions

Further assumptions about the seismic performance of the buildings were:

- Foundations and foundation connections had adequate capacity to resist and transfer earthquake loads.
- Connections between all elements of the lateral load resisting systems are detailed to adequately transfer their loads sufficiently and are strong enough so as to not fail before the lateral load resisting elements.

Appendix C – CERA DEE Spreadsheet

Location		Building Name: <input type="text" value="Gayhurst Road Housing Complex"/>	Reviewer: <input type="text" value="M A Halliday"/>
		67073 No: Street	CPEng No: <input type="text" value="67073"/>
Building Address: <input type="text" value="154 Gayhurst Road, Dallington"/>		Company: <input type="text" value="Opus International Consultants Ltd."/>	Company project number: <input type="text" value="6-OC343.00"/>
Legal Description: <input type="text"/>		Company phone number: <input type="text" value="03-363-5400"/>	Date of submission: <input type="text" value="17-Feb-14"/>
	Degrees Min Sec		Inspection Date: <input type="text" value="22/11/2013"/>
GPS south: <input type="text" value="43"/>	<input type="text" value="30"/>	<input type="text" value="46.65"/>	Revision: <input type="text" value="1"/>
GPS east: <input type="text" value="173"/>	<input type="text" value="40"/>	<input type="text" value="26.95"/>	Is there a full report with this summary? <input type="text" value="yes"/>
Building Unique Identifier (CCC): <input type="text" value="PRO 0712"/>			

Site	Site slope: <input type="text" value="flat"/>	Max retaining height (m): <input type="text"/>
	Soil type: <input type="text"/>	Soil Profile (if available): <input type="text"/>
	Site Class (to NZS1170.5): <input type="text" value="D"/>	If Ground improvement on site, describe: <input type="text"/>
Proximity to waterway (m, if <100m): <input type="text"/>		Approx site elevation (m): <input type="text" value="5.00"/>
Proximity to cliff top (m, if < 100m): <input type="text"/>		
Proximity to cliff base (m,if <100m): <input type="text"/>		

Building	No. of storeys above ground: <input type="text" value="1"/>	single storey = 1	Ground floor elevation (Absolute) (m): <input type="text" value="5.00"/>
	Ground floor split? <input type="text" value="no"/>		Ground floor elevation above ground (m): <input type="text" value="0.00"/>
	Storeys below ground: <input type="text" value="0"/>		if Foundation type is other, describe: <input type="text"/>
	Foundation type: <input type="text" value="mat slab"/>	height from ground to level of uppermost seismic mass (for IEP only) (m): <input type="text"/>	Date of design: <input type="text" value="1965-1976"/>
	Building height (m): <input type="text"/>		
	Floor footprint area (approx): <input type="text" value="40"/>		
	Age of Building (years): <input type="text" value="37"/>		
	Strengthening present? <input type="text" value="no"/>		If so, when (year)? <input type="text"/>
	Use (ground floor): <input type="text" value="multi-unit residential"/>		And what load level (%g)? <input type="text"/>
	Use (upper floors): <input type="text"/>		Brief strengthening description: <input type="text"/>
	Use notes (if required): <input type="text"/>		
	Importance level (to NZS1170.5): <input type="text" value="IL2"/>		

Gravity Structure	Gravity System: <input type="text" value="frame system"/>	truss depth, purlin type and cladding: <input type="text"/>
	Roof: <input type="text" value="timber truss"/>	slab thickness (mm): <input type="text"/>
	Floors: <input type="text" value="concrete flat slab"/>	type: <input type="text"/>
	Beams: <input type="text" value="timber"/>	typical dimensions (mm x mm): <input type="text"/>
	Columns: <input type="text" value="timber"/>	
	Walls: <input type="text" value="non-load bearing"/>	

Lateral load resisting structure	Lateral system along: <input type="text" value="lightweight timber framed walls"/>	Note: Define along and across in detailed report!	note typical wall length (m): <input type="text"/>
	Ductility assumed, μ: <input type="text" value="2.00"/>		estimate or calculation? <input type="text" value="estimated"/>
	Period along: <input type="text" value="0.10"/>		estimate or calculation? <input type="text"/>
	Total deflection (ULS) (mm): <input type="text"/>	0.00	estimate or calculation? <input type="text"/>
	maximum interstorey deflection (ULS) (mm): <input type="text"/>		
	Lateral system across: <input type="text" value="lightweight timber framed walls"/>		note typical wall length (m): <input type="text"/>
	Ductility assumed, μ: <input type="text" value="2.00"/>		estimate or calculation? <input type="text" value="estimated"/>
	Period across: <input type="text" value="0.10"/>		estimate or calculation? <input type="text"/>
	Total deflection (ULS) (mm): <input type="text"/>	0.00	estimate or calculation? <input type="text"/>
	maximum interstorey deflection (ULS) (mm): <input type="text"/>		estimate or calculation? <input type="text"/>

Separations:	north (mm): <input type="text"/>	leave blank if not relevant
	east (mm): <input type="text"/>	
	south (mm): <input type="text"/>	
	west (mm): <input type="text"/>	

Non-structural elements	Stairs: <input type="text"/>	describe: <input type="text"/>
	Wall cladding: <input type="text" value="other heavy"/>	describe: <input type="text" value="Summerhill stone"/>
	Roof Cladding: <input type="text" value="Heavy tiles"/>	describe: <input type="text" value="concrete tiles"/>
	Glazing: <input type="text" value="aluminium frames"/>	
	Ceilings: <input type="text" value="fibrous plaster, fixed"/>	
	Services(list): <input type="text"/>	

Available documentation	Architectural: <input type="text" value="full"/>	original designer name/date: <input type="text" value="Merritt-Beazley/1975"/>
	Structural: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="included in above"/>
	Mechanical: <input type="text" value="none"/>	original designer name/date: <input type="text" value="included in above"/>
	Electrical: <input type="text" value="partial"/>	original designer name/date: <input type="text" value="included in above"/>
	Geotech report: <input type="text" value="none"/>	original designer name/date: <input type="text"/>

Damage	Site performance: <input type="text" value="good"/>	Describe damage: <input type="text" value="lining and veneer cracking"/>
Site: (refer DEE Table 4-2)	Settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
	Differential settlement: <input type="text" value="none observed"/>	notes (if applicable): <input type="text"/>
	Liquefaction: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
	Lateral Spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
	Differential lateral spread: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
	Ground cracks: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>
	Damage to area: <input type="text" value="none apparent"/>	notes (if applicable): <input type="text"/>

Building:	Current Placard Status: <input type="text" value="green"/>	
Along	Damage ratio: <input type="text" value="0%"/>	Describe how damage ratio arrived at: <input type="text"/>
	Describe (summary): <input type="text"/>	
Across	Damage ratio: <input type="text" value="0%"/>	$Damage_Ratio = \frac{(\%NBS\ (before) - \%NBS\ (after))}{\%NBS\ (before)}$
	Describe (summary): <input type="text"/>	
Diaphragms	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>
CSWs:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Pounding:	Damage?: <input type="text" value="no"/>	Describe: <input type="text"/>
Non-structural:	Damage?: <input type="text" value="yes"/>	Describe: <input type="text"/>

Recommendations	Level of repair/strengthening required: <input type="text" value="minor non-structural"/>	Describe: <input type="text"/>
	Building Consent required: <input type="text" value="no"/>	Describe: <input type="text"/>
	Interim occupancy recommendations: <input type="text" value="full occupancy"/>	Describe: <input type="text"/>
Along	Assessed %NBS before e'quakes: <input type="text" value="43%"/>	If IEP not used, please detail assessment methodology: <input type="text" value="Equivalent Static"/>
	Assessed %NBS after e'quakes: <input type="text" value="43%"/>	
Across	Assessed %NBS before e'quakes: <input type="text" value="100%"/>	If IEP not used, please detail assessment methodology: <input type="text"/>
	Assessed %NBS after e'quakes: <input type="text" value="100%"/>	



Opus International Consultants Ltd
20 Moorhouse Avenue
PO Box 1482, Christchurch Mail Centre,
Christchurch 8140
New Zealand

t: +64 3 363 5400
f: +64 3 365 7858
w: www.opus.co.nz