



Heritage - Tranche 2

| | Asset Group/ Type | Address | Recommended Required Work | Ward |
|----|--|--|--|----------------------|
| 1 | Akaroa Court House | 69 Rue Lavaud, Akaroa | Works for this asset will include general repair and painting to heritage fabric. | Akaroa/Wairewa |
| 2 | Addington Water Station | 66H Clarence Street, Addington | Remediation of earthquake related cracking and displacement of the cast concrete structure is required to return this asset back to the community. | |
| 3 | Akaroa Weighbridge | Beach Road, Akaroa | Investigate and make good cracking to plaster and minor EQ repairs and painting | Banks Peninsula |
| 4 | Chokebore Lodge | 148 Racecourse Road, Sockburn | Substantial EQ repairs, multiple chimney deconstruction and reinstatement, Roof diaphragm cob repairs internal and externally | Riccarton - Wigram |
| 5 | Cob Cottage | 2 Main Road, Mt Pleasant | This asset has been on hold, the Heritage Architect is undertaking an inspection and measure any further damage as a result of the Ferrymead Bridge works. Following this inspection and subsequent report, a stakeholder meeting will be held to discuss repair options. | Hagley - Ferrymead |
| 6 | Coronation Library (Akaroa) | 103 Rue Jolie, Akaroa | Upon receipt of direction on target NBS level, it is likely that a programme of strengthening of ply shear walls to the existing linings will be incorporated and an indication of a possible timber roof diaphragm | Akaroa/Wairewa |
| 7 | Edmond Band Rotunda | 230 Cambridge Terrace, Christchurch Central | The works to include significant reconstruction, strengthening & improvement of the foundations & connections between lower & roof elements. It is likely that stabilisation of the river wall section & surrounding ground area would pre-empt these works. | Hagley - Ferrymead |
| 8 | Edmonds Band Rotunda - Poplar Cres Pavillion | 230 Cambridge Terrace, Christchurch Central | The works will predominantly focus around the foundation and entrance steps to this structure. | Hagley - Ferrymead |
| 9 | Donald Street Yard (Former Council Stables) | 4 Donald Street, Lyttelton | The works are likely to include reinstatement of masonry walls & upgrading the structural strength of the building. Design works awaiting funding & asset owner direction. | Lyttelton/Mt Herbert |
| 10 | Godley House | 2 Waipapa Avenue, Diamond Harbour | Building Demolished - New Building restoration to be confirmed | Lyttelton/Mt Herbert |
| 11 | Grubb Cottage | 62 London Street, Lyttelton | The works considered are the remediation of the sub-floor piles, conservation of heritage wall papers, repair and reinstatement of the chimney. | Lyttelton/Mt Herbert |
| 12 | Kapuatohe Cottage | 663 Main North Road, Belfast | Repair Complete. | Shirley - Papanui |
| 13 | Kapuatohe Museum | 663 Main North Road, Belfast | Works required on this asset include installing new fixings and new plywood shear wall to the internal masonry columns as well as the introduction of a ceiling diaphragm. | Shirley - Papanui |
| 14 | Kapuatohe Dwelling | 663 Main North Road, Belfast | Works for this asset will include reconstruction and structural tie of the chimney element and making good of damage walls and decorating. | Shirley - Papanui |
| 15 | Kukupa Hostel | Pettigrews Road, Pigeon Bay | Proposed works for this asset may include improvement of the connections within the roof and wall and reinstatement of the chimney | Akaroa/Wairewa |
| 16 | Eteveneaux Cottage (LE Cottage) | 71 Rue Lavaud, Akaroa | The works will include the repairs and bracing of linings and repair/strengthening to the chimney. | Akaroa/Wairewa |

COMMUNITY FACILITIES REBUILD UNIT

Facilities Rebuild Rebuilding our neighbourhoods



| | Asset Group/ Type | Address | Recommended Required Work | Ward |
|----|--|--|--|----------------------|
| 17 | Little River Library | 4313 Christchurch Akaroa Road, Little River | The works are likely to include reinstatement of masonry walls, improvement of the connection between the walls and the roof structure, possible instatement of steel ring beam. | Akaroa/Wairewa |
| 18 | Lyttelton Clocktower | 26 Oxford Street, Lyttelton | The works include crack repair/strengthening to the monolith | Lyttelton/Mt Herbert |
| 19 | Lyttelton Museum | Donald/Oxford/Sumner Street, Lyttelton | Demolished- New Building to be confirmed | Lyttelton/Mt Herbert |
| 20 | Mona Vale Bathhouse | 65 Fendalton Road, Fendalton | Repair and strengthening to the external perimeter walls and foundations including an external palisade wall. | Riccarton - Wigram |
| 21 | Mona Vale Fernery | 66 Fendalton Road, Fendalton | The likely repair strategy to include improvement & enhancement of the tie & strengthening between the roof structure & the perimeter wall including strengthening of the buttresses. | Riccarton - Wigram |
| 22 | Plunket Room 211 Oxford Tce | 211 Oxford Terrace, Central Christchurch | Demolished- New Building to be confirmed | Hagley - Ferrymead |
| 23 | Risingholme Community Centre - Workshops | 22 Cholmondeley Avenue | The works include making good T&G floor spread, refixing ceiling linings & painting. Externally making good damage to hot mix paving areas. | Spreydon - Heathcote |
| 24 | Governors Bay Old School House | 102 Main Road, Governors Bay | The works on this asset is to rebuild the partially deconstructed chimney whilst maintaining the overall strength of the building above 67% NBS. This will include roof diaphragm strengthening. | Lyttelton/Mt Herbert |
| 25 | Signal Mast Cave Rock | 16 Esplanade, Sumner | The works include deconstruction and reinstatement of the structure. | |
| 26 | Signal Box - Norwich Quay Reserve | 1 Norwich Quay, Lyttelton | The works include making good to damaged paving and retaining wall. | Lyttelton/Mt Herbert |
| 27 | Edmonds Phone Box | Cnr Madras Street & Oxford Terrace, Christchurch Central | Repair. | Hagley - Ferrymead |
| 28 | Nurses Memorial Chapel | Riccarton Avenue, Christchurch Central | The works include significant internal fabric repairs, building strengthening, and making good finishes. | Hagley - Ferrymead |