Appendix A

OLD MUNICIPAL CHAMBERS

REPAIRS, RESTORATION & RECONSTRUCTION RELEVANT INFORMATION

Thursday, 8 February 2018

The following documents and key sections noted below are not an exhaustive list but provides relevant information to the repairs, restoration and reconstruction of Old Municipal Chambers. This document is to be read in conjunction with Joseph & Associates Repairs, Restoration & Reconstruction Relevant Information Report for OMC dated 8th February 2018. Documents are not for construction.

Ref No.	Document	File Name	Contents	Section No.	Page No.	Dated	Author	Comments
	Relevant Information Report	1 - OMC Relevant Information Schedules 2018	Repairs, Restoration & Reconstruction Relevant Information			8-Feb-18	Joseph & Associates Ltd	
-	neletani momadon neport	ome neletane mormation sociedates 2020	Report for OMC dated 8th February 2018			0.002	Joseph a 7 Joseph Co	
			,					
!	Conservation Plan	2 - OMC Conservation Plan Part 1				1-Oct-00	Dave PearsonArchitects Ltd	For key information about OMC and its setting and pre-earthquake condition refer to Conservation Plan 2000.
							1	
3	Conservation Plan	3 - OMC Conservation Plan Part 2				1-Oct-00	Dave PearsonArchitects Ltd	
1	Verticality Survey	4 - OMC Verticality Survey-2012-05-29		1	 	29-May-12	//3 Relow	
,	verticality survey	4 - Olvic verticality Survey-2012-05-25				25-14184-12	43 Below	
	Verticality Re -Survey	5 - 43 Below Survey Report 2013-5-28			1	28-May-13	43 Below	
	Verticality Re -Survey	6 - OMC 43 Below Survey Report 120580 - 08-June-2015				8-Jun-15	43 Below	
	Puilding Condition Papart	7 OMC Building Condition Paperty rost 2015 07 14		-		14-Jul-15	BuildQual NZ Ltd	The purpose of this survey was to capture the general condition of the interior of the rooms of the building
	Building Condition Report	7 - OMC - Building Condition Report - rev0 - 2015-07-14				14-Jul-15	BUIIUQUAI INZ LLU	the time of the assessment.
	Geotech	8 - GEOTECH				1-May-16	Geotech Consulting Ltd	This developed design report summarises the geotechnical considerations relating to the restoration of OMC.
						1		
	Conceptual Structural Remedial Options Report Rev 8	9 - Combined Report OMC Conceptual Structural Remedial				29-Jul-16	Opus International Consultants	Combined Structural Report included in original feasibility report to CCC July 2016. This report has large
		Options Report Rev8					Ltd	been superseded by Developed Design documentation, however it contains key sections not carried throu
							1	into the developed design documents sections being 2,3,4 and Appendices A, F and G.
								NOTE: Key sections are listed
			Background	2	2			
			Building Description	2.3	3		†	
			Previous Strengthening/Securing Works	2.4	3			
			Damage Observed	3	4			
			4 September 2010	3.1	4			
			22 February 2011 & Aftershocks	3.2	4			
			Water Ingress & Dry Rot	3.3	8			
			Level & Verticality	3.4	8			
			Stabilisation and Securing Works	4	9		1	
			Reinstatement Guidelines	5	10		1	
			Building Use	5.1	10			
			Heritage Considerations	5.2	11		 	
			Likelihood of Seismic Event Structural Performance	5.3 5.4	11 11		+	
			Structural Analysis & Assessment	5.4	12		+	
			Global Assessment	6.1	12	- 		
			Local Architectural Features	6.2	15			
			Foundations	6.3	15		†	
			Approaches to Repair, Strengthening and Resilience	7	16-17			
			Reinstatement Options	8	20			
			Buildability	8.5	26			
			Peer Review	8.6	28			
			Conclusions	9	28			
			Recommendations	10	29			
			Damage Assessment	Appendix A				
			Peer Review Comments Register	Appendix F				
			3D Scan Level Assessment	Annendiy G	I	1	1	1

3D Scan, Level Assessment



Appendix A

OLD MUNICIPAL CHAMBERS

REPAIRS, RESTORATION & RECONSTRUCTION RELEVANT INFORMATION

Thursday, 8 February 2018

The following documents and key sections noted below are not an exhaustive list but provides relevant information to the repairs, restoration and reconstruction of Old Municipal Chambers. This document is to be read in conjunction with Joseph & Associates Repairs, Restoration & Reconstruction Relevant Information Report for OMC dated 8th February 2018.

Documents are not for construction.



No.	Document	File Name	Contents	Section No.	Page No.	Dated	Author	Comments
	DD Heritage Assessment Report	10- DD Heritage Assessment Report				24-Mar-17	Tony Ussher Architect & Conservation Consultant	This developed design report describes the history and cultural heritage significance of the building, its curr condition and status, summarises the options considered for its remediation at feasibility study stage, and discusses relevant construction and strengthening processes that could be applied. The scope of the propo
								work is described in detail including services and statutory upgrades required.
			Introduction	1	3			This report has been prepared to assess the effects of the proposed interventions of the preferred develop design solution on the heritage values of the OMC.
			Outline History	3	3			Summarised from the Heritage NZ list, reference number 1844.
			Building Description	4	5			
			Construction & Description- Pre Earthquake Damage Status	4.1	5			
			Previous Strengthening and Alterations	4.2	5			
			Cultural Heritage Significance	5	6			The Country of the ACD by December 1 and the Act of the ACD and the Act of the ACD and the
			Conservation Plan	5.1	/			The Conservation Plan (CP) by Dave Pearson Architects Ltd was prepared in October 2000 and is to be fo in regard to all works to the Chamber and its setting.
	1						Design options considered the significance values policies and recommendations of the CP.	
			Description of the 2010/11 Canterbury Earthquakes Damage and Stabilisation	6	8			
			Building Surveys	6.2	15			
			Heritage Fabric Recording	6.3	15			
		10a - DD Significance Schedule	Schedule of Authenticity, Significance, Condition and Status	7	16			Refer also to file named 9a DD Significance Schedule
			Options Considered for the Repairs, Restoration and	8	21			
			Strengthening					
			General Considerations	8.1	21			Principal to the Mark of Oakhan Providence and house the Mark of Oakhan Providence and the contributions of the Mark of Oakhan Providence and the contribution of the Mark of Oakhan Providence and the Contribution of Oakhan Providence and Oa
			Summary of the Feasibility Study Options considered	8.2	21			Refer also to the Matrix of Options Report prepared by consultant team.
			Masonry Wall Repair Processes Considered- Feasibility Study	8.3	22			Numerous appropriate repair processes and techniques were considered and assessed in the developm the repair and remediation strategies for the building. The structural engineering pros and cons of the care discussed in Section 7, Approaches to Repair, Strengthening and Resilience of the Structural Remedi Options Report by Opus Consultants. Comment on the effects of the various processes and technologies heritage values of the Chambers are included here.
			Authorit and December of December of December of	0.4	24			Figure 5 Hand Consideration Devices
			Architectural Drawings - Developed Design	8.4	24			Existing, Full and Staged Restoration Drawings.
		Structural Strengthening: Full Restoration with Strengthening to 67% NBS	8.5	24				
			Construction & Fabric Considerations	8.6	29			
			Disabled Persons Access- Statutory Requirements & Upgrading	9.2	34			
			Existing Situation Compliance with Acceptable Solutions in NZBC D1/AS1		34 34		+	Refer to the Barrier Free report for the full assessment of upgrading requirements and recommendation
			and NZS 4121:2001					neter to the partier rice report for the full assessment of upgrading requirements and recommendation
			Considerations Proposals for Electrical Services & Heating	9.2.3	35 36		+	Refer Opus Consultants OMC Repairs, Restoration & Report- available upon request.
			Proposed Electrical Supply and Reticulation	9.3.1	36			Refer Opus Consultants Offic Repairs, Restoration & Reports available upon request.
			Proposed for Ventilation and Space Heating	9.3.2	36			
			Proposals for Fire Protection	9.4	37			Refer to the Enlightened Solutions Fire Report.
			Conservation Policy Considerations & Constraints	10	37			
			ICOMOS NZ Charter 2010	10.1	37			
			Conservation Plan Christchurch Replacement District Plan	10.2 10.3	41 43			
			Assessment of Effects on Heritage Values - Full	11	44			
		14. 44. 46. 46. 46. 46. 46.	Restoration			4		
	Matrix of Options Considered	11 - Matrix of Options Considered				1-Apr-17	Joseph & Associates Ltd	Developed Design Report-In developing repair and reinstatement approaches for this building the Project have considered a broad range of materials and techniques. This section introduces this range of material approaches and intends to highlight the benefits and limitations of each as a basis for understanding how options outlined in the subsequent sections have been arrived at.
	DD Outline Specification	12 - DD Outline Spec-31.03.17				31-Mar-17	Tony Ussher Architect & Conservation Consultant	Developed Design Report-The Outline Specification describes the work and materials according to the component parts of the building and its elements. The outline specification is divided into two parts, the for the FULL RESTORATION proposal, and the second for the STAGED RESTORATION proposal which is a completion of the repair, strengthening and reconstruction of the building deferring its final restoration future date.

Appendix A

OLD MUNICIPAL CHAMBERS

REPAIRS, RESTORATION & RECONSTRUCTION RELEVANT INFORMATION

Thursday, 8 February 2018

The following documents and key sections noted below are not an exhaustive list but provides relevant information to the repairs, restoration and reconstruction of Old Municipal Chambers. This document is to be read in conjunction with Joseph & Associates Repairs, Restoration & Reconstruction Relevant Information Report for OMC dated 8th February 2018. Documents are not for construction.



0.	Document	File Name	Contents	Section No.	Page No.	Dated	Author	Comments
	Architectural Drawings	13 - Architectural Drawings 31.03.17				31-Mar-17	Tony Ussher Architect &	The developed design architectural drawings include the following series:
							Conservation Consultant	Drawings prefixed
								AE Existing Pre-Earthquake Damage Form.
								AF Developed Design Full Restoration.
								AS Developed Design, Staged (Partial Restoration)
	OMC Structural Design Features Report	14 - OMC Structural Design Features Report Issue 1				24-Mar-17	Opus International Consultants	
			General	1	2		Ltd	
				1.1	2		-	The building has not been presented since Contamber 2010 due to the demand contained and its risk of cells
			Introduction	1.1	2			The building has not been occupied since September 2010 due to the damage sustained and its risk of coll The building has generally been seismically stabilised to provide at least 34% NBS strength to the perimete including areas adjacent to public access ways.
			Objective	1.2	2		+	9 1 1
			Objective	1.2	2			The Design Features Report (DFR) is a detailed document defining the structure's design criteria and recor
								key decisions or outcomes. It outlines design loading, structural modelling assumptions, material properti
								foundation requirements and design standards. The DFR also defines the calculation procedure and check
								principles to be followed, providing a clear explanation of the full design.
			Building Use	1.3	3			At this stage the client (CCC) are expecting to use the building in essentially the same way as prior to the
								Canterbury Earthquake sequence.
			Approach to Consent	1.4	3			In order to future proof the building and to maximise the options for its re-use, CCC have decided to resto
								building and strengthen it to a level where the damage to the building in a future earthquake is expected
								moderate. Recommendation is that when CCC apply for consent to restore the building, approval is also
								for a change in use.
					_			
			Means of Compliance	1.5	3			The design of the structure is in compliance with the New Zealand Building Code (NZBC), section B1.
			The Structure	2	3			Note: This section has both Full Restoration and Staged Information.
			General	2.1	3			
			Existing Gravity Structure	2.2	6			
			Lateral Load Resisting Structure	2.3	7			
			Full Restoration Significant Design Features	2.4	8			
			Soil Conditions	3	16		1	
			Summary of Geotechnical Report	3.1	16		1	Refer to the Geotechnical Report by Geotech Consulting, dated May 2016.
			Soil Design Values	3.2	17			Refer to the Geotechnical Report by Geotech Consulting, dated May 2016.
			Seismic Design Methodology	4	18			This section outlines the seismic design methodology adopted for the design of the seismic lateral load re-
			Scisine Sesign Methodology	ſ				system.
			Design Loads	5	19			
			Structural Peer Review	6	20			Ruamoko Solutions was engaged to undertake a peer review of the structural aspects of this project. The
								of the peer review is listed within this section. Ruamoko has completed a review of the concept design re
								July 2016, their comments have been incorporated into the developed design documentation.
			Next Steps	7	21			There are a selection of structural items which need to be considered as part of the detailed design stage. These are summarised for future reference.
			Report Limitations	8	21			
			Full Restoration Sequencing Sketches	Appendix A				Appendix B includes Staged Restoration Sequencing Sketches.
	Old Municipal Chambers Structural Drawings	15 - Old Municipal Chamber Structural 2017-04-04				4-Apr-17	Opus International Consultants	Developed Design Structural Drawings - not for construction.
	Enlightened Fire Report	16 - Enlightened Fire Report	Means of Escape Fire Report		-	27 Mar 17	Enlightened Solutions	Developed Design Report-The purpose of this report is to satisfy Council that after the proposed alteration
	Linightened rife Report	10 - Linighteneu File Report	iviealis of Escape File Report			27-10181-17	Linightened Solutions	building will comply with the provisions of the building code for means of escape from fire as nearly as is reasonably practicable.
	Accessibility Report	17 - Accessibility Report 20170313	+	-		13-Mar-17	Rarrier Free New 7ealand Trust	Developed Design Report-Barrier Free NZ Trust was engaged to produce an Accessibility Report on Old
	Accessionity Report	17 - Accessibility Report 20170313				15 14101 17	barrier rice New Zealand Trust	Municipal Chambers building (OMC) with the purpose of ascertaining existing levels of accessibility compli
								and providing recommendations for the improvement of accessibility which could be incorporated 'as ne
								1
								is reasonably practicable' into the repair and upgrade works.
	Planning Considerations	18 - OMC - Planning Matters (January edition)				19-Dec-17	Planz Consultants Limited	This updated Developed Design Report summarises Planning Considerations for the Full Restoration of the
		3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3			1		1	including the underlying zone provisions . The underlying zone provisions provide for a range of permitted
					1		1	of the building- list included. The report lists the Key Stakeholders in the consenting process and other ma
								i.e. archaeological authority and planning conclusions.