

10 June 2025

03 941 8999

53 Hereford Street
Christchurch 8013

ccc.govt.nz

Lighthouse Road land instability update

Kia ora,

Thank you for getting in touch and for sharing your concerns and those of your community. We understand that the land instability near Lighthouse Road is a significant worry for residents and the community. Please be assured that a lot of work is happening at our end, and we aim to provide a more detailed update shortly.

Further investigation work has been completed, which has informed the next stages of investigations which are progressing.

We understand that those affected by this event are primarily seeking clarity on what work will be undertaken and when it will happen. We are continuing to work towards providing this update, including exploring options to accelerate the process where possible.

As a weather update, we've recorded a cumulative 70mm rainfall on site since Thursday 5 June, with further showers forecast. While the wet weather conditions have prompted increased monitoring during this period, current forecasts do not indicate any cause for concern. Importantly, movement sensors have not detected any significant ground movement – only minor, routine fluctuations consistent with daily patterns since monitoring began.

We are committed to providing regular updates to residents and will be back in touch with more information as soon as it becomes available. We truly appreciate your patience and understanding as we work through this complex situation, and we remain focused on ensuring the safety and wellbeing of everyone affected.

If you have any further questions, please contact me on 03 941 6462 or Brenden.winder@ccc.govt.nz

Ngā mihi nui,



Brenden Winder
Recovery Manager
Civil Defence & Emergency Management
Christchurch City Council